ଇ



Li-ion Soft Short Test & Cell Defect Correlation

by Eric Darcy NASA-JSC

NASA Aerospace Battery Workshop Huntsville, AL

5-7 Nov 2013

www.nasa.gov

00

Motivation

- Recent lot of YTP 30Ah flight cells are failing the soft short test at an alarming rate
 - 41/156 cells or 26% had $\Delta V > 2mV$
 - 31/156 cells or 20% had $\Delta V > 5mV$
 - 23/156 cells or 15% had $\Delta V > 10mV$
 - Test was repeated twice on cells with suspect curves
- Questions
 - Is the test validly identifying cells with shorting defects?
 - Are some cell designs predisposed to fail this test?
 - Should it be included in our revised battery safety standard

YTP 14-day Soft Short Test Results



3

Correlating Soft Short Rejects

- Objective
 - Determine how good the correlation is between OCV retention outliers and cell defects
 - Establish basis for soft short methodology using 18650 cells
- Plan
 - Use cells (Moli ICR18650J) that were rejected during acceptance OCV testing back in 2008-2009 for the EMU LLB project
 - Apr 2007 date code to Jul 2009 OCV test = 27 months of storage
 - 40 outliers out of 3641 kept in controlled storage since
 - For those that will accept a charge, cycle them and perform deep discharge, OCV bounce back soft short testing
 - CC discharge at C/10 to 3.0V
 - CV discharge at 3.0V to C/100 taper
 - Record OCV bounce back over 14 days
 - Perform cell DPA on the worst and best performers

As Received OCV Distribution



As Received OCVs after 1st scrub



37 new outliers found outside new -3 sigma range of 16.3 mV (0.43%) Note that none +3 sigma outliers suggests capacity cycler errors are small

Cell ID OCV @ BOC PD10SAAV120 3.722896 PD10SABP045 3.76379 PD10SABI040 3.765316 PD10SABG075 3.766155 PD10SABA058 3.767224 PD10SAAO084 3.768292 PD10SAAV083 3.768826 PD10SAAU062 3.769284 PD10SAAY085 3.769284 PD10SABD076 3.770275 PD10SAAP005 3.771115 PD10SABH010 3.774624 PD10SAAX044 3.776074 PD10SAAZ098 3.776074 PD10SAAX078 3.776684 PD10SABV106 3.7776 PD10SABA045 3.78233 PD10SAAY086 3.78294 PD10SABV128 3.784085 PD10SABL062 3.785992 PD10SAAU091 3.787137 PD10SABT110 3.787137 PD10SABR127 3.787289 PD10SAAS025 3.787976 PD10SABJ008 3.788586 PD10SABV070 3.788968 PD10SABF029 3.789502 PD10SAAW072 3.789654 PD10SAAP062 3.789883 PD10SAAU083 3.78996 PD10SABC011 3.791028 PD10SABD026 3.791485 PD10SABW092 3.791638 PD10SABX045 3.791714 PD10SAAU032 3.79202 PD10SABH126 3.792096 PD10SABP037 3.792172

11-24-09

As Received OCVs after 2nd scrub



Another 16 outliers found outside of recalculated 6σ range of <u>6.2 mV (0.16%)</u> These 16 were rejected, but a new 6σ range was not recalculated. In all, a total of 56 OCV outliers were removed from flight cell population

OCV History



- After the 2009 OCV measurement, cells were capacity cycled and stored at 0% SOC
- Squares are the 2013 OCVs on the 40 cells
- 12 cells with OCVs < 2.5V (shown as black squares) would not accept a charge
 - Exception was cell #120 in red whose OCV was 2.2719V and it cycled

Cells that wouldn't cycle

Cell ID

2009 OCV 2013 OC

- 12 of 40 cells would not cycle
- All their OCVs had degraded < 2.5V
- Five of the 12 have been DPA'ed so far

NC		PD10SAAR110	2.6226	1.5186
	\longrightarrow	PD10SABL117	2.7124	0.9531
		PD10SAAT113	3.7169	1.1313
	Possible active material	PD10SAAV120	3.7229	2.2719
	bridge in separator	PD10SABP045	3.7638	2.6484
	blidge in separator	PD10SABI040	3.7653	4.0751
01110(2)	/	PD10SABG075	3.7662	2.3907
54AUOB2	K	PD10SABA058	3.7672	1.396
	a state ?.	PD10SAAO084	3.7683	1.549
		PD10SAAV083	3.7688	1.909
		PD10SAAU062	3.7693	2.4004
		PD10SAAY085	3.7693	2.0677
		PD10SABD076	3.7703	1.338
		PD10SAAP005	3.7711	2.5417
		PD10SABH010	3.7746	2.3714
PD10SAAU062		PD10SAAX044	3.7761	2.5599
		PD10SAAZ098	3.7761	2.6227
		PD10SAAX078	3.7767	2.5401
		PD10SABV106	3.7776	2.6015
		PD10SABA045	3.7823	2.633
		PD10SAAY086	3.7829	2.3404

Moli Cell #PD10SABD076



Active material bump on anode coating

(

Active material deposit on cathode side of separator



Active material deposit on anode side of separator

Moli Cell #PD10SABL117



- Found active material deposit on both side of separator
- Most likely cause of the soft short

Anode side

Cathode side

200 µm

200 µm

Moli Cell #PD10SABL117 (cont)



 Found crease in cathode, but no separator mark

This defect may not have caused the soft short



Moli Cell #PD10SAAT113



Anode side

200 um

- Found active material deposit on both side of separator
- Most likely cause of the soft short

Cathode side

Moli Cell #PD10SAAR110



 Heavy delamination of cathode active material found in separator



Coulombic Efficiency of the 28 cells



Selected 2 high and 3 poor performers for first DPAs



OCV Bounce Back of 5 Selected Cells



Soft Short Results on all 28

	OCV				OCV ~Day	
	~Day 1	OCV ~Day 3		OCV ~Day	16 D (0 1	SHORE'
ID#	Date 8-20-	Date 8-22-	OCV ~Day 7 Date 8-26-13	10 Date 8-29-13	Date 9-4- 2013	ΔV drop
PD10SABL062	3.2990	3.2954	3.2950	3.2940	3.2934	0.0056
PD10SAAX078	3.3289	3.3289	3.3279	3.3268	3.326	0.0029
PD10SAAP005	3.3564	3.3570	3.3560	3.3554	3.3543	0.0027
PD10SAAX044	3.3065	3.3069	3.3059	3.3051	3.3042	0.0027
PD10SABV128	3.3000	3.2992	3.2985	3.2979	3.2973	0.0027
PD10SABV106	3.3122	3.3122	3.3112	3.3104	3.3096	0.0026
PD10SABP045	3.3327	3.3326	3.3317	3.3306	3.3302	0.0025
PD10SAAZ098	3.3012	3.3016	3.3007	3.3001	3.2991	0.0025
PD10SABA045	3.3112	3.3111	3.3105	3.3095	3.3087	0.0025
PD10SABT110	3.2970	3.2975	3.2967	3.2954	3.295	0.0025
PD10SAAU091	3.2947	3.3438	3.3432	3.3423	3.3418	0.0020
PD10SABJ008	3.3300	3.3299	3.3294	3.3283	3.3281	0.0019
PD10SABC011	3.2695	3.2805	3.2806	3.2797	3.2789	0.0017
PD10SABW092	3.2923	3.3073	3.3075	3.3066	3.3058	0.0017
PD10SAAU032	3.3234	3.3478	3.348	3.3471	3.3463	0.0017
PD10SAAW072	3.3432	3.3812	3.3852	3.3845	3.3837	0.0015
PD10SABR127	3.2972	3.3587	3.3583	3.3573	3.3572	0.0015
PD10SABF029	3.2929	3.3109	3.3112	3.3105	3.3099	0.0013
PD10SABD026	3.2878	3.3085	3.3091	3.3083	3.3078	0.0013
PD10SABX045	3.2941	3.3081	3.3087	3.3078	3.3074	0.0013
PD10SAAS025	3.3480	3.3484	3.3480	3.3472	3.3471	0.0013
PD10SAAU083	3.2991	3.3174	3.3179	3.3172	3.3166	0.0013
PD10SABH126	3.2854	3.2984	3.2988	3.2978	3.2976	0.0012
PD10SABV070	3.2864	3.3027	3.3034	3.3026	3.3023	0.0011
PD10SABP037	3.2988	3.3125	3.3129	3.3122	3.3122	0.0007
PD10SAAV120	3.3237	3.3239	3.3242	3.3241	3.3237	0.0005
PD10SAAP062	3.3554	3.3974	3.4047	3.4052	3.4051	0.0001
PD10SAB1040						0.0000

- 14-day soft short test identified most of the 27 months OCV rejects
- 24 cells with ∆V > 1 mV (86%)
- 11 cells with ∆V ≥ 2 mV (39%)

Moli Cell #PD10SAAP005



Active material bump on anode coating



OCV reject by 21.4 mV Failed Soft Short Test ($\Delta V = 2.7 \text{ mV}$)



Active material deposit on cathode side of separator

Active material deposit on anode side of separator

Moli Cell #PD10SAAX044



Active material spot on anode coating and adjacent spot on separator



Defect 2

Active material deposit on anode side of separator



OCV reject by 16.4 mV Failed Soft Short Test ($\Delta V = 2.9$ mV)



Active material deposit on cathode side of separator

Active material spot on anode coating

Moli Cell #PD10SAAX078



Active material bump on anode coating

OCV reject by 15.8 mV Failed Soft Short Test ($\Delta V = 2.7$ mV)



Active material deposit on cathode side of separator



Anode deposit causing halo mark

Active material deposit on anode side of separator

Moli Cell #PD10SABP037



Marginal OCV reject by 0.3 mV Passed Soft Short Test ($\Delta V = 0.7 \text{ mV}$)

Hole in active material laminated one separator

Active material deposit on anode side of separator with corresponding mark on anode



Separator does not appear to be bridged with active material Stereomicroscope analysis will be done for confirmation

Moli Cell #PD10SAAV120

OCV reject by 69.6 mV Passed Soft Short Test ($\Delta V = 0.5$ mV)



Active material bump on anode coating With corresponding deposit on separator



Shadow of spot on cathode side of separator

Stereomicroscope analysis will determine if material bridge exists

Preliminary Conclusions

- 14-day soft short test identified as suspect 86% of the 27-month OCV storage rejects
- DPA of cells that were too discharged to cycle
 - Revealed suspected bridging defects in the separator of each cell
 - First two that were analyzed with stereomicroscope were confirmed as shorted separator spots
- DPA of cells that did accept cycling and were soft short tested
 - Suspected defects in cells with poor Ah efficiency and ∆V ≥ 1 mV appear more severe than those in cells with good Ah efficiency and good OCV bounce back
- Remaining cell DPAs with stereomicroscope analysis pending
- Preliminary results indicate the value of 14-day soft short test
 - However, its resolution is not as good as received OCV measurement after long storage period (27 months)
- Test protocol may need to be adjusted with YTP cells
 - In 2010, 20% of heritage cells failed, but with lower ΔV declines
 - vs 20% of latest Orion cells failed with $\Delta V \ge 5 \text{ mV}$, 2013
 - The discharge voltage point of test may need to be adjusted higher

Acknowledgements

- Laura Baldwin/NASA-JSC for performing the cycling and soft short testing
- Chris Iannello/NASA Engineering Safety Center for funding the effort