

General Disclaimer

One or more of the Following Statements may affect this Document

- This document has been reproduced from the best copy furnished by the organizational source. It is being released in the interest of making available as much information as possible.
- This document may contain data, which exceeds the sheet parameters. It was furnished in this condition by the organizational source and is the best copy available.
- This document may contain tone-on-tone or color graphs, charts and/or pictures, which have been reproduced in black and white.
- This document is paginated as submitted by the original source.
- Portions of this document are not fully legible due to the historical nature of some of the material. However, it is the best reproduction available from the original submission.

9

AN-S-519



A Facsimile Report

Reproduced by
**UNITED STATES
ATOMIC ENERGY COMMISSION**
Division of Technical Information
P.O. Box 62 Oak Ridge, Tennessee 37830



FACILITY FORM 602

N71-14889	
(ACCESSION NUMBER)	(THRU)
10	H1
(PAGES)	(CODE)
CR-115886	15
(NASA CR OR TMX OR AD NUMBER)	(CATEGORY)

15
SQT-63930R

LEGAL NOTICE



RN-S-0519

WELDABILITY EVALUATION OF THICK SECTIONS
OF HASTELLOY X WITH VARYING ALUMINUM CONTENT

NERVA PROGRAM



CONTRACT SNP-1

NUCLEAR ROCKET OPERATIONS

JULY 1969

CLASSIFICATION CATEGORY

UNCLASSIFIED


CLASSIFYING OFFICER

8 July 69
DATE


AEROJET-GENERAL CORPORATION
A SUBSIDIARY OF THE GENERAL TIRE & RUBBER COMPANY

109

RN-S-0519

WELDABILITY EVALUATION OF THICK SECTIONS
OF HASTELLOY X WITH VARYING ALUMINUM CONTENT

C. W. Fletcher


C. W. Funk, Manager
Materials and Processes
Nuclear Rocket Operations


I. L. Odgers, Manager
Engineering Department
Nuclear Rocket Operations


R. V. Evleth, Manager
NERVA Program Office
Nuclear Rocket Operations

ABSTRACT

Hot cracking and poor wetability of the molten weld metal presented problems in welding the thick sections of the Hastelloy X Phoebus 2 nozzle. A program was conducted to evaluate the effect of varying percentages of aluminum on the weldability of Hastelloy X. The results indicate that lowering the aluminum content of Hastelloy X improves weldability. Utilization of the low-aluminum Hastelloy X material for the NERVA nozzle should result in improved weld quality and lower welding costs.

CONTENTS

<u>No.</u>	<u>Title</u>	<u>Page</u>
I.	Introduction	1
II.	Objective	1
III.	Summary	1
IV.	Conclusions	2

TABLES

<u>No.</u>		<u>Page</u>
1.	Chemical Analysis of Plates and Weld Wire of Several Heats	3
2.	Weldability Evaluation	4

FIGURES

<u>No.</u>		<u>Page</u>
1.	High Aluminum Base Plate - High Aluminum Filler	5
2.	Intermediate Aluminum Base Plate - High Aluminum Filler	6
3.	Intermediate Aluminum Base Plate - Low Aluminum Filler	7
4.	Low Aluminum Base Plate - High Aluminum Filler	8
5.	Low Aluminum Base Plate - Low Aluminum Filler	9
6.	Low Aluminum Base Plate - High Aluminum Filler	10

I. INTRODUCTION

Additions of aluminum which exceed the critical tolerance to fix gas reactions may induce weld hot cracking in nickel base alloys.* Hot cracking and poor wetability of the molten weld metal presented problems in welding the thick sections of the Hastelloy X Phoebus 2 nozzle. The Phoebus nozzle material and weld wire residual aluminum content was in the range of 0.25 to 0.35 percent, with 0.500 percent being the maximum allowed by the material specification. The aluminum forms a stable oxide which inhibits wetability and deposits oxides on the weld surface.

II. OBJECTIVE

The objective of this program was to evaluate the effect of varying percentages of aluminum on the weldability of Hastelloy X.

III. SUMMARY

Four 1-in. thick plates (representing four material heats with varying aluminum compositions) were procured to accomplish the evaluation. Aluminum content of the plates varied from 0.540 percent to 0.010 percent. All heats were vacuum-induction melted with one heat (ESR-68-603) being remelted by the electro-slag process. Hastelloy X weld-wire from two material heats (with aluminum content varying from 0.210 percent to 0.048 percent) was used to accomplish the welding. Material heat numbers and chemical analysis of the plates and weld wire are shown in Table 1. Weld preparation for all plates consisted of a double U-groove with a 60 deg included angle and a 0.050/0.060 root land. The plates were welded by the semi-automatic gas tungsten arc process (GTAW) under controlled conditions with such variables as amperage, voltage, wire-feeds, weld travel-speed, and shielding gas-flows remaining the same for each weldment. Welding conditions were as follows:

*Welding Handbook - Sec. 1, Chapter 2, Page 2.83; Sec 4, Chapter 67, Pages 67.2, 67.3, 67.39.

<u>Amps</u>	<u>Volts</u>	<u>Travel Speed</u>	<u>Wire Feed</u>	<u>Shielding Gas Mixture and Flow Rate</u>
215	9.5	5 in. per min.	30 in. per min.	50% He, - 50% A at 50 C. F. H.

An evaluation of the weldability characteristics of each plate was made by visual observation of the wetability, molten-pool cleanliness, and weld-surface characteristics. The Hastelloy X Phoebus-2 nozzle welding experience was used as a standard of comparison in making the evaluation.

IV. CONCLUSIONS

Oxide content and metal flow of TIG process welds are improved by reducing the Al content of Hastelloy X to 0.01%. There is some indication that the Al content of filler wire is more significant than that of the parent metal.

CHEMICAL ANALYSIS OF PLATES AND WELD WIRE OF SEVERAL HEATS

^aLedoux laboratory analysis

WELD WIRE

TABLE 2

WELDABILITY EVALUATION

<u>Heat No.</u>	<u>Alum. 1</u>	<u>Heat No.</u>	<u>Alum. 2</u>	<u>Weld Photo</u>	<u>Weldability Characteristics</u>
V-18-48-601	0.340	260-5-2784	0.210	Figure 1	<u>High Aluminum Base Plate - High Aluminum Filler</u> Weldability was significantly impaired by the heavy oxide formations. Weldability was poor and the surface of the completed weld bead was covered with a heavy oxide that obscured the normal weld ripple pattern.
V-22-48-632	0.270	260-5-2784	0.210	Figure 2	<u>Intermediate Aluminum Base Plate - High Aluminum Filler</u> Weldability was better than plate 48-601. However, oxide formations were evident which inhibit the flow of the molten metal and, instead of feathering at the weld edge, the molten metal tends to roll over. Oxide was evident on the completed weld, mostly along edge of the weld bead.
ESB-68-603	0.060	260-5-2784	0.210	Figure 3	<u>Low Aluminum Base Plate - High Aluminum Filler</u> An example of the adverse effect of high Al content filler wire on weldability characteristic. Note scattered oxides on weld surface.
V-18-48-617	0.010	260-5-2784	0.210	Figure 4	<u>Low Aluminum Base Plate - High Aluminum Filler</u> The high Al content wire definitely reduced the good weldability characteristics. The molten pool contained oxides and the weldability was somewhat impaired. Scattered oxides were evident on the completed weld.
V-22-48-632	0.270	260-7-2203	0.048	Figure 5	<u>Intermediate Aluminum Base Plate - Low Aluminum Filler</u> Cleanliness and improved fluidity of the molten pool was evident using the low aluminum filler wire. The surface of the completed weld exhibited a good ripple pattern and only one or two small oxide formations.
V-18-48-617	0.010	260-7-2203	0.048	Figure 6	<u>Low Aluminum Base Plate - Low Aluminum Filler</u> Weldability was very good, the flow characteristics were optimum with excellent blending at the edges. The molten pool was clean and the completed weld exhibited a clean surface and a well-defined ripple pattern.




P.M. V-18-68-601 0.540 % Al
F.M. 260-5-2784 0.210 % Al




Weldability was significantly impaired by the heavy oxide formations. Wetability was poor and the surface of the completed weld bead was covered with a heavy oxide that obscured the normal weld ripple pattern. Typical oxide formation is indicated by the arrows.

Figure 1 - High Aluminum Base Plate - High Aluminum Filler




Weldability was better than plate 68-601. However oxide formations were evident which inhibit the flow of the molten metal and, instead of feathering at the weld edge, the molten metal tends to roll-over. This roll-over usually causes voids or lack of fusion in multiple-pass welds. Oxide was evident on the completed weld, mostly along edge of the weld bead. Typical oxide formation is indicated by the arrows.

Figure 2 - Intermediate Aluminum Base Plate - High Aluminum Filler




An example of the adverse effect of high Al content filler wire on weldability characteristics. Note scattered oxides on weld surface. Typical oxide formation is indicated by the arrows.

Figure 3 - Low Aluminum Base Plate - High Aluminum Filler




The high Al content wire definitely reduced the good weldability characteristics. The molten pool contained oxides and the wetability was somewhat impaired. Scattered oxides were evident on the completed weld. Typical oxide formation is indicated by the arrows.

Figure 4 - Low Aluminum Base Plate - High Aluminum Content Filler



Cleanliness and improved fluidity of the molten pool was evident using the low aluminum filler wire. The surface of the completed weld exhibited a good ripple pattern and only one or two small oxide formations. Typical oxide formation is indicated by the arrow.

Figure 5 - Intermediate Aluminum Base Plate - Low Aluminum Filler



Weldability was very good, the flow characteristics were optimum with excellent blending at the edges. The molten pool was clean and the completed weld exhibited a clean surface and a well-defined ripple pattern.

Figure 6 - Low Aluminum Base Plate - Low Aluminum Filler