


N 71-22511
GESP-587
NASA-CR-72829



**CASE FILE
COPY**

**TOPICAL REPORT NO. 4
SNAP-8 REFRACTORY BOILER DEVELOPMENT PROGRAM**

**MERCURY THERMAL SHOCK TESTING OF 2½-INCH-DIAMETER
BIMETALLIC JOINTS FOR SNAP-8 APPLICATIONS**

**By
S. R. Thompson**

**prepared for
NATIONAL AERONAUTICS AND SPACE ADMINISTRATION**

**NASA Lewis Research Center
Contract NAS 3-10610
Edward R. Furman, Project Manager**

**NUCLEAR SYSTEMS PROGRAMS
SPACE SYSTEMS
GENERAL  ELECTRIC
CINCINNATI, OHIO 45215**

REPRODUCIBLE COPY

NOTICE

This report was prepared as an account of Government sponsored work. Neither the United States, nor the National Aeronautics and Space Administration (NASA), nor any person acting on behalf of NASA:

- A.) Makes any warranty or representation, expressed or implied, with respect to the accuracy, completeness, or usefulness of the information contained in this report, or that the use of any information, apparatus, method, or process disclosed in this report may not infringe privately owned rights; or
- B.) Assumes any liabilities with respect to the use of, or for damages resulting from the use of any information, apparatus, method or process disclosed in this report.

As used above, "person acting on behalf of NASA" includes any employee or contractor of NASA, or employee of such contractor, to the extent that such employee or contractor of NASA, or employee of such contractor prepares, disseminates, or provides access to, any information pursuant to his employment or contract with NASA, or his employment with such contractor.

Requests for copies of this report should be referred to:

National Aeronautics and Space Administration
Scientific and Technical Information Division
Attention: USS-A
Washington, D.C. 20546

TOPICAL REPORT NO. 4

SNAP-8 REFRACTORY BOILER DEVELOPMENT PROGRAM

MERCURY THERMAL SHOCK TESTING OF 2 $\frac{1}{2}$ -INCH-DIAMETER
BIMETALLIC JOINTS FOR SNAP-8 APPLICATIONS

prepared by

S. R. Thompson

NUCLEAR SYSTEMS PROGRAMS
SPACE DIVISION
GENERAL ELECTRIC COMPANY
Cincinnati, Ohio 45215

prepared for

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION

NASA Lewis Research Center
Contract NAS 3-10610
Edward R. Furman, Project Manager

TABLE OF CONTENTS

<u>Section</u>		<u>Page No.</u>
I.	Introduction.....	1
II.	Test Specimen Preparation.....	2
III.	Thermal Shock Testing.....	2
IV.	Posttest Evaluation of Tested Brazed Specimens.....	12
	A. Nondestructive Examination.....	12
	B. Destructive Evaluation.....	16
	1. Visual Examination of Interior Pipe Surfaces.....	16
	2. Hardness Testing and Microstructural Examination.....	16
V.	Summary of Evaluation Data from Failed Coextruded Joint.....	28
VI.	Summary.....	33
	References.....	35

LIST OF FIGURES

	<u>Page No.</u>
1. Braze Joint Design Configuration.....	3
2. Bimetallic Joint Thermal Shock Test-Section.....	5
3. Tantalum/Type 316 Stainless Steel Bimetallic Joint Mercury Thermal Shock Test Facility - Schematic.....	6
4. Typical Thermal Shock Cycle of 2 1/2-Inch-Diameter, SNAP-8 Type, Tantalum/Type 316 Stainless Steel Bimetallic Joint - Mercury Thermal Shock Test.....	7
5. Transient Temperatures of 2 1/2-Inch-Diameter, Tantalum/Type 316 Stainless Steel, Coextruded and Braze Joints - Mercury Thermal Shock Test.....	9
6. Transient Temperatures of 2 1/2-Inch-Diameter, Tantalum/Type 316 Stainless Steel Braze Joints - Mercury Thermal Shock Test.....	11
7. Thermal Shock Specimen (Two Braze Joints) after Test Exposure.....	13
8. "C" Scan Recordings from Braze Tantalum/Type 316 Stainless Steel Joints after Mercury Thermal Shock Test.....	15
9. Hardness Traverse across Wall of 2 1/2-Inch-Diameter Tantalum/Type 316 Stainless Steel Transition Joint (S/N 16-16 at 226°) after Mercury Thermal Shock Test (100 Cycles).....	17
10. Hardness Traverse across Wall of 2 1/2-Inch-Diameter Tantalum/Type 316 Stainless Steel Transition Joint (S/N 14-14 at 0°) after Mercury Thermal Shock Test (155 Cycles).....	18
11. Representative Microstructures of Braze Transition Joint, S/N 14-14, after Mercury Thermal Shock Test (155 Cycles).....	19
12. Representative Microstructure of Braze Transition Joint, S/N 16-16, after Mercury Thermal Shock Test (100 Cycles).....	20
13. Typical Microstructure at Inside Braze Fillet of Braze Joint, S/N No. 16-16, after Mercury Thermal Shock Test (100 Cycles)....	22
14. Microstructure Near Base of Tongue and Groove of Braze Joint, S/N No. 16-16, at 226° Rotation, after Mercury Thermal Shock Test (100 Cycles).....	24

LIST OF FIGURES (Cont.)

	<u>Page No.</u>
15. Presentations from Ultrasonic Inspection of Coextruded Tantalum/Type 316 Stainless Steel Joint after Mercury Thermal Shock Test (55 Cycles).....	29
16. Typical Microstructures in Joint Area of Coextruded Tantalum/ Type 316 Stainless Steel Joint after Mercury Thermal Shock Test (55 Cycles).....	30

ABSTRACT

Coextruded and brazed tubular transition joints, between 2.5-inch-outside diameter tantalum and Type 316 stainless steel, were evaluated for usage in the SNAP-8 Mercury Power Conversion System. Representative joints were exposed to repeated thermal shocks by flowing 300°F mercury through the joints which were initially heated to 1300°F. Failure of the coextruded specimen occurred after 55 thermal shocks; no brazed joint failure was noted after testing to 100 and 155 cycles (two brazed samples). Posttest destructive and nondestructive examination of the sample assemblies indicated that the braze method produced assemblies which were essentially unaffected by the shock testing. The results of the above testing, and other severe thermal shock tests of this type of joint, show that the brazing method for effecting transitions between tantalum and stainless steel will produce a reliable joint for SNAP-8 applications.

FOREWORD

This report was prepared and the associated work performed in support of NASA program, "SNAP-8 Refractory Boiler Development," Contract No. NAS 3-10610, under the management of R. D. Brooks.

The author gratefully acknowledges the contributions of J. Holowach, responsible for performance of the thermal shock testing; W. F. Zimmerman, for assistance in interpretation and evaluation of posttest data; and W. R. Young, for reviewing the content of the report. In addition, valuable assistance was provided by H. J. Bauer, I. A. Miller, and C. Asaud in the preparation and examination of the metallographic specimens.

MERCURY THERMAL SHOCK TESTING OF 2 1/2-INCH-DIAMETER BIMETALLIC JOINTS FOR SNAP-8 APPLICATIONS

I. Introduction

The Aerojet-General Corporation Specification AGC-10512, Power Conversion System, Ground Model (PSC-8), SNAP-8 requires that the mercury boiler be capable of a minimum of 100 restarts with a design life of 10,000 operational hours. The basic materials utilized in the system are unalloyed tantalum for the boiler tubes and Type 316 stainless steel for the remaining loop components. Both of these materials had been shown to have excellent individual resistance to mercury attack under conditions associated with the application.^(1, 2) The startup sequence of the SNAP-8 power conversion system subjects the entire boiler section to a severe thermal shock when 70°F mercury is injected into the 1300°F boiler. Further, for the present boiler design, 2.50-inch-outside-diameter tantalum-to-Type 316 stainless steel tubular transition joints are required at both the inlet and exit of the boiler. Two candidate methods under consideration for fabrication of the bimetallic transition joints were coextrusion and brazing. Representative joints - coextruded, manufactured by Nuclear Metals, Inc., and brazed, fabricated by GE - NSP - were prepared for thermal shock testing to establish the relative reliability of the different designs and manufacturing processes. The testing parameters selected were more severe than those conditions associated with normal startup of the power conversion system. The mercury testing also provided a quantitative means for reaffirming the resistance to mercury attack of the tantalum - braze alloy - stainless steel materials combination under SNAP-8 operating conditions, which had been established earlier for smaller diameter brazed joints.⁽³⁾


II. Test Specimen Preparation

The basic design configuration for the 2.5-inch-OD brazed samples was a tongue-in-groove, as shown in Figure 1. The two brazed assemblies (Serial No's 14-14 and 16-16) discussed within this report, were vacuum brazed at 2160°F - 2180°F for five minutes, using the cobalt-base filler alloy designated J-8400 (B50T56-S1)*. After brazing, both brazed assemblies were nondestructively inspected using visual, dye penetrant, ultrasonic, and mass spectrometer techniques, and no rejectionable defects were observed. The Nuclear Metals, Inc. coextruded joint was purchased by the NASA - Lewis Research Laboratory and assigned to GE - NSP for thermal shock testing without performance of additional pretest inspection by GE - NSP. In addition to the different methods utilized in fabrication of the test specimens, the wall thickness of the coextruded joint was 0.020 inch less than that of either brazed assembly; i.e., 0.110 inch vs. 0.130 inch.


III. Thermal Shock Testing

For the initial shock testing, brazed sample S/N No. 14-14 and the coextruded specimen were assembled to form a test section by tungsten inert gas (TIG) welding the tantalum ends of each together. The welded assembly was positioned with the coextruded joint nearest the mercury inlet end for the forthcoming thermal testing. A 0.060-inch-diameter orifice plate was inserted downstream of the two bimetallic joints to restrict the flow of mercury through the test section and rapidly build up the inlet mercury pressure to suppress film boiling of the mercury in the joint areas.


* Braze Alloy Composition: 21Cr-21Ni-3.5W-8.0Si-0.8B-0.04C-Bal. Co.




(PIA) MAT'L - 316 SST
SEAMLESS TUBING PER
ASTM A 269-65



(PIB) MAT'L - TANTALUM
UNALLOYED PER
ASTM B-365-62T EXCEPT
H₂ LESS THAN 10 PPM



VIEW AT G
SCALE 4/1



VIEW AT H
SCALE 4/1

- 6 ULTRASONIC INSPECT PER GE SPPS SPEC 03-0001-00-B OR X-RAY PER AMS 2635 ASSY FOR INTERNAL DEFECTS
- 5 PENETRANT INSPECT PER AMS 2645
- 4 MASS SPECTROMETER LEAK TEST PER GE SPPS SPEC 03-0013-00-B
- 3 CLEAN PER GE SPPS SPEC 03-0021-00-A
- 2 PARTS PIA & PIB MUST BE BAGGED OR TAGGED AS A MATCHED ASSY WITH IDENT & SERIAL NO
- 1 INTERPRETATION OF DWG TERMS AND TOL. PER GE SPPS SPEC 06-0002-00-A

Figure 1. Brazed Joint Design Configuration, Dwg. No. 47C143236.

A vacuum jacket was assembled around the test section to protect the tantalum members of the bimetallic joints from surface contamination during the temperature cycles. The jacket was fabricated from standard vacuum components with either welded or copper gasket joints. A flexible bellows coupling was used to accommodate the differential thermal expansion between the test section and the vacuum jacket during the heating and cooling cycle. The bimetallic joints were heated with an electrical resistance heater attached to the vacuum jacket section surrounding the bimetallic joints. Heat was transferred from the vacuum jacket to the bimetallic joints by thermal radiation. A chromel/alumel thermocouple was attached to both the stainless steel and tantalum sections of each bimetallic joint. Test temperatures were recorded with a high-speed recording potentiometer which allowed the temperature transients of each joint to be compared. The test section assembly is shown in Figure 2.

The thermal shock test facility consisted of a mercury EM pump, the test section, and a water-cooled heat exchanger as shown in Figure 3. An evacuation and gas pressurization port was used to evacuate the loop before the test and to pressurize the test section with helium for mass spectrometer leak testing of the bimetallic joints at specified intervals during the test. The test section was placed in a vertical position to allow the mercury to gravity drain from the test section after each thermal shock.

The thermal shock cycle as shown in Figure 4 was as follows: the electric power to the heater was adjusted to heat the bimetallic joints to 1300°F in 30 minutes. This temperature was maintained at the joints




Figure 10. Hardness Traverse Across Wall of 2 1/2-Inch Diameter Tantalum/Type 316 Stainless Steel Transition Joint (S/N 14-14 at 0°) After Mercury Thermal Shock Test (155 Cycles).




Figure 11. Representative Microstructures of Brazed Transition Joint, S/N No. 14-14, After Mercury Thermal Shock Test (155 Cycles).





Figure 12. Representative Microstructures of Brazed Transition Joint, S/N No. 16-16, After Mercury Thermal Shock Test (100 Cycles).

entrance braze flow side (outermost tantalum section). The reaction zone in the stainless steel was largest on the inside surfaces of the tongue (Kn 270 at 0.002 inch from the interface and Kn 200, 0.006 inch away); the lower hardness readings were encountered less than 0.002 inch away from the outside surfaces of the stainless steel tongue. The width of the diffusion zone in the outermost tantalum areas was approximately 0.007 inch to 0.011 inch; the hardness decreased in that area from Kn 180, 0.0005 inch from the braze interface to the base hardness of Kn 125.

Previous studies on Cb-1Zr/Type 316 stainless steel brazed transitions, using the J-8400 braze alloy⁽⁵⁾ have demonstrated that the formation of an intermetallic phase at the Cb-1Zr-braze alloy interface during brazing limited the amount of interdiffusion occurring during subsequent 1600°F/1000-hour exposures in vacuum. Microstructural examination of the tantalum/Type 316 stainless steel, 2.5-inch-OD joints, indicated the presence of a similar phase, as shown in Figures 11 and 12. If equivalent reaction rates are assumed between the braze alloy and both Cb-1Zr and tantalum, then the above indicated diffusion in the tantalum probably occurred during brazing.

Microstructural examination at high magnification (to 1000X) of the internal piping surfaces and the internal braze fillets produced no significant evidence of mass transfer, mercury corrosion, or joint deterioration caused by the repeated thermal/mercury shock cycles. Figure 13 shows a typical appearance of the inner braze fillet area for joint S/N No. 16-16; similar structures were also present at the inner fillet areas of joint S/N No. 14-14.

Microshrinkage voids were discovered to varying degrees in the



Neg. 11304

Mag.: 100X




Figure 13. Typical Microstructure at Inside Braze Fillet of Brazed Joint, S/N No. 16-16, After Mercury Thermal Shock Test (100 Cycles).

brazed flow paths of both assemblies. These voids were formed on cooling from the original brazing thermal cycle - they occur in the last portions of the braze alloy which solidify, and their occurrence is a normal brazing by-product if freezing of the alloy at a location between the entrance feed fillet and the discussed area blocks the supply of liquid braze. As shown in Figures 12B and 14B, the largest zones of microshrinkage were found in joint S/N No. 16-16, near the base of the tongue and groove in the sections taken at 180° and 226° rotation from the ultrasonic inspection reference index. As indicated previously, these sections represented (ultrasonic) intermediate and best-bonded areas of that assembly, and their presence to the extent shown in the microphotographs was not anticipated. Further, the extent of their size and agglomeration, while greater than desired, was not prohibitive from a brazing or structural standpoint. Microstructural examination of the most suspect area (at 0° rotation) of Specimen S/N No. 16-16 revealed a completely sound brazed section, in direct contradiction to the ultrasonic data. The lack of agreement, between the ultrasonic indications and the actual microstructures present, may possibly be explained by realizing that in cutting the assemblies, and subsequent metallographic preparation, material removal may be somewhat different than expected. Thus, the sections examined may not have coincided exactly with the desired locales, and the joint characteristics could be completely different at the positions examined.

The metallographic sections prepared from joint S/N No. 14-14, at 0°, 160°, and 316° rotation from the ultrasonic index, yielded essentially identical microstructures. Again, complete agreement between the actual




Figure 14. Microstructures Near Base of Tongue and Groove of Brazed Joint, S/N No. 16-16 at 226° After Rotation Mercury Thermal Shock Test (100 Cycles).

structures and the ultrasonic indications was not achieved, although generally better correlation was evident than with sample S/N No. 16-16. The microshrinkage present in sample S/N No. 14-14 (Figure 11A) was uniformly widespread, and individual voids were very small (0.0001 inch). It was possible that these voids were the cause for the ultrasonic indications at the above specified locations if the inspection equipment sensitivity was set too high. Also, the spacing between each void (approximately 0.010 inch) may have been small enough that the sensing transducer could not resolve their separation, since the transducer does sweep a finite distance. One additional factor that should be pointed out, since it could have influenced the ultrasonic data, was that the braze alloy on the inside of the tongue and groove (both brazed assemblies) was two-phase in nature, as shown in Figures 11A and 12A. This zoning effect essentially represented another possible interface, and the chemistry changes present therein could have altered the speed of the sound waves passing through, which in turn could cause suspect areas to appear on the ultrasonic "A" scans. Because none of the described phenomena for joint S/N No. 14-14, as well as joint S/N No. 16-16, were unacceptable from a structural standpoint, it was obvious that the ultrasonic inspection technique required refinement to more clearly define objectionable defects. The bulk of the difficulties associated with ultrasonic inspection of tongue-in-groove brazed specimens were contingent on the lack of a satisfactory "standard" brazed specimen. To alleviate the problem, "standard" specimens containing good and bad brazed areas at prespecified locations, are presently being prepared for future applications.

Other pertinent facts established by the microstructural examination and microhardness testing of the brazed specimens were as follows:

- a. The capillary spacing between the outside of the tongue and groove for the two specimens was different; 0.0015 inch for joint S/N No. 14-14, 0.005 inch for joint S/N No. 16-16.
- b. The previously mentioned microshrinkage voids in both brazed samples were prevalent in the wide gap side of the tongue and groove, in the light etching areas of the two-zone braze material. The braze material in the outside of the tongue and groove etched darker and was essentially free of voids.
- c. The two-zone nature of the braze in S/N No. 16-16 extended around the base of the tongue from the wide gap side and into the 0.005 inch capillary side for approximately 0.030 inch. Thus, some microshrinkage was also noted on the capillary side of that joint (see Figure 12B).
- d. The grain size of the stainless steel in the tongue areas of the brazed joints was larger than that determined in the remainder of that component. Two possible reasons for this larger grain size were stresses associated with (1) the original machining operation and/or (2) differential thermal expansion/contraction induced during testing. These stresses could have caused plastic deformation which coupled with the elevated test temperatures resulted in the increased grain size.
- e. The reaction zones identified in the stainless steel tongues by the microhardness testing resulted primarily from interdiffusion

with the J-8400 braze alloy. This was substantiated further by the fact that the grains in that area were equiaxed, implying that the thermal/mechanical stresses induced during machining or testing were completely relieved.

- f. As shown in Figure 14B, the corners at the base of the tongue and groove of joint S/N No. 16-16 were rounded (approximately 0.001-inch radius). This effect could have been produced by (1) interalloying of the base metals with the braze alloy during the brazing cycle or (2) the initial machining operation. In either event, the effect was beneficial, since the stress concentration factors are reduced; thus, the assembly can more readily withstand the stresses associated with thermal cycling. A similar corner rounding was observed for joint S/N No. 14-14.

No detrimental reactions between the joint components and mercury were noted; nor did the thermal stresses during testing cause degradation of the brazement with the possible exception of the stainless steel variation in grain size. Also, the fact that the ultrasonic inspection results before and after the thermal shock test were identical was meaningful because any significant degradation would no doubt have been identified by that technique. Since no change was observed in that data, the metallurgical phenomena observed were attributed primarily to the brazing operations and not to the thermal shock testing.


V. Summary of Evaluation Data from Failed Coextruded Joint

The 2 1/2-inch-diameter tantalum/Type 316 stainless steel coextruded joint was examined, after testing, nondestructively by ultrasonic and dye penetrant techniques and then sectioned for metallographic examination.

The ultrasonic inspection was performed using a focused transducer and a longitudinal wave mode through the total joint wall thickness; scans were made circumferentially along the outside diameter of the joint area. A "C"scan ultrasonic trace was prepared, from repeated "A" scans, by means of appropriate gating techniques, to differentiate and record any electronic signals different from those obtained for the outside and inside tube wall reflections and those found for a completely bonded cross section. The nature of the ultrasonic indications is shown in Figure 15.

The locations of the principal ultrasonic suspect areas were marked on the outside of the tested joint; after which the assembly was dye penetrant ("Zyglo") inspected. Continuous indications were noted around the "feather" edge of the joint area on the inside of the assembly and at several locations on the outside feather edge.


After "Zyglo" inspection, the joint was sectioned for microstructural study at the principal ultrasonic and "Zyglo" suspect areas. Several microstructures obtained at these locations are presented in Figure 16. The correlation between the inspection indications and the actual microstructures was excellent; i.e., at every suspect location examined, separation of the interface was observed metallographically. No evidence of any significant intermetallic phase formation at the interface was observed during examinations to 1000X. Further, no microstructural



- I. C-scan recording depicting areas of interface discontinuity. White indicates response areas.
- II. Longitudinal cross section indicating depth of indications relative and wall thickness. Note depth of #3
- III. Transverse cross section of joint indicating depth of indication and method of ultrasonic inspection.
- IV. A-scan presentation of A. defect #0 near OD B. defect #2 depth C. defect #1 & 4 depth D. defect #3 change of depth E. & F. change of time base due to velocity change created by change of ratio of Cb-1Zr to S.S.

Figure 15. Presentations from Ultrasonic Inspection of Coextruded Tantalum/Type 316 Stainless Steel Joint After Mercury Thermal Shock Test (55 Cycles).


Transverse Section



Unetched
F900311


Mag.: 50X

Longitudinal Section




Unetched
F900611

Mag.: 50X



Etchant: 10 Oxalic
100 H₂O
Electrolytic
F900313

Mag.: 1000X



Etchant: 10 Oxalic
100 H₂O
Electrolytic
F900614

Mag.: 1000X

Figure 16. Typical Microstructures in Joint Area Coextruded Tantalum/Type 316 Stainless Steel Joint After Mercury Thermal Shock Test (55 Cycles).

indications of mercury corrosion or erosion were found along the inside of the assembly. Microhardness traverse data were determined across the wall of the coextruded specimen. As shown in Table I, essentially constant hardness values were obtained throughout the individual components, tantalum and stainless steel, in the joint area. The data also verified the visual observations that no intermetallic phases were present at the joint interfaces.

The susceptibility of the coextruded joint to failure under severe thermal shock conditions was clearly indicated. Further, good agreement was realized between ultrasonically detected flaw locations and actual separation points of the joint.

TABLE I

TYPICAL MICROHARDNESS VALUES ACROSS WALL OF 2 1/2-INCH-
DIAMETER COEXTRUDED SPECIMEN AFTER MERCURY THERMAL SHOCK TEST

<u>Impression Location</u> (Inches from Interface)		<u>Hardness</u> (Knoop-100 gm Load)
0.002	} In Stainless Steel	251
0.004		258
0.006		258
0.008		272
0.010		247
0.012		259
0.014		259
0.016		259
0.018		263
0.002	} In Tantalum	159
0.004		146
0.006		154
0.008		166
0.010		156
0.012		151
0.014		156
0.016		147
0.018		138
0.020		140
0.022		159

VI. Summary

Tubular transition joints between 2.5-inch-OD tantalum and Type 316 stainless steel are required as components in the SNAP-8 Power Conversion System which utilizes mercury as the working fluid. Two candidate fabrication methods, coextrusion and brazing, were considered and both subsequently evaluated by exposing representative joints to repeated thermal shocks in the 1300°F to 300°F temperature range. Each individual thermal cycle was achieved by flowing mercury at 300°F through the joints which were initially heated to 1300°F. These test parameters were selected to simulate those conditions expected at the joint transitions during start-up of the SNAP-8 system. Failure of the coextruded joint was observed after 55 thermal cycles. The failed joint was subsequently replaced by another brazed joint and the testing continued until the initial brazed assembly had accumulated a total of 155 thermal shocks. Subsequent posttest examination of the brazed joints, using both destructive and nondestructive inspection techniques, indicated that the braze method (1) produced assemblies which were essentially unaffected by the mercury exposure and (2) could be used with a high degree of reliability to fabricate the transition joints necessary for the power conversion system. This report summarizes the results of the posttest evaluation of the brazed joints which support the previous statement regarding the suitability of the brazed technique for fabrication of the tantalum/stainless steel SNAP-8 bimetallic transitions.

REFERENCES

1. Engel, L. B. and Harrison, R. W., "The Corrosion Resistance of Tantalum, T-111, and Cb-1Zr to Mercury at 1200°F," Topical Report No. 2 for Program NAS 3-10610.
2. Weeks, J. R., "Liquidus Curves and Corrosion of Fe, Cr, Ni, Co, V, Cb, Ta, Ti, Zr in 500-750°C Mercury," Corrosion, Vol. 23, No. 4, pp. 98-106, April (1967).
3. Thompson, S. R. and Holowach, J., "SNAP-8 Mercury Thermal Shock Test of Bimetallic Joints," GESP-45, R68NSP-1, June 26, 1968.
4. Brooks, R. D., Editor, "SNAP-8 Refractory Boiler Development," NASA Contract No. NAS 3-10610, Monthly Status Report, Report Period Ending 10-18-68.
5. Jones, M. H. and Tippetts, F. E., Editors, "Heat Transfer Development Program," Monthly Status Report on NASA Contract NAS 3-2528 for the Period November 1, 1964 to November 30, 1964.

DISTRIBUTION LIST
TOPICAL REPORT
CONTRACT NAS 3-10610

NASA
Washington, D.C. 20546
Attn: P. R. Miller (RNP)

NASA
Washington, D.C. 20546
Attn: James J. Lynch (RNP)

NASA
Washington, D.C. 20546
Attn: George C. Deutsch (RR)

NASA
Washington, D.C. 20546
Attn: Dr. Fred Schulman (RNP)

NASA
Washington, D.C. 20546
Attn: H. Rothen (RNP)

NASA
Scientific and Tech. Info. Facility
P.O. Box 33
College Park, Maryland 20740
Attn: Acquisitions Branch
(SQT - 34054) 2 Copies

NASA
Ames Research Center
Moffett Field, California 94035
Attn: Librarian

NASA
Goddard Space Flight Center
Greenbelt, Maryland 20771
Attn: Librarian

NASA
Langley Research Center
Hampton, Virginia 23365
Attn: Librarian

NASA
Manned Spacecraft Center
Houston, Texas 77001
Attn: Librarian

NASA
George C. Marshall Space Flight Ctr.
Huntsville, Alabama 35812
Attn: Librarian

NASA
Jet Propulsion Laboratory
4800 Oak Grove Drive
Pasadena, California 91103
Attn: Librarian

NASA
Lewis Research Center
21000 Brookpark Road
Cleveland, Ohio 44135
Attn: Librarian

NASA
Lewis Research Center
21000 Brookpark Road
Cleveland, Ohio 44135
Attn: H. O. Slone, MS 500-201

NASA
Lewis Research Center
21000 Brookpark Road
Cleveland, Ohio 44135
Attn: G. M. Ault, MS 105-1

NASA
Lewis Research Center
21000 Brookpark Road
Cleveland, Ohio 44135
Attn: P. L. Stone, MS 106-1

NASA
Lewis Research Center
21000 Brookpark Road
Cleveland, Ohio 44135
Attn: G. M. Thur, MS 500-202

NASA
Lewis Research Center
21000 Brookpark Road
Cleveland, Ohio 44135
Attn: John E. Dilley, MS 500-309

NASA
Lewis Research Center
21000 Brookpark Road
Cleveland, Ohio 44135
Attn: Technology Utilization, MS 3-19

Report Distribution List - NAS 3-10610 - Topical (Continued)

NASA

Lewis Research Center
21000 Brookpark Road
Cleveland, Ohio 44135
Attn: Report Control Office, MS 5-5

NASA

Lewis Research Center
21000 Brookpark Road
Cleveland, Ohio 44135
Attn: R. L. Davies, MS 106-1

NASA

Lewis Research Center
21000 Brookpark Road
Cleveland, Ohio 44135
Attn: V. F. Hlavin, MS 3-14
(Final Only)

NASA

Lewis Research Center
21000 Brookpark Road
Cleveland, Ohio 44135
Attn: E. R. Furman, MS 500-202
3 Copies

NASA

Lewis Research Center
21000 Brookpark Road
Cleveland, Ohio 44135
Attn: M. J. Saari, MS 500-202

NASA

Lewis Research Center
21000 Brookpark Road
Cleveland, Ohio 44135
Attn: R. English, MS 500-201

NASA

Lewis Research Center
21000 Brookpark Road
Cleveland, Ohio 44135
Attn: M. Gutstein, MS 500-201

National Bureau of Standards
Washington, D.C. 20546
Attn: Librarian

AFSC

Aeronautical Systems Division
Wright-Patterson AFB, Ohio 45433
Attn: Charles Armbruster (ASRPP-10)

AFSC

Aeronautical Systems Division
Wright-Patterson AFB, Ohio 45433
Attn: T. Cooper

AFSC

Aeronautical Systems Division
Wright-Patterson AFB, Ohio 45433
Attn: Librarian

Army Ordnance Frankford Arsenal
Bridesburg Station
Philadelphia, Pennsylvania 19137
Attn: Librarian

U.S. Atomic Energy Commission
Tech. Info. Service Extension
P.O. Box 62
Oak Ridge, Tennessee 37831

U.S. Atomic Energy Commission
Washington, D.C. 20545
Attn: M. J. Whitman

U.S. Atomic Energy Commission
Washington, D.C. 20545
Attn: J. M. Simmons

Argonne National Laboratory
9700 South Cass Avenue
Argonne, Illinois 60440
Attn: Librarian

Battelle Memorial Institute
505 King Avenue
Columbus, Ohio 43201
Attn: R. T. Nichoff, DMIC

Battelle Memorial Institute
505 King Avenue
Columbus, Ohio 43201
Attn: Librarian

Brookhaven National Laboratory
Upton, Long Island, New York, 11973
Attn: Librarian

Brookhaven National Laboratory
Upton, Long Island, New York 11973
Attn: Dr. D. H. Gurinsky

Report Distribution List - NAS 3-10610 - Topical (Continued)

Brookhaven National Laboratory
Upton, Long Island, New York 11973
Attn: Dr. J. R. Weeks

Oak Ridge National Laboratory
Oak Ridge, Tennessee 37831
Attn: J. Devan

Oak Ridge National Laboratory
Oak Ridge, Tennessee 37831
Attn: R. MacPherson

Oak Ridge National Laboratory
Oak Ridge, Tennessee 37831
Attn: Librarian

Office of Naval Research
Power Division
Washington, D.C. 20360
Attn: Librarian

Bureau of Weapons
Research and Engineering
Materials Division
Washington, D.C. 20546
Attn: Librarian

U.S. Naval Research Laboratory
Washington, D.C. 20390
Attn: Librarian

Aerojet-General Corporation
Electronics Division
Azusa, California 91703
Attn: Librarian

AiResearch Manufacturing Company
Division of the Garrett Corporation
Sky Harbor Airport
402 South 36th Street
Phoenix, Arizona 85034
Attn: Librarian

AiResearch Manufacturing Company
Division of the Garrett Corporation
9851-9951 Sepulveda Boulevard
Los Angeles, California 90009
Attn: Librarian

IIT Research Institute
10 West 35th Street
Chicago, Illinois 60616
Attn: Librarian

Babcock & Wilcox Company
Research Center
Alliance, Ohio 44601
Attn: Librarian

North American Rockwell Corporation
Atomics International Division
8900 DeSoto Avenue
Canoga Park, California 91304
Attn: Librarian

North American Rockwell Corporation
Atomics International Division
8900 DeSoto Avenue
Canoga Park, California 91304
Attn: P. B. Ferry

North American Rockwell Corporation
Atomics International Division
8900 DeSoto Avenue
Canoga Park, California 91304
Attn: T. A. Moss

AVCO
Research & Advanced Development Dept.
201 Lowell Street
Wilmington, Massachusetts 01887
Attn: Librarian

Electro-Optical Systems, Inc.
Advanced Power Systems Division
Pasadena, California 91107
Attn: Librarian

Fansteel Metallurgical Corporation
North Chicago, Illinois 18201
Attn: Librarian

General Dynamics Corporation
General Atomic Division
John Jay Hopkins Lab.
P.O. Box 608
San Diego, California 92112
Attn: Librarian

General Electric Company
Space Division
3198 Chestnut Street
Philadelphia, Pennsylvania 19104
Attn: Librarian

Report Distribution List - NAS 3-10610 - Topical (Continued)

General Electric Company
Vallecitos Atomic Laboratory
Pleasanton, California 94566
Attn: Librarian

General Dynamics/Fort Worth
P.O. Box 748
Fort Worth, Texas 76101
Attn: Librarian

General Motors Corporation
Allison Division
Indianapolis, Indiana 46206
Attn: Librarian

Hamilton Standard
Division of United Aircraft Corp.
Windsor Locks, Connecticut 06096
Attn: Librarian

Hughes Aircraft Company
Engineering Division
Culver City, California 90230
Attn: Librarian

Lawrence Radiation Lab.
Livermore, California 94550
Attn: Librarian

Lockheed Missiles and Space Div.
Lockheed Aircraft Corporation
Sunnyvale, California 90221
Attn: Librarian

The Martin Company
Nuclear Division
P.O. Box 5042
Baltimore, Maryland 21203
Attn: Librarian

Martin Marietta Corporation
Metals Technology Laboratory
Wheeling, Illinois 60090

Materials Research Corporation
Orangeburg, New York 10962
Attn: Librarian

McDonnell Aircraft
St. Louis, Missouri 63166
Attn: Librarian

MSA Research Corporation
Callery, Pennsylvania 16024
Attn: Librarian

National Research Corporation
70 Memorial Drive
Cambridge, Massachusetts 02142
Attn: Librarian

North American Rockwell
Los Angeles Division
Los Angeles, California 90009
Attn: Librarian

United Aircraft Corporation
Pratt & Whitney Aircraft Division
400 Main Street
East Hartford, Connecticut 06108
Attn: Librarian

Republic Aviation Corporation
Farmingdale, Long Island, New York 11735
Attn: Librarian

Sandia Corporation
P.O. Box 5800
Albuquerque, New Mexico 87116
Attn: Librarian

Sandia Corporation
P.O. Box 5800
Albuquerque, New Mexico 87116
Attn: Don Johnson

Solar
2200 Pacific Highway
San Diego, California 92112
Attn: Librarian

Southwest Research Institute
8500 Culebra Road
San Antonio, Texas 78220
Attn: Librarian

Superior Tube Company
Norristown, Pennsylvania 19404
Attn: L. Shaheen

Philco Corporation
Aeronutronics
Newport Beach, California 92663
Attn: Librarian

Report Distribution List - NAS 3-10610 - Topical (Continued)

General Electric Company
Nuclear Systems Program
Space Division
Cincinnati, Ohio 45215

General Electric Company
Evendale, Ohio 45215
Technical Information Center
Building 700, Mail Drop N-32

TRW Inc.
23555 Euclid Avenue
Cleveland, Ohio 44117
Attn: Librarian

Union Carbide Corporation
Materials Systems Division
1020 W. Park
Kokomo, Indiana 46901
Attn: Librarian

Union Carbide Corporation
Materials Systems Division
1020 W. Park
Kokomo, Indiana 46901
Attn: Technology Department

Wah Chang Corporation
Albany, Oregon 97321
Attn: Librarian

Westinghouse Electric Corporation
Astronuclear Laboratory
P.O. Box 10864
Pittsburgh, Pennsylvania 15236
Attn: R. W. Luckman

Westinghouse Electric Corporation
Astronuclear Laboratory
P.O. Box 10864
Pittsburgh, Pennsylvania 15236
Attn: G. G. Lessman

Westinghouse Electric Corporation
Astronuclear Laboratory
P.O. Box 10864
Pittsburgh, Pennsylvania 15236
Attn: D. R. Stoner

Westinghouse Electric Corporation
Astronuclear Laboratory
P.O. Box 10864
Pittsburgh, Pennsylvania 15236
Attn: Librarian

Whittaker Corporation
Nuclear Metals Division
West Concord, Massachusetts 01781
Attn: P. Lowenstein

Geoscience, Ltd.
410 S. Cedros Avenue
Solana Beach, California 92075
Attn: H. Poppendiek

NASA
Lewis Research Center
21000 Brookpark Road
Cleveland, Ohio 44135
Attn: N.T. Saunders, MS 105-1