


TWR-17245



Field Joint Environmental Protection System Vibration/ Pressurization Qualification Final Test Report

9 March 1989

Prepared for

National Aeronautics and Space Administration
George C. Marshall Space Flight Center
Marshall Space Flight Center, Alabama 35812

Contract No. NAS8-30490
DR No. 5-3, Type 1
WBS No. 4B102-10-03
ECS No. 600

MORTON THIOKOL, INC.

Aerospace Group

Space Operations

P.O. Box 707, Brigham City, Utah 84302-0707 (801) 863-3511

Publications No. 89343

(NASA-CR-183673) FIELD JOINT ENVIRONMENTAL
PROTECTION SYSTEM VIBRATION/PRESSURIZATION
QUALIFICATION Final Test Report (Morton
Thiokol) 90 p

CSCL 21H

N89-24449

Unclass

G3/20 0218040

Field Joint Environmental Protection System
Vibration/Pressurization Qualification
Final Test Report

Prepared by:

M. J. Cook
Test Planning and Reporting

Approved by:

Neal Black
Test Planning and Reporting
Supervisor

G. W. Lof
Space Systems Engineering
Manager

Michael Williams
Systems Test and Support
Manager

D. M. Ketner / Jn
Space Engineering Design
Manager

Roy J. Hyer 3/13/89
Project Engineer

Harry L. Lippert
Program Manager

Timothy J. Farley
Design Engineer

Byron E. Jepsen
for Design Supervisor

J. R. Osborn 3/9/89
Certification Planning

Don Lamm 3-10-89
System Safety

Stephen M. West
Reliability

P. C. Lydeck 3-15-89
Data Management
ECS# 600

ABSTRACT

The field joint environmental protection system (herein referred to as the joint protection system (JPS)) vibration/pressurization qualification test consisted of flight-simulating environmental conditioning and dynamic environment testing of a JPS test article. The major purposes of the test were to certify that the flight-designed JPS will withstand the dynamic environmental conditions of flight, and to certify that the cartridge check valve (vent valve) will relieve pressure build-up under the JPS during the initial 120 sec (minimum) of flight.

The vibration test article performed satisfactorily and fulfilled all objectives listed in the test plan. The JPS remained intact, no visual anomalies were evident, and the bondlines showed no evidence of separation or degradation throughout the testing. All requirements for venting and pressure release were met. Also, button pull tests of the extruded cork insulation bondlines yielded acceptable results.

CONTENTS

<u>Section</u>		<u>Page</u>
1	INTRODUCTION	1
	1.1 BRIEF TEST ARTICLE DESCRIPTION	1
2	OBJECTIVES	7
3	APPLICABLE DOCUMENTS	8
4	RESULTS SUMMARY, CONCLUSIONS, AND RECOMMENDATIONS . .	10
	4.1 RESULTS SUMMARY	10
	4.2 CONCLUSIONS	11
	4.2.1 Requirement Traceability	11
	4.3 RECOMMENDATIONS	13
5	INSTRUMENTATION	14
6	PHOTOGRAPHY	15
7	RESULTS AND DISCUSSION	20
	7.1 TEST ARTICLE DESCRIPTION	20
	7.1.1 Joint Simulator Fixture	20
	7.1.2 Vibration Test Article Assembly	21
	7.2 ACCELERATED ENVIRONMENTAL CONDITIONING	22
	7.2.1 High-Temperature, High-Humidity Conditioning .	22
	7.2.2 Salt Spray Conditioning	22
	7.2.3 Rain Conditioning	25
	7.2.4 Low-Temperature Conditioning	25
	7.3 TEST RESULTS AND DISCUSSION	25
	7.3.1 Flight Random Vibration/Pressurization Test . .	27
	7.3.2 Reentry Random Vibration/Pressurization Test .	27
	7.3.3 Vehicle Dynamics Vibration/Pressurization Test	28
	7.3.4 Water Impact Shock Test	28
	7.3.5 Cork Button Pull Tests	29

CONTENTS (Cont)

<u>Appendix</u>		<u>Page</u>
A	DATA FROM SRM FJEPS VIBRATION/PRESSURIZATION TEST . .	A-1
B	MEMO A400-FY89-139, "REDLINE TO CTP-0054, REV. C, 'QUALIFICATION TEST PLAN FOR FIELD JOINT ENVIRONMENTAL PROTECTION SYSTEM VIBRATION/ PRESSURIZATION TEST'"	B-1
C	DISCREPANCY REPORTS NO. 168169 AND NO. 168188	C-1

FIGURES

<u>Figure</u>		<u>Page</u>
1	Top View, Field Joint Environmental JPS Vibration/ Pressurization Test Article	2
2	Front View, Field Joint Environmental JPS Vibration/ Pressurization Test Article	3
3	Side View, Field Joint Environmental JPS Vibration/ Pressurization Test Article	4
4	Side View, Close-up, Field Joint Environmental JPS Vibration/Pressurization Test Article	5
5	JPS Test Article Subject to Salt Spray Conditioning	16
6	JPS Test Article Positioned for Longitudinal Vibration	17
7	JPS Test Article Positioned for Tangential Vibration	18
8	JPS Test Article Positioned for Radial Vibration . . .	19
9	JPS Test Article Salt Spray Conditioning--High Temperature and Humidity	23
10	JPS Test Article Rain and Low-Temperature Conditioning--Chamber and Water Temperature	26

TABLES

<u>Table</u>		<u>Page</u>
1	JPS Test Article Salt Fog Conditioning Data	24
2	Cork Button Pull Test Results	30

ACRONYMS

CEI	contract end item
FJEPS	field joint environmental protection system
grms	gravity root mean square
JPS	joint protection system
LSC	linear-shaped charge
PSD	power spectral density
RSRM	redesigned solid rocket motor

1

INTRODUCTION

This report documents the procedures used and results obtained from vibration testing the redesigned solid rocket motor (RSRM) field joint environmental protection system (FJEPS), hereafter referred to as the joint protection system (JPS), per CTP-0054, "Qualification Test Plan for the Field Joint Environmental Protection System Vibration/Pressurization Test." The JPS is installed to protect the RSRM field joints from the exterior environment. The test consisted of flight-simulating environmental conditioning and dynamic environment testing of a JPS test article. The major purposes of the test were to certify that the flight-designed JPS will withstand the dynamic environmental conditions of the redesigned solid rocket booster, and to certify that the cartridge check valve (vent valve) will relieve pressure build-up under the JPS during the initial 120 sec (minimum) of flight. Also, an evaluation of the extruded cork insulation bonding was performed after the vibration testing.

The test article was assembled and instrumented according to Morton Thiokol drawings 7U76358 (test article assembly) and 2U132025 (vibration fixture). The test article was built using sections of current JPS production components, except that the field joint used was a fixture designed to simulate the external contour of the RSRM field joint. Accelerometer and pressure data were acquired to verify the input and response vibration spectrums and the pressure buildup under the JPS during testing.

Testing was conducted at the Morton Thiokol Utah-based test facilities T-3, T-51, T-53, M-15, and M-53 and was completed on 8 Feb 1989.

1.1 BRIEF TEST ARTICLE DESCRIPTION

The test article configuration represented flight hardware, except for the joint simulator fixture (Figures 1 through 4). The test article assembly

REVISION _____

DOC NO. TWR-17245
SEC _____

PAGE _____

VOL _____

1




Figure 1. Top View, Field Joint Environmental JPS Vibration/Pressurization Test Article




Figure 2. Front View, Field Joint Environmental JPS Vibration/Pressurization Test Article




Figure 3. Side View, Field Joint Environmental JPS Vibration/Pressurization Test Article




Figure 4. Side View, Closeup, Field Joint Environmental JPS Vibration/Pressurization Test Article

consisted of an aluminum joint simulator fixture and sections of pin retainer band, JPS heater, heater thermal barrier, moisture seal, moisture seal retainer straps, instrumented moisture seal retainer strap clips and links, JPS sensor, extruded cork insulation, and K5NA ablation compound. In addition, a cartridge check valve was installed into the center of the assembly.

2

OBJECTIVES

The JPS vibration/pressurization test objectives were derived from the objectives in TWR-15723, Rev. C, "Redesign D&V Plan," to satisfy the requirements of contract end item (CEI) specification CPW1-3600. The objectives are listed with the CEI paragraph numbers as follows:

- a. Certify that the JPS shall remain intact through simulated flight, post-separation, water impact and, as a goal, through recovery vibration and shock criteria. (3.2.1.11.d, 3.2.7.2.2.b)
- b. Certify that the JPS structures and components are designed to demonstrate the life factor requirements. (3.3.6.5)
- c. Certify that the JPS is designed to preclude the shedding of debris (Debris Prevention) from the elements during prelaunch and flight operations that would jeopardize the flightcrew and/or mission success. (3.2.6.5)
- d. Certify that the vent valve will relieve the pressure buildup under the JPS during the initial 120 sec minimum of both flight random and vehicle dynamics vibration criteria in each axis. (3.2.1.11.d, 3.2.7.2.2.b)
- e. Evaluate the JPS bondline performance when subjected to the prelaunch natural environments as listed:
 - Air temperature
 - Humidity
 - Rain
 - Salt air
- f. Evaluate the JPS post-test structural integrity (adhesive bondlines) through button pull tests.

APPLICABLE DOCUMENTS

<u>Morton Thiokol Documents</u>	<u>Title</u>
CPW1-3600	Prime Equipment Contract End Item (CEI) Detail Specifications
CTP-0054	Qualification Test Plan for the Field Joint Environmental Protection System Vibration/Pressurization Test
DPD 400	Data Procurement Document No. 400
SE-019-049-2H	Solid Rocket Booster Vibration, Acoustic and Shock Design and Test Criteria
STW5-2994	Paint, Polyethylene, Chlorosulfonated
STW5-3183	Ablation Compound, Cork Filled (K5NA)
STW4-3218	Epoxy Resin Adhesive, Nonasbestos, Structural Bonding (EA 934NA)
STW5-3225	Coatings, Epoxy-Polyamide
STW5-3226	Primer, Zinc-Rich, Epoxy-Polyamide
TWR-10163 (CD)	Safety Plan for Space Shuttle Solid Rocket Motor Project
TWR-15671	Quality Plan for the SRM Redesign Program
TWR-15723	Redesign D&V Plan
TWR-17230	Cork Extrusion Mechanical Characterization Final Test Report
TWR-19138	FJEPS Vibration/Pressurization Test Flash Report
GS&HM	Morton Thiokol/Wasatch Operations General Safety and Health Manual

Military
DocumentsTitle

MIL-STD-810C	Environmental Test Methods
MIL-STD-810D	Environmental Test Methods and Engineering Guidelines
MIL-S-8802	Type I C1 B-2 Sealant (PR1422 Polysulfide)
MIL-STD-45662	Calibration System Requirements

Drawing No.

2U132025	Vibration Fixture RSRM Field Joint
7U76358	Test Assembly, Vibration/Pressure

RESULTS SUMMARY, CONCLUSIONS, AND RECOMMENDATIONS

4.1 RESULTS SUMMARY

This section contains an executive summary of the key results from the test data evaluation and post-test inspection. Additional information and details can be found in Section 7 of this report.

The vibration test article performed satisfactorily and fulfilled all of the objectives listed in CTP-0054. The JPS remained intact, no visual anomalies were evident, and the EA 934NA adhesive and K5NA ablation compound bondlines showed no evidence of separation or degradation throughout the testing. The cartridge check valve performed as expected. All requirements for venting and pressure release were met and the cartridge check valve remained securely bonded in place. Button pull tests of the bonds between the extruded cork insulation and the aluminum joint simulator fixture, moisture seal, and moisture seal retainer straps yielded satisfactory results.

Throughout the vibration environment tests there was no drop or change in the moisture seal retainer strap tension. During all of the flight random and vehicle dynamics pressurization tests there was no internal pressure drop.

For the water impact shock test, the impact-simulating pulse duration criterion was changed from 0.050 to 0.010 sec to accommodate the capabilities of the test equipment. Longitudinal axis shock No. 1 was run with a loose lead on the control accelerometer, and thus the article was over-tested to 70.23 g (test criteria peak level was 20 g). Tangential axis shock No. 1 was run to 19.77 g (test criteria peak level was 8 g). The cause of the tangential over-test is unknown. Since no visual damage was done to the test article in each over-test, both test runs were acceptable.

Based on the results of these tests, it can be concluded that the test was successful.

4.2 CONCLUSIONS

Overall, the results of this test were satisfactory. Test results indicate that when proper installation procedures are followed the JPS will remain intact throughout the flight environment. The JPS tested remained intact and did not come free from the joint simulator fixture. No evidence of debris was present and the cartridge check valve relieved the pressure built up under the JPS as needed. All of the bondlines were in excellent condition and post-test pull tests showed greater-than-anticipated bondline strengths.

4.2.1 Requirement Traceability

Listed following are the conclusions as they correspond to the objectives and CEI paragraphs. Additional information to support these conclusions can be found in Sections 7.2 and 7.3 of this report.

<u>Objective</u>	<u>CEI Paragraph</u>	<u>Conclusions</u>
Certify that the JPS shall remain intact through simulated flight, post-separation, water impact and, as a goal, through recovery vibration and shock criteria.	3.3.1.11d. The field joint protection system shall remain intact through flight and, as a goal, through recovery.	<u>Certified.</u> Throughout testing, all of the bondlines and components of the test article remained intact and did not degrade in any way.
	3.2.7.2.2b: <u>Induced Environment Loads.</u> The RSRM shall be designed to withstand postseparation-through-recovery loads as specified...	
Certify that the JPS structures and components are designed to demonstrate the life factor requirements.	3.3.6.5: <u>Life Factors.</u> The RSRM shall be designed to withstand fatigue and fracture mechanics requirements as specified...	<u>Certified.</u> The test article was subjected to accelerated environmental conditioning prior to successful completion of vibration and pressurization testing.

<u>Objective</u>	<u>CEI Paragraph</u>	<u>Conclusions</u>
Certify that the JPS is designed to preclude the shedding of debris (Debris Prevention) from the elements during prelaunch and flight operations that would jeopardize the flight crew and/or mission success.	3.2.6.5: <u>Debris Prevention</u> . The SRM shall be designed to preclude the shedding of debris from the elements during prelaunch and flight operations...	<u>Certified</u> . Throughout testing, all components of the test article remained intact and did not degrade in any way.
Certify that the vent valve will relieve the pressure buildup under the JPS during the initial 120 sec minimum of both flight random and vehicle dynamics vibration criteria in each axis.	3.3.1.11d. The field joint protection system shall remain intact through flight and, as a goal, through recovery. 3.2.7.2.2b: <u>Induced Environment Loads</u> . The RSRM shall be designed to withstand postseparation-through-recovery loads as specified...	<u>Certified</u> . The vent valve performed as designed and relieved the JPS internal pressure during the initial 120 sec minimum of each flight random and vehicle dynamics vibration test. Salt deposits were present on the vent valve from the environmental conditioning, but the deposits did not impact valve performance.
Evaluate the JPS bondline performance when subjected to the prelaunch natural environments as listed: --Air temperature --Humidity --Rain --Salt air	None	The test article was subjected to the specified simulated prelaunch environments and all bondlines remained intact and did not degrade in any way.
Evaluate the JPS post-test structural integrity (adhesive bondlines) through button pull tests.	None	Cork insulation pull tests yielded results as expected, and all breaking strength values were higher than expected.

4.3 RECOMMENDATIONS

Based on the results of this test, it is recommended that the use of the flight configuration JPS, as documented in this report, should be continued.

INSTRUMENTATION

Vibration test instrumentation consisted of a triaxial accelerometer (A002-A004) mounted on the joint simulator fixture to measure response frequencies, and a single accelerometer (A001) mounted to the shaker table input plate to control input frequencies (Figure 1). In addition, a mass flowmeter controlled air flowing into the cavity under the JPS, and a pressure gage (P001) monitored the pressure buildup (Figure 2).

6

PHOTOGRAPHY

Pretest and post-test photographs of the test article were taken. Figures 5 through 8 show the test setup and post-test condition of the test article.

ORIGINAL PAGE
BLACK AND WHITE PHOTOGRAPH

N107751-1




Figure 5. JPS Test Article Subject to Salt Spray Conditioning




Figure 6. JPS Test Article Positioned for Longitudinal Vibration




Figure 7. JPS Test Article Positioned for Tangential Vibration

ORIGINAL PAGE
BLACK AND WHITE PHOTOGRAPH

N107962-4




Figure 8. JPS Test Article Positioned for Radial Vibration

REVISION _____

DOC NO. TWR-17245
SEC

VOL

PAGE

19

RESULTS AND DISCUSSION

Prior to the vibration/pressurization testing, the test article was assembled and subjected to accelerated environmental conditioning.

7.1 TEST ARTICLE DESCRIPTION

The test article configuration was designed to certify the JPS. Test article configuration represented flight hardware, except for the joint simulator fixture (Figures 1 through 4). The test article assembly consisted of an aluminum joint simulator fixture and sections of pin retainer band, JPS heater, heater thermal barrier, moisture seal, moisture seal retainer straps, instrumented moisture seal retainer strap clips and links, JPS sensor, extruded cork insulation, and K5NA ablation compound. In addition, a cartridge check valve was installed into the center of the assembly.

7.1.1 Joint Simulator Fixture

Drawing 2U132025 defined the joint simulator fixture configuration, which was designed to simulate the external profile of an assembled RSRM field joint and allow for the installation of the JPS. The fixture was machined from aluminum to be 32 in. long by 20 in. wide by 6.2 in. high. The 32-in. test article length was selected using the following criteria:

- a. Similarity to the test article length used in the nozzle linear-shaped charge (LSC) and the systems tunnel qualification tests (approximately 30-to-40-in. length).
- b. As close to the maximum length possible to achieve the 35.2-grms level required for reentry random vibration.

(Analysis shows that vibration modes which cause element lifting, separation, debonding, etc., are relatively high in frequency and pure radial, tangential, or longitudinal modes. Although 32 in. is only about 15 percent of the JPS circumference, test article length for the lifting, separation, debonding, etc., modes is not a factor.)

A requirement of the JPS vibration fixture was to simulate and monitor pressure buildup under and venting through the cartridge check valve in the JPS. To accomplish this, two pressure ports were drilled into the joint simulator fixture: one to allow an airflow into the volume under the JPS, and one to monitor the pressure directly under the cartridge check valve in the JPS (Figure 2).

To ensure that tension in the moisture seal retainer straps could be monitored and verified to be within the 1,300-to-3,000-lb range during assembly, two cavities were machined into the joint simulator fixture to accommodate two turnbuckle/load cell assemblies to which the straps were attached and tightened (Figure 3).

Prior to installing the JPS, the fixture was grit blasted, vapor degreased, and spray painted with STW5-3226 zinc-rich primer and STW5-3225 top coat.

7.1.2 Vibration Test Article Assembly

Assembly and instrumentation of the JPS vibration fixture was conducted at the Morton Thiokol M-15 facility and was defined by drawing 7U76358. The assembly consisted of sections of the pin retainer band, JPS heater, heater thermal barrier, moisture seal, moisture seal retainer straps, instrumented moisture seal retainer strap clips and links, JPS sensor, extruded cork insulation, and K5NA ablation compound installed on the joint simulator fixture. In addition, a cartridge check valve was installed into the center of the JPS assembly.

To obtain an assembly which was capable of holding pressure, the moisture seal was trimmed 0.75 to 2.0 in. on either end and sealed in place using polysulfide sealant (MIL-S-8802). The cartridge check valve was then bonded to the moisture seal with polysulfide sealant (MIL-S-8802).

Once the seal was verified, the moisture seal retainer straps were installed and tightened to $2,990 \pm 10$ lb tension. To monitor and record the tension in the straps, the straps were installed using two specially modified retainer strap clip and link assemblies (the modification to the strap clip and link assemblies consisted of instrumenting them to measure load) and two

turnbuckle/load cell assemblies. The straps were allowed a 30-min period of relaxation and then retightened, after which the heater sensor was put in place.

Finally, EA 934NA adhesive was applied to both the joint simulator fixture and the extruded cork insulation. The cork was positioned in place and cured inside a vacuum bag for 8 hr. After cure, the adhesive surrounding the upper 0.25 in. of the cartridge check valve was removed and replaced with K5NA (Figure 4). K5NA was applied at the aft end of the cork, and all the cork and K5NA were painted with white polyethylene paint (STW5-2994). Assembled, the test article weighed 171.4 lb.

7.2 ACCELERATED ENVIRONMENTAL CONDITIONING

Prior to vibration testing, the test article was subjected to temperature, humidity, salt spray, and rain conditioning per CTP-0054 and MIL-STD-810D to simulate the prelaunch natural environment. This conditioning took place from 29 Nov to 12 Dec 1988.

7.2.1 High-Temperature, High-Humidity Conditioning

Initially, the test article was placed in the Morton Thiokol T-51 test facility and subjected to an environment of $120^{\circ} \pm 10^{\circ}\text{F}$ and 90 ± 10 -0 percent relative humidity for 48 hr minimum (Figure 9). Upon completion of this conditioning, the test article was placed in a $75^{\circ} \pm 10^{\circ}\text{F}$ environment for 24 hr minimum and allowed to return to ambient condition.

7.2.2 Salt Spray Conditioning

Following the high-temperature, high-humidity, and return-to-ambient conditioning cycle, the test article was placed in the Morton Thiokol T-3 test facility and subjected to a $95^{\circ} \pm 10^{\circ}\text{F}$ salt spray conditioning for 48 hr (Table 1 and Figure 5). Upon completion of this conditioning, the test article was placed in a $75^{\circ} \pm 10^{\circ}\text{F}$ environment for 48 hr and allowed to return to ambient conditions. Postconditioning inspection of the test article showed salt deposits accumulated in and around the vent valve.




Figure 9. JPS Test Article Salt Spray Conditioning—High Temperature and Humidity

Table 1. JPS Test Article Salt Fog Conditioning Data

Required					
<u>pH</u>		<u>Specific Gravity</u>	<u>Temperature</u>	<u>Fallout</u>	
6.5 to 7.2		1.023 to 1.037	95 ±10°F	0.5 to 3.0 mL per hr of solution	
Actual (Pretest)					
<u>Date</u>	<u>pH</u>	<u>Specific Gravity</u>	<u>Temperature</u>	<u>Fallout</u>	
				<u>Receptacle No. 1</u>	<u>Receptacle No. 2</u>
1 Dec 1988	6.9	1.028	96°F	25	70
Actual (Test)					
<u>Date</u>	<u>pH</u>	<u>Specific Gravity</u>	<u>Temperature</u>	<u>Fallout</u>	
				<u>Receptacle No. 1</u>	<u>Receptacle No. 2</u>
2 Dec 1988	6.5	1.026	95°F	25	70
3 Dec 1988	7.1	1.029	95°F	30	50
4 Dec 1988	6.5	1.025	95°F	50	50

7.2.3 Rain Conditioning

Simulated rain conditioning was conducted after completion of the salt spray conditioning. The test article was subjected to a water spray for a minimum of 1 hr. The conditioning was conducted at the Morton Thiokol T-3 test facility and met the following conditions:

Water pressure:	40 psig
Water temperature:	45°F
Chamber temperature:	73°F
Rain duration:	1 hr minimum
Rain droplet size:	2 to 4.5 mm diameter
Distance from nozzle:	19 ±1 in.

7.2.4 Low-Temperature Conditioning

Low-temperature conditioning was conducted after completing the rain conditioning. The test article was towel dried, immediately placed in the Morton Thiokol T-3 test facility, and subjected to a 20° +0-10°F environment for a minimum of 48 hr (Figure 10). Upon completion of this conditioning, the test article was placed in a 75° ±10°F environment for a minimum of 24 hr and allowed to return to ambient conditions. Postinspection of the test article showed salt deposits accumulated in the bottom of the vent valve.

7.3 TEST RESULTS AND DISCUSSION

The vibration/pressurization test was conducted in the Morton Thiokol T-53 shaker facility from 19 Dec 1988 to 6 Jan 1989. Two Ling A340 shakers were used to conduct the test. The longitudinal and tangential axes tests were conducted using a shaker which was configured horizontally and bolted to a shaker plate (Figures 6 and 7). The other shaker was configured vertically for the radial test (Figure 8). Test results (control and response accelerometer power spectral density (PSD) plots and time history plots) are included in Appendix A.

The test setup included an internal pressurization pretest of the test article per paragraph 8.1.2 of CTP-0054. All requirements for air flow ($3.2 \pm 0.5 \text{ in.}^3/\text{sec}$ for 160 sec) and pressure (1.0 +0.5-0 psig) were met. The cartridge check valve (vent valve) performed as designed and relieved the JPS




Figure 10. JPS Test Article Rain and Low Temperature Conditioning—Chamber and Water Temperature

internal pressure during the initial 120 sec (minimum) of each flight random and vehicle dynamics vibration test.

7.3.1 Flight Random Vibration/Pressurization Test

The equipment armature and head expander exhibited a natural resonance in the 1,000-to-2,000-Hz range. Two types of accelerometers were used: control accelerometers which measure motion of the shaker plate, and response accelerometers which measure motion on the test article. Control accelerometer PSD plots show that the test article was subject to motion within tolerances specified by CTP-0054 (Table II). Response accelerometer PSD plots, however, show the equipment resonance as a data spike which exceeds the tolerance criteria of CTP-0054. The resonance/spike was allowed per MIL-STD-810C (Method 514.2, para 4.5.2) and upon receipt of a redline copy of CTP-0054 and a memo from the vice president of Space Operations (Memo A400-FY89-139, included in Appendix B). (The test changes specified in Memo A400-FY89-139 have been incorporated into CTP-0054, Rev. C.) Control and response accelerometer PSD plots are included in Appendix A.

The test article was pressurized (1.0 +0.5-0 psig) during the initial 160 sec of the vibration test. Pressure gages indicated no internal pressure drop throughout this test. Instrumented moisture seal retainer strap clips and links were monitored with a portable data acquisition system to detect any change in strap tension. No change in strap tension was indicated throughout this test. Upon test completion, no visual anomalies on the test article were found. The test article met the requirements of CTP-0054.

7.3.2 Reentry Random Vibration Test

Radial axis test levels could only be met by using two control accelerometers and averaging the two outputs for a solid control. This setup was a result of equipment armature and head expander natural resonance in the 1,000-to-2,000-Hz range. As in the Flight Random Test, control motion was within test criteria, while response motion exhibited a data spike due to equipment resonance. The resonance/spike was allowed per MIL-STD-810C, and per the redline version of CTP-0054 and Memo A400-FY89-139, both included in Appendix B.

Instrumented moisture seal retainer strap clips and links were monitored, and no change in the strap tension was indicated. Upon test completion, no visual anomalies on the test article were found. The test article met the requirements of CTP-0054.

7.3.3 Vehicle Dynamics Vibration/Pressurization Test

The test article was pressurized (1.0 +0.5-0 psig) during the initial 160 sec of the vibration test. Pressure gages indicated no internal pressure drop throughout this test. Instrumented moisture seal retainer strap clips and links were monitored, and no change in the strap tension was indicated. Upon test completion, no visual anomalies on the test article were found. The test article met the requirements of CTP-0054.

7.3.4 Water Impact Shock Test

The test criteria required an impact-simulating, half-sine pulse duration of 0.050 sec. However, the computerized equipment could only give a duration of 0.010 sec. The pulse duration criterion was changed to 0.010 sec per the redline version of CTP-0054 and Memo A400-FY89-139, included in Appendix B. Time history data for the shock tests are included in Appendix A.

Longitudinal axis shock No. 1+ was run with a loose lead on the control accelerometer, and thus the article was over-tested (70.23 g at 100 Hz on the shock spectrum and test criteria peak level at 20 g). Discrepancy Report No. 168169 was written to cover the over-test, and is included in Appendix C. Since no visual damage was done to the test article, the over-test was acceptable. Shock No. 2+ was run to 31.14 g.

Tangential axis shock No. 1+ was run to 19.77 g. (Test criteria peak level was 8 g). The cause of the over-test is unknown. Discrepancy Report No. 168188 was written to cover the over-test, and is included in Appendix C. Since no visual damage was done to the test article, it met or exceeded the test requirements and was acceptable. Shock No. 2+ was run to 16.68 g, No. 1- to 13.49 g, and No. 2- to 13.43 g.

Radial axis shock testing was satisfactory. Shock No. 1- was run to 12.96 g, No. 2- to 12.98 g, No. 1+ to 13.44 g, and No. 2+ to 13.44 g.

7.3.5 Cork Button Pull Tests

Cork button pull testing was conducted on 8 Feb 1989 in the Morton Thiokol M-53 Development Lab (Table 2). Five specimens located on the extruded cork-to-joint fixture bond failed 100 percent in the cork and failed at higher stress than cork tensile dog bone tests (documented in TWR-17230, "Cork Extrusion Mechanical Characterization Final Test Report"). Two other pull test locations (moisture seal-to-cork extrusion bondline and Kevlar® strap and K5NA-to-cork extrusion bondline) also yielded acceptable results.

Table 2. Cork Button Pull Test Results

Specimen No.	Location	Max Load (lb)	Max Stress (psi)	Failure Mode
1	Cork-to-Case Bond	160	133	100% CCF
2		329	275	
3		312	261	
4		288	241	
5		279	233	
6	Moisture Seal-to-Cork Bond	54	45	10% CCF, 90% AFMS
7		97	81	25% CCF, 75% AFMS
8		89	75	
9		106	89	50% CCF, 50% AFMS
10		131	110	70% CCF, 30% AFMS
11	Kevlar® Strap/K5NA-to-Cork Bond	291	243	70% CCF, 30% AFKS
12		124	104	50% CCF, 50% AFKS
13		251	210	
14		218	182	80% CCF, 20% AFKS
15		194	162	

A020996a

CCF: Cohesive cork failure

AFMS: Adhesive failure to moisture seal

AFKS: Adhesive failure to Kevlar® strap/K5NA

Button Diameter: 1.2340 in.

Button Cross Section: 1.196 in. 2

Crosshead Speed: 0.5 in./min

Date: 8 Feb 1989

Temperature: 75°F

REVISION

DOC NO. TWR-17245

VOL

SEC

PAGE

30

MORTON THIOKOL, INC.

Space Operations

Appendix A

DATA FROM SRM FJEPS VIBRATION/PRESSURIZATION TEST

REVISION _____

89656-1.27

DOC NO.	TWR-17245	VOL
SEC	PAGE	A-1

MORTON THIOKOL, INC.

**Aerospace Group
Support Services**

TEST REPORT

TITLE: Field Joint Environmental Protection System Vibration/Pressurization Test

PROJECT: HQ302-09-20 **DATE:** 25 January 1989

TEST DATE: 19 December 1988 - 6 January 1989 **REPORT NO.** TE-12775

PREPARED BY: *Rick Baird*

Rick Baird
Test Engineer

APPROVED BY: *Bruce O Tams*

Bruce O. Tams, Manager
Test Engineering

DISTRIBUTION:

MORTON THICKOL
WASATCH OPERATIONS

TABLE OF CONTENTS

1.0	SUMMARY
2.0	TEST RESULTS
3.0	TEST DATA

MORTON THIOKOL, INC.
WASATCH OPERATIONS

1.0 SUMMARY

This report contains the results of the Vibration Testing conducted on the 7U76358 Field Joint Test Assembly. Testing met or exceeded the requirements contained in the CTP-0054 test plan. Testing was run per Shop Travelers 7A052 and 7A053.

2.0 TEST RESULTS

2.1 Test Configuration

The following test tools were used:

2U105664	Vibration Slip Plate
6021ST	Drive Bar
X-M19506-6	Head Expander
7U76358	Test Assembly

2.2 Test Set-Up

The test article was received at T-53 on 12 December 1988. Visual inspection showed rust and corrosion on all exposed metal (non-painted or non-plated). Test article was stored at T-53 til 19 December 1988 when test set-up could be scheduled.

Test set-up included an internal pressurization pre-test per paragraph 8.1.2 of CTP-0054. All requirements for air flow (3.2 +/- .5 in 3/sec for 160 sec) and pressure (1.0 + .5 -0 psig) were met.

Testing was conducted using the Ling A340 shakers. Longitudinal and radial axes were run on the slip plate. Radial axis was run on the vertical shaker.

2.3 Test Performance

2.3.1 Flight Random Vibration

Test was run per requirements listed in CTP-0054 table II Flight Random Vibration. Test article was pressurized during initial 160 seconds visually monitoring pressure gages. FM Tape #22957 contains flight random vibration levels and pressure levels. No visual anomalies were noticed. Article met requirements of Test Plan.

2.3.2 Re-Entry Random

Test was run per requirements listed in CTP-0054 Table II Re-entry Random Vibration. FM Tape #22957 contains the longitudinal and tangential axes data. FM Tape #22959 contains the radial axis data. Article met requirements of test plan. Radial axis test levels could only be met by using two control accelerometers and averaging between their two outputs for a solid control. PSD plots show resonance between 1000-2000 Hz. This is due to armature and Head Expander set-up natural resonance.

MORTON THIOKOL
WASATCH OPERATIONS

2.3.3 Vehicle Dynamics

Test was run per requirement listed in CTP-0054 Table II Vehicle Dynamics Criteria. Test article was pressurized during initial 160 seconds of the vibration. No drop in pressure was seen by visually monitoring pressure gages. FM tape #22958 contains vehicle dynamics data. Article met requirements of test plan.

2.3.4 SRM Water Impact Shock

Test was run per requirements listed in CTP-0054 Table II under SRM Water Impact Shock Criteria.

Test criteria required a duration of .050 seconds. Computerized equipment can only give a duration of .010 seconds. Traveler was changed to .010 seconds upon receipt of a "red-lined" test plan and memo from J. D. Thirkill.

Longitudinal axis shock #1 was run with a loose lead on the control accelerometer and thus an overtest level of 70.23 G's was seen. DR #168169 was written to cover this. Disposition was that data was acceptable.

Tangential axis shock was run to a 19,77G level. Cause was unknown. DR #168188 was written and dispositioned that data was acceptable.

2.3.5 Test Monitoring of Clip Gages

During the Flight Random, Re-entry and Vehicle Dynamics Vibration, Clip Gages were monitored by C/C 5618. This consisted of a PDAS set-up to monitor "clip-gages". The clip gages were installed on the straps during Field Joint Build-up. No loosening or change in the straps was noticed during testing.


2.3.6 Post Test


Post test inspection showed no visual anomalies to the test article.

3.0 TEST DATA


A. Photographs

B. PSD Plots







FJEPSC
FJEPSC RANDOM LONG FLTS 15-DEC-88
FLIGHT




FJEP3F
FJEP3 FLIGHT RANDOM VIB/PRESS LONG AXIS 20-DEC-88




FJEPSP
FJEP8 FLIGHT RANDOM VIB/PRESS LONG AXIS 23-DEC-88




FJEPSCG
FJEPS FLIGHT RANDOM VIB/PRESS RADIAL AXIS 20-DEC-88




FJEPG
FJEPG FLIGHT RANDOM VIB/PRESS RADIAL AXIS 20-DEC-88




FJEP80
FJEP8 RE-ENTRY RANDOM, TANGENTIAL AXIS, 20-DEC-88




FJEP80
FJEP8 RE-ENTRY RANDOM, TANGENTIAL AXIS, 20-DEC-88




FJEPSE
FJEP3 RE-ENTRY RANDOM. LONGITUDINAL AXIS 20-DEC-88




FJEPSE
FJEPS RE-ENTRY RANDOM, LONGITUDINAL AXIS 20-DEC-88




FJEPSJ
FJEPS RE-ENTRY RANDOM VIB., RADIAL AXIS, 22-DEC-88



FJEP3J
FJEP3 RE-ENTRY RANDOM VIB., RADIAL AXIS, 22-DEC-88




RUN 1 FUEP5A
FUEP5 SINE VEHICLE DYN LONG AXIS 20-DEC-68




RUN 1 CLEPER
CLEPER SINE VEHICLE DYN LONG POTS 20-DEC-68

ORIGINAL PAGE IS
OF POOR QUALITY

1




RUN 1 FJEP5B
FJEP5 LATERAL (TANG) AXIS SINE 20-DEC-88




RUN 1 FJEP33
FJEP3 LATERAL (TANG) DATE SINE 20-DEC-88

ORIGINAL PAGE IS
OF POOR QUALITY


762



RUN 3 FJEPSC
PLPS LATERAL (MODEL) PXTS STNS 26-DEC-88



RUN 3 FUEPSC
FUEPS LATERAL (RADIAL) AXIS SINE 20-DEC-88



SHOCK SPECTRUM VALUES: SRM F.J.E.P.S. 3-JAN-69
 FREQ-HZ MAGN-G

1.32	35.43	88.68
1.585	39.81	96.76
1.703	44.65	95.17
2.155	50.1	72.85
2.421	56.22	79.47
2.741	63.08	81.25
3.205	70.8	65.43
3.473	79.42	74.24
3.931	89.11	65.87
4.284	100.	70.23
4.84	112.1	33.8
5.381	125.8	49.62
6.043	141.2	62.36
6.912	158.4	63.7
7.847	177.8	79.57
8.968	199.5	90.56
10.03	223.9	94.42
11.11	251.1	74.61
12.81	281.8	68.61
15.68	316.3	79.74
19.39	354.7	141.9
23.48	398.1	111.9
28.39	446.7	172.8
32.63	501.2	219.4
35.61	562.9	253.4
41.25	630.9	290.5
45.26	708.1	419.6
47.04	794.1	281.2
60.98	991.3	243.1
77.98	1000.	200.1
84.97		
1.121		
1.259		
1.412		
1.584		
1.773		
1.995		
2.238		
2.512		
2.818		
3.162		
3.547		
3.98		
4.467		
5.011		
5.623		
6.309		
7.078		
7.941		
8.912		
10.		
11.21		
12.58		
14.12		
15.84		
17.78		
19.95		
22.38		
25.11		
28.17		
31.62		

#1 POS 20G SHK LONG AXIS 3-JAN-89

A003 LONG RESPONSE

200.

G

TR

-200.


.34

INPUT-T

.2

#2 POS 20G SHOCK TRANS 3-JAN-89

A001 CONTROL
Long axis



SHOCK SPECTRUM VALUES: FJEPS 20G TRANS SHOCK 3-JAN-89

FREQ-HZ	MAGN-G	
5.011	6871	199.5
5.623	874	223.9
6.309	1.11	251.1
7.078	1.406	281.9
7.941	1.767	316.3
8.912	2.32	354.7
10.	3.098	398.1
11.21	4.279	446.7
12.58	5.377	501.2
14.12	7.127	562.9
15.84	8.898	630.9
17.78	10.45	708.1
19.95	11.81	794.1
22.38	13.51	891.3
25.11	15.18	1000.
28.17	17.37	
31.62	17.43	
35.48	16.98	
39.81	16.45	
44.65	14.85	
50.1	12.55	
56.22	13.74	
63.08	14.94	
70.8	21.38	
79.42	30.02	
89.11	32.38	
100.	31.14	
112.1	24.28	
125.8	18.05	
141.2	13.95	
158.4	14.13	
177.8	13.18	
		13.18
		13.23
		13.05
		13.11
		13.41
		12.72
		12.92
		13.2
		13.44
		13.38
		13.34
		13.48
		13.01
		13.28

FJEPS

50.


G

?R

-50.


#2 FDS 20G SHK LONG AXIS 3-JAN-89

A003 LONG RESPONSE



#1 POS 8G TRANS SHOCK TANG AXIS 4-JAN-89

4001
CONTROL



.3

INPUT-T

.2

50.

G

7R

-50.


SHOCK SPECTRUM VALUES: FJEP'S 8G SHOCK 4-JAN-89
FREQ-HZ MAGN-G

1.	09531	35.48	21.54
1.121	1196	39.81	20.8
1.259	1541	44.65	18.88
1.412	1629	50.1	16.31
1.584	1815	56.22	13.6
1.778	2117	63.88	13.25
1.995	2462	70.8	14.05
2.238	2767	79.42	16.1
2.512	3174	89.11	17.47
2.818	3664	100.	19.77
3.162	4085	112.1	26.14
3.547	4706	129.8	30.98
3.98	5539	141.2	38.92
4.467	6724	158.4	43.83
5.011	8301	177.8	45.09
5.623	1.056	199.5	39.19
6.309	1.359	223.9	35.6
7.078	1.778	251.1	35.47
7.941	2.353	281.8	41.39
8.912	3.151	316.3	50.63
10.	4.166	354.7	54.92
11.21	5.42	398.1	59.53
12.58	6.944	446.7	64.2
14.12	8.75	501.2	70.17
15.84	10.79	562.5	106.6
17.78	13.01	630.3	167.6
19.95	15.23	709.1	255.1
22.38	17.42	794.1	143.7
25.11	19.53	891.3	117.8
28.17	21.22	1000.	98.86
31.62	21.17		

ORIGINAL PAGE IS
OF POOR QUALITY


#1 POS 8G TRANS SHOCK TANG AXIS 4-JAN-89

A004 TANG RESPONSE



#2 POS BG SHOCK TANG AXIS 06-JAN-89

A001 CONTROL



RESP WAVE-T .2

SHOCK SPECTRUM VALUES: FJEPS BG TRANS SHOCK 06-JAN-89

FREQ-HZ	MAGN-G	
12.58	2.616	13.44
14.12	3.433	13.34
15.84	4.445	12.87
17.78	5.749	12.48
19.95	7.468	12.83
22.38	9.517	13.06
25.11	11.85	13.81
28.17	14.14	12.93
31.62	16.41	12.88
35.48	18.75	18.84
39.81	19.83	17.4
44.65	18.96	12.03
50.1	18.52	12.15
56.22	18.14	12.18
63.08	17.1	
70.8	15.61	
79.42	15.95	
89.11	16.12	
100.	16.68	
112.1	15.92	
125.8	15.12	
141.2	15.19	
158.4	14.58	
177.8	13.69	
199.5	13.52	
223.9	13.15	
251.1	13.12	
291.8	13.27	
316.3	12.83	
354.7	12.67	
398.1	12.1	
446.7		

↑


#1 NEG 8G TRANS SHOCK TANG AXIS 06-JAN-89

A001 CONTROL

10.

G

-10.



RESP WAVE-T

.2

0.


SHOCK SPECTRUM VALUES: FJEPS 8G TRANS SHOCK 06-JAN-89

FREQ-HZ	MAGN-G	
12.58	2.393	501.2
14.12	3.988	562.5
15.84	3.872	630.9
17.78	4.987	708.1
19.95	6.467	794.1
22.38	8.19	891.3
25.11	10.25	1000.
28.17	12.35	1122.
31.62	14.58	1259.
35.48	16.86	1412.
39.81	18.13	1584.
44.65	19.16	1778.
50.1	17.46	1994.
56.22	15.84	2238.
63.08	14.94	2511.
70.8	13.75	
79.42	13.61	
89.11	13.77	
100.	13.49	
112.1	12.8	
125.8	12.16	
141.2	12.88	
158.4	11.81	
177.8	9.92	
199.5	9.478	
223.9	8.914	
251.1	8.253	
281.8	8.747	
316.3	8.515	
354.7	8.194	
398.9	8.000	
449.	8.000	

↑

#2 NEG 8G TRANS SHOCK TANG AXIS 06-JAN-89

A001 CONTROL



.2

RESP WAVE-T

0.

-10.

G

10.

ORIGINAL PAGE IS
OF POOR QUALITY

SHOCK SPECTRUM VALUES: FJEPS 8G TRANS SHOCK 06-JAN-89

FREQ-HZ	MAGN-G	
12.58	2.387	501.2
14.12	3.989	562.9
15.84	3.865	630.9
17.78	5.004	708.1
19.95	6.466	794.1
22.38	8.172	891.3
25.11	10.24	1000.
28.17	12.34	1122.
31.62	14.55	1259.
35.48	16.83	1412.
39.81	18.12	1584.
44.65	19.12	1778.
50.1	17.42	1994.
56.22	15.71	2238.
63.08	14.89	2511.
70.8	13.72	
79.42	13.78	
89.11	13.8	
100.	13.43	
112.1	12.1	
125.8	11.79	
141.2	11.79	
158.4	10.8	
177.8	9.849	
199.5	9.379	
223.9	8.781	
251.1	8.173	
281.8	9.594	
316.3	9.499	
354.7	9.047	
398.1	8.759	
446.7	9.062	

↑


#1 NEG 8G TRANS SHOCK RADIAL AXIS 06-JAN-63

A001 CONTROL

10.

G

-10.



RESP WAVE-T .2


ORIGINAL PAGE IS
OF POOR QUALITY

SHOCK SPECTRUM VALUES: FJEPS 8G TRANS SHOCK 06-JAN-89

FREQ-HZ	MAGN-G		
12.58	1.956	501.2	8.467
14.12	2.66	562.5	8.377
15.84	3.57	630.9	8.159
17.78	4.687	708.1	8.315
19.95	6.022	794.1	8.2
22.38	7.644	891.3	8.258
25.11	9.639	1000.	8.164
28.17	11.71	1122.	8.223
31.62	13.61	1259.	8.151
35.48	14.91	1412.	8.11
39.81	15.34	1584.	8.09
44.65	15.23	1778.	8.089
50.12	14.72	1994.	8.059
56.22	13.84	2238.	8.008
63.08	13.11	2511.	7.874
70.8	11.68		
79.42	12.48		
89.11	13.17		
100.	12.96		
112.1	12.23		
125.8	11.57		
141.2	11.45		
158.4	10.77		
177.8	10.		
199.5	9.476		
223.9	8.588		
251.1	8.205		
281.8	8.776		
316.3	8.805		
354.7	8.713		
398.1	8.449		
446.7	8.247		

#2 NEG 8G TRANS SHOCK RADIAL AXIS 06-JAN-89

A001 CONTROL




0. .2

SHOCK SPECTRUM VALUES: FJEPS 8G TRANS SHOCK 06-JAN-89

FREQ-HZ	MAGN-G	
12.58	1.954	8.433
14.12	2.659	8.342
15.84	3.576	8.265
17.78	4.696	8.285
19.95	5.831	8.184
22.38	7.655	8.344
25.11	9.653	8.317
28.17	11.73	8.368
31.62	13.6	8.335
35.48	14.9	8.26
39.61	15.36	8.212
44.65	14.79	8.17
50.12	13.93	8.07
56.28	13.13	8.069
63.08	11.62	8.043
70.3	12.32	
79.42	13.11	
89.11	12.98	
100.	12.25	
112.1	11.7	
125.8	11.51	
141.2	10.85	
158.4	10.12	
177.8	9.543	
199.5	8.633	
223.9	8.214	
251.1	8.844	
281.8	8.796	
316.3	8.723	
354.7	8.513	
398.1	8.383	
446.7		

↑

#1 POS SG TRANS SHOCK RADIL AXIS 06-JAN-89



10.
A001
CONTROL

-10.

0. RESP WAVE-T .2

SHOCK SPECTRUM VALUES: FJEPS 8G TRANS SHOCK 06-JAN-89


FREQ-HZ	MAGN-G		
12.58	1.915	501.2	8.737
14.12	2.625	562.5	8.839
15.84	3.555	630.9	8.879
17.79	4.714	708.1	8.8514
19.95	6.11	794.1	8.721
22.59	7.752	891.3	8.659
25.11	9.825	1000.	8.572
28.17	11.97	1122.	8.58
31.62	14.93	1259.	8.576
35.48	15.58	1412.	8.688
39.81	16.31	1584.	8.789
44.65	16.55	1778.	8.993
50.12	15.8	1994.	9.101
55.22	14.68	2238.	9.31
63.98	13.65	2511.	9.228
70.9	12.58		
79.42	13.39		
89.11	13.86		
100.	13.44		
112.1	12.54		
125.8	12.		
141.2	11.95		
158.4	11.33		
177.8	10.51		
199.5	9.958		
223.9	9.142		
251.1	8.56		
281.8	8.212		
316.3	8.229		
354.7	8.126		
398.1	8.829		
445.7	8.833		

#2 POS 8G TRANS SHOCK RADAIL AXIS 06-JAN-89

10.
A001
CONTROL

G

-10.



RESP WAVE-T

.2

SHOCK SPECTRUM VALUES: FJEPS 8G TRANS SHOCK 06-JAN-89

FREQ-HZ	MAGN-G
12.58	1.925
14.12	2.625
15.84	3.552
17.78	4.728
19.95	6.123
22.38	7.792
25.11	9.868
28.17	11.99
31.62	14.07
35.48	15.63
39.81	16.35
44.65	16.42
50.1	15.85
56.22	14.71
63.03	13.65
70.8	12.55
79.42	13.32
89.11	13.85
100.	13.44
112.1	12.52
125.8	12.02
141.2	11.97
158.4	11.34
177.8	10.54
199.5	9.941
223.9	9.091
251.1	8.502
281.8	8.174
316.3	8.251
354.7	8.106
398.1	8.84
446.7	8.578

↑

501.2	8.55
562.9	8.774
630.1	8.534
708.1	8.705
794.1	8.908
891.3	8.654
1000.	8.554
1122.	8.757
1259.	8.829
1412.	8.569
1584.	8.559
1778.	8.488
1994.	8.559
2238.	8.593
2511.	8.618

Appendix B

MEMO A400-FY89-139, "REDLINE TO CTP-0054, REV. C,
'QUALIFICATION TEST PLAN FOR FIELD JOINT ENVIRONMENTAL
PROTECTION SYSTEM VIBRATION/PRESSURIZATION TEST'"

Note: The redline changes specified in this memo
have been incorporated into CTP-0054, Rev. C.
Revision C was accepted by NASA on 16 Feb
1989.

MORTON THIOKOL, INC.

Aerospace Group

Space Operations

John D. Thirkill
Director



4 January 1989
A400-FY89-139

TO: Distribution

FROM: J. D. Thirkill

SUBJECT: Redline to CTP-0054, Rev. C, "Qualification
Test Plan for Field Joint Environmental Protection
System Vibration/Pressurization Test"

NASA has already approved the redline change. However, there is one area that was not marked up. Sheets 15 and 16 that are in question are attached.

These changes are required to finish the vibration test on the joint protection system hardware at T-53.

The Test Plan will be corrected for engineering traceability.

A handwritten signature in cursive script, appearing to read "J. D. Thirkill".

J. D. Thirkill

Attachments: a/s

TABLE II
FJEPS TEST CRITERIA

TEST	SPECTRUM & TOLERANCES	NOTES
FLIGHT RANDOM VIBRATION	20 - 50 Hz @ 0.020 g_z/Hz 50 - 150 Hz @ +3 dB/oct. 150 - 500 Hz @ 0.060 g_z/Hz 500 - 2000 Hz @ -6 dB/oct. 2000 Hz @ 0.0038 g_z/Hz Composite = 6.9 g_{rms} Duration = 360 seconds/axis <u>Tolerances</u> Composite Amplitude $\pm 10\%$ PSD Amplitude +100%, -30% Frequency $\pm 5\%$ Duration $\pm 10\%$, - 0%	For the initial 160 seconds of the vibration test, pressurize the test article as noted in the internal pressurization test (section 8.1.2 A-E).
REENTRY RANDOM VIBRATION (Radial Axis)	20 Hz @ 0.036 g_z/hz 20 - 180 Hz @ +6 dB/oct 180 - 280 Hz @ 3.13 g_z/hz 280 - 2000 Hz @ -6 dB/oct 2000 Hz @ 0.059 g_z/hz Composite = 35.2 g_{rms} Duration = 90 seconds/axis For test tolerances, see Flight Random Vibration (above).	None. <i>1000-2000 Hz SYSTEM RESONANCES IN THIS RANGE EXCEEDS PSD AMPLITUDE TOLERANCE.</i>
(Tangential & Longitudinal Axis)	20 Hz @ 0.0039 g_z/hz 20 - 80 Hz @ +6 dB/oct 80 - 275 Hz @ 0.063 g_z/hz 275 - 560 Hz @ -9 dB/oct 560 - 2000 Hz @ 0.0075 g_z/hz Composite = 5.6 g_{rms} Duration = 90 seconds/axis For test tolerances, see Flight Random Vibration (above).	None.

TABLE II
FJEPS TEST CRITERIA (cont.)

TEST	SPECTRUM & TOLERANCES	NOTES
VEHICLE DYNAMICS CRITERIA (Longitudinal Axis) (Lateral Axis)	3.5 - 5 Hz @ 1.0 G's peak * 5 - 40 Hz @ 1.0 G's peak 2 - 5 Hz @ 1.7 G's peak * 5 - 10 Hz @ 0.6 G's peak 10 - 40 Hz @ 1.7 G's peak Sweep Rate = 3 Oct./Min. (1 Sweep from low to high frequency). <u>Tolerances</u> Peak Amplitude +20%, -10% Frequency $\pm$ 5% Duration +10%, -0%	For the initial 160 seconds of the vibration testing, pressurize the test article(s) as noted in the internal pressurization test (section 8.1.2 A-E). * Design Criteria Only.
SRB WATER IMPACT SHOCK CRITERIA (Longitudinal Axis) ----- (Radial and Tangential Axis)	20 G's peak, 0.010 0.050 second, $\frac{1}{2}$ - sine pulse. 2 shocks in flight direction. ----- 8 G peak, 0.010 0.050 second, $\frac{1}{2}$ - sine pulse. 2 shocks in each direction. ----- <u>Tolerances (for both)</u> Amplitude: +40%, -20% Pulse Overshoot: +20% Duration: $\pm$ 10%	Long duration (0.1 - 0.15 sec) pulses are impossible to achieve on most electrodynamic shakers (0.070 - 0.080 sec. being about the limit). Since the majority of the test article response lies in the higher frequency range (compared to these lower frequency pulses) the pulse duration can be decreased to 0.050 sec. with negligible effect.

Revision C

CTP-0054
Page 16

MORTON THIOKOL INC.

Space Operations

Appendix C

DISCREPANCY REPORTS NO. 168169 AND NO. 168188

REVISION _____

89656-1.29

DOC NO. TWR-17245

SEC

PAGE

VOL

C-1

MORTON THIOCK INC.
Wasatch Operation.

[illegible]

ORIGINAL PAGE IS
OF POOR QUALITY

ORIGINAL PAGE IS
OF POOR QUALITY

DISCREPANCY REPORT

MORION THOK NC
Wasatch Operations

1. PROGRAM SPACE SHUTTLE		2. PROGRAM CODE FE		3. NON CON MATL CUST/GOV'TURNITEM		4. PROJECT H03027A053000001		5. PASS ORDER NO N/A		6. VENDOR CODE N/A		7. TOTAL SHEETS X	
7. ASSEMBLY PART NO 7U76358-01		8. REV N/C		9. NAME OF ASSEMBLY F JEPS		10. VENDOR NAME N/A		11. PURCHASE ORDER/CONTRACT NO N/A		12. VENDOR CODE N/A		13. DATE 1-5-89	
12. DISCREPANT PART NO 7U76358-01		13. REV N/C		14. NAME OF DISCREPANT PART F JEPS		15. RECEIVING REPORT NO N/A		16. PURCHASE ORDER/CONTRACT NO N/A		17. VENDOR CODE N/A		18. DATE 1-5-89	
17. TOTAL QTY ONE		18. TOTAL QTY ONE		19. DISCREPANT QTY ONE		20. DISCREPANT QTY ONE		21. DISCREPANT QTY ONE		22. DISCREPANT QTY ONE		23. DISCREPANT QTY ONE	
24. QTY ONE		25. QTY ONE		26. QTY ONE		27. QTY ONE		28. QTY ONE		29. QTY ONE		30. QTY ONE	
31. QTY ONE		32. QTY ONE		33. QTY ONE		34. QTY ONE		35. QTY ONE		36. QTY ONE		37. QTY ONE	
38. QTY ONE		39. QTY ONE		40. QTY ONE		41. QTY ONE		42. QTY ONE		43. QTY ONE		44. QTY ONE	
45. QTY ONE		46. QTY ONE		47. QTY ONE		48. QTY ONE		49. QTY ONE		50. QTY ONE		51. QTY ONE	
52. QTY ONE		53. QTY ONE		54. QTY ONE		55. QTY ONE		56. QTY ONE		57. QTY ONE		58. QTY ONE	
59. QTY ONE		60. QTY ONE		61. QTY ONE		62. QTY ONE		63. QTY ONE		64. QTY ONE		65. QTY ONE	
66. QTY ONE		67. QTY ONE		68. QTY ONE		69. QTY ONE		70. QTY ONE		71. QTY ONE		72. QTY ONE	
73. QTY ONE		74. QTY ONE		75. QTY ONE		76. QTY ONE		77. QTY ONE		78. QTY ONE		79. QTY ONE	
80. QTY ONE		81. QTY ONE		82. QTY ONE		83. QTY ONE		84. QTY ONE		85. QTY ONE		86. QTY ONE	
87. QTY ONE		88. QTY ONE		89. QTY ONE		90. QTY ONE		91. QTY ONE		92. QTY ONE		93. QTY ONE	
94. QTY ONE		95. QTY ONE		96. QTY ONE		97. QTY ONE		98. QTY ONE		99. QTY ONE		100. QTY ONE	

NOTE: CAUSE UNKNOWN

SCOTT WILSON 1500 01/04/89

CAR TO TEST ENGINEERING (Robert Nielsen)

Preliminary Cause Code 04

Preliminary Cost Center 5632

SPSDB DEF FARA HC DC

DR

MOTOR NO. 106

RETEST

CRITERIA 1-5-89

NOTE: REF RD-168169

MARK SWABSKY 8830 01/04/89

ACCEPTABLE DAMAGE NO VISUAL DAMAGE TO TEST ARTICLE. OVERTEST

NET AND EXCEEDED TEST REQUIREMENTS. DATA FROM THIS TEST WILL BE

ACCEPTABLE. FACILITY CHECKOUT WILL BE PERFORMED TO VERIFY THE

INTEGRITY OF THE SHOCK SYSTEM BEFORE TESTING IS CONTINUED.

DATE 1-5-89

FOR RELEASE 1-5-89

DATE 01/05/89

NO 168188

DISTRIBUTION

<u>Recipient</u>	<u>No. of Copies</u>	<u>Mail Stop</u>
M. Cook	4	L36
N. Black	1	L36
M. Williams	1	L36
M. Cox	1	L36
G. Stephens	1	E12
J. Seiler	1	L10
R. Hyer	1	L10
R. Paliga	1	L23
J. Oostyen	1	L23
J. Kapp	1	L20
D. Mason	1	L22
T. Olsen	1	L34
J. Chaffee	1	L22
B. Tams	1	561
R. Larsen	1	851
S. West	1	851
F. Call	45	E05
Print Crib	5	282
Data Management	5	L23E