











![](_page_3_Figure_0.jpeg)

![](_page_3_Figure_1.jpeg)

![](_page_4_Figure_0.jpeg)

![](_page_4_Figure_1.jpeg)

![](_page_5_Figure_0.jpeg)

![](_page_5_Figure_1.jpeg)

![](_page_6_Figure_0.jpeg)

![](_page_6_Figure_1.jpeg)

![](_page_7_Figure_0.jpeg)

![](_page_7_Figure_1.jpeg)

![](_page_8_Figure_0.jpeg)

![](_page_8_Figure_1.jpeg)

![](_page_9_Figure_0.jpeg)

![](_page_9_Picture_1.jpeg)

![](_page_10_Figure_0.jpeg)

![](_page_10_Figure_1.jpeg)

![](_page_11_Figure_0.jpeg)

![](_page_11_Figure_1.jpeg)

![](_page_12_Figure_0.jpeg)

![](_page_12_Figure_1.jpeg)

![](_page_13_Figure_0.jpeg)

particle	Memories
Loss of normal operation	Complex devices with built-in state machine/control sections
High current condition	BJT, N channel power MOSFET
Stuck bit	Memories
Rupture of gate dielectric	Power MOSFETS, flash PROM,.
SESB, HCA,	
	Loss of normal operation High current condition Stuck bit Rupture of gate dielectric SESB, HCA,

![](_page_14_Figure_0.jpeg)

![](_page_14_Figure_1.jpeg)

![](_page_15_Figure_0.jpeg)

![](_page_15_Figure_1.jpeg)

![](_page_16_Figure_0.jpeg)

![](_page_16_Figure_1.jpeg)

![](_page_17_Figure_0.jpeg)

## Science Spacecraft Anomalies During Recent Solar Events

Type of Event	Spacecraft/ Instrument	Notes
Spontaneous Processor Resets	RHESSI	3 events; all recoverable
¢.	CLUSTER	Seen on some of 4 spacecraft; recoverable
	ChipSAT	S/C tumbled and required ground command to correct
High Bit Error Rates	GOES 9,10	
Magnetic Torquers Disabled	GOES 9, 10, 12	
Star Tracker Errors	MER	Excessive event counts
3	MAP	Star Tracker Reset occurred
Read Errors	Stardust	Entered safe mode; recovered
Failure?	Midori-2	
Memory Errors	GENESIS	19 errors on 10/29
	Many	Increase in correctable error rates on solid- state recorders noted in many spacecraft

DCIS04 – Space Radiation Effects presented by Christian Polvey, Bordeaux, France, November 26, 2004

	Recent Sola	ir Events
Type of Event	Spacecraft/ Instrument	Notes
Instrument Failure	GOES-8 XRS	Under investigation as to cause
	Mars Odyssey/Marie	Under investigation as to cause; power consumption increase noted; S/C also had a safehold event – memory errors
	NOAA-17/AMSU-A1	Lost scanner; under investigation
Excessive Count Rates	ACE, WIND	Plasma observations lost
	GALEX UV Detectors	Excess charge – turned off high voltages; Also Upset noted in instrument
	ACE	Solar Proton Detector saturated
Upset	Integral	Entered Safe mode
	POLAR/TIDE	Instrument reset spontaneously
Hot Pixels	SIRTF/IRAC	Increase in hot pixels on IR arrays; Proton heating also noted
Safe Mode	Many	Many instruments were placed in Safe mode prior to or during the solar events for protection

CIS04 - Space Radiation Effects presented by Christian Powey, Bordeaux, France, November 26, 2004

<section-header><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item>

![](_page_19_Figure_0.jpeg)

![](_page_19_Figure_1.jpeg)

![](_page_20_Figure_0.jpeg)

![](_page_20_Figure_1.jpeg)

![](_page_21_Figure_0.jpeg)

![](_page_21_Figure_1.jpeg)

![](_page_22_Figure_0.jpeg)

![](_page_22_Figure_1.jpeg)

![](_page_23_Figure_0.jpeg)

![](_page_23_Picture_1.jpeg)

## Conclusion

- The radiation environment makes the design of electronics for space very challenging
- High total dose hardness levels can be achieved with state of the art technologies
- A variety of design techniques exist for mitigating SEE

ted by Christian Poivey, Borde

- Area, power, speed penalties depend on chosen mitigation approach
- New effects occur for each new technology generation

DCIS04 - Space Radiation Effects prese