



Saturn V - Design Considerations & Launch Issues



Objectives

- ❑ Understand some of the design considerations that went into creating the Saturn V launch vehicle
- ❑ Gain an appreciation for some of the manufacturing issues concerning the Saturn V
- ❑ Review three major problems that affected Saturn V launches

Outline

- ❑ Lunar Voyages
- ❑ Weight Savings
- ❑ Manufacturing Issues
- ❑ Launch Issues



Lunar Voyages

- 3 Options considered:
 - Direct Ascent
 - Earth Orbit Rendezvous (EOR)
 - Lunar Orbit Rendezvous (LOR)

“NASA concluded that LOR offered the greatest assurance of successful accomplishment of the Apollo objectives at the earliest practical date.”¹



Outline

- ❑ Lunar Voyages
- ❑ Weight Savings
- ❑ Manufacturing Issues
- ❑ Launch Issues




Weight Savings

- To increase the payload by 1 kg (2.2 lbs):
 - Remove 14 kg (30 lbs) from S-IC
 - Remove 4 kg (8.8 lbs) from S-II
 - Remove 1 kg (2.2 lbs) from S-IVB


- Topics
 - Common Bulkheads
 - Tank Structures
 - Propellant Utilization (PU)

Common Bulkhead

S-IC



S-II (S-IVB)




Tank Structures



- Waffle pattern was etched into the S-II and S-IVB

Propulsion Utilization (PU)

- ❑ Ensure simultaneous depletion of propellants
- ❑ Increases stage payload capability



- ❑ PU on S-II and S-IVB

Outline

- ❑ Lunar Voyages
- ❑ Weight Savings
- ❑ Manufacturing Issues
- ❑ Launch Issues



Manufacturing Issues

- ❑ Insulation
- ❑ Welding



Insulation

❑ Why is insulation needed?

❑ Internal or External?

External

- Pros: Added material strength, meteorite protection
- Cons: bonding trouble, damage, repeated tanking, large boil-off to condition tank

Internal

- Pros: no bonding trouble, no damage issues, repeated tanking, boil-off to condition tank
- Cons: application

Space Shuttle External Fuel Tank



Insulation

S-II (External Insulation)

- ❑ First method of application: Glue large panels of insulation
 - Trapped air posed problems
 - Tried helium purge to remove trapped air



- ❑ Sprayed insulation on, trimmed excess

Insulation



S-IVB (Internal Insulation)

- ❑ 4,300 individually shaped foam bricks glued to the interior

Welding

- ❑ Large pieces that can deform under their own weight
- ❑ Extremely long welds required with tight tolerances



Welding

□ Problems

- First couple of propellant tanks for S-IC scrapped due to poor welding
- S-II bulkhead ruptured during testing, caused by a faulty, repaired weld
- Cracks in welds of first S-II flight stage caused Saturn V to be de-stacked and the welds repaired (Apollo 4)
- S-IVB flight stage exploded during an acceptance test

Welding

□ Improving Weld Quality

- Propellant tank components cleaned before welding
- Humidity and temperature tightly controlled
- Clean room environment

□ 10 – 15 specialists per welding team

- Every cm of weld had to be inspected
 - S-IC: 10 km/6.2 mi of welds
 - S-II: 1 km/.62 mi of welds
- 8 hours of procedures for a single weld

Welding



Outline

- ❑ Lunar Voyages
- ❑ Weight Savings
- ❑ Manufacturing Issues
- ❑ Launch Issues



Launch Issues – Apollo 6

- Apollo 6 (Saturn 502)
 - S-IC Pogo (duration ~35 seconds)
 - S-II Engines 2 & 3 shut down early
 - S-IVB J-2 failed to restart in orbit



Launch Issues – Apollo 12

- Apollo 12 (Saturn 507)
 - Struck twice by lightning
 - Command Module lost guidance platform
 - No issues to the launch vehicle




Launch Issues – Apollo 13

- Apollo 13 (Saturn 508)
 - Pogo on Stage 2 caused S-II Center Engine to shut down early




Pogo

- ❑ "Pogo" is a rocket scientist's slang for a longitudinal vibration or oscillation that sometimes occurs in rockets
- ❑ Caused by an interaction between the vehicle structure, propellant feed system, and engine system
 - Forced harmonic oscillations
- ❑ Can lead to structural failures or exceed human limitations
 - Tacoma Narrows Bridge collapse



Pogo – Stage 1

- Gaseous helium was pumped into propellant line cavities (Prevalve) to dampen out the pressure changes




Pogo – Stage 2

- ❑ Center Engine (#5) on S-II supported only via cross beams
 - Allowed engine to move, which contributed to the Pogo effect



Pogo – Stage 2

- ❑ Solution was to install a Pogo suppressor on the Center Engine
 - Accumulator filled with LOX pre-start, Helium post-ignition



Post-Flight Analysis of Apollo 6

□ S-II

- Engine 2 shut down due to a fuel leak
- Engine 3's LOX valve was incorrectly commanded to close


□ S-IVB

- Same fuel leak that occurred in S-II occurred in S-IVB




J-2 Engine Failure

Augmented Spark Igniter (ASI) fuel line



- ❑ ASI ignited propellants
- ❑ ASI fuel line broke at attach points in vacuum conditions

J-2 Engine Failure



Vehicle Failures



- ❑ 13 Launches
- ❑ 0 Catastrophic failures

Summary

- ❑ Discussed a couple of weight saving measures
- ❑ Discussed a couple of manufacturing issues for the Saturn V
- ❑ Discussed Saturn V launch issues



References

- ❑ ¹ “Saturn V News Reference”, August 1967
- ❑ “Stages to Saturn”, Roger Bilstein, University Press of Florida, 1993
- ❑ “NASA Experience with Pogo in Human Spaceflight Vehicles”, Dr. Curtis E. Larsen, JSC,
- ❑ “Saturn V Flight Manual (SA 503)”, November 1, 1968,
- ❑ “Saturn V Launch Vehicle Flight Evaluation Report-AS-502 Apollo 6 Mission”, June 25 1968

For More information, please visit the [Apollo-Saturn Wiki](#)