



NASA Work on Fatigue-Induced Cracking of H₂ Flow Control Valve Poppet

Miguel J. Maes

NASA WSTF

June 24, 2009



Agenda

- Problem Overview
- STS Hydrogen Flow Control Valve (HFCV) Layout
- Potential Issues Caused by Poppet Failure
- Discussion of Analysis & Testing Performed
- Current Work to Resolve Problem



Problem Overview

- In November 2008 (Endeavor: STS-126), GH_2 flow from one engine was higher than normal rate 1 min 26 s into launch (8.5 min ascent)
- The other two GH_2 flow control valves reduced their flow rates to compensate
- No major issue during ascent
- After returning to Earth the GH_2 system was inspected




Problem Overview (cont.)


- A piece of the flow control valve poppet was missing
- The HFCV works like a pop-up sprinkler to allow more GH_2 to flow
- The missing piece could have caused
 - a rupture in the GH_2 line –loss of H_2 , main engine (ME) shutdown
 - An over-pressurization in the external tank (ET) – overboard vent, hydrogen/oxygen mixing







Problem Overview (cont.)







STS HFCV Layout

- Three
- per en
- Manif
- Manif
- top of





STS HFCV Layout (cont.)



Potential Issues Caused by Poppet Failure




- The missing piece could have caused:
 - A rupture in the GH_2 line –loss of H_2 , main engine shutdown

REASONS:

- Poppet is a very hard material ($R_c=50$ min)
- System lines are much softer, lighter material ($\text{HRB}=85$)
- If a poppet particle is released, could the free particle puncture the downstream system piping?

Potential Issues Caused by Poppet Failure



Potential Issues Caused by Poppet Failure



- The missing piece could have caused:
 - An over-pressurization in the external tank (ET) – overboard vent, hydrogen/oxygen mixing

REASON

- While a single HFCV poppet failure can be handled safely by the throttling of the other two HFCVs, multiple failures at once could over-pressurize ET
- ET is maintained between 32 and 34 psia
- Consider all three SSMEs could empty a large public swimming pool in 3 min (SSME=375,000 lbf is 100% throttle thrust each at liftoff)

Discussion of Analysis & Testing Performed



■ Analysis


- Computational fluid dynamics (CFD) modeling for vibrational modes
- Hydrogen/oxygen mixing at supersonic velocities
- Lots of material analysis, nondestructive evaluation (NDE), and NDE technique development

■ Testing:

- Particle velocity testing
- Particle release testing
- Resonance/flutter testing
- Acceptance testing

-

Discussion of Analysis & Testing Performed (cont.)



Discussion of Analysis & Testing Performed (cont.)




- Testing:
 - Particle Release Testing




After all preparations were made, testing at SSC was cancelled, this apparatus not used





Current Work to Resolve the Problem



6/24/2009

Miguel J. Maes

15



Current Work to Resolve the Problem

■ Testing:

○ Acceptance Testing

- NDE (eddy current) new poppets ← New process
- GN₂ poppet balance (at vendor)
- EC post test ← New process
- GN₂ flow calibration (at vendor)
- EC post test ← New process
- GH₂ flow calibration (at WSTF)
- GH₂ mission duty cycle for acceptance (at WSTF)
- EC post test ← New process



Current Work to Resolve the Problem

- New poppet materials under review
 - Considerations
 - Need a material that has resistance to cycle fatigue
 - But still has good hydrogen compatibility
 - And can maintain dimensional stability through a wide range of operating temperatures (- 40 to 90 °F)
 - Shuttle program is slated to retire in 2010
 - Difficult to get funding for a whole new qual program with 1 year remaining



Questions?



References

- Flow Control Valve Fact sheet (publicly available) Feb. 3, 2009
http://www.nasa.gov/pdf/313985main_Flow_Valve_Fact.pdf
- NSTS 1988 News Reference Manual (publicly available)
<http://science.ksc.nasa.gov/shuttle/technology/sts-newsref/stsref-toc.html>
- Main Propulsion System Propellant Management Subsystem
<http://spaceflight.nasa.gov/shuttle/reference/shutref/orbiter/prop/propellant.html>