



External Surface Changes Observed on the International Space Station (ISS) Through 2010

J. L. Golden, Ph.D.
Boeing Technical Fellow
ICPMSE-10J Okinawa, Japan
13 June 2011

External Surface Changes on ISS

Engineering, Operations & Technology | Boeing Research & Technology

Materials & Fabrication Technology

- **Acknowledgements**
 - All Boeing and Boeing subcontractor activity conducted under NASA contract
 - NAS15-10000
 - All photography courtesy of NASA
 - Special thanks to the NASA Flight Image Science & Analysis Group (KX).

External Surface Changes on ISS

Engineering, Operations & Technology | Boeing Research & Technology

Materials & Fabrication Technology

Summary of Presentation

A sampling of ISS on-orbit and post-flight photography showing space environmental effects (SEE) in conjunction with:

- **Basic Materials Selection Issues**
- **Inadvertent Materials Substitution**
- **Materials Handling Issues (Ground Contamination)**
- **Contamination and MMOD**
- **Imaging Itself**

External Surface Changes on ISS

Engineering, Operations & Technology | Boeing Research & Technology

Materials & Fabrication Technology



ISS 2010

S129E009239

Copyright © 2009 Boeing. All rights reserved.

ICPMSE-10J J.L.Golden 2011 June 13 4

External Surface Changes on ISS

Engineering, Operations & Technology | Boeing Research & Technology


Materials & Fabrication Technology

Basic Materials Selection + SEE

Solar Array Wing (SAW) Blanket Box Assy

Polyimide Foam Covered by Aluminized Polyimide Film

Aluminized Film was severely degraded within months!



ISS003E5082 2001/08/04 03:40:57

External Surface Changes on ISS


Engineering, Operations & Technology | Boeing Research & Technology

Materials & Fabrication Technology

Basic Materials Selection + SEE

Solar Array Wing (SAW) Blanket Box Assy

Not all SAWs were equally affected, plus the damaged occurred quickly and did not continue with time.



3 Months



38 Months

External Surface Changes on ISS

Engineering, Operations & Technology | Boeing Research & Technology

Materials & Fabrication Technology

Basic Materials Selection + SEE

Trailing Umbilical System (TUS) Reel Grounding Strap (Tin-Plated)




External Surface Changes on ISS

Engineering, Operations & Technology | Boeing Research & Technology

Materials & Fabrication Technology

Basic Materials Selection + SEE



Detail of tin pest region

Ground strap removed from TUS

Scratches serving as initiation sites; low temperatures on-orbit accelerate phase transformation


External Surface Changes on ISS

Engineering, Operations & Technology | Boeing Research & Technology

Materials & Fabrication Technology

Basic Materials Design + SEE

ATV1 Thermal Blankets
show insufficient venting




S124E005722

External Surface Changes on ISS

Engineering, Operations & Technology | Boeing Research & Technology

Materials & Fabrication Technology

Inadvertent Materials Substitution + SEE



Battery Box Covers have a “Beta cloth” outer layer. One cover was inadvertently constructed using Chemfab 250 (with silicone sizing agent not removed during its fabrication) while other cover was correctly constructed using Chemfab 500.

photo iss015e21921.jpg

External Surface Changes on ISS

Engineering, Operations & Technology | Boeing Research & Technology

Materials & Fabrication Technology

Materials Handling Issues (Ground Contamination)




ISS026E030931

External Surface Changes on ISS

Engineering, Operations & Technology | Boeing Research & Technology

Materials & Fabrication Technology

Materials Handling Issues (Ground Contamination)




External Surface Changes on ISS

Engineering, Operations & Technology | Boeing Research & Technology

Materials & Fabrication Technology

Space Environmental Effects



MMOD impacts on handrails are becoming increasingly troublesome, causing EVA glove damage

S128E008100_can

External Surface Changes on ISS

Engineering, Operations & Technology | Boeing Research & Technology

Materials & Fabrication Technology

Space Environmental Effects



Anodized aluminum labels, which darkened quickly, have begun to recover their expected appearance with continued AO exposure!

S128E008103

External Surface Changes on ISS

Engineering, Operations & Technology | Boeing Research & Technology

Materials & Fabrication Technology

Space Environmental Effects – Frequent and “New” Visiting Vehicles



Soyuz docked to FGB
Outgassing or Thruster
Contamination

ISS022E067004

External Surface Changes on ISS

Engineering, Operations & Technology | Boeing Research & Technology

Materials & Fabrication Technology

Space Environmental Effects – Frequent and “New” Visiting Vehicles



Opposite
direction
from
previous
photo


ISS021E031911

External Surface Changes on ISS


Engineering, Operations & Technology | Boeing Research & Technology

Materials & Fabrication Technology

Issues with Imaging



Charged Particle affecting Digital Video Camera Imaging




External Surface Changes on ISS

Engineering, Operations & Technology | Boeing Research & Technology

Materials & Fabrication Technology

Issues with Imaging - Reflections



ISS023E021963


External Surface Changes on ISS

Engineering, Operations & Technology | Boeing Research & Technology

Materials & Fabrication Technology

Issues with Imaging

Pre-berthing inspection of a Node 1 sealing surface in 2001 identified these circular features as a concern. These features were later determined to be reflections of the camera's LED lighting system on the smooth, anodized aluminum sealing surface. No such feature actually exists.



External Surface Changes on ISS

Engineering, Operations & Technology | Boeing Research & Technology

Materials & Fabrication Technology

Summary

- **Some worse-than-expected materials degradation effects have been observed, but none have created any operational issues and some hardware (as with the anodized aluminum labels) appear to be recovering.**
- **Inadvertent materials substitutions have been observed, but none have created any operational issues.**
- **Hardware handling contamination effects have been observed, and although none have created operational issues, there is clearly room for improvement in this regard.**
- **Even with robust materials selections, space environmental effects will be observed.**
- **Be cautious when interpreting on-orbit photography, as lighting conditions and the space environment affect imaging.**

