

# **SPACE STATION SOLAR ARRAY JOINT REPAIR**

**Stuart Loewenthal\* , Curtis Allmon\* , Carter Reznik\*\* ,  
Justin McFatter\*\* and Robert E. Davis\*\*\***


**\*Lockheed Martin Space Systems Company, Sunnyvale CA**

**\*\*Boeing Space Systems, Houston, TX**


**\*\*\*NASA Johnson Space Center, Houston, TX**



# Solar Alpha Rotary Joint (SARJ)




- SARJ orients port & starboard solar array wings to sun providing power to station
  - 12 Trundle Bearing Assemblies support a 10.5 ft diameter race rings (redundant)





# SARJ Trundle Bearing Assys & Race Ring

## Candidate Bearing Configurations



### Trundle Bearings


- Less Sensitive to Temp
- Easier to Replace
- Lighter
- Easier to Make



# The Problem

- On 22 Oct 2007, ISS crew noticed vibration on camera in vicinity of Starboard SARJ
  - Unit had less than 4 months running time
- Velocity trace showed irregular servo errors at several clock positions
- Crew sent out to inspect and found race damage on outer 45 deg track
- Inner 45 deg & Datum-A races Okay
- Port SARJ races Okay  $\approx$ 14 months at time of inspection


Starboard SARJ Day 245 - 250  
RJMC Velocity Error Voltage Statistical Analysis by Joint Angle



Starboard SARJ  
velocity error  
changing each day




# Outer 45 Deg Race Shows Significant Damage




- Outer 45 deg race damaged
- Nitrided case spall fragments and ground up fine particles collected




# Tipping Mechanism




misaligned roller  
creates side slip  
between roller &  
race



tipped roller creates  
high edge contact  
stress



tipping  
confirmed




wear on edge of  
mistracked roller

**Side force from misalignment plus high friction  
creates tipping and high contact edge stress**

# Failure Investigation

- Government –Industry team formed to determine root cause
- Root cause found to be roller misalignment (aka mistracking) coupled with high contact friction
  - generates tipping and high roller edge contact stresses
  - edge stresses high enough to crack/fatigue the nitrided case
  - intergranular networking (crack-like separations) likely contributed to damage
- Least difficult repair would be to lubricate the SARJ tracks with grease
- How do we validated this fix and how long will it last between regreasing?
  - build a high fidelity SARJ life test rig

fragments



Intergranular networking  
in nitrided case


# Test Rig Parameters

- **Test rings diameters scaled by factor ~ 3 from flight**
  - able to fit into a reasonably sized vacuum chamber
- **3 full size, flight-like trundle roller assemblies selected vs normal 12.**
- **Track diameter sized to keep roller spacing same as flight**
- **Test plate is flight-like (same materials, heat-treats, surface finish)**
- **Outer track simulates damaged 45 deg outboard starboard flight race**
- **Inner track simulates undamaged Datum A roller contact**
- **Rollers have flight diameters, hardness, surface finish and profiles**
- **Mistracking angle set to 0.37 deg high-nominal**
- **Test Rig runs 24/7 with continuous data recording & safety shutdowns**
- **Side friction, drag & tipping angle recorded**
  - as indicator of lubrication degradation
  - provides on-orbit health trending data
  - trigger limits for rig safety shutdown
- **Vacuum ( $<10^{-5}$  torr) at ambient temp**






# Proving the Race will Last with Grease




**SARJ LITE Test Rig  
outside of vacuum chamber**




**Each Roller Trundle Assembly  
is Well Instrumented**



# Outer and Inner Tracks Simulate On-Orbit SARJ




Outer track pre-test damaged to simulate 45 deg outer race



Inner track simulates datum A track







Outer test track grease lubricated with Astronaut EVA tool





# Test Results Showed Relatively Steady Contact Friction Levels, Roller Tipping and Drag Torque Throughout Test




36 yr  
on-orbit  
revs

36 yr  
on-orbit  
revs



# Test Tracks at End of Test



Inner and outer test tracks



Datum A inner track



45 deg outer track

**Both Tracks showed Minor Wear after  
36+ Equivalent On-orbit Years**



# Post Script: *SARJ Races Greased (STS-126 Nov 2008)*

- Rollers replaced on damaged SARJ
- Starboard & Port Races cleaned & greased.



***Motor current and vibe levels returned to near normal***

- rose slightly through the years but still well below safe levels