



Space Shuttle Stiffener Ring Foam Failure Analysis, a Non-conventional Approach.



Philip M. Howard

NASA

Kennedy Space Center

Materials Science Division

Shuttle Legacy Flight Hardware will Fly on the Space Launch System



Space Shuttle on Ascent




SRB Recovery




Stiffener Ring




SRB Foam Buildup



•1/8 bond coat



•Coating Buildup



•Pull
•Test
•>20psi




Qualitative Inspection



- ATK define the foam failures qualitatively by visual inspection of the presence or absence of foam residue on the de-bonded surface.
- Foam Failures fall into two categories
 - Adhesive
 - Cohesive
 - Mixture of both



Solid Rocket Booster Stiffener Ring Foam Failure



Solid Rocket Booster Stiffener Ring Foam Failure



The classical methods of analysis failed to provide a root cause into this foam failures for the last 25 years.

- Chemistry-extraction of residues
- Bulk property test
- Fracture analysis
- No known nondestructive analysis
- 10,000's of hours testing “process” variables

A new approach was needed

How would a microscopist look at this?

Cell morphology determines the mechanical strength of the foam.

Foam is the ideal media to preserve its own failure.

Cross sectioning to observe the cell morphology.



Foam Chemistry



- A/B Ratio- mechanical strength and flexibility
- Blowing agent function of vapor pressure and temperature
- Exothermic reaction –driving the reaction rate
- Moisture


Application parameters




- Optimum two part ratio
 - Viscosities
 - Delivery Pressures
- Temperature
 - **Substraight temperature – infinite heat sink**
 - Exothermic reaction ~140 F
 - Ambient - outdoor conditions
- Operator application technique
 - Spray pattern
- Formulation changes
 - Blowing agent
 - Catalyst
- Humidity-dew point
 - Cure rate
 - Substraight




Polarized Light Microscopy



Polarized Light Microscopy of Foam






Exemplar




Failed Surface

Cross Sectioning of Foam




- Plastic slide with double
- sided tape




• 1st cut 1 mm
section single edge
razor

• 2nd cut 0.5-1mm
section double
edge razor



Cross Section of SRB Foam Failure




Chief SRB Engineer –we have never looked at foam like this


SRB Foam Failure



- Adhesive failure at RT-455
- Attachment ligament



SRB Foam Failure



SRB Foam Failure



The foam bond coat displayed two modes of failure:

- >80 percent application failed
- Cohesive failure was observed due to severely deformed foam cells in the bond coat
- Adhesive failure was observed at the RT-455 Epoxy interface.

The observed morphology indicates that the bond coat was not fully cured before other forces were applied, e.g. the expansion forces of the second coat distorted the bonding cells.




Process Changes

- Develop spray hardware to apply micro bond layers ($< 1/8''$ layers)
- The bond coat should be allowed to completely dry/cure
Never apply over wet uncured layers
- Smaller Soup can (1/2 inch) inspection plugs for SEM analysis should be developed

Sunset on International Space Station Expedition 15



ISS015E10469



A View from Above!




ISS007E07306


Supplemental Data



•30 % adhesive failure



MSL-2007-0134
1


200µm


EHT = 20.00 kV
WD = 8.5 mm


Signal A = QBSD
Mag = 27 X

Date : 13 Apr 2007
Time : 14:46:38

50 PSI



78 PSI



MSL-2007-0134
3

200µm
—|—|—

EHT = 20.00 kV
WD = 7.5 mm

Signal A = QBSD
Mag = 30 X

Date : 13 Apr 2007
Time : 15:27:54