




Lessons from the James Webb Space Telescope Vibration Test Prep



T. Schwartz
NASA GSFC



Agenda



JWST/OTIS Overview

Facility Commissioning Challenges

Operational Constraints

Control System

Data Acquisition

Pre/Post Test Signatures



James Webb Space Telescope (JWST)





Mission Objective

- Study the origin and history of galaxies, stars and planetary systems
 - *Optimized for infrared observations (0.6 – 28 μm)*

Organization

- Mission Lead: Goddard Space Flight Center
- International collaboration with ESA & CSA
- Prime Contractor: Northrop Grumman Space Technology
- Instruments:
 - Near Infrared Camera (NIRCam) – Univ. of Arizona
 - Near Infrared Spectrograph (NIRSpec) – ESA
 - Mid-Infrared Instrument (MIRI) – JPL/ESA
 - Fine Guidance Sensor (FGS) – CSA



Description

- Deployable telescope w/ 6.5m diameter segmented adjustable primary mirror
- Cryogenic temperature telescope and instruments for infrared performance
- Launch on an ESA-supplied Ariane 5 ECA rocket to Sun-Earth L2




Facility Requirements



- Test article size
 - OTIS envelope: 8'-5" x 7'-10" x 28'-3"
 - OTIS mass: 8,686 lbs
 - Fixture mass: 6,200 lbs
- Cross-axis motion
 - Bare Table: <10%
 - OTIS Payload: <40%
- Overturning moment capacity
 - Must react moments simultaneously
- No test aborts <400ms


	Horizontal	Vertical
Pitch	3.50e6 in-lbf	1.30e6 in-lbf
Roll	180,000 in-lbf	400,000 in-lbf
Yaw	50,000 in-lbf	300,000 in-lbf




Axis	Frequency (Hz)	Test Level (zero to peak)
V1	5-50	1.00 g
	50-80	1.25 g
	80-100	1.00 g
V2	5-50	1.00 g
	50-60	1.50 g
	60-80	1.00 g
	80-100	1.50 g
V3	5-20	1.50 g
	20-40	0.75 g
	40-60	1.25 g
	60-100	1.00 g



Dual Shaker Systems



- Horizontal system
 - T-film slip table system
 - Single ED shaker
 - Excite V1 & V2 axis
- Vertical System
 - Patented inertial mass guidance
 - Dual ED shakers
 - MIMO control
 - Excite V3





Horizontal System

- Design Concept: T-Film slip table with high rotary inertia reaction base
 - Expansion of standard Team T-Film Table to accommodate extremely large overturning moments
- Design Components:
 - Electrodynamic Shaker
 - Single 50,000 lbf shaker
 - Air isolated trunnion mount
 - T-Film Table
 - Hydrostatic Bearings
 - Couples overturning moments into reaction base
 - Reaction Base
 - High rotary inertia
 - Air isolated
 - High density concrete masses







Horizontal System – Hydrostatic Bearings




- T-Film Bearings
 - Fundamental element in Team slip tables
 - Reacts roll and pitch moments
 - Placed in load path from OTIS to reaction base
- Yaw Bearings
 - Reacts yaw moment
 - Guides slip plate in shaker axial direction
- Filler Elements
 - Static load support
 - Do not react moments
- 5-degrees of control



T.Schwartz/NASA GSFC




Vertical System




- Design Components:
 - Electrodynamic Excitation
 - Dual 50,000 lb shakers
 - Guided Head Expander
 - Transmits energy from shaker to test article
 - Inertial Masses
 - React moments generated by test article
 - Hydrostatic bearings
 - Provides short, stiff load path into masses
 - Air Isolated Supports
 - Isolates vibration system from building



Vertical System





Horizontal System

Vertical System



Soft Shutdown

- The soft shutdown requirement was integral to the system design
- Shutdowns are controlled by the furnished Data Physics control system
 - Abacus hardware
 - SignalStar Vector/Matrix software
- Shutdown time is software programmable
- The Abacus generates an enable signal that is passed to all hardware required to enable test (stop switch, THC, amplifier, TAPS)
- Each piece of equipment must command a relay closed to return the enable signal
- Removal of the enable signal triggers a controlled shutdown

Facility Commissioning Challenges

- Poor Coherence on Shaker#2:
 - Determined to be caused by poor connection between copper current lead and aluminum lead block on shaker
 - The likely root cause of the poor connection is a combination of dimensional discrepancy and galvanic corrosion



Arcing caused by the poor electrical connection.




A good electrode on the top

The bad electrode on the bottom

Facility Commissioning Challenges

- Opening the shaker up to investigate the coherence problem uncovered cracks in the copper compensating bands
 - Cracks formed in weld areas joining copper plates
 - Cracks formed in the plug welds joining the copper plate to the steel body
- Further investigation showed these cracks in all 3 DP shakers
- DP return the 2 vertical shakers to Corona for repair
- Horizontal shaker remained installed at GSFC



Facility Commissioning Challenges

- The shaker tear down also revealed some possible wear on the upper armature bearing
 - Initially thought the coherence problem could be stiction in bearing or armature rubbing
 - Raised concerns that shaker armature is over constrained
- Possible solutions
 - Redesign shaker driver adapter, adding compliance
 - Increase armature gap in shaker body
 - Compute lateral armature deflections from test data
- DP offers that the copper bands can be removed
 - Acts as a transformer but only at high frequencies (>500Hz)
 - Eliminates troublesome cracked components
 - Increases gap around armature




Figure 1: cross section 5022-3 shaker



Shaker Rework



- Decision to remove compensating bands
- Factory acceptance test without compensating bands
 - Without cooling integral to the compensating bands, shaker body gets hot and stays hot (250F on body and center pole)
 - Peak force degradation begins at 70Hz
- DP reconsiders and recommends reinstalling compensating bands/cooling, but first turning down the shaker body to retain gap
- JWST agrees and shaker #1 is expedited on the new plan with shaker #2 to follow



Shaker #1 Returns to GSFC



- Shaker #1 completes factory acceptance test and is shipped to GSFC
- During on site acceptance testing, at 27 min into a 30 min random test at 80% force, the amplifier aborted on a peak current fault
- The armature had ruptured and gallons of armature cooling water erupted into the shaker body.





Shaker #1 Compensating Band





Shaker #1 Hot Spots and Rupture



JWST-PV-106097

Blow out area between
steel cladding



JWST-PV-105841





Shaker #1 Failure

- Poor process control resulted in a poor installation of the compensating band
 - Copper was not in sufficiently in contact with the steel
 - Welding process not well controlled, resulted in poor heat conduction
 - The final machining of the band (following welding) resulted in very thin sections of the band
- The armature in shaker #1 was the armature exposed to “no copper” testing
 - Overheating of the fiberglass insulation resulted in compromised mechanical and dielectric properties resulting in catastrophic arcing



Shaker #2

- Following the failure of shaker #1, DP step up efforts to complete shaker #2 rework, perform factory acceptance testing, and deliver to GSFC
- Hot spots on shaker #1 were discovered while shaker #2 was in the midst of factory acceptance test, prompting disassembly of shaker #2 for inspection
- Some hot spots were found on shaker #2, but to a lesser extent than shaker #1



Operational Constraints



- Limit heating of the shaker internals
 - Limit amplifier current to 1750A, ~70% of capability
 - Reduces shaker force to ~35,000 lbf
 - Implemented as limit channel on controller
 - Measure hot spot temp directly with thermocouple
 - Record TC as response channel during test
 - Applied abort limit to TC at 100C
- Monitor voltage coherence for any deviation
- Monitor head expander/slip table/vibe fixture temps
 - Required average temp of 24C +/-3C to perform any test runs



Control System



- Data Physics Abacus/SignalStar
- Integral to satisfying soft shutdown requirement
- During the facility commissioning phase a hard shutdown was experienced while testing on the slip table
 - “Urgency Stop” error message was reported in the software
 - Shaker stopped abruptly
 - DP determined that the software had called for a stop in zero seconds by executing an unexpected code path due to a communication error
- NASA GSFC Flight Software Division was brought in to help



Control System

- Identified that the communication error is a vulnerability when using more than one Abacus chassis (>32 channels)
 - Communication over Ethernet in a 'realtime' control system is not robust
 - Ethernet protocol ensures that the data packets will get there eventually
 - Eventually resolved to limit control system to 32 channels
- Hard code 400ms shutdown is such a way that "stop" cannot be called with any other value
- Several other important, but less critical issues were identified
 - Software lockup
 - Lack of a global scale factor for limits
 - Overwrite of test data
 - Improper channel labeling
 - Painfully slow parameter file generation



Control System



- It took several months to get the bugs fixed, properly tested, and the new version delivered
- The fixes implemented seemed to reveal more bugs
 - Faulty start up logic when limits predicted to engaged at start frequency
 - Faulty startup logic when limits predicted to engage as stop frequency.
 - Failure to generate COLA running multiple test runs
- DP went through several iterations and provided several software releases to us
- Settled on a release that was stable and the known risks could be mitigated



Data Acquisition



- Initial requirement ~500 channels
- Existing DSPCon DataFlex 1000 Hardware 320 channels
- Supplemented by purchasing m+p VibRunner

- Final configuration: 544 channels of response + 64 channels for facility
 - 288 channels of DataFlex for response
 - 256 channels of VibRunner for response
 - Additional 64 channels of DataFlex backing Abacus and recording facility channels (reaction base accels, amp current, amp voltage, bearing pressures, etc.)



Data Acquisition


- After adding the VibRunner hardware we approached m+p about their ability to interact with our soft shutdown circuit.
- VibRunner is capable of commanding relays with digital I/O to trigger shutdown when abort limits are exceeded
- In our configuration VibRunner controls two relays in series
 - A normally open relay is commanded closed to enable the controller
 - A normally closed relay is commanded open when an abort limit is exceeded



Data Acquisition



- The resulting system can trigger an abort on any of the 256 channels
- Limitations:
 - COLA must be present to function, due to our use of the sine reduction package to drive data acquisition
 - Only configured to abort on time domain peak acceleration
 - Other options should be possible, but have not tested them yet






Completion of Facility Commissioning



- Dynamic test mass
- Final software
- Enforcing operational constraints
- Performing OTIS test specification









Pre/Post Signature

- Sine control at requested levels (0.025 to 0.05g) difficult to control with lightly damped test article





Pre/Post Signature






Pre/Post Signature

- Implemented method using open-loop pretest random for signatures
 - Computed transfer functions
 - Flat random drive signal does not result in uniform excitation, but transfer functions normalize the results
 - In axis input monitor accel as reference
 - SignalStar gives the user control over the pretest drive signal
 - Number of averages (indirectly controls duration)
 - Shaped pretest
 - Define breakpoints to set relative amplitudes
 - Burst random – need to experiment with this one
- This technique has the benefit of a built in signature in every test run




Example Response Signature Overlay



Notes:
(1) MP_V1Swp90.mat
Channel 52
Run: MP V1Swp90 : PreTest Only
Analysis: PreTest Transfer Fcn

Project: JWST
Test Item: OTIS
DDAS Channel: 52
Location: Fsum 300V3 F300V3
Low Pass Filter: 3686.4

Data Source	Units	Max Amp / Freq	Min Amp / Freq
(1) MP _V 1Swp90.mat	1b	1.47e+05 / 10.63	145 / 55.63
(2) MP _V 1Swp88.mat	1b	1.27e+05 / 10.63	115 / 55.63






Pre/Post Signature

- The pretest results were also used to verify facility and test article health in a more limited fashion after the execution of every pretest.
- For the 32 channels on the controller, transfer functions relative to the drive are already computed in SignalStar.
- This data was copied to an excel file and pasted into its own sheet.
- A macro was written to generate a new sheet with a chart for each channel overlaying data for all the runs stored in the current file.
- In this way all channels can be check for trends against the previous 5 to 10 runs.
- The process is fast enough that it can be completed for every run prior to executing the sweep.
- Sensitive to changes in the gain knob setting



Example Controller Pretest Overlay





Questions

