



LESSONS LEARNED FROM FLIGHT OBSERVATIONS OF THE GOES-R MAGNETOMETER



R. Schnurr⁽¹⁾, T. Bonalsky⁽¹⁾, M. Todorita⁽¹⁾, J. Kronenwetter⁽²⁾, D. Early⁽²⁾, M. Grotenhuis⁽³⁾,
R. Studer⁽⁴⁾, D. Carter⁽⁵⁾, R. Dence⁽⁶⁾, M. Wolf⁽⁶⁾, J. Mandi⁽⁶⁾


¹NASA, Greenbelt USA • ²Chesapeake Aerospace, Grasonville USA • ³SSAI Inc., Lanham USA • ⁴AS and D, Beltsville USA • ⁵Thearality, Inc, Glendale USA • ⁶Lockheed Martin Space, Littleton USA •



Introduction


Geostationary Operational Environmental Satellites (GOES)

- United States weather satellites in geostationary orbits
- Joint project between the National Oceanic and Atmospheric Administration (NOAA) and the National Aeronautics and Space Administration (NASA)



GOES-16

- GOES-R launched November 19, 2016
- The first satellite in the series, GOES-R, was renamed GOES-16 upon reaching geostationary orbit
- GOES-16 at GOES-Checkout location (89.5° W) during PLT
- The GOES-16 magnetometer boom was deployed on December 7, 2016 and magnetometer checkout began






Introduction

GOES-16 Magnetometer



- Measures the “in-situ” ambient magnetic field at geostationary orbit
- Consists of inboard (IB) and outboard (OB) fluxgate sensors mounted on a deployable boom 6.3 and 8.5 meters from the spacecraft, respectively
- Both the IB and OB measure the magnetic field in three orthogonal axes. The Z-axis follows the centerline of the deployed boom while X and Y are parallel to the mounting plate





On-Orbit Observations

Large Zero Offset




- Boom rotates about sensor Z axis providing visibility into X and Y axis zero offset
- Inboard Offset:
 - X axis = -6.3 nT
 - Y axis = -44.5 nT
- Outboard Offset:
 - X offset = -5.3 nT
 - Y offset = -32.6 nT
- ~ 30 to 40 nT change in Y axis relative to ground calibration



On-Orbit Observations

Large Variation Between Inboard and Outboard


- Expected difference between the two magnetometers should be <2 nT with small variances in the spacecraft field causing diurnal variation
- On-Orbit difference repeatable day to day with 15 to 20 nT swing in Y and Z axes
- Most of the variation is due to the Inboard Magnetometer





On-Orbit Observations Variation In Outboard Magnetometer



- Outboard Magnetometer has 5 to 10 nT variation when compared to existing on-orbit GOES satellites





Root Cause Investigation Inboard Shadowing



- Large swings in Inboard measurements correlates to shadowing of magnetometer by Spacecraft body and antenna



View from the Sun immediately prior to Inboard shadowing

Root Cause Investigation Inboard Shadowing


- Large swings in Inboard measurements correlates to shadowing of magnetometer by Spacecraft body and antenna



View from the Sun - Inboard shadowed

Root Cause Investigation Inboard Shadowing


- Large swings in Inboard measurements correlates to shadowing of magnetometer by Spacecraft body and antenna



View from the Sun - End of Inboard shadowing by Spacecraft body

Root Cause Investigation Inboard Shadowing

- Large swings in Inboard measurements correlates to shadowing of magnetometer by Spacecraft body and antenna



View from the Sun - Inboard shadowing by Spacecraft Antenna




Corrective Action Approach for GOES-S

- Identify all potential sources of magnetic contamination and eliminate
 - Thermo-electric effect (Seebeck or loop currents), or
 - Unintended contamination from magnetic material
- Perform ground tests where possible
 - Conservative approach is to eliminate regardless of test results
- Areas of concern:
 - Mounting plate and p-clamps
 - Mounting plate to boom bracket
 - Metallic backshell and grounding plug
 - Thermal blanket copper ground wires
 - Thermal blanket closeout tape
 - Incorrect cable length between sensor unit and electronics unit
 - Thermal design



Corrective Action Sensor Plate

- **Harness p-clamps wrapped in copper tape in contact with vapor deposited aluminum (VDA) on the magnetometer sensor plate**
 - Potential for current loops in the VDA
 - Potential to create voltage difference (Seebeck effect) along the loop formed by the harness, copper tape, and VDA.



Ground Testing did not generate stray magnetic field.

- Created 80C gradient across plate with harness and p-clamps
- Expected on-orbit gradient is ~90C

Design Changes:

- Score inboard and outboard VDA-coated mounting plates
- Replace copper tape on the p-clamps with non-conductive GBK tape
- Isolate multiple harnesses from each




Corrective Action Mounting Bracket

- Mounting bracket of the inboard plate has a chromium plated pin in contact with aluminum and titanium.
 - Seebeck coefficient for chromium and aluminum is 20.1 and $-2.9 \mu\text{V/K}$
 - Potential for field at magnetometer of 0.26 nT/K.

AL 7075-T73

Chrome plated
A286 pin

TI 6Al-4V



No Ground Testing Performed

- 77C gradient needed to create field unlikely due to size and high thermal conduction


Design Change:

- Replace the chrome-plated pin with a ceramic pin



Corrective Action Backshells


- **Metallic backshell and grounding plug allowing loop currents to form near the magnetometer**



No Ground Testing Performed

Design Change:

- **Replace backshell and grounding plug cover with non-conductive polymeric 3-D printed parts**





Corrective Action Thermal Blankets

- Thermal blanket has two grounding wires emanating from ends of the blanket.
 - Blanket are aluminum sheet and the wire is copper creating possible Seebeck effect



Ground Testing did not generate stray magnetic field.

- One side of blanket heated to 80C

Design Change:

- Eliminate second ground wire and lug





Corrective Action Ferromagnetic GBK Tape

- Germanium Black Kapton (GBK) tape with nickel coated beads for ESD inadvertently used during close out
 - Tape remained on the blankets for about three days
 - Tape removed and the correct GBK tape applied



Ground Testing:

- ESD tape can have up to 60 nT field at magnetometer
- Residual tape adhesive can have up to 5 nT field at magnetometer
- Magnetic field of tape can change by ~ 0.05 nT/C
 - Blanket expected temperature change from -175C to 75C

Corrective Action

- Enhanced magnetic screening and monitoring.





Corrective Action Incorrect Cable Length

- **Shield Can test added to the GOES–S spacecraft testing**
 - Magnetometers removed from the stowed boom and placed in magnetic shield cans
 - Measure noise and zero offset in ambient conditions
 - Zero offsets measured by manually rotating the sensors in the shield cans.
- **GOES-S Zero offsets significantly different from expected based on box level calibration**
 - up to 12 nT different
- **Discovered tuning and calibrations performed with cable configuration inconsistent with the flight configuration**
 - 2.4m difference in length.
- **Determined GOES-R flown with same configuration that was inconsistent with tuning and calibrations**
- **Design Change:**
 - Flight cables from electronics box to boom swapped to more closely match lengths of cables used during tuning and calibration



Corrective Action Thermal Control

- Insufficient thermal control requirements result in large swings in the bobbin temperature.
 - Temperature compensation applied but calibration accuracy and zero offset stability concern for such large temperature variations




- Design Changes:
 - Addition of blanket over the existing blanket
 - Addition of blankets over the harnesses
 - Addition of a heater and control thermistor to the harness adjacent to the sensor unit to reduce heat loss through the harness.



GOES-17 Results

- GOES-17 launched March 1, 2018.
- No large excursions during shadowing period from November December.
- Diurnal variation is greatly reduced.





Conclusions/Lessons Learned

- **Stringent magnetic screening and monitoring needs to be in place and followed at all times.**
 - All material used near the magnetometer needs to be screened and tagged as magnetically clean. Reliance on part numbers and kitting is insufficient.
- **Calibration of the sensors needs to be performed at the highest level of accuracy if there is any chance of thermal drift or thermal gradients.**
 - This includes measuring in a flight-like thermal environment.
- **System level testing at the spacecraft needs to include the ability to trend the zero offsets through the integration and test program.**
- **The accommodation design must eliminate the possibility of current loops, including in thermal blankets and harnessing.**
- **Adequate thermal requirements need to be established to maintain minimal temperature swings across the bobbins.**
- **Sensor unit thermal accommodation thermal requirements need to be understood and defined early in program through accurate thermal characterization of the sensor.**
- **Instrument level thermal balance is needed since spacecraft level thermal balance is insufficient for the accuracy required.**