



The International Space Station (ISS) Port 1 (P1) External Active Thermal Control System (EATCS) Ammonia Leak

Darnell T. Cowan, Timothy A. Bond
and Jordan L. Metcalf
NASA Lyndon B. Johnson Space
Center (JSC)

Presented By
Darnell Cowan




TFAWS
LaRC 2019

Thermal & Fluids Analysis Workshop
TFAWS 2019
August 26-30, 2019
NASA Langley Research Center
Hampton, VA




Purpose/Agenda




- **Purpose:** Discuss the ISS P1 EATCS ammonia leak investigation and current findings
- **Agenda:**
 - EATCS 101
 - Houston, We Have A Leak!
 - White Flakes
 - Locating Leaks
 - Root Cause Investigation and TT&E
 - Discussion
 - Conclusion
 - Summary

- EATCS - closed loop single phase system (two redundant loops)
- Mechanically pumps liquid ammonia to cool avionics, payloads and electronic equipment onboard the ISS
- Starboard (S1) and Port (P1) EATCS were launched in 2002, and activated in 2006




Note: RBVM= Radiator Beam Valve Module




P1 EATCS

S1 EATCS


- The Problem: P1 EATCS -detected a coolant inventory decay in 2012,leak began to accelerate
- Cause/Location: Unknown at the time




- In early 2016, began observing mysterious “white flakes”, on the P1 external high definition cameras as the leak rate approached 30 lbm/year (13.6 kg/year)
- Uncertain if related to ammonia leak, what else could they be?
- Leaks that produce visible particles or flakes typically thought to be > 50 lbm/day
- Flakes were sporadically seen moving across camera field of view seeming to come from a common location
- Lack of depth perception made it difficult to estimate possible originating locations



- Existing techniques to locate a leak was to isolate system into segments and monitor inventory decay
- Cons
 - Shutting down system, time, resources, low chance for success
- Remedy.....the Robotic External Leak Locator (RELL)
- New tool built to work with ISS Robotic Arm
- Remotely detect and ID various gases, and measure their pressures in a vacuum
- Launched in 2015
- Coincidentally, in time to help locate P1 EATCS leak





RELL Attached to the ISS Robotic Arm



RELL Unit

- Detect molecules up to 100 atomic mass units (amu)
- Measure pressures from standard atmosphere to $\sim E^{-12}$ torr
- Cold Cathode Ion Gauge measures total pressure
- Residual Gas Analyzer (mass spec) measures partial pressure of range of amu
- Pressure measurements are directional in space environment






- P1 EATCS Radiators circled in blue, Z1 (decommissioned) and a spare Pump Flow Control Subassembly (PFCS) circled in red, P1 EHDC circled in black, ATA behind structure (dotted purple)



2016 RELL Scans




- Demonstration Scans
 - ISS background (natural atmosphere, ISS vents and outgassing)
 - Pressures measured $\sim E-12$ to $E-8$ torr
- P1 EATCS leak and white flake scans
 - Z1, PFCS, ATA
 - No significant ammonia signature present ($\sim E-8$ to $E-7$ torr)
 - P1 EATCS Radiator Beam Valve Modules (RBVM)
 - **Significant ammonia signature pressure**

- P1 ISS EATCS Radiator Beam Valve Modules










- Noticed total pressure spike at P1-3-2 RBVM on order of $\sim 5E-5$ torr
- Low levels of ammonia around other RBVM $\sim 5E-7$ torr
- Partial pressure from RGA correlated with ammonia



**Scan
Direction** →





Highest Pressures @ P1-3-2 RBVM to the radiator jumper hoses, and the hard lines underneath





Pressures E-5 torr ~ 50 lbm/year (22.6 kg/year)




- Inspections of the RBVM jumpers hoses and system lines performed during an EVA in March 2017
- Nothing noteworthy observed from the crew
- Post EVA review, multiple white flakes seen from EVA GoPro video












- Following the EVA in May 2017, ground command remotely closed the RBVM to the P1-3 radiator; isolating that flow path
- Ammonia was vented to space, stopping the leak
- White flakes have not been observed since and subsequent mass plots show the leak stopped



Leak Stopped




- Most likely leak source - RBVM jumper hoses rather than the hard lines underneath them
- ISS Program agreed to remove the RBVM hoses and returned them to the ground for investigation
- Hoses removed during an EVA in March 2018, and return to the ground in May 2018



- 1" supply and 3/4th return hose
- Each hose contains two female Quick Disconnects (QD)
- Each QD contains multiple seals
- Some seals are not visible without significant QD disassembly





Female QD



Female Secondary Spool Seal (exposed portion of seal is not really visible)

Female Primary Spool Seal, behind which is the Female Primary Stop Plug Seal (seals are either uniform or not really visible)




Release Ring

Locking Collar


Detent Button

Bail

- Inspection shows the 1" supply hose looked good
- Barely failed Leakage requirement of 1 E-4 sccs of Helium at 500 psia (3447 kPa)
- Considered acceptable to be reused "as is", and returned to the ISS in April 2019





F141 QD secondary seal





F129 QD secondary seal


- The 3/4" return hose – not so good
- QD F140 failed the leakage requirement at $2.8E^{-3}$ sccs of Helium at 500psia (3447 kPa)
- QD F128 failed the leakage requirement at 1.91 sccs of Helium at 500 psia (3447 kPa)



- Forward half QD F128 failed the leakage requirement at $2.2E-1$ sccs of Helium at 500 psia (3447 kPa)
- Aft half failed at 0.5 sccs of Helium @ 500 psia (3447 kPa)
- QDs removed for additional TT&E
- New QDs installed, hose assembly launched to the ISS in April 2019





- Appears aft spool seals of QD F128 were responsible for the majority of the P1 EATCS leak
- Further analysis of the deposits and examination of surfaces is planned in the near future




**QD F128
Spool**


**QD F140
Spool**



**QD F128
Inner
Housing**



**QD F140
Inner
Housing**



- 200 QDs per EATCS, and 36 are the $\frac{3}{4}$ " hose
- All RBVM-to-radiator hoses exposed to similar thermal environments
- No other significant leaks observed to date
- GN2 filled radiator flow paths is slowly leaking ($5E-3$ sccs He) overboard
- All QD seals are made of the same material
- Seals leak worse while exposed to cold temperatures
- F128 QD, leaky QD, failed the leak test on the ground before launch but seals were replaced
- No leaks were detected for 4 years after activation
- EATCS were filled on-orbit, and the ammonia chemistry could not be evaluated

- The results of the QD F128 failure investigation should help address the following:
 - Unique or common failure
 - Male QD counterpart compromised?
 - Possible design changes
 - Sparing posture
 - On-orbit operation changes

- The ISS P1 EATCS had a slowly increasing ammonia leak, and white flakes were observed from the ISS video cameras
- RELL narrowed down the source of the leak to the P1-3-2 RBVM supply and return jumper hoses
- Hoses and radiator flow paths were isolated, and vented of ammonia; stopping the leak
- White flakes have not been observed since
- Hoses returned to the ground, refurbished and relaunched to ISS
- Leak source – aft seals in QD F128 (radiator end) on the $\frac{3}{4}$ " return hose
- Further evaluation in work