

# Accidents: Failures to Re-frame

Dr. Randy Mumaw

International Symposium on  
Pilot Training for Startle and Surprise Management

Soesterberg, Netherlands

September 26, 2019



**SAN JOSÉ STATE**  
UNIVERSITY

---

RESEARCH FOUNDATION

# Overview

Surprises; but Larger Theme is Understanding

---

- ❖ Accidents can occur when system operators fail to understand system or airplane state
  - . . . although misunderstandings also happen without accidents
- ❖ The design of the system interface, procedures, and training do not always support understanding
  - . . . in fact, they can make it harder
- ❖ There is a tension between design and the interests of the operators
  - . . . largely due to the evolution of system design
- ❖ I will offer several ideas for better supporting operator understanding

# Making Sense of a Complex World

Challenges: Complex systems and unfamiliar forces

---


What are common reasons for surprise?

- ❖ Knowledge: Inadequate understanding of systems
  - Singapore 006
  - Spanair 5022
- ❖ False perception: Spatial disorientation
  - Flash Air 604


Let's look at some missed opportunities to re-frame

# Singapore Airlines 006

Taipei, October 2000 / 747-400




**Surprise:** PVD did not activate  
**Response (Capt):** Not on yet er PVD huh never mind we can see the runway, not so bad. Ok, I am going to put it to high first.



# Spanair 5022


Madrid, August 2008 / MD-82



Full airplane sitting on the runway on a hot day in August.

**Surprise:** Ram Air Turbine probe heat is on and its temperature is increasing.


**Response (Capt):** Reset breaker several times; after 30 minutes saw that MEL said “the airplane could be dispatched with the probe heating inoperative as long as icing conditions were not forecast for the flight”; so, disconnect power to RAT probe and depart.



# Flash Air 604

Sharm el-Sheikh, January 2004

## Sub-threshold Roll



**Surprise 1 (with a Startle):** Due to force on the column, the autopilot does not engage in the expected mode; the FD roll bar is lost.

**Response (Capt):** A shocked exclamation; distraction.

**Surprise 2:** The distracted Captain continues to make roll inputs to the right, ending up at 20° right instead of 20° left.

**Response (Capt):**

FO: Turning right, sir

Captain: What?


FO: Aircraft turning right

Captain: Turning right? How turning right?

The airplane eventually rolled to about 110° to the right before substantial control inputs in the opposite direction were made, which was too late to avoid the crash into the Red Sea.

# SD in Commercial Aviation

SD is a Likely Contributor to a Significant Percentage of LOC Events



Blue = Likely somatogravic illusion  
Black = Other form of SD

# Autoflight Surprises (aka Mode Confusion)

16 Incidents and 26 Accidents

---

---

- ❖ The autopilot is off or failed, and the pilot thought it was engaged
  - Eastern L1011, near Miami, 1972; an inadvertent touch of the control column disengaged the A/P, and the airplane started a gradual, undetected descent into the ground
- ❖ The autopilot goes into an alternate control law and the autoflight behavior is changed
  - Air Asia A320, Indonesia, 2014; due to pilot actions, drop into Alternate Law mode. Unlike in normal operations, the airplane can stall in Alternate Law, and inappropriate pilot actions led to a stall.
- ❖ The autopilot takes actions that the pilot is not aware of
  - Aeroflot Nord 737, Perm, Russia, 2008; thrust levers were mis-calibrated but A/P was engaged and managing thrust. Pilot was unaware of A/P actions. When A/P was disengaged, pilot failed to handle thrust difference.
- ❖ The autopilot (or autothrottle) mode reverts to another mode
  - Flash Air 737, Sharm-el-Sheikh, Egypt, 2004; pilot engaged A/P but it engaged in control wheel steering (CWS-R) mode, and FD roll bar disappeared. Pilot exclaims from surprise by this reversion.
- ❖ The pilot does not understand the mode's behavior
  - Asiana 777, San Francisco, 2013; on approach, pilot selected FLCH mode for descent, and the airplane started climbing to the MCP altitude.
- ❖ The pilot failed to put the airplane into the correct mode or autoflight state
  - Air Inter A320, near Strasbourg France, 1992; on approach, the crew intended to program the autopilot for a 3.3-degree flight path, but inadvertently selected vertical speed mode (resulting in 3300 ft/min descent).



# Barriers to Understanding

(and some proposals to remove the barriers)

---

- ❖ System interface
  - single-sensor, single indicator
  - autoflight: hidden rules, states, targets, and more
- ❖ Operational procedures
  - no accommodation for knowledge-based performance
  - not oriented to operational decisions
- ❖ Operator training
  - equipment-oriented
  - a reluctance to dissect expertise (“airmanship”)



Single-sensor; single-indicator architecture

There is a burden on the operator to

- allocate attention appropriately
- add context
- understand system state
- identify developing problems




# Airplane Interface Started the Same Way



# The Airplane Interface has some Vestiges of SS-SI

## Engine Indications



The Regulations require all of these parameters

Important engine states must be inferred

- engine surge
- engine damage / severe engine damage
- significant degradation or vibration

There have been cases of confusion about which engine is affected

Centralized alerting



**ALERT SYS MESSAGE**

- Operating State (Engine Availability)
  - engine running
  - engine not running
  - failed
  - shut down
  - engine starting (and status)
- Non-Normal State
  - which engine is affected?
  - what is the required action?
    - reduce throttle
    - shut down engine
  - why? what condition is present?

Basic Thrust Parameter

TAT +13 C TO 1

1.340

1.340

1.290

1.290

EPR

Engine Indication

ENGINE

TAT +13 C TO 1

1.340

1.340

1.290

1.290

EPR

Deviation that caused the condition is revealed



**SURGE**

ENGINE

**ENG CAUTION L**

# Autoflight Interface

## Scattered Indicators and Hidden Rules

Will not pursue this altitude until button pressed

On climb in VNAV/LNAV, the airplane was leveled at FL150 for traffic. The airplane is now cleared to FL310. MCP is dialed up to 31000. However, when in VNAV ALT vertical mode, the pilot must push on the altitude knob to start climbing.

Target altitude

Will stay at this altitude

ASDF RTE 1 LEGS 1/4

186°	18NM
AARV	275 / FL180
172°	17NM
TIVV	.79 / FL250
198°	16NM
GIVU	.79 / FL270
270°	18NM
HUPP	.79 / FL310
< ERASE	

Target confusion

Multi-function buttons


Hidden VNAV behaviors

Early descent zone

# Procedure Use for a Cognitively Demanding Fault

## Solving the Problem

- ❖ Problem: Reactor coolant leak in an unusual place (distributed symptoms);  
Solution requires a transition between separate Emergency Operating Procedures (EOPs)
- ❖ Key EOP step: if Steam Generator (SG) pressure NOT stable or increasing return to step 1 [and, SG pressure is decreasing]
- ❖ Key to solving:
  - A focus on other inputs to SG pressure (use of schematics)
  - Understood that the point of the step was to determine if the SG was faulted
  - Awareness that they were stuck in a procedural loop



# The Struggle between Understanding and Following Procedures

Compliance >> Solving the Problem

---

- ❖ Nuclear power plant operators in a training exercise
  - They understand the limitations of the procedure
  - They understand that they are not addressing the problem

Malicious Procedural Compliance



# Explosion of Alert Messages

## Managing Non-Normals

### Qantas A380 Uncontained Engine Failure

- QF 32; Singapore to Sydney; 469 people on board
- 4 minutes after Take-off, engine no. 2 bursts, severely damaging other equipment
- 43 ECAM messages in first 60 seconds; many additional later (> 80 total)
- 50 minutes to sort through the non-normal checklists (NNCs)



“It was hard to work out a list of what had failed; it was getting to be too much to follow. So we inverted our logic: Instead of worrying about what failed, I said ‘Let’s look at what’s working.’” *A380 Captain*



# Qantas 32 (QF 32) Uncontained Engine Failure

2:01:08 ENG 2 TURBINE OVERHEAT		2:02:18 ENG 2 TURBINE OVERHEAT		
2:01:09 ENG 2 STALL	2:01:23 A-ICE WING VLV		ENG 2 OIL PRESSURE LOW	2:29:00ish FUEL L INR TK FWD+AFT PMPS FAULT
ENG 2 OIL TEMP HI	A-ICE ENG 1 VLV			FUEL R INR TK FWD+AFT PMPS FAULT
ENG 2 EGT OVER LIMIT	A-ICE ENG 2 VLV	2:02:41 ENG 2 FIRE	2:19:33 FUEL NORM+ALTN MODE FAULT	
	2:01:24 AIR L OUTR WIN			2:31:07 F/CTL ALTN LAW (PROT LOST)
2:01:13 F/CTL SLAT SYS 1+2 FAULT	AIR L INR WING I	2:03:00ish ENG 2 FAIL (flight crew st	2:21:50ish FUEL FEED TK2 MAIN+STBY PMPS FAULT	2:31:35 LOW OIL QUANTITY ENG 2
HYD G RSVR PRESS LO	AIR ENG 2 BLEED	2:03:30ish VENT COOLG SYS OVHT	FUEL NORM+ALTN XFR FAULT	2:31:46 FUEL FEED TK 2 MAIN+STBY PMPS FAULT
<b>HYD Y ENG 4 PMP A PRESS LO</b>	2:01:25 FUEL JETTISON V		FUEL JETTISON VLV NOT CLOSED	2:33:08 LOW OIL QUANTITY ENG 2
<b>HYD Y ENG 4 PMP B PRESS LO</b>	ENG 1 NORM+AI	2:06:29 ENG 2 SHUTDOWN		2:33:18 <b>A-ICE ENG VLV 1 OPEN</b>
L/G CTL 1 FAULT	ENG 2 NORM+AI	2:06:40 AUTO FLT A/THR OFF	2:21:56 F/CTL PART SPLRS FAULT	2:33:22 FUEL WINGS NOT BALANCED
AIR L OUTR WING LEAK	ENG 4 NORM+AI		2:22:06 ELEC AC BUS 2 FAULT	FUEL L INR TK FWD+AFT PMPS FAULT
AIR L INR WING LEAK		2:06:45ish F/CTL SLAT SYS 1+2 FAUL		FUEL R INR TK FWD+AFT PMPS FAULT
AIR ENG 2 BLEED LEAK	2:01:28 F/CTL AILERON A		2:22:30ish FUEL JETTISON VLV NOT CLOSED	
2:01:14 F/CTL PART SPLRS FAULT		2:07:19 HYD G RSVR LEVEL LO		2:34:18 LOW OIL QUANTITY ENG 2
F/CTL ALTN LAW (PROT LOST)			2:22:42 FUEL NORM+ALTN XFR FAULT	
L/G CTL 2 FAULT		2:07:40ish HYD G RSVR AIR PRESS LC		2:34:46 ELEC C/B TRIPPED
BRAKES A-SKID FAULT ON WING LG				2:35:01 F/CTL L OUTR AILERON FAULT
2:01:15 ELEC DRIVE 1 DISCONNECTED		2:11:30ish HYD G SYS PRESS LO		F/CTL R OUTR AILERON FAULT
F/CTL AILERON ACUATOR FAULT				F/CTL L MID AILERON FAULT
F/CTL AILERON ELEC ACTUATOR FAULT		2:12:45ish HYD Y ENG PMP A PRESS LO		F/CTL AILERON ACTUATOR FAULT
HYD G RSVR LEVEL LO		HYD Y ENG PMP B PRESS LO		
2:01:16 ELEC C/B TRIPPED				2:35:51 LOW OIL QUANTITY ENG 2
ELEC DRIVE 2 DISCONNECTED		2:16:20 ELEC AC BUS 2 FAULT		2:36:10 L/G CTL 2 FAULT
2:01:17 F/CTL L MID AILERON FAULT				2:36:26 COND FWD CARGO VENT FAULT
2:01:18 ELEC AC BUS 2 FAULT		2:16:29 FUEL JETTISON VLV NOT CLOSED		
ENG 2 NORM MODE FAULT				2:37:20 A-ICE WING VLV OPEN
		2:16:45 ENG 1 NORM+ALTN MODE FAULT		
		ENG 2 NORM+ALTN MODE FAULT		
		ENG 4 NORM+ALTN MODE FAULT		
		2:16:50ish LOW OIL QUANTITY ENG 2		
		2:18:43 AIR L INR WING LEAK		
		AIR L OUTR WING LEAK		
		AIR ENG 2 BLEED LEAK		


86 ECAM messages (over 36 minutes)

The crew later reported that they had begun to understand the effect of the engine failure on the aircraft and its systems. (after 1 hr 10 min)

# New Approach for Managing Non-normals

---

---



# What is a Capability?

---

---

## Airplane System Components

- Hydraulic system
- Thrust Reverser
- Battery
- Air conditioning pack

## Airplane Capabilities

- Range / Endurance
- Stopping Distance (on runway)
- Ability to perform a specific approach
- Ability to enter RVSM airspace
- Maneuver envelope

Airplane system  
components have failed




What can I do?  
Where can I go?

# Standard Approach to Systems Training

## Knobology

- ❖ Training on the interface to the flight deck interface is typically a tour of the physical features.
- ❖ Operational relevance is less of a focus


Fuel Control Panel




# A Reluctance to Treat “Airmanship” as Trainable



Situation: The airplane is held at cruise altitude past the Top of Descent point, and there is a waypoint altitude constraint that may be hard to make.

Example: Held in CRZ at FL310; using the BDEGA3 arrival (LEGGS transition) into SFO. The waypoint LOZIT has an ‘at or below’ restriction at 16000.

Situation Model	Expected Values & Decision Gates	Actions	Display Elements
<p><b><u>Nearing ToD; prior to new clearance</u></b>            Flight path is programmed in the FMS; A/P will descend aircraft on the arrival as programmed.            LOZIT to BDEGA leg is steep (known from experience)</p> 	<p>Should cross LOZIT below 16000 due to geometry of FMS flight path</p>	<p>Verbalize current plan and any inconsistencies            Monitor winds and update FMS            Identify difficult FPM segments            Identify traffic that might cause a late descent</p>	<p>NAV Display wind vector            FMS LEGS page            Nav display, Radio chatter</p>

At this point, the flight crew is expecting a normal descent on the FMS flight path. However, the flight crew is also looking ahead for potential threats to the plan, such as changes to the wind or traffic. Also, the flight crew has determined that one of the flight plan legs is pretty steep, and they know it can be flown more easily if they cross LOZIT well below 16,000 ft (rather than simply making the restriction at 16,000 ft).

<p><b><u>ATC requests delaying descent until notified</u></b>            Airplane will now go above FMS flight path; Eventual flown path will need to be steeper;            Use 3-to-1 to determine: What is latest position where I can still make LOZIT at 16000?</p> 	<p>Generate a GATE on current path at FL310 where it is too late to get down to LOZIT at 16000</p>	<p>Estimate how long you will be held high            CNTRL: slow down, as possible, to preserve options and decrease energy</p>	<p>Radio Traffic            NAV Display wind vector</p>
--	--	--	---



**Monitoring for Flight Path Management**

# Points to Take Away

---

---

- ❖ Operator surprises are not uncommon for jet transport pilots. System complexity and lack of transparency is a major contributor. For various reasons, re-framing can fail.
- ❖ Operators strive for system understanding; the interface, procedures, and training can create barriers to understanding. Designing to support understanding runs counter to early design ideas.
- ❖ The interface needs to integrate information to support operational decision making.
- ❖ Procedures need to find a way to remove limitations and support knowledge-based performance.
- ❖ Training also needs to be more operationally oriented and find a way to expose expertise.
- ❖ Operator communication is another significant method for supporting understanding.



*Thanks for your time!*



# Making Sense of a Complex World

Understanding relies on each individual's experience and knowledge

---

Seattle, home of Boeing, has many airplane-savvy people.



**LOOK!!  
It's a beaver !!**

????  
No, Jimmy, that's  
an airplane.

