STS-1 FORWARD RCS OXIDIZER TANK SUBSYSTEM FAILURE ASSESSMENT

K. Chauncey Wu NASA Langley Research Center Hampton, Virginia

John J. Zipay NASA Johnson Space Center Houston, Texas

2021 AIAA SciTech Forum and Expo 11-15 January 2021

STS-1 Forward RCS Oxidizer Tank Subsystem Failure Assessment

- Introduction
- Landing and post-flight inspection
- Launch and ignition overpressure (IOP)
- Orbiter reaction control system (RCS)
- Forward RCS (FRCS) module and oxidizer tank subsystem
- Loads, structural, and failure analyses
- Concluding remarks

The Crew, Young and Crippen




Landing at Edwards AFB - It Worked!



Orbiter Post-Flight Inspection


FLIGHT TEST PROBLEM REPORT NO. 58	_
Statement of problem: Forward RCS oxidizer tank aft Z strut found deformed.	1
Discussion: The forward RCS oxidizer aft Z strut failed in Euler buckling due to the lift-off dynamic response from the SRB overpressure. The forward and aft Z axis tank struts on both the fuel and the oxidizer tanks were replaced with struts reinforced by plies of boron/epoxy. The rod end diameter of the fuel tank struts was increased by 1/16 in. to be the same as the diameter of the ozidizer struts.	STS-1 Orbiter Final Mission Report, JSC-17378, Aug. 1981
The base heat shield left and right struts were reinforced and replaced. All other large mass support systems were reassessed for positive margins.	
	In-Flight Anomaly STS-1-V-58 (IFA Report V-58)
Required date for resolution: CLOSED 7/22/81 Comm Cohen Personnel assigned: E. W. Sandars/ES2 X-6156, R. J. Ward/WA3 X-4323	"Forward RCS oxidizer tank
Action progress: (blank)	- <i>aft Z strut found deformed.</i> "
Effect on subsequent missions: None	"The strut failed in Euler
Conclusions: Z axis accelerations exceeded design limits due to SRB overpressure which resulted in deformation of the forward RCS oxidizer tank aft Z strut.	 buckling due the lift-off dynamic response from the SRB overpressure."
Corrective action: Forward RCS struts were modified and replaced. Base heat shield left and right struts were reinforced and replaced. All large mass structures were analyzed and found to have positive margins of safety.	

Orbiter Reaction Control System (RCS)



(each 12@ 870 lbf thrusters; 2@ 24 lbf verniers)

April 12, 1981 - Liftoff!



LC-39A Perimeter Camera Views


April 12, 1981 - Liftoff! (2)




Fixed Service Structure Camera Views

Ignition Overpressure (IOP)


- At solid rocket booster (SRB) ignition, a strong transient IOP wave was generated
- SRB IOP environment was predicted pre-flight with analyses and scale-model testing
- Orbiter frequency response to IOP was greater than pre-flight predictions, exciting vehicle bending
- Peak Z (normal) accelerations of -2g to +3.5g were measured in Orbiter cockpit
- IOP caused other issues; aft heat shield and aerosurface acoustic loading at or near design limits




FRCS Module and Prop Tanks




FRCS Oxidizer Tank Subsystem



FRCS Oxidizer Tank Subsystem (2)



NTO Tank Subsystem Analysis Model




- Rigid tank and FRCS module structures
- Statically determinate => Solve equilibrium for individual strut forces P_i, i = A, ... F
- Calculate $P_F = -ma_Z/(2fz)$, $P_B = P_F fz$

IFA Report V-58

FLIGHT TEST PROBLEM REPORT NO. 58	
Statement of problem: Forward RCS oxidizer tank aft Z strut found deformed.	
Discussion: The forward RCS oxidizer aft Z strut failed in Euler buckling due to the lift-off dynamic response from the SRB overpressure. The forward and aft Z axis tank struts on both the fuel and the oxidizer tanks were replaced with struts reinforced by plies of boron/epoxy. The rod end diameter of the fuel tank struts was increased by 1/16 in. to be the same as the diameter of the ozidizer struts. The base heat shield left and right struts were reinforced and replaced. All other large mass support systems were reassessed for positive margins.	STS-1 Orbiter Final Mission Report, JSC-17378, Aug. 1981 In-Flight Anomaly STS-1-V-58 (IFA Report V-58)
Required date for resolution: CLOSED 7/22/81 Crown Lohan Personnel assigned: E. W. Sandars/ES2 X-6156, R. J. Ward/WA3 X-4323 Action progress: (blank)	"Forward RCS oxidizer tank aft Z strut found deformed."
Effect on subsequent missions: None	"The strut failed in Euler
Conclusions: Z axis accelerations exceeded design limits due to SRB overpressure which resulted in deformation of the forward RCS oxidizer tank aft Z strut.	buckling due the lift-off dynamic response from the SRB overpressure."
Corrective action: Forward RCS struts were modified and replaced. Base heat shield left and right struts were reinforced and replaced. All large mass structures were analyzed and found to have positive margins of safety.	

NTO Strut *F* **Structural Analysis**

- Simplified strut analysis model developed
 - Actual dimensions; D = 1.25 in., T = 0.026 in.
 - Strut A, I; modified for end fittings
 - No geometric imperfections, pinned ends
 - Ti-3Al-2.5V mat'l prop's; E, σ_{cv}



Strut Analysis Model

- Calculate Euler buckling load for slender strut
 P_{euler} = -4242 lbf
- Static a_z = +5.37 g required for buckling
- Euler buckling is elastic behavior
 => No lateral deflection for P < P_{euler}

IFA Report V-58 (2)

FLIGHT TEST PROBLEM REPORT NO. 58	
Statement of problem: Forward RCS oxidizer tank aft Z strut found deformed.]
Discussion: The forward RCS oxidizer aft Z strut failed in Euler buckling due to the lift-off dynamic response from the SRB overpressure. The forward and aft Z axis tank struts on both the fuel and the oxidizer tanks were replaced with struts reinforced by plies of boron/epoxy. The rod end diameter of the fuel tank struts was increased by 1/16 in. to be the same as the diameter of the ozidizer struts. The base heat shield left and right struts were reinforced and replaced. All other large mass support systems were reassessed for positive margins.	STS-1 Orbiter Final Mission Report, JSC-17378, Aug. 1981 In-Flight Anomaly STS-1-V-58 (IFA Report V-58)
Required date for resolution: CLOSED 7/22/81 Crann Lohan Personnel assigned: E. W. Sandars/ES2 X-6156, R. J. Ward/WA3 X-4323 Action progress: (blank)	"Forward RCS oxidizer tank aft Z strut found deformed."
Effect on subsequent missions: None Conclusions: Z axis accelerations exceeded design limits due to SRB overpressure which resulted in deformation of the forward RCS oxidizer tank aft Z strut.	"The strut failed in Euler buckling due the lift-off dynamic response from the
Corrective action: Forward RCS struts were modified and replaced. Base heat shield left and right struts were reinforced and replaced. All large mass structures were analyzed and found to have positive margins of safety.	SRB overpressure."

NTO Strut F Structural Analysis (2)

- Strut deformation noted post-flight
 => Material yield in deep postbuckling
- Calculate bending moment for first yield at mid-span, $M_{yield} = 2500$ lbf-in.
- Compute strain energies required for
 - Euler buckling, $U_{buck} = 133$ lbf-in.
 - Bending to yield, $U_{bend} = 141$ lbf-in.
- Estimate min. dynamic amplification factor $(U_{buck} + U_{bend})/U_{buck} = DAF = 2.06$
- Equivalent loading to buckle and yield Strut *F*

$$F_{equiv} = -1537 \text{ lbm x } 5.37 \text{ } g \text{ x } 2.06$$

= -17,002 lbf

FRCS Strut Failure Analyses

- For NTO tank Strut *B*, $P_{johns} = -10,947$ lbf
 - Calculate U_{johns} < U_{buck} + U_{bend} (for Strut F)
 => Possible NTO Strut B failure
- Calculate Strut *B* force under static a_z
 - $-P_B = -1537$ lbm x 5.37 g/2 = -4127 lbf
 - Estimate max. DAF = 2.65 (10,947 / 4127)
- Now consider failure of MMH tank Strut *F*
 - $P_F = -996$ lbm x 5.37 g/(2 fz) x 2.06
 - $= -5665 \text{ lbf} < P_{euler}$ (-4242 lbf)
 - => **Possible MMH Strut** *F* failure
- No corroborating evidence observed on these struts (still elastic)
- MMH tank Strut *B* failure discounted

FRCS Strut Failure Analyses

- For NTO tank Strut *B*, $P_{johns} = -10,947$ lbf
 - Calculate U_{johns} < U_{buck} + U_{bend} (for Strut F) => Possible NTO Strut B failure
- Calculate Strut B force
 - $-P_B = -1537$ lbms
 - Estimate
- Normank Strut *F* g/(2 fz) x 2.06 < P_{euler} (-4242 lbf) Sole MMH Strut *F* failure
- No corroborating evidence observed on these struts (still elastic)
- MMH tank Strut *B* failure discounted

Concluding Remarks

- Forward RCS NTO tank Strut F material failure noted in STS-1 post-flight inspection
- Analyses of Strut *F* failure performed for Euler buckling, followed by elastic bending, then material yielding
- Further analyses suggest possible elastic failures of NTO Strut *B* and MMH tank Strut *F*
- Mitigations on STS-2 and subsequent flights
 - Boron-epoxy strips bonded to all Struts *B* and *F* for added strength and stiffness
 - Root-cause IOP reduced with increased pad water suppression/injection

"We Just Became Infinitely Smarter"



Thank you! Questions?

CNG. CRIPPEN

USA