


Study of Spacecraft Deployables Failures

Alejandro Rivera
Deployables Analysis Engineer
NASA Goddard Space Flight Center

19th European Space Mechanisms and Tribology Symposium


September 24th, 2021



DISCLAIMER




The views and opinions expressed in this presentation are those of the author and do not necessarily reflect the official policy, procedures or position of NASA Goddard Space Flight Center or the National Aeronautics and Space Administration.




MOTIVATION




- Deployables failures still taking place at an average of 1 every two years
- Loss of mission goals and spacecraft performance
- Desire to understand what have historically been the most common modes of failure of deployables
- How can we prevent these from happening
- Share our findings with ESMATS Community



YEARLY ANOMALIES DISTRIBUTION






ANOMALIES BY TYPE




Deployables Anomalies by Type




- Solar Array anomalies most common (54%)
- High Gain Antenna (37%)
- Booms (18%)


* Based on published information. Actuals may differ.




MAIN ANOMALIES AND FAILURES CAUSES




* Based on published information. Actual root causes may differ.



INSURANCE CLAIMS



* Based on published information. Actuals may differ.




SEVERITY




- Vast majority of Spacecraft (68%) suffer some degree of mission and / or performance degradation
- 32% of anomalies results in partial loss of mission or substantial reduction of spacecraft performance

Deployables Anomalies by Severity



* Based on published information. Actuals may differ.



Thermal Blankets / Shields Interferences

New Dawn / Intelsat 28



Launch Date: April 22, 2011

Anomaly #1: Ku-band antenna fails to deploy


Cause: deployment mechanisms interference with sunshield

Resolution: motor-driven deployment mechanism moved up and down to free antenna from sunshield

Anomaly #2: unable to deploy its C-band reflector antenna


Cause: antenna's spring-loaded deployment mechanism got caught in the billows of its sunshield

Resolution: Shaking of the SC unsuccessful



Consequences: Mission Life reduced by 2 years

Insurance Claim: \$146M




Launch Date: October 10, 1984

Anomaly: One of the Solar Arrays failed to deploy

Cause: MoS₂ exposed to excessive humidity before launch resulting in excessive bearing friction in the space environment

Trouble shooting: exposure to sun until temperature above 0 °C





Launch Date: Nov 21, 1987

Anomaly: One of the Solar Arrays failed to deploy


Trouble shooting: Attempts to free it by spinning or shaking the satellite not successful.

Cause: Some of the hold down clips used to secure the SA panel during ground handling were not removed



Consequences: SC placed on a graveyard orbit. Total Mission Loss

Insurance Claim: \$51M





Launch Date: Feb 25, 1996

Anomaly: Reel-out mechanism jammed. Tether only released to about 256 m out of the planned 12.5 miles (20.1 Km)

Cause: Bolt added for structural margin to address a last minute concern, interfered with a traveling ball nut and thwarted satellite deployment.

Consequences: **Total Mission Loss**





SA Explosive Decompression Telstar14, 14R, Intelsat 19



Launch Dates: 2004, 2011, 2012


Anomaly: SA partially deployed (14, 14R) or failed to deploy (IS-19)

Cause: Inadvertent solar array pressurization and explosive decompression damaged the arrays' deployment mechanism



Consequences: all of them remained in service but with serious reductions in capacity

Insurance Claims: \$205M, \$132.7M, \$84M
(\$421.7M total)



Mechanisms Failure

Mars Global Surveyor



Launch Date: November 7, 1996


Anomaly: Solar Array fails to latch

Cause: input shaft of the damper sheared during SA deployment

Consequences: Aerobraking maneuvers had to be modified to put less pressure on solar panels.

New aerobraking schedule delayed reaching final polar science mapping orbit by 1 year.






Launch Date: June 2, 2003


Anomaly: MARSIS antenna booms' deployments delayed

Cause: Simulation refinements indicated potential risk that booms could back lash and damage SC

Trouble shooting: additional contingency simulations performed to assess risks; Mitigation scenarios defined.

Resolution: 1st boom failed to deploy until after exposure to sun; 2nd and 3rd deployed successfully.





Contingency Maneuvers

Anik E2



Launch Date: April 4, 1991

Anomaly: Ku-Band Antenna deployed after 2 days
C-Band Antenna did not fully deploy

Cause: Thermal blanket interference


Trouble shooting: long list of SC contingency maneuvers supported by remarkable ground team analysis and technical ingenuity

Resolution: C-band antenna deployed and mission saved





Consequences: Rescue maneuvers used a year's worth of fuel

Insurance Claim: \$208M



Prevention and Resolution Failures & Anomalies





FINAL THOUGHTS



- Spacecraft Deployables anomalies are a complex problem
- Sharing of information would be very beneficial
- Collaboration between space agencies
- Public disclosures by manufacturers that have experienced anomalies