

ISS Radiator Face Sheet Anomaly Investigation and Return to Function

Authors: Aaron Rodriguez (NASA JSC), Richard Morton(NASA JSC)

Presented by: Aaron Rodriguez (ISS ATCS Subsystem Manager)

55th International Conference on Environmental Systems

12-16 July 2026, Rio Grande, Puerto Rico

ICES-2026-281



EC6


Thermal Systems

Trade names and trademarks and company names are used in this presentation for identification only. Their usage does not constitute an official endorsement, either expressed or implied, by the National Aeronautics and Space Administration.



Purpose/Agenda


- **PURPOSE:** Document multi-year investigation, root cause, and rationale to return the radiator to service.
- **AGENDA:**
 - Overview of ISS EATCS
 - Radiator Panel Construction
 - Investigation
 - System Management and Monitoring
 - Use-As-Is Rationale
 - Flow Path Fill
 - Conclusion





Overview of ISS EATCS

- EATCS rejects heat collected from the ISS Modules to space using radiators.
- Two independent ammonia loops (A-Starboard, B-Port); six radiators total, each with eight panels and two isolated flow paths per radiator.
- Each Loop also contains a pump, accumulator, heat exchangers, a TRRJ for radiator positioning, and RBVM which allows flow paths to be isolate or vented to space.





Simplified Schematic of EATCS Radiator



Radiator Panel Construction


- Panel materials: aluminum face sheets + honeycomb core; 22 parallel Inconel flow tubes (11 per path) seated in aluminum extrusions; epoxy/foam bonding; Z93 coating.





Discovery and Investigation


- Face sheet peel was discovered in 2008 on the Starboard Radiator
- ISS Program decided to vent radiator to prevent additional failures during upcoming dynamic ops
- Cross-disciplinary team developed fault tree and eliminated thermal and external loads as well as material degradation.





Key Tests


- NDE testing on Qual Radiator- tap-test, x-ray, flash thermography
 - No Delamination
- He leak test on residual tube stock-passed leak test but had small manufacturing flaws in tube wall
 - Extracted tube from Qual radiator also passed leak tests
- Pressurized Panel Section
 - Honeycomb fails before face sheet delaminates







Possible Failure Scenario

- Leak may have developed from micro-flaw in flow tube which leaked into panel
 - Possible the freeze-thaw cycle exacerbated a flaw
- Radiator had a NH₃ and N₂ flow path – pressurization could have come from either
- Leak rate too small to be detected by NH₃ accumulator
- Only 40% of N₂ leaked needed to pressurize panel and cause failure







Triggering the Peel – Two possibilities


1. MMOD Strike

- Creates shock in gas pocket

2. Self-Propagating delamination

- Delamination grows, volume/pressure drops, leak adds gas, pressure rises again





LS-DYNA Correlation (Performed by NESCS)

- Dynamic FEA reproduced blow-out, crinkled face sheet, and tearing at the manifold fasteners

*flipped





ISS017E020145

ISS Radiator Analysis

Time = 0


(Marshall Neipert, NASA/ES, NESCS)






Risk Management and Monitoring (2009-2024)

- Decided to keep radiator deployed as analysis showed radiator would not break and retraction could cause more damage and create debris
- Software was updated to reduce NH₃ loss in the event of a large leak
- Perform periodic imagery of peeled face sheet and showed no change in 15 years
- Trending shows continued small leak in N₂ flow path and a small NH₃ leak INTO the vented flow path through the RBVM



Increasing Heat Rejection Demand

- Since 2010, heat loads have increased
 - Increased number of payloads and new efficiencies to increase utilization
- The loss of this flow path and another on the Port side due to a QD leak left little to no margin
 - Flight Controllers were forced to actively transfer loads from one loop to another or Autotrack the TRRJ
 - Loss of a single loop would force steep cuts to payloads and impact science operations





Use-as-is Rationale

- Radiator, by analysis and inspection, is structurally sound
- No large leak to space in the radiator as shown by a small pressure increase in the NH₃ flow path from the leaking RBVM
- Performance impact is minor as only 1 of the 8 panels was affected
- MMOD strikes to panel provide venting of other gas pockets
- Understanding the capability is useful for future planning- is this radiator a viable ORU




2025 Flow Path Refill

- ISS approved filling 1 flow path on each loop including the vented flow path on the damaged radiator to restore full redundancy
- Prior to fill, EATCS Loop was repressurized so that NH₃ remained liquid phase after the flow path was re-integrated
- Had to spin down the pump to avoid cavitation during filling but kept the controller energized to minimize risk of damaging controller during start up
- Fill was completed without anomalies and shown good performance since
 - Imagery shows no structural change and operational overhead has decreased



Lessons Learned and Conclusion

- Preventative options:
 1. Perform He leak checks at the tube stock level(~5 miles) to catch micro-leaks
 2. Use perforated honeycomb panels to prevent any pressurization in the panels
- EATCS robustness allowed Loop A to operate at 50% capability for 16 years while investigation took place
- Added flow paths allow for full redundancy of operations and reduces flight-ops burden



Acknowledgements and References

- NASA JSC PTCS, M&P, S&M, ISAG, Boeing ATCS, PTCS, M&P and S&M, NESC, Lockheed Martin.
- Cowan, D., and T. Bond, “Coolant Leak from ISS External Active Thermal Control System (EATCS) – An Examination of Most Probable,” (ICES 2022)