


CR-184026

TWR-17548
Vol VII



Flight Set 360L007 (STS-33R) Field Joint Protection System, Thermal Protection System, and Systems Tunnel Components Final Report—Volume VII

September 1990

Prepared for:

National Aeronautics and Space Administration
George C. Marshall Space Flight Center
Marshall Space Flight Center, Alabama 35812

Contract No. NAS8-30490
DR No. 3-5
WBS No. 4B601-03-08
ECS No. SS-1015

Thiokol CORPORATION
SPACE OPERATIONS

P.O. Box 707, Brigham City, UT 84302-0707 (801) 863-3511

Publications No. 91190

(NASA-CR-184026) FLIGHT SET 360L007
(STS-33R) FIELD JOINT PROTECTION SYSTEM,
THERMAL PROTECTION SYSTEM, AND SYSTEMS
TUNNEL COMPONENTS, VOLUME 7 Final Report
(Thiokol Corp.) 36 p

N91-10115

Unclass
0302730

CSCL 21H 63/20

Flight Set 360L007 (STS-33R)
Field Joint Protection System,
Thermal Protection System, and
Systems Tunnel Components
Final Report
Volume VII

Prepared by:

J.P. Williamson
Stage Hardware Design Engineer

Approved by:

Michael Williams
Supervisor
Stage Hardware Design

Robin Spencer
System Integration Engineer

Bruce Howard 9/13/90
SR&QA

Gary L. Stephens 9-12-90
Program Manager

Dolores Mice 9-13-90
Data Management
ECS SS-1015

R.M.D.

ABSTRACT

This report documents the performance of the thermal protection system, field joint protection system, and systems tunnel components of flight set 360L007 as evaluated by postflight hardware inspection.

The condition of both motors was similar to previous flights. Four aft edge strikes were noted on the ground environment instrumentation thermal protection system. The hits all left a clean substrate, indicating that the damage was caused by nozzle severance debris and/or water impact. No National Space Transportation System debris criteria for missing thermal protection system were violated.

Two problem reports were written against the field joint protection system. The first concerned two cracks in the K5NA closeout over the trunnion/vent valve location on the left-hand aft field joint. A similar condition was observed on Flight 5 (360H005B). The second problem report referred to a number of small surface cracks between two impact marks on the left-hand forward field joint. Neither area exhibited loose material or any abnormal heat effects, and they have no impact on flight safety.

CONTENTS

<u>Section</u>	<u>Page</u>
1 INTRODUCTION	1
2 OBJECTIVE	4
3 SUMMARY	5
4 CONCLUSIONS/RECOMMENDATIONS	6
5 DISCUSSION	7
5.1 PREFLIGHT HEATER CONTROL SYSTEM AND PERFORMANCE	7
5.2 POSTFLIGHT INSPECTION OF FJPS, TPS, SYSTEMS TUNNEL, AND IGNITER HEATER INSTALLATION	7
5.2.1 Field Joint Protection System	8
5.2.2 Thermal Protection System	11
5.2.3 Systems Tunnel	11
5.2.4 Igniter Heater and Forward Dome Power Cable Installation	11
6 REFERENCES	12

APPENDIXES

Appendix

A	LH Aft Field Joint Anomaly Documentation	A-1
B	LH Forward Field Joint Anomaly Documentation	B-1

FIGURES

<u>Figure</u>		<u>Page</u>
1	Field Joint Protection System	2
2	Igniter-to-Case Joint Heater Configuration	3
3	Impact Marks on FJPS Cork (LH forward field joint)	9
4	Splits in K5NA Ablation Compound (LH aft field joint)	10

ACRONYMS

deg	degree
FJPS	field joint protection system
ft	feet
GEI	ground environment instrumentation
hr	hour
in.	inch
IPR	interim problem report
JPS	joint protection system
KSC	Kennedy Space Center
L	launch
LCC	launch commit criteria
LH	left hand
NSTS	National Space Transportation System
PEEL	Postflight Engineering Evaluation Limit
RH	right hand
RSRM	redesigned solid rocket motor
SRB	solid rocket booster
STS	Space Transportation System
TPS	thermal protection system
V	volt
°F	degrees Fahrenheit

INTRODUCTION

STS-33R was launched from Kennedy Space Center (KSC) on 22 Nov 1989. Two redesigned solid rocket motors (RSRM) were used and were designated 360L007A and 360L007B. The three field joints on each motor (total of six field joints) were protected by the field joint protection system (FJPS) (Figure 1). The FJPS is used to keep the field joint O-rings above the minimum launch commit criteria (LCC) temperature during the launch countdown, to keep rain water from entering the field joint, and to protect the joint components from aerodynamic heating during flight. The igniter-to-case joint on each RSRM was fitted with an igniter heater to keep the igniter seals above minimum LCC temperature requirements during launch countdown (Figure 2).

The ground environment instrumentation (GEI) and heater power cables are protected by the thermal protection system (TPS). The purpose of the TPS is to protect the GEI and heater systems from aeroheating during flight.

After solid rocket booster (SRB) separation and splashdown, the SRBs were recovered and towed to KSC's Hangar AF for postflight inspection and disassembly. Retrieval and tow-back were delayed 24 hr by high sea states. The FJPS, TPS, systems tunnel, and igniter heater installation inspections were performed per Postflight Engineering and Evaluation Plan TWR-50050, Vol I (Reference 1).




Figure 1. Field Joint Protection System





Figure 2. Igniter-to-Case Joint Heater Configuration

OBJECTIVE

The objective of this report is to document any heater anomalies during the launch countdown and any anomalies to the FJPS, TPS, or systems tunnel components during flight and recovery operations. This report will also address all squawks or problem reports initiated during postflight evaluation.

3

SUMMARY

Postflight assessment results indicate that all TPS and systems tunnel components were in very good to excellent condition (compared to previous flights) with typical flight heat effects and erosion. No squawks or problem reports were written against the TPS or systems tunnel. There were a total of four aft edge hits: three on the left-hand (LH) motor and one on the right-hand (RH) motor, with the largest missing piece of TPS cork measuring 2.5 by 2.5 by 0.5 inches. The hits all left a clean substrate, indicating that the damage was caused by nozzle severance debris and/or water impact. No Postflight Engineering Evaluation Limit (PEEL) requirements or National Space Transportation System (NSTS) debris criteria for missing TPS were violated.

Two anomalies were observed on the LH aft and LH forward field joints and were documented as Problem Reports PV-6-146407 and PV-6-146109, respectively. The anomaly in the LH aft field joint consisted of two circumferential cracks in the K5NA closeout over the trunnion/vent valve location. The cracks were about 2 in. long and did not exhibit loose material or any abnormal heat effects. The LH forward field joint had two small impact marks on the forward edge and a series of small surface cracks in between. These also showed no abnormal heat effects.

CONCLUSIONS/ RECOMMENDATIONS

The joint protection system (JPS) heaters performed as expected and maintained the field joint temperatures within the LCC required range during launch countdown. Postflight inspection verified that the TPS, FJPS, and systems tunnel all performed as designed, with typical flight heat effects and erosion. The two anomalies reported on the FJPS did not exhibit loose material or any abnormal heat effects and had no impact on flight safety or schedule.

5

DISCUSSION

5.1 PREFLIGHT HEATER CONTROL SYSTEM AND PERFORMANCE

The field joint heaters and igniter-to-case joint heaters performed nominally during the launch countdown. The igniter heaters were activated between L - 24 hr and L - 6 hr 20 minutes, and maintained the joints within the LCC temperature limits of 90° to 108°F at all times. However, the temperature control band was changed from 95° ±5°F to 95° ±1°F, resulting in more frequent cycling and better heater control.

The field joint heaters were activated between L - 11 hr 20 minutes and L - 1 minute, and maintained an acceptable 17°F sensor temperature range from 90° to 107°F during the LCC timeframe. Prior to launch, an LCC contingency was created to lower the minimum redline temperature at any field joint from 85° to 69°F in the event of a complete heater failure. An interim problem report (IPR) was written against the LH aft field joint heater, which read 290 V instead of the nominal 209 V. This IPR was dispositioned when it was determined that the voltage must have been nominal since the current reading was nominal. In addition, the heater circuit breaker was not tripped, as it would have been had the voltage actually been 290 V.

5.2 POSTFLIGHT INSPECTION OF FJPS, TPS, SYSTEMS TUNNEL,
AND IGNITER HEATER INSTALLATION

The condition of both motors was similar to previous flight motors, with most of the heat effects occurring on the inboard side of the aft segments. These areas experience high aerodynamic heating normal to protuberance components. They also receive the high plume radiation and base recirculation heating induced by the adjacent SRB and space shuttle main engines on the aft-facing surfaces. There was slight charring of the TPS over the GEI cabling runs in this area, typical of previous flights.

5.2.1 Field Joint Protection System


The FJPS was in good condition overall. There were no signs of ablation on any of the JPS, with only slight paint blistering on the cork cover. The paint on the K5NA closeout aft of the cork was also slightly darkened and blistered, with occasional pitting. This condition was typical of previous flights and was probably due to aerodynamic heating and the result of nozzle severance debris and water impact.

Numerous small cracks were observed on the forward edge of the LH forward FJPS cork between 240 and 260 deg (Figure 3). Impact marks were noted on each side of the affected area approximately 3 ft apart. Problem Report PV-6-146407 was written against these cracks (Appendix A). The cracks measured approximately 0.50 in. axially by less than 0.10 in. radially and were within the current material acceptance requirements. The impact marks were most likely caused by a parachute float line. A limit was added to the PEEL stating that cracks in the FJPS that meet current acceptance criteria are acceptable and should not be reported.

Two circumferential cracks were found in the K5NA closeout over the trunnion/vent valve on the LH aft field joint at approximately 30 deg (Figure 4). The cracks were parallel (about 1.25 in. apart) and measured approximately 2.0 in. wide by less than 0.10 in. deep. The K5NA around the cracks was bulged out about 0.10 in. and could be depressed approximately 0.10 in. with hand pressure. Problem Report PV-6-146109 was written against these cracks (Appendix A). This condition was noted on a previous flight (360H005), and it was determined that a vacuum (due to vent valve operation) developed under the moisture seal during descent. This caused the moisture seal to be pulled down over the pin retainer band trunnion. The resulting stress in the K5NA induced a split. Since the condition occurred after SRB separation, there is no impact on flight safety and no corrective action was taken.


A 4- by 2-in. local blister was observed on the LH center field joint at 45 deg. There was peeling of the Hypalon paint in the area and cork was eroded from the surface approximately 0.05 to 0.10 in. deep. This damage was a first-time occurrence and was probably caused by burning debris from the nozzle severance system. No squawks or problem reports were written against this condition.

ORIGINAL PAGE
BLACK AND WHITE PHOTOGRAPH



**Figure 3. Impact Marks on FJPS Cork
(LH forward field joint)**

ORIGINAL PAGE
BLACK AND WHITE PHOTOGRAPH



**Figure 4. Splits in K5NA Ablation Compound
(LH aft field joint)**

5.2.2 Thermal Protection System

TPS performance was considered to be excellent during flight operation, with typical heat effects and no ablation. There were no in-flight anomalies, squawks, or problem reports written against the TPS.

There were a total of four aft edge hits: three on the LH forward center segment and one on the RH forward segment. The TPS cork pieces that were missing all left a clean substrate, indicating that the hits were caused by nozzle severance debris and/or water impact. The largest GEI cork piece missing was approximately 2.5 by 2.5 by 0.5 in., or 3.1 in.³. This piece was located at Station 691 on the RH forward segment at approximately 240 deg. No PEEL requirements or NSTS debris criteria for missing TPS were violated.

5.2.3 Systems Tunnel

The cork TPS adjacent to the systems tunnel floor plate was in excellent condition. There was very little paint blistering, and all K5NA closeouts over cables and tunnel seams were in excellent condition. No in-flight anomalies, squawks, or problem reports were written against the systems tunnel.

5.2.4 Igniter Heater and Forward Dome Power Cable Installation

Postflight inspection of the igniter heater installation and power cables revealed no anomalies. The igniter heater, cork, and band clamp were removed and inspected at Hangar AF; no anomalies were noted.

6

REFERENCES

1. TWR-50050 Vol I, Book I, Rev A, KSC Postflight Engineering Evaluation Plan (Internal and External Insulation), L. E. MacCauley and T. Morgan, 21 Nov 1989.
2. TWR-17432, KSC Ten-Day Postflight Hardware Evaluation Report for 360L007, L. E. MacCauley and T. Morgan, 18 Dec 1989.
3. TWR-17546 Vol I, Flight Motor Set 360L007 (STS-33R) Final Report, D. M. Garecht, 4 Jun 1990.

Appendix A
LH Aft Field Joint Anomaly Documentation

POSTFIRE OBSERVATION RECORD (PFOR) A-4
Field Joint External Insulation Condition

Motor No.: 360L007	Side: Left (A)	Date: 11/26/89
--------------------	----------------	----------------

Assessment Engineer(s): T. MORGAN, S. HICKEN

Joint: Aft (AFT)

Field Joint External Insulation Observations:	Yes	No	Comment #
A. Charred/Heat Affected Material (HTAFF)?	_____	✓ _____	_____
B. Missing TPS Material > 0.7 cu. In. Due To Ascent/Motor Operation (TPSVD)?	_____	✓ _____	_____
C. Missing TPS Material > 0.7 cu. In. Due To Reentry/Debrls/Water Impact (TPSDM)?	_____	✓ _____	_____
D. Unbonds/Cracks (DEBND)?	✓ _____	_____	1 _____
E. Evidence of Water Leakage From Field Joint (WATER)?	_____	✓ _____	_____
F. Missing/Unbonded Vent Valves (MISSG)? (FWD, CTR, and AFT joints only.)	_____	✓ _____	_____

Record the following if any of the above conditions exist:

Condition (Observation Code)	Starting Station Location (In.)	Ending Station Location (In.)	Starting Degree (deg.)	Ending Degree (deg.)	Circumferential Width (In.)	Axial Length (In.)	Radial Depth (In.)	Volume (In. ³)
DEBND	1491.5	N/A	~ 45	N/A	2 IN.	N/A	< .10	N/A

Notes / Comments


1. CRACKS IN KENA CLOSEOUT OVER TRUNNION

Clarification sheet(s) attached? _____ no _____ A-4B yes (Provide clarification number(s).)

Aft Segment TPS Clarification Form

Motor No.: 360L007	Side: <input checked="" type="checkbox"/> Left (A) <input type="checkbox"/> Right (B)	Date: 11/26/89
Assessment Engineer(s): T. MORGAN, S. HICKEN		

Sketch Aft Segment TPS Observations Below:



Clarification Number: A-4B

Corresponding Comment Number(s): 1

REVISION _____

SRB/SRM POSTFLIGHT HARDWARE ASSESSMENT SQUAWK SHEET

Page

| of |

2. DETECTED DURING OPEN ASSESSMENT		3. WORK AREA ON DOCK		4. SQUAWK ID NUMBER		4A. SIB SDE <input checked="" type="checkbox"/> LII <input type="checkbox"/> III	
5. WORK UNIT CODE INSULATION		6. PART NAME FIELD JOINT PROTECTION SYSTEM		7. PART NUMBER 1176803-01		8. SERIAL NUMBER	
11. PHA/PN FINAL		12. STS NUMBER 33		13. REPORTED BY (NAME/ORG) S. HICKEN / THIOKOL		14. DATE/TIME 26 NOV 87 / 12:00	
16. PHOTOGRAPH ID NUMBER 114472-1				16A. PHOTO ORGANIZATION <input type="checkbox"/> USPI <input checked="" type="checkbox"/> XMTI <input type="checkbox"/> OTHER			

16. ITEM	17. PROBLEM DESCRIPTION
	<p>The left-hand aft field joint transition location at 45° which was potted in with K5NA had two cracks. The cracks were parallel (0.25 inches apart) and extended 2 inches circumferentially. The cracks were opened approximately 0.1 inches. The material between the cracks could be depressed by moderate thumb pressure.</p>

18. ASSESSMENT TEAM CONCURRENCE

<u><i>Stere Hicken</i></u> CONTRACTOR ASSESSMENT ENGINEER	<u><i>Paul L. Gammey</i></u> MSFC ASSESSMENT ENGINEER
--------------------------------------------------------------	----------------------------------------------------------

19. EXECUTIVE BOARD DISPOSITION 20. P/N PRINTER

PR REQUIRED P/N NOT REQUIRED

21. EXECUTIVE BOARD REMARKS

22. APPROVALS

_____ CONTRACTOR BOARD MEMBER/DATE	_____ BOARD CHAIRMAN/DATE
---------------------------------------	------------------------------

POSTFIRE ANOMALY RECORD (PFAR)

1. PFAR NUMBER 360L007A-03	3. INSPECTION LOCATION KSC X T-24/T-97	4. REFERENCE SQUAWK NUMBER 33-030	5. REFERENCE PR NUMBER PV6-146109
2. SRM MOTOR NUMBER 360L007A	H-7 A-2	6. REFERENCE IFA NUMBER N/A	7. REFERENCE SPR NUMBER N/A
8. TITLE CRACK IN K5NA CLOSEOUT OVER FJPS TRUNNION			
9. CLASSIFICATION OBSERVATION X MINOR ANOMALY MAJOR ANOMALY CRITICAL ANOMALY			
10. PART NUMBER 1U76803-01	11. SERIAL NUMBER N/A	12. PART DESCRIPTION FIELD JOINT PROTECTION SYSTEM	
13. REPORTED BY (NAME / ORGANIZATION / OBSERVATION DATE) S. V. HICKEN / THERMAL INSULATION DESIGN ENGINEERING / 11/26/89			
14. RESPONSIBLE COMPONENT TEAM / PROGRAM MANAGER JPS / G. L. STEPHENS			
15. RESPONSIBLE PROJECT ENGINEER (NAME / ORGANIZATION) R. S. JENSEN / SYSTEMS INTEGRATION ENGINEERING			
16. RESPONSIBLE DESIGN ENGINEER (NAME / ORGANIZATION) C. L. PROKOP / STAGE HARDWARE DESIGN			
17. DESCRIPTION (ATTACH PFOR, FIGURES, PHOTOGRAPHS, ETC.) Two circumferential splits were found in the K5NA on the aft field joint at approximately 30 degrees measuring approximately 2.0 inches wide by 0.10 inch deep. The splits were about 1.25 inches apart. The K5NA around the splits was bulged out approximately 0.10 inch, was spongy, and could be depressed approximately 0.10 inch with hand pressure.			
18. JUSTIFICATION OF CLASSIFICATION (POSTFIRE ENGINEERING EVALUATION LIMITS) The K5NA split occurred during descent. This condition was noted on a previous flight (360H005) and has no impact on flight schedule or safety. No new corrective action will be implemented.			
19. CAUSE Vacuum under the moisture seal during descent caused the moisture seal to be pulled down over the pin retainer band trunnion. The resulting stress in the K5NA induced a split.			
20. RECOMMENDED CORRECTIVE ACTION None.		21. ANOMALY APPROVAL SIGNATURE RPRB SECRETARY: /S/S. T. MUNSON DATE: 12/13/89	
		22. OBSERVATION/ANOMALY APPROVAL SIGNATURES PE: /S/R. S. JENSEN DATE: 12/20/89 PM: /S/G. L. STEPHENS DATE: 01/05/90	
23. RESULTS OF RECOMMENDED CORRECTIVE ACTION N/A		24. REPORT RESULTS TO RPRB? YES NO X	
		25. RPRB CLOSURE SIGNATURE (REQUIRED ONLY IF BLOCK 24 CHECKED "YES") RPRB SECRETARY: N/A DATE: N/A	
		26. OBSERVATION/ANOMALY CLOSURE SIGNATURE PM: /S/G. L. STEPHENS DATE: 01/05/90	
27. ORIGINATION DATE 12/13/89	28. REQUIRED STATUS DATE 12/15/89	29. PR CLOSURE DATE	30. PFAR CLOSURE DATE 01/05/89

REV. 3/28/89

PR CLOSURE APPROVAL

Ref. P.F.A.R. Number: 360L007A-03

Engineering Approval

Signature

W. D. Handl

Date

2/6/90

Quality Assurance Approval

Signature

M. B. Johnson

Date

2/13/90

N.A.S.A. Resident O.A. Approval

Signature

J. G. Lewis

Date

2/13/90

N.A.S.A. R.M.O. Manager Approval

Signature

E. J. Szobiszewski

Date

2/13/90

N.A.S.A. S.R.M. Chief Engineer Approval

Signature

[Signature] FOR K. JONES

Date

2-20-90



2. DETECTED DURING <u>OPEN ASSESSMENT</u>		3. WORK AREA <u>HANGAR AF</u>		4. END ITEM CONTROL NUMBER <u>D-BI-034L-0008</u>	
5. WORK UNIT CODE		6. PART/PROG NAME <u>FIELD JOINT PROTECTION SYSTEM</u>		7. PART/PROG NO. <u>1476803-01</u>	
10. FSCM/VENDOR <u>07703</u>		11. NHA/PN/TAPE/DISC ID. <u>10100-001</u>		12. STS #/EFF. <u>000-B034L</u>	
		13. REPORTED BY (NAME/ORG) <u>S. HICKEN TH1</u>		14. DATE <u>11-26-89</u>	
		15. SOFTWARE PROBLEM LOCATOR DATE _____ TIME _____		8. SER./REV NO. <u>N/A</u>	
		9. QTY <u>1</u>		13. REPORTED BY (NAME/ORG) <u>8160</u>	

15. SOFTWARE PROBLEM LOCATOR
 DUMP TRANSLATOR OUTPUT LINE PRINTER OUTPUT COMPILER LISTING OTHER (SPECIFY)

16. ITEM <u>1.0</u>	17. PROBLEM DESCRIPTION <u>L/H AFT FIELD TRUNNION LOCATION AT 45° WHICH WAS POTTED IN WITH K5NA HAD TWO CRACKS. THE CRACKS WERE PARALLEL (1.25 INCHES APART) AND EXTENDED (2) INCHES CIRCUMFERENTIALLY. THE CRACKS WERE OPENED APPX. 0.1 INCH. THE MATERIAL BETWEEN THE CRACKS COULD BE DEPRESSED BY MODERATE THUMB PRESSURE.</u>	18. VALIDATION <u>Richard R. Huggins per telegram D. Johnson TH1 GHS</u>	11-28-89
		<u>REF. SQUAWK 33030</u>	

18. CRIT. SKILLS <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO ITEMS:	19. ENG. CHANGE REQ. <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO ITEMS:	20. CONSTRAINTS TO: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	21. CRIT <u>3/3</u>	22. RESP ORG. <u>LSOC</u>
23. WEIGHT REQ <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO ITEMS:	24. RETEST REQ <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO ITEMS:	25. HAZARDOUS OP <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO ITEMS:	26. MR REQ <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO ITEMS:	27. TIME/CYCLE <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO ITEMS:
28. FRACTURE CRIT <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO ITEMS:				

29. ITEM	30. DISPOSITION/CAUSE/CORRECTIVE ACTION <u>SEE PG 2 FOR DISPO</u>	31. TECH <u>3/3</u>	CONTR QA	GOVT QA
		<u>Part 1641 LSOC 1740 11-29-89</u>		
32. SYSTEM RESTORED (SIGNATURE)		33. FINAL ACCEP DATE <u>NOV 29 89</u>		

34. DATA CODE <u>B1081P</u>		35. REPL. S/N		36. RELATED REPORTS	
37. RC ACTION REQ <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO ITEMS:		38. RC CONSTRAINT (SIGNATURE DATE) TO:		39. RC CLOSURE (SIGNATURE) (DATE)	

PRESS FIRMLY - ALL COPIES MUST BE LEGIBLE



NONCONFORMANCE SYSTEM
(CONTINUATION SHEET)

PR 246-146109
 DR
 CAAR

1 OF

2. DETECTED DURING
3. RESERVED
4. END ITEM CONTROL NO.
D-BI-0342-0008

5. ITEM
6. TECH
7. CONTR QA
8. GOVT QA

1.1 TRANSFER THIS PR TO THOROL CORP.
RECORD TRACKING NUMBER.

SPC 247
NOV 29 89

TRACKING NUMBER: 3601007A-03
ACCEPTED BY: *[Signature]* 11/29/89

SUMMARY CLOSURE

PR WAS TRANSFERED TO
THOROL CORP

1.2 CLOSE THIS PR

SPC 247
NOV 29 89

LSOC SE: *[Signature]* 11/29/89

NASA SE: *[Signature]* 11/29/89

THI LSS: *[Signature]* 11/29/89

SPC OE: *[Signature]* 11/29/89

OE 155 SPC

9. CLOSURE
NOV 29 89
SPC 247

PRESS FIRMLY - ALL COPIES MUST BE LEGIBLE

Appendix B
LH Forward Field Joint Anomaly Documentation

POSTFIRE OBSERVATION RECORD (PFOR) A-4
Field Joint External Insulation Condition

Motor No.: 360L007	Side: Left (A)	Date: 11/26/89
Assessment Engineer(s): T. MORGAN, S. HICKEN		
Joint: Forward (FWD)		

Field Joint External Insulation Observations:	Yes	No	Comment #
A. Charred/Heat Affected Material (HTAFF)?	_____	_____✓_____	_____
B. Missing TPS Material > 0.7 cu. in. Due To Ascent/Motor Operation (TPSVD)?	_____	_____✓_____	_____
C. Missing TPS Material > 0.7 cu. in. Due To Reentry/Debris/Water Impact (TPSDM)?	_____	_____✓_____	_____
D. Unbonds/Cracks (DEBND)?	_____✓_____	_____	_____1_____
E. Evidence of Water Leakage From Field Joint (WATER)?	_____	_____✓_____	_____
F. Missing/Unbonded Vent Valves (MISSG)? (FWD, CTR, and AFT Joints only.)	_____	_____	_____

Record the following if any of the above conditions exist:

Condition (Observation Code)	Starting Station Location (In.)	Ending Station Location (In.)	Starting Degree (deg.)	Ending Degree (deg.)	Circumferential Width (In.)	Axial Length (In.)	Radial Depth (In.)	Volume (In. ³)
DEBND	N/A	N/A	240	260	~ 3 FT.	~ .50 IN.	< .10	N/A

Notes / Comments


1. NUMEROUS SMALL CRACKS ON FWD EDGE OF JPS CORK.
TWO IMPACT MARKS (POSSIBLE PARACHUTE FLAT LINE) ON EACH SIDE OF AFFECTED AREA

Clarification sheet(s) attached? _____ no _____ A-4A yes (Provide clarification number(s).)

Forward Segment TPS Clarification Form

Motor No.: 360L007	Side: <input checked="" type="checkbox"/> Left (A) <input type="checkbox"/> Right (B)	Date: 11/26/89
Assessment Engineer(s): T. MORGAN, S. HICKEL		

Sketch Forward Segment TPS Observations Below:



Clarification Number: A-4A

Corresponding Comment Number(s): 1

REVISION _____

DOC NO. TWR-17546 VOL VII
SEC PAGE

SRB/SRM POSTFLIGHT HARDWARE ASSESSMENT SQUAWK SHEET



Page

1 of 1

2. DETECTED DURING OPEN ASSESSMENT		3. WORK AREA ON DOCK		4. SQUAWK ID NUMBER	4A. SFB SIZE <input checked="" type="checkbox"/> LII <input type="checkbox"/> III
5. WORK UNIT CODE INSULATION	6. PART NAME FIELD JOINT PROTECTION SYSTEM		7. PART NUMBER 1076 803-01	8. SERIAL NUMBER	9. QUANTITY 1
11. PHA/PH FINAL	12. SFS NUMBER 33	13. REPORTED BY (NAME/ORG) S. HICKEN / THICKOL		14. DATE/TIME 26 NOV 89 / 12:00	
16. PHOTOGRAPH ID NUMBER 114470-5			16A. PHOTO ORGANIZATION <input type="checkbox"/> USBI <input checked="" type="checkbox"/> AMTI <input type="checkbox"/> OTHER		

16. ITEM	17. PROBLEM DESCRIPTION <p>The left hand forward field joint forward edge from 240° to 260° exhibited two possible impact marks approximately 3 feet apart. Numerous small surface cracks were on the forward facing edge between the marks.</p>
----------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

18. ASSESSMENT TEAM CONFERENCE

 _____ CONTRACTOR ASSESSMENT ENGINEER	 _____ MSFC ASSESSMENT ENGINEER
--------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------

19. EXECUTIVE BOARD DISPOSITION
 PR REQUIRED PR NOT REQUIRED

20. PR NUMBER

21. EXECUTIVE BOARD REMARKS

22. APPROVALS

_____ CONTRACTOR BOARD MEMBER/DATE	_____ BOARD CHAIRMAN/DATE
---------------------------------------	------------------------------

POSTFIRE ANOMALY RECORD (PFAR)

1. PFAR NUMBER 360L007A-05	3. INSPECTION LOCATION KSC X T-24/T-97	4. REFERENCE SQUAWK NUMBER 33-031	5. REFERENCE PR NUMBER PV6-146407
2. COMPONENT PROGRAM TEAM JPS	H-7 A-2	6. REFERENCE IFA NUMBER N/A	7. REFERENCE SPR NUMBER N/A
8. TITLE IMPACT MARKS/SURFACE CRACKS ON FORWARD FIELD JOINT FJPS			
9. CLASSIFICATION OBSERVATION MINOR ANOMALY X MAJOR ANOMALY CRITICAL ANOMALY			
10. JUSTIFICATION OF CLASSIFICATION This is a first-time occurrence but this condition imposes no impact on flight safety or schedule.			
11. PART NUMBER 1U76803-01	12. SERIAL NUMBER N/A	13. PART DESCRIPTION FIELD JOINT PROTECTION SYSTEM	
14. REPORTED BY (NAME / ORGANIZATION / OBSERVATION DATE) S. V. HICKEN / THERMAL INSULATION DESIGN ENGINEERING / 11/26/89			
15. RESPONSIBLE PROGRAM MANAGER (NAME / ORGANIZATION) G. L. STEPHENS / JPS PROGRAM MANAGEMENT		16. RESPONSIBLE POSTFIRE ENGINEER (NAME / ORGANIZATION) G. S. NIELSON / POSTFIRE HARDWARE ENGINEERING	
17. RESPONSIBLE INTEGRATION ENGINEER (NAME / ORGANIZATION) R. S. JENSEN / SYSTEMS INTEGRATION ENGINEERING		18. RESPONSIBLE ACTIONEE (NAME / ORGANIZATION) C. L. PROKOP / STAGE HARDWARE DESIGN	
19. DESCRIPTION (ATTACH PFORS, FIGURES, PHOTOGRAPHS, ETC.) Numerous small cracks were observed on the forward edge of the forward field joint FJPS cork from 240 to 260 degrees. Impact marks were noted on each side of the affected area approximately 3 feet apart. The cracks measured approximately 0.50 inch axially by less than 0.10 inch radially.			
20. HISTORY None. This is the first time that cracks of this type have been reported.			
21. CAUSE Cracks of this size meet the current material acceptance requirements. The impact marks were most likely caused by a parachute float line.			
22. CORRECTIVE ACTION Add a limit to the PEEL stating that cracks in the FJPS that meet current acceptance criteria are acceptable and should not be reported.			
23. RESULTS TWR-50050, Vol. I, Rev. C will state "Cracked cork or K5NA with no missing material - Acceptable".			
24. REPORT RESULTS TO RPRB? YES NO X	26. APPROVAL THROUGH CORRECTIVE ACTION RPRB SECRETARY: /S/S. T. MUNSON SIE: /S/R. S. JENSEN PM: /S/G. L. STEPHENS		27. CLOSURE RPRB SECRETARY: N/A DATE: N/A DATE: 10 July 90
25. RPRB MEETING DATES ORIGINATION: 12/13/89 CLOSURE: N/A			DATE: 01/05/90

PR CLOSURE APPROVAL

Ref. P.F.A.R. Number: 360L007A-05

Engineering Approval

Signature

W. A. Hart

Date

2/6/90

Quality Assurance Approval

Signature

AB Johnson

Date

2/13/90

N.A.S.A. Resident Q.A. Approval

Signature

J. G. Lewis

Date

2/13/90

N.A.S.A. R.M.O. Manager Approval

Signature

E. J. Sobiszewski

Date

2/13/90

N.A.S.A. S.R.M. Chief Engineer Approval

Signature

Ross for K. Jones

Date

2-20-90



1. REPORT NUMBER

INTERIM PROBLEM REPORT

PROBLEM REPORT *PV 6 146407*

DISCREPANCY REPORT

PAGE _____ OF _____

2. DETECTED DURING: *OPEN ASSESSMENT*

3. WORK AREA: *HANGAR A.F*

4. END ITEM CONTROL NUMBER: *D-B1034L-0011*

5. WORK UNIT CODE: _____

6. PART/PRDG NAME: *FIELD JOINT PROTECTION SYSTEM*

7. PART/PRDG NO.: *1476803-01*

8. SER./REV NO.: *N/A*

9. QTY: *1*

10. FSCM/VENDOR: *07703*

11. NHA/PN/TAPE/DISC ID.: *10100-001*

12. STS #/EFF.: *000B034L*

13. REPORTED BY (NAME/ORG): *S. HICKEN TH1 3-5838*

14. DATE: *11-26-89*

15. SOFTWARE PROBLEM LOCATOR

DUMP TRANSLATOR OUTPUT LINE PRINTER OUTPUT COMPILER LISTING OTHER (SPECIFY) _____

16. ITEM: *1.0*

17. PROBLEM DESCRIPTION: *L/H FWD FIELD JOINT FORWARD EDGE FROM 240° to 260° EXHIBITED TWO POSSIBLE EMPACT MARKS APPX. 3 FEET APART. NUMEROUS SMALL SURFACE CRACKS WERE ON THE FORWARD FACING EDGE BETWEEN THE MARKS.*

17A. VALIDATION: *Richard K. [unclear] per telecon. D. [unclear] TH1 DA Spc 11-20-89*

REF SQUAWK 33-031

18. CRIT. SKILLS: YES NO

19. ENG. CHANGE REQ.: YES NO

20. CONSTRAINTS: YES NO

21. CRIT: *3/3*

22. RESP ORG.: *LSOC*

23. WEIGHT RECD: YES NO

24. RETEST RECD: YES NO

25. HAZARDOUS OP: YES NO

26. MR RECD: YES NO

27. TIME/CYCLE: YES NO

28. FRACTURE CRIT: YES NO

29. ITEM: _____

30. DISPOSITION/CAUSE/CORRECTIVE ACTION: *SEE PG 2 FOR DISPO*

31. TECH: _____

CONTR OA: _____

GOVT OA: _____

32. SYSTEM RESTORED (SIGNATURE): _____ DATE: _____

33. FINAL ACCEP DATE: _____

34. DATA CODE: *B1081P*

35. REPL. S/N: _____

36. RELATED REPORTS: _____

37. RC ACTION REQ: YES NO

38. RC CONSTRAINT (SIGNATURE DATE) TO: _____

39. RC CLOSURE (SIGNATURE) (DATE): _____

PRESS FIRMLY - ALL COPIES MUST BE LEGIBLE



NONCONFORMANCE SYSTEM
(CONTINUATION SHEET)

1. REPORT NUMBER
 IPR
 PR PV6-196407
 DR
 CAAR

PAGE
2
OF

2. DETECTED DURING
3. RESERVED
4. END ITEM CONTROL NO. D-010346-0011

5. ITEM
6. TECH
7. CONTR QA
8. GOVT QA

1.1 TRANSFER THIS PR TO TH1 CORP.

TRACKING NO 5606007A-05

ACCEPTED BY: [Signature] ^{12/1/89}
TC-655-95

SUMMARY CLOSURE

PR WAS TRANSFERRED TO TH1/KOL CORP

1.2 CLOSE THIS PR

USOC SE: [Signature] ^{12/1/89}

NASA SE: [Signature] ¹¹⁻³⁰⁻⁸⁹ MUELLER.

TH1 USS: [Signature] ^{12/1/89}
SPL DE:

9. CLOSURE

PRESS FIRMLY - ALL COPIES MUST BE LEGIBLE

DISTRIBUTION

<u>Recipient</u>	<u>No. of Copies</u>	<u>Mail Stop</u>
G. Stephens	1	E66
R. Jensen	1	L72
R. Wilks	1	L62
M. Williams	1	L62B
J. Wilkinson	1	L62B
D. Garecht	1	L71
T. Morgan	1	L52
E. Bailey	1	694
R. Mikesell	1	811
E. Rodgers	1	851
P. Greenhalgh	1	851
Print Crib	5	K23B1
Stage Hardware File	1	L62B
Data Management	1	L74B
R. Papasian	15	E05

