


TWR-64204



Final Postflight Hardware Evaluation Report 360T026 (RSRM-26, STS-47)

Includes Sections 1-6

May 1993

Prepared for:

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION
GEORGE C. MARSHALL SPACE FLIGHT CENTER
MARSHALL SPACE FLIGHT CENTER, ALABAMA 35812

Contract No. NAS8-38100
DR No. 4-23
WBS No. 4C601-04-01
ECS No. SS4769

Thiokol CORPORATION
SPACE OPERATIONS

P.O. Box 707, Brigham City, Utah 84302-0707 (801) 863-3511

(NASA-CR-192559) POSTFLIGHT
HARDWARE EVALUATION 360T026
(RSRM-26, STS-47) Final Report
(Thiokol Corp.) 279 p

N94-17656

Unclas

G3/16 0171913



**Final Postflight
Hardware Evaluation Report
360T026 (RSRM-26, STS-47)**

April 1993

Prepared by:

Jay Nelson
Postfire Hardware Evaluation

Approved by:

Jay Nelson
Project Engineer,
Postfire Hardware Evaluation


[Signature]
Supervisor,
Postfire Hardware Evaluation

[Signature]
Program Manager,
Flight Motor Support


[Signature] 5-5-93
Release



Concurrence by:




Case Design




Joints & Seals Design



Integration Design



Nozzle Design




Igniter / Instrumentation /
Electrical Design



Thermal Insulation Design



Quality, Performance Evaluation



Systems Assurance



Table of Contents

<u>Section</u>	<u>Description</u>	<u>Page</u>
1.0	INTRODUCTION	1
2.0	REFERENCES	2
3.0	EVALUATION SUMMARY	3
3.1	CEI Specification Compliance	3
4.0	COMPONENT EVALUATIONS	5
4.1	Insulation	5
4.1.1	Thermal Performance Evaluation	5
4.1.2	Internal Insulation Samples	5
4.1.3	Liner	8
4.1.4	Igniter Nozzle Insert	8
4.1.5	Results of Special Issues and Concerns (Insulation)	8
4.2	Case, Seals, and Joints	9
4.2.1	S&As	9
4.2.2	Factory Joints	9
4.2.3	Internal Nozzle Joints	9
4.2.4	Port Plugs and Plug Seals	9
4.2.5	Results of Special Issues and Concerns	11
	(Case, Seals, and Joints)	
4.3	Nozzle	11
4.3.1	Nose Inlet/Forward End Ring/Cowl (Joint 2)	13
4.3.2	Nose Inlet/Throat (Joint 3)	14
4.3.3	Throat/Forward Exit Cone (Joint 4)	15
4.3.4	Flex Bearing/Fixed Housing (Joint 5)	16
4.3.5	Aft Exit Cone Assembly Bondlines	17
4.3.6	Forward Exit Cone Assembly Bondlines	18
4.3.7	Throat Assembly Bondlines	18

Table of Contents (Cont.)

<u>Section</u>	<u>Description</u>	<u>Page</u>
4.3.8	Nose Inlet Rings Bondlines	19
4.3.9	Nose Cap Bondlines	19
4.3.10	Cowl Bondlines	19
4.3.11	Fixed Housing Assembly Bondlines	20
4.3.12	Ultrasonic Inspection of Fixed Housing Assemblies	21
4.3.13	Char and Erosion Performance	21
4.3.14	Flex Boot Performance	21
4.3.15	Bearing Protector Performance	22
4.3.16	Cowl Insulation Segments	23
4.3.17	Flex Bearing Performance	23
4.3.18	Throat Diameter	24
4.3.19	Results of Special Issues and Concerns (Nozzle)	24

List of Figures

<u>Figure</u>	<u>Description</u>	<u>Page</u>
1	Case Configuration	1
2	Safe and Arm Device Configuration	10
3	Internal Nozzle Joint Configuration	12

List of Tables

<u>Table</u>	<u>Description</u>	<u>Page</u>
1	Summary of 360T026 Problems	3
2	Problem Summary for 360T026	4
3	Summary of 360T026 Nozzle-to-Case Joint and Field Joint Insulation Safety Factors	6
4	Summary of 360T026 Factory Joint Insulation Safety Factors	6
5	Summary of 360T026 Case Acreage Insulation Safety Factors	7
6	Summary of 360T026 Igniter Insulation Safety Factors	7
7	Summary of 360T026 Igniter Insulation at Station 5	8
8	360T026 Nozzle Char and Erosion Minimum Margins of Safety ..	22
9	360T026 Flex Boot Margins of Safety	23

List of Appendices

<u>Appendix</u>	<u>Description</u>	
A	Insulation PFORs	A-1
B	Case, Seals and Joints PFORs	B-1
C	Nozzle PFORs	C-1
D	Nozzle Postfire Data	D-1
E	Insulation Postfire Safety Factor Data	E-1



List of Acronyms

<u>Acronym</u>	<u>Definition</u>
CCP	Carbon Cloth Phenolic
CEI	Contract End Item
CPT	Component Program Team
ET	External Tank
GCP	Glass Cloth Phenolic
ID	Inside Diameter
IFA	In-Flight Anomaly
KSC	Kennedy Space Center
LDI	Low Density Indication
LH	Left Hand
NASA	National Aeronautics and Space Administration
OD	Outside Diameter
PEEP	Postflight Engineering Evaluation Plan
PFAR	Postfire Anomaly Record
PFOR	Postfire Observation Record
RH	Right Hand
RSRM	Redesigned Solid Rocket Motor
RTV	Room Temperature Vulcanized (Rubber)
S&A	Safe and Arm Device
SCP	Silica Cloth Phenolic
SII	SRM Ignition Initiator
STS	Space Transportation System
TWR	Thiokol Wasatch Report



1.0 INTRODUCTION

This document is the final report for the Clearfield disassembly evaluation and a continuation of the KSC postflight assessment for the 360T026 (STS-47) RSRM flight set. All observed hardware conditions were documented on PFORs and are included in Appendices A, B, and C. Appendices D and E contain the measurements and safety factor data for the nozzle and insulation components. This report, along with the KSC Ten-Day Postflight Hardware Evaluation Report (TWR-64203), represents a summary of the 360T026 hardware evaluation. The as-flown hardware configuration is documented in TWR-60472. Disassembly evaluation photograph numbers are logged in TWA-1987.

The 360T026 flight set disassembly evaluations described in this document were performed at the RSRM Refurbishment Facility in Clearfield, Utah. The final factory joint demate occurred on 12 April 1993.

Detailed evaluations were performed in accordance with the Clearfield PEEP, TWR-50051, Revision A. All observations were compared against limits that are also defined in the PEEP. These limits outline the criteria for categorizing the observations as acceptable, reportable, or critical. Hardware conditions that were unexpected and/or determined to be reportable or critical were evaluated by the applicable CPT and tracked through the PFAR system.

Figure 1 shows the RSRM Case Configuration.




Figure 1. Case Configuration

2.0 REFERENCES

The following documents are referenced herein:

- CPW1-3600A Prime Equipment End Item Detail Specification, Part I of Two Parts; Performance, Design, and Verification Requirements, Space Shuttle Redesigned Solid Rocket Motor CPW1-3600 For Space Shuttle Solid Rocket Motor Project, Operational Flight Motors (RSRM-4 and subsequent)
- TWA-1987 360T026, STS-47, Clearfield Postflight Photo Log
- TWR-50050 KSC Postflight Engineering Evaluation Plan (PEEP)
- TWR-50051 Clearfield Postflight Engineering Evaluation Plan (PEEP)
- TWR-60472 STS-47, 360T026, KSC Processing Configuration and Data Report
- TWR-64201 Postflight Hardware Special Issues, 360T026 (STS-47), Clearfield
- TWR-64203 KSC Ten-Day Postflight Hardware Evaluation Report, 360T026 (STS-47)
- TWR-60205 RSRM Hardware Assessment at KSC (Presentation of 360T026 PFARs to RPRB)

3.0 EVALUATION SUMMARY

Table 1 provides a summary of all postflight-related Squawks/Preliminary PFARs, PFARs, IFAs, and SPRs for 360T026.

	<u>Squawks/Prelim. PFARs</u>	<u>PFARs</u>	<u>IFAs</u>	<u>SPRs</u>
KSC	26	16	0	0
Clearfield	<u>20</u>	<u>8</u>	<u>0</u>	<u>1</u>
Total	46	24	0	1

A list of all 360T026 PFARs is included in Table 2. This includes Squawks (written at KSC) and Preliminary PFARs (written at Clearfield) that were written and not elevated to PFARs. Information relating to postflight Squawks can be found in TWR-64203.

3.1 CEI Specification Compliance

Based on hardware evaluations at KSC and Clearfield, as defined in the respective PEEPs (TWR-50050, Revision C and TWR-50051, Revision A), all CEI (CPW1-3600A) motor performance requirements were met.

Table 2. Problem Summary for 360T026

REF. NO.	PRELIM. PFAR NUMBER	TYPE	ELEVATED FROM	REFERENCE SPR NUMBER	REFERENCE IFA NUMBER	EVALUATION LOCATION	CURRY UNIT TEAM	HM/MD DATE	DESCRIPTION
	47-001	SQUAWK	N/A	N/A	N/A	KSC	CASE	09/15/92	UNBONDED PAINT AT 30-DEGREES OF CENTER FIELD JOINT AFT OF K5NA RUN
	47-004	SQUAWK	N/A	N/A	N/A	KSC	JPS/TPS	09/15/92	MISSING K5NA AT 210-DEGREES ON THE AFT STIFFENER RING SPLICE PLATE
	47-014	SQUAWK	N/A	N/A	N/A	KSC	JPS/TPS	09/16/92	MISSING PAINT ON CURRY RUNS ADJACENT TO SYSTEMS TUNNEL OF FORWARD CENTER SEGMENT
	47-022	SQUAWK	N/A	N/A	N/A	KSC	IGNITER	09/21/92	GRAYISH FOREIGN MATERIAL ON S&A GASKET RETAINER
	47-024	SQUAWK	N/A	N/A	N/A	KSC	SEALS	09/21/92	FOREIGN (WHITISH) MATERIAL ON NOZZLE-TO-CASE JOINT PACKINGS WITH RETAINERS
	47-026	SQUAWK	N/A	N/A	N/A	KSC	SEALS	09/21/92	MACHINE MARKS ON NOZZLE-TO-CASE JOINT PACKING WITH RETAINERS
	47-028	SQUAWK	N/A	N/A	N/A	KSC	SEAL SURF.	09/21/92	SCRATCHES ON SEAL SURFACE OF FIXED HOUSING RADIAL BOLT HOLE SPOTFACES
	47-030	SQUAWK	N/A	N/A	N/A	KSC	CASE	09/25/92	UNBONDED PAINT ON CASE CENTER FIELD JOINT (CLEVIS)
	47-039	SQUAWK	N/A	N/A	N/A	KSC	CASE	09/25/92	FITTING AT FORWARD FLUID JOINT HEATER SPOT BOND LOCATION
	47-040	SQUAWK	N/A	N/A	N/A	KSC	CASE	09/25/92	FITTING AT AFT FLUID JOINT HEATER SPOT BOND LOCATION
	47C-01	PRELIM.	N/A	N/A	N/A	H-5/H-7	NOZZLE	09/25/92	DAMAGED AREAS ON THE NOSE INLET ASSEMBLY PHENOLICS
	47C-03	PRELIM.	N/A	N/A	N/A	H-5/H-7	NOZZLE	09/29/92	FOREIGN MATERIAL ON THE JOINT 4 PRIMARY SEAL SURFACE
	47C-05	PRELIM.	N/A	N/A	N/A	H-5/H-7	NOZZLE	09/29/92	SLAG DAMAGE ON THE BEARING PROTECTOR
	47C-06	PRELIM.	N/A	N/A	N/A	H-5/H-7	NOZZLE	09/30/92	BUBBLED PAINT ON THE FIXED HOUSING ID
	47C-08	PRELIM.	N/A	N/A	N/A	H-5/H-7	NOZZLE	09/30/92	ADHESIVE AROUND SPRING PIN HOLES ON COWL HOUSING ID
	47C-11	PRELIM.	N/A	N/A	N/A	H-5/H-7	NOZZLE	09/30/92	POSTBURN SEPARATION IN THROAT INLET RING FORWARD END
	47C-12	PRELIM.	N/A	N/A	N/A	H-5/H-7	NOZZLE	10/01/92	HEAT AFFECTED PHENOLICS ON THE AFT END OF THE NOSE INLET ASSEMBLY AT THE GAS PATH AREA
	47C-13	PRELIM.	N/A	N/A	N/A	H-5/H-7	NOZZLE	10/01/92	HEAT AFFECTED PHENOLICS ON THE COWL ASSEMBLY AT THE GAS PATH AREA
	47C-16	PRELIM.	N/A	N/A	N/A	H-5/H-7	NOZZLE	10/02/92	ABNORMAL FIXED HOUSING BONDLINE FAILURE MODE
	47C-17	PRELIM.	N/A	N/A	N/A	H-5/H-7	NOZZLE	10/07/92	RESIN GLAZE ON FIXED HOUSING
	47C-18	PRELIM.	N/A	N/A	N/A	H-5/H-7	NOZZLE	10/07/92	RESIN GLAZE ON FIXED HOUSING
	47C-20	PRELIM.	N/A	N/A	N/A	H-5/H-7	INSULATION	02/05/93	APPARENT COMPLIANCE SAFETY FACTOR VIOLATIONS OPEN, FOR AFT CENTER SEGMENT
	360T026A-01	PFAR	47-002	N/A	N/A	KSC	JPS/TPS	10/14/92	VOID IN K5NA CLOSOUT AT 30-DEGREE NAT BAND TRUNION CLOSOUT ON FORWARD FIELD JOINT JPS
	360T026A-02	PFAR	47-013	N/A	N/A	KSC	JPS/TPS	10/14/92	MISSING PAINT ON CURRY RUNS ADJACENT TO SYSTEM TUNNEL OF AFT SEGMENT
	360T026A-03	PFAR	47-018	N/A	N/A	KSC	NOZZLE	10/14/92	FOREIGN MATERIAL (DARK FLUID) FROM AFT EXIT CONE FORWARD SHEAR PIN VENT HOLE
	360T026A-04	PFAR	47-019	N/A	N/A	KSC	SEAL SURF.	10/14/92	PIT ON B-B FLANGE SECONDARY SEAL SURFACE
	360T026B-05	PFAR	47-020	N/A	N/A	KSC	IGNITER	10/14/92	GREASE IN IGNITER ADJACENT S&A BOLT HOLES
	360T026A-06	PFAR	47-021	N/A	N/A	KSC	IGNITER	10/14/92	CONTAMINATION ON S&A GASKET RETAINER
	360T026A-07	PFAR	47-023	N/A	N/A	KSC	SEALS	10/14/92	FOREIGN (WHITE) MATERIAL ON NOZZLE-TO-CASE JOINT PACKINGS WITH RETAINERS
	360T026A-08	PFAR	47-025	N/A	N/A	KSC	SEALS	10/14/92	CIRCUMFERENTIAL/TANGENTIAL ABRASIONS ON NOZZLE-TO-CASE JOINT PACKINGS WITH RETAINERS
	360T026B-09	PFAR	47-027	N/A	N/A	KSC	NOZZLE	10/14/92	FOREIGN MATERIAL (METAL/FOIL) IN NOZZLE-TO-CASE JOINT POLYSULFIDE
	360T026B-10	PFAR	47-030	N/A	N/A	KSC	CASE	10/14/92	FOREIGN MATERIAL ON FIELD JOINT CLOSURE PLUG & O-RING
	360T026A-11	PFAR	47-035	N/A	N/A	KSC	JPS/TPS	10/14/92	PITTING AT FORWARD FIELD JOINT SPOT BOND LOCATIONS
	360T026A-12	PFAR	47-036	N/A	N/A	KSC	SEAL SURF.	10/14/92	DIAGONAL SCRATCH ON IGNITER CHAMBER SEALING SURFACE
	360T026A-13	PFAR	47-037	N/A	N/A	KSC	SEAL SURF.	10/14/92	IGNITER CHAMBER BLEND/REWORK ON OUTER SEALING/MATING SURFACE
	360T026B-14	PFAR	47-041	N/A	N/A	KSC	IGNITER	10/14/92	BLUE AND WHITE FOREIGN MATERIAL IN IGNITER INNER JOINT
	360T026B-15	PFAR	47-042	N/A	N/A	KSC	IGNITER	10/14/92	RED, BLUE AND GRAY/WHITE FOREIGN MATERIAL IN IGNITER OUTER JOINT
	360T026B-16	PFAR	47-043	N/A	N/A	KSC	CASE	10/14/92	DAMAGED TANG FIELD JOINT ALIGNMENT SLOTS
	360T026B-17	PFAR	47C-02	N/A	N/A	H-5/H-7	NOZZLE	10/14/92	DISCOLORATION AROUND THE FORWARD EXIT CONE AFT SHEAR PINS
	360T026A-18	PFAR	47C-04	N/A	N/A	H-5/H-7	NOZZLE	10/14/92	FOREIGN MATERIAL (INLOK) ON THE JOINT 5 PRIMARY O-RING
	360T026A-19	PFAR	47C-07	N/A	N/A	H-5/H-7	NOZZLE	10/14/92	ADHESIVE AROUND SPRING PIN HOLES ON COWL HOUSING ID
	360T026A-20	PFAR	47C-09	N/A	N/A	H-5/H-7	NOZZLE	10/14/92	BUBBLED PAINT ON FORWARD END RING OD
	360T026B-21	PFAR	47C-10	N/A	N/A	H-5/H-7	NOZZLE	10/14/92	FOREIGN MATERIAL (WASHER) IN THE FLEX BEARING/THROAT CAVITY
	360T026A-22	PFAR	47C-14	N/A	N/A	H-5/H-7	SEALS	10/14/92	CUT IN 306-DEGREE BARRIER-BOOSTER LEAK CHECK PLUG O-RING
	360T026B-23	PFAR	47C-15	DRG-5/235	N/A	H-5/H-7	NOZZLE	10/14/92	ABNORMAL FIXED HOUSING BONDLINE FAILURE MODE
	360T026A-24	PFAR	47C-19	N/A	N/A	H-5/H-7	NOZZLE	11/30/92	ABNORMAL ALC METAL TO-ADHESIVE FAILURE MODE

REVISION _____

4.0 COMPONENT EVALUATIONS

The following sections detail, by component, the hardware condition observed at Clearfield.

4.1 Insulation

Internal insulation evaluations of the igniters, case acreage, joints, and liners are summarized in the following sections. PFORs documenting the observations are found in Appendix A. Only the LH motor was evaluated as specified in the Clearfield PEEP.

4.1.1 Thermal Performance Evaluation

Summaries of the safety factors for the nozzle-to-case joint, field joint, factory joint, case acreage and igniter insulation are found in Table 3 through Table 7, respectively. All safety factors for these areas can be found in Appendix E, Tables E-1 through E-22. Note that all joint insulation regions, including factory joints, must meet a minimum safety factor of 2.0. A minimum safety factor of 1.5 is required in the acreage insulation regions.

The igniter insulation forward of the igniter nozzle insert (Station 5), requires a minimum remaining insulation thickness of 0.010 inch.

Preliminary PFAR 47C-20 was written for apparent CSF violations on the LH aft center segment (see Table 4). The apparent violations occurred at the factory joint (161.4 inch station) which has a history of providing inaccurate prefire data. The 161.4 inch station will be replaced by the 163.0 inch station effective RSRM-30. All other safety factors were within CEI specification limits. All thermal protection requirements were met.

4.1.2 Internal Insulation Samples

The Clearfield PEEP specified that removal of standard insulation samples was not required on 360T026.

Table 3. Summary of 360T026 Nozzle-to-Case Joint and Field Joint Insulation Safety Factors

<u>Joint</u>	<u>Min. Compliance Safety Factor (CSF) *</u>	<u>Degree Location</u>	<u>Min. Actual Safety Factor (ASF) *</u>	<u>Degree Location</u>
Nozzle-to-Case Joint, LH	3.6	0.0	4.1	0.0
Aft Field Joint, LH	6.0	90.0	6.2	90.0
Center Field Joint, LH	13.0	46.0	14.0	46.0
Forward Field Joint, LH	15.6	226.0	16.7	226.0

* Minimum required joint insulation safety factor is 2.0.

Table 4. Summary of 360T026 Factory Joint Insulation Safety Factors

<u>Joint</u>	<u>Station (inches)</u>	<u>Min. Compliance Safety Factor (CSF) *</u>	<u>Degree Location</u>	<u>Min. Actual Safety Factor (ASF) *</u>	<u>Degree Location</u>
Aft Dome/ Stiffener, LH	56.0	3.06	0.0	3.83	0.0
Stiffener/ Stiffener, LH	177.7	2.18	180.0	3.55	180.0
Stiffener/ET Attach, LH	299.1	2.86	180.0	4.68	180.0
Aft Center, LH	161.4	1.46**	90.0	4.22	90.0
Forward Center, LH	161.4	2.74	316.0	6.86	316.0
Forward Cylinder/ Cylinder, LH	162.0	3.99	286.0	5.35	286.0
Forward Dome/ Cylinder, LH	321.0	4.14	90.0	4.55	90.0

* Minimum required joint insulation safety factor is 2.0.

** Preliminary PFAR 47C-20 written on apparent CSF violations.

Table 5. Summary of 360T026 Case Acreage Insulation Safety Factors

<u>Segment</u>	<u>Min. Compliance Safety Factor (CSF) *</u>	<u>Station (inches)</u>	<u>Degree Location</u>	<u>Min. Actual Safety Factor (ASF) *</u>	<u>Station (inches)</u>	<u>Degree Location</u>
Aft Dome, LH	2.07	12.0	180.0	2.37	45.0	46.8
Aft, LH	2.25	133.0	0.0	2.32	145.5	0.0
Aft Center, LH	2.70	30.7	136.0	2.93	30.7	136.0
Forward Ctr., LH	3.10	178.0	0.0	3.89	71.5	316.0
Forward, LH	2.20	362.0	286.0	2.43	263.0	286.0

* Minimum required case acreage insulation safety factor is 1.5.

Table 6. Summary of 360T026 Igniter Insulation Safety Factors

	<u>Min. Compliance Safety Factor (CSF) *</u>	<u>Station</u>	<u>Degree Location</u>	<u>Min. Actual Safety Factor (ASF) *</u>	<u>Station</u>	<u>Degree Location</u>
LH Igniter Chamber OD	2.78	3	330.0	2.97	3	330.0
RH Igniter Chamber OD	2.52	3	0.0	2.73	3	0.0
LH Igniter Chamber ID	8.32	9	60.0	8.94	9	60.0
RH Igniter Chamber ID	9.98	7	180.0	10.94	7	180.0
LH Adapter	2.79	11	180.0	3.33	11	180.0
RH Adapter	3.32	11	180.0	3.97	11	180.0
LH Inner Joint	4.73	10	330.0	5.13	10	0.0
RH Inner Joint	9.58	10	90.0	10.76	10	90.0
LH Outer Joint	2.96	1	60.0	3.60	1	60.0
RH Outer Joint	3.13	1	330.0	3.73	1	330.0

* Minimum required safety factors are 1.5 for the chamber and adapter acreage and 2.0 for the igniter joints.

Table 7. Summary of 360T026 Igniter Insulation at Station 5

<u>Igniter</u>	<u>Station</u>	<u>Minimum Postflight Thickness *</u>	<u>Degree Location</u>
Igniter, LH	5	0.110	150.0
Igniter, RH	5	0.114	0.0

* Minimum required thickness is 0.010 inch at Station 5.

4.1.3 Liner

Detailed liner maps are included in Appendix A. The remaining liner patterns were typical of past flight motors.

4.1.4 Igniter Nozzle Insert

LH

The postflight igniter nozzle insert throat diameter measurements were 6.435 inches at 0 degrees, 6.421 inches at 60 degrees, and 6.438 inches at 120 degrees. Using the maximum postfire measurement provides a thermal factor of safety of 7.7.

RH

The postflight igniter nozzle insert throat diameter measurements were 6.372 inches at 0 degrees, 6.384 inches at 60 degrees, and 6.362 inches at 120 degrees. Using the maximum postfire measurement provides a thermal factor of safety of 8.9.

4.1.5 Results of Special Issues and Concerns (Insulation)

TWR-64201 identified areas for special evaluation for 360T026. A single insulation issue is listed below with the results.

1. Condition: Excess delay time occurred between the first liner mix and sling lining application during the liner application process of the RH aft center segment. No repair was made.

Reference: TWR-63082

Results: The RH center liner pattern was evaluated following low pressure rinse. The remaining liner pattern was normal and consistent with previous aft center segments. There were no anomalous conditions as a result of the time delay.

4.2 Case, Seals, and Joints

Seal and joint evaluations of the S&As, factory joints, internal nozzle joints, ports, and port plugs were performed. PFORs documenting the observations are found in Appendix B.

4.2.1 S&As

Figure 2 shows the Safe and Arm device (S&A) configuration. The S&As were disassembled on 1 October 1992 at the Clearfield H-5 facility. The following is a summary of the assessment observations.

Typical soot was observed up to, but not past, the forward primary rotor shaft O-ring of both S&As. No O-ring or other seal surface damage was observed.

4.2.2 Factory Joints

The factory joints were inspected by Quality Assurance at Clearfield. All fourteen factory joints were in good condition with no O-ring heat effect or erosion observed. The RH forward dome joints had small areas of heavy corrosion. The LH forward dome had minor fretting and small areas of medium corrosion. None of these conditions adversely affected the performance of the joint.

4.2.3 Internal Nozzle Joints

Details concerning the nozzle internal joint performance can be found in section 4.3.

4.2.4 Port Plugs and Port Plug Seals

S&As

One anomalous condition was observed. A scratch was observed on the LH S&A 306 degree leak check plug. Preliminary PFAR 47C-14 was written on this condition. The scratch was "V"-shaped and oriented in a radial direction. The cause or time of occurrence was unknown. Typical galling on the land between the SII port primary and secondary seal surfaces was observed on both S&As. No other O-ring, plug or seal surface damage was observed.

Factory Joints

No anomalous conditions were observed on any of the leak test ports, plugs or plug O-rings.

Internal Nozzle Joints

No anomalous conditions were observed on any of the internal nozzle joint leak test ports, plugs or plug O-rings.




Figure 2. Safe and Arm Device Configuration

4.2.5 Results of Special Issues and Concerns (Case, Seals, and Joints)

TWR-64201 identified areas for special evaluation of 360T026 at Clearfield. The case, seals, and joints issues are listed below with their respective results.

- 1. Condition:** Corrosion was observed on the rotor detent ball spring during postflight evaluation of the RSRM-21 LH barrier-booster device. The spring should have been a MS24585-C5 (stainless steel) spring, but was actually a MS24585-5 (non-corrosion resistant music wire) spring.

Reference: TWR-63082

Results: Discoloration was observed on the rotor detent ball spring of both S&As. The springs are being evaluated by M&P for evidence of corrosion.

- 2. Condition:** A recent seals audit identified discrepancies between the Refurbishment and process finalization specifications (STW7-3434 and STW7-3450, respectively) and Engineering requirement drawings. The specifications do not provide adequate criteria for the throat support housing forward and aft seal surfaces of nozzle joints 3 and 4.

Reference: Nozzle CPT, RDW 0640R1 (Effective through RSRM-26), (Joint 3 only)

Results: Typical light-to-medium corrosion was observed on both the LH and RH throat support housing forward and aft faces. No seal surface damage was observed.

- 3. Condition:** Both the LH and RH factory joints may have leak test plugs procured from Standard Press Steel. These plugs have a white locking device instead of the blue locking device that has been used on hardware procured from Nylock Fasteners, Inc.

Reference: DR 408903

Results: Several of the plugs had the white locking device. This did not affect the design or performance of the plug.

4.3 Nozzle

Figure 3 shows the internal nozzle joint nomenclature and details the internal nozzle joint configuration used in this report. The PFORs documenting the observations are contained in Appendix C.

The nozzles were off-loaded at Clearfield H-6 on 25 September 1992. The LH nozzle showed no transportation damage. The RH nozzle showed transport tie-down strap




Figure 3. Internal Nozzle Joint Configuration

damaged phenolic liners at 352-0-5 degrees on the nose cap and forward end of the forward inlet ring. Preliminary PFA 47C-01 was written on this condition. The RH nozzle forward exit cone showed foreign material around three of the aft end shear pin screws in the CCP/GCP interface. Samples were taken and Preliminary PFA 47C-02 was written on this condition. Analysis of the foreign material shows it was grease.

The internal nozzle joints were disassembled on September 28-30, 1992 at the H-6 facility in Clearfield. The condition of the RSRM-26 nozzle joints was generally typical of previous flight nozzles. RTV was below the char line in all joints. The primary and secondary O-rings in all joints showed no signs of blowby, erosion, heat effects or disassembly damage. There was no significant metal hardware damage.

The following sections provide detailed assessments of nozzle internal joints, bondlines, char and erosion performance, flex boot and flex bearing condition, and throat erosion data. The outcome of special issues and concerns for this nozzle flight set is also presented.

4.3.1 Nose Inlet/Forward End Ring/Cowl (Joint 2)

LH

The forward end ring forward spherical surface had paint bubbles from 170-to-325 degrees extending from forward end to within one inch of secondary O-ring groove. Clear fluid was present inside paint bubbles. Samples were taken and Preliminary PFA 47C-09 was written on this condition.

There was typical mixing of RTV and adhesive with the RTV reached below the char line over the complete circumference. Soot entered the joint between the layers of RTV and adhesive. Typical scalloped shaped soot was observed between the bolt holes on the nose inlet and forward end ring around the full circumference. Soot reached the primary O-ring intermittently from 195-to-345 degrees. No soot was observed past the primary O-ring.

Grease coverage on the joint metal surfaces was nominal. No excessive grease was found in the bolt holes. Light-to-medium corrosion was observed on the forward mounting face and ID of cowl housing and on forward side of flex bearing forward end ring flange intermittently around circumference. Typical burnishing was observed intermittently on the nose inlet secondary seal surface. No O-ring, seal surface or leak check plug damage was observed. The leak check port plug breakaway torque was 35 in-lb and the running torque was 20 in-lb.

There were no separations observed on the cowl assembly. The aft end of nose assembly had metal-to-adhesive separations intermittently around circumference a maximum radial width of 0.005 inch.

RH

A rusty 1.20 inch diameter washer was found in sand and splashdown debris of the throat/flex bearing cavity. Preliminary PFAR 47C-10 was written on this condition. Measurements and material test show the washer is not nozzle flight hardware. Sand in the cavity indicates the nozzle may have hit river bottom during towback operations and picked the washer up with the sand.

There was typical mixing of RTV and adhesive with the RTV reached below the char line over the complete circumference. Soot entered the joint between the layers of RTV and adhesive. A gas path through the RTV was observed at 350 degrees and extended circumferentially to 356 degrees within the RTV at the nose assembly GCP and the cowl assembly SCP interface. Typical scalloped shaped soot was observed between the bolt holes on the nose inlet and forward end ring, full circumference. Soot reached the primary O-ring intermittently from 290-0-40 degrees. No soot was observed past the primary O-ring. No heat effects were found in this area on the forward end ring or the cowl housing. The virgin CCP on both assemblies, the GCP on the nose cap and the SCP on the cowl showed shallow heat effects throughout the gas path. Preliminary PFAR's 47C-12 and 47C-13 were written on this condition.

Grease coverage on the joint metal surfaces was nominal. No excessive grease was found in the bolt holes. Light-to-medium corrosion was observed on the forward mounting face and ID of cowl housing and on forward side of flex bearing forward end ring flange intermittently around circumference. Typical burnishing was observed intermittently on the nose inlet secondary seal surface. No O-ring, seal surface, or leak check plug damage was observed. The leak check port plug breakaway torque was 34 in-lb and the running torque was 12 in-lb.

There were no separations observed on the cowl assembly. The aft end of nose assembly had metal-to-adhesive separations intermittently around circumference a maximum radial width of 0.005 inch.

4.3.2 Nose Inlet/Throat (Joint 3)

LH

The RTV reached below the char line over the complete circumference. Two RTV voids were observed at 85 and 238 degrees, but no gas paths were found in the joint. Grease did not interfere with the RTV fill in the joint.

Grease coverage on the joint metal surfaces was nominal. No excessive grease was found in the bolt holes. Light-to-medium corrosion was visible on in-board edge of the throat housing and GCP full circumference. Aluminum oxide corrosion was visible on the nose inlet housing in-board edge and GCP surface intermittently full circumference. No O-ring, seal

surface, or leak check port plug damage was observed. The leak check port plug breakaway torque was 36 in-lb and the running torque was 23 in-lb.

The nose inlet assembly showed two areas of metal-to-adhesive separations with a maximum radial width of 0.005 inch. The throat assembly forward end was separated intermittently around circumference at metal-to-adhesive with a maximum radial width of 0.015 inch.

RH

The RTV reached below the char line over the complete circumference. Grease did not interfere with the RTV fill in the joint. No gas paths were found in the joint.

Grease coverage on the joint metal surfaces was nominal. No excessive grease was found in the bolt holes. Light-to-medium corrosion was visible on inboard edge of the throat housing and GCP full circumference. Aluminum oxide corrosion was visible on the nose inlet housing in-board edge and GCP surface intermittently full circumference. No O-ring, seal surface, or leak check port plug damage was observed. The leak check port plug breakaway torque was 33 in-lb and the running torque was 11 in-lb.

The nose inlet assembly showed three areas of metal-to-adhesive separations with a maximum radial width of 0.005 inch. The throat assembly forward end was separated intermittently around circumference at metal-to-adhesive with a maximum radial width of 0.020 inch. The throat inlet ring also showed a separation within the CCP from 48-to-138 degrees with a maximum radial width of 0.058 inch. The separation extended through to the flow surface along the ply angle. Sharp edges around the separation flow surface indicate postburn occurrence. Preliminary PFAR 47C-11 was written on this because it was thought to be a first time occurrence. Further examination of our postfire database shows this was not a first time occurrence. Postfire virgin CCP separations is an acceptable condition.

4.3.3 Throat/Forward Exit Cone (Joint 4)

LH

Foreign material was observed on the primary seal surface of both the throat housing and forward exit cone at 28 and 30 degrees. Preliminary PFAR 47C-03 was written on the condition. The soot-like material, black and flaky, appeared to have been pressed into the O-ring groove by the primary O-ring from 23-to-30 degrees. Slag-like material was observed on the primary O-ring from 28-to-30 degrees. Loose, black material was also observed in the primary O-ring groove and on the mating surface of the throat housing intermittently, full circumference. The black material appeared to be from disassembly.

The RTV reached below the char line over the complete circumference of the joint with no gas paths. RTV did not reach the primary O-ring. Grease did not interfere with the RTV fill in the joint.

Grease coverage on the joint metal surface was nominal. Medium corrosion was observed at the throat housing and adhesive interface intermittently around the circumference. No other metal damage was observed. No O-ring, seal surface, or leak check port plug damage was observed. The leak check port plug breakaway torque was 28 in-lb and the running torque was 15 in-lb.

The FEC forward end showed full circumference metal-to-adhesive separation with a maximum radial width of 0.080 inch. Three adhesive-to-GCP separations with a maximum radial width of 0.060 inch were observed on the FEC forward end. The aft end of the throat assembly exhibited a separation full circumference with a maximum radial width of 0.050 inch.

RH

The RTV reached below the char line over the complete circumference of the joint. RTV extended to the primary O-ring from 0-to-184 and 260-to-350 degrees, but not past O-ring. No gas paths were present in the RTV. Grease did not interfere with the RTV fill in the joint.

Grease coverage on the joint metal surface was nominal. Typical medium corrosion was observed in the metal-to-adhesive separations. No other metal damage was observed. No O-ring, seal surface, or leak check port plug damage was observed. The leak check port plug breakaway torque was not obtained and the running torque was 24 in-lb.

Metal-to-adhesive separations with a maximum radial width of 0.019 inch were observed intermittently around circumference on the forward exit cone assembly. Two adhesive-to-GCP separations were also observed on the FEC with a maximum radial width of 0.011 inch. Metal-to-adhesive separations were also observed intermittently around circumference on the throat assembly with a maximum radial width of 0.015 inch.

4.3.4 Flex Bearing/Fixed Housing (Joint 5)

LH

Nylon material from the Nylok locking device of the bolts was observed on the downstream edge of the primary O-ring at 235 degrees. Preliminary PFAR 47C-04 was written on this condition. The Nylon did not completely bridge the O-ring footprint. All 72 Packing with Retainers had typical disassembly damage to the elastomer. No O-ring, seal surface, or leak check port plug damage was observed. Light corrosion was observed on the underside of the leak check port plug outboard of the O-ring. The leak check port plug breakaway torque was 39 in-lb and the running torque was 12 in-lb.

The RTV coverage was nominal with intermittent encapsulated voids due to assembly process. The RTV extended forward intermittently around the full circumference on the ID of bearing protector inner ring to the flex bearing aft end ring bearing protector interface.

Grease coverage on the joint metal surfaces was nominal with no excess grease in the bolt holes. Intermittent light-to-medium corrosion observed on the ID and OD of aft tip of the aft end ring intermittently around the circumference. There was medium-to-heavy corrosion on the ID forward tip of the fixed housing intermittently around the circumference. The fixed housing ID surface showed bubbled paint on the aft flange and on the chamfer surface from 340-0-110 degrees. There was also bubbled paint in a 6.00 inch axial wide area 5.00 inches from aft end from 47-to-83 degrees. Paint in these areas did not appear to be heat affected. No corrosion was found on metal surface under paint bubbles. Preliminary PFAR 47C-06 was written on this unbonded paint condition.

Typical even sooting was present on the bearing protector OD and the flexible boot ID.

No separations were observed between the inner boot ring and the fixed housing.

RH

The RTV coverage was nominal with intermittent encapsulated voids due to assembly process. The RTV extended forward intermittently around the full circumference on the ID of bearing protector inner ring to the flex bearing aft end ring flange surface.

Sixty-nine of the 72 Packings with Retainers had typical disassembly damage to the elastomer. No O-ring, seal surface, or leak check port plug damage was observed. The leak check port plug breakaway torque was 40 in-lb and the running torque was 11 in-lb.

Grease coverage on the joint metal surfaces was nominal with no excess grease in the bolt holes. Intermittent light-to-medium corrosion observed on the ID and OD of aft tip of the aft end ring and on the ID forward tip of the fixed housing intermittently around the circumference. The fixed housing showed bubbled paint on the ID surface sixteen inches from aft end from 90-to-180 degrees. Paint in this area did not appear to be heat affected.

Typical even sooting was present on the bearing protector OD and the flexible boot ID.

No separations were observed between the inner boot ring and the fixed housing.

4.3.5 Aft Exit Cone Assembly Bondlines

LH

The primary mode of separation was 85 percent within the GCP and 15 percent metal-to-adhesive. The secondary mode of separation was 94 percent adhesive-to-GCP, 5 percent metal-to-adhesive and 1 percent within adhesive. The bulk of the metal-to-adhesive separation occurred from 292-0-47 degrees. Preliminary PFAR 47C-19 was written because the total metal-to-adhesive separation exceeded 20 percent. Light-to-medium corrosion was observed in the areas of metal-to-adhesive. Four adhesive

voids has a diameter greater than 0.5 inch. Intermittent small voids (0.2 inch diameter maximum) were seen throughout the polysulfide. No voids extended the full axial length of the groove.

RH

The primary mode of separation was 2 percent metal-to-adhesive and 98 percent within GCP. The secondary mode was 1 percent metal-to-adhesive and 99 percent adhesive-to-GCP. No corrosion was observed. One adhesive void had a diameter greater than 0.5 inch. Intermittent small voids (0.1 inch diameter maximum) were seen throughout the polysulfide. No voids extended the full axial length of the groove.

4.3.6 Forward Exit Cone Assembly Bondlines

LH

Mode of separation was 52 percent metal-to-adhesive, 9 percent within adhesive and 39 percent adhesive-to-GCP. Medium-to-heavy corrosion observed on the aft 10.0 inches. Light-to-medium corrosion was present 5.0 inches aft of the forward shear pins in a band approximately 7.0 inches wide. Eight adhesive voids had a diameter greater than 0.5 inch.

RH

Mode of separation was 62 percent metal-to-adhesive, 37 percent adhesive-to-GCP and 1 percent within the adhesive. Medium-to-heavy corrosion observed in areas of adhesive-to-metal separation. Five adhesive voids had a diameter greater than 0.5 inch.

4.3.7 Throat Assembly Bondlines

LH

The throat inlet ring and throat ring mode of separation was 99 percent metal-to-adhesive and 1 percent adhesive-to-GCP. Medium-to-heavy corrosion was present. Three adhesive voids had a diameter greater than 0.5 inch.

RH

The throat inlet ring and throat ring mode of separation was 100 percent metal-to-adhesive. Medium-to-heavy corrosion present the full axial length of throat support housing and full circumference. Six adhesive voids had a diameter greater than 0.5 inch.

4.3.8 Nose Inlet Rings Bondlines

LH

The mode of separation was 98 percent metal-to-adhesive, 1 percent within the adhesive, and 1 percent adhesive-to-GCP. Two adhesive voids had a diameter greater than 0.5 inch. Light-to-medium corrosion was present in the areas of adhesive-to-metal separation except from 0-to-25 and 155-to-205 degrees on the aft 4.0 inches of the aft inlet ring bonding surface.

RH

The mode of separation was 91 percent metal-to-adhesive and 9 percent adhesive-to-GCP. Two adhesive voids had a diameter greater than 0.5 inch. Light-to-heavy corrosion was present in the areas of adhesive-to-metal separation except from 60-to-80 and 230-to-285 degrees on the forward 4.2 inches of the aft inlet ring bonding surface. The areas of heavy corrosion did not have any pitting that exceeded the 0.050 inch limit.

4.3.9 Nose Cap Bondlines

LH

The primary mode of separation was 95 percent CCP-to-GCP and 5 percent within GCP. The secondary mode of separation was 75 percent adhesive-to-GCP and 25 percent metal-to-adhesive. One adhesive void had a diameter greater than 0.5 inch. Light-to-medium corrosion was found in the metal-to-adhesive separation on the aft 2.0-to-3.0 inches and on the forward 0.25-to-1.5 inches.

RH

The mode of separation was 95 percent CCP-to-GCP and 5 percent within GCP. The secondary mode of separation was 96 percent adhesive-to-GCP and 4 percent metal-to-adhesive. Eight adhesive voids had a diameter greater than 0.5 inch. Light-to-medium corrosion was found in the metal-to-adhesive separation on the aft 1.0-to-4.5 inches and on the forward 0.5-to-1.5 inches

4.3.10 Cowl Bondlines

LH

The mode of separation was 100 percent metal-to-adhesive. Ten adhesive voids had a diameter greater than 0.5 inch. Light-to-medium corrosion was observed on the bonding surface around the full circumference.

RH

The mode of separation was 100 percent metal-to-adhesive. Three adhesive voids had a diameter greater than 0.5 inch. Light-to-medium corrosion was observed on the bonding surface around the full circumference.

4.3.11 Fixed Housing Assembly Bondlines

LH

The mode of separation was 64 percent metal-to-adhesive, 1 percent within the GCP, and 35 percent adhesive-to-GCP. Preliminary PFAR 47C-16 was written because the metal-to-adhesive separation exceeded 15 percent and was not elevated to a PFAR. Ultrasonic inspection did detect unbonds and are detailed in section 5.3.12. Stains were observed on the housing marking the location of the unbonds. Hardness checks were performed on the housing and found no sign of heat affects.

Resin glaze was observed at the GCP-to-adhesive interface. Preliminary PFAR 47C-17 was written because of this condition. One adhesive void had a diameter greater than 0.5 inch. Intermittent adhesive voids with diameters of 0.30 inch or smaller were observed around the circumference. No corrosion was observed on the housing

There were no signs of gas paths or heat affects on the inner boot ring-to-fixed housing interface. The bondline separation mode between the IBR and the Fixed Housing insulation was 85 percent IBR-to-adhesive, 10 percent virgin CCP-to-adhesive and 5 percent within adhesive. The bondline separation mode between the NBR rubber and the fixed housing insulation was 73 percent within NBR, 9 percent virgin CCP-to-adhesive, 7 percent within IBR GCP (aft corner), 7 percent within char CCP and 5 percent within adhesive.

The IBR-to-Fixed Housing bondline was assessed. The primary separation mode was 28 percent metal-to-adhesive, 22 percent adhesive-to-GCP, 32 percent within GCP and 18 percent within adhesive. The secondary mode was 96 percent adhesive-to-GCP and 4 percent metal-to-adhesive.

RH

The mode of separation was 95 percent metal-to-adhesive and 5 percent adhesive-to-GCP. Preliminary PFAR 47C-15 was written because the metal-to-adhesive separation exceeded 15 percent. Ultrasonic inspection did detect unbonds and are detailed in section 5.3.12. Stains were observed on the adhesive and housing marking the location of the unbonds. Hardness checks were performed on the housing and no sign of heat effects were found.

Resin glaze was observed at the GCP-to-adhesive interface. One adhesive void had a diameter greater than 0.5 inch. Intermittent adhesive voids with diameters of 0.30 inch or smaller were observed around the circumference. No corrosion was observed on the housing.

There were no signs of gas paths or heat effects on the inner boot ring-to-fixed housing bondline. The bondline separation mode between the IBR and the Fixed Housing insulation was 86 percent IBR-to-adhesive, 5 percent virgin CCP-to-adhesive and 9 percent within adhesive. The bondline separation mode between the NBR rubber and the Fixed Housing insulation was 6 percent within NBR, 62 percent virgin CCP-to-adhesive, 1 percent within IBR GCP (aft corner), 28 percent within char CCP and 3 percent within adhesive.

The IBR-to-Fixed Housing bondline was assessed. The primary separation mode was 66 percent metal-to-adhesive, 15 percent adhesive-to-GCP, 6 percent within GCP and 13 percent within adhesive. The secondary mode was 100 percent adhesive-to-GCP. Intermittent light-to-medium corrosion was observed in the areas of metal-to-adhesive.

4.3.12 Ultrasonic Inspection of Fixed Housing Assemblies

Unbonds that ran the full circumference were detected by ultrasonic inspection on the forward end of both fixed housings. The widest areas on the left-hand were 6.0 inches from 0-to-90 degrees and 8.5-to-11.0 inches from 90-to-270 degrees. The widest areas on the 6.0 inches and broken into several smaller distinct bands in several locations.

4.3.13 Char and Erosion Performance

Char and erosion margins of safety are summarized in Table 8. The char and erosion data tables for each component liner can be found in Appendix D. Measurement stations that contain an "N/A" means that data was not available due to missing material. The RH aft exit cone liner was not recovered and therefore is not included. Three large LH aft exit cone fragments were recovered from inside the motor at the KSC Hangar AF. Each fragment was sectioned in two places and evaluated. No plylifting or axial orientation features were present on the fragments. Therefore, erosion and char calculations could not be made. All stations showed positive margins of safety. The measurement stations can be found in Figure 1 of Appendix D.

4.3.14 Flex Boot Performance

The performance of both flex boots was nominal. The LH hand flex boot had a minimum of 3.0 NBR plies intact and the RH flex boot had a minimum of 3.4 NBR plies intact. Positive margins of safety were achieved at all measurement stations. The flex boot performance margins of safety are summarized in Table 9.

Table 8. 360T026 Nozzle Char and Erosion Minimum Margins of Safety

Hardware	Stations*												
	1	4	4.6	8	12	16	20	24	28	32	32.9	34	
Forward Exit Cone Assembly, LH	0.25	0.27	0.24	0.20	N/A	N/A	N/A	N/A	0.11	0.13	0.22	0.26	
Forward Exit Cone Assembly, RH	0.29	0.32	0.30	0.24	N/A								
Throat Assembly, LH	0.15	0.15	0.10	0.07	0.06	0.16	0.20	0.27	0.32	0.40	0.46	0.37	0.23
Throat Assembly, RH	0.20	0.21	0.19	0.14	0.09	0.20	0.26	0.32	0.39	0.43	0.49	0.43	0.22
Nose Inlet Rings (-503, -504), LH	0.23	0.34	0.15	0.39	0.37	0.18	0.15						
Nose Inlet Rings (-503, -504), RH	0.18	0.32	0.16	0.42	0.35	0.20	0.14						
Nose Cap, LH	N/A	0.50	0.74	0.74	0.89	0.84	0.81	0.69	0.67	0.58	0.19	0.08	0.12
Nose Cap, RH	0.24	0.44	0.48	0.63	0.72	0.75	0.77	0.59	0.62	0.51	0.20	0.10	0.21
Cowl/OBR, LH	0.38	0.33	0.28	0.29	0.35	N/A							
Cowl/OBR, RH	0.15	0.20	0.24	0.24	0.27	N/A	N/A	N/A	N/A	0.07	0.05	0.02	
Fixed Housing Assembly, LH	1.76	0.75	0.64	0.60	0.68	0.66	0.68	0.75	0.85	1.50	0.48		
Fixed Housing Assembly, RH	1.86	0.75	0.79	0.85	0.79	0.83	0.85	0.83	1.04	1.61	0.53		

* Station locations are shown in bold with the margin of safety shown below.

4.3.15 Bearing Protector Performance

Close examination showed both of the bearing protectors performed as expected during flight. Both of the protectors were evenly sooted around the circumference and showed typically greater erosion in line with the cowl vent holes. There was no evidence of heat effect on the flex bearing side of either bearing protector. PFOR C-9 in Appendix C shows the postflight bearing protector thickness measurements every 10 degrees. On the forward third of the RH bearing protector, fluid was observed coming out of the cracks. This condition was observed on past bearing protectors and found to be the by-product of the thermal degradation of the bearing protector material.

Table 9. 360T026 Flex Boot Margins of Safety

Degree Location	Left Hand			Right Hand		
	Remaining Plies	Max. Material Affected Depth (in.)	Performance Margin of Safety	Remaining Plies	Max. Material Affected Depth (in.)	Performance Margin of Safety
0	3.5	1.24	0.34	3.8	1.14	0.46
90	3.0	1.40	0.19	3.4	1.27	0.31
180	3.6	1.21	0.38	3.8	1.14	0.46
270	3.9	1.11	0.50	3.4	1.27	0.31

* Minimum flex boot overall prefire thickness is 2.5 inches.

4.3.16 Cowl Insulation Segments

Both nozzle segments performed as expected during flight. No abnormal heat effects were observed and no soot was found at the cowl housing interface. Adhesive that retains the silica plugs in the cowl phenolics, flowed into the cowl housing-to-insulation segments bondline around all 36 spring pins on both nozzles. Preliminary PFAR 47C-07 was written on this first time occurrence.

The mode of separation from the cowl housing for the LH segments was 1 percent within the rubber, 90 percent rubber-to-adhesive and 9 percent within the adhesive. The RH separation mode was 3 percent within the rubber, 85 percent rubber-to-adhesive and 12 percent within the adhesive.

4.3.17 Flex Bearing Performance

LH

The flex bearing performance during flight was acceptable. There were no anomalies associated with flight or splashdown. Examination of the flex bearing revealed no damage, soot, heat effect, or flow indications. Typical paint scrape marks, caused by contact with snubbers at splashdown, were observed on ID of aft end ring from 155-to-305 degrees with a maximum axial width of 7.00 inches at 150 degrees. Light corrosion was present on exposed metal surfaces.

RH

The flex bearing performance during flight was acceptable, with no anomalies reported. Examination of the flex bearing revealed no damage, soot, heat effect, or flow indications.

Typical paint scrape marks, caused by contact with snubbers at splashdown, were observed on ID of aft end ring from 165-to-290 degrees with a maximum axial width of 2.00 inches. Light-to-medium corrosion was present on exposed metal surfaces.

4.3.18 Throat Diameter

The average LH nozzle postfire throat diameter was 55.934 inches (erosion rate of 8.63 mils/sec based on an action time of 120.1 sec). The average RH nozzle postfire throat diameter was 55.888 inches (erosion rate of 8.36 mils/sec based on an action time of 121.3 sec). RSRM postfire throat diameters have ranged from 55.787 to 56.072 inches.

4.3.19 Results of Special Issues and Concerns (Nozzle)

TWR-64201 identified areas for special evaluation of 360T026 at Clearfield. The nozzle issues are listed below with their respective results.

- 1. Condition:** Both the LH and RH forward exit cone snubber support rings and snubber shim retainer bolts and bolt hole threads were damaged.

Reference: DRs (LH) 110496-01 & -03, 407068-01 & -02
(RH) 172373-01 & -02, 407152-01 & -02

Results: The LH and RH forward exit cone housings snubber support ring threaded bolt holes and the shim retainer threaded bolt holes showed no damage.

- 2. Condition:** Three voids exist on the RH flexible boot rubber aft side at 180 degrees, 0.95 inch from the inner boot ring interface.

Reference: DR 408970-01

Results: The RH flexible boot showed no unusual erosion or char on the forward or aft side at 180 degrees.

- 3. Condition:** An area of discoloration exists on the RH flexible boot rubber aft side at 140 degrees, 8.5 inches from the inner boot ring interface. The area measures 6.50 inches circumferentially and 0.75 inch radially.

Reference: DR 411227-01

Results: The RH flexible boot showed no unusual erosion or char on the forward or aft sides at 140 degrees. There was 3.8 boot piles remaining at this location which was the maximum thickness of the five measured sections.

4. Condition: Adhesive shims were added to the aft surface of the throat housing to guide the throat ring into the housing as it was installed. This change was incorporated to improve the bondline quality because the throat ring tends to scrape the adhesive and create voids during installation.

Reference: PFAR FSM03-09

Results: The adhesive shims added to the aft bondline surface of the throat housing appear to have improved the distribution of adhesive and reduced adhesive voids considerably on the LH and RH throat assemblies

5. Condition: Bent and broken flex bearing protector forward ring screws have been observed on flight and static test motors. Exact cause of the damage is under investigation.

Reference: SPR DR4-5/228, PFAR 360L022A-19


Results: No bend or broken screws were found on the LH or RH flex bearing protector forward GCP ring.

6. Condition: During the KSC evaluation a brown material was found on the LH aft exit cone OD at the 321 degree shear pin location. The substance seemed to originate from the 321 degrees shear pin and extended in a counterclockwise direction to 195 degrees.

Reference: RSRM-26 KSC Postflight Evaluation Team

Results: No obvious foreign material was found in the bondline at 321 degrees. A large metal-to-adhesive bondline failure was observed at 305-0-34 degrees on the forward half of the AEC housing. Heavy corrosion with dark stains was present throughout this area. This indicates sea water mixed with postburn nozzle substances trapped in this separation would leak out any open pin hole. The only open pin hole occurred at 321 degrees.





Appendix A Insulation PFORs

Final Postflight Hardware Evaluation Report 360T026 (RSRM-26, STS-47)

April 1993

Prepared for:

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION
GEORGE C. MARSHALL SPACE FLIGHT CENTER
MARSHALL SPACE FLIGHT CENTER, ALABAMA 35812

Contract No.	NAS8-38100
DR No.	4-23
WBS No.	4C601-04-01
ECS No.	SS4769

Thiokol CORPORATION
SPACE OPERATIONS

P.O. Box 707, Brigham City, Utah 84302-0707 (801) 863-3511



INSULATION REQUIRED PFOR LIST

<u>PFOR #</u>	<u>Title</u>	<u>Side</u>	<u>Joint or Location</u>	<u>Final Report Page Number</u>
A-1	Postfire Insulation CPI Log Numbers	Left	N/A	A-1
A-2	Segment Internal Insulation Condition	Left	Forward Segment	A-2
A-2	Segment Internal Insulation Condition	Left	Forward Center Segment	A-3
A-2	Segment Internal Insulation Condition	Left	Aft Center Segment	A-4
A-2	Segment Internal Insulation Condition	Left	Aft Segment	A-5
A-8	Igniter Nozzle Insert Throat Diameter Measurements	Left	Igniter Nozzle Insert	A-6
A-3	Forward Segment Liner Pattern	Left	Forward Segment	A-7
A-4	Forward Center Segment Liner Pattern	Left	Forward Center Segment	A-8
A-5	Aft Center Segment Liner Pattern	Left	Aft Center Segment	A-9
A-6	Aft Segment Liner Pattern	Left	Aft Segment	A-10
A-5	Aft Center Segment Liner Pattern	Right	Aft Segment	A-11
A-8	Igniter Nozzle Insert Throat Diameter Measurements	Right	Igniter Nozzle Insert	A-12



Thiokol CORPORATION
SPACE OPERATIONS

POSTFLIGHT OBSERVATION RECORD (PFOR) A-1
Postfire Insulation Common Planning Index (CPI) Log Numbers

Motor No.: 360T026	Side: Left (A)	Date: 11 MARCH 93
--------------------	----------------	-------------------

Assessment Engineer(s)/Inspector(s): BILL LESKO

Record CPI Log and Postfire Part and Serial Numbers Below:

	P/N	PPC No.	Serial No.	CPI Log No.
A. Igniter Chamber	<u>1075161-01</u>	<u>918</u>	<u>5</u>	<u>4CFSN</u>
B. Igniter Adapter	<u>1077457-01</u>	<u>903</u>	<u>5</u>	<u>4CIBH</u>
C. Forward Segment	<u>1076790-05</u>	<u>904</u>	<u>10</u>	<u>4CGXF</u>
D. Forward Center Segment	<u>1076791-01</u>	<u>903</u>	<u>23</u>	<u>4CFWM</u>
E. Aft Center Segment	<u>1076791-01</u>	<u>903</u>	<u>22</u>	<u>4CFWM</u>
F. Aft Segment	<u>1076957-03</u>	<u>(904)</u>	<u>0000011</u>	<u>4CGXH</u>

Notes / Comments

RH IGNITER CHAMBER	<u>1075161-01</u>	<u>918</u>	<u>6</u>	<u>4CFSN</u>
RH IGNITER ADAPTER	<u>1077457-01</u>	<u>903</u>	<u>6</u>	<u>4CIBH</u>

Clarification Form(s)? Yes No Clarification Form Page No.(s): _____

REVISION _____

DOC NO. TWR-64204	VOL
SEC	PAGE A-1

POSTFLIGHT OBSERVATION RECORD (PFOR) A-2
Segment Internal Insulation Condition (After Low Pressure Rinse)

Motor No.: 360T026	Side: Left (A)	Date: Dec 10, 1992	
Assessment Engineer(s)/Inspector(s): Res Markley			
Segment: Forward			
Segment Internal Insulation Observations:			
	Yes	No	Comment #
A. Abnormal Erosion?	_____	_____/_____ ✓	_____
B. Gas Paths?	_____	_____/_____ ✓	_____
C. Ply Separations?	_____	_____/_____ ✓	_____
D. Abnormal Blisters?	_____	_____/_____ ✓	_____
E. Abnormal Cuts or Gouges?	_____	_____/_____ ✓	_____
F. Foreign Material Within Insulation?	_____	_____/_____ ✓	_____
G. Non-Uniformities in the Eleven Point Burn-out Pattern? (Forward Segment Only)	_____	_____/_____ ✓	_____
Notes / Comments			
Preliminary PFAR(s)? _____ Yes _____ No Preliminary PFAR Number(s): _____			
Clarification Form(s)? _____ Yes _____ No Clarification Form Page No.(s): _____			

POSTFLIGHT OBSERVATION RECORD (PFOR) A-8
Igniter Nozzle Insert Throat Diameter Measurements (Data Collection Only)

Motor No.: 360T026	Side: Left (A)	Date: 2/23/93
Assessment Engineer(s)/Inspector(s): B BAUGH		
Record the Igniter Nozzle Insert Throat Diameter Measurements Below:		
Degree Location	Diameter Measurement (inches)	
0	<u>6.435</u>	
60	<u>6.421</u>	
120	<u>6.438</u>	
Notes / Comments		


Clarification Form(s)? Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) A-3
Forward Segment Liner Pattern (Data Collection Only)

Motor No.: 360T026 Side: Left (A) Date: 12-04-92

Assessment Engineer(s)/Inspector(s): Res Mackley

Sketch Forward Segment Liner Pattern Observations Below:




Clarification Form(s)? Yes No Clarification Form Page No. (s): NONE

REVISION _____

POSTFLIGHT OBSERVATION RECORD (PFOR) A-4
Forward Center Segment Liner Pattern (Data Collection Only)

Motor No.: 360T026	Side: Left (A)	Date: 3-3-93
--------------------	----------------	--------------

Assessment Engineer(s)/Inspector(s): Thalman



Clarification Form(s)? Yes No Clarification Form Page No.(s): _____


REVISION _____

POSTFLIGHT OBSERVATION RECORD (PFOR) A-5
Aft Center Segment Liner Pattern (Data Collection Only)

Motor No.: 360T026 Side: Left (A) Date: FEB, 2, 93

Assessment Engineer(s)/Inspector(s): M. NEVAREZ

Sketch Aft Center Segment Liner Pattern Observations Below:



Clarification Form(s)? Yes No Clarification Form Page No. (s): _____

REVISION _____

POSTFLIGHT OBSERVATION RECORD (PFOR) A-6
Aft Segment Liner Pattern (Data Collection Only)

Motor No.: 360T026	Side: Left (A)	Date: 11-11-92
--------------------	----------------	----------------

Assessment Engineer(s)/Inspector(s):

Sketch Aft Segment Liner Pattern Observations Below:

	FORWARD FACING NBR INHIBITOR	FACTORY JOINT <88.4>	FACTORY JOINT <208.4>	FACTORY JOINT <328.5>	AFT FACE OF AFT DOME
180°					
90°					
0°					
270°					
180°					

<Location From End of Clevis>

AFT LOOKING FORWARD

Heavy Liner

Light (spotty) Liner

No Liner

Clevis End

Clarification Form(s)? Yes No Clarification Form Page No.(s): 2/A

REVISION A

Thiokol CORPORATION
SPACE OPERATIONS

TWR-50051
Revision A

POSTFLIGHT OBSERVATION RECORD (PFOR) A-5
Aft Center Segment Liner Pattern (Data Collection Only)


Motor No.: RSRM-26

Side: Left (A) Right (B)

Date: April 6, 1993

Assessment Engineer(s)/Inspector(s): Reo Mackley

Sketch Aft Center Segment Liner Pattern Observations Below: * RESULTS OF SPECIAL ISSUE
3.1.1.1 :



Clarification Form(s)? Yes No

Clarification Form Page No.(s): _____

REVISION _____

DOC NO. TWR-64204
SEC _____

VOL _____
PAGE A-11

POSTFLIGHT OBSERVATION RECORD (PFOR) A-8
Igniter Nozzle Insert Throat Diameter Measurements (Data Collection Only)

Motor No.: 360T026	Side: Right (B)	Date: 10/20/92
--------------------	-----------------	----------------

Assessment Engineer(s)/Inspector(s): Carnell Johnson

Record the Igniter Nozzle Insert Throat Diameter Measurements Below:

Degree Location	Diameter Measurement (inches)
0	<u>6.435</u>
60	<u>6.421</u>
120	<u>6.439</u>

Notes / Comments None

Clarification Form(s)? Yes No Clarification Form Page No. (s): _____



Appendix B Case, Seals, and Joints PFORs

Final Postflight Hardware Evaluation Report 360T026 (RSRM-26, STS-47)

April 1993

Prepared for:

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION
GEORGE C. MARSHALL SPACE FLIGHT CENTER
MARSHALL SPACE FLIGHT CENTER, ALABAMA 35812

Contract No.	NAS8-38100
DR No.	4-23
WBS No.	4C601-04-01
ECS No.	SS4769

Thiokol CORPORATION
SPACE OPERATIONS

P.O. Box 707, Brigham City, Utah 84302-0707 (801) 863-3511



CASE, SEALS, AND JOINTS REQUIRED PFOR LIST

<u>PFOR #</u>	<u>Title</u>	<u>Side</u>	<u>Joint or Location</u>	<u>Final Report Page Number</u>
B-2	S&A Device (Barrier-Booster and Environmental Seal Region) Condition	Left	S&A	B-1
B-7	S&A Rotor Shaft O-ring Condition (Detailed)	Left	S&A	B-2
B-1	Leak Check Plug/SII and Port Condition (At Removal)	Left	S&A 126°	B-3
B-4	Leak Check Plug/SII Condition (Detailed)	Left	S&A 126°	B-4
B-6	Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)	Left	S&A 126°	B-5
B-1	Leak Check Plug/SII and Port Condition (At Removal)	Left	S&A 306°	B-6
B-4	Leak Check Plug/SII Condition (Detailed)	Left	S&A 306°	B-7
B-6	Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)	Left	S&A 306°	B-8
B-1	Leak Check Plug/SII and Port Condition (At Removal)	Left	18° SII	B-9
B-4	Leak Check Plug/SII Condition (Detailed)	Left	18° SII	B-10
B-6	Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)	Left	18° SII	B-11
B-1	Leak Check Plug/SII and Port Condition (At Removal)	Left	198° SII	B-12
B-4	Leak Check Plug/SII Condition (Detailed)	Left	198° SII	B-13
B-6	Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)	Left	198° SII	B-14

(Note: Clarification forms will be inserted after the required PFOR in the Final Report. The clarification form page number will be the same as the required PFOR Final Report page number appended by a sequential alphabetic extension.)

CASE, SEALS, AND JOINTS REQUIRED LIST (Cont.)

<u>PFOR #</u>	<u>Title</u>	<u>Side</u>	<u>Joint or Location</u>	<u>Final Report Page Number</u>
B-3	Internal Nozzle Joint Condition	Left	Nozzle Joint #2	B-15
B-5	Large Diameter (Joint) O-ring Condition (Detailed)	Left	Nozzle Joint #2	B-16
B-1	Leak Check Plug/SII and Port Condition (At Removal)	Left	Nozzle Joint #2	B-17
B-4	Leak Check Plug/SII Condition (Detailed)	Left	Nozzle Joint #2	B-18
B-6	Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)	Left	Nozzle Joint #2	B-19
B-3	Internal Nozzle Joint Condition	Left	Nozzle Joint #3	B-20
B-5	Large Diameter (Joint) O-ring Condition (Detailed)	Left	Nozzle Joint #3	B-21
B-1	Leak Check Plug/SII and Port Condition (At Removal)	Left	Nozzle Joint #3	B-22
B-4	Leak Check Plug/SII Condition (Detailed)	Left	Nozzle Joint #3	B-23
B-6	Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)	Left	Nozzle Joint #3	B-24
B-3	Internal Nozzle Joint Condition	Left	Nozzle Joint #4	B-25
B-5	Large Diameter (Joint) O-ring Condition (Detailed)	Left	Nozzle Joint #4	B-26
B-1	Leak Check Plug/SII and Port Condition (At Removal)	Left	Nozzle Joint #4	B-27
B-4	Leak Check Plug/SII Condition (Detailed)	Left	Nozzle Joint #4	B-28
B-6	Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)	Left	Nozzle Joint #4	B-29

(Note: Clarification forms will be inserted after the required PFOR in the Final Report. The clarification form page number will be the same as the required PFOR Final Report page number appended by a sequential alphabetic extension.)

CASE, SEALS, AND JOINTS REQUIRED LIST (Cont.)

<u>PFOR #</u>	<u>Title</u>	<u>Side</u>	<u>Joint or Location</u>	<u>Final Report Page Number</u>
B-3	Internal Nozzle Joint Condition	Left	Nozzle Joint #5	B-30
B-5	Large Diameter (Joint) O-ring Condition (Detailed)	Left	Nozzle Joint #5	B-31
B-1	Leak Check Plug/SII and Port Condition (At Removal)	Left	Nozzle Joint #5	B-32
B-4	Leak Check Plug/SII Condition (Detailed)	Left	Nozzle Joint #5	B-33
B-6	Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)	Left	Nozzle Joint #5	B-34
B-8	Packing With Retainer Condition (Detailed)	Left	Nozzle Fixed Housing	B-35
B-9	Case Factory Joint Condition	Left	Forward Dome	B-36
B-9	Case Factory Joint Condition	Left	Forward	B-37
B-9	Case Factory Joint Condition	Left	Forward Center	B-38
B-9	Case Factory Joint Condition	Left	Aft Center	B-39
B-9	Case Factory Joint Condition	Left	ET Attach/ Stiffener	B-40
B-9	Case Factory Joint Condition	Left	Stiffener/ Stiffener	B-41
B-9	Case Factory Joint Condition	Left	Aft Dome	B-42

(Note: Clarification forms will be inserted after the required PFOR in the Final Report. The clarification form page number will be the same as the required PFOR Final Report page number appended by a sequential alphabetic extension.)

CASE, SEALS, AND JOINTS REQUIRED LIST (Cont.)

<u>PFOR #</u>	<u>Title</u>	<u>Side</u>	<u>Joint or Location</u>	<u>Final Report Page Number</u>
B-2	S&A Device (Barrier-Booster and Environmental Seal Region) Condition	Right	S&A	B-43
B-7	S&A Rotor Shaft O-ring Condition (Detailed)	Right	S&A	B-44
B-1	Leak Check Plug/SII and Port Condition (At Removal)	Right	S&A 126°	B-45
B-4	Leak Check Plug/SII Condition (Detailed)	Right	S&A 126°	B-46
B-6	Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)	Right	S&A 126°	B-47
B-1	Leak Check Plug/SII and Port Condition (At Removal)	Right	S&A 306°	B-48
B-4	Leak Check Plug/SII Condition (Detailed)	Right	S&A 306°	B-49
B-6	Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)	Right	S&A 306°	B-50
B-1	Leak Check Plug/SII and Port Condition (At Removal)	Right	18° SII	B-51
B-4	Leak Check Plug/SII Condition (Detailed)	Right	18° SII	B-52
B-6	Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)	Right	18° SII	B-53
B-1	Leak Check Plug/SII and Port Condition (At Removal)	Right	198° SII	B-54
B-4	Leak Check Plug/SII Condition (Detailed)	Right	198° SII	B-55
B-6	Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)	Right	198° SII	B-56

(Note: Clarification forms will be inserted after the required PFOR in the Final Report. The clarification form page number will be the same as the required PFOR Final Report page number appended by a sequential alphabetic extension.)

CASE, SEALS, AND JOINTS REQUIRED LIST (Cont.)

<u>PFOR #</u>	<u>Title</u>	<u>Side</u>	<u>Joint or Location</u>	<u>Final Report Page Number</u>
B-3	Internal Nozzle Joint Condition	Right	Nozzle Joint #2	B-57
B-5	Large Diameter (Joint) O-ring Condition (Detailed)	Right	Nozzle Joint #2	B-58
B-1	Leak Check Plug/SII and Port Condition (At Removal)	Right	Nozzle Joint #2	B-59
B-4	Leak Check Plug/SII Condition (Detailed)	Right	Nozzle Joint #2	B-60
B-6	Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)	Right	Nozzle Joint #2	B-61
B-3	Internal Nozzle Joint Condition	Right	Nozzle Joint #3	B-62
B-5	Large Diameter (Joint) O-ring Condition (Detailed)	Right	Nozzle Joint #3	B-63
B-1	Leak Check Plug/SII and Port Condition (At Removal)	Right	Nozzle Joint #3	B-64
B-4	Leak Check Plug/SII Condition (Detailed)	Right	Nozzle Joint #3	B-65
B-6	Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)	Right	Nozzle Joint #3	B-66
B-3	Internal Nozzle Joint Condition	Right	Nozzle Joint #4	B-67
B-5	Large Diameter (Joint) O-ring Condition (Detailed)	Right	Nozzle Joint #4	B-68
B-1	Leak Check Plug/SII and Port Condition (At Removal)	Right	Nozzle Joint #4	B-69
B-4	Leak Check Plug/SII Condition (Detailed)	Right	Nozzle Joint #4	B-70
B-6	Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)	Right	Nozzle Joint #4	B-71

(Note: Clarification forms will be inserted after the required PFOR in the Final Report. The clarification form page number will be the same as the required PFOR Final Report page number appended by a sequential alphabetic extension.)

CASE, SEALS, AND JOINTS REQUIRED LIST (Cont.)

<u>PFOR #</u>	<u>Title</u>	<u>Side</u>	<u>Joint or Location</u>	<u>Final Report Page Number</u>
B-3	Internal Nozzle Joint Condition	Right	Nozzle Joint #5	B-72
B-5	Large Diameter (Joint) O-ring Condition (Detailed)	Right	Nozzle Joint #5	B-73
B-1	Leak Check Plug/SII and Port Condition (At Removal)	Right	Nozzle Joint #5	B-74
B-4	Leak Check Plug/SII Condition (Detailed)	Right	Nozzle Joint #5	B-75
B-6	Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)	Right	Nozzle Joint #5	B-76
B-8	Packing With Retainer Condition (Detailed)	Right	Nozzle Fixed Housing	B-77
B-9	Case Factory Joint Condition	Right	Forward Dome	B-78
B-9	Case Factory Joint Condition	Right	Forward	B-79
B-9	Case Factory Joint Condition	Right	Forward Center	B-80
B-9	Case Factory Joint Condition	Right	Aft Center	B-81
B-9	Case Factory Joint Condition	Right	ET Attach/ Stiffener	B-82
B-9	Case Factory Joint Condition	Right	Stiffener/ Stiffener	B-83
B-9	Case Factory Joint Condition	Right	Aft Dome	B-84

(Note: Clarification forms will be inserted after the required PFOR in the Final Report. The clarification form page number will be the same as the required PFOR Final Report page number appended by a sequential alphabetic extension.)

POSTFLIGHT OBSERVATION RECORD (PFOR) B-2
S&A Device (Barrier-Booster and Environmental Seal Regions) Condition

Motor No.: 360T026	Side: Left (A)	Date: 10-1-92
--------------------	----------------	---------------

Assessment Engineer(s)/Inspector(s): P. Albright, D. Bartelt, G. Neilson, D. Bullard

<u>Barrier-Booster Bore and Rotor Observations:</u>	Yes	No	Comment #
A. Heat Affected or Eroded O-ring (In Groove)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____
B. Soot To or Past O-rings?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
C. Heat Affected Metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____
D. O-ring Damage (In Groove)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____
E. Metal Damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____
F. Excessive or No Grease?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____
G. Corrosion?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____
H. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____
I. Teflon Retainer Damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____
 <u>Environmental Seal Region Observations:</u>			
J. Environmental O-ring Assembly Damage (Visible Without Magnification)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____
K. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____

Notes / Comments

Special Issues 3.2.3.1

1) Soot up to but not past the Fwd Rotor Primary O-ring.

Note: Special Issues 3.2.3.1 — Barrier-Booster rotor detent ball spring is being evaluated for corrosion by M&P.

Preliminary PFAR(s)?	_____ Yes	<input checked="" type="checkbox"/> No	Preliminary PFAR Number(s): _____
Clarification Form(s)?	_____ Yes	<input checked="" type="checkbox"/> No	Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-7
S&A Rotor Shaft O-ring Condition (Detailed)

Motor No.: 360T026	Side: Left (A)	Date: 10-1-92	
Assessment Engineer(s)/Inspector(s): P. Albright, D. Bartelt, G. Neilson, D. Bullard, D. Barecht			
Location: S&A Device Barrier-Booster Rotor Shaft			
<u>Forward Primary O-ring Observations:</u>			
A. Heat Affected or Eroded O-ring?	Yes _____ _____	No ↓ _____ _____	Comment # _____ _____
B. O-ring Defects/Damage?	_____ _____	↓ _____ _____	_____ _____
<u>Aft Primary O-ring Observations:</u>			
C. Heat Affected or Eroded O-ring?	_____ _____	↓ _____ _____	_____ _____
D. O-ring Defects/Damage?	_____ _____	↓ _____ _____	_____ _____
<u>Forward Secondary O-ring Observations:</u>			
E. Heat Affected or Eroded O-ring?	_____ _____	↓ _____ _____	_____ _____
F. O-ring Defects/Damage?	_____ _____	↓ _____ _____	_____ _____
<u>Aft Secondary O-ring Observations:</u>			
G. Heat Affected or Eroded O-ring?	_____ _____	↓ _____ _____	_____ _____
H. O-ring Defects/Damage?	_____ _____	↓ _____ _____	_____ _____

Notes / Comments

Preliminary PFAR(s)? ____ Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? ____ Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-1
Leak Check Plug/Sil and Port Condition (At Removal)

Motor No.: 360T026	Side: Left (A)	Date: 1 oct 92
Assessment Engineer(s)/Inspector(s): Robert Briggs, Phil Albright, MARRV Lyon, Doug Bullard		
Location: 126-Degree Barrier-Booster Bore		

Leak Check Plug Observations:

- A. Sooted Metal Surfaces?
- B. Soot To or Past O-ring?
- C. Foreign Material?
- D. O-ring Damage (In Groove)?
- E. Heat Affected or Eroded O-ring (In Groove)?
- F. Excessive or No Grease on O-ring?
- G. Excessive Grease on Plug?
- H. Corrosion?
- I. Thread Damage (Visible at Removal)?

Yes

No

Comment #

_____	_____	
_____	_____	
_____	_____	
_____	_____	
_____	_____	
_____	_____	
_____	_____	
_____	_____	
_____	_____	

Leak Check Port Observations:

- J. Sooted Metal Surfaces?
- K. Foreign Material?
- L. Excessive Grease?
- M. Corrosion?
- N. Metal Damage?
- O. Heat Affected Metal?
- P. Obstructed Through Hole?

_____	_____	
_____	_____	
_____	_____	
_____	_____	
_____	_____	
_____	_____	
_____	_____	

Notes / Comments

Preliminary PFAR(s)? _____ Yes No

Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No

Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-4
Leak Check Plug/SII Condition (Detailed)

Motor No.: 360T026	Side: Left (A)	Date: 1 Oct 92
Assessment Engineer(s)/Inspector(s): Robert Briggs, MARV Lyon, Doug Bullard, Diane ^{Garrett}		
Location: 126-Degree Barrier-Booster Bore		
<u>Leak Check Plug Observations:</u>	Yes	No
A. Foreign Material Between the O-ring and Plug?	_____	_____ <input checked="" type="checkbox"/>
B. Heat Affected Metal?	_____	_____ <input checked="" type="checkbox"/>
C. Seal Surface/Thread Damage?	_____	_____ <input checked="" type="checkbox"/>
Comment #		

Notes / Comments

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-4
Leak Check Plug/SII Condition (Detailed)

Motor No.: 360T026	Side: Left (A)	Date: 1 Oct 92
Assessment Engineer(s)/Inspector(s): Robert Briggs, MERV LYON, Doug Bullard ^{Diane} _{Garecht}		
Location: 306-Degree Barrier-Booster Flange		

Leak Check Plug Observations:	Yes	No	Comment #
A. Foreign Material Between the O-ring and Plug?	_____	_____/_____ ✓	_____
B. Heat Affected Metal?	_____	_____/_____ ✓	_____
C. Seal Surface/Thread Damage?	_____	_____/_____ ✓	_____

Notes / Comments

Preliminary PFAR(s)? _____ Yes ✓ No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes ✓ No Clarification Form Page No.(s): _____


POSTFLIGHT OBSERVATION RECORD (PFOR) B-6
Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)

Motor No.: 360T026	Side: Left (A)	Date: 1 Oct 92
Assessment Engineer(s)/Inspector(s): Robert Briggs, MARV Lyon, Doug Bullard ^{D.O.B} Garach		
Location: 306-Degree Barrier-Booster Flange		
<u>Secondary O-ring Observations:</u>	Yes	No
A. Heat Affected or Eroded O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
B. O-ring Defects/Damage?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
		Comment # 1

Notes / Comments

1) A scratch observed on the 306° O-ring.
Cut measured: Depth = undetermined.
Width = 0.025 inch approximately

Photo # 130563-1



Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): 47C-14

Clarification Form(s)? Yes No Clarification Form Page No.(s):

POSTFLIGHT OBSERVATION RECORD (PFOR) B-1
Leak Check Plug/SII and Port Condition (At Removal)

Motor No.: 360T026	Side: Left (A)	Date: 1 Oct 92
Assessment Engineer(s)/Inspector(s): Robert Briggs, MRV Lyon, Doug Bullard, ^{Diane} Barrett		
Location: 18-Degree SII		

SII Observations:

	Yes	No	Comment #
A. Sooted Metal Surfaces?	✓		#1
B. Soot To or Past O-ring?		✓	
C. Foreign Material?		✓	
D. O-ring Damage (In Groove)?		✓	
E. Heat Affected or Eroded O-ring (In Groove)?		✓	
F. Excessive or No Grease on O-ring?		✓	
G. Excessive Grease on SII?		✓	
H. Corrosion?		✓	
I. Thread Damage (Visible at Removal)?		✓	

SII Port Observations:

J. Sooted Metal Surfaces?	✓		#1
K. Foreign Material?		✓	
L. Excessive Grease?		✓	
M. Corrosion?		✓	
N. Metal Damage?		✓	2
O. Heat Affected Metal?		✓	
P. Obstructed Leak Check Through Hole?		✓	

Notes / Comments

1) Soot on the tip of the plug.
2) Typical galling on land between primary and secondary seal surfaces.

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-4
Leak Check Plug/SII Condition (Detailed)

Motor No.: 360T026	Side: Left (A)	Date: 1 Oct 92
Assessment Engineer(s)/Inspector(s): MARV LYON, Robert Briggs, Doug Bullard ^{Drone} Gorecki		
Location: 18-Degree SII		
SII Observations:	Yes	No
A. Foreign Material Between the O-ring and SII?	_____	✓ _____
B. Heat Affected Metal?	_____	✓ _____
C. Seal Surface/Thread Damage?	_____	✓ _____
Comment # _____ _____ _____		

Notes / Comments

Preliminary PFAR(s)? _____ Yes No _____ Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No _____ Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-6
Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)

Motor No.: 360T026	Side: Left (A)	Date: 1 Oct 92	
Assessment Engineer(s)/Inspector(s): Robert Briggs, MARV Lyon, Doug Bullard ^{Diane} Garecht			
Location: 18-Degree SII			
<u>Primary O-ring Observations:</u>	Yes	No	Comment #
A. Heat Affected or Eroded O-ring?	_____	✓ _____	_____
B. O-ring Defects/Damage?	_____	✓ _____	_____
<u>Secondary O-ring Observations:</u>			
C. Heat Affected or Eroded O-ring?	_____	✓ _____	_____
D. O-ring Defects/Damage?	_____	✓ _____	_____
Notes / Comments			

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-1
Leak Check Plug/SII and Port Condition (At Removal)

Motor No.: 360T026	Side: Left (A)	Date: 1 Oct 92
Assessment Engineer(s)/Inspector(s): Robert Briggs, MARV LYON, Doug Bullard, Diane Garecht		
Location: 198-Degree SII		

SII Observations:

	Yes	No	Comment #
A. Sooted Metal Surfaces?	✓		#1
B. Soot To or Past O-ring?		✓	
C. Foreign Material?		✓	
D. O-ring Damage (In Groove)?		✓	
E. Heat Affected or Eroded O-ring (In Groove)?		✓	
F. Excessive or No Grease on O-ring?		✓	
G. Excessive Grease on SII?		✓	
H. Corrosion?		✓	
I. Thread Damage (Visible at Removal)?		✓	

SII Port Observations:

J. Sooted Metal Surfaces?	✓		#1
K. Foreign Material?		✓	
L. Excessive Grease?		✓	
M. Corrosion?		✓	
N. Metal Damage?		✓	
O. Heat Affected Metal?		✓	2
P. Obstructed Leak Check Through Hole?		✓	

Notes / Comments

- 1) Soot on the tip of the plug.
- 2) Typical galling on land between primary and secondary seal surfaces.

Preliminary PFAR(s)? ___ Yes No

Preliminary PFAR Number(s): _____

Clarification Form(s)? ___ Yes No

Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-3
Internal Nozzle Joint Condition

Motor No.: 360T026	Side: Left (A)	Date: 9.30.92
Assessment Engineer(s)/Inspector(s): W. Sperry, D. Bartelt		
Joint: Nose Inlet-to-Flex Bearing-to-Cowl (Joint #2)		

Internal Nozzle Joint Observations:	Yes	No	Comment #
A. Soot To or Past O-rings?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
B. Heat Affected Metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
C. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
D. RTV in Contact With or Past the Primary O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
E. O-ring Damage (In Groove)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
F. Heat Affected or Eroded O-rings (In Groove)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
G. Excessive or No Grease?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
H. Corrosion?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3
I. Metal Damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments

① Typical scalloped shaped soot between bolt holes on nose inlet. Soot reached primary O-ring intermittently from 195° to 345°. ^{Forward} end ring.

② Typical Burnishing on nose inlet secondary seal surface intermittently.

③ Light-to-medium corrosion in the scalloped soot region of the forward end ring intermittently.

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-5
Large Diameter (Joint) O-ring Condition (Detailed)

Motor No.: 360T026	Side: Left (A)	Date: 9-30-92	
Assessment Engineer(s)/Inspector(s): <i>W. Sperry, D. Bartelt</i>			
Joint: Nose Inlet-to-Flex Bearing-to-Cowl (Joint #2)			
<u>Primary O-ring Observations:</u>	Yes	No	Comment #
A. Heat Affected or Eroded O-ring?	_____	_____/_____ ✓	_____
B. O-ring Damage/Defects?	_____	_____/_____ ✓	_____
<u>Secondary O-ring Observations:</u>			
A. Heat Affected or Eroded O-ring?	_____	_____/_____ ✓	_____
B. O-ring Damage/Defects?	_____	_____/_____ ✓	_____
Notes / Comments			

Preliminary PFAR(s)? _____ Yes _____ No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes _____ No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-1
Leak Check Plug/SII and Port Condition (At Removal)

Motor No.: 360T026	Side: Left (A)	Date: 9-30-92
Assessment Engineer(s)/Inspector(s): W. Sperry, D. Bartelt		
Location: Nose Inlet-to-Flex Bearing-to-Cowl (Joint #2)		

<u>Leak Check Plug Observations:</u>	Yes	No	Comment #
A. Sooted Metal Surfaces?	_____	✓	_____
B. Soot To or Past O-ring?	_____	✓	_____
C. Foreign Material?	_____	✓	_____
D. O-ring Damage (In Groove)?	_____	✓	_____
E. Heat Affected or Eroded O-ring (In Groove)?	_____	✓	_____
F. Excessive or No Grease on O-ring?	_____	✓	_____
G. Excessive Grease on Plug?	_____	✓	_____
H. Corrosion?	_____	✓	_____
I. Thread Damage (Visible at Removal)?	_____	✓	_____
 <u>Leak Check Port Observations:</u>			
J. Sooted Metal Surfaces?	_____	✓	_____
K. Foreign Material?	_____	✓	_____
L. Excessive Grease?	_____	✓	_____
M. Corrosion?	_____	✓	_____
N. Metal Damage?	_____	✓	_____
O. Heat Affected Metal?	_____	✓	_____
P. Obstructed Through Hole?	_____	✓	_____

Notes / Comments

Break away 35 in. lbs
Running 20 in. lbs.

Preliminary PFAR(s)? ___ Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? ___ Yes No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-4
Leak Check Plug/SII Condition (Detailed)

Motor No.: 360T026	Side: Left (A)	Date: 9-30-92
Assessment Engineer(s)/Inspector(s): <i>W. Sperry, D. Bartelt</i>		
Location: Nose Inlet-to-Flex Bearing-to-Cowl (Joint #2)		
<u>Leak Check Plug Observations:</u>	Yes	No
A. Foreign Material Between the O-ring and Plug?	_____	_____✓
B. Heat Affected Metal?	_____	_____✓
C. Seal Surface/Thread Damage?	_____	_____✓

Comment #

Notes / Comments

Preliminary PFAR(s)? _____ Yes _____✓ No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes _____✓ No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-3
Internal Nozzle Joint Condition

Motor No.: 360T026	Side: Left (A)	Date: 9-30-92	
Assessment Engineer(s)/Inspector(s): <i>W. Sperry, M. Lyons</i>			
Joint: Nose Inlet-to-Throat (Joint #3)			
<u>Internal Nozzle Joint Observations:</u>	Yes	No	Comment #
A. Soot To or Past O-rings?	_____	✓	_____
B. Heat Affected Metal?	_____	✓	_____
C. Foreign Material?	_____	✓	_____
D. RTV in Contact With or Past the Primary O-ring?	_____	✓	_____
E. O-ring Damage (In Groove)?	_____	✓	_____
F. Heat Affected or Eroded O-rings (In Groove)?	_____	✓	_____
G. Excessive or No Grease?	_____	✓	_____
H. Corrosion?	✓	_____	1
I. Metal Damage?	_____	✓	_____

Notes / Comments

Special Issues 3.2.3.2

No seal surface metal damage or atypical corrosion found.

① *Typical light-to-medium corrosion upstream of primary O-ring intermittent full circumference.*

Preliminary PFAR(s)? _____ Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-5
Large Diameter (Joint) O-ring Condition (Detailed)

Motor No.: 360T026	Side: Left (A)	Date: 9-30-92	
Assessment Engineer(s)/Inspector(s): <i>W. Sperry, M. Lyons</i>			
Joint: Nose Inlet-to-Throat (Joint #3)			
<u>Primary O-ring Observations:</u>	Yes	No	Comment #
A. Heat Affected or Eroded O-ring?	_____	_____/_____ ✓	_____
B. O-ring Damage/Defects?	_____	_____/_____ ✓	_____
<u>Secondary O-ring Observations:</u>			
A. Heat Affected or Eroded O-ring?	_____	_____/_____ ✓	_____
B. O-ring Damage/Defects?	_____	_____/_____ ✓	_____
Notes / Comments			

Preliminary PFAR(s)? _____ Yes _____/_____
 Clarification Form(s)? _____ Yes _____/_____ No

Preliminary PFAR Number(s): _____
 Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-1
Leak Check Plug/SII and Port Condition (At Removal)

Motor No.: 360T026	Side: Left (A)	Date: 9-30-92
Assessment Engineer(s)/Inspector(s): <i>W. Sperry, M. Lyons</i>		
Location: Nose Inlet-to-Throat (Joint #3)		

<u>Leak Check Plug Observations:</u>	Yes	No	Comment #
A. Sooted Metal Surfaces?	_____	_____/_____ ✓	_____
B. Soot To or Past O-ring?	_____	_____/_____ ✓	_____
C. Foreign Material?	_____	_____/_____ ✓	_____
D. O-ring Damage (In Groove)?	_____	_____/_____ ✓	_____
E. Heat Affected or Eroded O-ring (In Groove)?	_____	_____/_____ ✓	_____
F. Excessive or No Grease on O-ring?	_____	_____/_____ ✓	_____
G. Excessive Grease on Plug?	_____	_____/_____ ✓	_____
H. Corrosion?	_____	_____/_____ ✓	_____
I. Thread Damage (Visible at Removal)?	_____	_____/_____ ✓	_____
 <u>Leak Check Port Observations:</u>			
J. Sooted Metal Surfaces?	_____	_____/_____ ✓	_____
K. Foreign Material?	_____	_____/_____ ✓	_____
L. Excessive Grease?	_____	_____/_____ ✓	_____
M. Corrosion?	_____	_____/_____ ✓	_____
N. Metal Damage?	_____	_____/_____ ✓	_____
O. Heat Affected Metal?	_____	_____/_____ ✓	_____
P. Obstructed Through Hole?	_____	_____/_____ ✓	_____

Notes / Comments

Breakaway 36 in. lbs

Running 23 in. lbs

Preliminary PFAR(s)? _____ Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-4
Leak Check Plug/SII Condition: (Detailed)

Motor No.: 360T026	Side: Left (A)	Date: 9-30-92	
Assessment Engineer(s)/Inspector(s): <i>W. Sperry, M. Lyons</i>			
Location: Nose Inlet-to-Throat (Joint #3)			
<u>Leak Check Plug Observations:</u>	Yes	No	Comment #
A. Foreign Material Between the O-ring and Plug?	_____	_____/_____ ✓	_____
B. Heat Affected Metal?	_____	_____/_____ ✓	_____
C. Seal Surface/Thread Damage?	_____	_____/_____ ✓	_____

Notes / Comments

Preliminary PFAR(s)? _____ Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No Clarification Form Page No. (s): _____

5315

POSTFLIGHT OBSERVATION RECORD (PFOR) B-3
Internal Nozzle Joint Condition

Motor No.: 360T026	Side: Left (A)	Date: 9-29-92
Assessment Engineer(s)/Inspector(s): <i>A. Masciotti, D. Bertelt</i>		
Joint: Throat-to-Forward Exit Cone (Joint #4)		

Internal Nozzle Joint Observations:	Yes	No	Comment #
A. Soot To or Past O-rings?	_____	✓	_____
B. Heat Affected Metal?	_____	✓	_____
C. Foreign Material?	✓	_____	1
D. RTV in Contact With or Past the Primary O-ring?	_____	✓	_____
E. O-ring Damage (In Groove)?	_____	✓	_____
F. Heat Affected or Eroded O-rings (In Groove)?	_____	✓	_____
G. Excessive or No Grease?	_____	✓	_____
H. Corrosion?	✓	_____	2
I. Metal Damage?	_____	✓	_____

Notes / Comments

Special Issues 3.2.3.2 *N/A*

1. Foreign material on primary seal surface of both mating surfaces. The foreign material on the F.E.C. is black and flaky. It appears to have been pressed into the groove by the O-ring at 23-30°. The material resembles soot. Loose black material was seen in the groove intermittently full circumference. The loose material is believed to be due to disassembly/splashedown.

The mating surfaces on the throat primary seal surface had the black material and ~~slip-like materials~~ intermittently full circumference. Slip-like material was seen on the primary at 28° & 30°

2. Medium corrosion was observed on secondary seal ^{surface} and between primary and secondary seals intermittently 235-270° on the F.E.C. and mating surface of the throat. Medium corrosion was also observed inboard of primary seal on the throat housing int. full circum. Light corrosion between primary and secondary seals full circumference on mating metal surfaces

Special Issue: 3.2.3.2 : No metal damage was observed on the seal surfaces and corrosion was typical as described in comment #2.

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): 476-03

Clarification Form(s)? Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-1
Leak Check Plug/Sil and Port Condition (At Removal)

Motor No.: 360T026	Side: Left (A)	Date: 9-29-92
Assessment Engineer(s)/Inspector(s): <i>A. Mariani, D. Burtell</i>		
Location: Throat-to-Forward Exit Cone (Joint #4)		

<u>Leak Check Plug Observations:</u>	Yes	No	Comment #
A. Sooted Metal Surfaces?	_____	✓	_____
B. Soot To or Past O-ring?	_____	✓	_____
C. Foreign Material?	_____	✓	_____
D. O-ring Damage (In Groove)?	_____	✓	_____
E. Heat Affected or Eroded O-ring (In Groove)?	_____	✓	_____
F. Excessive or No Grease on O-ring?	_____	✓	_____
G. Excessive Grease on Plug?	_____	✓	_____
H. Corrosion?	_____	✓	_____
I. Thread Damage (Visible at Removal)?	_____	✓	_____
 <u>Leak Check Port Observations:</u>			
J. Sooted Metal Surfaces?	_____	✓	_____
K. Foreign Material?	_____	✓	_____
L. Excessive Grease?	_____	✓	_____
M. Corrosion?	_____	✓	_____
N. Metal Damage?	_____	✓	_____
O. Heat Affected Metal?	_____	✓	_____
P. Obstructed Through Hole?	_____	✓	_____

Notes / Comments

Break torque: 28 ft-lbs
Running torque: 15 ft-lbs

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-3
Internal Nozzle Joint Condition

Motor No.: 360T026	Side: Left (A)	Date: 9-29-92
Assessment Engineer(s)/Inspector(s): <i>A. MacCitt, M. Lyon</i>		
Joint: Aft End Ring-to-Fixed Housing (Joint #5)		

Internal Nozzle Joint Observations:	Yes	No	Comment #
A. Soot To or Past O-rings?	_____	✓	_____
B. Heat Affected Metal?	_____	✓	_____
C. Foreign Material?	✓	_____	1
D. RTV in Contact With or Past the Primary O-ring?	_____	✓	_____
E. O-ring Damage (In Groove)?	_____	✓	_____
F. Heat Affected or Eroded O-rings (In Groove)?	_____	✓	_____
G. Excessive or No Grease?	_____	✓	_____
H. Corrosion?	✓	_____	2
I. Metal Damage?	_____	✓	_____

Notes / Comments

1. Nyllok on primary O-ring. Nyllok was on downstream edge of O-ring. The Nyllok is a foreign material on the O-ring. The foreign material did not bridge the footprint. A PFAR was written. Pictures were taken. The time of occurrence could not be identified. The location of the Nyllok was 235°.

2. Heavy to medium corrosion on the aft end ring flange intermittently full circumference. Medium corrosion on the mating surface of the fixed housing.

Medium corrosion inboard of the secondary seal surface intermittently full circumference on the aft end ring and fixed housing.

Preliminary PFAR(s) Yes No Preliminary PFAR Number(s): 47C-04

Clarification Form(s)? Yes No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-1
Leak Check Plug/SII and Port Condition (At Removal)

Motor No.: 360T026	Side: Left (A)	Date: 29 Sept 1992
Assessment Engineer(s)/Inspector(s): ART MARRIOTT, MARVIN LYON		
Location: Aft End Ring-to-Fixed Housing (Joint #5)		

<u>Leak Check Plug Observations:</u>	Yes	No	Comment #
A. Sooted Metal Surfaces?	_____	✓	_____
B. Soot To or Past O-ring?	_____	✓	_____
C. Foreign Material?	_____	✓	_____
D. O-ring Damage (In Groove)?	_____	✓	_____
E. Heat Affected or Eroded O-ring (In Groove)?	_____	✓	_____
F. Excessive or No Grease on O-ring?	_____	✓	_____
G. Excessive Grease on Plug?	_____	✓	_____
H. Corrosion?	_____	✓	_____
I. Thread Damage (Visible at Removal)?	_____	✓	_____
 <u>Leak Check Port Observations:</u>			
J. Sooted Metal Surfaces?	_____	✓	_____
K. Foreign Material?	_____	✓	_____
L. Excessive Grease?	_____	✓	_____
M. Corrosion?	✓	_____	1
N. Metal Damage?	_____	✓	_____
O. Heat Affected Metal?	_____	✓	_____
P. Obstructed Through Hole?	_____	✓	_____

Notes / Comments
 Break Torque 39 ft-lbs
 Running Torque 12 ft-lbs.
 #1. Light corrosion ^{on plug} outside of O-RING.

Preliminary PFAR(s)? _____ Yes _____ No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes _____ No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-4
Leak Check Plug/SII Condition (Detailed)

Motor No.: 360T026	Side: Left (A)	Date: 29 Sept 1992
Assessment Engineer(s)/Inspector(s): ART MARRIOTT, MERVIN LYON		
Location: Aft End Ring-to-Fixed Housing (Joint #5)		
<u>Leak Check Plug Observations:</u> A. Foreign Material Between the O-ring and Plug? B. Heat Affected Metal? C. Seal Surface/Thread Damage?	Yes _____ _____ _____	No ✓ ✓ ✓
		Comment # _____ _____ _____

Notes / Comments

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-6
Small Diameter (Leak Check Plug/Sil) O-ring Condition (Detailed)

Motor No.: 360T026	Side: Left (A)	Date: 29 Sept 1992
Assessment Engineer(s)/Inspector(s): ART MARRIOT, MARVIN LYON		
Location: Aft End Ring-to-Fixed Housing (Joint #5)		
<u>Secondary O-ring Observations:</u>	Yes	No
A. Heat Affected or Eroded O-ring?	_____	_____/_____ ✓
B. O-ring Defects/Damage?	_____	_____/_____ ✓
		Comment # _____

Notes / Comments

Preliminary PFAR(s)? _____ Yes _____ No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes _____ No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-8
Packing With Retainer Condition (Detailed)

Motor No.: 360T026	Side: Left (A)	Date: 29 Sept 1992	
Assessment Engineer(s)/Inspector(s): ART MARRIOT, DAVE BARTELT			
Joint: Aft End Ring-to-Fixed Housing (Joint #5)			
<u>Packing With Retainer Observations:</u>	Yes	No	Comment #
A. Heat Affected or Eroded Seal or Retainer?	_____	✓	_____
B. Seal or Retainer Damage/Defects?	✓	_____	1
C. Corrosion?	_____	✓	_____

Notes / Comments

/ 72 of 72 PACKING WITH RETAINERS HAD SEAL DAMAGE.

Preliminary PFAR(s)? _____ Yes _____ ✓ No

Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes _____ ✓ No

Clarification Form Page No. (s): _____

REVISION _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-9
Case Factory Joint Condition

Motor No.: 360T026	Side: Left (A)	Date: 1-22-93
Assessment Engineer(s)/Inspector(s): HENRY ZAREMBA		
Factory Joint: Forward Dome		
Case Factory Joint Observations:		
	Yes	No
A. Heat Affected or Eroded Joint O-ring?	_____	_____X_____
B. Heavy Corrosion in Joint?	_____X_____	_____
C. Heavy Corrosion in Leak Check Port?	_____	_____X_____
<p>Comment #</p> <p>_____</p> <p>_____1_____</p> <p>_____</p>		
<p>Note: Heavy corrosion is defined as corrosion that causes pitting. It may be necessary to remove corrosion to determine if pitting has occurred; however, care should be taken not to damage the hardware. A cloth dampened with solvent or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.</p>		
Notes / Comments		
<p>Special Issues 3.2.3.1 (Leak test plug was removed)</p> <p>#1 FRETTING AND ^{MEDIUM} HEAVY CORROSION ON FWD DOME TANG. ALSO AFT OF SECONDARY ON CLEVIS 214°-230°</p>		
<p>Preliminary PFAR(s)? _____ Yes _____ No</p> <p>Preliminary PFAR Number(s): _____</p>		
<p>Clarification Form(s)? _____ Yes _____ No</p> <p>Clarification Form Page No.(s): _____</p>		

POSTFLIGHT OBSERVATION RECORD (PFOR) B-9
Case Factory Joint Condition

Motor No.: 360T026	Side: Left (A)	Date: 1-22-93
--------------------	----------------	---------------

Assessment Engineer(s)/Inspector(s): HENRY ZAREMBA

Factory Joint: Forward

<u>Case Factory Joint Observations:</u>	Yes	No	Comment #
A. Heat Affected or Eroded Joint O-ring?	_____	X _____	_____
B. Heavy Corrosion in Joint?	_____	Y _____	_____
C. Heavy Corrosion in Leak Check Port?	_____	X _____	_____

Note: Heavy corrosion is defined as corrosion that causes pitting. It may be necessary to remove corrosion to determine if pitting has occurred; however, care should be taken not to damage the hardware. A cloth dampened with solvent or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.

Notes / Comments

Special Issues 3.2.3.3

Leak test pass was normal

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-9
Case Factory Joint Condition

Motor No.: 360T026	Side: Left (A)	Date: 4-8-93
--------------------	----------------	--------------

Assessment Engineer(s)/Inspector(s): GARY W. ASPER (R.A.)

Factory Joint: Forward Center

Case Factory Joint Observations:	Yes	No	Comment #
A. Heat Affected or Eroded Joint O-ring?	_____	✓ _____	_____
B. Heavy Corrosion in Joint?	_____	✓ _____	_____
C. Heavy Corrosion in Leak Check Port?	_____	✓ _____	_____

Note: Heavy corrosion is defined as corrosion that causes pitting. It may be necessary to remove corrosion to determine if pitting has occurred; however, care should be taken not to damage the hardware. A cloth dampened with solvent or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.

Notes / Comments

Special Issues 3.2.3.3 The Leakt test play was nominal.

N/A

Preliminary PFAR(s)? _____ Yes No _____ Preliminary PFAR Number(s): N/A

Clarification Form(s)? _____ Yes No _____ Clarification Form Page No. (s): N/A

POSTFLIGHT OBSERVATION RECORD (PFOR) B-9
Case Factory Joint Condition

Motor No.: 360T026	Side: Left (A)	Date: 3-15-93
Assessment Engineer(s)/Inspector(s): G. RICH		
Factory Joint: Aft Center		

Case Factory Joint Observations:	Yes	No	Comment #
A. Heat Affected or Eroded Joint O-ring?	_____	<input checked="" type="checkbox"/>	_____
B. Heavy Corrosion in Joint?	_____	<input checked="" type="checkbox"/>	_____
C. Heavy Corrosion in Leak Check Port?	_____	<input checked="" type="checkbox"/>	_____

Note: Heavy corrosion is defined as corrosion that causes pitting. It may be necessary to remove corrosion to determine if pitting has occurred; however, care should be taken not to damage the hardware. A cloth dampened with solvent or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.

Notes / Comments

Special Issues 3.2.3.3

Leak test play was minimal

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-9
Case Factory Joint Condition

Motor No.: 360T026	Side: Left (A)	Date: 10 FEB 1993
Assessment Engineer(s)/Inspector(s): Schenck		
Factory Joint: ET Attach/Stiffener		

Case Factory Joint Observations:	Yes	No	Comment #
A. Heat Affected or Eroded Joint O-ring?	_____	_____/_____ ✓	_____
B. Heavy Corrosion in Joint?	_____	_____/_____ ✓	_____
C. Heavy Corrosion in Leak Check Port?	_____	_____/_____ ✓	_____

Note: Heavy corrosion is defined as corrosion that causes pitting. It may be necessary to remove corrosion to determine if pitting has occurred; however, care should be taken not to damage the hardware. A cloth dampened with solvent or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.

Notes / Comments

Special Issues 3.2.3.3

LEAK TEST PLUG WAS NOMINAL

Preliminary PFAR(s)? _____ Yes _____ No <input checked="" type="checkbox"/>	Preliminary PFAR Number(s): _____
Clarification Form(s)? _____ Yes _____ No <input checked="" type="checkbox"/>	Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-9
Case Factory Joint Condition

Motor No.: 360T026	Side: Left (A)	Date: 10 FEB 1993
Assessment Engineer(s)/Inspector(s): Schenck		
Factory Joint: Stiffener/Stiffener		

Case Factory Joint Observations:	Yes	* No	Comment #
A. Heat Affected or Eroded Joint O-ring?	_____	_____/_____ ✓	_____
B. Heavy Corrosion in Joint?	_____	_____/_____ ✓	_____
C. Heavy Corrosion in Leak Check Port?	_____	_____/_____ ✓	_____

Note: Heavy corrosion is defined as corrosion that causes pitting. It may be necessary to remove corrosion to determine if pitting has occurred; however, care should be taken not to damage the hardware. A cloth dampened with solvent or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.

Notes / Comments

Special Issues 3.2.3.3

LEAK TEST PLUG WAS NOMINAL

Preliminary PFAR(s)?	_____ Yes	_____/_____ ✓ No	Preliminary PFAR Number(s): _____
Clarification Form(s)?	_____ Yes	_____/_____ ✓ No	Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-9
Case Factory Joint Condition

Motor No.: 360T026	Side: Left (A)	Date: 10 FEB 1993
Assessment Engineer(s)/Inspector(s): <u>Schenck</u>		
Factory Joint: Aft Dome		
<p><u>Case Factory Joint Observations:</u></p> <p>A. Heat Affected or Eroded Joint O-ring?</p> <p>B. Heavy Corrosion in Joint?</p> <p>C. Heavy Corrosion in Leak Check Port?</p> <p>Note: Heavy corrosion is defined as corrosion that causes pitting. It may be necessary to remove corrosion to determine if pitting has occurred; however, care should be taken not to damage the hardware. A cloth dampened with solvent or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.</p>	<p>Yes</p> <p>_____</p> <p>_____</p> <p>_____</p>	<p>No</p> <p>_____ ✓</p> <p>_____ ✓</p> <p>_____ ✓</p>
<p>Comment #</p> <p>_____</p> <p>_____</p> <p>_____</p>		

Notes / Comments

Special Issues 3.2.3.3

NO BLUE PATCH WAS NOTED. (IN LEAK TEST PLUG.

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-2
S&A Device (Barrier-Booster and Environmental Seal Regions) Condition

Motor No.: 360T026	Side: Right (B)	Date: 10-1-92
--------------------	-----------------	---------------

Assessment Engineer(s)/Inspector(s): *P. Albright, M. Lyon, R. Briggs, G. Neilson, D. Bullard,*

<u>Barrier-Booster Bore and Rotor Observations:</u>	Yes	No	Comment #
A. Heat Affected or Eroded O-ring (In Groove)?	_____	<input checked="" type="checkbox"/>	_____
B. Soot To or Past O-rings?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	1
C. Heat Affected Metal?	_____	<input checked="" type="checkbox"/>	_____
D. O-ring Damage (In Groove)?	_____	<input checked="" type="checkbox"/>	_____
E. Metal Damage?	_____	<input checked="" type="checkbox"/>	_____
F. Excessive or No Grease?	_____	<input checked="" type="checkbox"/>	_____
G. Corrosion?	_____	<input checked="" type="checkbox"/>	_____
H. Foreign Material?	_____	<input checked="" type="checkbox"/>	_____
I. Teflon Retainer Damage?	_____	<input checked="" type="checkbox"/>	_____

<u>Environmental Seal Region Observations:</u>	Yes	No	Comment #
J. Environmental O-ring Assembly Damage (Visible Without Magnification)?	_____	<input checked="" type="checkbox"/>	_____
K. Foreign Material?	_____	<input checked="" type="checkbox"/>	_____

Notes / Comments

Special Issues 3.2.3.1 - Barrier-Booster rotor detent ball spring is being evaluated for corrosion by M&P

1- Soot up to but not past the forward rotor primary O-ring.

Preliminary PFAR(s)? _____ Yes <input checked="" type="checkbox"/> No	Preliminary PFAR Number(s): _____
Clarification Form(s)? _____ Yes <input checked="" type="checkbox"/> No	Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-7
S&A Rotor Shaft O-ring Condition (Detailed)

Motor No.: 360T026	Side: Right (B)	Date: 10-1-92	
Assessment Engineer(s)/Inspector(s): P. Albright, R. Briggs, M. Lyon, G. Neilson, D. Bertelt, D. Bullard			
Location: S&A Device Barrier-Booster Rotor Shaft			
<u>Forward Primary O-ring Observations:</u>	Yes	No	Comment #
A. Heat Affected or Eroded O-ring?	_____	✓ _____	_____
B. O-ring Defects/Damage?	_____	✓ _____	_____
<u>Aft Primary O-ring Observations:</u>			
C. Heat Affected or Eroded O-ring?	_____	✓ _____	_____
D. O-ring Defects/Damage?	_____	✓ _____	_____
<u>Forward Secondary O-ring Observations:</u>			
E. Heat Affected or Eroded O-ring?	_____	✓ _____	_____
F. O-ring Defects/Damage?	_____	✓ _____	_____
<u>Aft Secondary O-ring Observations:</u>			
G. Heat Affected or Eroded O-ring?	_____	✓ _____	_____
H. O-ring Defects/Damage?	_____	✓ _____	_____

Notes / Comments

Preliminary PFAR(s)? _____ Yes ✓ No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes ✓ No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-6
Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)

Motor No.: 360T026	Side: Right (B)	Date: 10-1-92
Assessment Engineer(s)/Inspector(s): P. Albright, D. Bartelt, G. Neilson, D. Bullard,		
Location: 126-Degree Barrier-Booster Bore		
Secondary O-ring Observations:		
	Yes	No
A. Heat Affected or Eroded O-ring?	_____	_____ <input checked="" type="checkbox"/>
B. O-ring Defects/Damage?	_____	_____ <input checked="" type="checkbox"/>
Comment #		

Notes / Comments

Preliminary PFAR(s)? _____ Yes No _____ Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No _____ Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-4
Leak Check Plug/SII Condition (Detailed)

Motor No.: 360T026	Side: Right (B)	Date: 10-1-92	
Assessment Engineer(s)/Inspector(s): P. Albright, D. Bartelt, G. Neilson, D. Bullard,			
Location: 306-Degree Barrier-Booster Flange			
<u>Leak Check Plug Observations:</u>	Yes	No	Comment #
A. Foreign Material Between the O-ring and Plug?	_____	✓ _____	_____
B. Heat Affected Metal?	_____	✓ _____	_____
C. Seal Surface/Thread Damage?	_____	✓ _____	_____

Notes / Comments

Preliminary PFAR(s)? _____ Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-1
Leak Check Plug/SII and Port Condition (At Removal)

Motor No.: 360T026	Side: Right (B)	Date: 10-1-92
Assessment Engineer(s)/Inspector(s): P. Albright, D. Bartelt, G. Neilson, D. Bullard		
Location: 18-Degree SII		

SII Observations:

	Yes	No	Comment #
A. Sooted Metal Surfaces?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
B. Soot To or Past O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
C. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
D. O-ring Damage (In Groove)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
E. Heat Affected or Eroded O-ring (In Groove)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
F. Excessive or No Grease on O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
G. Excessive Grease on SII?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
H. Corrosion?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
I. Thread Damage (Visible at Removal)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

SII Port Observations:

J. Sooted Metal Surfaces?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
K. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
L. Excessive Grease?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
M. Corrosion?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
N. Metal Damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	2
O. Heat Affected Metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
P. Obstructed Leak Check Through Hole?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments

- 1) Soot on top of SII.
- 2) Typical galling on land between primary and secondary seal surfaces.

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-1
Leak Check Plug/SII and Port Condition (At Removal)

Motor No.: 360T026	Side: Right (B)	Date: 10-1-92
Assessment Engineer(s)/Inspector(s): <i>R. Albright, D. Bartlett, G. Neilson, D. Ballard</i>		
Location: 198-Degree SII		

SII Observations:	Yes	No	Comment #
A. Sooted Metal Surfaces?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
B. Soot To or Past O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
C. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
D. O-ring Damage (In Groove)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
E. Heat Affected or Eroded O-ring (In Groove)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
F. Excessive or No Grease on O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
G. Excessive Grease on SII?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
H. Corrosion?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
I. Thread Damage (Visible at Removal)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
 <u>SII Port Observations:</u>			
J. Sooted Metal Surfaces?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
K. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
L. Excessive Grease?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
M. Corrosion?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
N. Metal Damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	2
O. Heat Affected Metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
P. Obstructed Leak Check Through Hole?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments

1) Soot on the tip of SII.

2) Typical galling on land between primary and secondary seal surfaces.

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-4
Leak Check Plug/SII Condition (Detailed)

Motor No.: 360T026	Side: Right (B)	Date: 10-1-92	
Assessment Engineer(s)/Inspector(s): P. Albright, D. Bartelt, G. Neilson, D. Bullard.			
Location: 198-Degree SII			
<u>SII Observations:</u>	Yes	No	Comment #
A. Foreign Material Between the O-ring and SII?	_____	<input checked="" type="checkbox"/>	_____
B. Heat Affected Metal?	_____	<input checked="" type="checkbox"/>	_____
C. Seal Surface/Thread Damage?	_____	<input checked="" type="checkbox"/>	_____

Notes / Comments

Preliminary PFAR(s)? _____ Yes No _____ Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No _____ Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-6
Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)

Motor No.: 360T026	Side: Right (B)	Date: 10-1-92
Assessment Engineer(s)/Inspector(s): P. Albright, D. Bartelt, G. Neilson, D. Ballard		
Location: 198-Degree SII		

<u>Primary O-ring Observations:</u>	Yes	No	Comment #
A. Heat Affected or Eroded O-ring?	_____	_____/_____ ✓	_____
B. O-ring Defects/Damage?	_____	_____/_____ ✓	_____
 <u>Secondary O-ring Observations:</u>			
C. Heat Affected or Eroded O-ring?	_____	_____/_____ ✓	_____
D. O-ring Defects/Damage?	_____	_____/_____ ✓	_____

Notes / Comments

Preliminary PFAR(s)? _____ Yes ✓ No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes ✓ No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-3
Internal Nozzle Joint Condition

Motor No.: 360T026	Side: Right (B)	Date: 9-30-92
Assessment Engineer(s)/Inspector(s): W. Sperry, D. Bartelt		
Joint: Nose Inlet-to-Flex Bearing-to-Cowl (Joint #2)		

Internal Nozzle Joint Observations:	Yes	No	Comment #
A. Soot To or Past O-rings?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
B. Heat Affected Metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
C. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
D. RTV in Contact With or Past the Primary O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
E. O-ring Damage (In Groove)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
F. Heat Affected or Eroded O-rings (In Groove)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
G. Excessive or No Grease?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
H. Corrosion?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	2
I. Metal Damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments

① Typical scalloped shaped soot ~~over~~ Between bolt holes on nose inlet and forward end ring. Soot reached primary O-ring ~~2~~ intermittently 290° - 0° - 40°.

② Light-to-medium corrosion intermittently in the scalloped soot region of both the forward end ring and nose inlet.

③ Typical light burnishing intermittently on nose inlet secondary seal surface.

W. Sperry 35 Nov 92
D. Bartelt 22 Nov 92

Preliminary PFA(s)? Yes No Preliminary PFA Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-5
Large Diameter (Joint) O-ring Condition (Detailed)

Motor No.: 360T026	Side: Right (B)	Date: 9-30-92
Assessment Engineer(s)/Inspector(s): <i>W. Sperry, M. Lyons, C. Walker</i>		
Joint: Nose Inlet-to-Flex Bearing-to-Cowl (Joint #2)		
<p><u>Primary O-ring Observations:</u></p> <p>A. Heat Affected or Eroded O-ring? _____</p> <p>B. O-ring Damage/Defects? _____</p> <p><u>Secondary O-ring Observations:</u></p> <p>A. Heat Affected or Eroded O-ring? _____</p> <p>B. O-ring Damage/Defects? _____</p>	<p>Yes</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p>	<p>No</p> <p><input checked="" type="checkbox"/></p> <p><input checked="" type="checkbox"/></p> <p><input checked="" type="checkbox"/></p> <p><input checked="" type="checkbox"/></p>
<p>Comment #</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p>		
<p>Notes / Comments</p>		

Preliminary PFAR(s)? _____ Yes No _____ Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No _____ Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-1
Leak Check Plug/SII and Port Condition (At Removal)

Motor No.: 360T026	Side: Right (B)	Date: 9-30-92
--------------------	-----------------	---------------

Assessment Engineer(s)/Inspector(s): W. Sperry, Marv Lyons

Location: Nose Inlet-to-Flex Bearing-to-Cowl (Joint #2)

<u>Leak Check Plug Observations:</u>	Yes	No	Comment #
A. Sooted Metal Surfaces?	_____	✓	_____
B. Soot To or Past O-ring?	_____	✓	_____
C. Foreign Material?	_____	✓	_____
D. O-ring Damage (In Groove)?	_____	✓	_____
E. Heat Affected or Eroded O-ring (In Groove)?	_____	✓	_____
F. Excessive or No Grease on O-ring?	_____	✓	_____
G. Excessive Grease on Plug?	_____	✓	_____
H. Corrosion?	_____	✓	_____
I. Thread Damage (Visible at Removal)?	_____	✓	_____
 <u>Leak Check Port Observations:</u>			
J. Sooted Metal Surfaces?	_____	✓	_____
K. Foreign Material?	_____	✓	_____
L. Excessive Grease?	_____	✓	_____
M. Corrosion?	_____	✓	_____
N. Metal Damage?	_____	✓	_____
O. Heat Affected Metal?	_____	✓	_____
P. Obstructed Through Hole?	_____	✓	_____

Notes / Comments

Break away 34 in. lbs
Running 12 in. lbs

Preliminary PFAR(s)? _____ Yes _____ No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes _____ No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-4
Leak Check Plug/SII Condition (Detailed)

Motor No.: 360T026	Side: Right (B)	Date: 9-30-92	
Assessment Engineer(s)/Inspector(s): <i>W. Sperry, M. Lyons</i>			
Location: Nose Inlet-to-Flex Bearing-to-Cowl (Joint #2)			
<u>Leak Check Plug Observations:</u>	Yes	No	Comment #
A. Foreign Material Between the O-ring and Plug?	_____	_____/_____ ✓	_____
B. Heat Affected Metal?	_____	_____/_____ ✓	_____
C. Seal Surface/Thread Damage?	_____	_____/_____ ✓	_____

Notes / Comments

Preliminary PFAR(s)? _____ Yes ✓ No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes ✓ No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-3
Internal Nozzle Joint Condition

Motor No.: 360T026	Side: Right (B)	Date: 9-30-92
Assessment Engineer(s)/Inspector(s): <i>W. Sperry, M. Lyons</i>		
Joint: Nose Inlet-to-Throat (Joint #3)		

Internal Nozzle Joint Observations:	Yes	No	Comment #
A. Soot To or Past O-rings?	_____	✓ _____	_____
B. Heat Affected Metal?	_____	✓ _____	_____
C. Foreign Material?	_____	✓ _____	_____
D. RTV in Contact With or Past the Primary O-ring?	_____	✓ _____	_____
E. O-ring Damage (In Groove)?	_____	✓ _____	_____
F. Heat Affected or Eroded O-rings (In Groove)?	_____	✓ _____	_____
G. Excessive or No Grease?	_____	✓ _____	_____
H. Corrosion?	✓ _____	_____	1 _____
I. Metal Damage?	_____	✓ _____	_____

Notes / Comments

Special Issues 3.2.3.2

No seal surface metal damage or atypical corrosion found.

① *Typical Light-to-medium corrosion upstream of primary O-ring intermittent full circumference.*

Preliminary PFAR(s)? _____ Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-5
Large Diameter (Joint) O-ring Condition (Detailed)

Motor No.: 360T026	Side: Right (B)	Date: 9-30-92
Assessment Engineer(s)/Inspector(s): <i>W. Sperry, M. Lyons</i>		
Joint: Nose Inlet-to-Throat (Joint #3) ▶		
Primary O-ring Observations:		
A. Heat Affected or Eroded O-ring?	Yes _____	No _____ ✓
B. O-ring Damage/Defects?	_____	_____ ✓
Secondary O-ring Observations:		
A. Heat Affected or Eroded O-ring?	_____	_____ ✓
B. O-ring Damage/Defects?	_____	_____ ✓
Notes / Comments		

Preliminary PFAR(s)? _____ Yes _____ No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes _____ No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-1
Leak Check Plug/SII and Port Condition (At Removal)

Motor No.: 360T026	Side: Right (B)	Date: 9-30-92
Assessment Engineer(s)/Inspector(s): <i>W. Sperry, M. Lyons</i>		
Location: Nose Inlet-to-Throat (Joint #3)		

<u>Leak Check Plug Observations:</u>	Yes	No	Comment #
A. Sooted Metal Surfaces?	_____	_____/_____ ✓	_____
B. Soot To or Past O-ring?	_____	_____/_____ ✓	_____
C. Foreign Material?	_____	_____/_____ ✓	_____
D. O-ring Damage (In Groove)?	_____	_____/_____ ✓	_____
E. Heat Affected or Eroded O-ring (In Groove)?	_____	_____/_____ ✓	_____
F. Excessive or No Grease on O-ring?	_____	_____/_____ ✓	_____
G. Excessive Grease on Plug?	_____	_____/_____ ✓	_____
H. Corrosion?	_____	_____/_____ ✓	_____
I. Thread Damage (Visible at Removal)?	_____	_____/_____ ✓	_____
 <u>Leak Check Port Observations:</u>			
J. Sooted Metal Surfaces?	_____	_____/_____ ✓	_____
K. Foreign Material?	_____	_____/_____ ✓	_____
L. Excessive Grease?	_____	_____/_____ ✓	_____
M. Corrosion?	_____	_____/_____ ✓	_____
N. Metal Damage?	_____	_____/_____ ✓	_____
O. Heat Affected Metal?	_____	_____/_____ ✓	_____
P. Obstructed Through Hole?	_____	_____/_____ ✓	_____

Notes / Comments

Breakaway 33 in. lbs.

Running 11 in. lbs.

Preliminary PFAR(s)? _____ Yes _____ No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes _____ No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-6
Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)

Motor No.: 360T026	Side: Right (B)	Date: 9-30-92
Assessment Engineer(s)/Inspector(s): <i>W. Sperry, M. Lyons</i>		
Location: Nose Inlet-to-Throat (Joint #3)		
<u>Secondary O-ring Observations:</u>	Yes	No
A. Heat Affected or Eroded O-ring?	_____	_____/_____ _____
B. O-ring Defects/Damage?	_____	_____/_____ _____
Notes / Comments		
Preliminary PFAR(s)? _____ Yes _____ <input checked="" type="checkbox"/> No _____ Preliminary PFAR Number(s): _____		

Clarification Form(s)? _____ Yes _____ No _____ Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-3
Internal Nozzle Joint Condition

Motor No.: 360T026	Side: Right (B)	Date: 9-28-92
Assessment Engineer(s)/Inspector(s): <i>A. Macneil, M. Ryan</i>		
Joint: Throat-to-Forward Exit Cone (Joint #4)		

Internal Nozzle Joint Observations:	Yes	No	Comment #
A. Soot To or Past O-rings?	_____	✓	_____
B. Heat Affected Metal?	_____	✓	_____
C. Foreign Material?	_____	✓	_____
D. RTV in Contact With or Past the Primary O-ring?	✓	_____	1
E. O-ring Damage (In Groove)?	_____	✓	_____
F. Heat Affected or Eroded O-rings (In Groove)?	_____	✓	_____
G. Excessive or No Grease?	_____	✓	3
H. Corrosion?	✓	_____	2
I. Metal Damage?	_____	✓	_____

Notes / Comments

Special Issues 3.2.3.2 *N/A*

1. RTV to primary O-ring intermittently full circumference
2. Medium corrosion inboard of primary seal surface on throat intermittently full circumference.
Light corrosion on secondary seal and between primary and secondary seal surfaces on the forward exit cone and mating surfaces intermittently full circumference.
3. Typical medium grease coverage on the primary seal and mating metal surface.

Special Issue 3.2.3.2: No metal damage was seen on the sealing surfaces and corrosion was typical as described in comment #2

Preliminary PFAR(s)? _____ Yes _____ No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes _____ No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-5
Large Diameter (Joint) O-ring Condition (Detailed)

Motor No.: 360T026	Side: Right (B)	Date: 9-28-92	
Assessment Engineer(s)/Inspector(s): <i>A. Macri, M. Lee</i>			
Joint: Throat-to-Forward Exit Cone (Joint #4)			
<u>Primary O-ring Observations:</u>	Yes	No	Comment #
A. Heat Affected or Eroded O-ring?	_____	✓ _____	_____
B. O-ring Damage/Defects?	_____	✓ _____	_____
<u>Secondary O-ring Observations:</u>			
A. Heat Affected or Eroded O-ring?	_____	✓ _____	_____
B. O-ring Damage/Defects?	_____	✓ _____	_____
Notes / Comments			

Preliminary PFAR(s)? _____ Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-1
Leak Check Plug/SII and Port Condition (At Removal)

Motor No.: 360T026	Side: Right (B)	Date: 9-28-92
Assessment Engineer(s)/Inspector(s): <i>A. Marrett, M. Lyon</i>		
Location: Throat-to-Forward Exit Cone (Joint #4)		

<u>Leak Check Plug Observations:</u>	Yes	No	Comment #
A. Sooted Metal Surfaces?	_____	✓	_____
B. Soot To or Past O-ring?	_____	✓	_____
C. Foreign Material?	_____	✓	_____
D. O-ring Damage (In Groove)?	_____	✓	_____
E. Heat Affected or Eroded O-ring (In Groove)?	_____	✓	_____
F. Excessive or No Grease on O-ring?	_____	✓	_____
G. Excessive Grease on Plug?	_____	✓	_____
H. Corrosion?	_____	✓	_____
I. Thread Damage (Visible at Removal)?	_____	✓	_____
 <u>Leak Check Port Observations:</u>			
J. Sooted Metal Surfaces?	_____	✓	_____
K. Foreign Material?	_____	✓	_____
L. Excessive Grease?	_____	✓	_____
M. Corrosion?	_____	✓	_____
N. Metal Damage?	_____	✓	_____
O. Heat Affected Metal?	_____	✓	_____
P. Obstructed Through Hole?	_____	✓	_____

Notes / Comments

Break Torque: Not obtained

Running Torque : 24

Preliminary PFAR(s)? _____ Yes No _____ Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No _____ Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-4
Leak Check Plug/SII Condition (Detailed)

Motor No.: 360T026	Side: Right (B)	Date: 9-28-92	
Assessment Engineer(s)/Inspector(s): <i>A. Marriott, M. Lyon</i>			
Location: Throat-to-Forward Exit Cone (Joint #4)			
<u>Leak Check Plug Observations:</u>	Yes	No	Comment #
A. Foreign Material Between the O-ring and Plug?	_____	_____/_____ ✓	_____
B. Heat Affected Metal?	_____	_____/_____ ✓	_____
C. Seal Surface/Thread Damage?	_____	_____/_____ ✓	_____

Notes / Comments

Preliminary PFAR(s)? _____ Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-3
Internal Nozzle Joint Condition

Motor No.: 360T026	Side: Right (B)	Date: 9-29-92
Assessment Engineer(s)/Inspector(s): <i>A. Marcell, D. Bartlett, C. Walker</i>		
Joint: Aft End Ring-to-Fixed Housing (Joint #5)		

Internal Nozzle Joint Observations:	Yes	No	Comment #
A. Soot To or Past O-rings?	_____	✓ _____	_____
B. Heat Affected Metal?	_____	✓ _____	_____
C. Foreign Material?	_____	✓ _____	_____
D. RTV in Contact With or Past the Primary O-ring?	_____	✓ _____	_____
E. O-ring Damage (In Groove)?	_____	✓ _____	_____
F. Heat Affected or Eroded O-rings (In Groove)?	_____	✓ _____	_____
G. Excessive or No Grease?	_____	✓ _____	_____
H. Corrosion?	✓ _____	_____	1 _____
I. Metal Damage?	_____	✓ _____	_____

Notes / Comments

1. Water droplets and light-medium corrosion observed inboard of secondary seal int. full circumference on mating surfaces. Medium corrosion was also observed on the aft end ring flange ID and mating surface on the fixed housing

Preliminary PFAR(s)? _____ Yes No _____ Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No _____ Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-1
Leak Check Plug/SII and Port Condition (At Removal)

Motor No.: 360T026	Side: Right (B)	Date: 9-29-92
Assessment Engineer(s)/Inspector(s): <i>A. Marshall, D. Bartlett</i>		
Location: Aft End Ring-to-Fixed Housing (Joint #5)		

<u>Leak Check Plug Observations:</u>	Yes	No	Comment #
A. Sooted Metal Surfaces?	_____	✓ _____	_____
B. Soot To or Past O-ring?	_____	✓ _____	_____
C. Foreign Material?	_____	✓ _____	_____
D. O-ring Damage (In Groove)?	_____	✓ _____	_____
E. Heat Affected or Eroded O-ring (In Groove)?	_____	✓ _____	_____
F. Excessive or No Grease on O-ring?	_____	✓ _____	_____
G. Excessive Grease on Plug?	_____	✓ _____	_____
H. Corrosion?	_____	✓ _____	_____
I. Thread Damage (Visible at Removal)?	_____	✓ _____	_____
 <u>Leak Check Port Observations:</u>			
J. Sooted Metal Surfaces?	_____	✓ _____	_____
K. Foreign Material?	_____	✓ _____	_____
L. Excessive Grease?	_____	✓ _____	_____
M. Corrosion?	_____	✓ _____	_____
N. Metal Damage?	_____	✓ _____	_____
O. Heat Affected Metal?	_____	✓ _____	_____
P. Obstructed Through Hole?	_____	✓ _____	_____

Notes / Comments

Break Torque: 40 ft-lbs

Running Tor 11 ft-lbs

Preliminary PFAR(s)? _____ Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-6
Small Diameter (Leak Check Plug/SII) O-ring Condition (Detailed)

Motor No.: 360T026	Side: Right (B)	Date: 9-29-92
Assessment Engineer(s)/Inspector(s): <i>A. Macciell, D. Bartlett, C. Walker</i>		
Location: Aft End Ring-to-Fixed Housing (Joint #5)		
<u>Secondary O-ring Observations:</u>	Yes	No
A. Heat Affected or Eroded O-ring?	_____	<input checked="" type="checkbox"/>
B. O-ring Defects/Damage?	_____	<input checked="" type="checkbox"/>
		Comment #

Notes / Comments

Preliminary PFAR(s)? _____ Yes No _____ Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No _____ Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-8
Packing With Retainer Condition (Detailed)

Motor No.: 360T026	Side: Right (B)	Date: 9-29-92	
Assessment Engineer(s)/Inspector(s): <i>D. Burtlett, A. Maciatt</i>			
Joint: Aft End Ring-to-Fixed Housing (Joint #5)			
Packing With Retainer Observations:			
	Yes	No	Comment #
A. Heat Affected or Eroded Seal or Retainer?	_____	_____✓	_____
B. Seal or Retainer Damage/Defects?	_____✓	_____	_____1
C. Corrosion?	_____	_____✓	_____

Notes / Comments

1. 3/72 packings did not have damage
15/72 had typical metal flaking-off the retainer

Preliminary PFAR(s)? _____ Yes _____✓ No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes _____✓ No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-9
Case Factory Joint Condition

Motor No.: 360T026	Side: Right (B)	Date: 1-4-93
Assessment Engineer(s)/Inspector(s): H. ZAREMBA		
Factory Joint: Forward Dome		

Case Factory Joint Observations:	Yes	No	Comment #
A. Heat Affected or Eroded Joint O-ring?	<u> </u>	<u> X </u>	<u> </u>
B. Heavy Corrosion in Joint?	<u> X </u>	<u> </u>	<u> #1 </u>
C. Heavy Corrosion in Leak Check Port?	<u> </u>	<u> X </u>	<u> </u>

Note: Heavy corrosion is defined as corrosion that causes pitting. It may be necessary to remove corrosion to determine if pitting has occurred; however, care should be taken not to damage the hardware. A cloth dampened with solvent or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.

Notes / Comments

Special Issues 3.2.3.3 Leak Test plug was removed

#1 HEAVY CORROSION ON LAND FWD OF PRIMARY O-RING,
AND ON LAND AND ON SEC. AFT WALL OUTBOARD EDGE
LOCATION AT 202°, ALSO ON TANK AT 202° ON FWD DOME
HEAVY CORROSION AT 180° FWD OF PRI. O-RING

Preliminary PFAr(s)? Yes No Preliminary PFAr Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-9
Case Factory Joint Condition

Motor No.: 360T026	Side: Right (B)	Date: 1-4-93
--------------------	-----------------	--------------

Assessment Engineer(s)/Inspector(s): H. ZAREMBA

Factory Joint: Forward

<u>Case Factory Joint Observations:</u>	Yes	No	Comment #
A. Heat Affected or Eroded Joint O-ring?	_____	<u>X</u>	_____
B. Heavy Corrosion in Joint?	_____	<u>X</u>	_____
C. Heavy Corrosion in Leak Check Port?	_____	<u>X</u>	_____

Note: Heavy corrosion is defined as corrosion that causes pitting. It may be necessary to remove corrosion to determine if pitting has occurred; however, care should be taken not to damage the hardware. A cloth dampened with solvent or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.

Notes / Comments

Special Issues 3.2.3.3 *Leak test plug was worn*

Preliminary PFAR(s)? _____ Yes ✓ No _____ Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes ✓ No _____ Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-9
Case Factory Joint Condition

Motor No.: 360T026	Side: Right (B)	Date: 4-28-93
--------------------	-----------------	---------------

Assessment Engineer(s)/Inspector(s): G. RICH

Factory Joint: Forward Center

<u>Case Factory Joint Observations:</u>	Yes -	No	Comment #
A. Heat Affected or Eroded Joint O-ring?	_____	✓ _____	_____
B. Heavy Corrosion in Joint?	_____	✓ _____	_____
C. Heavy Corrosion in Leak Check Port?	_____	✓ _____	_____

Note: Heavy corrosion is defined as corrosion that causes pitting. It may be necessary to remove corrosion to determine if pitting has occurred; however, care should be taken not to damage the hardware. A cloth dampened with solvent or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.

Notes / Comments

Special Issues 3.2.3.3
The leak test play was minimal

Preliminary PFAR(s)? _____ Yes No _____ Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No _____ Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-9
Case Factory Joint Condition

Motor No.: 360T026	Side: Right (B)	Date: 4-12-93
Assessment Engineer(s)/Inspector(s): GARY W. ASPER 640		
Factory Joint: Aft Center		

Case Factory Joint Observations:	Yes	No	Comment #
A. Heat Affected or Eroded Joint O-ring?	_____	<input checked="" type="checkbox"/>	_____
B. Heavy Corrosion in Joint?	_____	<input checked="" type="checkbox"/>	_____
C. Heavy Corrosion in Leak Check Port?	_____	<input checked="" type="checkbox"/>	_____

Note: Heavy corrosion is defined as corrosion that causes pitting. It may be necessary to remove corrosion to determine if pitting has occurred; however, care should be taken not to damage the hardware. A cloth dampened with solvent or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.

Notes / Comments

Special Issues 3.2.3.3 The (aft test plug) was worn

N/A

Preliminary PFAR(s)? _____ Yes No Preliminary PFAR Number(s): N/A

Clarification Form(s)? _____ Yes No Clarification Form Page No.(s): N/A

POSTFLIGHT OBSERVATION RECORD (PFOR) B-9
Case Factory Joint Condition

Motor No.: 360T026	Side: Right (B)	Date: 14 JAN 1993
Assessment Engineer(s)/Inspector(s): <i>Birch</i>		
Factory Joint: ET Attach/Stiffener		

Case Factory Joint Observations:	Yes	No	Comment #
A. Heat Affected or Eroded Joint O-ring?	_____	_____/_____ ✓	_____
B. Heavy Corrosion in Joint?	_____	_____/_____ ✓	_____
C. Heavy Corrosion in Leak Check Port?	_____	_____/_____ ✓	_____

Note: Heavy corrosion is defined as corrosion that causes pitting. It may be necessary to remove corrosion to determine if pitting has occurred; however, care should be taken not to damage the hardware. A cloth dampened with solvent or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.

Notes / Comments

Special Issues 3.2.3.3 This Leak Test Plug Has The Blue Locking Device Still Visible On The Threads. No Anomalous Condition Was Noted.

Preliminary PFAR(s)?	_____ Yes	_____/_____ ✓ No	Preliminary PFAR Number(s): _____
Clarification Form(s)?	_____ Yes	_____/_____ ✓ No	Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-9
Case Factory Joint Condition

Motor No.: 360T026	Side: Right (B)	Date: 14 JAN 1993
Assessment Engineer(s)/Inspector(s): <i>Birch</i>		
Factory Joint: Stiffener/Stiffener		

<u>Case Factory Joint Observations:</u>	Yes	No	Comment #
A. Heat Affected or Eroded Joint O-ring?	_____	_____/_____ ✓	_____
B. Heavy Corrosion in Joint?	_____	_____/_____ ✓	_____
C. Heavy Corrosion in Leak Check Port?	_____	_____/_____ ✓	_____

Note: Heavy corrosion is defined as corrosion that causes pitting. It may be necessary to remove corrosion to determine if pitting has occurred; however, care should be taken not to damage the hardware. A cloth dampened with solvent or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.

Notes / Comments

Special Issues 3.2.3.3 *Leak test play was normal*

Preliminary PFAR(s)? _____ Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) B-9
Case Factory Joint Condition

Motor No.: 360T026	Side: Right (B)	Date: 01-13-93
--------------------	-----------------	----------------

Assessment Engineer(s)/Inspector(s): ERIC HAY

Factory Joint: Aft Dome

<u>Case Factory Joint Observations:</u>	Yes	No	Comment #
A. Heat Affected or Eroded Joint O-ring?	_____	<input checked="" type="checkbox"/>	_____
B. Heavy Corrosion in Joint?	_____	<input checked="" type="checkbox"/>	_____
C. Heavy Corrosion in Leak Check Port?	_____	<input checked="" type="checkbox"/>	_____


Note: Heavy corrosion is defined as corrosion that causes pitting. It may be necessary to remove corrosion to determine if pitting has occurred; however, care should be taken not to damage the hardware. A cloth dampened with solvent or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.

Notes / Comments

Special Issues 3.2.3.3 Leak test plug was nominal

Preliminary PFAR(s)? Yes _____ No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes _____ No Clarification Form Page No. (s): _____



Appendix C Nozzle PFORs

Final Postflight Hardware Evaluation Report 360T026 (RSRM-26, STS-47)

April 1993

Prepared for:

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION
GEORGE C. MARSHALL SPACE FLIGHT CENTER
MARSHALL SPACE FLIGHT CENTER, ALABAMA 35812

Contract No.	NAS8-38100
DR No.	4-23
WBS No.	4C601-04-01
ECS No.	SS4769

Thiokol CORPORATION
SPACE OPERATIONS

P.O. Box 707, Brigham City, Utah 84302-0707 (801) 863-3511



NOZZLE REQUIRED EVALUATION FORMS LIST

<u>PFOR #</u>	<u>Title</u>	<u>Side</u>	<u>Joint, Part, or Location</u>	<u>Final Report Page Number</u>
C-1	Nozzle Assembly Quick-look Condition	Left	N/A	C-1
C-2	Nozzle Joint Condition	Left	Joint #2	C-2
C-3	Nose Inlet-to-Flex Bearing-to-Cowl Joint Condition Drawing Worksheet	Left	Joint #2	C-3
C-2	Nozzle Joint Condition	Left	Joint #3	C-4
C-4	Nose Inlet-to-Throat Joint Condition Drawing Worksheet	Left	Joint #3	C-5
C-2	Nozzle Joint Condition	Left	Joint #4	C-6
C-5	Throat-to-Forward Exit Cone Joint Condition Drawing Worksheet	Left	Joint #4	C-7
C-2	Nozzle Joint Condition	Left	Joint #5	C-8
C-6	Aft End Ring-to-Fixed Housing Joint Condition Drawing Worksheet	Left	Joint #5	C-9
C-7	Cowl Insulation Segment Condition	Left	Cowl	C-10
C-8	Flexible Bearing, Flexible Bearing Protector, and Flexible Boot Condition	Left	Flexible Bearing, Protector, & Boot	C-11
C-9	Flexible Bearing Protector Thickness Measurements	Left	Flexible Bearing Protector	C-12
C-10	Throat Diameter Measurements	Left	Throat	C-13

(Note: Clarification PFORs will be inserted after the applicable required PFOR in the Final Report and will have the same page number as the required PFOR appended by a sequential alphabetic extension.)

NOZZLE REQUIRED EVALUATION FORMS LIST (Cont.)

<u>PFOR #</u>	<u>Title</u>	<u>Side</u>	<u>Joint, Part, or Location</u>	<u>Final Report Page Number</u>
C-11	Outer Boot Ring Char and Erosion Measurements and Flexible Boot Condition	Left	Outer Boot Ring & Flexible Boot	C-14
C-12	Nozzle Subassembly Phenolic Bondline Condition	Left	Aft Exit Cone	C-15
C-12	Nozzle Subassembly Phenolic Bondline Condition	Left	Forward Exit Cone	C-16
C-12	Nozzle Subassembly Phenolic Bondline Condition	Left	Throat	C-17
C-12	Nozzle Subassembly Phenolic Bondline Condition	Left	Forward Nose & Aft Inlet Rings	C-18
C-12	Nozzle Subassembly Phenolic Bondline Condition	Left	Nose Cap	C-19
C-12	Nozzle Subassembly Phenolic Bondline Condition	Left	Cowl	C-20
C-12	Nozzle Subassembly Phenolic Bondline Condition	Left	Fixed Housing	C-21
C-13	Cowl Ring Phenolic (SCP) Section Condition	Left	Cowl	C-22
C-14	Forward Exit Cone Phenolic (CCP) Section Condition	Left	Forward Exit Cone	C-23
C-15	Fixed Housing Phenolic (CCP) Section Condition	Left	Fixed Housing	C-24
C-16	Throat Inlet Assembly Phenolic (CCP) Section Condition	Left	Throat	C-25
C-17	Nose Cap Phenolic (CCP) Section Condition	Left	Nose Cap	C-26
C-18	Forward Nose Ring and Aft Inlet Ring Phenolic (CCP) Section Condition	Left	Forward Nose & Aft Inlet Rings	C-27

(Note: Clarification PFORs will be inserted after the applicable required PFOR in the Final Report and will have the same page number as the required PFOR appended by a sequential alphabetic extension.)

NOZZLE REQUIRED EVALUATION FORMS LIST (Cont.)

<u>PFOR #</u>	<u>Title</u>	<u>Side</u>	<u>Joint, Part, or Location</u>	<u>Final Report Page Number</u>
C-1	Nozzle Assembly Quick-look Condition	Right	N/A	C-28
C-2	Nozzle Joint Condition	Right	Joint #2	C-29
C-3	Nose Inlet-to-Flex Bearing-to-Cowl Joint Condition Drawing Worksheet	Right	Joint #2	C-30
C-2	Nozzle Joint Condition	Right	Joint #3	C-31
C-4	Nose Inlet-to-Throat Joint Condition Drawing Worksheet	Right	Joint #3	C-32
C-2	Nozzle Joint Condition	Right	Joint #4	C-33
C-5	Throat-to-Forward Exit Cone Joint Condition Drawing Worksheet	Right	Joint #4	C-34
C-2	Nozzle Joint Condition	Right	Joint #5	C-35
C-6	Aft End Ring-to-Fixed Housing Joint Condition Drawing Worksheet	Right	Joint #5	C-36
C-7	Cowl Insulation Segment Condition	Right	Cowl	C-37
C-8	Flexible Bearing, Flexible Bearing Protector, and Flexible Boot Condition	Right	Flexible Bearing, Protector, & Boot	C-38
C-9	Flexible Bearing Protector Thickness Measurements	Right	Flexible Bearing Protector	C-39
C-10	Throat Diameter Measurements	Right	Throat	C-40

(Note: Clarification PFORs will be inserted after the applicable required PFOR in the Final Report and will have the same page number as the required PFOR appended by a sequential alphabetic extension.)

NOZZLE REQUIRED EVALUATION FORMS LIST (Cont.)

<u>PFOR #</u>	<u>Title</u>	<u>Side</u>	<u>Joint, Part, or Location</u>	<u>Final Report Page Number</u>
C-11	Outer Boot Ring Char and Erosion Measurements and Flexible Boot Condition	Right	Outer Boot Ring & Flexible Boot	C-41
C-12	Nozzle Subassembly Phenolic Bondline Condition	Right	Aft Exit Cone	C-42
C-12	Nozzle Subassembly Phenolic Bondline Condition	Right	Forward Exit Cone	C-43
C-12	Nozzle Subassembly Phenolic Bondline Condition	Right	Throat	C-44
C-12	Nozzle Subassembly Phenolic Bondline Condition	Right	Forward Nose & Aft Inlet Rings	C-45
C-12	Nozzle Subassembly Phenolic Bondline Condition	Right	Nose Cap	C-46
C-12	Nozzle Subassembly Phenolic Bondline Condition	Right	Cowl	C-47
C-12	Nozzle Subassembly Phenolic Bondline Condition	Right	Fixed Housing	C-48
C-13	Cowl Ring Phenolic (SCP) Section Condition	Right	Cowl	C-49
C-14	Forward Exit Cone Phenolic (CCP) Section Condition	Right	Forward Exit Cone	C-50
C-15	Fixed Housing Phenolic (CCP) Section Condition	Right	Fixed Housing	C-51
C-16	Throat Inlet Assembly Phenolic (CCP) Section Condition	Right	Throat	C-52
C-17	Nose Cap Phenolic (CCP) Section Condition	Right	Nose Cap	C-53
C-18	Forward Nose Ring and Aft Inlet Ring Phenolic (CCP) Section Condition	Right	Forward Nose & Aft Inlet Rings	C-54

(Note: Clarification PFORs will be inserted after the applicable required PFOR in the Final Report and will have the same page number as the required PFOR appended by a sequential alphabetic extension.)

POSTFLIGHT OBSERVATION RECORD (PFOR) C-2
Internal Nozzle Joint Condition

Motor No.: 360T026	Side: Left (A)	Date: 9-30-92
Assessment Engineer(s)/Inspector(s): M. Clark, J. Walker, R. Lange, T. Freston		
Joint: Nose Inlet-to-Flex Bearing-to-Cowl (Joint #2)		

Internal Nozzle Joint Observations:	Yes	No	Comment #
A. Gas Penetration In the RTV (Terminated, Through)?	✓	_____	1
B. RTV Not Below Char Line?	_____	✓	_____
C. RTV To the Primary O-ring?	_____	✓	_____
D. RTV Past the Primary O-ring?	_____	✓	_____
E. Uncured RTV?	_____	✓	_____
F. Voids Within RTV?	_____	✓	_____
G. Foreign Material?	_____	✓	_____
H. Heat Affected or Eroded Virgin CCP, GCP/SCP, or adhesive?	_____	✓	_____
I. Damaged Phenolics?	_____	✓	_____
J. Bondline Edge Separations? Use Clarification Form.	✓	_____	2
K. Phenolics Axially Displaced From Housing?	_____	✓	_____
L. Heat Affected Metal?	_____	✓	_____
M. Unbonded or Blistered Paint?	✓	_____	3
N. Corrosion?	✓	_____	4
O. Excessive Grease in Threaded Bolt Holes?	_____	✓	_____
P. Bolt Hole Damage (Through, Threaded/Helical Coil Insert)?	_____	✓	_____
Q. Bent or Broken Bolts?	_____	✓	_____
R. Metal Damage (Joints or Housings)?	_____	✓	_____

Notes / Comments

1) Soot in joint and reached primary o-ring at 190°-345°. No gas path into joint. Soot entered thru intermixed RTV.

2) Reference page C-2A

3) Bubbled paint on OD of forward end ring at 170°-325° Preliminary PFAR has been written.

4) Reference page C-3 for locations

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): 47C-09

Clarification Form(s)? Yes No Clarification Form Page No.(s): C-2A




POSTFLIGHT OBSERVATION RECORD (PFOR) C-3
Nose Inlet-to-Flex Bearing-to-Cowl Joint (Joint #2) Condition Drawing Worksheet

Motor No.: 360T026 Side: Left (A) Date: 9-30-92
Assessment Engineer(s)/Inspector(s): M. Clark, J. Walker, K. Lange, T. Freston

Sketch Observations Below (include locations and sizes of sketched features):

Soot to Primary O-ring
190°-345° intermittently
No Distinct gas path

6) Intermittent bubbled
Paint on fwd end ring
O.D. surface at 175°-325°
Bubble extends from fwd end
to within 1" of SECONDARY
O-ring groove, Clear fluid
in bubbles, Sample taken



1) Pry Bar used at 5° and 110°
to facilitate separation

2) Typical RTV and
adhesive intermixed
with soot entering
between layers.

- 3) Light-to-medium corrosion
intermittent 0°-360°
- 4) TYP. SOOTING, LIGHT/MEDIUM CORROSION
0°-360°
- 5) TYP. SOOTING, LIGHT/MED CORROSION TO PRI O-RING

Verification Form(s)? Yes No

Clarification Form Page No. (s): _____

REVISION _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-2
Internal Nozzle Joint Condition

Motor No.: 360T026	Side: Left (A)	Date: 9-30-92
Assessment Engineer(s)/Inspector(s): R. Quick		
Joint: Nose Inlet-to-Throat (Joint #3)		

Internal Nozzle Joint Observations:	Yes	No	Comment #
A. Gas Penetration in the RTV (Terminated, Through)?	_____	✓	_____
B. RTV Not Below Char Line?	_____	✓	_____
C. RTV To the Primary O-ring?	_____	✓	_____
D. RTV Past the Primary O-ring?	_____	✓	_____
E. Uncured RTV?	_____	✓	_____
F. Voids Within RTV?	_____	✓	_____
G. Grease Inhibiting RTV Backfill?	✓	_____	1
H. Foreign Material?	_____	✓	_____
I. Heat Affected or Eroded Virgin CCP, GCP/SCP, or adhesive?	_____	✓	_____
J. Damaged Phenolics?	_____	✓	_____
K. Bondline Edge Separations? Use Clarification Form.	✓	✓	3
L. Phenolics Axially Displaced From Housing?	_____	✓	_____
M. Heat Affected Metal?	_____	✓	_____
N. Unbonded or Blistered Paint?	_____	✓	_____
O. Corrosion?	_____	✓	_____
P. Alignment Pin Damage?	✓	_____	2
Q. Excessive Grease in Threaded Bolt Holes?	_____	N/A	_____
R. Bolt Hole Damage (Through, Threaded/Helical Coil Insert)?	_____	✓	_____
S. Bent or Broken Bolts?	_____	✓	_____
T. Metal Damage (Joints or Housings)?	_____	✓	_____

Notes / Comments

Special Issues 3.2.3.2 - NO SEAL SURFACE DAMAGE OR TYPICAL CORROSION FOUND
 1-2 VOIDS IN RTV AT 85° AND 238° BEYOND CHAR LINE
 2 - TYPICAL LIGHT TO MEDIUM CORROSION UPSTREAM OF PRIMARY O-RING INTERMITTENT 360° ON NOSE INLET HOUSING
 3 - SEE PAGE C-4A AND C-4B.

Preliminary PFAAR(s)? _____ Yes No _____ Preliminary PFAAR Number(s): _____

Clarification Form(s)? Yes _____ No _____ Clarification Form Page No. (s): C-4A & C-4B

POSTFLIGHT OBSERVATION RECORD (PFOR) C-4
Nose Inlet-to-Throat Joint (Joint #3) Condition Drawing Worksheet

Motor No.: 360T026


Side: Left (A)

Date: 9-30-92

Assessment Engineer(s)/Inspector(s): R. QUICK

Sketch Observations Below (include locations and sizes of sketched features):

- ① RTU BELOW CHAR LINE 360°
- ② NOMINAL GREASE COVERAGE
- ③ CORROSION FROM SEA WATER 360°
- ④ SOOT TO CHAR LINE INTERMITTENT 360°



⑤ SEE SHEET C-4

Clarification Form(s)? Yes No

Clarification Form Page No.(s): _____

REVISION _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-2
Internal Nozzle Joint Condition

Motor No.: 360T026	Side: Left (A)	Date: 9-29-92
Assessment Engineer(s)/Inspector(s): M.E. Clark, T. Freston		
Joint: Throat-to-Forward Exit Cone (Joint #4)		

Internal Nozzle Joint Observations:

	Yes	No	Comment #
A. Gas Penetration in the RTV (Terminated, Through)?	_____	✓	_____
B. RTV Not Below Char Line?	_____	✓	_____
C. RTV To the Primary O-ring?	_____	✓	_____
D. RTV Past the Primary O-ring?	_____	✓	_____
E. Uncured RTV?	_____	✓	_____
F. Voids Within RTV?	_____	✓	_____
G. Grease Inhibiting RTV Backfill?	_____	✓	_____
H. Foreign Material?	✓	✓	1
I. Heat Affected or Eroded Virgin CCP, GCP/SCP, or adhesive?	_____	✓	_____
J. Damaged Phenolics?	_____	✓	_____
K. Bondline Edge Separations? Use Clarification Form.	✓	✓	2
L. Phenolics Axially Displaced From Housing?	_____	✓	_____
M. Heat Affected Metal?	_____	✓	_____
N. Unbonded or Blistered Paint?	_____	✓	_____
O. Corrosion?	✓	✓	3
P. Alignment Pin Damage?	_____	✓	_____
Q. Excessive Grease in Threaded Bolt Holes?	_____	✓	_____
R. Bolt Hole Damage (Through, Threaded/Helical Coil Insert)?	_____	✓	_____
S. Bent or Broken Bolts?	_____	✓	_____
T. Metal Damage (Joints or Housings)?	_____	✓	_____

Notes / Comments

Special Issues 3.3.1, No sign of damage to bolts or threaded holes

1) Foreign Material in joint area. Reference page C-7 for locations.
A PPAR was written by joints and seals

2) Reference pages C-6A and C-6B

3) Reference page C-7 for location

SPECIAL ISSUE 3.2.3.2 NO METAL DAMAGE WAS OBSERVED ON THE SEAL SURFACE AND CORROSION WAS TYPICAL

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): 47C-03

Clarification Form(s)? Yes No Clarification Form Page No.(s): C-6A & C-6B

POSTFLIGHT OBSERVATION RECORD (PFOR) C-5
Throat-to-Forward Exit Cone Joint (Joint #4) Condition Drawing Worksheet


Motor No.: 360T026	Side: Left (A)	Date: 9-29-92
Assessment Engineer(s)/Inspector(s): M.E. Clark, T. Freston		

Sketch Observations Below (include locations and sizes of sketched features):

3) RTV Below charline
0°-360°. RTV did not
reach primary
O-ring

4) RTV reached to this point
at 0°-90°. RTV detected
by stains on phenolic
only.

5) Nominal Grease
coverage No Corrosion



1) 235°-270° medium corrosion
0-360° Light intermittent
corrosion
on Throat and FEC.
6) Medium corrosion in-board of
o-ring footprint

2) 28° and 2°, small ball of
foreign material at dogleg
at 2 and 30°, on primary
o-ring at 28°. Intermittent
black material on Throat
seal surface and FEC primary
o-ring groove heaviest at 75°,
23°-30°. No sign of gas path
into the joint. Material is
flakey on the sealing area

Clarification Form(s)? Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-2
Internal Nozzle Joint Condition

Motor No.: 360T026	Side: Left (A)	Date: 9-29-92
Assessment Engineer(s)/Inspector(s): M.E. Clark T. Freston		
Joint: Aft End Ring-to-Fixed Housing (Joint #5)		

Internal Nozzle Joint Observations:	Yes	No	Comment #
A. Gas Penetration in the RTV (Terminated, Through)?	_____	✓	_____
B. RTV Not Below Char Line?	_____	✓	_____
C. RTV To the Primary O-ring?	_____	✓	_____
D. RTV Past the Primary O-ring?	_____	✓	_____
E. Uncured RTV?	_____	✓	_____
F. Voids Within RTV?	✓	_____	1
G. Foreign Material?	✓	_____	2
H. Heat Affected or Eroded Virgin CCP, GCP/SCP, or adhesive?	_____	✓	_____
I. Damaged Phenolics?	_____	✓	_____
J. Bondline Edge Separations? Use Clarification Form.	_____	✓	_____
K. Phenolics Axially Displaced From Housing?	_____	✓	_____
L. Heat Affected Metal?	_____	✓	_____
M. Unbonded or Blistered Paint?	✓	_____	4
N. Corrosion?	✓	_____	3
O. Alignment Pin Damage?	_____	✓	_____
P. Excessive Grease in Threaded Bolt Holes?	_____	✓	_____
Q. Bolt Hole Damage (Through, Threaded/Helical Coil Insert)?	_____	✓	_____
R. Bent or Broken Bolts?	_____	✓	_____
S. Metal Damage (Joints or Housings)?	_____	✓	_____

Notes / Comments

1- TYPICAL ENCAPSULATED VOIDS DUE TO ASSEMBLY

2- FOREIGN MATERIAL AT BOLT HOLE(235°) SEALS GROUP
PRELIMINARY PPAR 47C-04.

3- CORROSION DOCUMENTED ON PAGE C-9

4- AREA OF PAINT THAT HAS SMALL BUBBLES FROM 50°-80° ON ED OF HOUSING 6.0 IN. FROM AFT FACE OF MOUNTING FLANGE. NO HEAT HAZARD. PRELIMINARY PPAR 47C-06.


Preliminary PPAR(s)?	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	Preliminary PPAR Number(s):	47C-04, 47C-06
Clarification Form(s)?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Clarification Form Page No.(s):	_____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-6
Aft End Ring-to-Fixed Housing Joint (Joint #5) Condition Drawing Worksheet

Motor No.: 360T026	Side: Left (A)	Date: 4-29-92
Assessment Engineer(s)/Inspector(s): R. QUICK R. TELLERS		REVISED LEW 10-2-92

Sketch Observations Below (include locations and sizes of sketched features):

SCRAPE MARKS FROM SPLASH DOWN FROM 155° THRU 305° 7.0" AXIAL AT LOC. 150° LIGHT CORROSION ON SCRAPE MARKS.



Flexible Bearing Protector

④ TYPICAL SOOTING ON BOOT & BRG PROTECTOR

- ① TYPICAL RTV COVERAGE AND CONDITION WAS NOMINAL WITH TYPICAL ENCAPSULATED VOIDS FROM ASSEMBLY
- ② NOMINAL GREASE COVERAGE NO EXCESS GREASE IN BOLT HOLES
- ③ LIGHT TO MEDIUM CORROSION INTERMITTENT 360°

Clarification Form(s)? Yes No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-7
Cowl Insulation Segment Condition

Motor No.: 360T026	Side: Left (A)	Date: 9/29/92
Assessment Engineer(s)/Inspector(s): <u>R. QUICK R. TELLERS</u>		(REVISED 4-6-93) L. WINKLES

Cowl Insulation Segment Observations:	Yes	No	Comment #
A. Spring Pin Holes Completely Through the Cowl Segment?	_____	✓	_____
B. Abnormal Heat Effects or Erosion?	_____	✓	_____
C. Soot Between the Cowl Segment and Cowl Housing?	_____	✓	2
D. Bondline Failure Mode? Data Collection Only.	N/A	N/A	1

Notes / Comments

① 1% WITHIN SEGMENT
90% RUBBER TO ADHESIVE FAILURE
9% CO ADHESIVE FAILURE

② ADHESIVE THAT RETAINS THE SILICA PLUGS IN THE COWL PHEXOLICS FLOWED INTO THE COWL HOUSING/COWL INSULATION SEGMENTS BONDLINE AROUND ALL 36 SPRING PINS. THE LARGEST AREA MEASURED ONE INCH DIAMETER AROUND THE 230 DEGREE PIN. PRELIMINARY PFAR 47C-07 WAS WRITTEN ON THIS FIRST TIME OCCURRENCE OBSERVATION.

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): 47C-07

Clarification Form(s)? Yes No Clarification Form Page No.(s): _____



POSTFLIGHT OBSERVATION RECORD (PFOR) C-7
Cowl Insulation Segment Condition

Motor No.: 360T026 Side: Left (A) Date: 9/29/92

Assessment Engineer(s)/Inspector(s): R. QUICK R. TELLECS (K. ...)

Cowl Insulation Segment Observations:	Yes	No	Comment #
A. Spring Pin Holes Completely Through the Cowl Segment?	_____	✓	_____
B. Abnormal Heat Effects or Erosion?	_____	✓	_____
C. Soot Between the Cowl Segment and Cowl Housing?	_____	✓	2
D. Bondline Failure Mode? Data Collection Only.	N/A	N/A	1

Notes / Comments

① 1% WITHIN SEGMENT
96% RUBBER TO ADHESIVE FAILURE
9% CO ADHESIVE FAILURE

② [Faded text, mostly obscured by a large handwritten 'X']

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): 47C-07

Clarification Form(s)? Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-8
Flexible Bearing, Flexible Bearing Protector, and Flexible Boot Condition

Motor No.: 360T026	Side: Left (A)	Date: 9-29-92
--------------------	----------------	---------------

Assessment Engineer(s)/Inspector(s): *R. QUICK R TELLERS*

<u>Flexible Bearing, Bearing Protector, and Boot Observations:</u>	Yes	No	Comment #
A. Bearing Protector Burn-Through?	_____	✓ _____	_____
B. Cracks Through the Bearing Protector?	_____	✓ _____	_____
C. Bearing Protector Heat Effects or Erosion Other Than at Cowl Vent Hole Locations?	_____	✓ _____	_____
D. Soot Between the Bearing Protector and Flexible Bearing?	_____	✓ _____	_____
E. Heat Effects to the Flexible Bearing?	_____	✓ _____	_____
F. Bent or Broken Bearing Protector Bolts?	_____	✓ _____	_____
G. Flexible Boot Burn-Through?	_____	✓ _____	_____
H. Abnormal Heat Effects or Erosion to Flexible Boot ID?	_____	✓ _____	_____
I. Foreign Material in Boot Cavity?	_____	✓ _____	_____

Notes / Comments
Special Issues 3.3.5 *No BENT OR BROKEN BOLTS*


Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No. (s): *C-11A*

Flexible Boot Cavity Clarification Form

Motor No.:	Side: <input checked="" type="checkbox"/> Left (A) <input type="checkbox"/> Right (B)	Date: 7-29-92
Assessment Engineer(s)/Inspector(s): R. QUICK - R. TELLERS		
Description: FLEX BOOT CAVITY OBSERVATIONS		

Sketch Observations Below (include locations and sizes of sketched features):



- ① NO BUBBLES ON INSULATION SEGMENTS
- ② HEAVY COATING 360 WHICH IS NORMAL
- ③ CAVITY BETWEEN BRG PROTECTOR & COWL INSUL SEGMENTS WAS FULL OF WATER

Corresponding Comment Number(s): NA

TWR-64204
PAGE C-11A


POSTFLIGHT OBSERVATION RECORD (PFOR) C-9
Flexible Bearing Protector Thickness Measurements

Motor No.: 360T026 Side: Left (A) Date: 10-14-92

Assessment Engineer(s)/Inspector(s): D. Turnbull, R.R. Gallegos

Record the Flexible Bearing Protector Gas Impingement Area Thickness Measurements (see figure) Below:

Degree Location	Thickness Measurement "A"* (inches)	Degree Location	Thickness Measurement "A"* (inches)	Degree Location	Thickness Measurement "A"* (inches)
0	<u>.673"</u>	120	<u>.655"</u>	240	<u>.650"</u>
10	<u>.695"</u>	130	<u>.654"</u>	250	<u>.668"</u>
20	<u>.685"</u>	140	<u>.647"</u>	260	<u>.653"</u>
30	<u>.680"</u>	150	<u>.655"</u>	270	<u>.650"</u>
40	<u>.690"</u>	160	<u>.654"</u>	280	<u>.702"</u>
50	<u>.685"</u>	170	<u>.665"</u>	290	<u>.689"</u>
60	<u>.670"</u>	180	<u>.645"</u>	300	<u>.684"</u>
70	<u>.671"</u>	190	<u>.667"</u>	310	<u>.660"</u>
80	<u>.685"</u>	200	<u>.680"</u>	320	<u>.667"</u>
90	<u>.674"</u>	210	<u>.675"</u>	330	<u>.670"</u>
100	<u>.692"</u>	220	<u>.675"</u>	340	<u>.670"</u>
110	<u>.655"</u>	230	<u>.661"</u>	350	<u>.685"</u>



* "A" is the minimum thickness of the bearing protector in-line with the cowl vent holes. It corresponds to the deepest gas impingement location.

Notes / Comments

SL-47230

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-10
Throat Diameter Measurements (Data Collection Only)

Motor No.: 360T026	Side: Left (A)	Date: 10-1-92
--------------------	----------------	---------------

Assessment Engineer(s)/Inspector(s):

Record the Nozzle Throat Diameter Measurements Below:

Degree Location	Diameter Measurement (inches)
0	<u>55.916</u>
45	<u>55.945</u>
90	<u>55.945</u>
135	<u>55.935</u>

Notes / Comments

Clarification Form(s)? Yes No Clarification Form Page No.(s): _____



POSTFLIGHT OBSERVATION RECORD (PFOR) C-11
Outer Boot Ring Char and Erosion Measurements and Flexible Boot Condition

Motor No.: 360T026 Side: Left (A) Date: 12-24-92

Assessment Engineer(s)/Inspector(s): WILKES

Flexible Boot/Outer Boot Ring Separation Observations:

A. Heat Effects in Boot/OBR Separation?

Yes _____ No Comment # _____

Record the Outer Boot Ring Char and Erosion Measurements Below:

Station Location	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
8.0		N/A *		N/A *		N/A *		N/A *
9.0								
10.0								
11.3								

Negative Margin of Safety? _____ Yes No _____ Station: _____ Degree: _____

Record the Number of Plies Remaining on the Flexible Boot:

Degree Location	Plies Remaining
0	3.5
90	3.0
180	3.6
270	3.9

Negative Margin of Safety? _____ Yes No _____ Degree: _____

Notes / Comments

* THE FORWARD HALF OF THE OUTER BOOT RING OVERBOARD WAS LOST AT MOTOR OPERATIONS. MOST OF THE AFT HALF WAS LOST IN AFT OPERATIONS AT CLEARFIELD.

Preliminary PFAR(s)? _____ Yes _____ No

Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes _____ No

Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-10
Throat Diameter Measurements (Data Collection Only)

Motor No.: 360T026	Side: Left (A)	Date: 11-1-92
--------------------	----------------	---------------

Assessment Engineer(s)/Inspector(s):

Record the Nozzle Throat Diameter Measurements Below:

Degree Location	Diameter Measurement (inches)
0	<u>55.94</u>
45	<u>55.94</u>
90	<u>55.94</u>
135	<u>55.95</u>

Notes / Comments

Clarification Form(s)? Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360T026 Side: Left (A) Date: 10-12-92

Assessment Engineer(s)/Inspector(s): L. WILKES / T. FRESTON

Phenolic Subassembly: Aft Exit Cone Assembly

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location					total
	4-70	70-143	143-215	215-275	275-0-4	
Metal-to-Adhesive	20*	7	3	4	40*	15
Within Adhesive						
Adhesive-to-GCP						
Within GCP	80	93	97	96	60	85
GCP-to-CCP						
Within CCP						

* SEE CLARIFICATION FORM PAGE C-15B AND PFAR NO. 47C-19.

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location					total
	4-70	70-143	143-215	215-275	275-0-4	
Metal-to-Adhesive		1	15	1	3	
Within Adhesive					1	
Adhesive-to-GCP	100	99	85	99	96	

Phenolic Removal Method: VERY DIFFICULT WEDGE & PEEL

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?		<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input checked="" type="checkbox"/>		1
C. Corrosion?	<input checked="" type="checkbox"/>		3
D. Foreign Material?		<input checked="" type="checkbox"/>	
E. Voids in Polysulfide (Aft Exit Cone Polysulfide Groove)?		<input checked="" type="checkbox"/>	4

Notes / Comments

① SEE CLARIFICATION FORM PAGE C-15A

② Special Issues 3.3.6 — NO FOREIGN MATERIAL WAS FOUND. A VERY LARGE METAL-TO-ADHESIVE SEPARATION WITH CORROSION WAS OBSERVED OVER THIS AREA. SEE CLARIFICATION FORM PAGE C-15B.

③ LIGHT-TO-MEDIUM CORROSION OBSERVED IN 2 LARGE METAL-TO-ADHESIVE SEPARATIONS. SEE CLARIFICATION FORM PAGE C-15B.

④ NO LARGE POLYSULFIDE VOIDS, 0.20 INCH DIAMETER MINIMUM, WERE OBSERVED.

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): 47C-19

Clarification Form(s)? Yes No Clarification Form Page No. (s): C-15A, C-15B, C-15C

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360T026 Side: Left (A) Date: 10-12-92
 Assessment Engineer(s)/Inspector(s): L. WILKES / T. FRESTON
 Phenolic Subassembly: Aft Exit Cone Assembly

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location					
	4-70	70-143	143-215	215-275	275-0-4	total
Metal-to-Adhesive	20*	7	3	4	40*	15
Within Adhesive						
Adhesive-to-GCP						
Within GCP	80	93	97	96	60	95
GCP-to-CCP						
Within CCP						

* SEE CLARIFICATION FORM PAGE C-15B AND PFAR NO. 47C-19.

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location					
	4-70	70-143	143-215	215-275	275-0-4	
Metal-to-Adhesive		1	15	1	3	
Within Adhesive					1	
Adhesive-to-GCP	100	99	85	90	96	

Phenolic Removal Method: VERY DIFFICULT WEDGE & PEEL

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
C. Corrosion?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	3
D. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
E. Voids in Polysulfide (Aft Exit Cone Polysulfide Groove)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	4

Notes / Comments
 ① SEE CLARIFICATION FORM PAGE C-15A
 ② Adhesive in contact with tip of shear pins and GCP.
 ③ Special Issues 3.3.6 - NO TOXIC MATERIAL WAS FOUND. A VERY LARGE METAL-TO-ADHESIVE SEPARATION WITH CORROSION WAS OBSERVED OVER THIS AREA. SEE CLARIFICATION FORM PAGE C-15B.
 ④ LIGHT-TO-MEDIUM CORROSION OBSERVED IN 2 LARGE METAL-TO-ADHESIVE SEPARATIONS. SEE CLARIFICATION FORM PAGE C-15B.
 ⑤ NO LARGE POLYSULFIDE VOIDS, 0.20 INCH DIAMETER MINIMUM, WERE OBSERVED.

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): 47C-19
 Clarification Form(s)? Yes No Clarification Form Page No.(s): C-15A, C-15B, C-15C

Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: 360T026 Side: Left (A) Right (B) Date: 10-12-92
 Assessment Engineer(s)/Inspector(s): L. WILKES / T. FRESTON
 Nozzle Subassembly: AFT EXIT CONE ASSEMBLY

Record Bondline Adhesive Void Measurements and Locations Below:

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd	Distance From Aft
215	2.00	0.65	1.40	_____
107	0.70	0.40	4.25	_____
78°	3.10	0.80	1.90	_____
11°	1.35	0.55	10.20	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____


Notes / Comments: VERY FEW SMALL ADHESIVE VOIDS, 0.30 DIAMETER MAXIMUM, WERE OBSERVED

Corresponding Comment Number(s): _____

General Hardware Clarification Form

Motor No.: 360T026	Side: <input checked="" type="checkbox"/> Left (A) <input type="checkbox"/> Right (B)	Date: 10-12-92
Assessment Engineer(s)/Inspector(s): L. WILKES / T. FRESTON		
Description: AFT EXIT CONE ASSEMBLY		

Sketch Observations Below (include locations and sizes of sketched features):



Corresponding Comment Number(s): _____

General Hardware Clarification Form

Motor No.: 360T026	Side: <input checked="" type="checkbox"/> Left (A) <input type="checkbox"/> Right (B)	Date: 3-12-93
--------------------	---	---------------

Assessment Engineer(s)/Inspector(s): L. WILKES

Description: NOZZLE AFT EXIT CONE LINER FRAGMENTS

Sketch Observations Below (include locations and sizes of sketched features):

THREE LARGE AEC CCP LINER FRAGMENTS WERE RECOVERED FROM INSIDE MOTOR AT KSC HANGAR AF. FRAGMENTS RANGED IN SIZE FROM FIVE INCHES TO APPROXIMATELY 15 INCHES AND WERE APPROXIMATELY 160 DEGREES CIRCUMFERENTIAL. NO AXIAL ORIENTATION FEATURES WERE PRESENT, THEREFORE EROSION AND CHAR CALCULATION COULD NOT BE DONE. EACH FRAGMENT WAS SECTIONED IN TWO PLACES APPROXIMATELY 45 DEGREES APART AND EXAMINED. NO PLY LIFTING WAS OBSERVED ON ANY OF THE SECTIONS. NO OTHER ANOMALOUS CONDITION WAS OBSERVED.

Corresponding Comment Number(s): _____

General Hardware Clarification Form

Motor No.: 360T026 Side: Left (A) Right (B) Date: 3-12-93

Assessment Engineer(s)/Inspector(s): L. WILKES

Description: NOZZLE AFT EXIT CONE LINER FRAGMENTS

Sketch Observations Below (include locations and sizes of sketched features):

THREE LARGE AEC CCP LINER FRAGMENTS WERE RECOVERED FROM INSIDE MOTOR AT KSC HANGAR AF. FRAGMENTS RANGED IN SIZE FROM FIVE INCHES TO APPROXIMATELY 15 INCHES AND WERE APPROXIMATELY 160 DEGREES CIRCUMFERENTIAL. NO AXIAL ORIENTATION FEATURES WERE PRESENT, THEREFORE EROSION AND CHAR CALCULATIONS COULD NOT BE DONE. EACH FRAGMENT WAS SECTIONED IN TWO PLACES APPROXIMATELY 45 DEGREES APART AND EVALUATED. NO PLYLIFTING WAS OBSERVED ON ANY OF THE SECTIONS. NO OTHER ANOMALIOUS CONDITION WAS OBSERVED.

Corresponding Comment Number(s): _____



POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360T026 Side: Left (A) Date: 10-6-92

Assessment Engineer(s)/Inspector(s): R. QUIRK, R. TELLERS, J. WALKER, R. LANGE

Phenolic Subassembly: Forward Exit Cone Assembly

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0
Metal-to-Adhesive	60%	75%	50%	20%	20%	65%	65%	60%
Within Adhesive	5%	5%	10%	15%	15%	5%	10%	5%
Adhesive-to-GCP	35%	20%	40%	65%	65%	30%	25%	25%
Within GCP								
GCP-to-CCP								
Within CCP								

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

N/A

	Degree Location							
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								

Phenolic Removal Method: _____

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?		<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input checked="" type="checkbox"/>		SEE PGC-16A
C. Corrosion?	<input checked="" type="checkbox"/>		
D. Foreign Material?		<input checked="" type="checkbox"/>	

Notes / Comments *1- MEDIUM TO HEAVY CORROSION ON AFT 10.0 INCHES
LIGHT TO MEDIUM CORROSION 5.0 AFT OF SHEAR PINS AND
BAND IS APPROX 7.0 INCHES WIDE*

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No. (s): C-16A

Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: 36T026 Side: Left (A) Right (B) Date: _____
 Assessment Engineer(s)/Inspector(s): QUICK-WALKER-TELLERS-LANGE
 Nozzle Subassembly: FWD EXIT CONE

Record Bondline Adhesive Void Measurements and Locations Below:

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd	Distance From Aft
<u>50°</u>	<u>1.0</u>	<u>.60</u>	_____	<u>9.1</u>
<u>225°</u>	<u>1.5</u>	<u>.70</u>	_____	<u>6.4</u>
<u>230°</u>	<u>1.9</u>	<u>1.1</u>	<u>0.0</u>	_____
<u>235°</u>	<u>1.2</u>	<u>1.0</u>	<u>2.08</u>	_____
<u>238°</u>	<u>.50</u>	<u>.30</u>	_____	<u>11.3</u>
<u>265°</u>	<u>1.10</u>	<u>1.70</u>	_____	<u>11.4</u>
<u>285°</u>	<u>1.3</u>	<u>1.3</u>	<u>1.3</u>	_____
<u>287°</u>	<u>2.0</u>	<u>.9</u>	<u>11.7</u>	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Notes / Comments

Corresponding Comment Number(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360T026 Side: Left (A) Date: 10-5-92

Assessment Engineer(s)/Inspector(s): *R. QUICK T. FRESTON*

Phenolic Subassembly: Throat Assembly

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location								
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	270-315	315-0
Metal-to-Adhesive	100%	100%	100%	100%	97%	100%	100%	100%	100%
Within Adhesive									
Adhesive-to-GCP					3%				
Within GCP									
GCP-to-CCP									
Within CCP									

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

NA

	Degree Location							
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								

Phenolic Removal Method: _____

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?		<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input checked="" type="checkbox"/>		<i>SEE Pg C-17A</i>
C. Corrosion?	<input checked="" type="checkbox"/>		
D. Foreign Material?		<input checked="" type="checkbox"/>	

Notes / Comments

Special Issues 3.3.4 *AFT SHIMS IMPROVED THE DISTRIBUTION OF ADHESIVE AND REDUCED THE VOIDS GREATLY*
1. MEDIUM TO HEAVY CORROSION FULL CIRCUMFERENCE

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No. (s): C-17A

Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: 360T026 Side: Left (A) Right (B) Date: 10-5-92

Assessment Engineer(s)/Inspector(s): R. QUICK T. FRESTON

Nozzle Subassembly: THROAT ASSEMBLY

Record Bondline Adhesive Void Measurements and Locations Below:

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd	Distance From Aft
50°	1.0	.28	_____	12.0
310°	.86	.25	_____	17.9
311°	.60	.22	_____	17.9
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Notes / Comments

Corresponding Comment Number(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360T026 Side: Left (A) Date: 10-5-72

Assessment Engineer(s)/Inspector(s): WILKES / MILLER

Phenolic Subassembly: Aft Inlet/Forward Nose Rings

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	45-135	135-225	225-315	315-360				
Metal-to-Adhesive	100	99	100	97				
Within Adhesive		1						
Adhesive-to-GCP				3				
Within GCP								
GCP-to-CCP								
Within CCP								

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

N/A

	Degree Location							
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								

Phenolic Removal Method: NYLON WEDGE & HAMMER

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?		<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input checked="" type="checkbox"/>		1
C. Corrosion?	<input checked="" type="checkbox"/>		2
D. Foreign Material?		<input checked="" type="checkbox"/>	

Notes / Comments ① SEE CLARIFICATION FORM PAGE C-18A

② LIGHT-TO-MEDIUM CORROSION OVER AXIAL LENGTH & CIRCUMFERENCE EXCEPT TWO PLACES ON AFT TO MID 4.00 INCHES OF AFT INLET RING (-504) INTERFACE AT 0°-25° AND 155°-205° SHOWED NO CORROSION

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No.(s): C-18A

Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: 360T026 Side: Left (A) Right (B) Date: 10-5-92

Assessment Engineer(s)/Inspector(s): WILKES / MILLER

Nozzle Subassembly: AFT INLET & FORWARD NOSE RINGS

Record Bondline Adhesive Void Measurements and Locations Below:

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd	Distance From Aft
175	0.80	0.50	1.30	
224	0.40	0.30	1.80	

Notes / Comments: VERY FEW SMALL VOIDS, 0.30 INCH DIAMETER MAXIMUM, WERE OBSERVED.

Corresponding Comment Number(s): 1

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360T026 Side: Left (A) Date: 10-5-92

Assessment Engineer(s)/Inspector(s): WILKES/MILLER

Phenolic Subassembly: Nose Cap

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	0-360							
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								
Within GCP	5							
GCP-to-CCP	95							
Within CCP								

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
	45-135	135-225	225-315	315-360				
Metal-to-Adhesive	30	25	25	20				
Within Adhesive								
Adhesive-to-GCP	70	75	75	80				

Phenolic Removal Method: _____

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?		✓	
B. Voids in Adhesive?	✓		1
C. Corrosion?	✓		2
D. Foreign Material?		✓	

Notes / Comments ① SEE CLARIFICATION FORM PAGE C-19A.

② LIGHT-TO-MEDIUM ON FORWARD 0.25-1.50 INCHES AND AFT 2.00-3.00 INCHES AROUND FULL CIRCUMFERENCE.

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No. (s): C-19A

Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: 360T026 Side: Left (A) Right (B) Date: 10-5-92

Assessment Engineer(s)/Inspector(s): WILKES / MILLER

Nozzle Subassembly: NOSE CAP

Record Bondline Adhesive Void Measurements and Locations Below:

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd	Distance From Aft
35B	0.50	0.30	10.10	

Notes / Comments VERY FEW SMALL VOIDS, 0.30 INCH DIAMETER MAXIMUM, WERE OBSERVED

Corresponding Comment Number(s): 1

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360T026	Side: Left (A)	Date: 10-6-92
Assessment Engineer(s)/Inspector(s): <i>R. QUICK T. FREESTON</i>		
Phenolic Subassembly: Cowl Assembly		

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0
Metal-to-Adhesive	100%	100%	100%	100%	100%	100%	100%	100%
Within Adhesive								
Adhesive-to-SCP								
Within SCP								
SCP-to-CCP								
Within CCP								

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

11F

	Degree Location							
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-SCP								

Phenolic Removal Method: _____

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>SEE PG C-20A</u>
C. Corrosion?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>1</u>
D. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments *1-LIGHT TO MEDIUM CORROSION 360*

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No. (s): C-20A

Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: 360T026

Side: Left (A) Right (B)

Date: 10-6-92


Assessment Engineer(s)/Inspector(s): R. QUICK T. FRESTON

Nozzle Subassembly: COWL ASSEMBLY

Record Bondline Adhesive Void Measurements and Locations Below:

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd	Distance From Aft
0°	1.2	.06	1.3	_____
1°	.75	.20	1.2	_____
40°	1.1	.03	1.2	_____
60°	1.75	.12	.7	_____
80°	1.8	.20	.8	_____
140°	1.8	.14	.8	_____
240°	.98	.18	1.7	_____
280°	2.1	.08	2.7	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Notes / Comments



Corresponding Comment Number(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360T026 Side: Left (A) Date: 10-2-92

Assessment Engineer(s)/Inspector(s): WILKES / FRESTON

Phenolic Subassembly: Fixed Housing Assembly

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location								AVG.
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-360	
Metal-to-Adhesive	75	49	25	40	65	95	80	85	64
Within Adhesive									
Adhesive-to-GCP	25	50	74	60	35	5	20	15	35
Within GCP		1	1						1
GCP-to-CCP									
Within CCP									

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

N/A

	Degree Location							
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								

Phenolic Removal Method: LARGE HAMMER, NYLON WEDGES

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?		<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input checked="" type="checkbox"/>		1
C. Corrosion?		<input checked="" type="checkbox"/>	
D. Foreign Material?		<input checked="" type="checkbox"/>	

Notes / Comments: (1) SEE CLARIFICATION FORM PAGE C-21A

(2) Resin glaze on ID side of GCP on aft end intermittently. largest area is at 70°-150° with axial width of 7.0" max. Several small areas on fwd end. Largest at 95°-135°

(3) IBR removed on 10-9-92, Reference C-21D. with an axial width of 3.5" max

(4) After removal of remaining adhesive, stains where unband occurred remained on housing.

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): 47C-17, 47C-16

Clarification Form(s)? Yes No Clarification Form Page No. (s): C-21A, B, C, D, E



POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 36T026 Side: Left (A) Date: 10-2-92

Assessment Engineer(s)/Inspector(s): WILKES / FRESTON

Phenolic Subassembly: Fixed Housing Assembly

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location								AVG.
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-360	
Metal-to-Adhesive	75	49	25	40	65	95	80	85	64
Within Adhesive									
Adhesive-to-GCP	25	50	74	60	35	5	20	15	35
Within GCP		1	1						1
GCP-to-CCP									
Within CCP									

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

N/A

	Degree Location							
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								

Phenolic Removal Method: LARGE HAMMER, NYLON WEDGES

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?		<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input checked="" type="checkbox"/>		1
C. Corrosion?		<input checked="" type="checkbox"/>	
D. Foreign Material?		<input checked="" type="checkbox"/>	

Notes / Comments: (1) SEE CLARIFICATION FORM PAGE C-21A

(2) Resin glue on ID end of GCP on aft end intermittently. largest area is at 10-150. A several small areas on the side at 45-135 with an axial width of 3.5" max

(3) IEK removed on 10-9-92, Reference C-21D.

(4) After removal of remaining adhesive, stain where unband occurred remained on housing.


Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): 47C-17, 47C-16

Clarification Form(s)? Yes No Clarification Form Page No. (s): C-21A, B, C, D, E

General Hardware Clarification Form

Motor No.: 360T026	Side: <input checked="" type="checkbox"/> Left (A) <input type="checkbox"/> Right (B)	Date: 10-2-92
Assessment Engineer(s)/Inspector(s): WILKES		
Description: FIXED HOUSING BONDLINE ADHESIVE STAIN MAP		

Sketch Observations Below (include locations and sizes of sketched features):




Corresponding Comment Number(s): _____



General Hardware Clarification Form

Motor No.: 360T026	Side: <input checked="" type="checkbox"/> Left (A) <input type="checkbox"/> Right (B)	Date: 10-2-92
Assessment Engineer(s)/Inspector(s): WILKES		
Description: FIRED HOLDING BONDLINE ADHESIVE STAIN MAP		

Sketch Observations Below (include locations and sizes of sketched features):



Corresponding Comment Number(s): _____

REVISION _____


General Hardware Clarification Form

Motor No.: 360T026 Side: Left (A) Right (B) Date: 10-5-92

Assessment Engineer(s)/Inspector(s): L.E. WILKES

Description: BOOT ASSEMBLY-TO-FIXED HOUSING PHENOLIC BONDLINE

Sketch Observations Below (include locations and sizes of sketched features):



BONDLINE 1 FAILURE MODE IBR-TO-FIXED HSG PHENOLICS	PERCENT OF CIRCUMFERENCE
FIXED HSG-TO-ADHESIVE	10
WITHIN ADHESIVE	5
IBR-TO- ADHESIVE	85

BONDLINE 2 FAILURE MODE FLEX BOOT-TO-FIXED HSG CCP	PERCENT OF CIRCUMFERENCE
WITHIN FIXED HSG CHARRED CCP	7
WITHIN INNER BOOT RING GCP	7
WITHIN FLEXIBLE BOOT NBR	73
ADHESIVE-TO-FIXED HSG CCP	9
WITHIN ADHESIVE	4

Corresponding Comment Number(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360T026	Side: Left (A)	Date: 10-9-92
Assessment Engineer(s)/Inspector(s): M. Clark, T. Freston		
Phenolic Subassembly: IBR		

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location				Total
	315-45	45-135	135-225	225-315	
Metal-to-Adhesive	30	25	5	50	28
Within Adhesive	15	30	15	15	18
Adhesive-to-GCP	20	25	40	5	22
Within GCP	35	20	40	30	32
GCP-to-CCP					
Within CCP					

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location				Total
	315-45	45-135	135-225	225-315	
Metal-to-Adhesive		2	5	10	4
Within Adhesive					
Adhesive-to-GCP	100	99	95	90	96

Phenolic Removal Method: hand & wedges

Metal Housing Bondline Surface Observations:	Yes	No	Comment #
A. Soot?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____
B. Voids in Adhesive?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
C. Corrosion?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	2
D. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____

Notes / Comments

- 1) Intermittent small voids with diameters of 0.30" or smaller
- 2) Light to medium corrosion intermittently in areas of metal-to-adhesive separations
- 3) Bulk of metal-to-adhesive separations occurred on aft end of bondline
- 4) The fixed housing insulation was removed 1 week ago (10/2/92)

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No. (s): _____



General Hardware Clarification Form

Motor No.: 360T026 Side: Left (A) Right (B) Date: 10-5-92
 Assessment Engineer(s)/Inspector(s): T. FRESTON / L. WILKES
 Description: FIXED HOUSING BONDLINE METAL SURFACE HARDNESS

Sketch Observations Below (include locations and sizes of sketched features):

ROCKWELL - C HARDNESS MEASUREMENTS

AXIAL LOCATIONS	ANGULAR LOCATIONS			
	40°	170°	200°	240°
ADJACENT TO IBR				
HARDNESS *	48		47	
	48		47	
	50		47	
	49		45	
IN STAINED AREA				
HARDNESS *	47	48		46
	50	47		46
	50	47		48
	48	47		48
CLEAN SURFACE AREA				
HARDNESS *	46	45		46
	49	48		47
	50	46		47
	48	47		46

* HARDNESS MEASUREMENTS TAKEN AT APPROXIMATELY EQUAL DISTANCES APART OVER AXIAL LENGTH OF SURFACE CONDITION.

Corresponding Comment Number(s): _____



POSTFLIGHT OBSERVATION RECORD (PFOR) C-13
Cowl Ring Phenolic (CCP) Section Condition

Motor No.: 360T026 Side: Left (A) Date: 3-1-93

Assessment Engineer(s)/Inspector(s): WILKES

Cowl Phenolic Section Observations:

	Yes	No	Comment #
A. Cross-ply cracking in virgin material?	_____	✓	_____
B. Ply lifting?	_____	✓	_____

Record the Cowl Char and Erosion Measurements Below:

Station Location	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
0.3	.17	.70	.21	.60	.19	.66	.20	.64
1.0	.21	.67	.25	.59	.23	.62	.23	.67
2.0	.28	.67	.28	.62	.28	.59	.27	.62
3.0	.31	.66	.31	.62	.28	.65	.28	.65
4.0	NA	.98*	NA	.93*	.31	.66	.25	.71
5.0	NA	.96*	NA	.97*	.29	.67	NA	.93*
6.0	NA	NA	NA	NA	.18	.81	NA	.95*
6.8	NA	NA	NA	NA	.15	.87	NA	1.01*

Negative Margin of Safety? _____ Yes No _____ Station: _____ Degree: _____

Notes / Comments * TOTAL EROSION AND CHAR DEPTH.

Preliminary PFAR(s)? _____ Yes No _____ Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No _____ Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-14
Forward Exit Cone Phenolic (CCP) Section Condition

Motor No.: 360T026	Side: Left (A)	Date: 3-1-93
Assessment Engineer(s)/Inspector(s): WILKES		

Forward Exit Cone Phenolic Section Observations:	Yes	No	Comment #
A. Cross-ply cracking in virgin material?	_____	✓ _____	_____
B. Ply lifting?	_____	✓ _____	_____

Record the Forward Exit Cone Char and Erosion Measurements Below:

Station Location	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
1.0	.38	.71	.38	.80	.37	.76	.37	.75
4.0	.37	.70	.37	.73	.35	.72	.35	.68
4.6	.37	.70	.35	.77	.34	.71	.35	.69
8.0	.40	.68	.39	.70	.28	.73	.39	.68
12.0	NA	NA	NA	NA	NA	NA	NA	NA
16.0	↓	↓	↓	↓	↓	↓	↓	↓
20.0	↓	↓	↓	↓	↓	↓	↓	↓
24.0	↓	↓	↓	↓	↓	↓	↓	↓
28.0	.27	.72	.26	.71	.28	.72	.25	.73
32.0	.26	.74	.27	.75	.23	.70	.21	.71
32.9	.21	.75	.21	.76	.17	.74	.21	.69
34.0	.18	.80	.21	.76	NA	NA	.17	.70

Negative Margin of Safety? _____ Yes No Station: _____ Degree: _____

Notes / Comments

Preliminary PFAR(s)? _____ Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-15
Fixed Housing Phenolic (CCP) Section Condition

Motor No.: 360T026 Side: Left (A) Date: 3-3-93

Assessment Engineer(s)/Inspector(s): WILKES

Fixed Housing Phenolic Section Observations:

- A. Cross-ply cracking in virgin material?
B. Ply lifting?

Yes	No	Comment #
_____	<input checked="" type="checkbox"/>	_____
_____	<input checked="" type="checkbox"/>	_____

Record the Fixed Housing Char and Erosion Measurements Below:

Station Location	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
0.0	.11	1.16	.09	1.01	.07	1.14	.07	1.07
1.0	.06	1.07	.06	1.06	.06	1.05	.03	1.03
2.0	.01	1.08	.00	1.04	.00	1.01	.02	1.07
3.0	.02	1.07	↓	1.02	↓	1.04	.01	1.12
4.0	.02	1.03	↓	1.03	↓	1.01	.00	1.09
5.0	.01	1.04	↓	1.00	↓	.98	↓	1.10
6.0	.01	1.01	↓	1.01	↓	.95	↓	1.09
7.0	.00	1.02	↓	.93	↓	.96	↓	1.05
8.0	.00	.85	.00	.90	↓	.91	↓	.99
9.0	.00	.87	.01	.78	.00	.83	.00	.97
10.75	.12	1.82	.17	1.65	.05	1.69	.13	1.73

Negative Margin of Safety? _____ Yes No Station: _____ Degree: _____

Notes / Comments

Preliminary PFAR(s)? _____ Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-16
Throat Inlet Assembly Phenolic (CCP) Section Condition

Motor No.: 360T026 Side: Left (A) Date: 3-2-93

Assessment Engineer(s)/Inspector(s): WILKES

Throat Inlet Assembly Phenolic Section Observations:

	Yes	No	Comment #
A. Cross-ply cracking in virgin material?	_____	_____ <input checked="" type="checkbox"/>	_____
B. Ply lifting?	_____	_____ <input checked="" type="checkbox"/>	_____

Record the Throat Inlet Ring and Throat Ring Char and Erosion Measurements Below:

Station Location	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
1.0	1.09	.62	1.07	.55	1.02	.63	1.06	.60
2.0	1.13	.60	1.02	.57	1.06	.66	1.01	.60
4.0	1.20	.65	1.18	.63	1.10	.66	1.15	.64
6.0	1.23	.66	1.21	.61	1.16	.67	1.20	.69
8.0	1.26	.52	1.25	.51	1.19	.52	1.26	.53
10.0	1.19	.54	1.20	.57	1.13	.52	1.17	.51
12.0	1.16	.54	1.19	.58	1.14	.48	1.12	.52
14.0	1.14	.53	1.13	.63	1.12	.51	1.11	.50
16.0	1.07	.59	1.09	.68	1.06	.60	1.06	.55
18.0	.93	.67	.93	.70	.88	.66	.91	.65
20.0	.73	.76	.75	.72	.72	.73	.73	.73
22.0	.51	.82	.55	.78	.50	.86	.45	.86
23.0	.41	.81	.44	.84	.39	.89	.37	.89

Negative Margin of Safety? _____ Yes No Station: _____ Degree: _____

Notes / Comments

Preliminary PFAR(s)? _____ Yes No Preliminary PFAR Number(s): _____
 Clarification Form(s)? _____ Yes No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-17
Nose Cap Phenolic (CCP) Section Condition

Motor No.: 360T026 Side: Left (A) Date: 3-3-93

Assessment Engineer(s)/Inspector(s): WILKES

Nose Cap Phenolic Section Observations:

	Yes	No	Comment #
A. Cross-ply cracking in virgin material?	_____	<input checked="" type="checkbox"/>	_____
B. Ply lifting?	_____	<input checked="" type="checkbox"/>	_____

Record the Nose Cap Char and Erosion Measurements Below:

Station Location	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
1.5	NA	.93 *	NA	.87 *	NA	.83 *	NA	.88 *
4.0	.33	.60	.25	.62	.33	.53	.36	.64
6.0	.35	.59	.34	.57	.33	.50	.31	.59
8.0	.35	.60	.44	.53	.35	.50	.40	.60
10.0	.38	.63	.41	.58	.37	.50	.43	.57
12.0	.50	.56	.47	.53	.43	.51	.48	.50
14.0	.57	.57	.55	.43	.50	.51	.51	.49
16.0	.73	.49	.59	.43	.64	.55	.61	.55
18.0	.80	.50	.71	.42	.73	.53	.72	.46
20.0	1.07	.42	.98	.44	.94	.55	.92	.48
22.0	1.65	.67	1.49	.72	1.46	.62	1.50	.65
24.0	1.84	.65	1.67	.75	1.59	.68	1.75	.68
26.0	1.28	.71	1.18	.71	1.05	.77	1.31	.87

Negative Margin of Safety? _____ Yes No Station: _____ Degree: _____

Notes / Comments * TOTAL DEPTH, EROSION PLUS CHAR

Preliminary PFAR(s)? _____ Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-18
Forward Nose Ring and Aft Inlet Ring Phenolic (CCP) Section Condition

Motor No.: 360T026	Side: Left (A)	Date: 3-2-93
--------------------	----------------	--------------

Assessment Engineer(s)/Inspector(s): WILKES

Forward Nose and Aft Inlet Ring Phenolic Section Observations:	Yes	No	Comment #
A. Cross-ply cracking in virgin material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____
B. Ply lifting?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____

Record the Forward Nose Ring (-503) Char and Erosion Measurements Below:

Station	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
28.0	<u>.14</u>	<u>.62</u>	<u>.12</u>	<u>.55</u>	<u>1.05</u>	<u>.71</u>	<u>1.01</u>	<u>.72</u>
30.0	<u>.89</u>	<u>.67</u>	<u>.91</u>	<u>.65</u>	<u>.83</u>	<u>.62</u>	<u>.87</u>	<u>.74</u>
32.0	<u>.97</u>	<u>.63</u>	<u>.97</u>	<u>.66</u>	<u>.94</u>	<u>.63</u>	<u>.98</u>	<u>.63</u>

Negative Margin of Safety? _____ Yes No Station: _____ Degree: _____

Record the Aft Inlet Ring Char (-504) and Erosion Measurements Below:

Station	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
34.0	<u>.89</u>	<u>.55</u>	<u>.91</u>	<u>.52</u>	<u>.86</u>	<u>.56</u>	<u>.92</u>	<u>.52</u>
36.0	<u>.87</u>	<u>.60</u>	<u>.89</u>	<u>.56</u>	<u>.87</u>	<u>.58</u>	<u>.94</u>	<u>.48</u>
38.0	<u>.98</u>	<u>.59</u>	<u>.95</u>	<u>.61</u>	<u>.95</u>	<u>.65</u>	<u>.97</u>	<u>.63</u>
39.0	<u>.99</u>	<u>.61</u>	<u>.96</u>	<u>.66</u>	<u>.98</u>	<u>.64</u>	<u>1.03</u>	<u>.59</u>

Negative Margin of Safety? _____ Yes No Station: _____ Degree: _____

Notes / Comments

Preliminary PFAR(s)? _____ Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-1
Nozzle Assembly Quick-look Condition

Motor No.: 360T026 Side: Right (B) Date: 9-25-92

Assessment Engineer(s)/Inspector(s): M. Clark, T. Freston

Nozzle Assembly Quick-look Observations:	Yes	No	Comment #
A. Metal Damage Due to Transportation or Handling?	_____	✓	_____
B. Phenolic Damage Due to Transportation or Handling?	✓	_____	1
C. Foreign Material?	_____	✓	_____

Notes / Comments
 Damaged phenolic
 1) Area between 351°-0°-5° on nose cap forward end and -503 forward inlet ring. The area measured 7.5" radial by 6" circ. The deepest area was centered at 1° and measured 1.5" radial by 2.8" circ. by 0.55" deep from flow surface. The phenolic edges are sharp. This is centered on the Nosecap/Nose inlet ring bondline and appears to have been rubbed or worn. A preliminary PFAIR was written.
 2) Area of discoloration on forward exit cone aft shear pins at:
 172.5°, 3.3" circ. by 0.9" axial
 202.5°, 2.5" circ. by 1.0" axial
 270°, 2.4" circ. by 1.0" axial
 Area was observed at KSC. A preliminary PFAIR has been written. Samples were taken.

Preliminary PFAIR(s)? Yes No Preliminary PFAIR Number(s): 47C-01, 47C-02
 Clarification Form(s)? Yes No Clarification Form Page No. (s): _____



POSTFLIGHT OBSERVATION RECORD (PFOR) C-1
Nozzle Assembly Quick-look Condition

Motor No.: 360T026	Side: Right (B)	Date: 1-25-92
--------------------	-----------------	---------------

Assessment Engineer(s)/Inspector(s): M. Clark, T. Freston

Nozzle Assembly Quick-look Observations:	Yes	No	Comment #
A. Metal Damage Due to Transportation or Handling?	_____	✓	_____
B. Phenolic Damage Due to Transportation or Handling?	✓	_____	1
C. Foreign Material?	_____	✓	_____

Notes / Comments
 Damaged phenolic
 1) Area between 351°-0°-5° on nose cap forward end and -303
 facing inlet ring. The area measured 7.5" radial by 6" circ. The defect
 area was centered at 1" and measured 1.5" radial by 2.5" circ. by
 0.55" deep from flow surface. The phenolic edges are sharp. This is centered
 on the Nose cap/Nose inlet ring bandline and appears to have been
 rubbed or worn. A preliminary PFAIR was written.
 2) Area of discontinuity on forward exit cone of 4 description at:
 172.5°, 3.3" circ. by 0.9" axial
 202.5°, 2.5" circ. by 1.0" axial
 270°, 2.4" circ. by 1.0" axial
 None were observed at KSC. A preliminary PFAIR was written.
 Samples were taken.

Preliminary PFAIR(s)?	✓	Yes	_____	No	Preliminary PFAIR Number(s): 47C-01, 47C-02
Clarification Form(s)?	_____	Yes	✓	No	Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-2
Internal Nozzle Joint Condition

Motor No.: 360T026	Side: Right (B)	Date: 9-30-92
Assessment Engineer(s)/Inspector(s): M. Clark, R. Lange, J. Waller, T. Preston		
Joint: Nose Inlet-to-Flex Bearing-to-Cowl (Joint #2)		

Internal Nozzle Joint Observations:	Yes	No	Comment #
A. Gas Penetration in the RTV (Terminated, Through)?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
B. RTV Not Below Char Line?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
C. RTV To the Primary O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
D. RTV Past the Primary O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
E. Uncured RTV?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
F. Voids Within RTV?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
G. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
H. Heat Affected or Eroded Virgin CCP, GCP/SCP, or adhesive?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
I. Damaged Phenolics?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
J. Bondline Edge Separations? Use Clarification Form.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	2
K. Phenolics Axially Displaced From Housing?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
L. Heat Affected Metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
M. Unbonded or Blistered Paint?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
N. Corrosion?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	3
O. Excessive Grease in Threaded Bolt Holes?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
P. Bolt Hole Damage (Through, Threaded/Helical Coil Insert)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Q. Bent or Broken Bolts?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
R. Metal Damage (Joints or Housings)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments

1. SOOT TO PRI O-RING AND IN JOINT INTERMITTENTLY. GAS PAID AT 350° (47C-12)
2. REF PAGE C-29A
3. REF PAGE C-30 FOR LOCATION AND DESCRIPTION
4. FOREIGN MATERIAL IN BEARING/THROAT CAVITY. PPAR 47C-10.

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): 47C-10, -12, -13

Clarification Form(s)? Yes No Clarification Form Page No. (s): C-29A

POSTFLIGHT OBSERVATION RECORD (PFOR) C-3
Nose Inlet-to-Flex Bearing-to-Cowl Joint (Joint #2) Condition Drawing Worksheet


Motor No.: 360T026

Side: Right (B)

Date: 9-30-92

Assessment Engineer(s)/Inspector(s): M. Clark, R. Lange, J. Walker, T. Freston

Sketch Observations Below (include locations and sizes of sketched features):



- 1. LIGHT-MEDIUM CORROSION INTERMITTENTLY
- 2. TYP REV & ADHESIVE INTERMIXED WITH SEST ENTERING BETWEEN LAYERS
- 3. GAS PATH AT 350° Reference C-30A WITH HEAT AFFECTED CCP & GCP/SLP
- 4. TYP SECTIONS, LIGHT/MEDIUM INTERMITTENTLY
- 5. TYP LIGHT BURNISHING INTERMITTENTLY
- 6. WASHER WAS FOUND AT THE INTERSECTION OF FLEX BRG CORE AND FWD END RING 205° (47C-10)


Clarification Form(s)? Yes No

Clarification Form Page No.(s): C-30A

POSTFLIGHT OBSERVATION RECORD (PFOR) C-3
Nose Inlet-to-Flex Bearing-to-Cowl Joint (Joint #2) Condition Drawing Worksheet

Motor No.: 360T026	Side: Right (B)	Date: 9-30-92
Assessment Engineer(s)/Inspector(s): M. Clark, R. Lange, J. Walker, T. Freston		

Sketch Observations Below (include locations and sizes of sketched features):



- 2. TYP RTV & ADHESIVE INTERMIXED WITH SOOT ENTERING BETWEEN LAYERS
- 3. GAS PATH AT 350° Reference C-30A with heat affected CCP & GCP/SLP
- 4. TYP SOOTING, LIGHT/MEDIUM INTERMITTENTLY
- 5. TYP LIGHT BURNISHING INTERMITTENTLY
- 6. WASHER WAS FOUND AT THE INTERSECTION OF FLEX BRG CORE AND FWD ENDRING 265° (ATC-10)


Clarification Form(s)? Yes No Clarification Form Page No.(s): C-30A



General Hardware Clarification Form

Motor No.: 360T026	Side: <input type="checkbox"/> Left (A) <input checked="" type="checkbox"/> Right (B)	Date: 10-1-92
Assessment Engineer(s)/Inspector(s): M. Clark, B. Quick, T. Freston		
Description: Joint 2 Gaspath		

Sketch Observations Below (include locations and sizes of sketched features):



Corresponding Comment Number(s): 3

POSTFLIGHT OBSERVATION RECORD (PFOR) C-2
Internal Nozzle Joint Condition

Motor No.: 360T026

Side: Right (B)

Date: 9-30-92

Assessment Engineer(s)/Inspector(s): R. Quick

Joint: Nose Inlet-to-Throat (Joint #3)

Internal Nozzle Joint Observations:	Yes	No	Comment #
A. Gas Penetration in the RTV (Terminated, Through)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
B. RTV Not Below Char Line?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
C. RTV To the Primary O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
D. RTV Past the Primary O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
E. Uncured RTV?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
F. Voids Within RTV?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
G. Grease Inhibiting RTV Backfill?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
H. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
I. Heat Affected or Eroded Virgin CCP, GCP/SCP, or adhesive?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
J. Damaged Phenolics?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
K. Bondline Edge Separations? Use Clarification Form.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
L. Phenolics Axially Displaced From Housing?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
M. Heat Affected Metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
N. Unbonded or Blistered Paint?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
O. Corrosion?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	2
P. Alignment Pin Damage?	<input type="checkbox"/>	N/A	
Q. Excessive Grease in Threaded Bolt Holes?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
R. Bolt Hole Damage (Through, Threaded/Helical Coil Insert)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
S. Bent or Broken Bolts?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
T. Metal Damage (Joints or Housings)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments

Special Issues 3.2.3.2 - No SEAL SURFACE DAMAGE OR ATYPICAL CORROSION FOUND
1- SEE SHEET C-31A & C-31B.
2-TYPICAL LIGHT TO MEDIUM CORROSION UPSTREAM OF PRIMARY O-RING
INTERMITTENT 360° ON NOSE INLET HOUSING

Preliminary PFAR(s)? Yes No

Preliminary PFAR Number(s): 47C-11

Clarification Form(s)? Yes No

Clarification Form Page No.(s): C-31A & C-31B

POSTFLIGHT OBSERVATION RECORD (PFOR) C-4
Nose Inlet-to-Throat Joint (Joint #3) Condition Drawing Worksheet


Motor No.: 360T026

Side: Right (B)

Date: 9-30-92

Assessment Engineer(s)/Inspector(s): R. QUICK

Sketch Observations Below (include locations and sizes of sketched features):



- ⑥ CORROSION FROM SEA WATER 360°
- ⑦ RTV AT LOC 50°-60°, 65°-90°, 100°-130°

- ① SEPARATION IN THROAT INLET RING FROM 48°-138° MAX GAP = .058 @ 90°
- ② SEE SHEET C-31
- ③ NO EXCESS GREASE IN BOLT HOLES
- ④ RTV BELOW CHAR LINE 360°
- ⑤ SOOT TO CHAR LINE INTERMITTENT 360°

Clarification Form(s)? Yes No

Clarification Form Page No. (s): _____



POSTFLIGHT OBSERVATION RECORD (PFOR) C-2
Internal Nozzle Joint Condition

Motor No.: 360T026

Side: Right (B)

Date: 9-28-92

Assessment Engineer(s)/Inspector(s): *R. QUICK R. TELLERS*

Joint: Throat-to-Forward Exit Cone (Joint #4)

Internal Nozzle Joint Observations:

	Yes	No	Comment #
A. Gas Penetration in the RTV (Terminated, Through)?	_____	<input checked="" type="checkbox"/>	_____
B. RTV Not Below Char Line?	_____	<input checked="" type="checkbox"/>	_____
C. RTV To the Primary O-ring?	<input checked="" type="checkbox"/>	_____	<i>SEE Pg 34</i>
D. RTV Past the Primary O-ring?	_____	<input checked="" type="checkbox"/>	_____
E. Uncured RTV?	_____	<input checked="" type="checkbox"/>	_____
F. Voids Within RTV?	_____	<input checked="" type="checkbox"/>	_____
G. Grease Inhibiting RTV Backfill?	_____	<input checked="" type="checkbox"/>	_____
H. Foreign Material?	_____	<input checked="" type="checkbox"/>	_____
I. Heat Affected or Eroded Virgin CCP, GCP/SCP, or adhesive?	_____	<input checked="" type="checkbox"/>	_____
J. Damaged Phenolics?	_____	<input checked="" type="checkbox"/>	_____
K. Bondline Edge Separations? Use Clarification Form.	<input checked="" type="checkbox"/>	_____	<i>1</i>
L. Phenolics Axially Displaced From Housing?	_____	<input checked="" type="checkbox"/>	_____
M. Heat Affected Metal?	_____	<input checked="" type="checkbox"/>	_____
N. Unbonded or Blistered Paint?	_____	<input checked="" type="checkbox"/>	_____
O. Corrosion?	<input checked="" type="checkbox"/>	_____	<i>2</i>
P. Alignment Pin Damage?	_____	<input checked="" type="checkbox"/>	_____
Q. Excessive Grease in Threaded Bolt Holes?	_____	<input checked="" type="checkbox"/>	_____
R. Bolt Hole Damage (Through, Threaded/Helical Coil Insert)?	_____	<input checked="" type="checkbox"/>	_____
S. Bent or Broken Bolts?	_____	<input checked="" type="checkbox"/>	_____
T. Metal Damage (Joints or Housings)?	_____	<input checked="" type="checkbox"/>	_____

Notes / Comments

Special Issues 3.3.1 *NO DAMAGE TO BOLTS OR BOLT HOLES*
1 - SEE CLARIFICATION PAGE C-33A & C-33B
2 - MEDIUM CORROSION IN BOARD OF PRIMARY SEAL SURFACE ON THROAT FULL CIRCUMFERENCE, LIGHT CORROSION ON SECONDARY SEAL SURFACE AND BETWEEN PRIMARY AND SECONDARY SEAL SURFACE OF FWD EXIT CONE AND MATING SURFACES ON THROAT INTERMITTENT FULL CIRCUMFERENCE

Preliminary PFAR(s)? _____ Yes No

Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes _____ No

Clarification Form Page No. (s): *C-33A & C-33B*








POSTFLIGHT OBSERVATION RECORD (PFOR) C-5
Throat-to-Forward Exit Cone Joint (Joint #4) Condition Drawing Worksheet

Motor No.: 360T026	Side: Right (B)	Date: 9-28-92
--------------------	-----------------	---------------

Assessment Engineer(s)/Inspector(s): R. QUICK, R. TELLERS

Sketch Observations Below (include locations and sizes of sketched features):



Clarification Form(s)? Yes No

Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-2
Internal Nozzle Joint Condition

Motor No.: 360T026	Side: Right (B)	Date: 9-29-72
Assessment Engineer(s)/Inspector(s): M.E. Clark, T. Freston		
Joint: Aft End Ring-to-Fixed Housing (Joint #5)		

Internal Nozzle Joint Observations:	Yes	No	Comment #
A. Gas Penetration in the RTV (Terminated, Through)?	_____	✓	_____
B. RTV Not Below Char Line?	_____	✓	_____
C. RTV To the Primary O-ring?	_____	✓	_____
D. RTV Past the Primary O-ring?	_____	✓	_____
E. Uncured RTV?	_____	✓	_____
F. Voids Within RTV?	✓	_____	1
G. Foreign Material?	_____	✓	_____
H. Heat Affected or Eroded Virgin CCP, GCP/SCP, or adhesive?	_____	✓	_____
I. Damaged Phenolics?	_____	✓	_____
J. Bondline Edge Separations? Use Clarification Form.	_____	✓	_____
K. Phenolics Axially Displaced From Housing?	_____	✓	_____
L. Heat Affected Metal?	_____	✓	_____
M. Unbonded or Blistered Paint?	✓	_____	3
N. Corrosion?	✓	_____	2
O. Alignment Pin Damage?	_____	✓	_____
P. Excessive Grease in Threaded Bolt Holes?	_____	✓	_____
Q. Bolt Hole Damage (Through, Threaded/Helical Coil Insert)?	_____	✓	_____
R. Bent or Broken Bolts?	_____	✓	_____
S. Metal Damage (Joints or Housings)?	_____	✓	_____

Notes / Comments

- 1) Typical encapsulated voids due to assembly process.
- 2) Corrosion documented on ^{page} DWAC-36.
- 3) AREA OF PAINT THAT HAS SMALL BUBBLES FROM 90°-180° ON I D OF HOUSING 16.0 IN. FROM AFT FACE OF MOUNTING FLANGE. NO HEAT AFFECT


Preliminary PFAF(s)? _____ Yes No _____ Preliminary PFAF Number(s): _____

Clarification Form(s)? _____ Yes No _____ Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-6
Aft End Ring-to-Fixed Housing Joint (Joint #5) Condition Drawing Worksheet

Motor No.: 360T026	Side: Right (B)	Date: 9-29-92
Assessment Engineer(s)/Inspector(s): M.E. Clark, T. Freston		*REVISED 10-5-92 LEW

Sketch Observations Below (include locations and sizes of sketched features):



- 1) Nominal Grease
No Corrosion
- 2) Intermittent + Light-to-medium corrosion
- 3) Typical coating of soot

4) RTU condition was nominal. Typical encapsulated voids from assembly.

Clarification Form(s)? Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-7
Cowl Insulation Segment Condition

Motor No.: 360T026	Side: Right (B)	Date: 9/29/92
--------------------	-----------------	---------------

Assessment Engineer(s)/Inspector(s): *R. Quick R. Tellers*

Cowl Insulation Segment Observations:	Yes	No	Comment #
A. Spring Pin Holes Completely Through the Cowl Segment?	_____	✓	_____
B. Abnormal Heat Effects or Erosion?	_____	✓	_____
C. Soot Between the Cowl Segment and Cowl Housing?	_____	✓	_____
D. Bondline Failure Mode? Data Collection Only.	N/A	N/A	_____

Notes / Comments
3% Within Segment
85% Rubber to Adhesive Failure
12% Co adhesive Failure

Pin Location 0 - 360 adhesive from silica pin
extruded To I.D. of cowl housing intermittent.
Appx. 1.3 inch Diameter

Preliminary PFAR(s)? _____ Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No Clarification Form Page No.(s): _____



POSTFLIGHT OBSERVATION RECORD (PFOR) C-8
Flexible Bearing, Flexible Bearing Protector, and Flexible Boot Condition

Motor No.: 360T026

Side: Right (B)

Date: 9-29-92

Assessment Engineer(s)/Inspector(s): M.E. Clark, T. Freston

Flexible Bearing, Bearing Protector, and Boot Observations:

	Yes	No	Comment #
A. Bearing Protector Burn-Through?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
B. Cracks Through the Bearing Protector?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
C. Bearing Protector Heat Effects or Erosion Other Than at Cowl Vent Hole Locations?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
D. Soot Between the Bearing Protector and Flexible Bearing?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
E. Heat Effects to the Flexible Bearing?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
F. Bent or Broken Bearing Protector Bolts?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
G. Flexible Boot Burn-Through?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
H. Abnormal Heat Effects or Erosion to Flexible Boot ID?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
I. Foreign Material in Boot Cavity?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1

Notes / Comments

Special Issues 3.3.2, 3.3.3 and 3.3.5

3.3.2 No abnormal erosion on flex boot.

3.3.3 No abnormal erosion on flex boot

3.3.5 No BENT OR BROKEN BOLTS

1) Two areas of erosion other than cowl vent location on belly band. Reference C-38A for size and locations. Slag found in cavity is same location as erosion. Preliminary PFAR has been written.

Preliminary PFAR(s)? Yes No

Preliminary PFAR Number(s): 47C-05

Clarification Form(s)? Yes No

Clarification Form Page No.(s): C-38A


Flexible Boot Cavity Clarification Form

Motor No.: 360T026	Side: <input type="checkbox"/> Left (A) <input checked="" type="checkbox"/> Right (B)	Date: 9-29-92
Assessment Engineer(s)/Inspector(s): M.E. Clark, T. Freston		
Description: Boot Cavity Conditions		

Sketch Observations Below (include locations and sizes of sketched features):

3) Bubbles on cowl segments at 260°-360° average size = 0.25" dia.

- 1) Erosion areas not at the vent hole impingement
 - a) 4.8" circ x 1.8" axial x .12" deep 1.4" aft of belly Band, 132°
 - b) 1.6" circ x .85" axial x shallow depth. Can not be measured, 4.4" aft of belly, 133°



2) Deepest erosion on belly band occurred at 10°. The cowl vent hole was open with plugging with slag when it was removed from segment

The remaining material thickness at 180° will be recorded on C-39.

4) Fluid observed on bearing protector at 50°-90° in and forward of belly band. Fluid has been observed on previous motors and is the result of the thermal degradation of the bearing protector material

Corresponding Comment Number(s): 1


POSTFLIGHT OBSERVATION RECORD (PFOR) C-9
Flexible Bearing Protector Thickness Measurements

Motor No.: 360T026 Side: Right (B) Date: 10-14-92

Assessment Engineer(s)/Inspector(s): P.R. Gallegos / D. TURNALL

Record the Flexible Bearing Protector Gas Impingement Area Thickness Measurements (see figure) Below:

Degree Location	Thickness Measurement "A"* (inches)	Degree Location	Thickness Measurement "A"* (inches)	Degree Location	Thickness Measurement "A"* (inches)
0	<u>.1654</u>	120	<u>.1653</u>	240	<u>.1653</u>
10	<u>.1696</u>	130	<u>.1610</u>	250	<u>.1693</u>
20	<u>.1699</u>	140	<u>.1646</u>	260	<u>.1650</u>
30	<u>.1675</u>	150	<u>.1658</u>	270	<u>.1684</u>
40	<u>.1686</u>	160	<u>.1670</u>	280	<u>.1671</u>
50	<u>.1691</u>	170	<u>.1668</u>	290	<u>.1686</u>
60	<u>.1683</u>	180	<u>.1670</u>	300	<u>.1692</u>
70	<u>.1694</u>	190	<u>.1671</u>	310	<u>.1704</u>
80	<u>.1677</u>	200	<u>.1673</u>	320	<u>.1705</u>
90	<u>.1688</u>	210	<u>.1691</u>	330	<u>.1703</u>
100	<u>.1650</u>	220	<u>.1691</u>	340	<u>.1697</u>
110	<u>.1654</u>	230	<u>.1699</u>	350	<u>.1689</u>



* "A" is the minimum thickness of the bearing protector in-line with the cowl vent holes. It corresponds to the deepest gas impingement location.

Notes / Comments

SL 47230

NOTE: At Approx. 12° there is a divit that checks .532"

Preliminary PFAR(s)? Yes No

Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No

Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-10
Throat Diameter Measurements (Data Collection Only)


Motor No.: 360T026 Side: Right (B) Date: 10-1-82

Assessment Engineer(s)/Inspector(s):

Record the Nozzle Throat Diameter Measurements Below:

Degree Location	Diameter Measurement (inches)
0	<u>55.885</u>
45	<u>55.885</u>
90	<u>55.870</u>
135	<u>55.870</u>

Notes / Comments



Clarification Form(s)? Yes No Clarification Form Page No. (s): _____

REVISION _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-10
Throat Diameter Measurements (Data Collection Only)

Motor No.: 360T026

Side: Right (B)

Date: 10-1-92

Assessment Engineer(s)/Inspector(s):

Record the Nozzle Throat Diameter Measurements Below:

Degree Location	Diameter Measurement (inches)
0	<u>55.888</u>
45	<u>55.885</u>
90	<u>55.890</u>
135	<u>55.890</u>

Notes / Comments

Clarification Form(s)? Yes No

Clarification Form Page No.(s): _____



POSTFLIGHT OBSERVATION RECORD (PFOR) C-11
Outer Boot Ring Char and Erosion Measurements and Flexible Boot Condition

Motor No.: 360T026	Side: Right (B)	Date: 12-24-92
--------------------	-----------------	----------------

Assessment Engineer(s)/Inspector(s): WILKES

Flexible Boot/Outer Boot Ring Separation Observations:

A. Heat Effects in Boot/OBR Separation?	Yes	No <input checked="" type="checkbox"/>	Comment #
---	-----	--	-----------

Record the Outer Boot Ring Char and Erosion Measurements Below:

Station Location	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
8.0	<u>NA</u>	<u> </u>						
9.0	<u>.01</u>	<u>.98</u>	<u>NA</u>	<u> </u>	<u>NA</u>	<u> </u>	<u>.10</u>	<u>1.18</u>
10.0	<u>.03</u>	<u>.97</u>	<u>.01</u>	<u>1.33</u>	<u>.09</u>	<u>1.10</u>	<u>.11</u>	<u>1.19</u>
11.3	<u>.05</u>	<u>1.09</u>	<u>.00</u>	<u>1.14</u>	<u>.07</u>	<u>1.17</u>	<u>.09</u>	<u>1.28</u>

Negative Margin of Safety? Yes No Station: Degree:

Record the Number of Plies Remaining on the Flexible Boot:

Degree Location	Plies Remaining	STATION	EROSION	CHAR
0	<u>3.8</u>	<u>8.0</u>	<u>NA</u>	<u> </u>
90	<u>3.4</u>	<u>9.0</u>	<u>NA</u>	<u> </u>
180	<u>3.8</u>	<u>10.0</u>	<u>.07</u>	<u>1.08</u>
270	<u>3.4</u>	<u>11.3</u>	<u>.07</u>	<u>1.02</u>
140	<u>3.8</u>			

Negative Margin of Safety? Yes No Degree:

Notes / Comments

Special Issues 3.3.3 NO ABNORMAL EROSION OF FLEX BOOT PLYS WAS OBSERVED AT 140 DEGREES. REMAINING BOOT PLYS WERE AT MAXIMUM AT THIS SECTION.

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s):

Clarification Form(s)? Yes No Clarification Form Page No.(s):

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360T026 Side: Right (B) Date: 10-12-92

Assessment Engineer(s)/Inspector(s): M. Clark

Phenolic Subassembly: Aft Exit Cone Assembly

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location				Total
	0-90	90-180	180-270	270-360	
Metal-to-Adhesive	5	2	3	0	2
Within Adhesive					
Adhesive-to-GCP					
Within GCP	95	98	97	100	98
GCP-to-CCP					
Within CCP					

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location				Total
	0-90	90-180	180-270	270-360	
Metal-to-Adhesive		1		1	
Within Adhesive					
Adhesive-to-GCP	100	99	100	99	

Phenolic Removal Method: _____

Metal Housing Bondline Surface Observations:

- A. Soot?
- B. Voids in Adhesive?
- C. Corrosion?
- D. Foreign Material?
- E. Voids in Polysulfide (Aft Exit Cone Polysulfide Groove)?

Yes	No	Comment #
<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____
<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____
<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2

Notes / Comments

1) Intermittent small voids, largest void at 185°, 1.1" axial x 0.70" circ, 24" from fwd.
2) Intermittent small voids, largest void: 0.10" diameter

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360T026 Side: Right (B) Date: 10-12-92

Assessment Engineer(s)/Inspector(s): M. Clark

Phenolic Subassembly: Aft Exit Cone Assembly

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							Total
	0-90	90-180	180-270	270-360				
Metal-to-Adhesive	5	2	3	0				2
Within Adhesive								
Adhesive-to-GCP								
Within GCP	95	98	97	100				98
GCP-to-CCP								
Within CCP								

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
	0-90	90-180	180-270	270-360				
Metal-to-Adhesive		1		1				
Within Adhesive								
Adhesive-to-GCP	100	99	100	99				

Phenolic Removal Method: _____

<u>Metal Housing Bondline Surface Observations:</u>	Yes	No	Comment #
A. Soot?		<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input checked="" type="checkbox"/>		1
C. Corrosion?		<input checked="" type="checkbox"/>	
D. Foreign Material?		<input checked="" type="checkbox"/>	
E. Voids in Polysulfide (Aft Exit Cone Polysulfide Groove)?	<input checked="" type="checkbox"/>		2

Notes / Comments
 1) Intermittent small voids, largest void at 185°, 1.1" axial x 0.70" circ, 24" from fwd.
 2) Intermittent small voids, largest void: 0.10" diameter

Preliminary PFAR(s)? ___ Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? ___ Yes No Clarification Form Page No.(s): _____



POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360T026 Side: Right (B) Date: 10-7-92
 Assessment Engineer(s)/Inspector(s): M.E. Clark, J. Walker, R. Tellers
 Phenolic Subassembly: Forward Exit Cone Assembly

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0
Metal-to-Adhesive	45	85	40	60	65	30	80	68
Within Adhesive	5		5	5	1	5	2	2
Adhesive-to-GCP	50	15	55	35	34	65	18	30
Within GCP								
GCP-to-CCP								
Within CCP								

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
Metal-to-Adhesive	N/A							
Within Adhesive								
Adhesive-to-GCP								

Phenolic Removal Method: _____

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?		✓	
B. Voids in Adhesive?	✓		1
C. Corrosion?	✓		2
D. Foreign Material?		✓	

Notes / Comments

1) Reference C-43A
 2) Medium- to -heavy corrosion in areas of metal-to-adhesive separation.

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____
 Clarification Form(s)? Yes No Clarification Form Page No.(s): C-43A

Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: 360T026 | Side: Left (A) Right (B) | Date: 10-7-92
 Assessment Engineer(s)/Inspector(s): M.E. Clark, J. Walker, R. Teller
 Nozzle Subassembly: Fwd Exit Cone

Record Bondline Adhesive Void Measurements and Locations Below:

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd	Distance From Aft
150	1.0	0.5	_____	10.9
168	0.7	0.5	_____	8.2
213	1.0	0.7	_____	11.5
_____	1.4	0.5	_____	9.8
_____	0.7	0.4	_____	14.7
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Notes / Comments

Corresponding Comment Number(s): 1


POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360T026	Side: Right (B)	Date: 10-5-92
Assessment Engineer(s)/Inspector(s): <u>R.Quick T.FRESTON</u>		
Phenolic Subassembly: Throat Assembly		

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	0°-45°	45°-90°	90°-135°	135°-180°	180°-225°	225°-270°	270°-315°	315°-0°
Metal-to-Adhesive	100%	100%	100%	100%	100%	100%	100%	100%
Within Adhesive								
Adhesive-to-GCP								
Within GCP								
GCP-to-CCP								
Within CCP								

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):



Phenolic Removal Method: _____

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____
B. Voids in Adhesive?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>2</u>
C. Corrosion?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>1</u>
D. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____

Notes / Comments

Special Issues 3.3.4

AFT SHIMS IMPROVED THE DISTRIBUTION OF ADHESIVE AND REDUCED THE VOIDS GREATLY
1. MEDIUM TO HEAVY CORROSION FULL CIRCUMFERENCE
2. SEE CLARIFICATION FORM PAGE C-44 A.

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No. (s): C-44A

Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: 360T026 Side: Left (A) Right (B) Date: 10-5-92

Assessment Engineer(s)/Inspector(s): R. QUICK / T. FRESTON

Nozzle Subassembly: THROAT ASSEMBLY

Record Bondline Adhesive Void Measurements and Locations Below:

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd	Distance From Aft
5°	.80	.30	_____	1.00
6°	.85	.45	_____	1.00
50°	_____	.40	_____	.70 *
58°	.65	.30	_____	.10
60°	.35	.65	_____	.08
62°	.60	1.05	_____	0
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Notes / Comments
EXTENDS DOWN 3.5 IN A "U" SHAPE

Corresponding Comment Number(s): 2

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360T026	Side: Right (B)	Date: 10-5-92
Assessment Engineer(s)/Inspector(s): WILKES/FRESTON		
Phenolic Subassembly: Aft Inlet/Forward Nose Rings		

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-360
Metal-to-Adhesive	100	85	100	100	100	80	100	100
Within Adhesive								
Adhesive-to-GCP		15				20		
Within GCP								
GCP-to-CCP								
Within CCP								

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

NA

	Degree Location							
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								

Phenolic Removal Method: N/A

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?		✓	
B. Voids In Adhesive?	✓		1
C. Corrosion?	✓		2
D. Foreign Material?		✓	

Notes | Comments ① ONE ADHESIVE VOID WAS OBSERVED IN THE NOSE CAP-TO-FWD NOSE RING (-503) AT 187°, LOCATED FROM METAL INTERFACE TO 1.10 INCH AFT AND 0.35 INCH CIRCUMFERENCE. VERY FEW SMALL VOIDS, 0.30 INCH MAXIMUM DIAMETER, WERE OBSERVED.

② LIGHT-TO-HEAVY CORROSION WAS OBSERVED OVER LENGTH AND CIRCUMFERENCE EXCEPT AT 60°-80° AND 230°-285° ON FORWARD TO MID 4.20 INCHES ON THE AFT INLET RING (-504) SHOWED NO CORROSION.

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s):

Clarification Form(s)? Yes No Clarification Form Page No. (s):



POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360T026	Side: Right (B)	Date: 10-5-92
Assessment Engineer(s)/Inspector(s): WILKES / FRESTON		
Phenolic Subassembly: Nose Cap		

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	0-360							
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								
Within GCP	5							
GCP-to-CCP	95							
Within CCP								

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0
Metal-to-Adhesive	15	15	20	20	25	20	20	25
Within Adhesive	5	5				5	3	3
Adhesive-to-GCP	80	80	80	80	75	75	77	72

Phenolic Removal Method: NYLON WEDGE & HAMMER & EVERY HARD TO PEEL

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
C. Corrosion?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	2
D. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments ① SEE PFOR CLARIFICATION FORM PAGE C-46A.

② LIGHT TO MEDIUM CORROSION FORWARD 0.5-1.5 INCHES AND AFT 1.0-4.5 INCHES FOR FULL CIRCUMFERENCE.

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No. (s): C-46A



Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: 360T026

Side: Left (A) Right (B)

Date: 10-5-92

Assessment Engineer(s)/Inspector(s): WILKES / FRESTON

Nozzle Subassembly: NOSE CAP

Record Bondline Adhesive Void Measurements and Locations Below:

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd	Distance From Aft
33°	1.70	1.50	3.80	
50°	0.50	0.35	0.20	
218°	0.40	0.20	5.25	
251°	0.70	0.50	11.50	
281°	0.57	0.28	9.60	
288°	0.47	0.25	7.00	
290°	0.40	0.23	6.50	
320°	0.43	0.30	2.70	

Notes / Comments: ① VERY FEW SMALL VOIDS 0.30 INCH MAXIMUM DIAMETER WERE OBSERVED.

Corresponding Comment Number(s): 1

REVISION _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360T026	Side: Right (B)	Date: 6 Oct 92
Assessment Engineer(s)/Inspector(s): R. QUICK T. FRESTON		
Phenolic Subassembly: Cowl Assembly		

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0
Metal-to-Adhesive	100%	100%	100%	100%	100%	100%	100%	100%
Within Adhesive								
Adhesive-to-SCP								
Within SCP								
SCP-to-CCP								
Within CCP								

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-SCP								

Phenolic Removal Method: _____

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>SEE PG C-47A</u>
C. Corrosion?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>1</u>
D. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments 1-LIGHT TO MEDIUM CORROSION FULL CIRCUMFERENCE

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No. (s): C-47A

Nozzle Subassembly Bondline Adhesive Void Clarification Form


Motor No.: 360T026 Side: Left (A) Right (B) Date: 10-6-92

Assessment Engineer(s)/Inspector(s): *R. QUICK T. FRESTON*

Nozzle Subassembly: *COWL ASSEMBLY*

Record Bondline Adhesive Void Measurements and Locations Below:

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd	Distance From Aft
<i>90°</i>	<i>.80</i>	<i>.28</i>	<i>.60</i>	
<i>282°</i>	<i>.58</i>	<i>.20</i>	<i>.20</i>	



Corresponding Comment Number(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360T026	Side: Right (B)	Date: 10-2-97
Assessment Engineer(s)/Inspector(s): M. Clark, P. Miller		
Phenolic Subassembly: Fixed Housing Assembly		

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location				TOTAL
	315-45	45-135	135-225	225-315	
Metal-to-Adhesive	95	93	97	96	95
Within Adhesive					
Adhesive-to-GCP	5	7	3	4	5
Within GCP					
GCP-to-CCP					
Within CCP					

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location				
Metal-to-Adhesive	N/A				
Within Adhesive					
Adhesive-to-GCP					

Phenolic Removal Method: _____

Metal Housing Bondline Surface Observations:

- A. Soot? _____
- B. Voids in Adhesive? Yes _____ No
- C. Corrosion? _____
- D. Foreign Material? _____

Yes	No	Comment #
<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____
<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____
<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____

Notes / Comments

1) Inlet Hunt void, 0.20" dia
Reference C-48A

2) Unbonded area on forward flut that was detected by ultrasonics is visible on the nozzle. The area is 2.12" x 3.12" gray than the other areas of adhesive and has a white line at the boundary between unbonded and bonded areas. The line is most visible between 45°-225°

3) Resin Glaze present in 95% of glass-to-adhesive separation areas. Max axial width of 3.0"

Preliminary PFAR(s)? Yes _____ No Preliminary PFAR Number(s): 47C-15

Clarification Form(s)? Yes _____ No Clarification Form Page No.(s): C-48A, B, C, D, E

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360T026 Side: Right (B) Date: 10-2-92

Assessment Engineer(s)/Inspector(s): M. Clark, P. Miller

Phenolic Subassembly: Fixed Housing Assembly

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location				TOTAL
	315-45	15-135	135-225	225-315	
Metal-to-Adhesive	95	93	97	96	95
Within Adhesive					
Adhesive-to-GCP	5	7	3	4	5
Within GCP					
GCP-to-CCP					
Within CCP					

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location				TOTAL
Metal-to-Adhesive	N/A				
Within Adhesive					
Adhesive-to-GCP					

Phenolic Removal Method: _____

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?		<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input checked="" type="checkbox"/>		1
C. Corrosion?		<input checked="" type="checkbox"/>	
D. Foreign Material?		<input checked="" type="checkbox"/>	

Notes / Comments

1) Intermittent void, 0.20" dia
Reference C-48A

2) Unbond area on weldend that was detected by ultrasonics is visible on adhesive. Unbond area is lighter gray than the other areas of adhesive and has a white line that mark the boundary between unbond and bond areas. The line is most visible between 45°-225°

3) Resin Glaze present in 95% of glass-to-adhesive separation areas. max axial width of 3.0".


Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): 47C-15

Clarification Form(s)? Yes No Clarification Form Page No.(s): C-48A, B, C, D, E



General Hardware Clarification Form

Motor No.: 360T026	Side: <input type="checkbox"/> Left (A) <input checked="" type="checkbox"/> Right (B)	Date: 10-2-92
Assessment Engineer(s)/Inspector(s): M. Clark		
Description: Fixed housing bondline separation (Fixed Housing Side)		
Sketch Observations Below (include locations and sizes of sketched features):		



Corresponding Comment Number(s): 2

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360T026 Side: Right (B) Date: 10-9-92

Assessment Engineer(s)/Inspector(s): M. Clark, T. Freston

Phenolic Subassembly: IBR

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location				Total
	315-45	45-135	135-225	225-315	
Metal-to-Adhesive	70	65	80	50	66
Within Adhesive	10	10	10	20	13
Adhesive-to-GCP	20	15	10	15	15
Within GCP		10		15	6
GCP-to-CCP					
Within CCP					

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location		Total
	45-135	225-315	
Metal-to-Adhesive			
Within Adhesive			
Adhesive-to-GCP	100	100	

Phenolic Removal Method: hand & wedges

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?		<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input checked="" type="checkbox"/>		1
C. Corrosion?	<input checked="" type="checkbox"/>		2
D. Foreign Material?		<input checked="" type="checkbox"/>	

Notes / Comments

1) Intermittent small voids with diameter of 0.30" or smaller
 2) Light-to-medium corrosion intermittently in areas of metal-to-adhesive separations
 3) The fixed housing insulation was removed 1 week ago (10/2/92)

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s):

Clarification Form(s)? Yes No Clarification Form Page No.(s): C-48D


General Hardware Clarification Form

Motor No.: 360T026 Side: Left (A) Right (B) Date: 10-5-92

Assessment Engineer(s)/Inspector(s): L.E. WILKES

Description: BOOT ASSEMBLY-TO-FIXED HOUSING PHENOLIC BONDLINE

Sketch Observations Below (include locations and sizes of sketched features):



RSRM-26B NOZZLE

BONDLINE 1 FAILURE MODE IBR-TO-FIXED HSG PHENOLICS	PERCENT OF CIRCUMFERENCE
FIXED HSG-TO-ADHESIVE	5
WITHIN ADHESIVE	9
IBR-TO- ADHESIVE	86

BONDLINE 2 FAILURE MODE FLEX BOOT-TO-FIXED HSG CCP	PERCENT OF CIRCUMFERENCE
WITHIN FIXED HSG CHARRED CCP	28
WITHIN INNER BOOT RING GCP	1
WITHIN FLEXIBLE BOOT NBR	6
ADHESIVE-TO-FIXED HSG CCP	62
WITHIN ADHESIVE	3

Corresponding Comment Number(s): 3

General Hardware Clarification Form

Motor No.: 360T026	Side: <input type="checkbox"/> Left (A) <input checked="" type="checkbox"/> Right (B)	Date: 10-5-92
Assessment Engineer(s)/Inspector(s): T. FRESTON / L. WILKES		
Description: FIXED HOUSING BONDLINE METAL SURFACE HARDNESS		

Sketch Observations Below (include locations and sizes of sketched features):

ROCKWELL - C HARDNESS MEASUREMENTS

AXIAL
LOCATIONS

ANGULAR
LOCATIONS

RANDOM AREAS
APPROXIMATELY EQUAL
DISTANCE APART
OVER AXIAL LENGTH

	90°	270°
HARDNESS	48	48
	49	48
	50	47
	48	49

Corresponding Comment Number(s): 2

POSTFLIGHT OBSERVATION RECORD (PFOR) C-13
Cowl Ring Phenolic (CCP) Section Condition

Motor No.: 360T026	Side: Right (B)	Date: 3-2-93
Assessment Engineer(s)/Inspector(s): WILKES		

Cowl Phenolic Section Observations:	Yes	No	Comment #
A. Cross-ply cracking in virgin material?	_____	<input checked="" type="checkbox"/>	_____
B. Ply lifting?	_____	<input checked="" type="checkbox"/>	_____

Record the Cowl Char and Erosion Measurements Below:

Station Location	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
0.3	.25	.62	.29	.58	.28	.69	.25	.71
1.0	.31	.63	.30	.57	.28	.68	.27	.64
2.0	.33	.55	.32	.60	.32	.63	.30	.65
3.0	.37	.58	.35	.60	.33	.62	.31	.71
4.0	.35	.60	.35	.59	.35	.63	.31	.74
5.0	NA	.87*	NA	.97*	NA	1.00*	NA	1.10*
6.0	NA	.88*	NA	.95*	NA	.97*	NA	1.06*
6.8	NA	.92*	NA	1.00*	NA	1.00*	NA	1.05*

Negative Margin of Safety? _____ Yes No _____ Station: _____ Degree: _____

Notes / Comments * TOTAL EROSION AND CHAR DEPTH

Preliminary PFAR(s)? _____ Yes No _____ Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No _____ Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-14
Forward Exit Cone Phenolic (CCP) Section Condition

Motor No.: 360T026	Side: Right (B)	Date: 3-1-93
Assessment Engineer(s)/Inspector(s): WILKES		

Forward Exit Cone Phenolic Section Observations:	Yes	No	Comment #
A. Cross-ply cracking in virgin material?	_____	✓	_____
B. Ply lifting?	_____	✓	_____

Record the Forward Exit Cone Char and Erosion Measurements Below:

Station Location	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
1.0	.36	.74	.36	.72	.36	.78	.35	.81
4.0	.34	.69	.36	.70	.34	.71	.36	.70
4.6	.35	.66	.34	.72	.33	.74	.33	.74
8.0	.35	.65	.32	.74	.35	.72	.33	.71
12.0	NA	NA	NA	NA	NA	NA	NA	NA
16.0	↓	↓	↓	↓	↓	↓	↓	↓
20.0	↓	↓	↓	↓	↓	↓	↓	↓
24.0	↓	↓	↓	↓	↓	↓	↓	↓
28.0	↓	↓	↓	↓	↓	↓	↓	↓
32.0	↓	↓	↓	↓	↓	↓	↓	↓
32.9	↓	↓	↓	↓	↓	↓	↓	↓
34.0	↓	↓	↓	↓	↓	↓	↓	↓

Negative Margin of Safety? _____ Yes No Station: _____ Degree: _____

Notes / Comments

Preliminary PFAR(s)? _____ Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-15
Fixed Housing Phenolic (CCP) Section Condition

Motor No.: 360T026 Side: Right (B) Date: 3-3-93
Assessment Engineer(s)/Inspector(s): WILKES

Fixed Housing Phenolic Section Observations:

	Yes	No	Comment #
A. Cross-ply cracking in virgin material?	_____	<input checked="" type="checkbox"/>	_____
B. Ply lifting?	_____	<input checked="" type="checkbox"/>	_____

Record the Fixed Housing Char and Erosion Measurements Below:

Station Location	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
0.0	.09	.90	.08	1.17	.06	1.19	.10	1.08
1.0	.06	.99	.04	1.08	.02	1.11	.05	1.07
2.0	.00	.92	.01	.95	.00	.99	.00	1.02
3.0	↓	.91	.00	.97	↓	.96	↓	.99
4.0	↓	.89	.00	.93	↓	1.02	↓	.98
5.0	↓	.86	.00	.96	↓	1.00	↓	.99
6.0	↓	.88	.02	.91	↓	.99	↓	.98
7.0	↓	.87	.00	.95	↓	1.00	↓	1.00
8.0	.00	.79	.00	.90	.00	.85	↓	.87
9.0	NA	.77 *	.00	.93	NA	.82 *	↓	.76
10.75	NA	1.67 *	.07	1.85	NA	.85 *	.00	1.70

Negative Margin of Safety? _____ Yes No Station: _____ Degree: _____

Notes / Comments * TOTAL DEPTH, EROSION PLUS CHAR

Preliminary PFAR(s)? _____ Yes No Preliminary PFAR Number(s): _____
Clarification Form(s)? _____ Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-16
Throat Inlet Assembly Phenolic (CCP) Section Condition

Motor No.: 360T026 Side: Right (B) Date: 3-3-93

Assessment Engineer(s)/Inspector(s): WILKES

Throat Inlet Assembly Phenolic Section Observations:	Yes	No	Comment #
A. Cross-ply cracking in virgin material?	_____	<input checked="" type="checkbox"/>	_____
B. Ply lifting?	_____	<input checked="" type="checkbox"/>	_____

Record the Throat Inlet Ring and Throat Ring Char and Erosion Measurements Below:

Station Location	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
1.0	1.05	.57	NA	NA	1.03	.58	1.03	.53
2.0	1.07	.53	1.06	.53	1.07	.57	1.08	.53
4.0	1.09	.59	1.11	.56	1.11	.60	1.10	.61
6.0	1.04	.57	1.16	.57	1.14	.60	1.15	.62
8.0	1.08	.57	1.20	.51	1.22	.49	1.21	.52
10.0	1.16	.48	1.15	.50	1.14	.49	1.15	.56
12.0	1.15	.53	1.16	.48	1.15	.49	1.14	.52
14.0	1.13	.52	1.15	.47	1.10	.50	1.12	.50
16.0	1.07	.55	1.06	.58	1.03	.55	1.02	.59
18.0	.94	.59	.91	.69	.92	.61	.89	.64
20.0	.73	.67	.74	.69	.71	.70	.71	.67
22.0	.51	.79	.46	.79	.43	.86	.46	.79
23.0	.44	.85	.41	.85	.37	.87	.40	.80

Negative Margin of Safety? _____ Yes No Station: _____ Degree: _____

Notes / Comments

Preliminary PFAR(s)? _____ Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-17
Nose Cap Phenolic (CCP) Section Condition

Motor No.: 360T026 Side: Right (B) Date: 3-3-93

Assessment Engineer(s)/Inspector(s): WIKES

Nose Cap Phenolic Section Observations:

	Yes	No	Comment #
A. Cross-ply cracking in virgin material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
B. Ply lifting?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Record the Nose Cap Char and Erosion Measurements Below:

Station Location	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
1.5	.30	.67	.29	.69	.38	.67	.28	.63
4.0	.34	.74	.35	.64	.36	.61	.33	.57
6.0	.37	.78	.39	.65	.41	.63	.35	.58
8.0	.44	.63	.46	.54	.44	.60	.41	.55
10.0	.45	.65	.49	.51	.50	.50	.49	.49
12.0	.50	.59	.55	.50	.56	.52	.50	.52
14.0	.57	.53	.59	.53	.61	.52	.56	.52
16.0	.66	.51	.73	.49	.80	.47	.70	.43
18.0	.84	.48	.83	.42	.90	.47	.79	.39
20.0	1.03	.39	1.04	.48	1.10	.48	1.02	.37
22.0	1.53	.57	1.55	.60	1.66	.61	1.53	.53
24.0	1.67	.66	1.71	.65	1.79	.70	1.73	.70
26.0	1.10	.77	1.18	.66	1.21	.74	1.27	.71

Negative Margin of Safety? Yes No Station: _____ Degree: _____

Notes / Comments

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-18
Forward Nose Ring and Aft Inlet Ring Phenolic (CCP) Section Condition

Motor No.: 360T026 Side: Right (B) Date: 3-2-93

Assessment Engineer(s)/Inspector(s): WILKES

Forward Nose and Aft Inlet Ring Phenolic Section Observations:	Yes	No	Comment #
A. Cross-ply cracking in virgin material?	_____	<input checked="" type="checkbox"/>	_____
B. Ply lifting?	_____	<input checked="" type="checkbox"/>	_____

Record the Forward Nose Ring (-503) Char and Erosion Measurements Below:

Station	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
28.0	<u>1.06</u>	<u>.70</u>	<u>1.10</u>	<u>.77</u>	<u>1.14</u>	<u>.63</u>	<u>1.16</u>	<u>.70</u>
30.0	<u>.86</u>	<u>.67</u>	<u>.87</u>	<u>.76</u>	<u>.89</u>	<u>.66</u>	<u>.93</u>	<u>.65</u>
32.0	<u>.94</u>	<u>.66</u>	<u>.95</u>	<u>.63</u>	<u>.95</u>	<u>.62</u>	<u>.98</u>	<u>.62</u>

Negative Margin of Safety? _____ Yes No _____ Station: _____ Degree: _____

Record the Aft Inlet Ring Char (-504) and Erosion Measurements Below:

Station	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
34.0	<u>.83</u>	<u>.59</u>	<u>.82</u>	<u>.58</u>	<u>.82</u>	<u>.62</u>	<u>.84</u>	<u>.60</u>
36.0	<u>.85</u>	<u>.56</u>	<u>.86</u>	<u>.60</u>	<u>.92</u>	<u>.56</u>	<u>.86</u>	<u>.58</u>
38.0	<u>.95</u>	<u>.61</u>	<u>.91</u>	<u>.63</u>	<u>1.00</u>	<u>.56</u>	<u>.93</u>	<u>.63</u>
39.0	<u>.97</u>	<u>.65</u>	<u>.96</u>	<u>.71</u>	<u>1.02</u>	<u>.62</u>	<u>.97</u>	<u>.67</u>


Negative Margin of Safety? _____ Yes No _____ Station: _____ Degree: _____

Notes / Comments

Preliminary PFAR(s)? _____ Yes No _____ Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes No _____ Clarification Form Page No.(s): _____





Appendix D Nozzle Postfire Data

Final Postflight Hardware Evaluation Report 360T026 (RSRM-26, STS-47)

April 1993

Prepared for:

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION
GEORGE C. MARSHALL SPACE FLIGHT CENTER
MARSHALL SPACE FLIGHT CENTER, ALABAMA 35812

Contract No.	NAS8-38100
DR No.	4-23
WBS No.	4C601-04-01
ECS No.	SS4769

Thiokol CORPORATION
SPACE OPERATIONS

P.O. Box 707, Brigham City, Utah 84302-0707 (801) 863-3511



360T026 Appendix D Contents

List of Figures

<u>Figure</u>	<u>Description</u>	<u>Page</u>
1	RSRM Nozzle Liner Char and Erosion Station Locations	D-2

List of Tables

<u>Table</u>	<u>Description</u>	<u>Page</u>
1	RSRM-26A Forward Exit Cone Assembly Erosion and Char Data	D-3
2	RSRM-26B Forward Exit Cone Assembly Erosion and Char Data	D-4
3	RSRM-26A Throat Assembly Erosion and Char Data	D-5
4	RSRM-26B Throat Assembly Erosion and Char Data	D-6
5	RSRM-26A Nose Inlet Assembly Erosion and Char Data	D-7
6	RSRM-26B Nose Inlet Assembly Erosion and Char Data	D-9
7	RSRM-26A Cowl/OBR Erosion and Char Data	D-11
8	RSRM-26B Cowl/OBR Erosion and Char Data	D-12
9	RSRM-26A Fixed Housing Assembly Erosion and Char Data	D-13
10	RSRM-26B Fixed Housing Assembly Erosion and Char Data	D-14












Figure 1
Nozzle Liner Char and Erosion Station Locations

RSRM-26A Forward Exit Cone Assembly Erosion and Char Data

Angular Location	Stations							
0 degrees	1.0	4.0	4.6	8.0	28.0	32.0	32.9	34.0
Measured Erosion	0.38	0.37	0.37	0.40	0.27	0.26	0.21	0.18
Measured Char	0.71	0.70	0.70	0.68	0.72	0.74	0.75	0.80
Adjusted Char *	0.57	0.56	0.56	0.54	0.58	0.59	0.60	0.64
Denominator	1.36	1.33	1.11	1.36	1.18	1.18	0.92	1.11
RSRM Liner Thickness	1.807	1.731	1.411	1.629	1.328	1.372	1.127	1.408
Margin of Safety	0.33	0.30	0.27	0.20	0.13	0.16	0.23	0.27
90 degrees								
Measured Erosion	0.38	0.37	0.35	0.39	0.26	0.27	0.21	0.21
Measured Char	0.80	0.73	0.77	0.70	0.71	0.75	0.76	0.76
Adjusted Char *	0.64	0.58	0.62	0.56	0.57	0.60	0.61	0.61
Denominator	1.45	1.36	1.14	1.36	1.15	1.21	0.92	1.12
RSRM Liner Thickness	1.807	1.731	1.411	1.629	1.328	1.372	1.127	1.408
Margin of Safety	0.25	0.27	0.24	0.20	0.15	0.13	0.22	0.26
180 degrees								
Measured Erosion	0.37	0.35	0.34	0.28	0.28	0.23	0.17	
Measured Char	0.76	0.72	0.71	0.73	0.72	0.70	0.74	
Adjusted Char *	0.61	0.58	0.57	0.58	0.58	0.56	0.59	
Denominator	1.39	1.31	1.08	1.21	1.20	1.09	0.85	
RSRM Liner Thickness	1.807	1.731	1.411	1.629	1.328	1.372	1.127	1.408
Margin of Safety	0.30	0.32	0.31	0.35	0.11	0.26	0.33	
270 degrees								
Measured Erosion	0.37	0.35	0.35	0.39	0.25	0.21	0.21	0.17
Measured Char	0.75	0.68	0.69	0.68	0.73	0.71	0.69	0.70
Adjusted Char *	0.60	0.54	0.55	0.54	0.58	0.57	0.55	0.56
Denominator	1.38	1.28	1.08	1.34	1.16	1.07	0.87	0.99
RSRM Liner Thickness	1.807	1.731	1.411	1.629	1.328	1.372	1.127	1.408
Margin of Safety	0.31	0.36	0.31	0.21	0.15	0.29	0.30	0.42

Minimum margin of safety is 0.11 at station 28.00 degree 180.00
 Maximum margin of safety is 0.42 at station 34.00 degree 270.00

* Measured char adjusted to end of action time

Margin of Safety = $\frac{\text{Minimum liner thickness}}{1.70 \times \text{erosion} + 1.25 \times \text{adj char}}$ - 1

Stations

Angular Location

0 degrees	1.0	4.0	4.6	8.0
Measured Erosion	0.36	0.34	0.35	0.35
Measured Char	0.74	0.69	0.66	0.65
Adjusted Char *	0.59	0.55	0.53	0.52
Denominator	1.35	1.27	1.05	1.25
RSRM Liner Thickness	1.807	1.731	1.411	1.629
Margin of Safety	0.34	0.37	0.34	0.31

90 degrees

Measured Erosion	0.36	0.36	0.34	0.32
Measured Char	0.72	0.70	0.72	0.74
Adjusted Char *	0.58	0.56	0.58	0.59
Denominator	1.33	1.31	1.09	1.28
RSRM Liner Thickness	1.807	1.731	1.411	1.629
Margin of Safety	0.36	0.32	0.30	0.27

180 degrees

Measured Erosion	0.36	0.34	0.33	0.35
Measured Char	0.78	0.71	0.74	0.72
Adjusted Char *	0.62	0.57	0.59	0.58
Denominator	1.39	1.29	1.09	1.31
RSRM Liner Thickness	1.807	1.731	1.411	1.629
Margin of Safety	0.30	0.34	0.30	0.24

270 degrees

Measured Erosion	0.35	0.36	0.33	0.33
Measured Char	0.81	0.70	0.74	0.71
Adjusted Char *	0.65	0.56	0.59	0.57
Denominator	1.41	1.31	1.09	1.27
RSRM Liner Thickness	1.807	1.731	1.411	1.629
Margin of Safety	0.29	0.32	0.30	0.28

Minimum margin of safety is 0.24 at station 8.00 degree 180.00
 Maximum margin of safety is 0.37 at station 4.00 degree 0.00

* Measured char adjusted to end of action time

$$\text{Margin of Safety} = \frac{\text{minimum liner thickness}}{1.70 \times \text{erosion} + 1.25 \times \text{adj char}} - 1$$

REVISION _____

Table 2

RSRM-26A Throat Assembly Erosion and Char Data

Angular Location	Stations												
	0	2.0	4.0	6.0	8.0	10.0	12.0	14.0	16.0	18.0	20.0	22.0	23.0
Measured Erosion	1.09	1.13	1.20	1.23	1.26	1.19	1.16	1.14	1.07	0.93	0.73	0.51	0.41
Measured Char *	0.62	0.60	0.65	0.66	0.52	0.54	0.54	0.53	0.59	0.67	0.76	0.82	0.81
Adjusted Char *	0.47	0.45	0.49	0.50	0.39	0.41	0.41	0.40	0.44	0.54	0.61	0.66	0.65
Denominator	2.76	2.82	3.01	3.08	3.01	2.89	2.83	2.78	2.69	2.53	2.22	1.84	1.63
RSRM Liner Thickness	3.174	3.247	3.314	3.280	3.183	3.397	3.517	3.626	3.710	3.586	3.231	2.583	2.110
Margin of Safety	0.15	0.15	0.10	0.07	0.06	0.18	0.24	0.31	0.38	0.42	0.46	0.40	0.29
90 degrees													
Measured Erosion	1.07	1.02	1.18	1.21	1.25	1.20	1.19	1.13	1.09	0.93	0.75	0.55	0.44
Measured Char	0.55	0.57	0.63	0.61	0.51	0.57	0.58	0.63	0.68	0.70	0.72	0.78	0.84
Adjusted Char *	0.41	0.43	0.47	0.46	0.38	0.43	0.43	0.47	0.51	0.56	0.58	0.62	0.67
Denominator	2.66	2.57	2.95	2.99	2.98	2.93	2.92	2.85	2.82	2.56	2.22	1.88	1.72
RSRM Liner Thickness	3.174	3.247	3.314	3.280	3.183	3.397	3.517	3.626	3.710	3.586	3.231	2.583	2.110
Margin of Safety	0.20	0.26	0.12	0.10	0.07	0.16	0.20	0.27	0.32	0.40	0.46	0.37	0.23
180 degrees													
Measured Erosion	1.02	1.06	1.10	1.16	1.19	1.13	1.14	1.12	1.06	0.88	0.72	0.50	0.39
Measured Char	0.63	0.66	0.66	0.67	0.52	0.52	0.48	0.51	0.60	0.66	0.73	0.86	0.89
Adjusted Char *	0.47	0.50	0.50	0.50	0.39	0.39	0.36	0.38	0.45	0.53	0.58	0.69	0.71
Denominator	2.63	2.74	2.82	2.95	2.87	2.75	2.73	2.72	2.68	2.42	2.17	1.86	1.67
RSRM Liner Thickness	3.174	3.247	3.314	3.280	3.183	3.397	3.517	3.626	3.710	3.586	3.231	2.583	2.110
Margin of Safety	0.21	0.19	0.18	0.11	0.11	0.24	0.29	0.33	0.38	0.48	0.49	0.39	0.26
270 degrees													
Measured Erosion	1.06	1.01	1.15	1.20	1.26	1.17	1.12	1.11	1.06	0.91	0.73	0.45	0.37
Measured Char	0.60	0.60	0.64	0.69	0.53	0.51	0.52	0.50	0.55	0.65	0.73	0.86	0.89
Adjusted Char *	0.45	0.45	0.48	0.52	0.40	0.38	0.39	0.38	0.41	0.52	0.58	0.69	0.71
Denominator	2.68	2.58	2.90	3.05	3.02	2.82	2.73	2.69	2.64	2.47	2.19	1.76	1.63
RSRM Liner Thickness	3.174	3.247	3.314	3.280	3.183	3.397	3.517	3.626	3.710	3.586	3.231	2.583	2.110
Margin of Safety	0.18	0.26	0.14	0.08	0.06	0.21	0.29	0.35	0.41	0.45	0.48	0.47	0.29

Minimum margin of safety is 0.06 at station 8.00 degree 270.00
 Maximum margin of safety is 0.49 at station 20.00 degree 180.00

* Measured char adjusted to end of action time

$$\text{Margin of Safety} = \frac{\text{minimum liner thickness}}{2.00 \times \text{erosion} + 1.25 \times \text{adj char}} - 1$$

Angular Location	Stations													
	0 degrees	1.0	2.0	4.0	6.0	8.0	10.0	12.0	14.0	16.0	18.0	20.0	22.0	23.0
Measured Erosion	1.05	1.07	1.09	1.04	1.08	1.15	1.16	1.15	1.13	1.07	0.94	0.73	0.51	0.44
Measured Char *	0.57	0.53	0.59	0.57	0.57	0.51	0.48	0.53	0.52	0.55	0.59	0.67	0.79	0.85
Adjusted Char *	0.43	0.40	0.44	0.43	0.43	0.38	0.36	0.40	0.39	0.41	0.47	0.54	0.63	0.68
Denominator	2.63	2.64	2.73	2.61	2.69	2.88	2.77	2.80	2.75	2.66	2.47	2.13	1.81	1.73
RSRM Liner Thickness	3.174	3.247	3.314	3.280	3.183	3.397	3.397	3.517	3.626	3.710	3.586	3.231	2.583	2.110
Margin of Safety	0.20	0.23	0.21	0.25	0.18	0.23	0.23	0.26	0.32	0.40	0.45	0.52	0.43	0.22
90 degrees														
Measured Erosion		1.06	1.11	1.16	1.20	1.15	1.15	1.16	1.15	1.06	0.91	0.74	0.46	0.41
Measured Char		0.53	0.56	0.57	0.51	0.48	0.48	0.48	0.47	0.58	0.69	0.69	0.79	0.85
Adjusted Char *		0.40	0.42	0.43	0.38	0.36	0.36	0.36	0.35	0.43	0.55	0.55	0.63	0.68
Denominator		2.62	2.75	2.85	2.88	2.77	2.77	2.77	2.74	2.66	2.51	2.17	1.71	1.67
RSRM Liner Thickness	3.174	3.247	3.314	3.280	3.183	3.397	3.397	3.517	3.626	3.710	3.586	3.231	2.583	2.110
Margin of Safety		0.24	0.21	0.15	0.11	0.23	0.23	0.27	0.32	0.39	0.43	0.49	0.51	0.26
180 degrees														
Measured Erosion	1.03	1.07	1.11	1.14	1.22	1.15	1.14	1.15	1.10	1.03	0.92	0.71	0.43	0.37
Measured Char	0.58	0.57	0.60	0.60	0.49	0.49	0.49	0.49	0.50	0.55	0.61	0.70	0.86	0.87
Adjusted Char *	0.43	0.43	0.45	0.45	0.37	0.37	0.37	0.37	0.38	0.41	0.49	0.56	0.69	0.70
Denominator	2.60	2.67	2.78	2.84	2.90	2.74	2.74	2.76	2.67	2.58	2.45	2.12	1.72	1.61
RSRM Liner Thickness	3.174	3.247	3.314	3.280	3.183	3.397	3.397	3.517	3.626	3.710	3.586	3.231	2.583	2.110
Margin of Safety	0.22	0.21	0.19	0.15	0.10	0.24	0.24	0.27	0.36	0.44	0.46	0.52	0.50	0.31
270 degrees														
Measured Erosion	1.03	1.08	1.10	1.15	1.21	1.15	1.15	1.14	1.12	1.02	0.89	0.71	0.46	0.40
Measured Char	0.53	0.53	0.61	0.62	0.52	0.56	0.56	0.52	0.50	0.59	0.64	0.67	0.79	0.80
Adjusted Char *	0.40	0.40	0.46	0.47	0.39	0.42	0.42	0.39	0.38	0.44	0.51	0.54	0.63	0.64
Denominator	2.56	2.66	2.77	2.88	2.91	2.82	2.82	2.77	2.71	2.59	2.42	2.09	1.71	1.60
RSRM Liner Thickness	3.174	3.247	3.314	3.280	3.183	3.397	3.397	3.517	3.626	3.710	3.586	3.231	2.583	2.110
Margin of Safety	0.24	0.22	0.20	0.14	0.09	0.20	0.20	0.27	0.34	0.43	0.48	0.55	0.51	0.32

Minimum margin of safety is 0.09 at station 8.00 degree 270.00
 Maximum margin of safety is 0.55 at station 20.00 degree 270.00

* Measured char adjusted to end of action time

$$\text{Margin of Safety} = \frac{\text{minimum liner thickness}}{2.00 \times \text{erosion} + 1.25 \times \text{adj char}} - 1$$

Table 4

Station Erosion and Char Data

Stations

Angular Location

0 degrees	10.0	12.0	14.0	16.0	18.0	20.0	22.0	24.0	26.0	28.0
Measured Erosion	0.50	0.50	0.57	0.73	0.80	1.07	1.05	1.34	1.28	1.14
Measured Char	0.45	0.56	0.57	0.48	0.50	0.42	0.67	0.65	0.71	0.62
Adjusted Char *	0.45	0.48	0.46	0.39	0.40	0.34	0.54	0.52	0.53	0.47
Denominator	1.30	1.34	1.34	1.71	2.10	2.56	3.97	4.33	3.23	2.86
RSRM Liner Thickness	2.458	2.668	2.878	3.088	3.507	4.055	4.713	4.691	3.863	3.508
Margin of Safety	0.62	0.84	0.81	0.69	0.67	0.58	0.19	0.08	0.20	0.23
90 degrees										
Measured Erosion	0.25	0.41	0.47	0.55	0.71	0.98	1.49	1.67	1.18	1.12
Measured Char	0.32	0.58	0.53	0.43	0.42	0.44	0.72	0.75	0.71	0.55
Adjusted Char *	0.32	0.46	0.42	0.34	0.34	0.35	0.58	0.60	0.53	0.41
Denominator	1.11	1.40	1.47	1.53	1.84	2.40	3.70	4.09	3.03	2.76
RSRM Liner Thickness	2.038	2.668	2.878	3.088	3.507	4.055	4.713	4.691	3.863	3.508
Margin of Safety	0.87	0.91	0.96	1.02	0.91	0.69	0.27	0.15	0.28	0.27
180 degrees										
Measured Erosion	0.37	0.43	0.43	0.50	0.73	0.94	1.46	1.59	1.05	1.05
Measured Char	0.50	0.51	0.51	0.51	0.53	0.55	0.62	0.68	0.77	0.71
Adjusted Char *	0.40	0.40	0.41	0.41	0.42	0.44	0.50	0.54	0.58	0.53
Denominator	1.18	1.24	1.37	1.51	1.99	2.43	3.54	3.86	2.82	2.77
RSRM Liner Thickness	2.458	2.668	2.878	3.088	3.507	4.055	4.713	4.691	3.863	3.508
Margin of Safety	1.11	1.05	1.10	1.05	0.76	0.67	0.33	0.22	0.37	0.27
270 degrees										
Measured Erosion	0.36	0.43	0.48	0.51	0.72	0.92	1.50	1.75	1.31	1.01
Measured Char	0.51	0.55	0.50	0.49	0.46	0.48	0.65	0.68	0.87	0.72
Adjusted Char *	0.40	0.40	0.40	0.39	0.37	0.38	0.52	0.54	0.65	0.54
Denominator	1.11	1.11	1.46	1.51	1.90	2.32	3.65	4.18	3.44	2.70
RSRM Liner Thickness	2.458	2.668	2.878	3.088	3.507	4.055	4.713	4.691	3.863	3.508
Margin of Safety	0.87	0.89	0.97	1.05	0.85	0.75	0.29	0.12	0.12	0.30

Minimum margin of safety = 0.08 at 24.00 degree
 Maximum margin of safety = 1.11 at 10.00 degree 180.00

* Me

Margin of

Minimum margin of safety = 0.08 at 24.00 degree

Maximum margin of safety = 1.11 at 10.00 degree 180.00

RSRM-26A Nose Inlet Assembly Erosion and Char Data

Angular Location	Stations													
	0	4.0	6.0	8.0	10.0	12.0	14.0	16.0	18.0	20.0	22.0	24.0	26.0	28.0
Measured Erosion	0.33	0.35	0.35	0.35	0.38	0.50	0.57	0.73	0.80	1.07	1.65	1.84	1.28	1.14
Measured Char *	0.60	0.59	0.47	0.48	0.63	0.56	0.57	0.49	0.50	0.42	0.67	0.65	0.71	0.62
Adjusted Char *	0.48	0.47	0.47	0.48	0.50	0.45	0.46	0.39	0.40	0.34	0.54	0.52	0.53	0.47
Denominator	1.26	1.29	1.29	1.30	1.39	1.56	1.71	1.95	2.10	2.56	3.97	4.33	3.23	2.86
RSRM Liner Thickness	2.038	2.248	2.248	2.458	2.668	2.878	3.088	3.298	3.507	4.055	4.713	4.691	3.863	3.508
Margin of Safety	0.62	0.74	0.74	0.89	0.92	0.84	0.81	0.69	0.67	0.58	0.19	0.08	0.20	0.23
90 degrees														
Measured Erosion	0.25	0.34	0.34	0.44	0.41	0.47	0.55	0.59	0.71	0.98	1.49	1.67	1.18	1.12
Measured Char	0.62	0.57	0.57	0.53	0.58	0.53	0.43	0.43	0.42	0.44	0.72	0.75	0.71	0.55
Adjusted Char *	0.50	0.46	0.46	0.42	0.46	0.42	0.34	0.34	0.34	0.35	0.58	0.60	0.53	0.41
Denominator	1.12	1.25	1.25	1.41	1.40	1.47	1.53	1.61	1.84	2.40	3.70	4.09	3.03	2.76
RSRM Liner Thickness	2.038	2.248	2.248	2.458	2.668	2.878	3.088	3.298	3.507	4.055	4.713	4.691	3.863	3.508
Margin of Safety	0.82	0.80	0.80	0.74	0.91	0.96	1.02	1.05	0.91	0.69	0.27	0.15	0.28	0.27
180 degrees														
Measured Erosion	0.33	0.33	0.33	0.35	0.37	0.43	0.50	0.64	0.73	0.94	1.46	1.59	1.05	1.05
Measured Char	0.53	0.50	0.50	0.50	0.50	0.51	0.51	0.55	0.53	0.55	0.62	0.68	0.77	0.71
Adjusted Char *	0.42	0.40	0.40	0.40	0.40	0.41	0.41	0.44	0.42	0.44	0.50	0.54	0.58	0.53
Denominator	1.19	1.16	1.16	1.20	1.24	1.37	1.51	1.83	1.99	2.43	3.54	3.86	2.82	2.77
RSRM Liner Thickness	2.038	2.248	2.248	2.458	2.668	2.878	3.088	3.298	3.507	4.055	4.713	4.691	3.863	3.508
Margin of Safety	0.71	0.94	0.94	1.05	1.15	1.10	1.05	0.80	0.76	0.67	0.33	0.22	0.37	0.27
270 degrees														
Measured Erosion	0.36	0.31	0.31	0.40	0.43	0.48	0.51	0.61	0.72	0.92	1.50	1.75	1.31	1.01
Measured Char	0.64	0.59	0.59	0.60	0.55	0.50	0.49	0.55	0.46	0.48	0.65	0.68	0.87	0.72
Adjusted Char *	0.51	0.47	0.47	0.48	0.44	0.40	0.39	0.44	0.37	0.38	0.52	0.54	0.65	0.54
Denominator	1.36	1.21	1.21	1.40	1.41	1.46	1.51	1.77	1.90	2.32	3.65	4.18	3.44	2.70
RSRM Liner Thickness	2.038	2.248	2.248	2.458	2.668	2.878	3.088	3.298	3.507	4.055	4.713	4.691	3.863	3.508
Margin of Safety	0.50	0.86	0.86	0.76	0.89	0.97	1.05	0.86	0.85	0.75	0.29	0.12	0.12	0.30

Minimum margin of safety is 0.08 at station 24.00 degree 0.00
 Maximum margin of safety is 1.15 at station 10.00 degree 180.00

* Measured char adjusted to end of action time
 Margin of Safety = $\frac{\text{minimum liner thickness}}{2.00 \times \text{erosion} + 1.25 \times \text{adj char}}$ - 1

Table 5

RSRM-26A Nose Inlet Assembly Erosion and Char Data

Angular Location	Stations						
	0	30.0	32.0	34.0	36.0	38.0	39.0
0 degrees							
Measured Erosion	0.89	0.97	0.89	0.87	0.98	0.99	0.99
Measured Char	0.69	0.63	0.55	0.60	0.59	0.61	0.61
Adjusted Char *	0.52	0.47	0.41	0.45	0.44	0.46	0.46
Denominator	2.43	2.53	2.30	2.30	2.51	2.55	2.55
RSRM Liner Thickness	3.252	2.950	3.182	3.200	3.026	3.000	3.000
Margin of Safety	0.34	0.17	0.39	0.39	0.20	0.18	0.18
90 degrees							
Measured Erosion	0.91	0.97	0.91	0.89	0.95	0.96	0.96
Measured Char	0.65	0.66	0.52	0.56	0.61	0.66	0.66
Adjusted Char *	0.49	0.50	0.39	0.42	0.46	0.50	0.50
Denominator	2.43	2.56	2.31	2.31	2.47	2.54	2.54
RSRM Liner Thickness	3.252	2.950	3.182	3.200	3.026	3.000	3.000
Margin of Safety	0.34	0.15	0.38	0.39	0.22	0.18	0.18
180 degrees							
Measured Erosion	0.83	0.94	0.86	0.87	0.95	0.98	0.98
Measured Char	0.62	0.63	0.56	0.58	0.65	0.64	0.64
Adjusted Char *	0.47	0.47	0.42	0.43	0.49	0.48	0.48
Denominator	2.24	2.47	2.25	2.28	2.51	2.56	2.56
RSRM Liner Thickness	3.252	2.950	3.182	3.200	3.026	3.000	3.000
Margin of Safety	0.45	0.19	0.42	0.40	0.21	0.17	0.17
270 degrees							
Measured Erosion	0.87	0.98	0.92	0.94	0.99	1.03	1.03
Measured Char	0.74	0.63	0.52	0.48	0.63	0.59	0.59
Adjusted Char *	0.56	0.47	0.39	0.36	0.47	0.44	0.44
Denominator	2.43	2.55	2.33	2.33	2.57	2.61	2.61
RSRM Liner Thickness	3.252	2.950	3.182	3.200	3.026	3.000	3.000
Margin of Safety	0.34	0.16	0.37	0.37	0.18	0.15	0.15

* Measured char adjusted to end of action time

Margin of Safety = $\frac{\text{minimum liner thickness}}{2.00 \times \text{erosion} + 1.25 \times \text{adj char}}$ - 1

Table 5



RSRM-26B Nose Inlet Assembly Erosion and Char Data

Angular Location	Stations												
	1.5	4.0	6.0	8.0	10.0	12.0	14.0	16.0	18.0	20.0	22.0	24.0	26.0
0 degrees	0.30	0.34	0.37	0.44	0.45	0.50	0.57	0.66	0.84	1.03	1.53	1.67	1.10
Measured Erosion	0.67	0.74	0.78	0.63	0.65	0.59	0.53	0.51	0.48	0.39	0.57	0.66	0.77
Measured Char	0.54	0.59	0.62	0.50	0.52	0.47	0.42	0.41	0.38	0.31	0.46	0.53	0.58
Adjusted Char *	1.27	1.42	1.52	1.51	1.55	1.59	1.67	1.83	2.16	2.45	3.63	4.00	2.92
Denominator	1.776	2.038	2.248	2.458	2.668	2.878	3.088	3.298	3.507	4.055	4.713	4.691	3.863
RSRM Liner Thickness	0.40	0.44	0.48	0.63	0.72	0.81	0.85	0.80	0.62	0.66	0.30	0.17	0.32
Margin of Safety													
90 degrees	0.29	0.35	0.39	0.46	0.49	0.55	0.59	0.73	0.83	1.04	1.55	1.71	1.18
Measured Erosion	0.69	0.64	0.65	0.54	0.51	0.50	0.53	0.49	0.42	0.48	0.60	0.65	0.66
Measured Char	0.55	0.51	0.52	0.43	0.41	0.40	0.42	0.39	0.34	0.38	0.48	0.52	0.50
Adjusted Char *	1.27	1.34	1.43	1.46	1.49	1.60	1.71	1.95	2.08	2.56	3.70	4.07	2.98
Denominator	1.776	2.038	2.248	2.458	2.668	2.878	3.088	3.298	3.507	4.055	4.713	4.691	3.863
RSRM Liner Thickness	0.40	0.52	0.57	0.68	0.79	0.80	0.81	0.69	0.69	0.58	0.27	0.15	0.30
Margin of Safety													
180 degrees	0.38	0.36	0.41	0.44	0.50	0.56	0.61	0.80	0.90	1.10	1.66	1.79	1.21
Measured Erosion	0.67	0.61	0.63	0.60	0.50	0.52	0.52	0.47	0.47	0.48	0.61	0.70	0.74
Measured Char	0.54	0.49	0.50	0.48	0.40	0.42	0.42	0.38	0.38	0.38	0.49	0.56	0.56
Adjusted Char *	1.43	1.33	1.45	1.48	1.50	1.64	1.74	2.07	2.27	2.68	3.93	4.28	3.11
Denominator	1.776	2.038	2.248	2.458	2.668	2.878	3.088	3.298	3.507	4.055	4.713	4.691	3.863
RSRM Liner Thickness	0.24	0.53	0.55	0.66	0.78	0.75	0.77	0.59	0.54	0.51	0.20	0.10	0.24
Margin of Safety													
270 degrees	0.28	0.33	0.35	0.41	0.49	0.50	0.56	0.70	0.79	1.02	1.53	1.73	1.27
Measured Erosion	0.63	0.57	0.58	0.55	0.49	0.52	0.52	0.43	0.39	0.37	0.53	0.70	0.71
Measured Char	0.50	0.46	0.46	0.44	0.39	0.42	0.42	0.34	0.31	0.30	0.42	0.56	0.53
Adjusted Char *	1.19	1.23	1.28	1.37	1.47	1.52	1.64	1.83	1.97	2.41	3.59	4.16	3.21
Denominator	1.776	2.038	2.248	2.458	2.668	2.878	3.088	3.298	3.507	4.055	4.713	4.691	3.863
RSRM Liner Thickness	0.49	0.66	0.76	0.79	0.81	0.89	0.88	0.80	0.78	0.68	0.31	0.13	0.21
Margin of Safety													

Minimum margin of safety is 0.10 at station 24.00 degree 180.00
 Maximum margin of safety is 0.89 at station 12.00 degree 270.00

* Measured char adjusted to end of action time

$$\text{Margin of Safety} = \frac{\text{minimum liner thickness}}{2.00 \times \text{erosion} + 1.25 \times \text{adj char}} - 1$$

Table 6



RSRM-26B Nose Inlet Assembly Erosion and Char Data

Angular Location	Stations						
	28.0	30.0	32.0	34.0	36.0	38.0	39.0
0 degrees	28.0	30.0	32.0	34.0	36.0	38.0	39.0
Measured Erosion	1.06	0.86	0.94	0.83	0.85	0.95	0.97
Measured Char	0.70	0.67	0.66	0.59	0.56	0.61	0.65
Adjusted Char *	0.53	0.50	0.50	0.44	0.42	0.46	0.49
Denominator	2.78	2.35	2.50	2.21	2.23	2.47	2.55
RSRM Liner Thickness	3.508	3.252	2.950	3.182	3.200	3.026	3.000
Margin of Safety	0.26	0.38	0.18	0.44	0.44	0.22	0.18
90 degrees							
Measured Erosion	1.10	0.87	0.95	0.82	0.86	0.91	0.96
Measured Char	0.77	0.76	0.63	0.58	0.60	0.63	0.71
Adjusted Char *	0.58	0.57	0.47	0.43	0.45	0.47	0.53
Denominator	2.92	2.45	2.49	2.18	2.28	2.41	2.59
RSRM Liner Thickness	3.508	3.252	2.950	3.182	3.200	3.026	3.000
Margin of Safety	0.20	0.33	0.18	0.46	0.40	0.26	0.16
180 degrees							
Measured Erosion	1.14	0.89	0.95	0.82	0.92	1.00	1.02
Measured Char	0.63	0.66	0.62	0.62	0.56	0.56	0.62
Adjusted Char *	0.47	0.50	0.47	0.47	0.42	0.42	0.47
Denominator	2.87	2.40	2.48	2.22	2.37	2.52	2.62
RSRM Liner Thickness	3.508	3.252	2.950	3.182	3.200	3.026	3.000
Margin of Safety	0.22	0.36	0.19	0.43	0.35	0.20	0.14
270 degrees							
Measured Erosion	1.16	0.93	0.98	0.84	0.86	0.93	0.97
Measured Char	0.70	0.65	0.62	0.60	0.58	0.63	0.67
Adjusted Char *	0.53	0.49	0.47	0.45	0.43	0.47	0.50
Denominator	2.98	2.47	2.54	2.24	2.26	2.45	2.57
RSRM Liner Thickness	3.508	3.252	2.950	3.182	3.200	3.026	3.000
Margin of Safety	0.18	0.32	0.16	0.42	0.41	0.23	0.17

* Measured char adjusted to end of action time

$$\text{Margin of Safety} = \frac{\text{minimum liner thickness}}{2.00 \times \text{erosion} + 1.25 \times \text{adj char}} - 1$$

Table 6



Stations

Angular Location	0.3	1.0	2.0	3.0	4.0
0 degrees					
Measured Erosion	0.17	0.21	0.28	0.31	
Measured Char	0.70	0.67	0.67	0.66	
Adjusted Char *	0.56	0.54	0.54	0.53	
Denominator	1.04	1.09	1.23	1.28	
RSRM Liner Thickness	1.438	1.499	1.577	1.655	1.733
Margin of Safety	0.38	0.38	0.28	0.29	

90 degrees

Measured Erosion	0.21	0.25	0.28	0.31	
Measured Char	0.60	0.59	0.62	0.62	
Adjusted Char *	0.48	0.47	0.50	0.50	
Denominator	1.02	1.09	1.18	1.24	
RSRM Liner Thickness	1.438	1.499	1.577	1.655	1.733
Margin of Safety	0.41	0.38	0.34	0.33	

180 degrees

Measured Erosion	0.19	0.23	0.28	0.28	0.31
Measured Char	0.66	0.62	0.59	0.65	0.66
Adjusted Char *	0.53	0.50	0.47	0.52	0.53
Denominator	1.04	1.08	1.15	1.21	1.28
RSRM Liner Thickness	1.438	1.499	1.577	1.655	1.733
Margin of Safety	0.38	0.39	0.37	0.37	0.35

270 degrees

Measured Erosion	0.20	0.23	0.27	0.28	0.25
Measured Char	0.64	0.67	0.62	0.65	0.71
Adjusted Char *	0.51	0.54	0.50	0.52	0.57
Denominator	1.04	1.13	1.16	1.21	1.21
RSRM Liner Thickness	1.438	1.499	1.577	1.655	1.733
Margin of Safety	0.38	0.33	0.36	0.37	0.43

Minimum margin of safety is 0.28 at station 2.00 degree 0.00
 Maximum margin of safety is 0.53 at station 6.80 degree 180.00

* Measured char adjusted to end of action time

Margin of Safety = $\frac{\text{minimum liner thickness}}{2.00 \text{ X erosion} + 1.25 \text{ X adj char}}$ - 1



Angular Location	Stations										
	0	1.0	2.0	3.0	4.0	9.0	10.0	11.3			
0 degrees	0.3	1.0	2.0	3.0	4.0	9.0	10.0	11.3			
Measured Erosion	0.25	0.31	0.33	0.37	0.35	0.01	0.03	0.05			
Measured Char	0.62	0.63	0.55	0.58	0.60	0.98	0.97	1.09			
Adjusted Char *	0.50	0.50	0.44	0.46	0.48	0.78	0.78	0.87			
Denominator	1.12	1.25	1.21	1.32	1.30	1.19	1.21	1.38			
RSRM Liner Thickness	1.438	1.499	1.577	1.655	1.733	1.674	1.687	1.703			
Margin of Safety	0.28	0.20	0.30	0.25	0.33	0.41	0.40	0.23			
90 degrees											
Measured Erosion	0.29	0.30	0.32	0.35	0.35	0.01	0.01	0.00			
Measured Char	0.58	0.57	0.60	0.60	0.59	1.33	1.33	1.14			
Adjusted Char *	0.46	0.46	0.48	0.48	0.47	1.06	1.06	0.91			
Denominator	1.16	1.17	1.24	1.30	1.29	1.61	1.61	1.37			
RSRM Liner Thickness	1.438	1.499	1.577	1.655	1.733	1.674	1.687	1.703			
Margin of Safety	0.24	0.28	0.27	0.27	0.34	0.05	0.05	0.24			
140 degrees											
Measured Erosion									0.07	0.07	
Measured Char									1.08	1.02	
Adjusted Char *									0.86	0.82	
Denominator									1.40	1.33	
RSRM Liner Thickness	1.438	1.499	1.577	1.655	1.733	1.674	1.687	1.703			
Margin of Safety									0.20	0.28	
180 degrees											
Measured Erosion	0.28	0.28	0.32	0.33	0.35			0.07	0.09	0.07	
Measured Char	0.69	0.68	0.63	0.62	0.63			1.10	1.10	1.17	
Adjusted Char *	0.55	0.54	0.50	0.50	0.50			0.88	0.88	0.94	
Denominator	1.25	1.24	1.27	1.28	1.33			1.46	1.46	1.51	
RSRM Liner Thickness	1.438	1.499	1.577	1.655	1.733	1.674	1.687	1.703			
Margin of Safety	0.15	0.21	0.24	0.29	0.30			0.16	0.16	0.13	
270 degrees											
Measured Erosion	0.25	0.29	0.30	0.31	0.31	0.10	0.11	0.09			
Measured Char	0.71	0.64	0.65	0.71	0.74	1.18	1.19	1.28			
Adjusted Char *	0.57	0.51	0.52	0.57	0.59	0.94	0.95	1.02			
Denominator	1.21	1.22	1.25	1.33	1.36	1.57	1.59	1.67			
RSRM Liner Thickness	1.438	1.499	1.577	1.655	1.733	1.674	1.687	1.703			
Margin of Safety	0.19	0.23	0.26	0.24	0.27	0.07	0.06	0.02			

Table 8



Angular Location	Stations										
	0	degrees	0.3	1.0	2.0	3.0	4.0	9.0	10.0	11.3	
0 degrees											
Measured Erosion		0.28	0.28	0.32	0.33	0.35	0.35	0.41	0.40	0.05	
Measured Char		0.69	0.63	0.63	0.62	0.60	0.63	0.63	0.63	0.97	
Adjusted Char *		0.50	0.44	0.48	0.48	0.47	0.47	0.47	0.47	0.78	
Denominator		1.12	1.17	1.24	1.30	1.29	1.29	1.19	1.21	1.38	
RSRM Liner Thickness		1.333	1.499	1.577	1.655	1.733	1.733	1.674	1.687	1.703	
Margin of Safety		1.333	1.499	1.577	1.655	1.733	1.733	1.674	1.687	1.703	
90 degrees											
Measured Erosion		0.24	0.24	0.32	0.35	0.35	0.35	0.41	0.40	0.05	
Measured Char		0.69	0.63	0.63	0.62	0.60	0.63	0.63	0.63	0.97	
Adjusted Char *		0.50	0.44	0.48	0.48	0.47	0.47	0.47	0.47	0.78	
Denominator		1.12	1.17	1.24	1.30	1.29	1.29	1.19	1.21	1.38	
RSRM Liner Thickness		1.333	1.499	1.577	1.655	1.733	1.733	1.674	1.687	1.703	
Margin of Safety		1.333	1.499	1.577	1.655	1.733	1.733	1.674	1.687	1.703	
140 degrees											
Measured Erosion		0.07	0.07	0.32	0.35	0.35	0.35	0.41	0.40	0.05	
Measured Char		1.08	1.08	1.08	1.08	1.08	1.08	1.08	1.08	1.08	
Adjusted Char *		0.86	0.86	0.86	0.86	0.86	0.86	0.86	0.86	0.86	
Denominator		1.40	1.40	1.40	1.40	1.40	1.40	1.40	1.40	1.40	
RSRM Liner Thickness		1.438	1.499	1.577	1.655	1.733	1.733	1.674	1.687	1.703	
Margin of Safety		1.438	1.499	1.577	1.655	1.733	1.733	1.674	1.687	1.703	
180 degrees											
Measured Erosion		0.28	0.28	0.32	0.33	0.35	0.35	0.41	0.40	0.05	
Measured Char		0.69	0.63	0.63	0.62	0.60	0.63	0.63	0.63	0.97	
Adjusted Char *		0.50	0.44	0.48	0.48	0.47	0.47	0.47	0.47	0.78	
Denominator		1.12	1.17	1.24	1.30	1.29	1.29	1.19	1.21	1.38	
RSRM Liner Thickness		1.333	1.499	1.577	1.655	1.733	1.733	1.674	1.687	1.703	
Margin of Safety		1.333	1.499	1.577	1.655	1.733	1.733	1.674	1.687	1.703	

Table 8

RSRM-26A Fixed Housing Assembly Erosion and Char Data

Angular Location	Stations											
	0	1.00	2.00	3.00	4.00	5.00	6.00	7.00	8.00	9.00	10.75	
0 degrees	0.00	0.06	0.01	0.02	0.02	0.01	0.01	0.00	0.00	0.00	0.00	0.12
Measured Erosion	0.11	0.06	0.01	0.02	0.02	0.01	0.01	0.00	0.00	0.00	0.00	0.12
Measured Char	1.16	1.07	1.08	1.07	1.03	1.04	1.01	1.02	1.02	0.85	0.87	1.82
Adjusted Char *	0.93	0.86	0.86	0.86	0.82	0.83	0.81	0.82	0.82	0.68	0.70	1.46
Denominator	1.38	1.19	1.10	1.11	1.07	1.06	1.03	1.02	1.02	0.85	0.87	2.06
RSRM Liner Thickness	3.807	2.081	1.825	1.827	1.829	1.831	1.832	1.834	1.836	2.426	2.426	3.048
Margin of Safety	1.76	0.75	0.66	0.65	0.71	0.73	0.78	0.80	1.16	1.79	1.79	0.48
90 degrees												
Measured Erosion	0.09	0.06	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.01	0.17
Measured Char	1.01	1.06	1.04	1.02	1.03	1.00	1.01	0.93	0.90	0.70	0.78	1.65
Adjusted Char *	0.81	0.85	0.81	0.82	0.82	0.80	0.81	0.74	0.72	0.62	0.62	1.32
Denominator	1.19	1.18	1.04	1.02	1.03	1.00	1.01	0.93	0.90	0.80	0.80	1.99
RSRM Liner Thickness	3.807	2.081	1.825	1.827	1.829	1.831	1.832	1.834	1.836	2.426	2.426	3.048
Margin of Safety	2.20	0.76	0.75	0.79	0.78	0.83	0.81	0.97	1.04	2.03	2.03	0.53
180 degrees												
Measured Erosion	0.07	0.06	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.05
Measured Char	1.14	1.05	1.01	1.04	1.01	0.98	0.95	0.96	0.91	0.83	0.83	1.69
Adjusted Char *	0.91	0.84	0.81	0.83	0.81	0.78	0.76	0.77	0.73	0.66	0.66	1.35
Denominator	1.28	1.17	1.01	1.04	1.01	0.98	0.95	0.96	0.91	0.83	0.83	1.79
RSRM Liner Thickness	3.807	2.081	1.825	1.827	1.829	1.831	1.832	1.834	1.836	2.426	2.426	3.048
Margin of Safety	1.97	0.78	0.81	0.76	0.81	0.87	0.93	0.91	1.02	1.92	1.92	0.70
270 degrees												
Measured Erosion	0.07	0.03	0.02	0.01	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.13
Measured Char	1.07	1.03	1.07	1.12	1.09	1.10	1.09	1.05	0.99	0.97	0.97	1.73
Adjusted Char *	0.86	0.82	0.86	0.90	0.87	0.88	0.87	0.84	0.79	0.78	0.78	1.38
Denominator	1.21	1.09	1.11	1.14	1.09	1.10	1.09	1.05	0.99	0.97	0.97	1.99
RSRM Liner Thickness	3.807	2.081	1.825	1.827	1.829	1.831	1.832	1.834	1.836	2.426	2.426	3.048
Margin of Safety	2.15	0.91	0.64	0.60	0.68	0.66	0.68	0.75	0.85	1.50	1.50	0.53

Minimum margin of safety is 0.48 at station 10.75 degree 0.00
 Maximum margin of safety is 2.20 at station 0.00 degree 90.00

* Measured char adjusted to end of action time

$$\text{Margin of Safety} = \frac{\text{minimum liner thickness}}{2.00 \times \text{erosion} + 1.25 \times \text{adj char}^*} - 1$$

Table 9

RSRM-26B Fixed Housing Assembly Erosion and Char Data

Angular Location	Stations										
	0	1.00	2.00	3.00	4.00	5.00	6.00	7.00	8.00	9.00	10.75
Measured Erosion	0.09	0.06	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Measured Char	0.90	0.99	0.92	0.91	0.89	0.86	0.88	0.87	0.79	0.79	0.79
Adjusted Char *	0.72	0.79	0.74	0.73	0.71	0.69	0.70	0.70	0.63	0.63	0.63
Denominator	1.08	1.11	0.92	0.91	0.89	0.86	0.88	0.87	0.79	0.79	0.79
RSRM Liner Thickness	3.807	2.081	1.825	1.827	1.829	1.831	1.832	1.834	1.836	2.426	3.048
Margin of Safety	2.52	0.87	0.98	1.01	1.06	1.13	1.08	1.11	1.32	1.61	0.53
90 degrees											
Measured Erosion	0.08	0.04	0.01	0.00	0.00	0.00	0.02	0.00	0.00	0.00	0.07
Measured Char	1.17	1.08	0.95	0.97	0.93	0.96	0.91	0.95	0.90	0.93	1.85
Adjusted Char *	0.94	0.86	0.76	0.78	0.74	0.77	0.73	0.76	0.72	0.74	1.48
Denominator	1.33	1.16	0.97	0.97	0.93	0.96	0.95	0.95	0.90	0.93	1.99
RSRM Liner Thickness	3.807	2.081	1.825	1.827	1.829	1.831	1.832	1.834	1.836	2.426	3.048
Margin of Safety	1.86	0.79	0.88	0.88	0.97	0.91	0.93	0.93	1.04	1.61	0.53
180 degrees											
Measured Erosion	0.06	0.02	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Measured Char	1.19	1.11	0.99	0.96	1.02	1.00	0.99	1.00	0.85	0.85	0.85
Adjusted Char *	0.95	0.89	0.79	0.77	0.82	0.80	0.79	0.80	0.68	0.68	0.68
Denominator	1.31	1.15	0.99	0.96	1.02	1.00	0.99	1.00	0.85	0.85	0.85
RSRM Liner Thickness	3.807	2.081	1.825	1.827	1.829	1.831	1.832	1.834	1.836	2.426	3.048
Margin of Safety	1.91	0.81	0.84	0.90	0.79	0.83	0.85	0.83	1.16	1.61	0.53
270 degrees											
Measured Erosion	0.10	0.05	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Measured Char	1.08	1.09	1.02	0.99	0.98	0.99	0.98	1.00	0.87	0.76	1.70
Adjusted Char *	0.86	0.87	0.82	0.79	0.78	0.79	0.78	0.80	0.70	0.61	1.36
Denominator	1.28	1.19	1.02	0.99	0.98	0.99	0.98	1.00	0.87	0.76	1.70
RSRM Liner Thickness	3.807	2.081	1.825	1.827	1.829	1.831	1.832	1.834	1.836	2.426	3.048
Margin of Safety	1.97	0.75	0.79	0.85	0.87	0.85	0.87	0.83	1.11	2.19	0.79

Minimum margin of safety is 0.53 at station 10.75 degree 90.00
 Maximum margin of safety is 2.52 at station 0.00 degree 0.00

* Measured char adjusted to end of action time

Margin of Safety = $\frac{\text{minimum liner thickness}}{2.00 \text{ X erosion} + 1.25 \text{ X adj char}}$ - 1

REVISION _____

Table 10





Appendix E Insulation Postfire Data

Final Postflight Hardware Evaluation Report 360T026 (RSRM-26, STS-47)

April 1993

Prepared for:

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION
GEORGE C. MARSHALL SPACE FLIGHT CENTER
MARSHALL SPACE FLIGHT CENTER, ALABAMA 35812

Contract No. NAS8-38100

DR No. 4-23

WBS No. 4C601-04-01

ECS No. SS4769

Thiokol CORPORATION
SPACE OPERATIONS

P.O. Box 707, Brigham City, Utah 84302-0707 (801) 863-3511

360T026 Appendix E Contents

List of Tables

<u>Table</u>	<u>Description</u>	<u>Page</u>
1	RSRM-26A Nozzle-to-Case Joint Performance	E-2
2	RSRM-26A Aft Field Joint Performance	E-3
3	RSRM-26A Center Field Joint Performance	E-4
4	RSRM-26A Forward Field Joint Performance	E-5
5	RSRM-26A Aft Dome Insulation Performance	E-6
6	RSRM-26A Aft Cylinder Insulation Performance	E-9
7	RSRM-26A Aft Center Segment Insulation Performance	E-15
8	RSRM-26A Forward Center Segment Insulation Performance ...	E-18
9	RSRM-26A Forward Segment Star Tip Insulation Performance ..	E-21
10	RSRM-26A Fwd. Segment Non-Star Tip Insulation Performance	E-24
11	RSRM-26A Igniter Chamber and Adapter Insulation Performance	E-27
12	RSRM-26B Igniter Chamber and Adapter Insulation Performance	E-30

TABLE 1

RSRM-26A NOZZLE TO CASE JOINT PERFORMANCE

DEGREE LOCATION	PREFIRE (INCHES)	POSTFIRE (INCHES)	MDD	CSF	ASF
0.0	5.633	4.262	1.371	3.6	4.1
21.6	5.626				
46.8	5.618	5.000	0.618	7.9	9.1
68.4	5.607				
90.0	5.622	4.962	0.660	7.4	8.5
111.6	5.629				
136.8	5.635	4.731	0.904	5.4	6.2
158.4	5.623				
180.0	5.628	4.710	0.918	5.3	6.1
201.6	5.624				
226.8	5.582	4.481	1.101	4.5	5.1
248.4	5.606				
270.0	5.622	4.797	0.825	5.9	6.8
291.6	5.621				
316.8	5.594	4.878	0.716	6.8	7.8
338.4	5.606				
	MEDIAN	MEDIAN	MEDIAN	MINIMUM	MINIMUM
	5.622	4.764	0.865	3.6	4.1

A SAFETY FACTOR OF 2.0 IS REQUIRED

A BLANK INDICATES THAT POSTFIRE DATA COLLECTION IS NOT REQUIRED AT THAT LOCATION

TABLE 2

RSRM-26A AFT FIELD JOINT PERFORMANCE

DEGREE LOCATION	PREFIRE (INCHES)	POSTFIRE (INCHES)	MDD	CSF	ASF
2.0	2.686	2.358	0.328	7.9	8.2
16.0	2.698				
30.0	2.696				
46.0	2.701	2.294	0.407	6.4	6.6
60.0	2.704				
76.0	2.697				
90.0	2.704	2.270	0.434	6.0	6.2
106.0	2.703				
120.0	2.706				
136.0	2.702	2.330	0.372	7.0	7.3
150.0	2.701				
166.0	2.699				
180.0	2.704	2.278	0.426	6.1	6.3
196.0	2.702				
210.0	2.700				
226.0	2.697	2.285	0.412	6.3	6.5
242.0	2.701				
256.0	2.704				
270.0	2.699	2.305	0.394	6.6	6.9
286.0	2.706				
300.0	2.703				
316.0	2.702	2.322	0.380	6.8	7.1
330.0	2.697				
346.0	2.693				
	MEDIAN 2.701	MEDIAN 2.300	MEDIAN 0.401	MINIMUM 6.0	MINIMUM 6.2

A SAFETY FACTOR OF 2.0 IS REQUIRED

A BLANK INDICATES THAT POSTFIRE DATA COLLECTION IS NOT REQUIRED AT THAT LOCATION

TABLE 3

RSRM-26A CENTER FIELD JOINT PERFORMANCE

DEGREE LOCATION	PREFIRE (INCHES)	POSTFIRE (INCHES)	MDD	CSF	ASF
2.0	2.787	2.614	0.173	15.0	16.1
16.0	2.793				
30.0	2.793				
46.0	2.790	2.591	0.199	13.0	14.0
60.0	2.780				
76.0	2.770				
90.0	2.769	2.643	0.126	20.6	22.0
106.0	2.759				
120.0	2.765				
136.0	2.772	2.609	0.163	15.9	17.0
150.0	2.788				
166.0	2.795				
180.0	2.776	2.615	0.161	16.1	17.2
196.0	2.761				
210.0	2.752				
226.0	2.749	2.609	0.140	18.5	19.6
242.0	2.742				
256.0	2.760				
270.0	2.754	2.605	0.149	17.4	18.5
286.0	2.750				
300.0	2.751				
316.0	2.747	2.629	0.118	22.0	23.3
330.0	2.744				
346.0	2.749				
	MEDIAN	MEDIAN	MEDIAN	MINIMUM	MINIMUM
	2.763	2.612	0.155	13.0	14.0

A SAFETY FACTOR OF 2.0 IS REQUIRED

A BLANK INDICATES THAT POSTFIRE DATA COLLECTION IS NOT REQUIRED AT THAT LOCATION

TABLE 4

RSRM-26A FORWARD FIELD JOINT PERFORMANCE

DEGREE LOCATION	PREFIRE (INCHES)	POSTFIRE (INCHES)	MDD	CSF	ASF
2.0	2.706	2.621	0.085	30.5	31.8
16.0	2.689				
30.0	2.688				
46.0	2.705	2.642	0.063	41.2	42.9
60.0	2.680				
76.0	2.691				
90.0	2.687	2.659	0.028	92.7	96.0
106.0	2.693				
120.0	2.710				
136.0	2.799	2.636	0.163	15.9	17.2
150.0	2.786				
166.0	2.754				
180.0	2.770	2.618	0.152	17.1	18.2
196.0	2.768				
210.0	2.762				
226.0	2.775	2.609	0.166	15.6	16.7
242.0	2.757				
256.0	2.747				
270.0	2.745	2.625	0.120	21.6	22.9
286.0	2.763				
300.0	2.737				
316.0	2.751	2.633	0.118	22.0	23.3
330.0	2.744				
346.0	2.727				
	MEDIAN 2.744	MEDIAN 2.629	MEDIAN 0.119	MINIMUM 15.6	MINIMUM 16.7

A SAFETY FACTOR OF 2.0 IS REQUIRED

A BLANK INDICATES THAT POSTFIRE DATA COLLECTION IS NOT REQUIRED AT THAT LOCATION

TABLE 5
RSRM-26A AFT DOME INSULATION PERFORMANCE

COMPLIANCE SAFETY FACTOR (CSF)

STATION (IN)	DEGREE LOCATIONS										REQUIRED S.F.
	0.0	46.8	90.0	136.8	180.0	226.8	270.0	316.8	MIN.	PLANE	
9.3	4.58	4.18	4.61	4.96	3.91	4.38	4.84	5.88	3.91	180.0	1.5
10.7	5.37	4.02	4.51	4.24	3.72	4.16	4.67	4.45	3.72	180.0	1.5
12.0	5.03	3.70	3.85	3.90	2.07	3.69	3.67	4.25	2.07	180.0	1.5
13.1	5.30	3.35	3.39	3.87	3.81	3.15	3.26	3.91	3.15	226.8	1.5
14.4	5.54	3.18	3.48	3.77	4.13	3.07	3.20	3.63	3.07	226.8	1.5
16.0	5.01	3.08	3.48	3.31	4.42	3.14	3.16	3.46	3.08	46.8	1.5
17.3	5.04	3.26	3.67	3.38	4.70	3.31	3.38	4.29	3.26	46.8	1.5
18.5	5.64	3.76	4.16	3.50	5.25	3.64	3.43	3.56	3.43	270.0	1.5
19.5	5.30	4.29	4.43	3.81	5.17	4.49	4.40	4.04	3.81	136.8	1.5
21.3	5.86	4.43	4.19	4.03	4.32	4.34	4.66	3.95	3.95	316.8	1.5
24.3	4.79	3.87	3.24	3.09	3.53	3.65	3.49	4.02	3.09	136.8	1.5
33.0	2.61	2.48	2.60	2.42	2.55	2.33	2.49	2.30	2.30	316.8	1.5
45.0	2.41	2.18	2.64	2.49	2.65	2.27	2.32	2.22	2.18	46.8	1.5
53.0	2.91	2.82	3.52	3.61	3.93	3.50	3.37	3.14	2.82	46.8	1.5
56.0	3.06	3.41	3.60	3.69	4.09	5.20	5.82	3.73	3.06	0.0	2.0
72.0	4.38	4.83	5.73	3.65	4.16	4.13	4.25	4.13	3.65	136.8	1.5
75.0	4.16	4.38	5.92	6.52	4.29	4.11	3.77	3.81	3.77	270.0	1.5
78.0	3.92	4.28	6.15	3.23	4.23	4.24	3.91	3.70	3.23	136.8	1.5

SEGMENT MINIMUM = 2.07 AT THE 12.0 INCH STATION

ACTUAL SAFETY FACTOR (ASF)

STATION (IN)	DEGREE LOCATIONS										REQUIRED S.F.
	0.0	46.8	90.0	136.8	180.0	226.8	270.0	316.8	MIN.	PLANE	
9.3	4.69	4.41	4.94	5.04	4.01	4.58	4.93	5.86	4.01	180.0	1.5
10.7	5.82	4.41	4.91	4.64	4.05	4.57	5.00	4.81	4.05	180.0	1.5
12.0	5.53	4.11	4.23	4.32	2.74	4.09	4.00	4.68	2.74	180.0	1.5
13.1	5.86	3.76	3.76	4.31	4.22	3.50	3.58	4.34	3.50	226.8	1.5
14.4	5.99	3.50	3.80	4.11	4.50	3.37	3.47	3.98	3.37	226.8	1.5
16.0	5.55	3.43	3.89	3.71	4.90	3.51	3.50	3.94	3.43	46.8	1.5
17.3	5.76	3.76	4.21	3.93	5.40	3.82	3.85	4.90	3.76	46.8	1.5
18.5	6.64	4.42	4.90	4.17	6.20	4.32	4.04	4.23	4.04	270.0	1.5
19.5	6.39	5.22	5.30	4.65	6.24	5.35	5.24	4.87	4.65	136.8	1.5
21.3	6.98	5.28	4.98	4.77	5.16	5.09	5.49	4.71	4.71	316.8	1.5
24.3	5.68	4.67	3.90	3.72	4.16	4.30	4.06	4.73	3.72	136.8	1.5
33.0	2.93	2.84	2.91	2.78	2.98	2.73	2.85	2.68	2.68	316.8	1.5
45.0	2.62	2.37	2.81	2.74	2.99	2.61	2.57	2.43	2.37	46.8	1.5
53.0	3.31	3.18	3.82	4.00	4.36	3.91	3.73	3.56	3.18	46.8	1.5
56.0	3.83	4.29	4.29	4.44	4.93	6.29	6.98	4.54	3.83	0.0	2.0
72.0	4.90	5.15	6.09	4.21	4.64	4.74	4.74	4.58	4.21	136.8	1.5
75.0	4.54	4.93	6.31	7.26	4.76	4.75	4.26	4.34	4.26	270.0	1.5
78.0	4.15	4.72	6.56	3.61	4.62	4.74	4.32	4.19	3.61	136.8	1.5

SEGMENT MINIMUM = 2.37 AT THE 45.0 INCH STATION

TABLE 5
RSM-26A AFT DOME INSULATION PERFORMANCE

MATERIAL DECOMPOSITION DEPTH (MDD)
INCHES

STATION (IN)	DEGREE LOCATIONS										DESIGN M+3S
	0.0	46.8	90.0	136.8	180.0	226.8	270.0	316.8	MEDIAN	MAX.	
9.3	1.070	1.173	1.063	0.988	1.253	1.120	1.012	0.834	1.066	1.253	2.560
10.7	0.876	1.169	1.043	1.108	1.264	1.129	1.007	1.056	1.082	1.264	2.261
12.0	0.894	1.215	1.170	1.154	2.171	1.220	1.225	1.058	1.192	2.171	2.208
13.1	0.811	1.284	1.270	1.112	1.129	1.366	1.318	1.099	1.200	1.366	2.218
14.4	0.740	1.289	1.178	1.088	0.992	1.334	1.282	1.128	1.153	1.334	2.225
16.0	0.754	1.229	1.085	1.143	0.856	1.203	1.196	1.092	1.118	1.229	1.980
17.3	0.707	1.092	0.969	1.054	0.757	1.075	1.052	0.829	1.010	1.092	1.675
18.5	0.596	0.893	0.808	0.960	0.640	0.922	0.980	0.943	0.907	0.980	1.496
19.5	0.594	0.734	0.711	0.826	0.609	0.702	0.716	0.780	0.714	0.826	1.617
21.3	0.502	0.664	0.701	0.729	0.680	0.677	0.631	0.744	0.678	0.744	1.654
24.3	0.614	0.760	0.908	0.950	0.833	0.806	0.843	0.732	0.820	0.950	1.832
33.0	1.226	1.292	1.233	1.320	1.257	1.371	1.283	1.392	1.288	1.392	1.399
45.0	1.079	1.193	0.984	1.043	0.980	1.144	1.121	1.169	1.100	1.193	1.222
53.0	1.162	1.200	0.959	0.936	0.859	0.965	1.002	1.077	0.983	1.200	1.305
56.0	0.912	0.817	0.774	0.756	0.682	0.537	0.479	0.748	0.752	0.912	1.369
72.0	0.457	0.414	0.349	0.548	0.481	0.484	0.471	0.484	0.476	0.548	0.817
75.0	0.433	0.411	0.304	0.276	0.420	0.438	0.478	0.473	0.426	0.478	0.773
78.0	0.408	0.374	0.260	0.495	0.378	0.377	0.409	0.432	0.393	0.495	0.718

MATERIAL DECOMPOSITION RATE (MDR)
MILS / SECOND

STATION (IN)	DEGREE LOCATIONS EXPOSURE AVE. TIME									
	0.0	46.8	90.0	136.8	180.0	226.8	270.0	316.8	MEDIAN	MAX.
9.3	8.9	9.8	8.9	8.3	10.5	9.4	8.5	7.0	8.9	119.6
10.7	7.5	9.9	8.9	9.4	10.8	9.6	8.6	9.0	9.2	117.5
12.0	7.8	10.6	10.2	10.1	19.0	10.7	10.7	9.2	11.0	114.5
13.1	7.3	11.5	11.4	9.9	10.1	12.2	11.8	9.8	10.5	111.8
14.4	6.8	11.8	10.8	10.0	9.1	12.2	11.8	10.3	10.3	109.1
16.0	7.1	11.6	10.2	10.8	8.1	11.3	11.3	10.3	10.1	106.1
17.3	6.9	10.6	9.4	10.2	7.3	10.4	10.2	8.0	9.1	103.2
18.5	5.9	8.8	8.0	9.5	6.3	9.1	9.7	9.3	8.3	101.1
19.5	6.0	7.4	7.2	8.3	6.1	7.1	7.2	7.9	7.2	99.1
21.3	5.2	6.9	7.3	7.6	7.1	7.1	6.6	7.8	7.0	95.8
24.3	6.7	8.3	9.9	10.3	9.1	8.8	9.2	8.0	8.8	91.9
33.0	15.0	15.8	15.1	16.1	15.3	16.7	15.7	17.0	15.8	81.9
45.0	14.7	16.2	13.4	14.2	13.3	15.6	15.3	15.9	14.8	73.5
53.0	15.9	16.4	13.1	12.8	11.8	13.2	13.7	14.7	14.0	73.1
56.0	12.5	11.2	10.6	10.4	9.4	7.4	6.6	10.3	9.8	72.9
72.0	8.3	7.5	6.3	9.9	8.7	8.8	8.5	8.8	8.3	55.3
75.0	8.7	8.3	6.1	5.6	8.5	8.8	9.6	9.5	8.1	49.6
78.0	9.0	8.2	5.7	10.9	8.3	8.3	9.0	9.5	8.6	45.5

REVISION _____

MOTOR ACTION TIME = 120.4 SECONDS

TABLE 5
RSRM-26A AFT DOME INSULATION PERFORMANCE

PART NO. 1U76668-02
SERIAL NO. 0000020

PREPIRE MEASUREMENTS
INCHES

STATION (IN)	DEGREE LOCATIONS										MDT
	0.0	46.8	90.0	136.8	180.0	226.8	270.0	316.8	MIN.	MEDIAN	
9.3	5.017	5.171	5.252	4.983	5.028	5.134	4.991	4.887	4.887	5.023	4.900
10.7	5.094	5.156	5.121	5.140	5.121	5.161	5.039	5.076	5.039	5.121	4.700
12.0	4.940	4.996	4.948	4.987	4.958	4.991	4.901	4.950	4.901	4.969	4.500
13.1	4.756	4.832	4.781	4.793	4.762	4.776	4.723	4.769	4.723	4.773	4.300
14.4	4.435	4.516	4.473	4.474	4.460	4.495	4.448	4.492	4.435	4.474	4.100
16.0	4.187	4.215	4.216	4.241	4.196	4.219	4.190	4.304	4.187	4.216	3.780
17.3	4.073	4.102	4.082	4.146	4.085	4.103	4.047	4.065	4.047	4.083	3.560
18.5	3.959	3.944	3.956	4.001	3.965	3.987	3.962	3.985	3.944	3.964	3.360
19.5	3.795	3.830	3.767	3.838	3.799	3.758	3.755	3.797	3.755	3.796	3.150
21.3	3.506	3.504	3.493	3.480	3.508	3.443	3.464	3.503	3.443	3.498	2.940
24.3	3.486	3.549	3.545	3.535	3.469	3.462	3.422	3.465	3.422	3.478	2.940
33.0	3.597	3.671	3.591	3.671	3.745	3.743	3.661	3.730	3.591	3.671	3.200
45.0	2.831	2.827	2.761	2.853	2.928	2.984	2.882	2.845	2.761	2.849	2.600
53.0	3.842	3.817	3.668	3.746	3.748	3.774	3.734	3.839	3.668	3.761	3.380
56.0	3.492	3.507	3.322	3.357	3.363	3.380	3.344	3.397	3.322	3.372	2.790
72.0	2.241	2.133	2.125	2.306	2.233	2.292	2.234	2.215	2.125	2.234	2.000
75.0	1.967	2.028	1.917	2.005	2.000	2.079	2.035	2.052	1.917	2.017	1.800
78.0	1.692	1.764	1.705	1.787	1.748	1.787	1.767	1.808	1.692	1.766	1.600

PART NO. 1U76957-03
SERIAL NO. 0000011

POSTFIRE MEASUREMENTS
INCHES

STATION (IN)	DEGREE LOCATIONS										MDT
	0.0	46.8	90.0	136.8	180.0	226.8	270.0	316.8	MIN.	MEDIAN	
9.3	3.947	3.998	4.189	3.995	3.775	4.014	3.979	4.053	3.775	3.997	3.997
10.7	4.218	3.987	4.078	4.032	3.857	4.032	4.032	4.020	3.857	4.032	4.032
12.0	4.046	3.781	3.778	3.833	3.787	3.771	3.676	3.892	3.676	3.784	3.784
13.1	3.945	3.548	3.511	3.681	3.633	3.410	3.405	3.670	3.405	3.591	3.591
14.4	3.695	3.227	3.295	3.386	3.468	3.161	3.166	3.364	3.161	3.330	3.330
16.0	3.433	2.986	3.131	3.098	3.340	3.016	2.994	3.212	2.986	3.115	3.115
17.3	3.366	3.010	3.113	3.092	3.328	3.028	2.995	3.236	2.995	3.102	3.102
18.5	3.363	3.051	3.148	3.041	3.325	3.065	2.982	3.042	2.982	3.058	3.058
19.5	3.201	3.096	3.056	3.012	3.190	3.056	3.039	3.017	3.012	3.056	3.056
21.3	3.004	2.840	2.792	2.751	2.828	2.766	2.833	2.759	2.751	2.810	2.810
24.3	2.872	2.789	2.637	2.585	2.636	2.656	2.579	2.733	2.579	2.647	2.647
33.0	2.371	2.379	2.358	2.351	2.488	2.372	2.378	2.338	2.338	2.372	2.372
45.0	1.752	1.634	1.777	1.810	1.948	1.840	1.761	1.676	1.634	1.769	1.769
53.0	2.680	2.617	2.709	2.810	2.889	2.809	2.732	2.762	2.617	2.747	2.747
56.0	2.580	2.690	2.548	2.601	2.681	2.843	2.865	2.649	2.548	2.665	2.665
72.0	1.784	1.719	1.776	1.758	1.752	1.808	1.763	1.731	1.719	1.761	1.761
75.0	1.534	1.617	1.613	1.729	1.580	1.641	1.557	1.579	1.534	1.597	1.597
78.0	1.284	1.390	1.445	1.292	1.370	1.410	1.358	1.376	1.284	1.373	1.373

REVISION _____

TABLE 6
 RSRM-26A AFT CYLINDER INSULATION PERFORMANCE
 COMPLIANCE SAFETY FACTOR (CSF)

STATION (IN)	COMPLIANCE SAFETY FACTOR (CSF)										REQUIRED S.F.
	0.0	46.8	90.0	136.8	180.0	226.8	270.0	316.8	DEGREE LOCATIONS MIN.	PLANE	
85.0	3.57	3.05	3.62	3.25	3.78	4.96	3.12	3.37	3.05	46.8	1.5
90.0	2.85	3.45	3.83	3.19	3.17	4.85	3.15	2.96	2.85	0.0	1.5
98.0	2.51	3.05	3.21	2.40	2.49	3.28	2.59	2.43	2.40	136.8	1.5
105.8	2.62	2.71	2.92	2.51	2.76	2.27	2.66	2.64	2.27	226.8	1.5
116.0	2.65	3.01	2.94	2.64	2.63	2.62	2.69	2.71	2.62	226.8	1.5
124.5	2.33	3.07	2.77	2.53	2.70	2.75	2.62	2.42	2.33	0.0	1.5
133.0	2.25	2.63	2.68	2.58	2.63	2.68	2.40	2.44	2.25	0.0	1.5
145.5	2.28	2.45	2.38	2.27	2.44	2.30	2.61	2.38	2.27	136.8	1.5
158.5	2.43	2.55	2.57	2.94	2.53	2.91	2.99	2.38	2.38	316.8	1.5
166.0	3.06	2.59	3.06	2.58	2.25	2.44	2.56	2.29	2.25	180.0	1.5
177.7	2.51	3.02	3.22	2.40	2.18	2.34	2.52	3.68	2.18	180.0	2.0
192.5	2.49	2.61	2.84	2.77	3.02	2.69	3.16	2.95	2.49	0.0	1.5
202.5	2.53	3.02	2.75	2.65	2.57	3.17	2.73	2.91	2.53	0.0	1.5
214.0	2.63	2.62	3.04	2.64	2.46	2.78	3.15	3.02	2.46	180.0	1.5
227.3	3.14	2.84	2.50	3.65	3.01	3.11	2.70	3.07	2.50	90.0	1.5
238.3	3.04	3.42	2.84	2.81	3.42	3.00	3.28	3.04	2.81	136.8	1.5
250.0	2.61	2.50	2.93	2.75	2.63	2.85	3.16	3.14	2.50	46.8	1.5
269.0	2.60	3.27	3.55	3.27	2.96	2.81	5.43	3.01	2.60	0.0	1.5
283.9	2.83	2.59	3.06	3.00	2.56	2.83	3.98	2.78	2.56	180.0	1.5
299.1	3.43	4.42	3.41	3.12	2.86	3.60	3.25	3.86	2.86	180.0	2.0
322.0	3.11	2.79	2.64	3.22	3.14	3.19	3.19	3.69	2.64	90.0	1.5
339.0	5.28	4.81	7.92	3.80	5.67	2.68	3.96	4.00	2.68	226.8	1.5
358.0	6.03	+	+	47.50	42.22	4.87	+	8.44	4.87	226.8	1.5
367.0	5.00	3.22	3.28	4.75	3.36	5.28	3.22	5.94	3.22	46.8	1.5
377.5	9.14	3.05	4.86	5.30	3.66	5.25	8.55	4.31	3.05	46.8	1.5

SEGMENT MINIMUM = 2.18 AT THE 177.7 INCH STATION
 A " + " MEANS NEGLIGIBLE MDD HAS OCCURRED

TABLE 6
RSRM-26A AFT CYLINDER INSULATION PERFORMANCE

STATION (IN)	ACTUAL SAFETY FACTOR (ASF)										DEGREE LOCATIONS		REQUIRED S.F.
	0.0	46.8	90.0	136.8	180.0	226.8	270.0	316.8	MIN.	PLANE			
85.0	4.12	3.77	4.28	3.98	4.60	6.11	3.83	4.05	3.77	46.8	1.5		
90.0	3.41	4.08	4.35	3.79	3.81	5.81	3.78	3.54	3.41	0.0	1.5		
98.0	3.38	4.06	4.34	3.10	3.27	4.27	3.40	3.31	3.10	136.8	1.5		
105.8	2.72	2.83	3.04	2.64	2.94	2.43	2.85	2.79	2.43	226.8	1.5		
116.0	2.72	3.05	3.07	2.80	2.80	2.79	2.90	2.85	2.72	0.0	1.5		
124.5	2.45	3.18	2.93	2.71	2.92	2.95	2.83	2.60	2.45	0.0	1.5		
133.0	2.79	3.29	3.34	3.13	3.27	3.33	2.99	3.10	2.79	0.0	1.5		
145.5	2.32	2.51	2.47	2.34	2.50	2.36	2.63	2.42	2.32	0.0	1.5		
158.5	2.51	2.68	2.68	3.05	2.62	3.02	3.10	2.57	2.51	0.0	1.5		
166.0	3.70	3.16	3.71	3.29	3.02	3.13	3.28	2.94	2.94	316.8	1.5		
177.7	3.71	4.56	4.79	3.66	3.55	3.59	3.90	5.65	3.55	180.0	2.0		
192.5	2.89	3.05	3.29	3.34	3.64	3.18	3.65	3.44	2.89	0.0	1.5		
202.5	2.59	3.09	2.81	2.71	2.62	3.25	2.78	2.96	2.59	0.0	1.5		
214.0	2.68	2.72	3.13	2.66	2.58	2.88	3.20	3.06	2.58	180.0	1.5		
227.3	3.70	3.45	2.84	4.11	3.48	3.62	3.21	3.70	2.84	90.0	1.5		
238.3	3.12	3.49	2.93	2.83	3.49	3.07	3.34	3.08	2.83	136.8	1.5		
250.0	2.71	2.60	3.02	2.79	2.72	2.95	3.22	3.18	2.60	46.8	1.5		
269.0	3.02	3.79	4.20	3.80	3.43	3.30	6.28	3.49	3.02	0.0	1.5		
283.9	3.08	2.90	3.46	3.33	2.91	3.14	4.42	3.04	2.90	46.8	1.5		
299.1	5.47	7.01	5.50	5.06	4.68	5.84	5.39	6.23	4.68	180.0	2.0		
322.0	3.41	3.10	2.96	3.62	3.55	3.60	3.66	4.11	2.96	90.0	1.5		
339.0	5.88	5.29	8.79	4.18	6.39	2.99	4.43	4.45	2.99	226.8	1.5		
358.0	7.67	+	+	55.00	53.00	6.29	+	9.56	6.29	226.8	1.5		
367.0	6.14	4.17	4.19	6.21	4.27	6.78	4.14	7.81	4.14	270.0	1.5		
377.5	10.67	4.03	5.86	6.61	4.54	6.45	10.03	5.15	4.03	46.8	1.5		

SEGMENT MINIMUM = 2.32 AT THE 145.5 INCH STATION
A * + * MEANS NEGLIGIBLE MDD HAS OCCURRED

TABLE 6
RSRM-26A AFT CYLINDER INSULATION PERFORMANCE

MATERIAL DECOMPOSITION DEPTH (MDD)
INCHES

STATION (IN)	MATERIAL DECOMPOSITION DEPTH (MDD)										DEGREE LOCATIONS		DESIGN M+3S
	0.0	46.8	90.0	136.8	180.0	226.8	270.0	316.8	MEDIAN	MAX.			
85.0	0.364	0.426	0.359	0.400	0.344	0.262	0.416	0.386	0.375	0.426	0.618		
90.0	0.444	0.367	0.330	0.396	0.399	0.261	0.401	0.427	0.397	0.444	0.576		
98.0	0.453	0.372	0.354	0.473	0.455	0.346	0.439	0.467	0.446	0.473	0.582		
105.8	0.413	0.398	0.370	0.431	0.391	0.475	0.406	0.409	0.407	0.475	0.559		
116.0	0.396	0.349	0.357	0.397	0.399	0.401	0.390	0.387	0.393	0.401	0.527		
124.5	0.442	0.335	0.372	0.407	0.381	0.374	0.393	0.425	0.387	0.442	0.522		
133.0	0.436	0.372	0.366	0.380	0.373	0.366	0.409	0.402	0.377	0.436	0.516		
145.5	0.408	0.380	0.390	0.410	0.381	0.404	0.357	0.391	0.390	0.410	0.493		
158.5	0.362	0.345	0.342	0.299	0.348	0.302	0.294	0.369	0.344	0.369	0.491		
166.0	0.278	0.328	0.278	0.330	0.377	0.348	0.332	0.371	0.331	0.377	0.466		
177.7	0.399	0.331	0.311	0.416	0.459	0.428	0.397	0.272	0.398	0.459	0.452		
192.5	0.313	0.299	0.275	0.282	0.258	0.290	0.247	0.264	0.278	0.313	0.400		
202.5	0.288	0.242	0.265	0.275	0.284	0.230	0.267	0.251	0.266	0.288	0.376		
214.0	0.266	0.267	0.230	0.265	0.284	0.252	0.222	0.232	0.259	0.284	0.351		
227.3	0.207	0.229	0.260	0.178	0.216	0.209	0.241	0.212	0.214	0.260	0.317		
238.3	0.207	0.184	0.222	0.224	0.184	0.210	0.192	0.207	0.207	0.224	0.331		
250.0	0.211	0.220	0.188	0.200	0.209	0.193	0.174	0.175	0.197	0.220	0.285		
269.0	0.192	0.153	0.141	0.153	0.169	0.178	0.092	0.166	0.160	0.192	0.297		
283.9	0.159	0.174	0.147	0.150	0.176	0.159	0.113	0.162	0.159	0.176	0.251		
299.1	0.197	0.153	0.198	0.217	0.236	0.188	0.208	0.175	0.197	0.236	0.253		
322.0	0.122	0.136	0.144	0.118	0.121	0.119	0.119	0.103	0.120	0.144	0.197		
339.0	0.072	0.079	0.048	0.100	0.067	0.142	0.096	0.095	0.087	0.142	0.190		
358.0	0.063	0	0	0.008	0.009	0.078	0	0.045	0.008	0.078	0.181		
367.0	0.076	0.118	0.116	0.080	0.113	0.072	0.118	0.064	0.097	0.118	0.175		
377.5	0.058	0.174	0.109	0.100	0.145	0.101	0.062	0.123	0.105	0.174	0.237		

A * < " INDICATES THE PRECEDING MDD HAS EXCEEDED THE M + 3 SIGMA DESIGN CRITERIA

TABLE 6
RSRM-26A AFT CYLINDER INSULATION PERFORMANCE

MATERIAL DECOMPOSITION RATE (MDR)
MILS / SECOND

STATION (IN)	DEGREE LOCATION										EXPOSURE TIME
	0.0	46.8	90.0	136.8	180.0	226.8	270.0	316.8	AVE.		
85.0	8.2	9.6	8.1	9.0	7.8	5.9	9.4	8.7	8.4	44.2	
90.0	10.2	8.4	7.6	9.1	9.2	6.0	9.2	9.8	8.7	43.6	
98.0	10.6	8.7	8.3	11.1	10.7	8.1	10.3	11.0	9.9	42.6	
105.8	9.9	9.5	8.9	10.3	9.4	11.4	9.7	9.8	9.8	41.8	
116.0	9.7	8.5	8.7	9.7	9.7	9.8	9.5	9.4	9.4	41.0	
124.5	11.0	8.4	9.3	10.1	9.5	9.3	9.8	10.6	9.8	40.1	
133.0	11.2	9.6	9.4	9.8	9.6	9.4	10.5	10.3	10.0	38.9	
145.5	11.1	10.3	10.6	11.1	10.3	10.9	9.7	10.6	10.6	36.9	
158.5	10.2	9.7	9.7	8.4	9.8	8.5	8.3	10.4	9.4	35.4	
166.0	7.9	9.4	7.9	9.4	10.8	9.9	9.5	10.6	9.4	35.0	
177.7	11.9	9.9	9.3	12.4	13.7	12.7	11.8	8.1	11.2	33.6	
192.5	10.3	9.8	9.0	9.2	8.5	9.5	8.1	8.7	9.1	30.5	
202.5	9.9	8.3	9.1	9.5	9.8	7.9	9.2	8.6	9.0	29.1	
214.0	9.7	9.7	8.4	9.7	10.4	9.2	8.1	8.5	9.2	27.4	
227.3	8.1	9.0	10.2	7.0	8.5	8.2	9.5	8.3	8.6	25.4	
238.3	8.7	7.7	9.3	9.4	7.7	8.8	8.1	8.7	8.6	23.8	
250.0	9.5	9.9	8.4	9.0	9.4	8.7	7.8	7.8	8.8	22.3	
269.0	9.9	7.9	7.3	7.9	8.7	9.2	4.7	8.6	8.0	19.4	
283.9	9.6	10.5	8.9	9.0	10.6	9.6	6.8	9.8	9.3	16.6	
299.1	11.5	8.9	11.5	12.6	13.7	10.9	12.1	10.2	11.4	17.2	
322.0	9.8	10.9	11.5	9.4	9.7	9.5	9.5	8.2	9.8	12.5	
339.0	6.1	6.6	4.0	8.4	5.6	11.9	8.1	8.0	7.3	11.9	
358.0	5.7	0	0	0.7	0.8	7.0	0	4.1	2.3	11.1	
367.0	7.0	10.9	10.7	7.4	10.5	6.7	10.9	5.9	8.8	10.8	
377.5	2.9	8.7	5.5	5.0	7.3	5.1	3.1	6.2	5.5	19.9	

MOTOR ACTION TIME = 120.4 SECONDS

REVISION _____

TABLE 6
 RSRM-26A AFT CYLINDER INSULATION PERFORMANCE

PART NO. 1U76668-02
 SERIAL NO. 0000020

PREFIRE MEASUREMENTS
 INCHES

STATION (IN)	DEGREE LOCATIONS										MEDIAN	MDT
	0.0	46.8	90.0	136.8	180.0	226.8	270.0	316.8	MIN.			
85.0	1.501	1.608	1.537	1.592	1.583	1.602	1.592	1.565	1.501	1.587	1.300	
90.0	1.512	1.499	1.436	1.502	1.522	1.516	1.515	1.512	1.436	1.512	1.265	
98.0	1.533	1.512	1.535	1.466	1.486	1.478	1.491	1.547	1.466	1.502	1.135	
105.8	1.123	1.126	1.125	1.139	1.151	1.155	1.157	1.140	1.123	1.140	1.080	
116.0	1.076	1.065	1.096	1.110	1.116	1.117	1.132	1.102	1.065	1.106	1.050	
124.5	1.084	1.065	1.091	1.102	1.111	1.103	1.112	1.106	1.065	1.103	1.030	
133.0	1.215	1.223	1.224	1.189	1.218	1.220	1.221	1.247	1.189	1.220	0.980	
145.5	0.948	0.954	0.964	0.960	0.952	0.953	0.940	0.946	0.940	0.953	0.930	
158.5	0.908	0.925	0.916	0.912	0.912	0.912	0.912	0.947	0.908	0.912	0.880	
166.0	1.029	1.038	1.031	1.087	1.137	1.088	1.088	1.091	1.029	1.088	0.850	
177.7	1.482	1.509	1.489	1.523	1.630	1.538	1.549	1.538	1.482	1.531	1.000	
192.5	0.904	0.912	0.905	0.942	0.938	0.921	0.902	0.909	0.902	0.910	0.780	
202.5	0.745	0.748	0.744	0.745	0.744	0.748	0.741	0.742	0.741	0.745	0.730	
214.0	0.712	0.727	0.720	0.706	0.734	0.725	0.711	0.710	0.706	0.716	0.700	
227.3	0.766	0.789	0.738	0.731	0.751	0.757	0.774	0.785	0.731	0.762	0.650	
238.3	0.646	0.643	0.650	0.635	0.642	0.645	0.641	0.638	0.635	0.643	0.630	
250.0	0.571	0.571	0.567	0.557	0.569	0.569	0.560	0.557	0.557	0.568	0.550	
269.0	0.579	0.580	0.592	0.582	0.579	0.588	0.578	0.579	0.578	0.580	0.500	
283.9	0.490	0.504	0.509	0.500	0.512	0.500	0.499	0.492	0.490	0.500	0.450	
299.1	1.078	1.072	1.089	1.097	1.105	1.097	1.122	1.091	1.072	1.094	0.676	
322.0	0.416	0.421	0.426	0.427	0.430	0.428	0.436	0.423	0.416	0.426	0.380	
339.0	0.423	0.418	0.422	0.418	0.428	0.425	0.425	0.423	0.418	0.423	0.380	
358.0	0.483	0.420	0.441	0.440	0.477	0.491	0.430	0.430	0.420	0.441	0.380	
367.0	0.467	0.492	0.486	0.497	0.483	0.488	0.488	0.500	0.467	0.488	0.380	
377.5	0.619	0.701	0.639	0.661	0.659	0.651	0.622	0.633	0.619	0.645	0.530	

REVISION _____

TABLE 6
RSRM-26A AFT CYLINDER INSULATION PERFORMANCE

POSTFIRE MEASUREMENTS
INCHES

PART NO. IU76957-03
SERIAL NO. 0000011

STATION (IN)	DEGREE LOCATIONS											MEDIAN
	0.0	46.8	90.0	136.8	180.0	226.8	270.0	316.8	MIN.			
85.0	1.137	1.182	1.178	1.192	1.239	1.340	1.176	1.179	1.137			1.181
90.0	1.068	1.132	1.106	1.106	1.123	1.255	1.114	1.085	1.068			1.110
98.0	1.080	1.140	1.181	0.993	1.031	1.132	1.052	1.080	0.993			1.080
105.8	0.710	0.728	0.755	0.708	0.760	0.680	0.751	0.731	0.680			0.729
116.0	0.680	0.716	0.739	0.713	0.717	0.716	0.742	0.715	0.680			0.716
124.5	0.642	0.730	0.719	0.695	0.730	0.729	0.719	0.681	0.642			0.719
133.0	0.779	0.851	0.858	0.809	0.845	0.854	0.812	0.845	0.779			0.845
145.5	0.540	0.574	0.574	0.550	0.571	0.549	0.583	0.555	0.540			0.563
158.5	0.546	0.580	0.574	0.613	0.564	0.610	0.618	0.578	0.546			0.579
166.0	0.751	0.710	0.753	0.757	0.760	0.740	0.756	0.720	0.710			0.752
177.7	1.083	1.178	1.178	1.107	1.171	1.110	1.152	1.266	1.083			1.161
192.5	0.591	0.613	0.630	0.660	0.680	0.631	0.655	0.645	0.591			0.638
202.5	0.457	0.506	0.479	0.470	0.460	0.518	0.474	0.491	0.457			0.477
214.0	0.446	0.460	0.490	0.441	0.450	0.473	0.489	0.478	0.441			0.467
227.3	0.559	0.560	0.478	0.553	0.535	0.548	0.533	0.573	0.478			0.550
238.3	0.439	0.459	0.428	0.411	0.458	0.435	0.449	0.431	0.411			0.437
250.0	0.360	0.351	0.379	0.357	0.360	0.376	0.386	0.382	0.351			0.368
269.0	0.387	0.427	0.451	0.429	0.410	0.410	0.486	0.413	0.387			0.420
283.9	0.331	0.330	0.362	0.350	0.336	0.341	0.386	0.330	0.330			0.338
299.1	0.881	0.919	0.891	0.880	0.869	0.909	0.914	0.916	0.869			0.900
322.0	0.294	0.285	0.282	0.309	0.309	0.309	0.317	0.320	0.282			0.309
339.0	0.351	0.339	0.374	0.318	0.361	0.283	0.329	0.328	0.283			0.334
358.0	0.420	0.442	0.443	0.432	0.468	0.413	0.434	0.385	0.385			0.433
367.0	0.391	0.374	0.370	0.417	0.370	0.416	0.370	0.436	0.370			0.383
377.5	0.561	0.527	0.530	0.561	0.514	0.550	0.560	0.510	0.510			0.540

REVISION _____

TABLE 7
 RSRM-26A AFT CENTER SEGMENT INSULATION PERFORMANCE
 COMPLIANCE SAFETY FACTOR (CSF)

STATION (IN)	0.0	46.0	90.0	136.0	180.0	226.0	270.0	316.0	MIN.	PLANE	REQUIRED S.F.
3.5	4.41	4.88	3.61	6.01	4.76	3.93	4.83	4.08	3.61	90.0	2.0
11.0	3.23	3.30	3.78	4.46	2.88	3.63	3.77	3.04	2.88	180.0	1.5
30.7	2.88	3.47	3.74	2.70	3.38	3.41	2.76	2.90	2.70	136.0	1.5
36.2	3.06	6.19	4.08	4.11	4.00	4.41	3.70	3.49	3.06	0.0	1.5
44.6	6.00	+	7.66	10.59	5.81	5.54	12.00	7.66	5.54	226.0	1.5
71.5	4.59	4.25	42.50	4.25	6.30	3.47	12.14	4.36	3.47	226.0	1.5
126.0	12.50	10.71	13.64	18.75	7.89	3.00	21.43	15.00	3.00	226.0	1.5
145.0	10.00	4.84	10.00	9.37	25.00	7.89	4.05	13.64	4.05	270.0	1.5
161.4	+	7.15	1.46	8.14	2.78	13.88	9.44	4.37	1.46	90.0	2.0
163.0	11.80	11.24	3.32	4.92	4.92	3.58	3.69	9.08	3.32	90.0	2.0
178.0	5.42	7.65	26.00	16.25	14.44	5.00	8.12	5.20	5.00	226.0	1.5
214.1	+	+	+	+	14.44	4.48	+	+	4.48	226.0	1.5
280.0	+	+	+	+	8.18	+	+	+	8.18	180.0	1.5
298.0	+	+	+	+	+	+	+	+	+	0.0	1.5
311.8	+	+	+	+	+	+	+	+	+	0.0	1.5

SEGMENT MINIMUM = 1.46 AT THE 161.4 INCH STATION

A " < " INDICATES THE PRECEDING SAFETY FACTOR HAS VIOLATED THE MINIMUM SAFETY FACTOR REQUIREMENT
 A " + " MEANS NEGLIGIBLE MDD HAS OCCURRED

ACTUAL SAFETY FACTOR (ASF)

STATION (IN)	0.0	46.0	90.0	136.0	180.0	226.0	270.0	316.0	MIN.	PLANE	REQUIRED S.F.
3.5	5.52	5.97	4.64	6.99	5.72	4.86	5.97	5.02	4.64	90.0	2.0
11.0	4.21	4.17	4.75	5.56	3.60	4.79	5.13	4.00	3.60	180.0	1.5
30.7	3.15	3.91	4.15	2.93	3.81	3.74	3.07	3.20	2.93	136.0	1.5
36.2	4.13	8.41	5.49	5.46	5.33	6.01	4.99	4.66	4.13	0.0	1.5
44.6	6.35	+	7.85	10.97	6.15	5.77	12.60	8.13	5.77	226.0	1.5
71.5	5.32	4.85	47.00	4.62	6.85	3.92	13.07	4.72	3.92	226.0	1.5
126.0	13.58	11.64	14.82	20.00	8.47	3.20	23.00	16.20	3.20	226.0	1.5
145.0	11.00	5.32	11.20	10.12	28.00	8.63	4.41	14.64	4.41	270.0	1.5
161.4	+	17.67	4.22	20.34	6.88	33.71	22.48	9.98	4.22	90.0	2.0
163.0	27.50	26.19	7.75	11.46	11.46	8.33	8.59	21.15	7.75	90.0	2.0
178.0	7.92	11.18	36.60	23.50	20.67	7.12	11.62	7.52	7.12	226.0	1.5
214.1	+	+	+	+	15.67	4.76	+	+	4.76	226.0	1.5
280.0	+	+	+	+	9.91	+	+	+	9.91	180.0	1.5
298.0	+	+	+	+	+	+	+	+	+	0.0	1.5
311.8	+	+	+	+	+	+	+	+	+	0.0	1.5

SEGMENT MINIMUM = 2.93 AT THE 30.7 INCH STATION

A " + " MEANS NEGLIGIBLE MDD HAS OCCURRED

TABLE 7
RSRM-26A AFT CENTER SEGMENT INSULATION PERFORMANCE

STATION (IN)	MATERIAL DECOMPOSITION RATE (MDR)										DESIGN M+3S
	0.0	46.0	90.0	136.0	180.0	226.0	270.0	316.0	MEDIAN	MAX.	
3.5	0.481	0.434	0.588	0.353	0.445	0.540	0.439	0.519	0.463	0.588	1.067
11.0	0.589	0.575	0.502	0.426	0.660	0.524	0.504	0.626	0.549	0.660	0.829
30.7	0.269	0.223	0.207	0.287	0.229	0.227	0.280	0.267	0.248	0.287	0.484
36.2	0.196	0.097	0.147	0.146	0.150	0.136	0.162	0.172	0.148	0.196	0.318
44.6	0.060	0	0.047	0.034	0.062	0.065	0.030	0.047	0.047	0.065	0.090
71.5	0.037	0.040	0.004	0.040	0.027	0.049	0.014	0.039	0.038	0.049	0.086
126.0	0.012	0.014	0.011	0.008	0.019	0.050	0.007	0.010	0.012	0.050	0.074
145.0	0.015	0.031	0.015	0.016	0.006	0.019	0.037	0.011	0.016	0.037	0.063
161.4	0	0.033	0.162	0.029	0.085	0.017	0.025	0.054	0.031	0.162	0.082
163.0	0.020	0.021	0.071	0.048	0.048	0.066	0.064	0.026	0.048	0.071	0.082
178.0	0.024	0.017	0.005	0.008	0.009	0.026	0.016	0.025	0.017	0.026	0.065
214.1	0	0	0	0	0.009	0.029	0	0	0	0.029	0.029
280.0	0	0	0	0	0.011	0	0	0	0	0.011	0.005
298.0	0	0	0	0	0	0	0	0	0	0	0.005
311.8	0	0	0	0	0	0	0	0	0	0	0.003

A * < * INDICATES THE PRECEDING MDR HAS EXCEEDED THE M + 3 SIGMA DESIGN CRITERIA

STATION (IN)	MATERIAL DECOMPOSITION RATE (MDR)										EXPOSURE TIME
	0.0	46.0	90.0	136.0	180.0	226.0	270.0	316.0	AVE.	TIME	
3.5	4.4	4.0	5.4	3.2	4.1	4.9	4.0	4.7	4.3	109.5	
11.0	6.2	6.0	5.3	4.5	6.9	5.5	5.3	6.6	5.8	95.2	
30.7	5.8	4.8	4.5	6.2	4.9	4.9	6.0	5.7	5.3	46.5	
36.2	6.1	3.0	4.6	4.6	4.7	4.3	5.1	5.4	4.7	31.9	
44.6	5.1	0	4.0	2.9	5.3	5.6	2.6	4.0	3.7	11.7	
71.5	3.7	4.0	0.4	4.0	2.7	4.9	1.4	3.9	3.1	10.0	
126.0	1.4	1.6	1.3	0.9	2.2	5.8	0.8	1.2	1.9	8.6	
145.0	2.1	4.3	2.1	2.2	0.8	2.6	5.1	1.5	2.6	7.2	
161.4	0	3.4	16.5	3.0	8.7	1.7	2.6	5.5	5.2	9.8	
163.0	2.0	2.1	7.2	4.9	4.9	6.7	6.5	2.7	4.6	9.8	
178.0	4.1	2.9	0.8	1.4	1.5	4.4	2.7	4.2	2.8	5.9	
214.1	0	0	0	0	1.5	4.9	0	0	0.8	5.9	
280.0	0	0	0	0	3.3	0	0	0	0.4	3.3	
298.0	0	0	0	0	0	0	0	0	0	2.7	
311.8	0	0	0	0	0	0	0	0	0	2.0	

MOTOR ACTION TIME = 120.4 SECONDS

TABLE 7
RSRM-26A AFT CENTER SEGMENT INSULATION PERFORMANCE

PART NO. 1U76667-02 PREFIRE MEASUREMENTS
SERIAL NO. 0000051 INCHES

STATION (IN)	0.0	46.0	90.0	136.0	180.0	226.0	270.0	316.0	MIN.	MEDIAN	MDT
3.5	2.656	2.589	2.726	2.467	2.547	2.626	2.619	2.605	2.467	2.612	2.120
11.0	2.479	2.399	2.386	2.368	2.373	2.510	2.585	2.507	2.368	2.439	1.900
30.7	0.848	0.871	0.860	0.841	0.872	0.848	0.861	0.854	0.841	0.857	0.774
36.2	0.809	0.816	0.807	0.797	0.800	0.817	0.808	0.802	0.797	0.808	0.600
44.6	0.381	0.373	0.369	0.373	0.381	0.375	0.378	0.382	0.369	0.377	0.360
71.5	0.197	0.194	0.188	0.185	0.185	0.192	0.183	0.184	0.183	0.186	0.170
126.0	0.163	0.163	0.163	0.160	0.161	0.160	0.161	0.162	0.160	0.162	0.150
145.0	0.165	0.165	0.168	0.162	0.168	0.164	0.163	0.161	0.161	0.165	0.150
161.4	0.539	0.583	0.683	0.590	0.585	0.573	0.562	0.539	0.539	0.578	0.236
163.0	0.550	0.550	0.550	0.550	0.550	0.550	0.550	0.550	0.550	0.550	0.236
178.0	0.190	0.190	0.183	0.188	0.186	0.185	0.186	0.188	0.183	0.187	0.130
214.1	0.138	0.142	0.140	0.139	0.141	0.138	0.139	0.136	0.136	0.139	0.130
280.0	0.108	0.118	0.105	0.111	0.109	0.106	0.107	0.105	0.105	0.108	0.090
298.0	0.109	0.119	0.105	0.109	0.107	0.110	0.107	0.109	0.105	0.109	0.090
311.8	0.109	0.113	0.110	0.109	0.109	0.110	0.107	0.109	0.107	0.109	0.090

PART NO. 1U76791-01 POSTFIRE MEASUREMENTS
SERIAL NO. 0000022 INCHES

STATION (IN)	0.0	46.0	90.0	136.0	180.0	226.0	270.0	316.0	MIN.	MEDIAN
3.5	2.175	2.155	2.138	2.114	2.102	2.086	2.180	2.086	2.086	2.126
11.0	1.890	1.824	1.884	1.942	1.713	1.986	2.081	1.881	1.713	1.887
30.7	0.579	0.648	0.653	0.554	0.643	0.621	0.581	0.587	0.554	0.604
36.2	0.613	0.719	0.660	0.651	0.650	0.681	0.646	0.630	0.613	0.650
44.6	0.321	0.381	0.322	0.339	0.319	0.310	0.348	0.335	0.310	0.329
71.5	0.160	0.154	0.184	0.145	0.158	0.143	0.169	0.145	0.143	0.156
126.0	0.151	0.149	0.152	0.152	0.142	0.110	0.154	0.152	0.110	0.152
145.0	0.150	0.134	0.153	0.146	0.162	0.145	0.126	0.150	0.126	0.148
161.4	0.558	0.550	0.521	0.561	0.500	0.556	0.537	0.485	0.485	0.544
163.0	0.530	0.529	0.479	0.502	0.502	0.484	0.486	0.524	0.479	0.502
178.0	0.166	0.173	0.178	0.180	0.177	0.159	0.170	0.163	0.159	0.171
214.1	L	L	L	L	0.132	0.109	L	L	0.109	0.139
280.0	L	L	L	L	0.098	L	L	L	0.098	0.106
298.0	L	L	L	L	L	L	L	L	L	0.109
311.8	L	L	L	L	L	L	L	L	L	0.109

AN " L " INDICATES THAT LINER MATERIAL WAS REMAINING AT THAT LOCATION.
THE MEDIAN AND MINIMUM VALUES WERE CALCULATED USING THE PREFIRE THICKNESSES
AT THE LOCATIONS WHERE LINER MATERIAL WAS REMAINING

TABLE 8
RSRM-26A FORWARD CENTER SEGMENT INSULATION PERFORMANCE

COMPLIANCE SAFETY FACTOR (CSF)

STATION (IN)	DEGREE LOCATIONS								MIN.	PLANE	REQUIRED S.F.
	0.0	46.0	90.0	136.0	180.0	226.0	270.0	316.0			
3.5	22.80	39.26	12.62	15.25	16.56	35.33	34.19	19.81	12.62	90.0	2.0
11.0	18.45	63.33	39.58	+	+	82.61	+	+	18.45	0.0	1.5
30.7	5.09	8.90	8.06	7.17	5.53	7.74	4.93	6.00	4.93	270.0	1.5
36.2	4.69	8.11	+	5.71	6.90	9.52	5.26	8.45	4.69	0.0	1.5
44.6	+	90.00	+	72.00	+	60.00	20.00	+	20.00	270.0	1.5
71.5	+	+	21.25	85.00	14.17	34.00	34.00	3.62	3.62	316.0	1.5
126.0	7.50	4.29	+	+	+	7.89	37.50	+	4.29	46.0	1.5
145.0	+	+	+	+	+	6.82	+	+	6.82	270.0	1.5
161.4	3.52	+	9.08	3.11	14.75	3.11	4.14	2.74	2.74	316.0	2.0
163.0	2.95	6.74	3.15	4.00	3.58	3.81	19.67	3.06	2.95	0.0	2.0
178.0	3.10	+	+	+	+	+	+	+	3.10	0.0	1.5
214.1	+	+	+	+	+	+	+	+	+	0.0	1.5
280.0	+	+	+	+	+	+	+	+	+	0.0	1.5
298.0	+	+	+	+	+	+	+	+	+	0.0	1.5
311.8	+	+	+	+	+	+	+	+	+	0.0	1.5

SEGMENT MINIMUM = 2.74 AT THE 161.4 INCH STATION

A " + " MEANS NEGLIGIBLE MDD HAS OCCURRED

ACTUAL SAFETY FACTOR (ASF)

STATION (IN)	DEGREE LOCATIONS								MIN.	PLANE	REQUIRED S.F.
	0.0	46.0	90.0	136.0	180.0	226.0	270.0	316.0			
3.5	27.30	46.93	15.08	18.04	19.52	42.00	40.82	24.08	15.08	90.0	2.0
11.0	24.18	80.00	48.46	+	+	+	+	+	24.18	0.0	1.5
30.7	5.61	9.74	8.96	7.93	6.36	8.56	5.61	6.81	5.61	270.0	1.5
36.2	6.66	10.85	+	8.13	9.18	12.84	7.31	11.49	6.66	0.0	1.5
44.6	+	92.00	+	72.60	+	61.33	20.56	+	20.56	270.0	1.5
71.5	+	+	23.25	91.00	15.50	36.20	36.60	3.89	3.89	316.0	1.5
126.0	7.70	4.49	+	+	+	8.05	38.25	+	4.49	46.0	1.5
145.0	+	+	+	+	+	+	7.41	+	7.41	270.0	1.5
161.4	8.61	+	20.46	7.14	36.94	7.88	10.30	6.86	6.86	316.0	2.0
163.0	6.87	15.71	7.33	9.32	8.33	8.87	45.83	7.14	6.87	0.0	2.0
178.0	4.38	+	+	+	+	+	+	+	4.38	0.0	1.5
214.1	+	+	+	+	+	+	+	+	+	0.0	1.5
280.0	+	+	+	+	+	+	+	+	+	0.0	1.5
298.0	+	+	+	+	+	+	+	+	+	0.0	1.5
311.8	+	+	+	+	+	+	+	+	+	0.0	1.5

SEGMENT MINIMUM = 3.89 AT THE 71.5 INCH STATION

A " + " MEANS NEGLIGIBLE MDD HAS OCCURRED

TABLE 8
RSRM-26A FORWARD CENTER SEGMENT INSULATION PERFORMANCE

MATERIAL DECOMPOSITION DEPTH (MDD)
INCHES

STATION (IN)	DEGREE LOCATIONS										MEDIAN	MAX.	DESIGN M+3S
	0.0	46.0	90.0	136.0	180.0	226.0	270.0	316.0					
3.5	0.093	0.054	0.168	0.139	0.128	0.060	0.062	0.107	0.100	0.168	1.067		
11.0	0.103	0.030	0.048	0	0	0.023	0	0.010	0.010	0.103	0.829		
30.7	0.152	0.087	0.096	0.108	0.140	0.100	0.157	0.129	0.118	0.157	0.484		
36.2	0.128	0.074	0	0.105	0.087	0.063	0.114	0.071	0.081	0.128	0.318		
44.6	0	0.004	0	0.005	0	0.006	0.018	0	0.002	0.018	0.090		
71.5	0	0.001	0.008	0.002	0.012	0.005	0.005	0.047	0.005	0.047	0.086		
126.0	0.020	0.035	0	0	0	0.019	0.004	0	0.002	0.035	0.074		
145.0	0	0	0	0	0	0.022	0	0	0	0.022	0.063		
161.4	0.067	0.002	0.026	0.076	0.016	0.076	0.057	0.086	0.062	0.086	0.082		
163.0	0.080	0.035	0.075	0.059	0.066	0.062	0.012	0.077	0.064	0.080	0.082		
178.0	0.042	0	0	0	0	0	0	0	0	0.042	0.065		
214.1	0	0	0	0	0	0	0	0	0	0	0.029		
280.0	0	0	0	0	0	0	0	0	0	0	0.005		
298.0	0	0	0	0	0	0	0	0	0	0	0.005		
311.8	0	0	0	0	0	0	0	0	0	0	0.003		

A * < " INDICATES THE PRECEDING MDD HAS EXCEEDED THE M + 3 SIGMA DESIGN CRITERIA

MATERIAL DECOMPOSITION RATE (MDR)
MILS / SECOND

STATION (IN)	DEGREE LOCATIONS										AVE.	EXPOSURE TIME
	0.0	46.0	90.0	136.0	180.0	226.0	270.0	316.0				
3.5	0.8	0.5	1.5	1.3	1.2	0.5	0.6	1.0	0.9	109.5		
11.0	1.1	0.3	0.5	0	0	0	0.2	0	0.3	95.4		
30.7	3.2	1.9	2.0	2.3	3.0	2.1	3.3	2.8	2.6	46.9		
36.2	4.0	2.3	0	3.2	2.7	1.9	3.5	2.2	2.5	32.4		
44.6	0	10.0	0	12.5	0	15.0	45.0	0	10.3	0.4		
71.5	0	0.1	0.7	0.2	1.1	0.5	0.5	4.4	0.9	10.8		
126.0	2.1	3.7	0	0	0	2.0	0.4	0	1.0	9.4		
145.0	0	0	0	0	0	0	2.8	0	0.4	7.8		
161.4	6.3	0.2	2.5	7.2	1.5	7.2	5.4	8.1	4.8	10.6		
163.0	7.5	3.3	7.1	5.6	6.2	5.8	1.1	7.3	5.5	10.6		
178.0	6.0	0	0	0	0	0	0	0	0.7	7.0		
214.1	0	0	0	0	0	0	0	0	0	7.0		
280.0	0	0	0	0	0	0	0	0	0	4.1		
298.0	0	0	0	0	0	0	0	0	0	3.9		
311.8	0	0	0	0	0	0	0	0	0	3.3		

MOTOR ACTION TIME = 120.4 SECONDS

TABLE 8
RSM-26A FORWARD CENTER SEGMENT INSULATION PERFORMANCE

PART NO. 1U76667-02
SERIAL NO. 0000052

PREFIRE MEASUREMENTS
INCHES

STATION (IN)	DEGREE LOCATIONS										MIN.	MEDIAN	MDT
	0.0	46.0	90.0	136.0	180.0	226.0	270.0	316.0					
3.5	2.539	2.534	2.534	2.507	2.498	2.520	2.531	2.577	2.498	2.533	2.120		
11.0	2.491	2.400	2.326	2.131	2.344	2.299	2.385	2.351	2.131	2.348	1.900		
30.7	0.852	0.847	0.860	0.856	0.891	0.856	0.880	0.879	0.847	0.858	0.774		
36.2	0.853	0.803	0.790	0.854	0.799	0.809	0.833	0.816	0.790	0.813	0.600		
44.6	0.373	0.368	0.367	0.363	0.371	0.368	0.370	0.368	0.363	0.368	0.360		
71.5	0.185	0.188	0.186	0.182	0.186	0.181	0.183	0.183	0.181	0.184	0.170		
126.0	0.154	0.157	0.153	0.153	0.154	0.153	0.153	0.158	0.153	0.154	0.150		
145.0	0.161	0.160	0.158	0.163	0.159	0.158	0.163	0.160	0.158	0.160	0.150		
161.4	0.577	0.531	0.532	0.543	0.591	0.599	0.587	0.590	0.531	0.582	0.236		
163.0	0.550	0.550	0.550	0.550	0.550	0.550	0.550	0.550	0.550	0.550	0.236		
178.0	0.184	0.187	0.185	0.192	0.187	0.188	0.187	0.187	0.184	0.187	0.130		
214.1	0.133	0.129	0.130	0.139	0.114	0.130	0.129	0.130	0.114	0.130	0.130		
280.0	0.107	0.093	0.103	0.100	0.105	0.104	0.105	0.110	0.093	0.105	0.090		
298.0	0.105	0.103	0.099	0.097	0.104	0.105	0.103	0.104	0.097	0.104	0.090		
311.8	0.104	0.095	0.105	0.100	0.104	0.104	0.104	0.111	0.095	0.104	0.090		

PART NO. 1U76791-01
SERIAL NO. 0000023

POSTFIRE MEASUREMENTS
INCHES

STATION (IN)	DEGREE LOCATIONS										MIN.	MEDIAN
	0.0	46.0	90.0	136.0	180.0	226.0	270.0	316.0				
3.5	2.446	2.480	2.366	2.368	2.370	2.460	2.469	2.470	2.366	2.453	2.453	
11.0	2.388	2.370	2.278	2.470	2.356	2.443	2.362	2.354	2.278	2.366	2.366	
30.7	0.700	0.760	0.764	0.748	0.751	0.756	0.723	0.750	0.700	0.751	0.751	
36.2	0.725	0.729	0.817	0.749	0.712	0.746	0.719	0.745	0.712	0.737	0.737	
44.6	0.373	0.364	0.378	0.358	0.371	0.362	0.352	0.372	0.352	0.368	0.368	
71.5	0.200	0.187	0.178	0.180	0.174	0.176	0.178	0.136	0.136	0.178	0.178	
126.0	0.134	0.122	L	L	L	0.134	0.149	L	0.122	0.151	0.151	
145.0	0.170	0.173	L	L	L	L	0.141	L	0.141	0.160	0.160	
161.4	0.510	0.529	0.506	0.467	0.575	0.523	0.530	0.504	0.467	0.516	0.516	
163.0	0.470	0.515	0.475	0.491	0.484	0.488	0.538	0.473	0.470	0.486	0.486	
178.0	0.142	L	L	L	0.242	L	L	L	0.142	0.187	0.187	
214.1	L	L	L	L	L	L	L	L	L	0.130	0.130	
280.0	L	L	L	L	L	L	L	L	L	0.105	0.105	
298.0	L	L	L	L	L	L	L	L	L	0.104	0.104	
311.8	L	L	L	L	L	L	L	L	L	0.104	0.104	

AN "L" INDICATES THAT LINER MATERIAL WAS REMAINING AT THAT LOCATION.
THE MEDIAN AND MINIMUM VALUES WERE CALCULATED USING THE PREFIRE THICKNESSES
AT THE LOCATIONS WHERE LINER MATERIAL WAS REMAINING

TABLE 9
RSRM-26A FORWARD SEGMENT STAR TIP INSULATION PERFORMANCE

COMPLIANCE SAFETY FACTOR (CSF)			ACTUAL SAFETY FACTOR (ASF)		
STATION (IN)	DEGREE LOCATIONS	MIN.	STATION (IN)	DEGREE LOCATIONS	MIN.
90.0	154.0 222.0 286.0 352.0		90.0	154.0 222.0 286.0 352.0	
3.5	8.95 42.40 +	23.82	3.5	11.50 49.68 +	11.50
13.0	+ 40.62 19.12 25.00 21.67	19.12	13.0	+ 53.75 28.35 33.35 29.53	28.35
27.0	+ + + +		27.0	+ + + +	
44.0	+ + + +		44.0	+ + + +	
60.0	+ + + +		60.0	+ + + +	
94.7	+ + + +		94.7	+ + + +	
142.0	+ + + +		142.0	+ + + +	
152.0	+ 3.87 7.55 7.04 4.17	3.87	152.0	+ 4.74 10.36 8.33 5.16	4.74
162.0	+ 4.48 5.16 3.99 6.75	3.99	162.0	+ 5.87 6.89 5.35 8.96	5.35
175.5	3.47 4.00 3.97 3.23 4.54	3.23	175.5	4.04 4.53 4.51 3.80 5.08	3.80
187.0	2.66 3.17 3.02 2.53 3.28	2.53	187.0	2.65 3.14 3.04 2.53 3.22	2.53
199.0	3.10 2.36 3.01 3.15 2.87	2.36	199.0	3.27 2.60 3.13 3.32 2.96	2.60
213.0	3.08 3.42 3.21 3.54 3.39	3.08	213.0	3.31 3.65 3.42 3.77 3.57	3.31
224.0	2.96 2.81 2.96 2.84 2.97	2.81	224.0	3.37 3.20 3.38 3.17 3.38	3.17
230.0	3.33 2.94 3.54 3.32 3.15	2.94	230.0	3.53 3.09 3.79 3.48 3.33	3.09
236.0	2.95 2.79 4.52 3.78 3.18	2.79	236.0	3.29 3.04 4.93 4.06 3.51	3.04
240.0	2.52 2.55 2.59 2.97 2.68	2.52	240.0	2.84 2.84 2.84 3.30 2.99	2.84
254.0	2.83 2.94 2.81 2.81 3.36	2.81	254.0	2.88 2.96 2.84 2.79 3.37	2.79
263.0	2.84 3.07 2.51 2.38 2.94	2.38	263.0	2.91 3.10 2.58 2.43 2.98	2.43
282.0	2.94 3.26 3.14 3.38 2.97	2.94	282.0	3.22 3.59 3.50 3.72 3.27	3.22
293.0	2.79 2.74 3.33 2.81 3.55	2.74	293.0	3.09 3.08 3.74 3.15 3.92	3.08
305.0	3.55 2.50 2.79 4.30 3.09	2.50	305.0	4.15 2.97 3.31 5.01 3.76	3.76
312.0	2.96 3.22 3.18 2.80 2.85	2.80	312.0	3.56 3.87 3.76 3.33 3.61	3.33
321.0	4.14 5.63 5.28 6.12 6.51	4.14	321.0	4.55 5.79 5.51 6.39 6.97	6.97
339.0	3.10 2.96 2.70 2.99 3.17	2.70	339.0	3.20 3.05 2.78 3.18 3.29	2.78
350.0	4.12 3.49 3.93 2.59 3.66	2.59	350.0	4.70 3.89 4.39 2.95 4.10	2.95
362.0	2.71 2.81 3.33 2.20 3.88	2.20	362.0	3.12 3.19 3.74 2.51 4.40	2.51
371.0	3.13 2.63 3.42 2.81 2.99	2.63	371.0	4.00 3.12 3.91 3.17 3.41	3.12
383.0	3.15 2.99 3.43 3.68 3.08	2.99	383.0	3.83 3.41 4.09 4.13 3.63	3.41
397.0	3.01 3.14 4.16 2.73 2.99	2.73	397.0	3.58 3.76 5.02 3.22 3.63	3.22
403.0	4.61 3.83 3.75 5.49 4.63	3.75	403.0	5.08 4.26 4.10 6.08 5.26	4.10

SEGMENT MINIMUM = 2.20 AT THE 362.0 INCH STATION
A * + * MEANS NEGLIGIBLE MDD HAS OCCURRED

SEGMENT MINIMUM = 2.43 AT THE 263.0 INCH STATION

REVISION _____

DOC NO. TWR-64204
SEC

PAGE: E-21

TABLE 9

RSRM-26A FORWARD SEGMENT STAR TIP INSULATION PERFORMANCE

PART NO. IU76790-05
SERIAL NO. 0000010

POSTFIRE MEASUREMENTS
INCHES

PART NO. IU76666-02
SERIAL NO. 0000027

PREFIRE MEASUREMENTS
INCHES

STATION (IN)	DEGREE LOCATIONS			MDT	DEGREE LOCATIONS			MIN.	MEDIAN	MIN.	MEDIAN
	90.0	154.0	222.0		286.0	352.0	90.0				
3.5	2.726	2.484	2.468	2.531	2.520	2.520	2.120	2.468	2.520	2.431	2.468
13.0	0.863	0.860	0.964	0.867	0.866	0.867	0.650	0.860	0.867	0.841	0.856
27.0	0.563	0.563	0.561	0.579	0.582	0.563	0.450	0.561	0.563	L	0.563
44.0	0.298	0.291	0.292	0.293	0.292	0.292	0.250	0.291	0.292	L	0.292
60.0	0.140	0.138	0.139	0.141	0.138	0.139	0.100	0.138	0.139	L	0.139
94.7	0.113	0.111	0.110	0.112	0.092	0.111	0.090	0.092	0.111	L	0.111
142.0	0.163	0.163	0.162	0.160	0.164	0.163	0.113	0.160	0.163	L	0.163
152.0	0.351	0.389	0.435	0.375	0.392	0.389	0.317	0.351	0.389	L	0.389
162.0	0.728	0.716	0.730	0.726	0.716	0.728	0.547	0.716	0.728	L	0.728
175.5	0.703	0.684	0.686	0.710	0.675	0.686	0.604	0.675	0.686	L	0.686
187.0	0.638	0.635	0.644	0.628	0.628	0.638	0.640	0.628	0.638	L	0.638
199.0	0.719	0.754	0.710	0.720	0.704	0.719	0.677	0.713	0.719	L	0.719
213.0	0.729	0.722	0.721	0.721	0.713	0.721	0.677	0.713	0.721	L	0.721
224.0	0.771	0.772	0.773	0.755	0.771	0.771	0.677	0.755	0.771	L	0.771
230.0	0.716	0.710	0.723	0.710	0.715	0.716	0.677	0.710	0.715	L	0.715
236.0	0.645	0.630	0.631	0.621	0.638	0.631	0.574	0.621	0.631	L	0.631
240.0	0.647	0.640	0.631	0.637	0.639	0.639	0.574	0.631	0.639	L	0.639
254.0	0.579	0.571	0.573	0.564	0.569	0.571	0.568	0.564	0.571	L	0.568
263.0	0.583	0.573	0.583	0.580	0.576	0.580	0.568	0.573	0.580	L	0.568
282.0	0.622	0.625	0.634	0.625	0.625	0.622	0.546	0.622	0.625	L	0.546
293.0	0.605	0.613	0.613	0.612	0.603	0.603	0.525	0.603	0.603	L	0.525
305.0	0.614	0.624	0.623	0.611	0.640	0.611	0.541	0.611	0.623	L	0.541
312.0	0.652	0.651	0.640	0.643	0.686	0.640	0.541	0.640	0.651	L	0.541
321.0	1.011	0.944	0.958	0.958	0.983	0.944	0.918	0.944	0.958	L	0.918
339.0	0.570	0.568	0.567	0.586	0.573	0.567	0.523	0.567	0.570	L	0.523
350.0	0.597	0.583	0.584	0.596	0.589	0.583	0.520	0.583	0.591	L	0.520
362.0	0.599	0.591	0.583	0.592	0.589	0.583	0.520	0.583	0.591	L	0.520
371.0	0.664	0.617	0.595	0.587	0.593	0.587	0.511	0.587	0.595	L	0.511
383.0	0.620	0.583	0.609	0.574	0.603	0.574	0.503	0.574	0.603	L	0.503
397.0	0.598	0.601	0.607	0.593	0.610	0.601	0.503	0.593	0.601	L	0.503
403.0	1.047	1.057	1.038	1.052	1.078	1.038	0.950	1.038	1.052	L	0.950

AN " L " INDICATES THAT LINER MATERIAL WAS REMAINING AT THAT LOCATION.
THE MEDIAN AND MINIMUM VALUES WERE CALCULATED USING THE PREFIRE THICKNESSES
AT THE LOCATIONS WHERE LINER MATERIAL WAS REMAINING

TABLE 9

RSRM-26A FORWARD SEGMENT STAR TIP INSULATION PERFORMANCE

MATERIAL DECOMPOSITION DEPTH (MDD) INCHES

MATERIAL DECOMPOSITION RATE (MDR) MILS / SECOND

STATION (IN)	90.0	154.0	222.0	286.0	352.0	DEGREE LOCATIONS	MEDIAN	MAX.	DESIGN M+3S	STATION (IN)	90.0	154.0	222.0	286.0	352.0	DEGREE LOCATIONS	AVE.	EXPOSURE TIME
3.5	0.237	0.050	0	0	0.089	0.045	0.050	0.237	0.103	3.5	7.1	1.5	0	0	2.6	0	2.2	33.6
13.0	0	0.016	0.034	0.026	0.030	0.026	0.026	0.034	0.101	13.0	0	0.8	1.8	1.4	1.6	0	1.1	19.0
27.0	0	0	0	0	0	0	0	0	0.044	27.0	0	0	0	0	0	0	0	4.7
44.0	0	0	0	0	0	0	0	0	0.015	44.0	0	0	0	0	0	0	0	2.9
60.0	0	0	0	0	0	0	0	0	0.012	60.0	0	0	0	0	0	0	0	1.4
94.7	0	0	0	0	0	0	0	0	0.004	94.7	0	0	0	0	0	0	0	0.8
142.0	0	0.082	0.042	0.045	0.076	0.045	0.045	0.082	0.019	142.0	0	0	0	0	0	0	0	1.0
162.0	0	0.122	0.106	0.137	0.081	0.106	0.106	0.137	0.123	162.0	0	2.6	1.3	1.4	2.4	1.4	1.5	31.9
175.5	0.174	0.151	0.152	0.187	0.133	0.152	0.152	0.187	0.227	175.5	2.0	1.7	1.7	2.1	1.5	1.4	1.6	56.7
187.0	0.241	0.202	0.212	0.253	0.195	0.212	0.212	0.253	0.324	187.0	2.4	2.0	2.1	2.5	2.0	1.8	1.8	87.2
199.0	0.220	0.290	0.227	0.217	0.238	0.227	0.227	0.290	0.398	199.0	2.2	2.9	2.3	2.2	2.4	2.4	2.2	99.7
213.0	0.220	0.198	0.211	0.191	0.200	0.200	0.200	0.290	0.427	213.0	2.2	2.0	2.1	1.9	2.0	2.0	2.0	99.7
224.0	0.229	0.241	0.229	0.238	0.228	0.229	0.229	0.241	0.423	224.0	2.3	2.4	2.3	2.4	2.3	2.3	2.3	99.7
230.0	0.203	0.230	0.191	0.204	0.215	0.204	0.204	0.230	0.204	230.0	2.0	2.3	1.9	2.0	2.2	2.1	2.1	99.7
236.0	0.196	0.207	0.128	0.153	0.182	0.182	0.182	0.207	0.327	236.0	2.0	2.1	1.3	1.5	1.8	1.7	1.7	99.7
240.0	0.201	0.193	0.202	0.202	0.169	0.201	0.201	0.228	0.342	240.0	2.3	2.3	2.2	1.9	2.1	2.2	2.2	99.7
254.0	0.200	0.185	0.226	0.239	0.193	0.200	0.200	0.239	0.318	254.0	2.0	1.9	2.0	2.0	1.7	1.9	1.9	99.7
263.0	0.193	0.174	0.181	0.168	0.191	0.181	0.181	0.239	0.334	263.0	2.0	1.9	2.3	2.4	1.9	2.1	2.1	99.7
282.0	0.196	0.199	0.164	0.174	0.154	0.174	0.174	0.199	0.349	282.0	1.9	1.7	1.8	1.7	1.9	1.8	1.8	99.7
293.0	0.148	0.210	0.188	0.122	0.170	0.170	0.170	0.199	0.330	293.0	2.0	2.0	1.6	1.9	1.5	1.8	1.8	99.7
305.0	0.183	0.168	0.170	0.193	0.190	0.183	0.183	0.210	0.309	305.0	1.5	2.1	1.9	1.2	1.7	1.5	1.8	99.7
312.0	0.222	0.163	0.174	0.150	0.141	0.163	0.163	0.193	0.308	312.0	1.8	1.7	1.7	1.9	1.9	1.8	1.8	99.7
321.0	0.178	0.186	0.204	0.184	0.174	0.184	0.184	0.222	0.434	321.0	2.2	1.6	1.7	1.5	1.4	1.7	1.7	101.8
339.0	0.127	0.150	0.133	0.202	0.143	0.143	0.143	0.204	0.319	339.0	1.8	1.9	2.1	1.9	1.8	1.9	1.9	98.3
350.0	0.192	0.185	0.156	0.236	0.134	0.143	0.143	0.202	0.300	350.0	1.3	1.5	1.4	2.1	1.5	1.5	1.5	98.1
362.0	0.166	0.198	0.152	0.185	0.174	0.174	0.174	0.236	0.285	362.0	2.0	1.9	1.6	2.4	1.4	1.4	1.9	97.1
371.0	0.162	0.171	0.149	0.139	0.166	0.162	0.162	0.171	0.304	371.0	1.8	2.1	1.6	2.0	1.9	1.9	1.9	92.8
397.0	0.167	0.160	0.121	0.184	0.168	0.167	0.167	0.184	0.295	397.0	1.7	1.8	1.6	1.5	1.8	1.7	1.7	94.0
403.0	0.206	0.248	0.253	0.173	0.205	0.206	0.206	0.253	0.287	403.0	1.7	2.1	1.6	1.2	1.9	1.7	1.6	98.1
									0.287		1.7	2.1	2.1	1.4	1.7	1.7	1.8	120.4

MOTOR ACTION TIME = 120.4 SECONDS

A " < " INDICATES THE PRECEDING MDD HAS EXCEEDED THE M + 3 SIGMA DESIGN CRITERIA

REVISION _____

TABLE 10
RSRM-26A FORWARD SEGMENT NON-STAR TIP INSULATION PERFORMANCE

MATERIAL DECOMPOSITION DEPTH (MDD) INCHES		MATERIAL DECOMPOSITION RATE (MDR) MILS / SECOND		MATERIAL DECOMPOSITION RATE (MDR) MILS / SECOND		STATION (IN)	DESIGN M+3S	MAX.	MEDIAN	DEGREE LOCATIONS 74.0 140.0 206.0 270.0 336.0	DEGREE LOCATIONS 74.0 140.0 206.0 270.0 336.0	AVE.	EXPOSURE TIME
STATION (IN)	74.0 140.0 206.0 270.0 336.0	74.0 140.0 206.0 270.0 336.0	74.0 140.0 206.0 270.0 336.0	74.0 140.0 206.0 270.0 336.0	74.0 140.0 206.0 270.0 336.0								
3.5	0.034	0.029	0.053	0.117	0.067	3.5	0.103	0.117	0.053	0.029	0.053	0.117	33.6
13.0	0.024	0.016	0	0.017	0.024	13.0	0.101	0.024	0.017	0.016	0	0.017	19.0
27.0	0	0	0	0	0	27.0	0.044	0	0	0	0	0	4.7
44.0	0	0	0	0	0	44.0	0.015	0	0	0	0	0	2.9
60.0	0	0	0	0	0	60.0	0.012	0	0	0	0	0	1.4
94.7	0	0	0	0	0	94.7	0.004	0	0	0	0	0	0.8
142.0	0	0	0	0	0	142.0	0.019	0	0	0	0	0	1.0
152.0	0	0.011	0.051	0	0.014	152.0	0.123	0.051	0.011	0.011	0.051	0	20.3
162.0	0.066	0.087	0.063	0.088	0.072	162.0	0.227	0.088	0.072	0.066	0.087	0.063	43.4
175.5	0.110	0.114	0.126	0.128	0.150	175.5	0.324	0.150	0.126	0.110	0.114	0.126	66.8
187.0	0.146	0.126	0.138	0.140	0.126	187.0	0.398	0.146	0.138	0.146	0.126	0.138	65.1
199.0	0.158	0.154	0.160	0.138	0.121	199.0	0.427	0.160	0.138	0.158	0.154	0.160	65.1
213.0	0.118	0.150	0.137	0.137	0.111	213.0	0.423	0.150	0.137	0.118	0.150	0.137	65.1
224.0	0.113	0.136	0.121	0.140	0.139	224.0	0.422	0.140	0.136	0.113	0.136	0.121	65.1
230.0	0.115	0.119	0.111	0.121	0.123	230.0	0.375	0.123	0.119	0.115	0.119	0.111	65.1
236.0	0.139	0.123	0.094	0.122	0.122	236.0	0.327	0.139	0.122	0.139	0.123	0.094	65.1
240.0	0.108	0.122	0.128	0.119	0.117	240.0	0.342	0.128	0.119	0.108	0.122	0.128	65.1
254.0	0.101	0.099	0.097	0.128	0.107	254.0	0.318	0.128	0.101	0.101	0.099	0.097	65.1
263.0	0.110	0.106	0.118	0.125	0.096	263.0	0.334	0.125	0.110	0.110	0.106	0.118	65.1
282.0	0.062	0.102	0.107	0.118	0.123	282.0	0.349	0.123	0.107	0.062	0.102	0.107	65.1
305.0	0.083	0.109	0.104	0.117	0.108	305.0	0.309	0.150	0.109	0.083	0.109	0.104	65.1
312.0	0.125	0.093	0.086	0.112	0.100	312.0	0.308	0.125	0.100	0.125	0.093	0.086	65.1
321.0	0.104	0.150	0.101	0.097	0.046	321.0	0.434	0.150	0.101	0.104	0.150	0.101	69.4
339.0	0.111	0.135	0.099	0.100	0.129	339.0	0.319	0.135	0.111	0.111	0.135	0.099	71.3
350.0	0.115	0.127	0.153	0.143	0.129	350.0	0.300	0.153	0.127	0.115	0.127	0.153	75.1
362.0	0.174	0.145	0.154	0.084	0.145	362.0	0.285	0.174	0.145	0.174	0.145	0.084	79.9
371.0	0.139	0.188	0.133	0.144	0.126	371.0	0.304	0.188	0.139	0.139	0.188	0.133	80.3
383.0	0.132	0.189	0.159	0.123	0.121	383.0	0.295	0.189	0.132	0.132	0.189	0.159	87.6
397.0	0.168	0.178	0.202	0.178	0.172	397.0	0.287	0.202	0.178	0.168	0.178	0.202	95.6
403.0	0.193	0.190	0.233	0.236	0.203	403.0	0.287	0.236	0.203	0.193	0.190	0.233	120.4

MOTOR ACTION TIME = 120.4 SECONDS

A " < " INDICATES THE PRECEDING MDD HAS EXCEEDED THE M + 3 SIGMA DESIGN CRITERIA

REVISION _____

PREFIRE MEASUREMENTS				POSTFIRE MEASUREMENTS							
INCHES				INCHES							
STATION (IN)	74.0	140.0	206.0	270.0	336.0	STATION (IN)	74.0	140.0	206.0	270.0	336.0
DEGREE LOCATIONS				DEGREE LOCATIONS							
MIN.	MEDIAN	MDT		MIN.	MEDIAN	MDT		MIN.	MEDIAN		
3.5	2.537	2.460	2.538	2.460	2.538	2.120	3.5	2.503	2.431	2.485	2.478
13.0	0.866	0.870	0.876	0.920	0.855	0.650	13.0	0.842	0.854	0.897	0.903
27.0	0.559	0.573	0.558	0.572	0.558	0.450	27.0	L	L	L	L
44.0	0.297	0.297	0.298	0.297	0.297	0.250	44.0	L	L	L	L
60.0	0.143	0.140	0.141	0.140	0.140	0.100	60.0	L	L	L	L
94.7	0.110	0.092	0.110	0.113	0.094	0.090	94.7	L	L	L	L
142.0	0.165	0.164	0.164	0.163	0.163	0.113	142.0	L	L	L	L
152.0	0.373	0.359	0.379	0.358	0.384	0.317	152.0	0.381	0.348	0.328	0.358
162.0	0.717	0.728	0.717	0.737	0.731	0.547	162.0	0.651	0.641	0.654	0.649
175.5	0.674	0.695	0.679	0.686	0.694	0.604	175.5	0.564	0.581	0.553	0.558
187.0	0.644	0.656	0.628	0.648	0.636	0.640	187.0	0.498	0.530	0.490	0.508
199.0	0.724	0.714	0.714	0.726	0.717	0.683	199.0	0.566	0.560	0.554	0.588
213.0	0.720	0.721	0.724	0.721	0.712	0.677	213.0	0.602	0.571	0.587	0.584
224.0	0.761	0.764	0.764	0.768	0.763	0.677	224.0	0.648	0.628	0.643	0.628
230.0	0.717	0.728	0.721	0.714	0.713	0.677	230.0	0.602	0.609	0.610	0.593
236.0	0.652	0.650	0.630	0.661	0.632	0.578	236.0	0.513	0.527	0.536	0.539
240.0	0.639	0.637	0.637	0.648	0.632	0.574	240.0	0.531	0.515	0.509	0.529
254.0	0.572	0.568	0.568	0.592	0.577	0.568	254.0	0.471	0.469	0.471	0.464
263.0	0.578	0.573	0.572	0.596	0.575	0.568	263.0	0.468	0.467	0.454	0.471
282.0	0.637	0.631	0.626	0.632	0.638	0.568	282.0	0.575	0.529	0.519	0.514
293.0	0.616	0.619	0.609	0.619	0.614	0.546	293.0	0.533	0.510	0.505	0.502
305.0	0.634	0.625	0.617	0.627	0.681	0.525	305.0	0.507	0.531	0.509	0.518
312.0	0.635	0.630	0.628	0.663	0.633	0.541	312.0	0.510	0.537	0.542	0.551
321.0	0.998	1.022	1.014	0.990	0.960	0.918	321.0	0.894	0.872	0.913	0.893
339.0	0.576	0.590	0.556	0.592	0.563	0.551	339.0	0.465	0.455	0.457	0.492
350.0	0.598	0.589	0.605	0.615	0.586	0.523	350.0	0.483	0.462	0.452	0.472
362.0	0.612	0.610	0.598	0.614	0.613	0.520	362.0	0.438	0.465	0.444	0.530
371.0	0.615	0.617	0.595	0.603	0.600	0.603	371.0	0.476	0.429	0.462	0.459
383.0	0.581	0.624	0.570	0.597	0.581	0.511	383.0	0.449	0.435	0.411	0.474
397.0	0.595	0.600	0.627	0.629	0.613	0.503	397.0	0.427	0.422	0.425	0.451
403.0	1.048	1.057	1.049	1.056	1.069	0.950	403.0	0.855	0.867	0.816	0.820

AN " L " INDICATES THAT LINER MATERIAL WAS REMAINING AT THAT LOCATION.
 THE MEDIAN AND MINIMUM VALUES WERE CALCULATED USING THE PREFIRE THICKNESSES
 AT THE LOCATIONS WHERE LINER MATERIAL WAS REMAINING

TABLE 11

RSRM-26A IGNITER CHAMBER AND ADAPTER INSULATION PERFORMANCE

CHAMBER PART NO. 1U75162-01
 CHAMBER SERIAL NO. 0000080
 ADAPTER PART NO. 1U77392-01(902)
 ADAPTER SERIAL NO. 0000009

PREFIRE MEASUREMENTS
 INCHES

STATION (NO.)	DEGREE LOCATION										
	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	MEDIAN	MINIMUM	
1.0	1.040	1.115	1.100	1.110	1.040	1.050	1.050	1.050	1.050	1.040	
2.0	0.990	0.990	1.020	1.000	1.000	1.000	1.020	1.000	1.000	0.990	
3.0	0.968	0.978	1.010	0.980	0.980	0.980	0.980	0.980	0.980	0.968	
4.0	1.060	1.020	1.010	1.050	1.050	1.020	1.040	1.040	1.040	1.010	
5.0	0.370	0.370	0.380	0.390	0.390	0.391	0.422	0.390	0.390	0.370	
6.0	0.480	0.500	0.480	0.490	0.500	0.490	0.490	0.480	0.490	0.480	
7.0	0.630	0.640	0.660	0.630	0.650	0.630	0.630	0.650	0.635	0.630	
8.0	0.550	0.550	0.560	0.540	0.540	0.550	0.530	0.530	0.545	0.530	
9.0	0.420	0.420	0.410	0.400	0.400	0.403	0.400	0.400	0.402	0.400	
10.0	0.390	0.400	0.390	0.370	0.380	0.370	0.370	0.400	0.385	0.370	
11.0	0.540	0.540	0.540	0.540	0.540	0.540	0.540	0.540	0.540	0.540	

CHAMBER PART NO. 1U75161-01(918)
 CHAMBER SERIAL NO. 0000005
 ADAPTER PART NO. 1U77547-01(903)
 ADAPTER SERIAL NO. 0000005

POSTFIRE MEASUREMENTS
 INCHES

STATION (NO.)	DEGREE LOCATION										
	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	MEDIAN	MINIMUM	
1.0	0.789	0.805	0.836	0.826	0.779	0.798	0.808	0.789	0.802	0.779	
2.0	0.705	0.753	0.783	0.710	0.751	0.732	0.757	0.745	0.748	0.705	
3.0	0.680	0.720	0.767	0.660	0.670	0.670	0.660	0.650	0.670	0.650	
4.0	0.830	0.780	0.790	0.780	0.760	0.770	0.770	0.760	0.775	0.760	
5.0	0.140	0.120	0.110	0.110	0.130	0.130	0.130	0.120	0.125	0.110	
6.0	0.480	0.529	0.507	0.523	0.540	0.520	0.490	0.505	0.514	0.480	
7.0	0.590	0.640	0.630	0.610	0.650	0.633	0.610	0.580	0.620	0.580	
8.0	0.513	0.513	0.522	0.532	0.526	0.525	0.523	0.513	0.523	0.513	
9.0	0.382	0.373	0.380	0.361	0.359	0.366	0.369	0.371	0.370	0.359	
10.0	0.314	0.342	0.342	0.331	0.324	0.342	0.350	0.323	0.337	0.314	
11.0	0.419	0.395	0.398	0.391	0.378	0.389	0.386	0.401	0.393	0.378	

TABLE 11

RSRM-26A IGNITER CHAMBER AND ADAPTER INSULATION PERFORMANCE

COMPLIANCE SAFETY FACTORS (CSF)

STATION (NO.)	DEGREE LOCATION										MINIMUM	PLANE
	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	330.0	330.0		
1.0	3.66	2.96	3.48	3.23	3.52	3.64	3.79	3.52	2.96	60.0		
2.0	3.22	3.87	3.87	3.17	3.69	3.43	3.49	3.60	3.17	150.0		
3.0	3.19	3.56	3.78	2.87	2.96	2.96	2.87	2.78	2.78	330.0		
4.0	3.99	3.82	4.17	3.40	3.17	3.67	3.40	3.28	3.17	180.0		
5.0	1.50	1.38	1.28	1.24	1.33	1.33	1.18	1.28	1.18	270.0		
6.0	+	+	+	+	+	+	+	+	99.90	0.0		
7.0	15.72	+	20.97	31.45	+	+	31.45	8.99	8.99	330.0		
8.0	13.78	13.78	13.42	63.75	36.43	20.40	72.86	30.00	13.42	90.0		
9.0	10.29	8.32	13.03	10.03	9.54	10.57	12.61	13.48	8.32	60.0		
10.0	4.79	6.28	7.58	9.33	6.50	13.00	18.20	4.73	4.73	330.0		
11.0	3.74	3.12	3.18	3.03	2.79	2.99	2.94	3.25	2.79	180.0		

SF = + INDICATES THAT NEGLIGIBLE MDD OCCURRED

ACTUAL SAFETY FACTORS (ASF)

STATION (NO.)	DEGREE LOCATION										MINIMUM	PLANE
	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	330.0	330.0		
1.0	4.14	3.60	4.17	3.91	3.98	4.17	4.34	4.02	3.60	60.0		
2.0	3.47	4.18	4.30	3.45	4.02	3.73	3.88	3.92	3.45	150.0		
3.0	3.36	3.79	4.16	3.06	3.16	3.16	3.06	2.97	2.97	330.0		
4.0	4.61	4.25	4.59	3.89	3.62	4.08	3.85	3.71	3.62	180.0		
5.0	1.61	1.48	1.41	1.39	1.50	1.50	1.45	1.44	1.39	150.0		
6.0	+	+	+	+	+	+	+	+	99.90	0.0		
7.0	15.75	+	22.00	31.50	+	+	31.50	9.29	9.29	330.0		
8.0	14.86	14.86	14.74	67.50	38.57	22.00	75.71	31.18	14.74	90.0		
9.0	11.05	8.94	13.67	10.26	9.76	10.89	12.90	13.79	8.94	60.0		
10.0	5.13	6.90	8.13	9.49	6.79	13.21	18.50	5.19	5.13	0.0		
11.0	4.46	3.72	3.80	3.62	3.33	3.58	3.51	3.88	3.33	180.0		

SF = + INDICATES THAT NEGLIGIBLE MDD OCCURRED

TABLE 11

ESRM-26A IGNITER CHAMBER AND ADAPTER INSULATION PERFORMANCE

REVISION _____

STATION (NO.)	MATERIAL DECOMPOSITION DEPTH (MDD) (INCHES)									
	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	MEDIAN	MAXIMUM
1.0	0.251	0.310	0.264	0.284	0.261	0.252	0.242	0.261	0.261	0.310
2.0	0.285	0.237	0.237	0.290	0.249	0.268	0.263	0.255	0.259	0.290
3.0	0.288	0.258	0.243	0.320	0.310	0.310	0.320	0.330	0.310	0.330
4.0	0.230	0.240	0.220	0.270	0.290	0.250	0.270	0.280	0.260	0.290
5.0	0.230	0.250	0.270	0.280	0.260	0.261	0.292	0.270	0.266	0.292
6.0	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
7.0	0.040	0.000	0.030	0.020	0.000	0.000	0.020	0.070	0.020	0.070
8.0	0.037	0.037	0.038	0.008	0.014	0.025	0.007	0.017	0.021	0.038
9.0	0.038	0.047	0.030	0.039	0.041	0.037	0.031	0.029	0.037	0.047
10.0	0.076	0.058	0.048	0.039	0.056	0.028	0.020	0.077	0.052	0.077
11.0	0.121	0.145	0.142	0.149	0.162	0.151	0.154	0.139	0.147	0.162

MATERIAL DECOMPOSITION RATE (MDR)
(MILS/SEC)

STATION (NO.)	MATERIAL DECOMPOSITION RATE (MDR) (MILS/SEC)									
	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	AVERAGE	
1.0	2.1	2.6	2.2	2.4	2.2	2.1	2.0	2.2	2.2	
2.0	2.4	2.0	2.0	2.4	2.1	2.2	2.2	2.1	2.2	
3.0	2.4	2.1	2.0	2.7	2.6	2.6	2.7	2.7	2.5	
4.0	1.9	2.0	1.8	2.2	2.4	2.1	2.2	2.3	2.1	
5.0	1.9	2.1	2.2	2.3	2.2	2.2	2.4	2.2	2.2	
6.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
7.0	0.3	0.0	0.2	0.2	0.0	0.0	0.2	0.6	0.2	
8.0	0.3	0.3	0.3	0.1	0.1	0.2	0.1	0.1	0.2	
9.0	0.3	0.4	0.2	0.3	0.3	0.3	0.3	0.2	0.3	
10.0	0.6	0.5	0.4	0.3	0.5	0.2	0.2	0.6	0.4	
11.0	1.0	1.2	1.2	1.2	1.3	1.3	1.3	1.2	1.2	

MOTOR ACTION (EXPOSURE) TIME = 120.40 SEC

A MDR=0 INDICATES THAT MDR < .1 MIL/SEC

TABLE 12

RSRM-26B IGNITER CHAMBER AND ADAPTER INSULATION PERFORMANCE

MATERIAL DECOMPOSITION DEPTH (MDD)
(INCHES)

STATION (NO.)	DEGREE LOCATION							330.0	MEDIAN	MAXIMUM
	0.0	60.0	90.0	150.0	180.0	240.0	270.0			
1.0	0.228	0.223	0.183	0.207	0.189	0.255	0.228	0.293	0.225	0.293
2.0	0.292	0.184	0.241	0.154	0.234	0.246	0.225	0.238	0.236	0.292
3.0	0.365	0.307	0.295	0.251	0.263	0.309	0.313	0.315	0.308	0.365
4.0	0.272	0.306	0.289	0.273	0.303	0.297	0.231	0.297	0.293	0.306
5.0	0.272	0.270	0.277	0.243	0.230	0.269	0.252	0.243	0.261	0.277
6.0	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
7.0	0.058	0.013	0.000	0.050	0.063	0.000	0.000	0.019	0.016	0.063
8.0	0.000	0.000	0.000	0.000	0.007	0.000	0.000	0.000	0.000	0.007
9.0	0.004	0.000	0.004	0.000	0.000	0.018	0.000	0.000	0.000	0.018
10.0	0.006	0.012	0.038	0.021	0.000	0.000	0.002	0.017	0.009	0.038
11.0	0.127	0.129	0.113	0.124	0.136	0.123	0.108	0.112	0.124	0.136

MATERIAL DECOMPOSITION RATE (MDR)
(MILS/SEC)

STATION (NO.)	DEGREE LOCATION							330.0	AVERAGE
	0.0	60.0	90.0	150.0	180.0	240.0	270.0		
1.0	1.9	1.8	1.5	1.7	1.6	2.1	1.9	2.4	1.9
2.0	2.4	1.5	2.0	1.3	1.9	2.0	1.9	2.0	1.9
3.0	3.0	2.5	2.4	2.1	2.2	2.5	2.6	2.6	2.5
4.0	2.2	2.5	2.4	2.2	2.5	2.4	1.9	2.4	2.3
5.0	2.2	2.2	2.3	2.0	1.9	2.2	2.1	2.0	2.1
6.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
7.0	0.5	0.1	0.0	0.4	0.5	0.0	0.0	0.2	0.2
8.0	0.0	0.0	0.0	0.0	0.1	0.0	0.0	0.0	0.0
9.0	0.0	0.0	0.0	0.0	0.0	0.1	0.0	0.0	0.0
10.0	0.0	0.1	0.3	0.2	0.0	0.0	0.0	0.1	0.1
11.0	1.0	1.1	0.9	1.0	1.1	1.0	0.9	0.9	1.0

MOTOR ACTION (EXPOSURE) TIME = 121.50 SEC

A MDR=0 INDICATES THAT MDR < .1 MIL/SEC



TABLE 12

RSRM-26B IGNITER CHAMBER AND ADAPTER INSULATION PERFORMANCE

REVISION _____

COMPLIANCE SAFETY FACTORS (CSF)

STATION (NO.)	DEGREE LOCATION								MINIMUM PLANE
	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	
1.0	4.03	4.12	5.02	4.43	4.86	3.60	4.03	3.13	330.0
2.0	3.14	4.99	3.81	5.96	3.92	3.73	4.08	3.86	0.0
3.0	2.52	2.99	3.11	3.66	3.49	2.97	2.91	2.52	0.0
4.0	3.38	3.00	3.18	3.36	3.03	3.09	3.97	3.09	60.0
5.0	1.27	1.28	1.25	1.42	1.50	1.29	1.37	1.42	90.0
6.0	+	+	+	+	+	+	+	+	99.90
7.0	10.84	48.38	+	12.58	9.98	+	+	33.11	180.0
8.0	+	+	+	+	72.86	+	+	+	72.86
9.0	97.75	+	97.75	+	+	21.72	+	+	21.72
10.0	60.67	30.33	9.58	17.33	+	+	99.00	21.41	90.0
11.0	3.56	3.50	4.00	3.65	3.32	3.67	4.19	4.04	3.32

SF= + INDICATES THAT NEGLIGIBLE MDD OCCURRED

ACTUAL SAFETY FACTORS (ASF)

STATION (NO.)	DEGREE LOCATION								MINIMUM PLANE
	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	
1.0	4.83	4.81	5.78	5.18	5.38	4.17	4.37	3.73	330.0
2.0	3.37	5.32	4.06	6.42	4.22	3.98	4.43	4.18	0.0
3.0	2.73	3.25	3.35	3.98	3.76	3.23	3.16	3.17	0.0
4.0	3.90	3.46	3.61	3.83	3.51	3.65	4.52	3.61	60.0
5.0	1.42	1.50	1.43	1.66	1.70	1.51	1.62	1.61	0.0
6.0	+	+	+	+	+	+	+	+	99.90
7.0	11.55	51.62	+	13.64	10.94	+	+	35.53	180.0
8.0	+	+	+	+	77.14	+	+	+	77.14
9.0	99.00	+	99.00	+	+	23.72	+	+	23.72
10.0	68.33	32.58	10.76	19.43	+	+	99.00	24.24	90.0
11.0	4.25	4.19	4.78	4.35	3.97	4.39	5.00	4.82	3.97

SF= + INDICATES THAT NEGLIGIBLE MDD OCCURRED

TABLE 12

RSRM-26B IGNITER CHAMBER AND ADAPTER INSULATION PERFORMANCE

CHAMBER PART NO. 1U75162-01
 CHAMBER SERIAL NO. 0000081
 ADAPTER PART NO. 1U77392-01(902)
 ADAPTER SERIAL NO. 0000007

PREFIRE MEASUREMENTS
 INCHES

STATION (NO.)	DEGREE LOCATION									
	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	MEDIAN	MINIMUM
1.0	1.102	1.073	1.058	1.073	1.016	1.064	0.997	1.092	1.069	0.997
2.0	0.984	0.978	0.978	0.988	0.988	0.978	0.997	0.995	0.986	0.978
3.0	0.995	0.998	0.988	0.998	0.988	0.998	0.988	1.000	0.997	0.988
4.0	1.060	1.059	1.043	1.045	1.064	1.083	1.045	1.073	1.059	1.043
5.0	0.386	0.405	0.395	0.404	0.392	0.405	0.407	0.391	0.400	0.386
6.0	0.508	0.502	0.504	0.518	0.519	0.512	0.508	0.505	0.508	0.502
7.0	0.670	0.671	0.669	0.682	0.689	0.674	0.672	0.675	0.673	0.669
8.0	0.534	0.530	0.524	0.541	0.540	0.532	0.540	0.560	0.537	0.524
9.0	0.446	0.408	0.417	0.417	0.401	0.427	0.418	0.443	0.418	0.401
10.0	0.410	0.391	0.409	0.408	0.385	0.389	0.397	0.412	0.403	0.385
11.0	0.540	0.540	0.540	0.540	0.540	0.540	0.540	0.540	0.540	0.540

CHAMBER PART NO. 1U75161-01(918)
 CHAMBER SERIAL NO. 0000006
 ADAPTER PART NO. 1U77547-01(903)
 ADAPTER SERIAL NO. 0000006

POSTFIRE MEASUREMENTS
 INCHES

STATION (NO.)	DEGREE LOCATION									
	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	MEDIAN	MINIMUM
1.0	0.874	0.850	0.875	0.866	0.827	0.809	0.769	0.799	0.839	0.769
2.0	0.692	0.794	0.737	0.834	0.754	0.732	0.772	0.757	0.756	0.692
3.0	0.630	0.691	0.693	0.747	0.725	0.689	0.675	0.685	0.690	0.630
4.0	0.788	0.753	0.754	0.772	0.761	0.786	0.814	0.776	0.774	0.753
5.0	0.114	0.135	0.118	0.161	0.162	0.136	0.155	0.148	0.142	0.114
6.0	0.508	0.533	0.531	0.548	0.537	0.542	0.532	0.510	0.533	0.508
7.0	0.612	0.658	0.678	0.632	0.626	0.684	0.721	0.656	0.657	0.612
8.0	0.534	0.544	0.540	0.564	0.533	0.567	0.575	0.570	0.554	0.533
9.0	0.442	0.432	0.413	0.430	0.447	0.409	0.465	0.460	0.437	0.409
10.0	0.404	0.379	0.371	0.387	0.419	0.393	0.395	0.395	0.394	0.371
11.0	0.413	0.411	0.427	0.416	0.404	0.417	0.432	0.428	0.417	0.404

DS:ND TWE 5420
 SEC 100
 E-32