

## The IRAC Shutter Mechanism: Residual Magnetism and the Rotary Solenoid

Scott Schwinger\*, Claef Hakun\*, Gary Brown\*, Ken Blumenstock\*

### Abstract

The IRAC Shutter mechanism was originally presented in the paper, "A Low Power Cryogenic Shutter Mechanism for Use on Infrared Imagers" at the 34<sup>th</sup> Aerospace Mechanisms Symposium, May 2000. At that time, the shutter was believed to be performing flawlessly and there was every indication it would continue to do so. In early spring of 2001, the calibration shutter, a rotary solenoid designed to be fail-safe open, remained in a closed state with no power to the electromagnetic coils. The ensuing investigation, subsequent testing, proposed remedy, and lessons learned are the focus of this paper.

### Introduction

The Infrared Array Camera (IRAC) is one of three instruments on board the Space Infrared Telescope Facility (SIRTF), the fourth "Great Observatory". The SIRTF instruments will provide imagery, photometry, and spectroscopy of astronomical bodies of interest over a spectral range of 3.6 to 160  $\mu\text{m}$ . IRAC will take images in four bands centered on 3.6, 4.6, 5.8, and 8.0  $\mu\text{m}$  wavelengths<sup>1</sup>. It is a cryogenic instrument thermally coupled to a superfluid Helium dewar with an operational temperature of 1.4 Kelvin (K).

#### Shutter Background and Description

The IRAC shutter mechanism is required to block incoming light energy, producing a dark internal environment, and to allow viewing of internal calibration sources for IRAC to calibrate its detectors. The two most important requirements for the shutter, aside from the level of light attenuation the shutter is to provide, are to exhibit low power dissipation to limit cryogen depletion, and to be fail-safe open to avoid loss of mission in the event of a failure in the closed state. These two requirements factored heavily into the shutter design and will be addressed further. The mechanism (Figure 1) is approximately 0.15 m (5.9 in) long and has a mass of 1.25 Kg. It translates a mirrored panel through an arc of 0.663 rad (38 deg). The shutter is required to attenuate incoming radiation by  $1.0\text{E}+06$ . On the inside portion of the panel, mirrored surfaces are diamond turned to reflect an on-board calibration source through the instrument optics onto the focal plane detectors. This shutter is required to be fail-safe open, have a lifetime of 20,000 actuations, operate at 1.4 K, and dissipate less than 5 mW average power (0.5J/100s). It is required to be redundant, and therefore, has two separate actuators, Side A and Side B, located on opposite ends of the mechanism, driving a common shaft as shown in Figure 2. Separate electronic cards drive the Side A and Side B actuators independently. Only one card can be powered at a time and only one actuator is required to close the shutter.





Figure 1. IRAC Shutter Mechanism

The suspension system of the shutter relies on a torsion flexure to provide axial stiffness, torsional preload and restoring torque upon actuation (Figure 3). This flexure is chemically etched from a 0.660-


\* NASA Goddard Space Flight Center, Greenbelt, MD

mm (0.026 in) thick sheet of Beryllium Copper (BeCu) 25AT. The flexure is attached to the shaft of the shutter at its center point and is fixed at either end by components that fix them in rotation. As the shutter closes, a restoring torque is produced in each half of the flexure. The nominal torsional preload in the flexure in the open state is approximately 24.7 mN•m (3.5 in•oz). Closed, the flexure produces 49.4 mN•m (7 in•oz). Bushings at either end of the shaft provide radial stability. They limit radial motion of the shaft during vibration and closing operations. Since radial forces approach zero with no current applied to the actuators, friction at the bushing interfaces approaches zero as the shutter opens.



**Figure 2. Shutter mechanism cross-section**

The actuators are variable reluctance rotary solenoids designed at GSFC for the IRAC project. All magnetic components are made of Hiperco 50A, a soft magnetic material with high magnetic saturation, which was heat treated to minimize coercive force. With no permanent magnets in the circuit, the actuation of the motor is insensitive to voltage polarity across the coil (i.e. these motors always pull, they never push). The design of these motors consists of two stators and a rotor housed within an electromagnetic coil. A closeout cylinder then surrounds the coil and joins the two stators at either end (Figure 4) thus closing the magnetic circuit. The coil consists of 11500 turns of 38 gage 99.99% pure copper wire. Coil resistance drops from 2700  $\Omega$  at room temperature to 17  $\Omega$  at 1.4 K. Low power dissipation is achieved by virtue of this resistance change and the ability to drop the current input necessary to hold the shutter closed. The lower hold current is a product of magnetic tabs that extend normal to the stator faces (Figure 5). These tabs are contacted by the rotor in the closed state and complete the magnetic circuit in the motor. The closed magnetic circuit requires dramatically lower current to achieve the required flux level and resultant torque to maintain a



**Figure 3. Shutter suspension system**

closed state against the restoring torque of the torsion flexure. Since power to the coils is  $I^2R$ , lower current means less power dissipation. The drive circuitry provides approximately -60 mA to close the

shutter. The current is then reduced to -2.5 mA to maintain the closed position while the instrument runs calibration procedures. Current is then removed to allow the shutter to open.




Figure 4. Exploded view of shutter actuator




Figure 5. Shutter rotor and stator

### Description of Failure

During ground testing at the SIRTf system level, the shutter was found to remain closed with no current applied at the conclusion of one of the test sequences, thus violating the fail-open requirement. An investigative team was assembled to determine if there were, in fact, a failure, the extent, repeatability, and cause of the failure, as well as how to resolve it.

#### Events Leading Up To The Failure

During a review of the IRAC operations, it was discovered that the shutter was operated in an illogical manner that, while not damaging hardware, stressed certain electrical components more than necessary. The original shutter electronics and software design engineers had long since left NASA, so the design philosophy of the command sequence is unclear. The electronics are primarily a closed loop current drive with a solid state relay in series with the shutter coil output. When the relay is opened, the feedback electronics are zeroed out and held in a low state. When the relay is closed, the system uses feedback and a PID controller to track the current level command. The command is a 12-bit word and is scaled such that the electronics can output up to +/-80mA in 40µA steps. The original opening sequence in V3.13 of the software was:

- Simultaneously command zero current and open the relay (with 5mA of holding current flowing)
- 0.2 second later, close the relay
- 0.1 second later re-open the relay

This opening and closing of a relay driving current into an inductive load seemed inappropriate. Another problem with the original software was that the sensor was not being operated properly. To correct the sensor operation and reduce the stress on this relay, the shutter opening command sequence was changed in V3.2 to:

- Command the current to zero (Wait at least 0.1 second)
- Open the relay


Soon after the implementation of V3.2, the failure occurred. Therefore, the first suspect was the software. However, the investigation showed the software sequence that provided smoother, gentler current profiles simply uncovered the low torque margins upon opening that were due to residual magnetism in the shutter.

#### Investigations on Flight Hardware

The failure was first diagnosed while processing data taken during the last functional test before breaking configuration. The first action was to thoroughly examine all data and telemetry taken during that test. There was no evidence of improper commands or current anomalies, so the detailed investigation began.

The next step was an attempt to determine the actual state of the shutter. Since the impedance of the magnetic circuit changes, resistance, inductance, and capacitance measurements were made on the two shutter coils and the sensor coils to determine the state. The shutter was verified to be open. However, the shutter coils were inadvertently measured, including changing scales on the resistance meter, before those of the sensor. In later investigations, it was determined the current spike produced by changing the scale on the multi-meter had the ability to open the shutter if it did remain closed. It was never determined whether the shutter opened at the end of the testing, during the move of the dewar, or during the impedance measurements, but testing the sensor coil proved to be a valid means to verify position when the instrument was powered off.

A set of tests, run on 6/3/01, instrumented the voltage and current waveforms to verify the functionality of the electronics and to capture the differences in behavior using the various software versions. These waveforms suggested that the electronics were healthy and appropriately responding to all commands sent. They also verified the differences between the command software versions and gave insight to the behavior of the shutter under various conditions. During the attempt to capture full opening and closing waveforms, it was discovered that using a short pull-in and hold cycle would reproduce the failure somewhat consistently. Figure 6 shows the current and voltage profiles of an actuator that fails to open at zero current and one that opens properly. This command sequence proved invaluable in further



**Figure 6. Current and voltage profiles for an actuator that fails to open at zero current (left) and one that opens properly (right)**


investigating the anomaly. The first round of tests included capturing the waveforms, sending individual commands to prove the closed shutter could be opened by sending current of the opposite polarity, measuring the pull-in and release currents on the shutter, and sending various static current levels to properly calibrate the current output and telemetry test points for updating the ground data system. Figure 7 summarizes the release current data for the flight shutter. The results of the tests on 6/3/01 showed that the hold currents on Side B were lower than expected, but did not require opposite polarity current to open. This was supported by the fact that Side B operations NEVER led to the shutter remaining closed. Side A current measurements showed that a slight current in the opposite polarity opened the shutter reliably. The results also showed that the pull-in currents were virtually unchanged from previous data. This suggested that the spring and shutter coils were healthy. Finally, the calibration tests revealed a +50  $\mu$ A Side A offset and a +360  $\mu$ A Side B offset when zero current was commanded. The current output responded linearly to commands and the telemetry feedback equations were updated from a generic approximation equation to side-specific equations which fit the data.

Once these tests were completed, a new and final version of the software was written. The new command sequence added a commandable current pulse in the opposite polarity to counteract residual magnetism, more time for current commands to settle, and more flexibility in command parameters. The Version 3.21 opening sequence is as follows:

- Turn on the position sensor

- Command zero current then wait 1 second
- Send a commandable "kick current", +2.5mA, (Wait a commandable time, 3 seconds)
- Command zero current then wait 1 second
- Read the sensor and store the value
- Open shutter relay and turn off the sensor

This software version was implemented and the electronics were instrumented on 6/14/01. The waveforms verified proper operation and the failure never repeated. Other tests were run on the flight instrument including reverse polarity closings, unexpected loss of power, and attempting to use Side B to release the shutter after being deliberately stuck closed using Side A. The reverse polarity tests showed pull-in and hold current comparable to the nominal operations. This verified that the magnetic circuit fully saturates regardless of polarity when the high, 60mA, pull-in current is applied. Side B always released during a sudden loss of power, but Side A could be made to stay closed under certain conditions. Unfortunately, Side B operations were unsuccessful in releasing the shutter once Side A was stuck due to residual magnetism. This ultimately became the a concern of SIRTF management and prompted the study into mitigation approaches which could be implemented on the flight system.



**Figure 7. Release current data for the IRAC flight shutter**

### GSFC Actuator Testing and Analysis

Considerable effort went into testing the 2 spare units at GSFC to duplicate the failure experienced on the flight unit. The impacts of software and electronics board performance were eliminated as root causes of the failure through extensive characterization. In order for the mechanism to remain closed with zero current the following equation must be satisfied:

$$T_{\text{Restoring Spring}} \leq T_{\text{Residual Magnetism}} + T_{\text{Friction}}$$


Both the magnetic and frictional sources of torque in the mechanism which could cause the mechanism to stick with zero current were investigated at length at both room and cryogenic temperatures. The actuator components were also tested separately to characterize the release currents and torque generated in an actuator without the influence of being in the more complicated shutter assembly. This section of the paper will summarize the testing history, magnetic analysis efforts, and some of the key test results obtained at GSFC. The results of these efforts confirm that the flight failure is due to intimate contact between rotor and stator tab surfaces and the torque generated by residual magnetism.

#### History

Our initial suspicions were that the problem was related to residual magnetism in the rotary solenoid. The theoretical possibility that enough residual magnetism could be developed in the actuator to overcome the restoring torque of the spring, and thus not allow for failsafe operation, was an aspect of the design and was anticipated from the beginning of the design process. The electronics were designed to allow for reverse polarity currents to be applied to the actuator to cancel any residual magnetism and the potential need for a degauss command was identified. The problem during initial testing prior to delivery to the IRAC instrument was that we did not observe a zero current stick condition on any of the 4 units developed at GSFC including the flight unit. However, we did see lower than desired hold currents on the flight unit during initial assembly and testing. A non-magnetic shim was placed in the magnetic circuit to maintain a fixed gap in the circuit in the closed condition. At the time, it was thought that this shim provided enough coercive force on the magnetic circuit to effectively reduce the residual magnetism in the actuator components after the 60 mA pull-in current was applied. After reassembly with this shim, desired release currents were achieved. Unfortunately, after the flight failure occurred, a closer look into the

placement of the shim revealed that it was not placed optimally and was subject to potential magnetic shorting due to small variations in assembly or shifting of gaps during shutter operation.

Considerable frustration was endured during initial post failure testing which showed very little effect of magnetics on the ability of the shutter to remain closed with zero current. Upon examination of the rotor and stator parts, a slight burnishing of the rotor where it contacted the stator tabs was revealed (Figure 8). Clearly the majority of the tab surface was not in intimate contact with the rotor. Only when the contacting surfaces of a set of actuators were lapped together (Figure 8) did it become apparent that our initial suspicions were most likely correct. Approximately 12  $\mu\text{m}$  (0.0005 in) of material was removed during the lapping process. When these components were assembled into a spare mechanism, the unit consistently failed to open with zero current applied. This was a breakthrough in the testing program. It showed that small variations in the nature of the contact between the rotor and the stator have a significant impact on residual magnetism and, therefore, the residual torque that the actuator could exhibit.




**Figure 8. Rotor pre and post lapping**


#### Magnetic Analysis and Parameters

Considerable magnetic analysis was done on the actuator by constructing 2-D and 3-D BEM models. Unfortunately, these models proved of no use in understanding “small air gap” behavior. It was suspected that large flux levels could be developed when the gap between rotor and stator tabs approaches zero. Since laboratory measurements on spare units failed to duplicate flight residual magnetic torques necessary to overcome the flexure torque (measurements were less than 14 mN•m (2 in•oz) compared with the flexure return torque of 50 mN•m (7 in•oz)) and result in a “stuck” condition, the question arose as to what the theoretical maximum residual magnetic torque was, and moreover, how this behavior was related to air gap distance. Stator/rotor alignment is one factor affecting the minimum air gap and tab surface quality is another.

One analytic solution was utilized which assumed all the material, Carpenter Hiperco 50A, was magnetized and that all the reluctance was in the air gap. Another case was run for the case of zero air gap wherein the reluctance of the Hiperco was used to determine the maximum magnetic flux,  $B_{\text{max}}$ . Hiperco 50A, an alloy of nearly 50/50 iron and cobalt and a few other ingredients, was selected due to its ability to carry high flux levels and minimize actuator size and mass. Figures 9 and 10 proved to be interesting showing that the B-field at the tabs, and thus the torque generated by the tabs, rises rapidly as the air gap reduces below 5  $\mu\text{m}$  (0.0002 in).



**Figure 9. Analytic solution showing relationship of flux with air gap**



**Figure 10. Analytic solution showing relationship of torque with air gap**

Laboratory measurements indicated that providing a 2.5 mA reverse current, which allows the “stuck” rotor to release, could essentially degauss a lapped unit. Providing too much reverse current resulted in re-magnetizing the Hiperco in the reverse direction resulting, again, in a residual magnetic torque.

Key Test Results


The following sets of data will be summarized: the ability of residual magnetism to exhibit torques in excess of the restoring torque of the spring, the ability to reduce the residual magnetism to a minimum by applying a small current of the reverse polarity to the actuator, and the ability to measure the change in residual magnetism due to this reverse polarity degauss current by measuring back emf.

Spare Unit Release Current (Pre Lapping)

The release current is the value of current at which the shutter opens due to the spring. The torque due to friction was found to be negligible due to the design of the shutter mechanism. Measurements of release current were made during the assembly process. The desired release current was 1 to 1.5 mA. After the failure occurred, it was determined that the assembly process could have a major impact on the release current. Machining tolerances were also shown to have a significant effect on residual torques. Better alignment and tab contact between the rotor and stator lowers the release current and, therefore, decreases the torque margin available to open the shutter.

Initial testing of the release currents on the spare units showed lower but acceptable release current values in some cases. None of the spare shutter assemblies or actuator components exhibited enough residual magnetism to overcome the restoring torque of the spring. However, a spare unit was then disassembled and reassembled. It was noted that the assembly process could impact the release current value. After one particular reassembly process, the assembly did fail to open with zero current on rare occasions. Figure 11 shows release currents for Side A and B for the spare unit. It shows the Side A actuator had intimate contact and better alignment between the rotor and stator than Side B. The more “normal” release currents on Side B indicate less tab contact and poorer alignment between the rotor and stator in the closed position.


These measurements were made using a power supply at room temperature. Approximately 60 mA was applied to the actuator causing the shutter to close. The current was then decreased until the shutter opened. The value of the release current was then recorded. It is important to note that on the rare occasions that a mechanism stuck, it always opened when a slight reverse polarity current was applied. These reverse polarity currents reduced the residual magnetism torque to a level below the restoring torque of the spring thus allowing the mechanism to open.



**Figure 11. Spare shutter release currents**

Actuator torque characteristics and optimal degauss currents (Bounding the Problem)

After the sensitivity to the nature of the contact between the tab of the rotor to the stator was fully appreciated, we decided to improve this contact by lapping. Lapping caused the spare unit to fail to open at zero current consistently. However, the mechanism still reliably opened upon application of a slight reverse polarity current. We isolated the actuator components in a test set-up to simplify measurement of actuator torque. Measurements of torque generated verses applied current were then made and are shown in Figure 12. These measurements were performed both pre and post lapping. Prior to lapping of the actuator components, intimacy of contact between the rotor and stator was not good enough to generate significant residual magnetism torques. After lapping, measurements showed significant residual magnetism torques. Values of two to three times the restoring torque of the spring were




**Figure 12. Torque vs. current for non-lapped (left) and lapped (right) actuators**

demonstrated. It is believed that the nature of the contact on the flight unit is somewhere in between the pre and post lapped cases and that these two cases bound the problem. Therefore, the important concept to note is that in the shutter mechanism assembly, the problem is bounded: i.e. higher residual magnetism can still be cancelled with slight reverse polarity currents. The magnetic analysis confirmed this bounding. There is no condition in which the mechanism can remain closed after sufficient reverse polarity current is applied.

The efficiency of the actuator in the closed position increases as the contact between rotor and stator becomes more intimate. Since the gap is smaller with improved contact, a larger percentage of the possible residual flux due to saturation (~ 1.5 tesla) can be retained. At the same time, since the actuator is more efficient, it takes a comparably less Ni of reverse polarity to cancel the residual flux in the magnetic circuit. Thus, the problem is bounded.

Back EMF Measurements and Demonstration of Like Polarity Release Currents

There still remained the task of devising a test to prove that the failure of the flight mechanism to open with zero current was due to residual magnetism and not friction. Friction was eliminated as a plausible source of resistive torque through tolerance analysis and observations. Multiple degauss schemes were devised to show that the residual magnetism could be affected by reverse polarity currents. In an actuator with relatively poor rotor to stator alignment (i.e. a mechanism that does not stick), the effect of reverse currents has minimal effect on release currents since the amount of residual flux is small. In addition, since a relatively small value of current saturates and re-gausses the tabs, it is difficult to degauss the actuator within the constraints of the flight mechanism. In fact, when constrained to access of one coil at a




**Figure 13. Back EMF measurements before (left) and after (right) applying a reverse polarity current**

time as in the flight set-up, it is virtually impossible. However, if both Side A and B are energized at the same time it is possible to show that residual magnetism exists in a mechanism. It is also possible to show that this residual can be removed by a slight reverse polarity current. Figure 13 shows the voltage induced on the shutter coil during opening, or Back EMF, before and after a small reverse polarity degauss current is applied. The figure shows that  $\sim 85\%$  of the magnetism is removed. In fact tests at cryogenic temperature showed that the tabs could easily be degaussed if the shutter was held closed during degaussing. However, closing the shutter would re-gauss the tabs and generate the same residual magnetism. Unfortunately, due to SIRTf project management concerns over risk and schedule we were not able to duplicate these tests on the flight unit.

### Proposed Solutions and Recommendations for the Flight System

Once the problem had been assessed, we considered several solution remedies to guarantee recovery from all plausible failure modes. Opening the dewar and modifying the electronics were both deemed unacceptable since the flight hardware was in its final delivered state. This imposed condition limited options, but a simple harness modification solution was designed and tested. This "soft cross-strapping" concept simply involved adding a resistor between the drive outputs of the Side A and Side B boards (Figure 14). This resistor would be significantly larger than the coil resistance, but would allow a small transient current to flow in the unused coil. Therefore, if a failure caused a shutdown and the shutter remained closed on Side A, simply actuating Side B would provide enough current to Side A to erase the residual magnetism. Since the cross-strapped current is a fraction of the primary drive current, it could be controlled by command as well. Models were created and tests on an engineering unit were run to determine an appropriate range of values for the resistor as well as effects on the un-powered electronics board. The soft cross-strap approach successfully closed and opened the engineering unit shutter which had been lapped to have maximum residuals on both Side A and Side B. Effects on the un-powered board were negligible. Implementing the fix with a combination of series and parallel resistors, this solution promised a fault tolerant, robust, and simple fix to the Flight Shutter problem. The only fault that could not be corrected was if the Side A coil opened or shorted during a closing cycle using the Side A electronics and the residual magnetism was high enough to keep the shutter closed. A thorough study of the materials and fabrication techniques of the coil and harnessing indicated this scenario was extremely implausible, but not absolutely impossible. However, the final decision of SIRTf management not was to run further tests or implement the recommended fix on the Flight Unit.



**Figure 14. Schematic showing soft cross-strapping configuration**

## Lessons Learned

During the post failure investigation, several notable lessons in the design, fabrication, assembly and testing of a space flight mechanism were learned. Errors during each phase of the evolution of a space flight mechanism can go undetected. We are fortunate that this characteristic of the IRAC shutter mechanism was discovered during ground testing. Problems and solutions that eluded detection during each major phase of the IRAC shutter mechanism development will now be discussed.

### Design

Designing a defined fixed gap into a closed magnetic circuit is a basic concept that should have been implemented on the IRAC shutter mechanism rotary actuators. In fact, on a previous mechanism, the DIRBE shutter (also designed by GSFC), this was accomplished by gold plating of the contacting surfaces of the magnetic circuit. We understood that theoretically the design was sensitive to changes in gap in the closed position. However, since testing of engineering units never revealed this sensitivity, this possibility was largely ignored. Provisions were taken in the electronics to counteract this problem should it occur. However, the implications of discovering this problem later in the program were not fully appreciated during the early design phase.

In addition, material selection could have minimized the potential for this problem to occur. We chose Hiperco 50A because of its stable properties from room temperature to 2K and for its high flux saturation levels we thought we would need. Hiperco does have a relatively low coercive force when heat treated properly. However, other materials, such as pure iron, can exhibit an order of magnitude lower coercive force and also have stable properties over our temperature range.

### Fabrication

Be careful what you ask for; you might get it. During fabrication of developmental units it is sometimes tempting to use parts which may have been discrepant or have been made to tolerances that will later be tightened for the flight mechanism. In this case, where a design is so sensitive to small variations this could be a critical error in thinking. The parameters established by testing of early prototypes often become a benchmark for the mechanism developed for flight. Therefore, tightening tolerances to improve fit or function may invalidate previous qualification efforts and move the design to an unproven state.

### Assembly

During the assembly of the flight unit, care was taken to align all of the contact surfaces in both the A and B Side actuators. The A Side was aligned first and the B Side was then allowed to conform to the A Side alignment. Measurements of release currents were made to ensure the desired value is obtained during the assembly process. Release currents on the A Side are typically lower than the B Side. Just prior to integration into the IRAC cold assembly, the flight shutter mechanism was disassembled for cleaning. Upon reassembly, it underwent a characterization at 4K and was then integrated into the cold assembly. Not until after the failure occurred was it appreciated how much of an impact the assembly process could have on the release currents and, therefore, the reliability of the mechanism. It is theorized that the final assembly of the flight mechanism and subtle shifts during operations and vibrations caused the A Side actuator to become marginally "sticky" and detection of its behavior eluded us. Therefore, it is critical to understand the impact of the assembly process on the performance of a space flight mechanism.

### Testing

Even if extensive test data indicates no problem with a mechanism, if flaws exist in the test program or if a design error is being masked, there may still be a problem waiting to surface. In this case, continued system level characterization of the shutter mechanism was limited due to conflicts with other sub-system demands such as software checkout, optical alignment, etc. It is believed that the failure to open with zero current on the A side actuator was present but not detected throughout system level testing at GSFC. The lesson learned here for a mechanism engineer is not to assume your job is done when a mechanism is delivered to the system level. Do not bow to schedule concerns. Make sure that the mechanism is functioning properly at the system level. Make sure that the proper check-outs can be implemented at the system level.

The influence of maintaining a schedule, minimizing costs and accepting some level of risk are always present during a project. Many of the lessons learned could have been realized if the development effort had not yielded to these pressures. Although it is inevitable that these factors will always influence the development process, the mechanism designer must ensure that every aspect of their development process is validated by theory, analysis, and test.

## Conclusions

### Disposition of Shutter Failure Investigation

After the extensive test effort, a SIRTf project peer review was held where the following conclusions and recommendation were presented by GSFC to a panel of independent experts:

- Failure to open at zero current is due to residual magnetism in the shutter mechanism actuator
- The cause of the residual magnetism is a combination of two factors:
  - An improvement in rotor to stator tab alignment when the shutter was reassembled just prior to installation
  - The revised shutter open sequence in software v3.20 augmenting previously unseen characteristics
- The sensitivity of shutter release current to its mechanical alignment was not previously well understood and unintended magnetic effects were revealed following the software change from v3.13 to v3.20.
- Shutter characterization tests since May 15th have indicated stable performance – no changes in performance were observed pre and post CTA vibration testing.
- Residual magnetic forces are highly sensitive to rotor to stator alignment and gaps
- Residual magnetism can readily be offset by a small current flow in reverse polarity to the direction of actuation
- The Flight Mechanism has no “defect” and is operating nominally with current understanding of mechanism behavior and residual magnetism.
- It has been shown that Side A shutter can require a slight reverse current to open. Side B has always opened at zero current.
- The shutter can be reliably closed and opened with v3.21 commands.
- In the event of a failure of the primary drive electronics, a simple resistor “soft cross-strap” can provide a reliable secondary current source to open the shutter from the redundant drive electronics.
- A simple means to provide a small reverse current flow, even in the event of primary electronics failure has been developed
- The case of an open coil winding has been studied and determined to be non-credible
- Flight shutter Side B has been shown to be completely failsafe in all test and operational scenarios

### Recommendations

- Continue use of the flight shutter on both Sides A and B where B is the primary side and A is the secondary side
- Implement the Soft Cross-Strap Circuit to provide a backup release means for both actuators

The independent review panel concurred with all of the conclusions and recommendations that GSFC proposed. They agreed with the proposed testing and added that a mini life test be performed to ensure the reliability of the mechanism. GSFC was prepared to follow through with the proposed cross-strapping modification and necessary testing. Unfortunately, due to programmatic concerns, SIRTf project management deemed there would be no further shutter operations and the proposed soft cross strapping modification would not be implemented. An operational scheme will be used which will allow calibration of the detectors without using the shutter mechanism.

The IRAC shutter is a prime example of how secondary effects or subtle changes in the design, assembly, and testing of a flight mechanism can mask or reveal undesired behavior. As stated above, the ultimate conclusion of the investigative team is that the shutter is behaving as one should expect the design to behave. It is behaving nominally as built, but not as intended. Its “anomalous” behavior is, in

reality, an unfortunate byproduct of improvements in command sequences, tightly toleranced machining, precision alignment, and skilled assembly. At first glance, these are all desirable traits for any mechanism. However, inconsistencies in any one of these areas during the qualification phase of a development can foster a false sense of security and result in surprises during a phase when more rigorous control is applied. Fortunately, due to the commitment of a talented group of individuals, a hidden problem for this mechanism was found and a potential mission ending failure avoided.

### References

1. Schwinger, D. Scott and Claef F. Hakun. "A Low Power Cryogenic Shutter Mechanism for Use on Infrared Imagers." Goddard Space Flight Center, Greenbelt, MD. 34<sup>th</sup> Aerospace Mechanisms Symposium, Greenbelt, MD, May, 2000

### Acknowledgments

Ted Ackerson/GSFC – Quality assurance  
Marty Brown/OSC – I&T  
Bill Burmeister/Ball Aerospace – Ball SIRTf Lead I&T  
Giovanni Fazio/SAO – IRAC PI  
Rainer Fettig/Raytheon – Magnetics and mechanics  
Jose Florez/GSFC – Electronics  
Leslie Frazier/SAO – Quality assurance  
Sid Johnson/GSFC – Mechanical design, assembly, test  
Robert Kichak/GSFC – Failure investigation team chair  
Ed Lander/ Raytheon – I&T  
Norm Lee/GSFC – Quality assurance  
Steve Mann/Hammers – Software  
Ahmean Mekhail/OSC – I&T  
Shirley Paul/OSC – Quality assurance  
Lois Workman/GSFC – GSFC IRAC project manager