


NASA/TM-2002-211732



Thermal Nondestructive Evaluation
Report - Inspection of the Refurbished
Manipulator Arm System in the
Manipulator Development Facility of
Johnson Space Center 10-12 January 2001

*K. Elliott Cramer
Langley Research Center, Hampton, Virginia*

July 2002

The NASA STI Program Office ... in Profile

Since its founding, NASA has been dedicated to the advancement of aeronautics and space science. The NASA Scientific and Technical Information (STI) Program Office plays a key part in helping NASA maintain this important role.

The NASA STI Program Office is operated by Langley Research Center, the lead center for NASA's scientific and technical information. The NASA STI Program Office provides access to the NASA STI Database, the largest collection of aeronautical and space science STI in the world. The Program Office is also NASA's institutional mechanism for disseminating the results of its research and development activities. These results are published by NASA in the NASA STI Report Series, which includes the following report types:


- TECHNICAL PUBLICATION. Reports of completed research or a major significant phase of research that present the results of NASA programs and include extensive data or theoretical analysis. Includes compilations of significant scientific and technical data and information deemed to be of continuing reference value. NASA counterpart of peer-reviewed formal professional papers, but having less stringent limitations on manuscript length and extent of graphic presentations.
- TECHNICAL MEMORANDUM. Scientific and technical findings that are preliminary or of specialized interest, e.g., quick release reports, working papers, and bibliographies that contain minimal annotation. Does not contain extensive analysis.
- CONTRACTOR REPORT. Scientific and technical findings by NASA-sponsored contractors and grantees.
- CONFERENCE PUBLICATION. Collected papers from scientific and technical conferences, symposia, seminars, or other meetings sponsored or co-sponsored by NASA.
- SPECIAL PUBLICATION. Scientific, technical, or historical information from NASA programs, projects, and missions, often concerned with subjects having substantial public interest.
- TECHNICAL TRANSLATION. English-language translations of foreign scientific and technical material pertinent to NASA's mission.

Specialized services that complement the STI Program Office's diverse offerings include creating custom thesauri, building customized databases, organizing and publishing research results ... even providing videos.

For more information about the NASA STI Program Office, see the following:

- Access the NASA STI Program Home Page at <http://www.sti.nasa.gov>
- E-mail your question via the Internet to help@sti.nasa.gov
- Fax your question to the NASA STI Help Desk at (301) 621-0134
- Phone the NASA STI Help Desk at (301) 621-0390
- Write to:
NASA STI Help Desk
NASA Center for AeroSpace Information
7121 Standard Drive
Hanover, MD 21076-1320

NASA/TM-2002-211732



Thermal Nondestructive Evaluation
Report - Inspection of the Refurbished
Manipulator Arm System in the
Manipulator Development Facility of
Johnson Space Center 10-12 January 2001

*K. Elliott Cramer
Langley Research Center, Hampton, Virginia*

National Aeronautics and
Space Administration

Langley Research Center
Hampton, Virginia 23681-2199

July 2002

The use of trademarks or names of manufacturers in the report is for accurate reporting and does not constitute an official endorsement, either expressed or implied, of such products or manufacturers by the National Aeronautics and Space Administration.

Available from:

NASA Center for AeroSpace Information (CASI)
7121 Standard Drive
Hanover, MD 21076-1320
(301) 621-0390

National Technical Information Service (NTIS)
5285 Port Royal Road
Springfield, VA 22161-2171
(703) 605-6000

Thermal Nondestructive Evaluation Report – Inspection of the Refurbished Manipulator Arm System in the Manipulator Development Facility at Johnson Space Center 10-12 January 2001

K. Elliott Cramer
NASA Langley Research Center

Background

The Manipulator Development Facility (MDF) is a Shuttle robotic training facility located in Building 9 at the Johnson Space Center. The facility provides a full scale robotic arm, designed to simulate the Shuttle's Remote Manipulator System (RMS), for astronaut robotic training. The hydraulically controlled robotic arm is located in a full scale Shuttle payload bay mockup and is controlled from a high fidelity Shuttle Aft Cockpit. The arm simulates the six degrees of freedom of the Shuttle's RMS: shoulder yaw, shoulder pitch, elbow pitch, wrist roll, wrist pitch and wrist yaw. Along the Shuttle payload bay port longeron is a personnel access platform (MDF catwalk) with fall protection handrails.

On 4 December 2000, after repairs were made to the robotic arm's shoulder yaw (SY) joint a hydraulics failure occurred while the MDF Test Director (TD), commanding the robotic arm from the Aft Cockpit, attempted to position the arm properly in the cradle position prior to beginning crew training. When the Test Director commanded a shoulder pitch maneuver to lift the arm from its payload bay pedestal, the yaw controls failed due to bleed valves not being closed properly. This, coupled with gravitational forces (due to the angle of the shoulder joint with respect to vertical), resulted in uncontrolled arm motion. The shoulder yaw joint moved approximately 20 degrees, causing the extended arm to strike (and severely damage) the port side MDF catwalk handrails. The arm motion stopped after impact with the handrails (See Figure 1).




Figure 1 -- Incident photographs showing MDF Arm after yaw hydraulics failure

Introduction

On 10-12 January 2001, inspections were performed on the face of the lower and upper arms of the Refurbished Manipulator Arm System (RMAS) in the Manipulator Development Facility (MDF) at Johnson Space Center (JSC). Figure 2 shows a block diagram of the system used in the inspection. The thermal images are produced with a commercial infrared (IR) radiometer (Raytheon / Amber model Radiance 1n) which uses a Indium-Antimonide (InSb) staring focal plane array detector cooled to near liquid nitrogen temperatures by an closed cycle electric microcooler. The radiometer's noise equivalent temperature difference (NEDT), cited by the manufacturer, is 0.025°C when operating the detector in the 3 to 5 micrometer wavelength range. The radiometer produces images at both 30 frames per second output (video frame rate, in an RS170, format compatible with standard video equipment) and 60 frames per second output in a 12-bit, RS422 digital format. External optics, consisting of a wide-angle lens, using germanium optical elements, was used to increase the system field-of-view by a factor of approximately two, to 22° in both the horizontal and vertical directions.

The heat source used consists of two commercially available quartz lamps (750 Watts each), which are mounted on either side of the IR camera. Quantitative time based analysis requires synchronization between the IR imager, the heat source and the digital image processor. This synchronization is achieved by computer control of the application of heat and the data acquisition. For all cases presented in this paper, the maximum surface temperature change of the sample above ambient never exceeded 10°C.




Figure 2 -- LaRC Thermal imaging system

The digital data from the radiometer is acquired and stored at a maximum of 60 frames-per-second in a real-time image processor board in the control computer. The image processor board has 256 megabytes of image memory available for storage and is capable of real-time floating point processing of the incoming data. From a set of acquired images, a single image is then reconstructed that represents the instantaneous rate of change of the temperature immediate after the heat source is turned off. The image processor does the reconstruction after the data has been collected and stored to the control computer's hard disk. All of the data presented in the remainder of the paper (unless otherwise noted) were reconstructed in this manner.

Because the RMAS has low emissivity surfaces, it is necessary to enhance the emissivity by coating the surface. For the results presented here, the samples are treated with water washable, nontoxic paint (Krylon® Washable Tempera Paint), to enhance the emissivity.

Data Collection

To initially assess the viability of thermal imaging to inspect the RMAS Arm material and to establish the inspection parameters a cursory inspection of a test coupon was performed. From this inspection a calculation of the thermal diffusivity was performed¹. The thermal diffusivity was found to be $0.004 \text{ cm}^2/\text{s}^*$.

The results of the thermal diffusivity measurement were then used to establish the inspection parameters. Digital data from the IR radiometer was collected at 30 frames per second, and every 14 consecutive frames were averaged together to enhance signal to noise. Heat from the quartz lamps was applied for 40 seconds and data was collected for an additional 120 seconds after the heat was removed. After storage, the resulting time series of temperature images was reduced to a single image by calculating the instantaneous time derivative immediately after the removal of the heat source (the final image in the series was used to normalize the time derivative to remove the effects of uneven heating)². Figure 3 show photographs of the IR camera and quartz heaters (both on and off) during an inspection of the upper arm.




Figure 3 -- LaRC Thermal System During Inspection of RMAS

* The accuracy of this measurement is dependent on several factors. First, the coupon inspected was from the end of one of the RMAS, which has a construction that differs from the central arm regions. Second, since only one coupon was available it is impossible to assess the accuracy or repeatability of the thermal diffusivity measurements for this material system.

Inspection Areas




Figure 4 -- Inspection Areas on the (a) Upper and (b) Lower Arm




Figure 5 -- JSC Defined Locations of Interest for Inspection

Inspection Results Summary

Figure 4 shows all of the inspection areas for both the upper and lower arm as well as the numbers for mounting pads located along the arm. Composite time derivative thermal images for Locations 1-9, as defined in Figure 5, are shown on pages 9-13 of this report. In many of the images where inspections were performed close to the mounting pads a darkening of the image occurs on either side of the pad. This darkening is the result of both the changes in heat flow in the composite and nonuniformities in the application of heat due to the presence of the pad. These areas are not as pronounced above and below the pads because of the orientation of the quartz heat lamps relative to the pads (see Figure 2).

The general mottling observable in the images is typical of thermal data and does not represent indications of defects or damage. This mottling is due primarily to stretching of the contrast of the image in an attempt to utilize the full range of gray level available in the computer. The determination of indications is accomplished by looking at the time-resolved data.

Location #1 (Figure 6):

No indications of material degradation were recorded in the thermal inspection. Note that the fiber lay-up is clearly visible in this image.

Location #2 (Figure 7):

Several small indications were recorded, especially between pad #2 and pad #3. These indications are consistent with a reduction in thermal heat flow into the material,

which could be due to a number of factors such as porosity, resin rich regions or localized delaminations[#].

The two indications above pad #3 are also consistent with a reduction in thermal heat flow, but are of a larger extent. The time resolved data reveals that these indications appear to be limited in extent to very close to the surface.

Indication Sizes:

#1 – 1.4 in. wide x 1.1 in. high

#2 – 0.9 in. wide x 0.8 in. high

#3 – 0.3 in. long

#4 – 0.4 in. long

#5 – 0.35 in. long

Location #3 (Figure 8):

Directly below pad #1 the visible surface damage can also be seen in the IR images. This damage appears to be limited in extent to the near surface region and does not display thermal characteristics of impact damage that has resulted in subsurface delaminations.

Between pad #1 and the elbow indications were observed which are consistent with wrinkles in the composite material.

Additionally, just above the right corner of pad #1 is a small indication[#] consistent with those seen throughout both the upper and lower arms (see note on location #2).

Indication Sizes:

#1 – 0.9 in. wide x 0.6 in. high

#2 – 0.8 in. wide x 0.7 in. high

#3 – 0.32 in. long

Note: It was not possible to make measurements of the size of the wrinkles because of the large camera angle required to access this location.

Location #4 (Figure 10):

One indication was recorded between pad #10 and the elbow. This indication (although larger) is consistent with the small indications[#] seen throughout both arms (see note on location #2).

Indication Sizes:

#1 – 1.35 in. wide x 0.3 in. high

[#] Note: These small indications are seen throughout the upper and lower arm, even in areas where no impact is suspected, which may indicate that they are a result of the manufacture of the structure.

Locations #5 & #9 (Figure 12):

A number of significant indications were observed in these locations. First, a large vertical indication parallel and to the left of pad #4 was observed. This indication appears to extend quite deep into the material (at least through ½ the thickness) and also tends to spread parallel to the fibers. Again this is a region that does not allow good propagation of the heat flux and could be attributed to porosity, dry fibers (resin poor regions) or delaminations.

Another series of indications were recorded directly below pad #4. These indications do not appear to follow the fiber layup and also extend quite deep into the material.

Indication Sizes:

#1 – 0.8 in. wide x 0.5 in. high

#2 – 0.8 in. wide x 0.6 in. high

#3 – 0.5 in. wide x 0.8 in. high

#4 – 0.8 in. wide x 6.25 in. high

Location #6 (Figure 13):

Four indications were recorded between pad #2 and pad #1. These indications are consistent with the small indications[#] seen throughout both arms (see note on location #2).

Indication Sizes:

#1 – 1.7 in. wide x 0.3 in. high

#2 – 0.8 in. wide x 0.3 in. high

#3 – 0.8 in. wide x 0.2 in. high

#4 – 0.4 in. wide x 0.3 in. high

Location #7 (Figure 9):

Between pad #9 and the shoulder indications were observed which are consistent with wrinkles in the composite material as seen in Location #3.

Indication Sizes:

#1 – 2.8 in. long

#2 – 3.8 in. long

Location #8 (Figure 14):

Between pads #7 & #8 a single indication was observed which is consistent with impact damage indications that have been observed in other composite materials. This indication is fairly localized on near the surface, but appears to grow in size deeper into the material.

Indication Sizes:

#1 – 2.2 in. wide x 0.6 in. high

Conclusions

While numerous indications were recorded in both the suspect locations and in other areas, it is extremely difficult to accurately interpret the results with out either a baseline inspection of the RMAS against which the current inspection can be compared. Appropriate standards to calibrate the inspection procedures and results are required.

Some indications are observed that could potentially indicate damage that resulted from the impact the RMAS sustained, but no absolute conclusions can be drawn given the inspection circumstances.

Certain areas (Locations 5, 8 and 9) showed indications unique enough to warrant further investigation of these with other techniques such as conventional and advanced ultrasound or x-ray.

Inspection Results by Location of Interest

The collage of images that follow are representative of the results obtained using the LaRC Thermal NDE technique. These images are only a subset of all the data obtained.

Upper Arm

Pad #6




Figure 6 -- Location #1 (No Indications Recorded)




Figure 7 -- Location #2




Figure 8 --Location #3




Figure 9 -- Location #7




Figure 10 -- Location #4




Figure 11 -- Pad #9 No Indications (Recorded for Reference)




Figure 12 -- Locations #5 & #9




Figure 13 -- Location #6




Figure 14 -- Location #8

References

1. K.E. Cramer, W.P. Winfree, E.R. Generazio, R. Bhatt and D.S. Fox, *Review of Progress in Quantitative Nondestructive Evaluation*, Vol. 12, ed. D.O. Thompson and D.E. Chimenti (Plenum Press, New York, 1993), p. 1305.
2. K.E. Cramer, P.A. Howell and H.I. Syed, *Proceedings SPIE - Thermosense XVII*, Vol. 2473, ed. S. A. Semanovich (SPIE, Bellingham, 1995), p. 226.

