N79-28139

PRESSURE DISTRIBUTIONS ON THREE DIFFERENT CRUCIFORM AFT-TAIL CONTROL SURFACE OF A WINGLESS MISSILE AT MACH 1.60, 2.36, AND 3.70 VOLUME II - CLIPPED DELTA TAIL

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION
WASHINGTON, DC

DEC 79

NASA Technical Memorandum 80097

Pressure Distributions on Three Different Cruciform Aft-Tail Control Surfaces of a Wingless Missile at Mach 1.60, 2.36, and 3.70

Volume II - Clipped Delta Tail

Milton Lamb, Wallace C. Sawyer,
Donald L. Wassum, and C. Donald Babb
Langley Research Center
Hampton, Virginia

1. Report No. NASA TM-80097	2. Government Accession No.	3. Recipient's Catalog No. N79-28139
4. Title and Subtitle PRESSURE DISTRIBUTIONS ON THREE DIFFERENT CRUCIFORM AFT-TAIL CONTROL SURFACES OF A WINGLESS MISSILE AT MACH 1.60, 2.36, AND 3.70 - VOLUME II - CLIPPED DELTA TAIL		5. Report Date August 1979
		6. Performing Organization Code
7. Author(s) Milton Lamb, Wallace C. Sawyer, Donald L. Wassum, and C. Donald Babb		8. Performing Organization Report No. L-12993
		10. Work Unit No. 505-11-23-03
9. Performing Organization Name and Address NASA Langley Research Center Hampton, VA 23665		11. Contract or Grant No.
		13. Type of Report and Period Covered Technical Memorandum
12. Sponsoring Agency Name and Address National Aeronautics and Space Administration Washington, DC 20546		14. Sponsoring Agency Code

15. Supplementary Notes

16. Abstract

The results of pressure distribution tests conducted in the Langley Unitary Plan wind tunnel are presented without analysis. The data were obtained for three sets of cruciform aft-tail control surfaces on a wingless missile model at Mach numbers of 1.60, 2.36, and 3.70 for angles of attack from -4° to 20°, model roll angles from 0° to 90°, and tail deflections of 0° and -15°. The test Reynolds number used was 6.6×10^6 per meter.

17. Key Words (Suggested by Author(s)) Pressure distributions Missile tails Supersonic speeds	18. Distribution Statement Unclassified - Unlimited Subject Category 02
19. Security Classif. (of this report) Unclassified	20. Security Classif. (of this page) Unclassified	21. No. of Pages 343

SUMMARY

The results of pressure distribution tests conducted in the Langley Unitary Plan wind tunnel are presented without analysis. The data were obtained for three sets of cruciform aft-tail control surfaces on a wingless missile model at Mach numbers of 1.60, 2.36, and 3.70 for angles of attack from -4° to 20°, model roll angles from 0° to 90°, and tail deflections of 0° and -15°. The test Reynolds number used was 6.6 × 10^6 per meter.

Volume I presents the pressure distributions for a trapezoidal tail; volume II, for a clipped delta tail; and volume III, for a cranked tail.

INTRODUCTION

Theoretical aerodynamicists are continually seeking consistent and accurate experimental data as an aid in the development and evaluation of computational methods. This study was made to provide a complete set of pressure distribution data on three sets of cruciform aft-tail control surfaces for a wingless missile model.

The investigation was conducted in the Langley Unitary Plan wind tunnel at Mach numbers of 1.60, 2.36, and 3.70 at a Reynolds number per meter of 6.6 × 10^6. The angle of attack was varied from -4° to 20°, model roll angle was varied from 0° to 90° in 22.5° increments, and tail deflections were 0° to -15°. The model consisted of a body of revolution with interchangeable aft-tail control surfaces. Three sets of model tails with identical root chords and span lengths were used. The pressures were measured on two adjacent tail surfaces (tails 1 and 2) using 91 pressure orifices per tail surface. The results are presented in plotted and tabular form.

SYMBOLS

b   exposed tail span, cm

C_p pressure coefficient, $\dfrac{P_l - P_\infty}{q_\infty}$ (Cp on tables and plots)

c   tail local chord, cm

M   free-stream Mach number

P_l local pressure, Pa

P_∞ free-stream static pressure, Pa

L-12993

q_∞ free-stream dynamic pressure, Pa

x longitudinal distance measured from local chord leading edge, cm

x/c fraction of local tail chord (see fig. 1)

y lateral distance measured from root chord, cm

y/b fraction of exposed tail span (see fig. 1)

α angle of attack, deg

δ pitch control deflection (negative with leading edge down; without subscripts, refers to all tails; with subscripts, only to those tails indicated), deg

ϕ model roll angle, positive clockwise when viewed from rear ($\phi = 0^\circ$ when tail no. 1 is in lower vertical position, see fig. 1), deg

Abbreviations:

L.S.   lower surface (see fig. 1)

U.S.   upper surface (see fig. 1)

APPARATUS AND TESTS

Tunnel

The tests were conducted in both the low and high Mach number test sections of the Langley Unitary Plan wind tunnel which is a variable-pressure, continuous-flow facility. The asymmetric sliding-block nozzles lead to the test sections and permit a continuous variation in Mach number from about 1.5 to 2.9 in the low Mach number test section and from about 2.3 to 4.7 in the high Mach number test section.

Model

The configuration consisted of a simple wingless aft-tail cruciform control missile model with three sets of interchangeable tail surfaces. The pressure tubes were integrally cast into the tail surfaces to permit a greater number of more closely spaced pressure orifices (91 per tail surface). Details of the model and pressure orifice locations are given in figures 1 and 2. The upper- and lower-surface orifices were serviced by the same pressure tube, and thus required the taping of one surface while the other surface was being

2

tested. The missile model was sting mounted from the rear on the main support system of the tunnel.

Test Conditions

Tests were conducted at the following test conditions:

Mach number	Stagnation temperature, K	Stagnation pressure, kPa	Reynolds number, m^{-1}
1.60	339	54.6	6.6×10^6
2.36	339	75.7	6.6
3.70	339	152.7	6.6

The dew-point temperature measured at stagnation pressures was maintained below 239 K to assure negligible condensation effects. In order to assure a turbulent boundary layer, all tests were conducted with a boundary-layer transition strip on the body 3.05 cm aft of the nose. At a Mach number of 1.60, the transition strip consisted of a 0.16-cm-wide strip of sprinkled No. 60 sand. For the other two Mach numbers, the strip was composed of single-spaced No. 40 sand.

Measurements

The angles of attack have been corrected for tunnel-flow misalinement. Pressures were measured by six scanning valves. All pressure coefficients were referenced to free-stream conditions. The accuracy of the scanning-valve system is within 1 percent of the gage range. When expressed as pressure coefficients C_p, 1 percent of the gage range is 0.030 at Mach 1.60, 0.016 at Mach 2.36, and 0.024 at Mach 3.70.

PRESENTATION OF RESULTS

Due to the large volume of data and for the convenience of the reader, the data are presented as three volumes as follows:

Volume I . . . . Trapezodial tail (planform A)
Volume II . . . . Clipped delta tail (planform B)
Volume III . . . . Cranked tail (planform C)

The pressure coefficients are given in tables I to XXIV, and, to aid the reader, an index of tables follows:

Table	M	ϕ, deg	$\delta_{1,3}$, deg	$\delta_{2,4}$, deg
I	1.60	0	0	0
II	↓	22.5		
III		45		
IV		67.5		
V	↓	90		
VI	2.36	0		
VII		22.5		
VIII		45		
IX		67.5		
X	↓	90		
XI	3.70	0		
XII		22.5		
XIII		45		
XIV		67.5		
XV	↓	90		↓
XVI	1.60	0		−15
XVII	2.36			
XVIII	3.70	↓	↓	
XIX	1.60	45	−15	
XX	2.36			
XXI	3.70	↓		↓
XXII	1.60	90		0
XXIII	2.36			
XXIV	3.70	↓	↓	↓

Only a limited amount of machine-plotted data are presented to show trends, but all data are presented in tabular form. The plotted data are presented in the following figures:

TABLE I.- PRESSURE COEFFICIENTS, φ = 0°, δ = 0°, M = 1.60

(a) α = -3.35°

TAIL 1

	Cp at y/b of											
	0.02		0.22		0.44		0.56		0.67		0.83	0.98
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S. L.S.	U.S. L.S.

TAIL 1

TAIL 2

	Cp at y/b of											
	0.02		0.22		0.44		0.56		0.67		0.83	0.98
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S. L.S.	U.S. L.S.

TAIL 2

6

TABLE I. - CONTINUED
(b) α = -1.35°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.55 U.S.	0.55 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1426	.2025	.3453	.4018	.3825	.5809	.4553	.5315	.5850	.5622				.5809
.10	.1380	.1322	.2959	.4053	.3830				.5845	.5840	.4475	.6106	.5502	.5194
.15	.1401	.1896	.2665	.3610	.2948	.4593		.4416	.3459	.5236				.4241
.20		.1699	.2382	.3373	.3230	.3260	.3615		.3380	.4825	.5818	.5074	.3642	.3657
.25					.2907		.3057		.3560	.4356	.5883	.4504	.2950	.2716
.30	.0297	-.0662	-.0932	-.0967	-.0863	-.0854	-.0955	-.2949	-.3251	-.4006	.3251	.1511	.2050	
.40	.0660	-.1109	-.0372	-.0088	-.0974	-.0855	-.0650	-.0838	-.0810	-.0728	.2914	.3529		.1299
.50					-.0982	-.0760	-.0950	-.074C			.0524	.0936		
.60	.0133	.0173	.2209	.0377	-.0800	-.0633	-.1240	-.1475	-.3109	-.3051	.3258	.3055	-.2943	-.3267
.70	-.2208	-.1788	-.2291	-.2294			-.3084	-.3045	-.3217	-.3152	-.3265	-.3243	-.2437	-.3365
.80	-.1918	-.1954	-.2614	-.2636	-.2457	-.2477	-.2815	-.2813	-.3157	-.3037	-.2859	-.2955	-.2512	-.2783
.90	-.1916	-.2009	-.2676	-.2630				-.2666	-.2985	-.2823	-.2968	-.2923	-.2570	-.2761

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2482	.1778	.4653	.3296			.6597	.4452			.5625	.4282	.6390	.3722
.10	.2499	.1571					.5568	.4338	.5678	.4324			.5005	.3939
.15					.4713	.3542	.5146	.3966	.5427	.4236	.6085	.3686	.4323	.3490
.20	.2118	.1302					.4747	.3672	.4841	.3964	.5104	.4038	.3715	.3044
.25	-.0663	-.0474	.0413	.1868	.3924	.3046	.4409	.3417	.4677	.3692	.4822	.3862	.3356	.2659
.30			.0899	.1201			.3953	.2862	.4377	.3354	.3672	.2833	.3058	.2439
.40	.1269	.0504											.2632	.2053
.50	.1098	-.0027	.1065	.0024	-.0561	-.1023	-.0565	-.0963	-.0619	-.0793	-.0899	-.1084	-.1557	.0819
.60					-.0223	-.1179	-.0569	-.1093	-.0657	-.1015	-.663	-.2027	-.3130	-.2972
.70	-.1365	-.1985	-.1875	-.2467	-.2080	-.3092	-.2026	-.2589	-.0637	-.1047	-.3285	-.3301	-.3366	-.2571
.80	-.1547	-.1947	-.2200	-.2737	-.2141	-.2788	-.2922	-.2828	-.2837	-.3073	-.3052	-.2924	-.2709	-.3103
.95	-.2342	-.2557	-.2342	-.2557	-.2151	-.2613	-.2636	-.2672	-.2907	-.2689	-.2884	-.2912	-.2718	-.3021

TAIL 2

7

TABLE L - CONTINUED
(c) a = 0.66°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1638	.2384	.3583	.4092	.3684	.5948	.3759	.6475	.2878	.5737	.4666	.6413	.4977	.5926
.10	.1531	.2126	.3096	.4232	.3892	.5180			.3921	.6077				.5561
.15	.1519	.2169	.2737	.3793	.3517	.4739			.3623	.5444			.3671	.4338
.20	.1454	.2021	.2494	.3507	.3334	.4385	.3848	.4648	.3766	.4985	.3900	.5268	.3297	.3769
.25					.3067	.4020	.3486	.4333	.3740	.4488	.3552	.5115	.2918	.3278
.30	-.0275	.0507	-.0806	-.0856	-.0772	-.0771	-.0861	-.0685	.3448	.4191	.3485	.4671	.2509	.2886
.40	.0775	.1398	-.0348	-.0153	-.0934	-.0784	-.0894	-.0776	-.0652	-.0632	.3066	.3720	.2.7.	.242.
.50					-.0924	-.0708	-.0871	-.0666			-.0975	-.0846	.1625	.1532
.60			.0506	.0637	-.0687	-.06:2	-.205	-.1439	-.3096	-.2996	-.1280	-.1363	-.2820	-.317.
.70	.0483	.0474	-.2032	-.2144			-.3079	-.3021	-.3191	-.3122	-.3256	-.3266	-.2552	-.3148
.80	-.2037	-.1525	-.2398	-.2409	-.2356	-.2358	-.3010	-.2742	-.3079	-.2988	-.3203	-.3196	-.2531	-.2777
.90	-.1743	-.1784	-.2476	-.2419			-.2758	-.2612	-.2848	-.2785	-.2919	-.2922	-.2774	-.2794
.95	-.1744	-.1860									-.2878	-.2883	-.2810	-.2940

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1783	.2254	.3324	.4700			.4379	.6005		.5424	.4171	.6509	.3899	.5233
.10	.1841	.2139					.4705	.5327	.4749	.5424			.4191	.4671
.15					.3894	.4419	.4280	.4876	.4474	.5237	.5374	.5363	.3729	.4001
.20	.1519	.1868	.0084	.2504	.3250	.3760	.3961	.4515	.4094	.4859	.4328	.4849	.3294	.3432
.25	-.0284	-.0134	-.1224	-.0858			.3694	.4131	.3924	.4471	.4153	.4556	.3019	.2962
.30							.3379	.3458	.3715	.4033	.3288	.3225	.2770	.2664
.40	-.0578	.1317			-.0937	-.0633	-.0910	-.0583	-.0829	-.05:0	-.1044	-.0905	.2444	.2158
.50	.0546	.0459	.0369	.0745	-.0985	-.0660	-.0964	-.0693	-.0971	-.0679	-.1832	-.1873	-.1542	-.0761
.60					-.2838	-.263.	-.2336	-.2287	-.0974	-.0671	-.3405	-.3273	-.3125	-.3021
.70							-.3207	-.2980	-.3066	-.2826	-.3061	-.2967	-.3194	-.2655
.80	-.1643	-.1788	-.2216	-.2123	-.2665	-.2479	-.2985	-.2749	.2811	-.2712	-.2942	-.2824		
.90	-.1744	-.1715	-.2485	-.2411	-.2550	-.2294	-.2800	-.2595	-.2860	-.2721	-.2959	-.2856	-.3011	-.2671
.95			-.2468	-.2346									-.2792	-.2603

8

TABLE I.- CONTINUED
(d) α = 2.57°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1832	.2767	.3558	.4170	.3572	.6258	.3624	.6691	.2866	.5935				.5844
.10	.1650	.2253	.3189	.4410	.4036	.5378			.3946	.6309	.4835	.6642	.4051	.5710
.15	.1510	.2325	.2817	.3969	.3645	.4930			.3772	.5628			.3708	.4462
.20	.1504	.2245	.2528	.3504	.3440	.4503	.3955	.4831	.3919	.5152	.3978	.5497	.3423	.3925
.25					.3149	.4150	.3573	.4540	.3915	.4698	.3770	.5327	.3062	.3457
.30	-.0031	.0092	-.0840	-.0844	-.0736	-.0706	-.0789	-.0535	.3607	.4453	.3678	.4862	.2756	.3058
.40	.0775	.1621	-.0416	-.0264	-.0958	-.0747	-.0840	-.0704	.3552	-.0489	.3169	.3839	.2400	.2682
.50					-.0958	-.0708	-.0847	-.0625			-.0904	-.0785	.1670	.1794
.60	.0889	.0893	.0943	.0973	-.0690	-.0662	-.1207	-.1380	-.3068	-.2979	-.1280	-.1329	.2833	.3052
.70	-.1862	-.1210	-.1754	-.1907			-.3123	-.3005	-.3205	-.3127	-.3250	-.3244	-.2626	-.2860
.80	-.1558	-.1575	-.2197	-.2155	-.2235	-.2251	-.2974	-.2718	-.3054	-.2938	-.3177	-.3159	-.2626	-.2795
.90	-.1560	-.1643	-.2284	-.2210			-.2733	-.2586	-.2844	-.2769	-.2892	-.2907	-.3015	-.2890
.95											-.2863	-.2865	-.3103	-.3022

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1187	.2830	.2031	.5715			.1714	.7025		.6390	.1475	.7642	.0997	.6194
.10	.1267	.2779					.3307	.6256	.3020	.6070			.2396	.5427
.15					.2848	.5248	.3201	.5718	.3255		.4140	.6016	.2715	.4502
.20	.1089	.2553	-.0349	.3055			.3107	.5251	.3238	.5584			.2942	.3792
.25	-.0569	.0198	-.1502	-.0515	.2480	.4401	.2937	.4783	.3158	.5094	.3447	.5475	.2813	.3182
.30							.2702	.3958	.2968	.4549	.3306	.5059	.2622	.2791
.40	.0260	.2063							-.1100	-.0296	.2722	.3512	.2344	.2155
.50			-.0320	.424	-.1311	-.0218	-.1258	-.0228	-.1293	-.0354	-.1273	-.0703	.1475	.0708
.60	-.0126	.1002					-.1348	-.0283	-.1328	-.0290	-.2015	-.1657	-.3135	-.3063
.70					-.1428	-.0019	-.2588	-.1969	-.3271	-.2577	-.3477	-.3090	-.2647	-.2973
.80	-.1900	-.1614	-.2638	-.1866	-.3286	-.2025	-.3417	-.2633			-.3122	-.3202		
.90	-.1797	-.1542	-.2789	-.2137	-.3032	-.1964	-.3038	-.2482	-.2930	-.2798	-.3057	-.3080	-.3491	-.3593
.95			-.2530	-.2138	-.2668	-.1855	-.2845	-.2417	-.2986	-.2969	-.3047	-.2933	-.3481	-.3517

TABLE I.- CONTINUED
(a) α = 4.66°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2011	.3116	.3646	.4231	.3723	.6563	.3601	.6904	.2924	.6046	.4917	.6821	.3038	.5877
.10	.1808	.2417	.3302	.4627	.4183	.5620			.4015	.6510			.3624	.5854
.15	.1569	.2466	.2923	.4132	.3861	.5114	.4099	.5025	.3568	.5767	.3994	.5714	.3594	.4617
.20	.1541	.2417	.2609	.3680	.3639	.4703	.3657	.4696	.4087	.5294	.3970	.5499	.3275	.4070
.25					.3272	.4316			.4077	.4919	.3861	.5006	.2985	.3657
.30	-.0079	-.0106	-.0948	-.0888					.3736	.4675	.3307	.3942	.2622	.3299
.40	.0751	.1605	-.0600	-.0429	-.0705	-.0619	-.0710	-.0529	-.0465	-.0329	-.0800	-.0759	.2149	.2906
.50					-.0965	-.0699	-.0786	-.0615			-.1236	-.1307	.2149	.2023
.60	.1340	.1305	.1518	.1320	-.0973	-.0698	-.0807	-.0568	-.3011	-.2970	-.3201	-.3265	.2009	.2531
.70	.1641	.0960	.1458	.1645	-.0758	-.0705	-.1198	-.1344	-.3191	-.3135	-.3142	-.3085	.2556	.2763
.80	.1287	.1339	.2018	.1969	-.2116	-.2291	-.3145	-.3006	-.2989	-.2855	-.2859	-.2866	.3213	.2962
.90	.1259	.1366	.2058	.2026			-.2934	-.2702	-.2816	-.2737	-.2822	-.2834	.3323	.3095
.95							-.2712	-.2538						

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0608	.3529	.0777	.6615			.0358	.7891		.7159	-.0113	.8507	-.0387	.6376
.10	.0704	.3556			.1623	.5986	.1388	.7091	.1413	.6746	.2591	.6769	.0927	.5092
.15							.1865	.6471	.1715	.6175			.1409	.5010
.20	.0723	.3442	-.0759	.3573	.1546	.4936	.1935	.5899	.1817	.5613	.2105	.5993	.1629	.4227
.25	-.0870	.0636	-.1775	-.0172			.1960	.5313	.2029	.4979	.2169	.5483	.1657	.3557
.30		.2889					.1815	.4329	.2083		.1909	.3768	.1715	.3110
.40	-.0021				-.1685	.0302	-.1688	.0189	-.1447	-.0091	-.1629	-.0481	.1867	.2337
.50	-.0221	.1621	-.0836	.2136	-.1814	-.1171	-.1754	-.0256	-.1698	-.0025	-.2266	-.1390	-.1267	-.0702
.60					-.3530	-.1289	-.2868	-.1464	-.1756	-.0105	-.3554	-.2892	-.3125	-.3120
.70					-.3165	-.1510	-.3519	-.1967	-.3522	-.2308	-.3224	-.2965	-.2713	-.3146
.80	-.2073	-.1408	-.2906	-.1644	-.2710	-.1587	-.3181	-.1689	-.3091	-.2377	-.3153	-.2976	-.3455	-.2416
.90	-.1967	-.1336	-.2993	-.1874			-.2875	-.1620	-.3078	-.2488	-.3126	-.2957	-.3493	-.2344
.95			-.2433	-.1912										

TABLE II.- CONTINUED
(f) α = 6.65°

TAIL 1

x/c	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.2151	.3419	.3705	.4372	.3764	.6832	.3683	.7111	.2632	.6069				.5772
.10	.1957	.2666	.3374	.4890	.4409	.5833			.4025	.6711	.4889	.6986	.2360	.6013
.15	.1681	.2704	.3036	.4351	.4039	.5283	.4170		.4058	.5901	.4013	.5915	.3587	.4764
.20	.1589	.2602	.2752	.3842	.3695	.4833	.4170	.5188	.4182	.5443	.4101	.5727	.3665	.4238
.25					.3321	.4412	.3757	.4853	.4151	.5150	.3874	.5124	.3435	.3853
.30	-.0158	-.0089	-.1016	-.0892	-.0669	-.0563	-.0656	-.0424	.3825	.4895	.3408	.4019	.3166	.3486
.40	-.0698	.1553	-.0693	-.0550	-.0958	-.0615	-.0726	-.0505	-.0358	-.0251	-.0677	-.0752	-.2855	-.3128
.50					-.0926	-.0644	-.0726	-.0523			-.1136	-.1292	-.2462	-.2281
.60					-.0721	-.0695	-.0726	-.0523					-.2630	-.2857
.70	.1748	.1676	.1931	.1697	-.0721	-.0695	-.1155	-.1347	-.2927	-.2968	-.3137	-.3247	-.1918	-.2283
.80	-.1305	-.0767	-.1221	-.1435			-.3092	-.2984	-.3160	-.3119	-.3087	-.2999	-.2104	-.2639
.90	-.1007	-.1063	-.1840	-.1790	-.2137	-.2360	-.2870	-.2602	-.2890	-.2764	-.2803	-.2825	-.3308	-.3062
.95	-.0916	-.1019	-.1856	-.1802			-.2678	-.2517	-.2760	-.2676	-.2760	-.2798	-.3417	-.3191

TAIL 2

x/c	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	-.0123	.4109	-.0400	.7473			-.0742	.8609			-.1154	.9079	-.1291	.7508
.10	.0073	.4282					.0022	.7748	.0272	.7780			-.0151	.6649
.15					.0487	.6639	-.0503	.7045	.0480	.7294	.1186	.7329	.0495	.5479
.20	-.0380	.4363	-.1408	.3969	.0631	.5353	.0811	.6392	.0574	.6666	.0704	.6403	.0833	.4667
.25	-.1081	.1209	-.2210	.0148			.0914	.5721	.0842	.6027	.0857	.5851	.0978	.3929
.30							.0849	.4641	.0899	.5314	.0883	.4054	.1016	.3452
.40	-.0201	.3800			-.2256	.1019	-.2200	-.0691	-.1920	.0108	-.2065	-.0217	-.1013	.2598
.50	-.0505	.2179	-.1057	.2656			-.2303	-.1005	-.2178	.0368	-.2541	-.1062	-.0600	-.0833
.60					-.2203	.2499	-.3285	-.0610	-.2242	.0630	-.3526	-.2614	-.3360	-.3152
.70					-.2203	-.2499	-.3466	-.1068	-.3740	-.1893	-.3526	-.2614	-.3116	-.3018
.80	-.2205	-.1153	-.3083	-.1458	-.3659	-.0971	-.3466	-.1068			-.3365	-.2675		
.90	-.2219	-.1097	-.2928	-.1522	-.3259	-.1333	-.3268	-.1150	-.3209	-.1543	-.3265	-.2676	-.3736	-.2559
.95	-.1995		-.1955	-.1632	-.2763	-.1393	-.2996	-.1240	-.3158	-.1541	-.3172	-.2709	-.3558	-.2282

TABLE I.- CONTINUED
(g) α = 8.65°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2308	.3746	.3862	.4637	.3726	.7080	.3566	.7250	.2944	.6159				.5786
.10	.2110	.2916	.3597	.5182	.4471	.6024			.3391	.6941			.2006	.6154
.15	.1799	.2949	.3253	.4514	.4064	.5459			.4113	.6127	.4764	.7193	.3620	.4915
.20	.1695	.2800	.2897	.3971	.3738	.5015	.4179	.5472	.4257	.5720	.4098	.6114	.3758	.4381
.25					.3339	.4588	.3746	.5108	.4245	.5424	.4232	.5824	.3653	.4028
.30	-.0121	-.0045							.3972	.5093	.4123	.5225	.3503	.3677
.40	.0711	.1545	-.1025	-.0845	-.0657	-.0471	-.0535	-.0307	.3225	-.0232	.3603	.4135	.2793	.3363
.50			-.0593	-.0537	-.0877	-.0565	-.0578	-.0457			-.0517	-.0716	.2797	.2542
.60					-.0769	-.0588	-.0611	-.0467			-.1017	-.1224	.2524	.2739
.70	.2164	.2032	.2271	.1993	-.0582	-.0669	-.1102	-.1314	-.2918	-.2940	-.3091	-.3205	-.1877	-.2041
.80	-.1188	-.0542	-.1024	-.1237			-.3032	-.2939	-.3128	-.3079	-.3019	-.2952	-.2266	-.2541
.90	-.0653	-.0722	-.1649	-.1541			-.2808	-.2539	-.2829	-.2691	-.2730	-.2783	-.3403	-.3148
.95	-.0581	-.0646	-.1659	-.1514	-.2123	-.2380	-.2629	-.2465	-.2725	-.2620	-.2592	-.2767	-.3466	-.3254

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.1032	.4601	-.1432	.8320			-.1680	.9171					-.1960	.8000
.10	-.0444	.4994					-.1091	.8316	-.0714	.8322	-.2057	.9604	-.1107	.7107
.15					-.0506	.7181	-.0580	.7570	-.0517	.7789	.0070	.7808	-.0491	.5874
.20	.0001	.5314					-.0311	.6857	-.0573	.7117			-.0087	.5053
.25	-.1350	.1876	-.2114	.4310	-.0366	.5750	-.0114	.6128	-.0276	.6432	-.0300	.6849	.0133	.4264
.30			-.2705	.0569			-.0112	.4954	-.0196	.5668	-.0202	.6257	-.0287	.3767
.40	-.0428	.4666							-.2533	.0361	-.0107	.4317	-.0332	.2865
.50							-.2707	.1471	-.2685	.0973	-.2347	.0066	-.0005	.1003
.60	-.0728	.2778	-.1440	.3185	-.2756	.1910	-.2801	.2164	-.2724	.1451	-.3089	-.0690	-.3712	-.3279
.70					-.2771	.3043	-.3630	-.0415	-.3396	-.1005	-.3506	-.2235	-.3551	-.3003
.80	-.2326	-.0865	-.3229	-.1189	-.3574	-.0691	-.3500	-.0714			-.3535	-.2219		
.90	-.2427	-.0813	-.2901	-.1163	-.3394	-.1122	-.3313	-.0856	-.3172	-.0888	-.3397	-.2071	-.4122	-.2732
.95			-.2921	-.1396	-.3028	-.1177	-.3160	-.0951	-.3209	-.1142	-.3288	-.2060	-.4016	-.2730

TAIL 2

TABLE I. - CONTINUED
(h) α = 10.68°

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	-.2521	.4090	.4121	.4875	.3842	.7368	.3572	.7517	.2401	.6419				.5684
.10	-.2322	.3171	.3707	.5444	.4517	.6264			.3994	.7150	.4765	.7357	.1890	.6327
.15	-.1922	.3123	.3287	.4664	.4176	.5695			.4350	.6330			.3910	.5077
.20	-.1719	.2908	.2885	.4155	.3900	.5230	.4332	.5687	.1559	.5951	.4444	.6276	.4075	.4568
.25					.3596	.4761	.3949	.5263	.1508	.5587	.4549	.5939	.3933	.3955
.30	-.0161	.0074					-.0347	-.0178	.1330	.5247	.4336	.5337	.3767	.3755
.40	.0912	.1645	-.0873	-.0795	-.0519	-.0408	-.0947	-.0378	-.2206	-.0147	.3718	.4234	.3451	.3601
.50			-.0419	-.0611	-.0735	-.0485	-.0553	-.0380			-.0450	-.0659	.3058	.2853
.60					-.0675	-.0503	-.1048	-.1263			-.0917	-.1162	.2392	.2535
.70	.2467	.2444	.2518	.2342	.2562	-.0605	-.2988	-.2856	.2926	.2930	-.3028	-.3155	-.1772	-.1857
.80	-.0890	-.0275	-.0854	-.1015			-.2760	-.2486	-.3058	-.2982	-.2954	-.2983	-.2329	-.2443
.90	-.0359	-.0365	-.1438	-.1272	-.2111	-.2386	-.2578	-.2364	-.2743	-.2595	-.2663	-.2721	-.3618	-.3222
.95	-.0213	-.0253	-.1378	-.1200					-.2711	-.2543	-.2623	-.2706	-.3512	-.3340

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	-.1854	.4961	-.2319	.9011			-.2486	.9654		.8801	-.2781	1.0025	-.2656	.8398
.10	-.0912	.5700					-.1976	.8788	-.1769	.8268			-.2138	.7494
.15					-.1439	.7671	-.1576	.8010	-.1438	.7599	-.0845	.8459	-.1525	.6241
.20	-.0424	.6243	-.2705	.4573	-.1207	.6123	-.1253	.7271	-.1449	.6871	-.1143	.7205	-.1034	.5388
.25	-.1611	.2519	-.3106	.1217			-.1100	.6485	-.1159	.6067	-.1079	.6586	-.0530	.4571
.30							-.1044	.5257	-.1073	.0735	-.1065	.4527	-.0383	.4073
.40	-.0743	.5585			-.3231	.4093	-.3179	.2574	-.3036	.1902	-.2997	.0451	-.0377	.3078
.50			-.1700	.3679			-.3246	.4353	-.3162	.3481	-.3409	-.0147	-.0629	.1157
.60	-.0908	.3319			-.3226	.3492	-.3811	.0639	-.3175	-.0056	-.3389	-.1457	-.3798	-.3254
.70			-.3347	-.0921	-.3627	-.0455	-.3560	-.0545	-.3304		-.3512	-.1109	-.3713	-.3189
.80	-.2418	-.0586	-.2839	-.0871	-.3479	-.0902	-.3276	-.0744	-.3133	-.0721	-.3512	-.1089	-.4429	-.2556
.90	-.2771	-.0435	-.1811	-.1118	-.3041	-.0947	-.3137	-.0858	-.3178	-.0953	-.3424	-.1203	-.4358	-.2499

TAIL 2

13

TABLE I.- CONTINUED
(I) a = 12.66°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2608	.4319	.4152	.5116	.4071	.7672	.3820	.7744	.2609	.6554				.5439
.10	.2395	.3417	.3830	.5678	.4813	.6495			.4198	.7384	.4995	.7546	.1918	.6472
.15	.1981	.3427	.3514	.4817	.4518	.5914			.4602	.6598			.4097	.5283
.20	.1800	.3133	.3150	.4283	.4184	.5434	.4508	.5931	.4761	.6192	.4669	.6931	.4223	.4815
.25					.3925	.4990	.4050	.5488	.4787	.5839	.4748	.6073	.4080	.4552
.30	-.0015	.0143							.4530	.5160	.4506	.5547	.3956	.4232
.40	-.1337	.1638	-.0728	-.0737	-.0507	-.0307	-.0230	-.0066	-.0225	-.0046	.3894	.4364	.3650	.3959
.50			-.0281	-.0556	-.0642	-.0371	-.0367	-.0292			-.0557	-.0551	.3253	.3133
.60					-.0569	-.0413	-.0495	-.0308			-.0961	-.1102	.2299	.2457
.70	.2816	.2863	.2845	.2620	-.0509	-.0551	-.0923	-.1210	-.2882	-.2811	-.3000	-.3102	-.1762	-.1710
.80	-.0565	-.0026	-.0673	-.0868			-.2941	-.2703	-.2977	-.2873	-.2924	-.2780	-.2528	-.2305
.90	-.0089	-.0066	-.1216	-.0971	-.2086	-.2341	-.2711	-.2423	-.2670	-.2525	-.2540	-.2650	-.3720	-.3316
.95	-.0159	-.0093	-.1036	-.0941			-.2514	-.2270	-.2630	-.2474	-.2597	-.2643	-.3552	-.3458

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.2734	.5190	-.3050	.9584			-.3228	1.0061			-.3346	1.0337	-.3265	.8695
.10	-.1519	.6315					-.2772	.9249	-.2739	.9280			-.2889	.7819
.15	-.0741				-.2208	.8086	-.2406	.8469	-.2183	.8714	-.1593	.8679	-.2353	.6555
.20	-.1816	.7007					-.2142	.7696	-.2063	.7994			-.1805	.5695
.25		.3160	-.3171	.4852	-.2023	.6445	-.1927	.6874	-.1880	.7221	-.1884	.7528	-.1269	.4858
.30	-.1069		-.3401	.2233			-.1785	.5571	-.1802	.6354	-.1813	.6868	-.123	.4352
.40		.6345							-.3446	.2225	-.1813	.4755	-.1011	.3335
.50	-.1095	.3755	-.1947	.4196	-.3637	.5088	-.3576	.5474	-.3583	.3834	-.3507	.1799	-.1211	.1382
.60							-.3628	.4685	-.3593	.4630	-.3334	.2131	-.375	.2953
.70					-.3434	.3847	-.3936	.0858	-.3488	-.0002	-.3285	-.0493	-.3619	-.2430
.80	-.2565	-.0213	-.3524	-.0394	-.3770	-.0278	-.3727	-.035	-.3257	-.0575	-.3348	-.0821	-.4072	-.1792
.90	-.2995	-.0009	-.2641	-.0580	-.3422	-.0678	-.3525	-.0505	-.3265	-.0817	-.3395	-.0946	-.4014	-.1939
.95			-.1930	-.0942	-.2902	-.0739	-.3290	-.0618			-.3378	-.1050		

TAIL 2

TABLE I. - CONTINUED

(β α = 16.66°)

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

15

TABLE I.- CONCLUDED
(k) α = 18.76°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.3381	.5363	.5153	.6322	.4927	.8603	.4363	.8666	.2990	.7418	.5052	.8045	.2109	5.170
.10	.3126	.4175	.4621	.6494	.5627	.7409			.4762	.8105			.4433	.6843
.15	.2715	.4197	.4235	.5530	.5136	.6756			.5293	.737			.4133	.5895
.20	.2486	.3821	.3835	.5065	.4888	.6756	.4942	.6670	.5416	.6940	.4918	.8883	.4343	.5772
.25					.4606	.5750	.4555	.6208	.5162	.6462			.4278	.5266
.30	.0605	.0807					.0071	.0223	.4909	.6000			.3232	.5039
.40	.2980	.2424	.0112	-.0312	-.0035	-.0019	-.0198	-.0050	.0100	-.0161	-.1250	-.1263	-.7203	-.4778
.50			-.0322	.0112	-.0302	-.0092	-.0276	-.0138			-.0518	-.0857	-.3855	-.3955
.60					-.0310	-.0167							-.1943	-.2051
.70	.3757	.4019	.3736	.3497	-.0310	-.0349	-.0807	-.1096	-.2382	-.1729	-.2583	-.2111	-.1807	-.1347
.80	-.0057	.0725	-.0459	-.0327			-.2463	-.1652	-.2040	-.1737	-.2294	-.2069	-.3735	-.1945
.90	.0758	.0676	-.0659	-.0363	-.1531	-.1569	-.1926	-.1488	-.1804	-.1583	-.2157	-.2127	-.3760	-.3381
.95	.1056	.0814	-.0143	-.0145			-.1375	-.1164	-.1469	-.1300	-.1755	-.1893	-.3682	-.344

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.3998	.3793	-.4557	1.0815			-.4604	1.1139	-.4504	1.0503	-.4449	1.1103	-.4413	.9474
.10	-.2158	.5764					-.4465	1.0557	-.4262	1.0052			-.4485	.8711
.15	-.1551	.8258			-.4093	.9430	-.4174	.9889	-.3966	.9428	-.3239	.9974	-.4403	.7605
.20	-.2259	.4891	-.4117	.6262	-.3755	.8080	-.3907	.9213	-.3709	.8760	-.3800	.8845	-.4122	.6789
.25			-.4188	.5704			-.3759	.8482	-.3578	.8009	-.3751	.825	-.3670	.5944
.30							-.3657	.7391					-.3461	.5526
.40	-.1961	.7988			-.4287	.6455	-.4358	.6432	-.4502	.5672	-.3568	.6348	-.3450	.4526
.50	-.1751	.5323	-.2782	.5717			-.4266	.6079	-.4382	.6163	-.3755	.5038	-.3522	.2687
.60									-.4215	.5826	-.3677	.3050	-.4616	-.1223
.70					-.4186	.5028	-.4197	.1481	-.4055	.0540	-.3676	-.0138	-.4571	-.1244
.80	-.2935	.0806	-.3893	.0388	-.4387	.0405	-.4039	.0328	-.3685	.0178	-.3725	-.004		
.90	-.3515	.0889	-.3510	-.0062	-.4031	.0255	-.3697	.0250	-.3634	-.0013	-.3635	-.0126	-.4392	-.1241
.95	-.3092	-.0505			-.3992	-.0267	-.3642	.0177			-.3721	-.0234	-.4225	-.1430

16

TABLE II.- PRESSURE COEFFICIENTS, φ = 22.5°, δ = 9°, M = 1.50
(a) α = -3.16°

Cp at y/b of

	0.02		0.22		0.44		0.56		0.67		0.33		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 1

Cp at y/b of

	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

TABLE II. - CONTINUED
(b) α = -1.25°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.02	.155	.862	.3951	.2707	.1233	.531	.4729	.5676	.3653	.947	.4894	.573		
.05	.555	.755	.3304	.3758	.3895	.4053			.1245	.5455		.3745	.3707	
.10	.575	.744	.2800	.3291	.3640	-.434			.3078	.4061			.2757	
.20	.435	.555	.2597	.3070	.3306	.3865	.3897	-.25	.3801	.4604	.1775	.1871	.2855	
.25		.0586			.3091	.3519	.3658	.3874	.3970	.1959	.3840	.3070	.2905	
.30	.3735		-.0895	-.1065	-.3750	-.3614	-.0785	-.0774	.3659	.3813	.3725	.3935	.2485	
.40	.0768	.0850	-.0203	-.0315	-.3819	-.364.	-.0792	-.0903	.0644	-.0702	.3214	.3615	.1775	
.50					-.0725	-.0841	-.0725	-.082.			.0840	.3600	.1675	
.60	.2341	-.0078	-.0534	-.0220	-.0491	-.0786	-.1099	-.1547	-.3019	-.3077	-.178	-.3363	-.2082	
.70	.2112	-.1841	-.2185	-.2337			-.2974	-.3093	-.3123	-.3182	-.3247	-.3139	-.3010	
.80	-.1904	-.1967	-.2501	-.2678	-.2249	-.2534	-.2913	-.2808	-.3094	-.3020	-.2826	-.2852	-.2514	
.90	-.1803	-.1978	-.2588	-.2643	-.2735	-.2708	-.3089	-.2752	-.2965	-.2835	-.2578			

Cp at y/b of

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.02	.2469	.1939	.4547	.3397			.6544	.4649		.1120	.5889	.572	.6345	.3931
.05	.2635	.1740					.3608	.4437	.57.7	.1350	.5119	.4683	.539	.4061
.10					.4729	.3660	.5.72	.4079	.5759	.4100	.5119		.4109	.3594
.20	.2228	.1369	.0438	.1950	.3960	.3126	.474	.3777	.4853	.3836	.5766	.4157	.3647	.3755
.25	-.3509	-.0438	-.0862	-.1148			.4415	.3505	.4725	.3502	.1880	.3918	.3525	.2764
.30	.1290	.0467					.4007	.2948	.4430	.3502	.3742	.2916	.3002	.2543
.40	.1157	.0048	.1112	.0041	-.0515	-.0985	-.0532	-.0899	-.2603	-.0718	.3850	-.1286	.2717	.0814
.50					-.0334	-.1115	-.0567	-.1035	-.2602	-.1003	-.1051	-.2265	.1652	.3011
.70	-.1289	-.1932	-.1814	-.2374	-.214.	-.3045	-.2012	-.2531	-.2810	-.3052	-.3281	-.3287	-.3114	-.3011
.80	-.1492	-.1910	-.2145	-.2647	-.2089	-.2750	-.2930	-.2792	-.2822	-.2663	-.3039	-.2863	-.3363	-.3054
.90			-.2279	-.2470	-.2089	-.259.	-.2819	-.2652	-.2825	-.2752	-.2955	-.2765	-.2707	-.3.38
.95							-.2864	-.2639	-.2767		-.2845	-.2920	-.27.7	-.3055

18

TABLE II. - CONTINUED
(c) α = 0.78°

Cp at y/b of

TAIL 1

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.622	.2379	.3573	.4327	.3533	.5847	.3479	.6352	.2567	.5704	.4393	.6439	.4634	.6037
.10	.513	.2123	.3144	.3241	.3743	.5107			.3864	.6043			.3517	.5647
.15	.534	.2170	.2763	.384	.3284	.4656			.3508	.5597			.3336	.4402
.20	.465	.2024	.2482	.351	.3050	.4312	.3660	.4599	.3515	.5041	.3930	.5363	.2937	.3802
.25					.2812	.3935	.3716	.4361	.2677	.4556	.3607	.5233	.2535	.3293
.30	.2285	.2463							.3274	.4263	.3527	.4737	.2535	.2895
.40	.2575	.447	.0873	.0647	.0797	.0733	.0855	.0606	.4670	.3553	.372	.3752	.226	.2443
.50			.0531	.2081	.2921	.2722	.0855	.0715			.0055	.0801	.733	.56
.60					.2934	.0636	.08.3	.36.2			.1259	.1317	.2835	.3.24
.70	.3158	.3529	.0592	.0685	.0651	.05.1	.3169	.349	.3059	.2859	.324	.3250	.2555	.3077
.80	.2044	.488	.2043	.2044			.308	.2954	.3.86	.3070	.3186	.3163	.26.7	.2742
.90	.722	.760	.2357	.2350	.239	.2305	.3018	.2708	.3076	.3026	.2903	.2883	.2817	.2778
.95	.718	.1839	.2474	.2381			.2752	.2560	.2841	.2829	.2868	.2934	.2860	.29.5

TAIL 1

Cp at y/b of

TAIL 2

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.736	.2235	.3315	.4352			.44.0	.5909	.4763	.5407	.4340	.6534	.4374	.5302
.10	.519	.2117					.4752	.5329	.4527	.5222			.342	.4722
.15	.558	.846			.3865	.4408	.4252	.4866	.4130	.4852	.5025	.5283	.384	.4013
.20	.52.1	.2123	.0114	.2516	.3276	.3743	.3978	.4481	.3878	.4478	.4384	.4858	.336	.3448
.25			.1193	.0853			.3731	.4128	.3756	.4056	.3203	.4586	.2939	.3502
.30	.5603	.259					.34.6	.3460			.3354	.3220	.2522	.2853
.40	.55.1	.0355	.0358	.3704	.09.5	.0639	.0878	.0570	.0780	.3489	.3097	.060	.3552	.71
.50							.0648	.0675	.3638	.0673	.2997	.055	.3037	.3052
.60	.6.5	.793	.2215	.2141	.0975	.0632	.2315	.2271	.2958	.0656	.1707	.2856	.3352	.2772
.70	.739	.735	.2472	.2385	.2859	.2670	.3203	.2965	.3053	.28.8	.3356	.3252		
.80					.2665	.2457	.2962	.2758			.3055	.2952		
.90			.2463	.2313	.2558	.2278	.2779	.2604	.2733	.2749	.2651	.28.9	.2957	.263
.95									.2966	.2731	.2943	.2736	.278	.2333

TAIL 2

19

TABLE ... CONTINUED
(d) α = 2.?°

Cp at y/b of

TAIL 1

x/c	0.02		0.22		0.4		0.56		0.67		0.83		0.99	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

20

TABLE II. - CONTINUED
(e) α = 4.75°

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1339	.3756	.2389	.5630	.1832	.7009	.1696	.7656	.271b	.7277	.2878		.2737	.7347
.10	.1225	.3103	.2318	.5308	.2260	.6238			.2572	.7143		.7481	.2608	.6362
.15	.0610	.3019	.2212	.4797	.2718	.5703							.2308	.5017
.20	.1035	.3072	.1940	.4233	.2601	.5260	.3123	.5673	.3133	.5985	.2875	.3355	.2688	.4417
.25					.2415	.477	.2954	.528.	.3222	.5579	.2613	.6028	.2763	.3808
.30	.3655	.6042							.990	.5157	.3232	.5172	.3670	.3772
.40	.3164	.2365	.1378	.0427	.1014	.0342	.1051	.0250	.1762	.0186	.2808	.4201	.2461	.2893
.50			.1094	.0351	.1225	.0343	.1085	.0293			.0453	.0620	.2088	.1949
.60					.1316	.0257	.084	.0209			.385		.2813	
.70	.0844	.1557	.0715	.1917	.1252	.3061	.1453	.1002	.3173	.2779	.3261	.3126	.2212	.2915
.80	.1819	.0697	.1569	.1382			.3333	.2746	.3333	.2920	.3092	.3160	.2479	.263
.90	.1449	.1206	.2161	.1773	.2771	.1510	.2853	.2553	.2945	.2968	.2901	.2832	.3404	.2765
.95	.1378	.131.	.2278	.1840			.2664	.2387	.2860	.2815	.2823	.2755	.2544	.2813

TAIL 1

TAIL 2

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0760	.2676	.0895	.6250			.044.	.7533			.0000	.8183	.0217	.6679
.10	.0855	.2849			.1703	.5705	.1511	.6764	.1509	.6856			.0936	.5833
.15							.2099	.6181	.1899	.5468	.2725	.6557	.464	.4785
.20	.0505	.278.	.0942	.3364	.1692	.4715	.2042	.5655	.2013	.5923			.1653	.397.
.25	.0339	.0508	.0952	.0250			.2358	.5077	.2112	.5373	.2299	.5768	.734	.3338
.30	.2135	.2372					.922	.4128	.2183	.4753	.2293	.5277	.769	.2895
.40	.0206	.095	.0159	.1839	.1692	.0175	.1633	.0084	.1435	.0189	.2651	.3606	.796	.2172
.50							.1749	.0166	.1695	.0105	.1581	.0560	.297	.2527
.60					.1818	.0953	.2877	.1555	.3489	.0023	.2291	.1445	.3175	.3383
.70	.1708	.1515	.2822	.1860	.3440	.1476	.3518	.2068	.3086	.2355	.3567	.2923	.2653	.3227
.90	.192.	.133	.3018	.2074	.3156	.1714	.3193	.1851	.3086	.2437	.3224	.2997	.2216	.2418
.95	.1378		.2507	.2051	.2784	.1744	.2885	.187	.3092	.2540	.3261	.2981	.3445	.231.
											.3086	.2926		

TAIL 2

TABLE II.- CONTINUED
(f) α = 5.48°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05								.3351						.7862
.10										.7000				.5105
.15											.2718			
.20														
.25														
.30		.3445												
.40		.2784												
.50		.2214	.3703	.2473			.1573	.2814	.3207	.2678	.3332	.3055		.2455
.70		.2359	.1593	.1195			.3383	.3576	.3314	.2895	.3068	.3762	.2611	.2459
.90	.1293	.2850	.1293	.1294	.2837		.2960	.2319	.2972	.2876	.2913	.2763	.36	.2555
.95	.1219	.2006	.2243	.1617		.1255	.2502	.2212	.294	.2742	.2613	.2587		.2761

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0339	.2769	-.0239	.6949			.0702	.8127	.0285	.734	-.1121	.8579	-.1244	.7199
.10	.0474	.3087					.0155	.7316	.0586	.6895	.235	.7632	-.0545	.6385
.15					.0574	.5253	.0637	.5850	.0586	.6895			-.0455	.5235
.20	.0332	.3291					.0915	.6025	.0733	.0317			.0713	.440
.25	.0405	.0845	-.253	.3729	.0692	.5080	.0975	.5398	.294	.5696	.0882	.6057	.0899	.3605
.30			.2679	.0542			.0908	.4344	.0493	.502	.533	.533	.0915	.3295
.50	.0036	.3362							-.857	.1005	.0639	.3760	.0650	.2356
.70	-.0436	.1654	-.0734	.221	-.2082	.0793	.212	.0521	-.2146	.0198	-.2615	.305	.057	.0622
.90						.487	-.266	.0795	-.2208	.0416	-.2618	.223	-.3372	.3245
.95	.2233	.1376	.2091	.172	.653	.1212	-.3163	.0898	-.2715	.2663	-.3381	.0625	-.3083	.300
1.0	.2263	.1362	.2863	.960	-.3256	.1605	-.3483	.1417	.3238	.1779	-.3250	.2719	-.3559	.2735
1.05	-.2416	.1006	-.2309	.1931	-.2840	.1867	-.2947	.1515	-.3157	.1801	-.3719	.2763	-.3387	.2512

TAIL 2

TABLE II.- CONTINUED
(g) α = 8.75°

Cp at y/b of

TAIL 1

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0886	.5316	.1468	.6374	.3540	.8491	.0999	.9046	-.0293	.9937				.8337
.10	.0874	.4417	.1550	.6507	.2257	.7514	-.1108		.1781	.8312	.2933		-.1753	.7035
.15	.0508	.4496	.1427	.5823	.2162	.5880	-.0553	.7769	.1688	.7552	.3004	.8470	-.081	.5793
.20	.0537	.4154	.1363	.5316	.2125	.6309	-.0265	.6376	.2347	.7018	.832		.2072	.605
.25					.1943	.5613	-.0055	.5670	.2574	.6175		.7218	.2273	.138
.30	-.0284	.0857					-.0047	.4534	.2543	.6809		.0785	.235	
.40	-.2478	.3221	-.1765	.0229	-.1308	.0050	-.1237	.3095	-.2413	.0399		.6008	.32	.3172
.50			-.1535	.1383	-.1520	.0110	-.1352	.0107	-.0290	.0266		.4636		
.60		.2086			-.1582	.0348	-.1332	.0198		.066		.048		
.70	.1189	.2722	.0471	.2965	-.1589	.0532	-.1737	.0699	-.3353	.2585	-.485	-.0993	-.2757	.2929
.80	.0564	.0023	-.0735	-.0764			-.3349	.2175	-.3251	.2734	-.3374	-.2967	-.2657	.2823
.90	-.103	.2481	-.2031	-.136	-.2796	-.022	-.2835	.1904	-.3006	.2715	-.3123	-.3033	-.3693	.2587
.95	-.0790	.0639	-.917	-.177			-.2476	.1582	-.2832	.2570	-.2958	-.2629	-.3663	.2703

TAIL 1

Cp at y/b of

TAIL 2

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0228	.2617	-.1239	.7482			-.1660	.8569			-.2080	.8905	-.2062	.782
.10	.0261	.2850					-.1108	.7769	-.0732	.7731	.3004		-.203	.6800
.15	.0073	.3656		.4040	-.0062	.6672	-.0553	.7055	-.0537	.7235		.7320	-.0553	.5588
.20	.0016	.2200	.0663	.0408	-.0313	.5344	-.0265	.6376	-.0462	.6582	.3251	.6433	-.0065	.4760
.25	.0025	.4385	-.0422				-.0055	.5670	-.0227	.5912	-.0153	.5895	-.0062	.4955
.30							-.0047	.4534	-.0146	.5153	-.0157	.4016	-.0295	.3572
.40	.0556	.2086	-.0872	.2504	-.1541	.1549	-.0656	.1059	-.2413	.0399	-.3573	.0052	-.2357	.2572
.50					-.1810	.2473	-.2743	.1657	-.2653	.0993	-.2513	-.0777	-.0059	.3331
.60	-.0449	.0029	-.3223	-.1575	-.3347	-.1135	-.3592	-.0368	-.2635	.1022	-.3093	-.2316	-.3652	.2213
.70	-.0262	-.2241	-.3006	-.778	-.3331	-.1480	-.3375	-.1081	-.3604	.382	-.3427	-.345	-.3321	.245
.80			-.2357	.788	-.2767	-.1518	-.3102	-.1309	-.3311	-.175	-.3121	-.260	-.381	.203
.90									-.3252	.375	-.3353	-.261	-.371	.323

TAIL 2

TABLE II.- CONTINUED
(h) α = 10.76°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0531	.6015	.1034	.7792	.0022	.9152	.0496	.9692	-.0688	.9672	.0680	.9554	-.0550	.8722
.10	.0538	.5180	.1250	.7167	.1886	.8135	-.2055	-.8843	-.1112	.8843	-.0594		-.0593	-.1763
.15	-.0215	.5143	-.1163	.6402	.1845	.7397	.1635	.7291	-.1378	.6037	-.0516	.7586	-.0663	-.0955
.20	-.0317	.4667	.1128	.5802	.1828	.6750	.2203	.7144	.2014	.7443	-.0510	.7166	-.1100	-.4645
.25					.670	.6015	-.2016	.5530	-.2213	.685	-.1890	-.3608		
.30	-.1402	.2358	-.1944	.0793	-.1496	.0240	-.1355	.0295	-.2108	.6252	-.1820	-.3904	-.0440	
.40	-.0685	.3722	-.1777	.2774	-.1718	.0444	-.1479	.0329	-.1938	-.0133	-.279	-.0022	-.1752	-.0522
.50					-.1726	.1049	-.1485	.0489			-.0612	-.0700	-.2854	-.0970
.60	-.1143	.3367	-.1225	.3650	-.1750	.2597	-.1932	-.0279	-.2440	-.2440	-.3112	-.2917	-.3663	-.1411
.70	-.1477	-.0367	-.2056	-.0397			-.3187	-.1719	-.3118	-.2523	-.3021	-.2719	-.3663	-.2351
.80	-.0894	-.0689	-.1893	-.0781			-.2809	-.1319	-.3023	-.2437	-.2935	-.2535	-.3863	-.2553
.90	-.0409	-.0243	-.1614	-.0857	-.2670	-.0708	-.2415	-.1156	-.2805	-.2425				

TAIL 1

Cp at y/b of

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0008	.2372	-.2037	.8011			-.2493	.8844			-.2708	.9255	-.2738	.7832
.10	-.0045	.3036					-.2055	.8030	-.1580	.7953	-.0653		-.2225	.7129
.15					-.1338	.7024	-.1635	.7291	-.1565	.7488	-.0653	.7748	-.1651	.5842
.20	-.0174	.3841	-.2072	.4373	-.1152	.5539	-.1295	.6567	-.1469	.6857	-.1221	.6572	-.1100	.4977
.25	-.0591	.1515	-.2588	.0796			-.1105	.5837	-.1207	.6233	-.147	.6112	-.0574	.3691
.30							-.1007	.4673	-.1021	.5427	-.1042	.418.	-.0441	.2703
.40	-.0205	.4658			-.2865	.2245	-.3126	.1874	-.3018	.0365	-.2855	.0253	-.0731	.0813
.50	-.0532	.2482	-.1095	.2782			-.3144	.3322	-.3118	.1347	-.3330	.0329	-.3502	.3332
.60					-.1886	.2849	-.3754	.0271	-.3135	.2087	-.3234	.1830	-.3976	.3272
.70	-.2515	-.0921	-.3196	-.1424	-.3401	-.0922	-.3630	.0840	-.3580	.0357	-.3354	.1608		
.80	-.2779	-.1023	-.2959	-.1555	-.3271	-.1244	-.3419	-.1045	-.3390	-.0922	-.3392	.1392	-.3665	-.2847
.90			-.2378	-.1626	-.2513	-.1303	-.2852	-.1120	-.3310	-.1157	-.3308	-.14:3	-.3813	-.2822

TAIL 2

TABLE II.- CONTINUED
(i) a = 12.76°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.57 U.S.	0.57 L.S.	0.33 U.S.	0.33 L.S.	0.98 U.S.	0.98 L.S.
		.6708	.0725	.6562				.0210						
		.5842												
		.5732	.0848	.6679	.1557									
		.5262	.0766	.6305										
	.1503	.1815					.1655	.7242						
		.4435	.2086	.1350	.1819	.0529		.6855						
			.1954	.3847	.3869									
		.4050	.396	.4451	.1921	.3535	.1642	.0102	.3469			.3035	
	.1354	.3725	.2662	.0152	.3553	.0717	.2113	.1122	.2026	.2230	.3053	.3634	
	.0742	.0294	.1702	.0517	.3330	.1040	.2582	.0553	.2821	.2070	.2869	.4315	
	.0126	.0150	.1318	.0576	.2444	.0352	.2350	.0696	.2595	.2077	.2855	.4054	

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.57 U.S.	0.57 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
	.1038		.2695	.8373			.3930	.8986			.3370	.9378	.3383	.8127
	.2703						.2793	.8261	.2671	.8329			.3027	.736
		.3758			.2685	.72·6	.2465	.7655	.2222	.7837	.425	.8001	.2465	.6452
	.1763		.2049	.4577	.1946	.565	.2175	.6852	.221	7·75			.2061	.525
	.511		.2572	.1265			.1659	.4833	.1917	.3550	.357	.3996		.1435
	.3832		.1416	.3084	.3·76	.3072	.3533	.3·48	.3529	.2·13	.302	.4322		
	.2542	.0747	.3299	.1243	.2142	.3742	.3458	.4021	.3615	.1.85	.3361	.0603	.3639	.3255
	.3832	.3037	.31·7	.1272	.3553	.0717	.3817	.0497	.3503	.8255	.3351	.0667		
			.313	.1462	.3330	.1043	.3217	.0855	.3567	.819	.357	.3·42		
					.2555		.2762	.0863	.336	.1034	.3252	.249		

TAIL 2

TABLE II.- CONTINUED
(u = 12.3°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0050	.8164		.0153	-.1188	.8667								
.10	-.0158	.1679			.0905	.8875								
.15	-.0070	.7443			.0887	.9059								
.20	-.0181	.7022		.7483		.9131								
.25					-.0915	.7255								
.30	-.1736	.5551												
.40	-.1157	.5435	-.2355	.3567	-.195	.5520	.805							
.50			-.2172	.5323	-.222	.335								
.60					-.2222	.561	-.666							
.70	.017	.5230	-.372	.551	-.228	.4777	-.2353		-.2987					
.80	-.379	.356	-.333	.5357			-.2222		-.2178					
.90	-.0681	.0804	-.2405	.0063	-.1946	-.0017	-.2012		-.2341					
.95	.0245	.0658	-.272	.0092			-.1856		-.2617					

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0129	.1363	-.3628	.8790			-.4291	.9212			-.4112	.9382	-.4089	.8328
.10	-.0314	.1845				.7618	-.4117	.8585	-.4165	.9564			-.4036	.7689
.15					-.3460		-.3795	.7910	-.3832	.9091	-.2389	.8317	-.4020	.6555
.20	-.0567	.2763	-.3198	.4802	-.3201	.6035	-.3545	.7479	-.3558	.7438	-.3418	.7306	-.3825	.5705
.25	-.1510	.1761	-.3117	.2243			-.3389	.6386	-.3366	.6753	-.3286	.5725	-.3557	.4878
.30							-.3272	.5104	-.3309	.5022	-.3228	.4972	-.3376	.4417
.40	-.0979	.5244			-.3430	.4588	-.4075	.4812	-.4237	.3632	-.4314	.3549	-.2954	.3406
.50			-.1900	.3672			-.3582	.4465	-.4383	.1854	-.4129	.2346	-.2969	.1582
.60	-.0857	.3439			-.2667	.3576	-.4088	.0704	-.4278	.1493	-.4117	-.0453	-.3963	-.1850
.70			-.3474	-.0939	-.3726	-.0441	-.4267	-.0365	-.4329	-.0025	-.4123	-.0720	-.4035	-.1824
.80	-.2530	-.0290	-.3519	-.0916	-.3485	-.0795	-.3747	-.0542	-.3670	-.0513	-.3685	-.0857	-.4133	-.1937
.90	-.2940	-.0611	-.3032	-.1350	-.3102	-.0857	-.3252	-.0661	-.3826	-.0722	-.3823	-.0945	-.3926	-.2142
.95														

TABLE II.- CONCLUDED
(b) α = 18.76°

TAIL 1

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	-.0045	.9087	-.0405	1.0983	-.1473	1.1522	-.1013	1.1970	-.1836	1.1966				1.0456
.10	-.0109	.8815	.0083	.9840	-.0422	1.0404			-.0142	1.0817	-.0069	1.0698	-.1075	.8935
.15	-.0057	.8430	.0169	.8906	-.0523	.9478			.0264	.9910			-.0962	.7722
.20	-.0178	.7714	-.0094	.7978	-.0679	.8616	.1044	.8984	.0946	.9151	.0576	.9050	.1756	.7013
.25					-.0568	.7637	.0758	.8121	.1025	.8375	.0763	.8470	-.1699	.6462
.30	-.1793	.4563					-.1934	-.1375	.0934	.7580	.0942	.7535	-.1513	.5952
.40	-.1193	.6035	-.2493	.5604	-.2139	.2256	-.2033	.2215	-.1653	.0848	.0749	.5925	-.1330	.5309
.50			-.2458	.6119	-.2352	.4334	-.2027	.4158			-.1681	.0390	-.0583	.3949
.60	-.0997	.5592			-.2272	.5646	-.2262	.3078	-.2366	-.0652	-.1842	-.0030	-.3442	-.2117
.70	-.1193	.1579	-.1979	.5804	-.2282	.4960	-.1909	.0112	-.2201	-.0182	-.2912	-.2230	-.4337	-.1400
.80	-.0480	.0963	-.3218	.0502			-.1741	-.0038	-.1976	-.0219	-.3004	-.1	-.4275	-.0917
.90	.0478	.0822	-.2070	.0114	-.1778	.0066	-.1699	-.0098	-.1930	-.0305	-.2315	-.1682	-.4231	-.1005
.95			-.1179	.0091							-.1832	-.1604	-.4052	-.1382

TAIL 2

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	-.0109	.1308	-.3966	.9084			-.4590	.9162	-.4552	.8653	-.4379	.9263	-.4303	.8305
.10	-.0405	.1771					-.4557	.8636	-.4423	.8279	-.3147	.8438	-.4316	.7844
.15					-.4021	.7703	-.4366	.8009	-.4209	.7732			-.4306	.6814
.20	-.0688	.2437					-.4118	.7366	-.3966	.7114	-.4171	.7502	-.4302	.6017
.25	-.1681	.1654	-.3275	.5113	-.3586	.6117	-.3948	.6731	-.3842	.6414	-.4075	.7009	-.4206	.5198
.30			-.3130	.2877			-.3852	.5831	-.4548	.4366	-.3888	.5362	-.3943	.4786
.40	-.1122	.5192			-.3405	-.4740	-.4123	.5106	-.4441	.4919	-.4418	.4269	-.3554	.3830
.50	-.1019	.3737	-.1994	.3848	-.2989	.3771	-.3843	.4659	-.4312	.4660	-.4273	-.2569	-.3532	.2129
.60							-.4269	-.0822	-.4556	.0094	-.4285	-.0242	-.4108	-.1515
.70	-.2485	-.0081	-.3532	-.0825	-.3931	-.0322	-.4280	-.0303			-.4263	-.0467	-.4256	-.1580
.80	-.2917	-.0472	-.3471	-.0779	-.3606	-.0700	-.3761	-.0440	-.3974	-.0349	-.3914	-.0564	-.4385	-.1673
.90	-.2932	-.1203	-.2932	-.1203	-.3233	-.0773	-.3445	-.0552	-.3948	-.0566	-.3908	-.0670	-.3996	-.1891

TABLE III.- PRESSURE COEFFICIENTS, $\phi = 45°$, $\delta = 0°$, $M = 1.60$

(a) $\alpha = -3.27°$

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.57		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05		.241	.4546	.3305	.508	.2987	.588	.3065	.5125	.2652				
.10		.1161	.3826	.2564	.486	.3604							.5555	
.15		.1146	.3460	.2250	.4377	.3254			.467	.4004		.1100		
.20		.0970	.3171	.2034	.4007	.2918	.4509	.3592	.4600	.3765	.4962		.3602	.3502
.25					.361	.2630	.4075	.2665	.4933	.3355	.465	.3600	.3065	
.30	.0895	.0336							.4029	.3041	.4325	.2945	.2573	
.35	.1283	.3203	.0201	.1385	.048	.1289	.0531		.0485		.350	.2945		
.40			.0715	.0553	.0443	.1441	.0469				.350	.1380		
.50					.0042	.1401	.0337				.735			
.60	.0673	.0380	.0989	.0256	.0309	.1308	.0652		.2803	.3356	.1007	.1600	.3224	
.70	.2071	.2227	.2044	.2656			.2482		.2972	.3402	.3077	.3165	.3300	
.80	.1556	.2081	.2406	.3020	.1917	.2900	.2145		.2803	.3024	.3260	.3160	.2600	
.90	.1693	.1856	.2472	.2731			.2030		.2736	.2951	.2939	.3092	.2549	
.95													.2574	.2875

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.310	.847	.5376	.2850			.7174	.3403				.3092	.6835	.3587
.10	.3055	.1500					.5302		.6362	.4037	.6654		.5655	.3624
.15					.5205	.3328	.5798		.6608	.4047	.3076	.4506	.4793	.3666
.20	.2844	.1231					.5336	.3501	.5357	.3858			.4175	
.25	.0172	.0740	.0628	.1609	.4454	.2862	.4953	.3643	.5294	.3558	.5605	.3926	.3828	.2958
.30			.2672	.1353			.4471	.2040	.4903	.3278	.5265	.3751	.3537	.2732
.40	.1678	.0124									.3906	.2768	.3082	.2385
.50					.0274	.1169	.0294	.1057	.0554	.0640	.0731		.1900	.1208
.60	.1829	.0026	.1849	.0542			.0215	.1222	.0357	.1152	.1555	.2033	.2087	.2817
.75					.0294	.1410	.1838	.2518	.2756	.3120	.3154	.3363	.3151	.2255
.85	.0653	.1875	.1452	.2451	.546	.3114	.2695	.3055			.3012	.3044		
.90	.162	.1800	.1840	.2533	.1526	.2893	.2405	.2855	.2825	.2778	.2903	.2648	.2692	.3550
.95			.2007	.2351	.1728	.2782	.2299	.2537	.2467	.2874	.2753	.2981	.2675	.3654

TAIL 2

TABLE III. - CONTINUED
(b) α = -1.21°

TAIL 1

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1782	.1748	.4118	.3365	.4?78	.5?36	.5225	.5262	.4335	.46?0	.52?9	.5??	.3?75	.437?
.10	.17?5	.16?5	.3427	.3529	.3?90	.3?30			.4517	.5288			.29?5	.3?5?
.15	.751	.656	.3033	.3?1?	.3922	.3?39		.3924	.4046	.4822			.24?0	.39??
.20	.1500	.1482	.2767	.29?3	.3?12	.3?6?	.4?26		.4106	.447?	.4?5?	.45?5	.24?4	.3434
.25					.32?4	.3359	.3760	.3726	.4?23	.4?25	.4?10	.4?93	.24?4	.285?
.30	.0438	.0515		.204?	.24??	.999?	.0638	.0828	.2731	.3693	.3663	.4?99	.2512	.255?
.40	.0855	.0648		.1064	.0?15	.4?10	.0638	.0997	.0567	.0802	.3333	.0855	.25??	.2?0?
.50			.0108	.0541	.0490	.0850	.0534	.0982			.03?2	.0855	.5?2	.1?70
.60											.143	.03?3	.3?03	.3?90
.70	.0530	.0012	.0786	.0141	.0254	.0851	.096?	.1613	.2968	.3158	.3?81	.3353	.30?7	.32?7
.80	.2025	.1883	.2070	.2361	.2364	.297?	.2838	.3171	.3049	.3251	.3208	.3113	.2523	.2770
.90	.1683	.1962	.2408	.2585	.2634	.285?	.2735	.2914	.3036	.2970	.2990	.2988	.2503	.2858
.95	.1698	.1925	.2492	.2632	.2602	.2740			.2891	.2833	.2834	.287?	.2543	.2858

TAIL 2

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.2341	.2121	.4299	.3849			.6184	.5157	.5512	.4779	.5629	.531?	.537?	.434?
.10	.2374	.1910					.5464	.4778	.5292	.468?		.48?	.493?	.462?
.15	.2?4?	.1638			.4568	.3856	.5050	.4379	.5292	.468?	.5242	.49?	.?57	.38??
.20	.0691	.0347	.0363	.2049	.3845	.3394	.4639	.4060	.4692	.4391	.38.3		38.3	.3383
.25			.0980	.1064			.4330	.3747	.4614	.4070	.5036	.4?35	.353?	.305?
.30	.055	.0507					.3944	.3148	.4355	.3708	.4752	.42?.	.3253	.279?
.40				.0191	.05?8	.285?	.0609	.0801	.0585	.0620	.3572	.3052	.2839	.2353
.50	.1072	.0258	.1001		.0558	.1029	.0667	.0932	.0697	.0846	.0879	.0970	.782	.?51
.60					.2364	.2971	.2092	.2458	.0698	.0885	.1697	.1960	.2023	.2997
.70	.1325	.1823	.1831	.2264	.2?10	.2681	.3008	.2751	.2906	.2986	.3292	.3187	.3187	.2478
.80	.?33	.1785	.2136	.2528	.2412	.2538	.2894	.2584	.2736	.2550	.2987	.2835		
.90			.2258	.2353			.2690	.2570	.2758	.2672	.2856	.280?	.2865	.305?
.95											.2845	.2807	.2950	.300?

29

TABLE III. - CONTINUED
(c) α = 0.74°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1635	.2397	.3422	.4403	.3452	.5956	.3538	.6443	.2602	.5878				.6173
.10	.1536	.2156	.2968	.4335	.3799	.5228			.3941	.6113	.4318	.6487	.4681	.5719
.15	.1549	.2212	.2609	.3870	.3383	.4717			.3443	.5543			.3570	.4468
.20	.1379	.2054	.2360	.3535	.3165	.4363	.3660	.4605	.3532	.5110	.3927	.5435	.3335	.3850
.25					.2889	.3971	.3369	.4412	.3598	.4635	.3613	.5259	.2883	.3320
.30	.0223	.0455							.3328	.4343	.3515	.4779	.2576	.2918
.40	.0669	.1452	-.0910	-.0821	-.0833	-.0718	-.0902	-.0600	-.0669	-.0560	.3103	.3777	.2253	.2446
.50			-.0420	-.0104	-.0954	-.0715	-.0913	-.0709			-.0920	-.0804	.1699	.1556
.60					-.0911	-.0644	-.0834	-.0653			-.1254	-.1327	-.2860	-.3147
.70	.0451	.0946	.0590	.0735	-.0654	-.0529	-.1186	-.1368	-.3071	-.2968	-.3256	-.3261	-.2607	-.3141
.80	-.2025	-.1472	-.2082	-.2011			-.3068	-.2963	-.3193	-.3083	-.3193	-.3177	-.2628	-.2753
.90	-.1700	-.1732	-.2436	-.2312	-.2370	-.2242	-.3010	-.2697	-.3081	-.3015	-.2912	-.2894	-.2848	-.2796
.95	-.1702	-.1819	-.2494	-.2354			-.2750	-.2552	-.2848	-.2816	-.2874	-.2844	-.2887	-.2930

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1731	.2216	.3365	.4714			.4381	.6013			.4297	.6502	.4307	.5266
.10	.1850	.2145					.4758	.5355	.4747	.5449			.4384	.4739
.15					.3864	.4426	.4289	.4906	.4496	.5252	.5059	.5362	.3845	.4088
.20	.1560	.1885					.3979	.4536	.4110	.4868	.4366	.4879	.3444	.3515
.25	-.0185	-.0094	-.0098	.2439	.3259	.3769	.3733	.4149	.3971	.4491	.4178	.4574	.3167	.3078
.30			-.1213	-.0865			.3417	.3469	.3766	.4050	.3340	.3229	.2929	.2809
.40	.0601	.1140			-.0913	-.0641	-.0887	-.0585	-.0778	-.0506	-.0994	-.0873	.2580	.2260
.50							-.0955	-.0689	-.0950	-.0679	-.1792	-.1846	.1603	.0824
.60	.0499	.0393	.0327	.0723	-.0986	-.0676	-.2318	-.2281	-.0960	-.0667	-.3366	-.3252	-.3074	-.3012
.70							-.3203	-.2975	-.3055	-.2825	-.3060	-.2949	-.3236	-.2681
.80	-.1647	-.1804	-.2210	-.2168	-.2847	-.2699	-.2960	-.2734	-.2785	-.2702	-.2915	-.2806		
.90	-.1737	-.1737	-.2478	-.2423	-.2681	-.2488	-.2780	-.2581	-.2847	-.2704	-.2924	-.2783	-.3008	-.2679
.95			-.2466	-.2353	-.2543	-.2300							-.2808	-.2618

TABLE III. - CONTINUED
(d) α = 2.75°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1292	.3295	.2293	.5533	.1820	.6799	.1746	.7405	.0664	.7210	.2538			.7366
.10	.1155	.2871	.2235	.5118	.2982	.6003			.3966	.7201		.7248	.0534	.6253
.15	.1102	.2929	.2049	.4584	.2754	.5470			.3602	.7254			.2170	.4950
.20	.1142	.2788	.1839	.4119	.2624	.5041	.3053	.5402	.2933	.6758	.3141	.6151	.2581	.4225
.25					.2515	.4578	.2860	.5044	.3052	.7299	.2611	.5850	.2672	.3555
.30	-.0280	.0304							.2921	.7290	.2944	.5271	.2549	.3143
.40	.0285	-.2255	-.1089	-.0447	-.1099	-.0420	-.1114	-.0370	-.2820	-.1930	.2982	.4072	.2253	.2522
.50			-.0765	.0450	-.1233	-.0412	-.1174	-.0394	-.0862	.0333	-.1031	.0677	-.1864	.1661
.70	.0383	-.1195	.0279	.1443	-.1254	-.0307	-.1098	-.0322			-.1438	-.1160	-.2984	-.3290
.80	-.2040	-.1007	-.2044	-.1598	-.1057	.0032	-.1487	-.1060	-.3231	-.2798	-.3335	-.3149	-.2237	-.2660
.90	-.1861	-.1472	-.2480	-.1981			-.3277	-.2730	-.3354	-.2817	-.3146	-.3227	-.2559	-.2767
.95	-.1641	-.1622	-.2502	-.2064	-.2779	-.2739	-.3006	-.2520	-.3008	-.2865	-.2848	-.2913	-.3199	-.2767
							-.2770	-.2386	-.2803	-.2886	-.2929	-.2814	-.3399	-.2870

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1349	.2096	.2260	.5169			.2198	.6626			.2255	.7244	.1811	.5987
.10	.1426	.2144				.4866	.3821	.5906	.3478	.5984			.3048	.5210
.15	.1025	.1864			.3042		.3577	.5380	.3740	.5696	.4409	.5790	.3529	.4385
.20	-.0131	.0184	-.0375	.2732	.2584	.4108	.3303	.4943	.3415	.5230	.3676	.5248	.3286	.3553
.25			-.1521	-.0685			.3098	.4486	.3321	.4792	.3529	.4886	.2974	.3096
.30	.0342	.1703					.2808	.3697	.3136	.4286	.2875	.3381	.2637	.2724
.40													.2250	.2109
.50	.0054	.0544	-.0168	.1004	-.1253	-.0390	-.1186	-.0369	-.1073	-.0422	-.1170	-.0744	-.1324	.0613
.60							-.1285	-.0413	-.1239	-.0489	-.1948	-.1672	-.3166	-.3103
.70					-.1361	-.0251	-.2572	-.2056	-.1276	-.0434	-.3464	-.3109	-.3119	-.3075
.80	-.1923	.1802	-.2576	-.2147	-.3131	-.2234	-.3405	-.2728	-.3228	-.2651	-.3151	-.3193	-.3358	-.2610
.90	-.1784	.1660	-.2863	-.2297	-.2985	-.2112	-.3039	-.2624	-.2895	-.2834	-.3003	-.2982		
.95			-.2602	-.2332	-.2697	-.2071	-.2848	-.2570	-.2970	-.2965	-.3012	-.2860	-.3079	-.2535

31

TABLE III.- CONTINUED
(a) α = 4.74°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0830	.4279	.1300	.6333	.0815	.7683	.0759	.8291	-.0525	.8323		.7906		.8263
.10	.0749	.3636	.1393	.5929	.2027	.6812			.1694	.7629	.1675		-.0330	.6743
.15	.0540	.3809	.1373	.5292	.1961	.6247			.1570	.6928			.1630	.5408
.20	.0613	.3600	.1313	.4816	.1952	.5733	.2332	.6109	.2141	.6412	.2013	.6746	.1791	.4704
.25					.1767	.5111	.2211	.5617	.2344	.5904	.1905	.6356	.1974	.4025
.30	-.0939	.0460							.2196	.5410	.2103	.5688	.1966	.3501
.40	-.0122	.2976	-.1562	-.0000	-.1388	-.0140	-.1432	-.0122	-.1138	-.0137	.2156	.4355	.1879	.2830
.50			-.1301	-.1279	-.1534	-.0075	-.1459	-.0092			-.1238	-.0537	.1679	.1806
.60					-.1616	.0136	-.1381	.0033			-.1640	-.0981	-.2935	-.3089
.70	.0252	.1810	-.0024	.2155	-.1569	.1334	-.1760	-.0723	-.3379	-.2625	-.3442	-.3017	-.2486	-.3161
.80	-.2055	-.0547	-.2275	-.1256			-.3474	-.2248	-.3427	-.2733	-.3159	-.3115	-.2746	-.2442
.90	-.1638	-.1145	-.2570	-.1671	-.2953	-.1338	-.3089	-.1876	-.3071	-.2739	-.3039	-.2915	-.3570	-.2670
.95	-.1567	-.1298	-.2476	-.1738			-.2753	-.1640	-.2956	-.2713	-.3011	-.2783	-.3533	-.2795

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1007	.1704	.0844	.5445			.0908	.7044	.2026	.6358	.0491	.7694	.0281	.6435
.10	.1008	.1844					.2265	.6276	.2379	.6013			.1281	.5608
.15					.2080	.5228	.2535	.5709	.2522	.5520	.3316	.6200	.1950	.4650
.20	.0603	.1720	-.0962	.3055			.2411	.5214	.2550	.5013			.2265	.3845
.25	-.0010	.0591	-.2001	-.0514	.1887	.4364	.2364	.4701	.2441	.4451	.2785	.5485	.2309	.3216
.30							.2143	.3836	-.1402	-.0342	.2737	.5059	.2230	.2755
.40	.0055	.1851			-.1647	-.0105	-.1547	-.0139	-.1564	-.0302	.2306	.3491	.2020	.1983
.50							-.1660	-.0105	-.1611	-.0189	-.1416	-.0616	.1111	.0364
.60	-.0339	.0676	-.0543	.1195	-.1588	-.0478	-.2852	-.1796	-.3445	-.2471	-.2151	-.1488	-.3302	-.3265
.70					-.3153	-.1827	-.3528	-.2337			-.3588	-.2981	-.3115	-.3356
.80	-.2147	-.1783	-.2897	-.2117	-.3142	-.1977	-.3176	-.2159	-.3056	-.2558	-.3225	-.3083		
.90	-.1927	-.1572	-.2992	-.2224	-.2835	-.1999	-.2898	-.2115	-.3106	-.2690	-.3112	-.3097	-.3368	-.2566
.95			-.2536	-.2300							-.3096	-.3028	-.3330	-.2467

Cp at η/b of

x/c	0.02		0.22		0.44		0.56		0.57		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05		.5293	.0428	.735			-.0060	.9136		.2248				
		.4594	.0675	.6706								.5333	-.0687	
		.4686	.0675	.6008									-.0875	
		.4385	.0588											
.20														
.30		.1038	-.1998											
		.3517	-.1767	.2538								-.0363		
													-.267	
.70		.2404	-.0310	.2757	-.1911	.2831	-.2103	-.0127	-.3573	.2337		-.0775	-.3025	
.80		-.0140	-.2534	-.0892			-.3565		-.3396	-.238		-.2836	-.2895	-.2368
		-.0767	-.2727	-.1206	-.3074		-.3194	-.160	-.3193	-.2185		-.2865	-.3671	-.2426
.85		-.0917	-.2383	-.1368		-.1045	-.2804	-.1235	-.3002	-.2158		-.2707	-.3590	-.2629

TAIL 1

Cp at η/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1035	.1484	-.0045	.5801			.0228	.7378		.6684	-.0607	.8005	-.0809	.6753
	.1067	.1633					.0820	.6348	.0831	.630			.0204	.5223
.15					.0952	.5552	.0302	.6030	.1213	.5778	.1395	.6505	.0763	.4825
.20	.0565	.1603					.0371	.4939	.1357	.5221			.1092	.3990
.25	.0255	.0824	-.1531	.3312	.1229	.4522	.1457	.4932	.1467	.4533	.1626	.5665	.1222	.3200
.30			-.2071	-.0321			.1458	.3355	.1550		.1632	.5209	.1249	.2509
.40	-.0133	.1909							.1693	-.0244	.1470	.3513	.1292	.194
.50	-.0534	.0833	-.0750	.1396	-.2016	.0326	-.1579	-.0163	-.1383	-.0060	-.783	-.523	-.0747	.0653
							-.2061	-.0342	-.1915	-.0156	-.2416	-.1375	-.3425	-.372
.60	-.2357	-.1847	-.2969	-.2065	-.1371	.1059	-.3054	-.1306	-.3625	-.2209	-.3655	-.2853	-.3181	-.3232
.70					-.3161	-.1614	-.3178	-.1900			-.3335	-.2945		
.80	-.2433	-.1423	-.2994	-.2181	-.3273	-.1931	-.3266	-.1839	-.3183	-.2189	-.3224	-.2948	-.3166	-.2642
.85			-.2662	-.2300	-.2949	-.1966	-.2995	-.1852	-.3129	-.2309	-.3174	-.2944	-.3274	-.2326

TAIL 2

33

TABLE III.- CONTINUED
(g) α = 8.75°

TAIL 1

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	-.0496	.6222	-.0286	.8361	-.1203	.9307	-.0822	.9896	-.2046	1.0313				.9373
.10	-.0363	.5537	-.0023	.7483	-.0284	.8385			-.0354	.9034	-.0056	.9155	-.1494	.7619
.15	-.0594	.5544	-.0029	.6769	.0506	.7636			.0135	.8252			-.0251	.6312
.20	-.0419	.5235	-.0032	.6130	-.0604	.6933	-.0913	.7331	-.0620	.7625	.0642	.7779	-.0936	.5542
.25					.0539	.6111	.0915	.6656	.0917	.6983	.0325	.7277	.0907	.4813
.30	-.1928	.1771	-.2338	.1543	-.2102	.0538	-.2057	.0442	-.0886	.6336	-.0514	.6467	.1023	.4238
.40	-.0948	.4351	-.2141	.3675	-.2225	.1278	-.2086	.0852	-.1841	.0285	-.0775	.4930	.1090	.3465
.50					-.2322	.3019	-.2013	.1454			-.1914	-.0204	-.0868	.2211
.60					-.2310	.3519	-.2417	-.1057			-.2136	-.0524	-.3291	-.3037
.70	-.0063	.3067	-.1536	.3511			-.3402	-.0675	-.3759	-.2021	-.3638	-.2663	-.3428	-.2951
.80	-.2212	.0313	-.2818	-.0479			-.3103	-.0889	-.3365	-.1756	-.3337	-.2717	-.4329	-.2559
.90	-.1683	-.0340	-.2767	-.0878	-.3049	-.0762	-.2803	-.0999	-.3244	-.1416	-.3276	-.2665	-.4024	-.2158
.95	-.1185	-.0468	-.2129	-.0986					-.3062	-.1275	-.3130	-.2646	-.3891	-.2362

TAIL 2

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1205	.1676	-.0677	.5920			-.1220	.7639	-.0261	.6951	-.1568	.8128	-.1628	.6869
.10	.1190	.1740					-.0457	.6827	-.0036	.6554			-.0737	.6093
.15					.0050	.5855	-.0093	.6315	.0197	.5960	-.0748	.6649	-.0258	.4968
.20	-.0633	.1587	-.1991	.3467	-.0625	.4815	-.0303	.5723	-.0384	.5376	.0366	.5633	.0089	.4157
.25	-.0537	.0771	-.2204	-.0105			-.0543	.5393	-.0517	.4682	.0495	.5155	.0256	.3444
.30							.0726	.4043	-.2026	-.0172	.0498	.3478	.0383	.3003
.40	-.0165	.1789			-.2292	.0894	-.2184	-.0612	-.2179	.0213	-.2248	-.0394	.0457	.2135
.50							-.2321	-.0985	-.2209	.0537	-.2769	-.1120	.0140	-.0396
.60	-.0648	.0902	-.0932	.1567	-.1426	.1550	-.3288	-.0821	-.3783	-.1900	-.3555	-.2558	-.3567	-.3380
.70					-.3213	-.1550	-.3554	-.1668			-.3424	-.2587	-.3412	-.3139
.80	-.2501	-.1887	-.3128	-.1998	-.3360	-.1919	-.3372	-.1747	-.3264	-.1790	-.3293	-.2566		
.90	-.2687	-.1290	-.3172	-.2124	-.2977	-.1668	-.3098	-.1827	-.3113	-.1945	-.3190	-.2619	-.3213	-.2789
.95	-.2862	-.2274											-.3118	-.2703

TABLE III. – CONTINUED
(h) a = 10.76°

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	-.1306	.7158	-.1006	.9323	-.1926	1.0066	-.1542	1.0631	-.2401	1.0939				.9833
.10	-.0902	.6608	-.0634	.8362	-.0328	.845			-.0230	.9681	-.0818	.5580	-.1778	.8026
.15	-.0959	.6525	-.0561	.7595	-.0129	.833			-.0406	.8851			-.0672	.6758
.20	-.0722	.6208	-.0629	.6846	-.0040	.7513	.0265	.7937	.0038	.8161	.0126	.3240	-.0519	.5953
.25					-.0009	.66	.0330	.7167	-.0295	.7451	.0164	.7696	.0552	.5233
.30	-.2290	.2827							.0267	.6731	.0162	.6339	.0529	.4640
.40	-.1408	.5148	-.2687	.3697	-.2441	.1293	-.2377	.0768	-.2215	.0472	-.0110	.5223	.0533	.3850
.50	-.2522		-.2522	.4304	-.2544	.2211	-.2429	.1699			-.2285	.0004	.0533	.2510
.60					-.2641	.4930	-.2352	.2600			-.2470	.0641	.3529	.2976
.70	-.0331	.3771	-.2138	.4417	-.2683	.4167	-.2734	.2554	-.3493	.1190	-.2486	.2425	-.4069	.2829
.80	-.2283	.0760	-.3225	-.0173			-.3277	-.0395	-.3279	.0631	-.3412	.2373	-.4427	.2525
.90	-.1698	.0036	-.2787	-.0599	-.3086	.0321	-.3020	-.0581	-.3130	-.0746	-.3385	-.2188	-.4150	-.2001
.95	-.1060	-.0065	-.1742	-.0686			-.2888	-.0663	-.3032	-.0866	-.3073	-.2178	-.3990	-.2178

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1282	.1723	-.0899	.5795			-.2102	.7835		.7110	-.2330	.8100	-.2333	.7108
.10	.1275	.1742					-.1625	.7138	-.1269	.6652			-.1599	.6536
.15					-.0701	.6084	-.1078	.6514	-.1027	.6652	-.0206	.6786	-.1440	.5304
.20	.0771	.1541					-.0567	.5917	-.0923	.6022			-.0687	.4452
.25	-.0520	-.0570	-.2154	.3569	.0017	.4946	-.0240	.5285	-.0687	.5359	-.0724	.5878	-.0441	.3699
.30			-.2286	.0152			.0043	.4176	-.0566	.4643	-.0559	.5393	-.0330	.3192
.40	-.0347	.1638							-.2440	-.0118	-.0460	.3656	-.0199	.2279
.50					-.2470	.1423	-.2541	.1041	-.2567	.0607	-.2724	-.0076	-.0565	.211
.60	-.0816	-.0807	-.1191	.1743	-.1511	.1780	-.2643	.1613	-.2583	.1119	-.3215	-.0705	-.3810	-.3464
.70					-.3290	.1613	-.3299	-.0533	-.3958	-.1236	-.3459	-.2199	-.3640	-.320
.80	-.2576	-.1948	-.3241	-.1957	-.3450	.1932	-.3612	-.1465			-.3526	.2157		
.90	-.2715	-.1249	-.3429	-.2132			-.3382	-.1582	-.3400	-.1430	-.3314	-.2088	-.3411	-.2965
.95			-.3118	-.2287	-.3093	-.1955	-.2841	-.1664	-.3241	-.1614	-.3168	-.2088	-.3236	-.2856

TAIL 2

35

TABLE III.- CONTINUED
(l) α = 12.75°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.1817	.8113	-.1692	1.0254	-.2483	1.0758	-.2117	1.1253	-.2774	1.1549				1.03:2
.10	-.1252	.7788	-.1283	.9191	-.1136	.9822			-.0964	1.0241	-.1522	1.0166	-.2233	.8478
.15	-.1303	.7690	-.1130	.8354	-.0739	.8948			-.0917	.9370			-.1052	.7213
.20	-.1071	.7282	-.1164	.7474	-.0600	.8103	-.0266	.8471	-.0632	.8661	-.0489	.8677	-.0240	.6398
.25	-.250?	.4241			-.0558	.7135	-.0230	.7611	-.0399	.7899	-.0598	.8132	-.0361	.5665
.30	-.183?	.5681	-.3032	.5176	-.2781	.2157	-.2679	.1542	-.0335	.7130	-.0669	.7226	-.0323	.50??
.40			-.2885	.5245	-.2863	.5486	-.2784	.2506	-.2559	.0698	-.0488	.5529	-.0324	.4?35
.50			-.2550	.5071	-.2943	.5131	-.2661	.5065			-.2553	-.0228	-.0314	-.2822
.60	-.0546	.4350			-.2990	.4666	-.3035	.2945	-.3176	-.0122	-.2586	.0116	-.3655	-.2788
.70			-.3692	-.0084			-.3014	-.0164	-.3156	-.0400	-.3457	-.1896	-.4358	-.2448
.80	-.2351	.1145	-.3090	-.0256			-.2850	-.0392	-.3111	-.0536	-.3442	-.1588	-.4380	-.2272
.90	-.1751	.0388			-.2877	-.0142	-.2805	-.0462	-.3049	-.0625	-.3361	-.1084	-.4182	-.1908
.95	-.1035	.0316	-.1537	-.0320							-.2857	-.0967	-.3932	-.1972

Cp at y/b of

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1321	.1689	-.0851	.5615			-.2939	.7850			-.3033	.8314	-.2987	.7251
.10	.1300	.1676			-.1253	.6303	-.2512	.7174	-.2181	.7132			-.2592	.6732
.15							-.2148	.6523	-.1981	.6759	-.1034	.6973	-.2117	.5488
.20	.0729	.1505	-.2169	.3556	-.0588	.5028	-.1581	.5861	-.1895	.6183	-.1606	.6017	-.1656	.4631
.25	-.0638	.0315					-.1037	.5181	-.1638	.5570	-.1537	.5508	-.1352	.3830
.30			-.2390	.0442			-.0723	.4061	-.1492	.4829	-.1393	.3704	-.1151	.3332
.40	-.0277	.1539			-.2703	.1936			-.2911	.0154	-.3178	-.0248	-.0794	.2351
.50							-.2931	.1679	-.2926	.1228	-.3563	-.0160	-.1118	-.0484
.60	-.0692	.0608	-.1120	.1828	-.1672	.2054	-.2833	.2541	-.2858	.2248	-.3532	-.1616	-.3736	-.3476
.70							-.3259	-.0204	-.4080	-.0934	-.3631	-.1513	-.3662	-.3277
.80	-.2696	-.2002	-.3332	-.1991	-.3372	-.1436	-.3628	-.1297	-.3430	-.1296	-.3397	-.1609	-.3314	-.2746
.90	-.2822	-.1410	-.3499	-.2182	-.3477	-.1770	-.3432	-.1494	-.3216	-.1505	-.3286	-.1705	-.3249	-.2741
.95			-.3188	-.2274	-.3141	-.1819	-.3018	-.1604						

TABLE III. - CONTINUED
(j) α = 16.76°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.2870	.9914	-.2997		-.3418	.2022	-.3145	1.2399	-.3538	.5580		1.1235		1.1190
.10	-.1983	.3302	-.2481		-.2562	1.1142			-.2674	.4559			-.3035	.3442
.15	-.1950	.3090	-.2246		-.2044	.6254			-.2062	.3568			-.2096	.8186
.20	-.1655	.8164	-.2189		-.1828	.9354	-.1442	.9658	-.1467	.9320	-.1570	.8712	-.0835	.7384
.25					-.1718	.8292	-.1539	.8758	-.1255	.8016	-.1513	.9117	-.0571	.6655
.30	-.3126	.7817	-.3611		-.3382	.5517	-.3282	.4257	-.1259	.8160	-.1207	.8166	-.0549	.6040
.40	-.2519	.7091	-.3504		-.3450	.6533	-.3299	.6280	-.3060	.3418	-.1218	.6303	-.0668	.5140
.50	-.3504				-.3474	.6282	-.3132	.6047			-.3083	.2290	-.1344	.3519
.60											-.2942	.3279	-.4227	.2690
.70	-.1232	.5407	-.2919	.6119	-.3338	.5496	-.3073	.3519	-.3049	.0230	-.3492	-.0107	-.4531	-.1987
.80	-.2764	.1751	-.3546	.0523			-.2829	.0227	-.2962	-.0068	-.3592	-.0288	-.4521	-.0788
.90	-.1959	.0759	-.2718	.0250	-.2729	.0305	-.2702	.0066	-.2895	-.0141	-.3258	-.0413	-.4598	-.0066
.95	-.1160	.0769	-.2133	.0239			-.2649	-.0005	-.2906	-.0212	-.2946	-.0454	-.4702	-.0330

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1124	.1893	.0185	.4753			-.3944	.7550	-.4019	.7110	-.4029	.7894	-.4200	.7300
.10	.1238	.1483					-.3567	.7085					-.4126	.6944
.15					-.2261	.6177	-.3039	.6527	-.3352	.6724	-.2190	.7014	-.3886	.5811
.20	-.0783	-.1505	-.1794	-.2850	-.1677	.4983	-.2524	.5940	-.3062	.6181			-.3562	.4959
.25	-.0739	-.0183					-.2248	.5279	-.2712	.5553	-.3399	.6013	-.3319	.4126
.30			-.2410	-.0387			-.2207	.4142	-.2527	.4784	-.3274	.5481	-.3111	.3625
.40	-.0260	.1498							-.3652	.1176	-.3053	.3664	-.2824	.2555
.50					-.2924	.2839	-.3286	.3210	-.3611	.3380	-.4075	.1997	-.2820	.0728
.60	-.0681	-.0009	-.1332	.1746			-.3081	.2904	-.3485	.3157	-.4265	.1843	-.4298	-.2347
.70					-.2550	.2093	-.3632	-.0113	-.4277	-.0708	-.4440	-.0901	-.4305	-.2156
.80	-.2541	-.2049	-.3339	-.1912	-.3811	-.1405	-.4003	-.1230			-.4362	-.1161		
.90	-.2714	-.1847	-.3591	-.2419	-.3766	-.1763	-.3743	-.1466	-.3667	-.1209	-.3757	-.1327	-.4339	-.2348
.95			-.3300	-.2381	-.3476	-.1828	-.3388	-.1582	-.3313	-.1438	-.3665	-.1431	-.3834	-.2536

TAIL 2

TABLE III.- CONCLUDED
(k) α = 18.75°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.3484	1.0414	-.3535	1.2634	-.3739	1.2623	-.3520	1.2905	-.3884	1.3052	-.4268	.7526		1.1548
.10	-.2619	1.1442	-.3031	1.1549	-.3212	1.1815			-.3084	1.2018	-.3182	1.1775	-.3376	.9884
.15	-.2357	1.1152	-.2766	1.0601	-.2555	1.0923			-.2559	1.1155			-.2575	.8684
.20	-.2077	1.0081	-.2672	.9561	-.2302	1.0021	-.2044	1.0294	-.2015	1.0384	-.2179	1.024	-.1210	.7905
.25					-.2133	.8958	-.1965	.9382	-.1700	.9602	-.2140	.9640	-.1061	.7152
.30	-.3365	.8885	-.3855	.7724	-.3637	.6991	-.3522	.5653	-.1714	.8720	-.1919	.8674	-.0982	.6526
.40	-.2847	.7949	-.3744	.7411	-.3683	.7113	-.3553	.6920	-.3351	.4540	-.1616	.6781	-.1416	.5630
.50					-.3706	.6780	-.3425	.6526			-.3255	.3201	-.2109	.3891
.60					-.3522	.5837	-.3211	.3761			-.3094	.4213	-.4311	.2285
.70	-.1287	.5887	-.3161	.6560			-.2888	.0376	-.3201	.0313	-.3582	.0055	-.4402	.1312
.80	-.2832	.1956	-.3381	.0667			-.2809	.0270	-.3041	.0128	-.3680	.0085	-.4576	.0430
.90	-.2003	.0993	-.2803	.0464	-.2817	.0478	-.2766	.0214	-.3006	.0106	-.3419	.0168	-.4683	.0136
.95	-.1342	.0860	-.2279	.0460					-.3023	.0043	-.3064	.0235	-.4658	.0326

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0993	-.1808	.0322	.4269			-.3947	.7138			-.4268	.7526	-.4453	.6843
.10	.1119	-.1526					-.3955	.6775	-.3920	.6849	-.4431	.6843	-.4431	.6759
.15					-.2810	.5934	-.3724	.6314	-.3860	.6537	-.3251	.6843	-.4388	.5759
.20	-.0705	-.1381	-.1770	-.2631			-.3327	.5755	-.3889	.6013			-.4323	.4995
.25	-.0685	-.0210	-.2500	-.0424	-.1808	.4799	-.3052	.5101	-.3716	.5426	-.3743	.5781	-.4130	.4222
.30	-.0306	-.1187					-.2980	.3996	-.3580	.4679	-.3542	.5302	-.3878	.3789
.40									-.4025	.2040	-.3670	.3801	-.3488	.2875
.50	-.0806	-.0213	-.1511	-.1484	-.3212	.2786	-.3469	.3163	-.4009	.3298	-.4210	.3005	-.3285	.1252
.60							-.3329	.2844	-.3853	.3065	-.4370	.1696	-.4683	-.1967
.70					-.2782	-.1963	-.3849	.0177	-.4504	-.0737	-.4578	-.0865	-.46?6	-.2022
.80	-.2405	-.2247	-.3292	-.2017	-.4013	-.1462	-.4190	-.1283			-.4395	-.1108		
.90	-.2502	-.2088	-.3519	-.2509	-.3939	-.1823	-.3946	-.1516	-.3847	-.1268	-.3942	-.1251	-.4292	-.2168
.95			-.3301	-.2498	-.3662	-.1889	-.3634	-.1633	-.3551	-.1497	-.3945	-.137?	-.3953	-.2359

38

TABLE IV.- PRESSURE COEFFICIENTS, $\Phi = 67.5°$, $\delta = 0°$, $M = 1.60$
(a) $\alpha = -3.24°$

TAIL 1

| x/c | Cp at y/b of | | | | | | | | | | | | | |
| | 0.02 | | 0.22 | | 0.44 | | 0.56 | | 0.67 | | 0.83 | | 0.98 | |
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.2513	.1378	.5120	.2212	.6267	.2578	.6420	.2902	.5767	.1693	.6193	.3619		.0602
.10	.2523	.0980	.4620	.2385	.5385	.3323			.5643	.4041		.3619	.5803	.2778
.15	.2422	.0072	.4613	.2174	.4865	.3072			.5296	.3778	.5365	.3939	.4440	.3449
.20	.2152	.0853	.3664	.2090	.4478	.2776	.4825	.3576	.5105	.3465	.5095	.3470	.3880	.3027
.25					.4029	.2501	.4424	.2702	.4849	.3453	.4684	.3130	.3253	.2628
.30	.0994	.0035							.3379	.2884	.3753	.2810	.2743	.2230
.40	.0546	.0017	.0171	.1599	.0281	.1367	.0311	.1212	.3316	.1191	.0658	.1153	.2185	.1861
.50			.1003	.1126	.0163	.1529	.0265	.1377			.0920	.1773	.1574	.1157
.60					.0325	.1489	.0178	.0738					.3149	.3190
.70	.1147	.0325	.0388	.0385	.0852	.1474	.0349	.2003	.2668	.3409	.3061	.3553	.3216	.3104
.80	.1920	.2153	.1711	.2667			.2131	.3447	.2720	.3407	.3113	.3219	.2455	.2837
.90	.1501	.2044	.2141	.2983	.1642	.3016	.1731	.3079	.2593	.3054	.3111	.3134	.2513	.3107
.95	.1592	.1758	.2258	.2705			.1657	.2877	.2533	.2981	.2990	.3063	.2518	.3140

TAIL 2

| x/c | Cp at y/b of | | | | | | | | | | | | | |
| | 0.02 | | 0.22 | | 0.44 | | 0.56 | | 0.67 | | 0.83 | | 0.98 | |
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.2550	.2383	.4443	.3801			.6330	.5127			.6047	.5368	.6075	.4265
.10	.2570	.2052					.5661	.4769	.5761	.4876	.5724	.5377	.5230	.4438
.15					.4762	.3934	.5288	.4416	.5533	.4824			.4404	.3993
.20	.2364	.1633					.4854	.4145	.4841	.4542			.4009	.3554
.25	-.0131	-.0481	.0382	.2172	.4037	.3356	.4550	.3863	.4881	.4229	.5245	.4630	.3741	.3227
.30			-.0914	-.1106			.4173	.3285	.4628	.3858	.4944	.4380	.3452	.3019
.40	.1066	.0459							-.0434	-.0524	.3816	.3131	.3080	.2609
.50			.1403	-.0080			-.0506	-.0738	-.0589	-.0767	-.0802	-.0930	.2041	-.1338
.60	.1555	.0401			-.0560	-.0851	-.0568	-.0886	-.0589	-.0815	-.1631	-.1919	-.2909	-.2772
.70					-.0495	-.1127	-.2027	-.2433	-.2869	-.2951	-.3231	-.3218	-.2755	-.2262
.80	-.1060	-.1623	-.1556	-.1989	-.2251	-.2907	-.2963	-.2695	-.2664	-.2538	-.2949	-.2823	-.2921	-.3319
.90	-.1269	-.1557	-.1915	-.2217	-.1875	-.2665	-.2814	-.2565	-.2719	-.2666	-.2903	-.2802	-.2952	-.3342
.95			-.2069	-.2087	-.1822	-.2536	-.2624	-.2544			-.2811	-.2816		

39

TABLE IV. - CONTINUED
(b) a = -1.25°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2045	.1779	.4317	.3239	.5124	.5161	.5507	.5039	.4738	.4351				.3720
.10	.2007	.1543	.3648	.3339	.4602	.4382			.4763	.5124	.5484	.5258	.5438	.5039
.15	.1924	.1621	.3288	.3024	.4132	.3950			.4327	.4639			.4047	.3886
.20	.1675	.1460	.3007	.2874	.3819	.3608	.4383	.3810	.4355	.4348	.4626	.4535	.3536	.3369
.25					.3466	.3295	.3926	.3587	.4253	.3906	.4432	.4345	.2969	.2945
.30	-.0612	-.0375	-.0453	-.1217	-.0540	-.1050	-.0594	-.0875	.3900	.3586	.4197	.4093	.2583	.2577
.40	-.1146	-.0513	-.0303	-.0685	-.0610	-.1118	-.0598	-.1067	-.0496	-.0829	.3467	.3371	.2197	.2191
.50					-.0307	-.1070	-.0479	-.1035			-.0803	-.0946	.1571	.1386
.60					-.0025	-.1058	-.0891	-.1663			-.1126	-.1515	-.3025	-.3160
.70	-.0775	.0019	.1009	.0084			-.2750	-.3214	-.2909	-.3196	-.3171	-.3389	-.2965	-.3182
.80	-.1962	-.1866	-.1927	-.2416	-.1885	-.2746	-.2579	-.2925	-.2995	-.3284	-.3196	-.3123	-.2506	-.2749
.90	-.1609	-.1945	-.2286	-.2705			-.2418	-.2746	-.2991	-.2945	-.2885	-.3007	-.2450	-.2900
.95	-.1647	-.1884	-.2390	-.2610					-.2893	-.2838	-.2825	-.2977	-.2500	-.2639

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2137	.2344	.3868	.4290			.5542	.5569	.5247	.5215			.5308	.4851
.10	.2179	.2123					.5188	.5001	.5027	.5078	.5231	.6072	.5308	.4601
.15					.4310	.4124	.4788	.4631	.4474	.4718			.4755	.4020
.20	.1986	.1900					.4904	.4369	.4420	.4361	.5490	.5367	.4083	.3539
.25	-.0214	-.0225	.0267	.2338	.3639	.3526	.4127	.4060	.4223	.3978	.4815	.4779	.3705	.3144
.30		-.0886	-.1081	-.0957			.3786	.3432	-.0609	-.0496	.4567	.4501	.3435	.2899
.40	.0796				-.0750	-.0719	-.0688	-.0636	-.0763	-.0709	.3570	.3215	.3178	.2420
.50			.0834	.0401			-.0747	-.0754	-.0777	-.0732	-.0907	-.0890	.2831	.1079
.60	.0983	.0368			-.0692	-.0885	-.2146	-.2347	-.2947	-.2902	-.1736	-.1872	.1827	-.2867
.70							-.3058	-.2902			-.3298	-.3200	-.2996	-.2430
.80	-.1370	-.1728	-.1894	-.2081	-.2605	-.2868	-.2911	-.2556	-.2703	-.2510	-.2984	-.2796	-.2990	-.2903
.90	-.1542	-.1652	-.2166	-.2349	-.2350	-.2589	-.2700	-.2517	-.2766	-.2584	-.2866	-.2739	-.2979	-.2850
.95			-.2277	-.2233	-.2243	-.2397					-.2861	-.2752	-.2868	

TABLE IV. - CONTINUED
(c) α = 0.30°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.33 U.S.	0.33 L.S.	0.93 U.S.	0.93 L.S.

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.

TAIL 2

TABLE IV.- CONTINUED
(d) α = 2.75°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.1143	.3283	.1846	.5713	.1493	.6978	.1314	.7576	.0181	.7666				.7734
.10	-.0961	.2996	.1953	.5287	.2577	.6208			.2257	.6999	.2189	.7299	.0143	.6359
.15	-.0973	.3038	.1904	.4753	.2454	.5659		.5427	.2272	.6337	.2753	.6221	.1779	.5040
.20	-.0925	.2857	.1731	.4300	.2367	.5214	.2761		.2622	.5833	.2592	.5904	-.2189	.4342
.25					.2193	.4689	.2620	.5117	.2738	.5359	.2616	.5314	-.2303	.3685
.30	-.0321	.0453	-.1108	-.0285	-.1207	-.0374	-.1244	-.0353	.2550	.4954	.2456	.4105	-.2232	.3152
.40	-.0324	.2354	-.0786	-.0780	-.1298	-.0336	-.1285	-.0339	-.0975	-.0348	-.1131	-.0652	-.1988	.2516
.50					-.1300	-.0194	-.1196	-.0286			-.1553	-.1096	-.1570	.1538
.60					-.1132	-.0397	-.1568	-.0995	-.3302	-.2735	-.3408	-.3103	-.3058	-.3175
.70	.0114	-.1209	.0030	.1471			-.3307	-.2593	-.3404	-.2846	-.3169	-.3206	-.2319	-.3321
.80	-.2162	-.1030	-.2271	-.1617	-.2854	-.1715	-.3021	-.2354	-.3046	-.2890	-.3010	-.2952	-.2552	-.2589
.90	-.1828	-.1498	-.2642	-.2010			-.2782	-.2207	-.2937	-.2873	-.2985	-.2822	-.3179	-.2723
.95	-.1742	-.1648	-.2595	-.2079									-.3364	-.2807

Cp at y/b of

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1569	.1931	.2683	.5016			.3059	.6265	.4102	.5684	.3218	.6817	.2783	.5672
.10	.1614	.1915					.4156	.5584	.4057	.5440			.3818	.4959
.15					.3252	.4509	.3815	.5085			.4623	.5673	.3663	.4213
.20	.1180	.1642					.3516	.4664	.3594	.5018			.3258	.3546
.25	-.0126	.0086	-.0217	.2426	.2796	.3874	.3306	.4253	.3529	.4604	.3875	.4993	.2910	.3014
.30			-.1427	-.0915			.3034	.3524	.3334	.4129	.3713	.4660	.2623	.2675
.40	-.0396	-.1346									.3014	.3266	.2312	.2077
.50							-.1020	-.0484	-.0979	-.0497	-.1061	-.0827	-.1365	-.0593
.60	.0121	.0280	-.0078	.0796	-.1079	-.0527	-.1096	-.0554	-.1109	-.0552	-.1858	-.1754		
.70							-.2431	-.2172	-.1113	-.0562	-.3176	-.3171	-.3176	-.3129
.80	-.1931	-.1896	-.2531	-.2222	-.1195	-.0507	-.3327	-.2872	-.3140	-.2737	-.3102	-.3196	-.3338	-.3042
.90	-.1886	-.1757	-.2814	-.2398	-.3025	-.2460	-.3034	-.2812	-.2852	-.2908	-.2950	-.2901	-.3062	-.2588
.95			-.2659	-.2466	-.2938	-.2321	-.2857	-.2728	-.2895	-.2982	-.2956	-.2822	-.2750	-.2506

TABLE IV. - CONTINUED
(e) α = 4.74°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0559	.4371	.0645	.6802	.0146	.7909	.0058	.8507	-.1050	.8828	.8975	.804	.8972	.8530
.10	.0397	.3913	.0910	.6200	.0352	.7103		.6175	-.114	.7796		.804		.8883
.15	.0359	.4002	.0921	.5576	.1402	.6458	.1697		.0943	.7054		.685		.5562
.20	.0522	.3764	.0966	.5086	.1403	.5891	.1672	.5677	.1439	.6512		.5143		.4820
.25					.1310	.5235			.1732	.5972		.5768		.4120
.30	-.0891	.0706	-.1564	.0419	-.1628	-.0057	-.1644	-.0081	.656	.5143				.2505
.40	-.0094	.2260			-.1700	.0107	-.1718	.3054	-.1420	-.0151		.0498		.1780
.50			-.1305	-.1815	-.1721	.0579	-.1614	.0214						.1508
.60					-.1640	.2061	-.1953	-.0495	-.3523	-.2483				.3217
.70	-.0216	.1813	-.0417	.2116			-.3544	-.1738	-.3461	-.2556		.2911		.2629
.80	-.2269	-.0572	-.2613	-.1309	-.3046	-.1323	-.3163	-.1419	-.3184	-.2419		.2922		.2532
.90	-.1991	-.1233	-.2904	-.1692			-.2823	-.1438	-.3036	-.2378				.2696
.95	-.1770	-.1368	-.2610	-.1757										

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.88 U.S.	0.88 L.S.	0.98 U.S.	0.98 L.S.
.05	.2116	.668	.1847	.4781			.1803	.6391	.3134	.5762	.1821	.6993	.1385	.5987
.10	.2004	.550					.3470	.5661	.3526	.5471			.2551	.5165
.15					.2777	.4632	.3394	.5127	.3258	.5032	.4126	.5803	.3420	.4302
.20	.1440	.210	-.0641	.2280	.2540	.3895	.3119	.4708	.3216	.4589	.3488	.5036	.3167	.3533
.25	-.0237	-.0026	-.1752	-.1071			.2985	.4273	.3030	.4083	.3386	.4693	.2859	.2937
.30	-.0049	.1254					.2721	.3505			.2777	.3278	.2561	.2530
.40					-.1270	-.0441	-.1209	-.0407	-.1125	-.0518	-.1179	-.0777	.2102	.1859
.50	-.0322	.0215	-.0501	.3735			-.1322	-.0447	-.1284	-.0547	.984	.1671	-.1107	.0341
.60					-.1326	-.0138	-.2603	-.2079	-.1322	-.0480	-.3487	-.3032	-.3304	-.3222
.70									-.3274	-.2666	-.3171	-.329	-.3520	-.3342
.80	-.2245	-.1959	-.2790	-.2323	-.3072	-.2223	-.3457	-.2732	-.2944	-.2813	-.3033	-.3077	-.3037	-.2550
.90	-.2150	-.1783	-.3002	-.2482	-.3118	-.2279	-.3098	-.2557	-.2995	-.2955	-.3026	-.2952	-.2767	-.2459
.95			-.2670	-.2572	-.2854	-.2292	-.2916	-.2512						

43

TABLE IV.- CONTINUED
(f) α = 6.76°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0381	.5394	-.0393	.7934	-.1188	.8737	-.0986	.9303	-.1999	.9728	-.0301			.9149
.10	-.0304	.4867	-.0051	.7102	-.0002	.7874			-.0199	.8505		.8677	-.1686	.7348
.15	-.0421	.4954	-.0003	.6425	.0408	.7167			.0014	.7740			-.0434	.6039
.20	-.0133	.4744	-.0005	.5828	-.0427	.6502	.0765	.6834	-.0420	.7135	-.0477	.7407	.0570	.5271
.25					.0449	.5728	.0715	.6207	-.0728	.6531	-.0317	.6957	.0686	.4517
.30	-.1522	-.1328	-.2092	.1157	-.2151	.0319	-.2095	-.0227	-.0725	.5904	-.0320	.6179	.0854	.3893
.40	-.0551	.4064	-.1917	.2996	-.2243	.0957	-.2179	-.0666	-.1860	.0074	-.0580	.4687	.0866	.3098
.50					-.2240	.2283	-.2055	-.1106			-.1991	-.0303	.0759	.1820
.60					-.2198	.3141	-.2455	-.0939			-.2298	-.0577	-.3210	.3237
.70	-.0481	.2375	-.0749	.2776			-.3542	-.0854	-.3767	-.2072	-.3635	-.2690	-.3115	.3063
.80	-.2332	-.0162	-.2799	-.0935			-.3267	-.1098	-.3456	-.1832	-.3384	-.2747	-.3847	.2985
.90	-.2986	-.0869	-.3038	-.1339	-.3200	-.1073	-.2913	-.1203	-.3304	-.1441	-.3317	-.2724	-.3837	.2464
.95	-.1704	-.0974	-.2516	-.1391					-.3114	-.1385	-.3211	-.2722	-.3635	.2625

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.3492	.1727	.2015	.4013			.0835	.6547			.0684	.7143	.0375	.6126
.10	-.2928	.1513					.2345	.5807	.2092	.5866			.1358	.5314
.15					.2424	.4781	.2853	.5239	.2595	.5539	.3429	.5886	.2331	.4343
.20	-.1997	.1293	-.1256	.1772	.2103	.3975	.2660	.4768	.2759	.5081	.2913	.5052	.2534	.3579
.25	-.0403	-.0615	-.1237	-.1342			.2502	.4315	.2740	.4619	.2783	.4686	.2516	.2927
.30							.2208	.3498	.2542	.4069	.2282	.3217	.2222	.2507
.40	-.0090	-.1514			-.1556	-.0391	-.1478	-.0305	-.1373	-.0514	-.1386	-.0732	.1771	.1722
.50							-.1520	-.0354	-.1520	-.0466			.0844	-.0146
.60	-.0637	.0148	-.0833	-.0630	-.1048	-.0396	-.2733	-.1941	-.1492	-.0351	-.2148	-.1582	-.3421	-.3315
.70					-.3142	-.2030	-.3453	-.2363	-.3363	-.2584	-.3530	-.2987	-.3554	-.3360
.80	-.2506	-.2004	-.2882	-.2396	-.3327	-.2308	-.3152	-.2247	-.3026	-.2623	-.3231	-.3103	-.3040	-.2457
.90	-.2456	-.1902	-.3021	-.2461	-.2997	-.2309	-.2947	-.2250	-.3047	-.2701	-.3098	-.3060	-.2831	-.2339
.95	-.2707		-.2707	-.2611							-.3052	-.2982		

44

TABLE IV. - CONTINUED
(g) α = 8.76°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.1538	.6310	-.1303	.8909	-.2178	.9455	-.1888	1.0005	-.2601	1.0487				.9529
.10	-.0966	.5893	-.0928	.7936	-.0983	.8597	-.0804		-.0804	.9180	-.1345	.32.0	-.22.4	.7727
.15	-.1018	.5970	-.0800	.7187	-.0474	.7830			-.0738	.8386		.123.	.123.	.6501
.20	-.0679	.5778	-.28.3	.6451	-.0425	.7099	-.0169	.7443	-.0437	.7709	-.0335	.7892	-.0139	.5713
.25			-.0387	.6246			-.0164	.6745	-.0140	.7036	-.0405	.7400	-.0233	.4923
.30	-.2121	.2388							-.0114	.6329	-.0513	.6519	-.0232	.4278
.40	-.11.4	.4830	-.2610	.2870	-.2322	.1023	-.2544	.0619	-.2369	.0282	-.0270	.4962	-.0315	.3433
.50			-.2478	.3863	-.2687	.2214	-.2606	.1503			-.2401	.0090	-.0255	.2070
.60					-.2728	.3973	-.2499	.2752			-.2614	.0232	-.3533	.3286
.70	-.0833	.3000	-.1452	.3542	-.2753	.3602	-.2888	.2325	-.3707	-.0871	-.3590	-.2385	-.3550	-.3004
.80	-.2456	.0245	-.3135	.0548			-.3442	-.0621	-.3431	-.0790	-.3500	-.2317	-.4385	-.2852
.90	-.2159	-.0485	-.3113	-.0907	-.3333	-.0736	-.3190	-.0853	-.3287	-.0956	-.3440	-.2127	-.4063	-.2640
.95	-.1625	-.0569	-.1965	-.1019			-.3049	-.0948	-.3178	-.1060	-.3223	-.2084	-.3989	-.2751

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.4.54	.14.5.	.1874	.3.67			-.0201	.6753	.0980	.5960	-.0258	.7.84	-.0469	.6269
.10	.379.	-.072.				.4950	-.1020	.5984	.14.2	.5625	.2495	.59.2	-.0462	.5492
.15					.1853		-.18.7	.5395	.17.3	.5154			-.0988	.4455
.20	.2537	-.1378					-.207.	.4894	.1713	.5154			.353	.3672
.25	-.0243	-.0800	-.360.	.1627	-.1479	.4045	-.2047	.4378	.2167	.4656	.2231	.50.4	-.1434	.3011
.30	.00.2	-.111.	-.110.	-.1210			.1813	.3528	.2137	.4086	.2328	.4637	.1600	.2579
.35									-.1570	-.0502	.1899	.3177	.1634	.1732
.50	-.073.	.000.	-.0998	.0600	-.1579	-.0284	-.1829	-.0233	-.1782	-.0361	-.1565	-.0679	-.0743	-.0066
.60							-.1797	-.0132	-.1807	-.0190	-.2257	-.1562	-.3527	-.3399
.70					-.1068	.0910	-.2601	-.1535	-.3546	-.2491	-.3598	-.2866	-.249.	-.3307
.80	-.2927	-.2238	-.3150	-.2407	-.3184	-.2016	-.3290	-.2019	-.3114	-.2296	-.3262	-.2957	-.3123	-.2614
.90	-.2707	-.2033	-.3258	-.2496	-.3355	-.2353	-.3310	-.2122	-.3114	-.2296	-.3148	-.2990	-.3123	-.2614
.95			-.2926	-.2565	-.3031	-.2367	-.3023	-.2200	-.3072	-.2365	-.3085	-.3015	-.3037	-.2337

TAIL 2

TABLE IV.- CONTINUED
(h) α = 10.75°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.2339	.7248	-.2153	.9739	-.2933	1.0142	-.2658	1.0622	-.3210	1.0980	-.2224	.9700		.9920
.10	-.1409	.6983	-.1753	.8723	-.1763	.9310			-.1722	.9719			-.2672	.8185
.15	-.1408	.7122	-.1575	.7922	-.1299	.8484			-.1419	.8921			-.1828	.6929
.20	-.1096	.6830	-.1552	.7089	-.1207	.7689	-.0876	.7980	-.1217	.8209	-.1101	.8329	-.0935	.6125
.25	-.2567	.3776			-.1096	.6738	-.0923	.7210	-.0949	.7494	-.0990	.7817	-.0267	.5333
.30	-.1696	.5513							-.0933	.6728	-.1116	.6940	-.0210	.4703
.40			-.3060	.4807	-.3052	.1952	-.2956	.1353	-.2837	.0569	-.0955	.5257	-.0272	.3812
.50			-.2955	.4566	-.3102	.4740	-.3051	.3256			-.2786	.0190	-.0276	.2362
.60					-.3136	.4532	-.2891	.4562			-.2978	-.0270	-.3720	-.3235
.70	-.1304	.3629	-.2528	.4410	-.3195	.4136	-.3259	.2615	-.3425	-.0385	-.3558	-.1457	-.3989	-.3006
.80	-.2628	-.0630	-.3482	-.0252			-.3331	-.0386	-.3351	-.0564	-.3614	-.1057	-.4518	-.2686
.90	-.2250	-.0132	-.3101	-.0566	-.3362	-.0408	-.3175	-.0605	-.3284	-.0709	-.3602	-.1012	-.4236	-.2463
.95	-.1590	-.0191	-.1628	-.0682			-.3124	-.0672	-.3237	-.0795	-.3348	-.1113	-.4164	-.2424

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.3655	.1475	.1872	.2112			-.1108	.6938			-.1070	.7221	-.1230	.6322
.10	.4199	.0941					-.0207	.6180	.0015	.6124			-.0356	.5625
.15					.1146	.5002	.1010	.5572	.0451	.5754	.1057	.5964	-.0216	.4515
.20	.3132	-.0322					.1305	.5032	.0795	.5239			-.0531	.3715
.25	-.0020	-.1157	-.1394	.1178	.0657	.4011	.1275	.4514	.1294	.4719	.0940	.5085	-.0600	.3012
.30			-.1345	-.0864			.1045	.3641	.1439	.4152	.1338	.4653	-.0591	.2529
.40	.0109	-.0420							.1922	-.0372	.1291	.3084	-.0854	.1654
.50					-.1115	.0432	-.2090	-.0067	-.2130	-.0082	-.1833	-.0627	-.0459	-.0028
.60	-.0762	-.0199	-.0959	.0559			-.1550	-.0445	-.2142	-.0113	-.2500	-.1336	-.3631	-.3472
.70					-.1181	.0996	-.2396	-.1110	-.3665	-.2215	-.3594	-.2730	-.3493	-.3224
.80	-.2918	-.2494	-.3248	-.2482	-.3152	-.1967	-.3237	-.1953			-.3348	-.2833		
.90	-.2885	-.2283	-.3425	-.2813	-.3294	-.2329	-.3344	-.2139	-.3192	-.2085	-.3220	-.2846	-.3125	-.2914
.95	-.3095	-.2806			-.2977	-.2378	-.3047	-.2245	-.3050	-.2251	-.3090	-.2879	-.2989	-.2784

TABLE IV. - CONTINUED
(i) α = 12.75°

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

47

TABLE IV.- CONTINUED
(j) α = 16.76°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.3870	.8427	-.4115	1.1802	-.4192	1.1840	-.4162	1.2139	-.4312	1.2366				1.0845
.10	-.3089	.9627	-.3730	1.0918	-.3923	1.1227			-.3929	1.1472	-.3967	1.1281	-.4025	.9472
.15	-.2669	1.0141	-.3441	1.0051	-.3397	1.0439			-.3446	1.0723			-.3835	.8334
.20	-.2067	.9561	-.3302	.9068	-.3192	.9617	-.2815	.9878	-.3168	1.0055	-.3290	.9995	-.3306	.7571
.25					-.3041	.8633	-.2971	.9081	-.2897	.9355	-.3104	.9440	-.2314	.6802
.30	-.3360	.8632							-.2704	.8568	-.2928	.8548	-.2290	.6151
.40	-.2348	.7755	-.3953	.7222	-.4119	.7069	-.4021	.6224	-.3881	.5257	-.2719	.6727	-.2471	.5188
.50			-.3859	.6913	-.4127	.6873	-.4072	.6772			-.3860	.4363	-.3298	.3490
.60					-.4106	.6562	-.3788	.6414			-.3893	.4377	-.4464	.1628
.70	-.2346	.5168	-.3761	.6169	-.3875	.5658	-.3734	.3686	-.3674	.0223	-.3831	.0002	-.4451	-.1329
.80	-.3243	.1796	-.4317	-.0607			-.3411	-.0342	-.3556	.0135	-.3794	-.0162	-.4857	-.1219
.90	-.2728	.0993	-.3699	.0332	-.3557	.0389	-.3385	.0223	-.3455	.0093	-.3705	-.0232	-.4842	-.1175
.95	-.2586	.0763	-.2983	.0294			-.3357	.0156	-.3416	.0020	-.3650	-.0292	-.4819	-.1420

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2081	.1447	.4575	.0864			-.1908	.4768			-.2845	.7387	-.3409	.6666
.10	.2220	.1012					-.0917	.4785	-.2189	.6215			-.3214	.6371
.15					-.0591	.2489	-.0782	.4573	-.1623	.5846	-.0908	.6303	-.2795	.5203
.20	.2246	-.0623					-.0979	.4230	-.1047	.5297			-.1915	.4391
.25	-.0220	-.1209	.0062	.0381	-.1053	.2416	-.1265	.3758	-.0763	.4740	-.1297	.5455	-.1263	.3609
.30			-.1015	-.2004			-.1653	.2827	-.0852	.4103	-.1244	.4992	-.0978	.3107
.40	-.0594	-.0763			-.2007	-.0094	-.2315	.0780	-.2772	.0205	-.1516	.3349	-.0858	.2131
.50							-.2173	.0719	-.2285	.1091	-.2747	.0499	-.1480	-.0272
.60	-.0188	-.1766	-.0524	-.1016	-.1035	-.0257	-.3120	-.1486	-.2112	.1269	-.3138	.0258	-.4222	-.3322
.70					-.3041	-.2299	-.3673	-.2271	-.3538	.1693	-.3967	-.1741	-.4051	-.2927
.80	-.2815	-.3454	-.2831	-.2910	-.3426	-.2476	-.3688	-.2300			-.3892	-.1967		
.90	-.2870	-.3380	-.3208	-.3379	-.3362	-.2545	-.3429	-.2284	-.3322	-.2124	-.3404	-.2094	-.2924	-.2700
.95			-.3317	-.3422					-.3084	-.2309	-.3024	-.2202	-.2513	-.2513

TABLE IV.- CONCLUDED
(k) a = 19.1°

Cp at y/b of

TAIL 1

x/c	0.02		0.22		0.14		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

Cp at y/b of

TAIL 2

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TABLE V.- PRESSURE COEFFICIENTS, $\phi = 90°$, $\delta = 0°$, $M = 1.60$

(a) $\alpha = -3.30°$

Cp at y/b of

TAIL 1

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TABLE V - CONTINUED
(b) α = -1.30°

Cp at y/b of

x/c	0.02		0.22		0.44		0.55		3.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.025	.2235	.1876	.4502	.3331	.5322	.5095	.5643	.4887	.4322	.4493			.4293	.5433
.050	.2054	.1510	.3814	.3367	.4770	.4363			.4911	.5132	.5659	.5183	.5015	.5011
.075	.2071	.1621	.3456	.3019	.4234	.3970	.4772	.3732	.3500	.4693	.4783	.4536	.3510	.3662
.20	.1848	.1513	.3148	.2869	.3903	.3625	.4633	.3566	.3552	.4703	.4657	.4365	.3623	.3597
.25					.3567	.3295	.4557		.4401	.3608	.4328	.3667	.3063	.2827
.30	.0634	.0224									.3557	.3313	.2893	.2516
.40	.1137	.0485	.0385	.1196	.0487	.1048	.0551	.4903	.3075	.3615	.0758	.0642	.2937	.2635
.50			.0343	.0715	.0516	.1096	.0506	.1059		.4910	.1583	.1543	.2537	.2611
.60					.0203	.0945	.0405	.1073			.1985	.1543	.2613	.2613
.70	.0938	.0108	.1166	.0140	.0118	.1065	.0838	.1604	.2839	.3204	.3137	.3403	.2712	.2413
.80	.1890	.1805	.1813	.2400			.2693	.2223	.2562	.3289	.3122	.3112	.2518	.2711
.90	.1526	.1906	.2191	.2638	.1745	.2780	.2511	.2900	.2962	.2921	.2875	.3007	.2487	.3023
.95	.1578	.1814	.2296	.2541			.2356	.2731	.2885	.2840	.2800	.2975	.2635	.2825

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.025	.1922	.2593	.3450	.4837			.4282	.6193	.4970	.5668	.4516	.5665	.4293	.5307
.050	.1835	.2394					.4912	.5516	.4770	.5498			.4635	.4837
.075	.1751	.2190			.4071	.4574	.4536	.5381	.4770	.5115	.4792	.5620	.3517	.4126
.20	.2036	.2317	.3127	.2535	.3483	.3935	.3802	.4711	.4441	.4715	.4493	.5075	.3625	.3665
.25			.1160	.0789			.3572	.3701	.3932	.4252	.3131	.3717	.3355	.3032
.30	.2525	.1221							.3932	.4252	.3458	.3238	.3175	.2917
.40			.0502	.0757	.0876	.0052	.0845	.0515	.0667	.0425	.0637	.0845	.2823	.2435
.50	.2715	.0625			.0959	.0705	.0887	.0655	.0848	.0625	.1757	.1805	.1993	.1735
.70	.1395	.1655	.2052	.1978	.2923	.2703	.2283	.2263	.3890	.2827	.3336	.2178	.2576	.2836
.80	.1532	.1550	.2275	.2201	.2716	.2446	.3195	.2917	.3034		.3012	.2903	.2830	.2838
.90			.2304	.2122	.2479	.2151	.2871	.2638	.2738	.2686	.2917	.2758	.3226	.2773
.95							.2751	.2651	.2832	.2571	.2804	.2743	.2653	.2773

TAIL 2

TABLE V.- CONTINUED
(c) a = 0.??°

Cp at y/b of

TAIL 1

Cp at y/b of

TAIL 2

TABLE V.- CONTINUED
(d) α = 2.70°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1089	.3118	.1723	.5855	.1390	.6889	.1161	.7564	.0039	.6174	.6012	.7248	.0001	.7771
.10	.0903	.2864	.1810	.5286	.2470	.6184			.2131	.7030			.1581	.6286
.15	.1004	.2901	.1977	.4750	.2341	.5651			.2189	.6356			.1581	.4980
.20	.0965	.2725	.1733	.4282	.2256	.5206	.2718	.5479	.0514	.5217	.2631	.3634	.2010	.4280
.25					.2109	.4660	.2542	.5130	.0654	.3310	.2552	.3547	.2160	.3609
.30	-.0254	.0661							.2498	.4908	.2500	.3521		.3050
.40	-.0377	.2340	-.1157	.0224	-.0377	.0295	-.1260	.0350	.0985	.3302	.2338	.3053	.980	.2412
.50			-.0823	.0930	-.1292	-.0295	-.1302	-.0336			-.1176	.0633	.1602	.1464
.60					-.1293	.0121	-.1161	.0239			-.1573	.3218	-.3053	-.3187
.70	-.0033	.1205	-.0096	.0397	-.1162	.0609	-.1552	-.0967	-.3308	-.2751	-.3414	.3218	-.2317	-.3329
.80	-.2216	-.1123	-.2380	-.1661			-.3312	-.2567	-.3414	-.2847	-.3169	.3211	-.2537	-.2542
.90	-.1881	-.1548	-.2750	-.2075	-.2876	-.1789	-.3057	-.2275	-.3060	-.2877	-.3011	-.2851	-.3095	-.2708
.95	-.1771	-.1680	-.2630	-.2159			-.2914	-.2112	-.2949	-.2846	-.2983	-.2823	-.3315	-.2792

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1679	.2005	.3328	.4577			.4812	.5873			.4315	.6278	.4392	.5205
.10	.174?	.1920					.4665	.5269	.4582	.5269			.4233	.4602
.15					.3734	.4323	.4157	.4825	.4358	.5081	.4723	.5460	.3714	.3910
.20	.1319	.1601					.3833	.4424	.3963	.4661			.3224	.3315
.25	-.0197	-.0055	.0022	.2360	.3138	.3682	.3566	.4020	.3868	.4264	.4209	.4653	.2955	.2871
.30			-.1278	-.0924			.3262	.3292	.3660	.3825	.4029	.4415	.2685	.2600
.40	.0474	.1131									.3179	.3173	.2334	.2056
.50							-.0938	-.0675	-.0866	-.0638	-.064	-.0868	.1330	.0608
.60	.0234	.0084	.0168	.0408	-.0961	-.0727	-.1025	-.0729	-.1035	-.0750	-.1865	-.0832	-.3192	-.3151
.70							-.2364	-.2283	-.1054	-.0712	-.3417	-.3239	-.3456	-.3011
.80	-.1893	-.1973	-.2454	-.2324	-.1083	-.0778	-.3263	-.2989	-.3113	-.2826	-.3102	-.3090		
.90	-.1956	-.1890	-.2707	-.2566	-.2915	-.2706	-.3055	-.2880	-.2856	-.2897	-.2978	-.2859	-.2870	-.2552
.95			-.2687	-.2548	-.2837	-.2545	-.2857	-.2706	-.2899	-.2853	-.2963	-.2831	-.2714	-.2462
					-.2721	-.2415								

TAIL 2

53

TABLE V. - CONTINUED
(e) α = 4.70°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0527	.3986	.0508	.6930	-.0097	.7787	-.0207	.8422	-.161	.9000	.0522	.787	.55	.8494
.10	.036:	.3665	.381:	.677	-.05:	.7000			.0850	.775			.723	.887
.15	.0507	.3761	.0869	.5561	.1203	.6900		.6163	.0750	.6577	.1203	.6666	.1.2	.55.6
.20	.061:	.3539	.0944	.5080	.201:	.5848	.1448	.6163	.195	.6901		.6311		.678
.25					.1.0	.5195	.1438	.5618	.514	.5851	.125	.5629	.290	.1053
.30	-.0637	.0972	-.512	.0560	-.684	.005:	-.686	-.0120	.1957	.5331	.302	.4290	.285	.3456
.40	-.0647	.322:	-.1193	.1926	-.1710	.0.64	-.1778	.0065	.514	-.0214	.587	.0533	.1.5	.2.04
.50					-.674	.0824	-.653	.0279			.1450	.085	.1.8	.1506
.60	-.0414	.687	-.0508	.1956	-.576	.203:	-.1922	-.0348	-.3553	.2463	-.3585	.2904	-.3.8	-.3256
.70	-.123.5	-.0750	-.2656	.1448			-.3549	-.1613	-.3481	.2484	-.3253	.288:	-.28C7	-.2837
.80	-.2017	-.372	-.3015	.1838	-.3089	-.1473	-.387	-.1516	-.3225	-.2301	-.3173	-.2930	-.3439	-.2492
.95	-.1750	-.51.4	-.2611	.1917			-.2886	-.1559	-.3056	-.22.14	-.3084	-.285:	-.342:	-.264:

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.208C	.2701	.3720	.4894			.4805	.5768	.4516	.4939	.4328	.5950	.4334	.5147
.10	.2105	.2383					.461:	.5101	.4357	.4833			.4011	.4543
.15					.3668	.4238	.4110	.4592	.4357	.4447	.4592	.5218	.3547	.3864
.20	.1469	.1741					.382C	.4186	.3838				.3072	.3221
.25	-.0635	-.0530	-.0007	.2291	.3146	.3484	.3533	.3787	.3748	.4039	.400:	.454:	.2795	.2725
.30			.281:	-.1023			.3152	.3108	.3471	.3693	.384:	.4266	.2521	.2383
.40	-.0011	.0303							.3471		.302c	.3030	.2.37	.1800
.50					-.1003	-.0757	-.0995	-.0665	-.0955	-.0656	-.3029		-.1.5	.035C
.60	.0078	.0097	-.0133	.0248			-.C6C	-.0741	-.120	-.0775	-.1078	-.0925	-.325:	.32:8
.70					-.1221	-.0858	-.2378	-.2305	-.1161	-.0765	-.1880	-.1851	-.3265	-.3296
.80	-.2150	-.2197	-.2625	-.2388	-.3208	-.292:	-.3292	-.3039	-.3138	-.287:	-.3424	-.3221	-.3568	
.90	-.2192	-.2093	-.2803	-.2861	-.3016	-.2717	-.3167	-.2942	-.2908	-.2931	-.3173	-.3145		
.95			-.2809	-.2926	-.2821	-.2512	-.2947	-.2749	-.29.4	-.2980	-.3002	-.2857	-.2772	-.2513
											-.2982	-.2833	-.2716	-.2413

TAIL 2

TABLE V.- CONTINUED
(f) α = 6, 70°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0212	.4820	-.0647	.7890	-.1414	.8522	-.1389	.9103	-.2091	.9504			-.1817	.9170
.10	-.0229	.4472	-.0267	.7007	-.0457	.7756			-.0253	.8292	-.0792	.3367	-.1759	.7313
.15	-.0054	.4647	-.0153	.6372	-.0115	.7068			-.0325	.7545			-.0138	.6012
.20	-.0232	.4515	-.0073	.5786	.0112	.6339	.3254	.6703	.0006	.6937	.0038	.7763	-.0496	.5249
.25					.0137	.5518	.3352	.6006	.0355	.6303	.3657	.6768	-.3508	.4185
.30	-.0936	.1425	-.850	.1331	-.2292	.0348	-.2095	-.0164	-.2395	.5087	.3055	.5034	-.3538	.3853
.40	-.0173	.4086	-.152	.2830	-.2314	.1049	-.2317	.0623	-.2059	.0044	.0244	.4575	-.3539	.3014
.50					-.2187	.2561	-.2251	.1246			-.2100	-.0308	-.0481	.1700
.60											-.2385	-.0495	-.3357	.3347
.70	-.0703	.2120	-.0796	.2407	-.2043	.2768	-.2560	.1301	-.3824	-.1969	-.3627	-.2615	-.3124	.3107
.80	-.2462	-.0381	-.2893	-.138			-.3527	-.0976	-.3476	-.566	-.3415	-.2649	-.3650	.2953
.90	-.2110	-.142	-.3012	-.1566	-.3217	-.1254	-.3259	-.1214	-.3301	-.312	-.3344	-.2626	-.3793	.2759
.95	-.1936	-.277	-.2299	-.1619			-.2879	-.1297	-.3089	-.1363	-.3179	-.2637	-.3523	.2825

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2069	.3042	.3991	.5403			.4788	.5541			.4163	.5839	-.1162	.5117
.10	.2351	.3224					.4600	.4977	.4385	.4925			-.3823	.4476
.15					.3786	.4122	.4028	.4567	.4160	.4610	.4389	.5064	-.3415	.3715
.20	.1797	.1991					.3686	.4138	.3599	.4457			.2555	.3073
.25	-.0923	-.0822	-.0031	.2096	.3047	.3471	.3394	.3836	.3597	.4062	.3847	.4370	-.2528	.2522
.30			-.1493	-.1153			.3015	.3145	.3331	.361	.3677	.4110	-.2327	.2236
.40	-.0406	-.0444			-.1044	-.0735	-.1045	-.0676	-.1020	-.0746	-.2983	.2868	-.0889	.1610
.50	-.0001	-.0053	-.0592	-.0315			-.1092	-.0756	-.1152	-.0795	-.1163	-.0961	-.0856	.0150
.60					-.1365	-.1106	-.2409	-.2388	-.3117	-.2388	-.1933	-.1847	-.3387	.3205
.70	-.2265	-.2342	-.2614	-.2406	-.3369	-.3105	-.3332	-.3084			-.3474	-.3251	-.3571	.3471
.80	-.2106	-.2310	-.2873	-.2843	-.3192	-.2934	-.3259	-.3023	-.2956	-.2976	-.3223	-.3217	-.2800	.2545
.95			-.2953	-.2979	-.2968	-.2753	-.3024	-.2809	-.2970	-.2980	-.3039	-.2849	-.2720	-.2372

TAIL 2

55

TABLE V.- CONTINUED
(g) α = 8.70°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.1130	.5464	-.1648	.8701	-.2525	.9303	-.2350	.9621	-.2948	1.0090				.9441
.10	-.0668	.5230	-.1261	.7762	-.1551	.8321			-.1379	.8799	-.1894	.8897	-.3417	.7687
.15	-.0460	.5185	-.1045	.7066	-.0906	.7588			-.1175	.8007			-.1729	.6413
.20	-.0013		-.0962	.6379	-.0843	.6846	-.0595	.7184	-.0964	.7361	-.0791	.7577	-.0787	.5635
.25	-.1154	.2217			-.0767	.5933	-.3617	.5464	-.0638	.6703	-.0705	.7215	-.0136	.4812
.30	-.0471	.1748	-.2343	.2588	-.2798	.0951	-.0593	.0519	-.0595	.6014	-.3770	.6147	-.0125	.4202
.40			-.1830	.3405	-.2841	.2534	-.2833	.1428	-.2600	.0194	-.3617	.4825		.2279
.50					-.2740	.3578	-.2688	.3355			-.2584	.0655		.1955
.60	-.0813	.2520	-.1121	.3006	-.2609	.3313	-.3012	.2079	-.3591	-.0649	-.2857	.0653	-.3633	.3393
.70	-.2528	.3072	-.3310	-.0860			-.3524	-.0768	-.3415	-.0808	-.3487	-.2216	-.4213	.3178
.80	-.2218	-.0845	-.3051	-.1294	-.3241		-.3271	-.0953	-.3247	-.0960	-.3560	-.2051	-.3965	.3080
.90	-.1838	-.0984	-.2274	-.1355	-.3241	-.0966	-.3087	-.1034	-.3149	-.1092	-.3462	-.1802	-.3962	.2929
.95											-.3292	-.1623	-.3922	.2981

Cp at y/b of

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1821	.2958	.4141	.5442			.4791	.5731	.4366	.4938	.402	.5753	.3952	.5011
.10	.1990	.2721				.4711	.4629	.5135	.436	.4767			.3746	.4431
.15					.3897		.4080	.4658	.4036	.4417	-.297	.4952	.3308	.3683
.20	.1782	.2388	-.0046	.2160	.3158	.3654	.3731	.4255	.3644	.4021	.3735	.4263	.2873	.3017
.25	-.0676	-.0256	-.0515	-.0187			-.3438	.3855	.3588	.3516	.3551	.3972	.2551	.2461
.30							-.3046	.3134	.3313		.2725	.2764	.2235	.2089
.40	-.0570	-.0496							-.1051	-.0774			.775	.408
.50					-.0950	-.0672	-.0852	-.0598	-.1165	-.0804	-.1198	-.0977	-.0727	-.0037
.60	-.0367	-.0456	-.3321	-.1185		-.1148	-.0993	-.0685	-.1115	-.0725	.949	-.1824	-.3477	-.3343
.70					-.1378	-.3204	-.2365	-.2285	-.3103	-.2817	-.3318	-.3184	-.3438	-.3475
.80	-.2290	-.2410	-.2640	-.2442	-.3404	-.3123	-.3331	-.3100			-.3216	-.3251		
.90	-.2484	-.2405	-.2958	-.2813	-.3347	-.3123	-.3312		-.2995	-.2980	-.3018	-.2962	-.2929	-.255
.95			-.3057	-.2984	-.3091	-.2894	-.3059	-.2863	-.2944	-.3043	-.2977	-.2847	-.2737	-.2335

TABLE V. - CONTINUED
(b) α = 10.5°

Cp at y/b of

x/c	0.02		0.22		0.44		0.55		0.67		0.88	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.93	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

TABLE V.- CONTINUED
(i) α = 12.70°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05					-.3725	.3983		.3373		.0779				
.10														
.15														
.20						.7653		.3006		.8246				
.25										.7542	-.2505			
.30										.0761	-.2733			
.40					-.3701	.4354		.2786		.2213				
.50					-.3630			.5026						
.60					-.3424			.478						
.70		.3508	-.1767	.4253	-.3156			-.2726	-.3508	-.0248	-.3557			
.80		.0596	-.3489	-.0281				-.0300	-.3436	-.0472	-.3417			
.90		-.0197	-.3060	-.3567				-.0485	-.3356	-.0597	-.3426			
.95		-.0247	-.2059	-.0813	-.3395	-.0397		-.0579	-.3272	-.0702	-.3355			

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.151.	.2836	.3008	.5014			.5532	.6483	.4858	.5360	.159	.5722	.3861	.4947
.10	.1613	.2733					.534.	.5907					.3782	.4471
.15					.4649	.5005	.4807	.53C8	.4568	.5165	.4237	.4947	.3376	.3660
.20	.1262	.201.					.4285	.4790	.4020	.4766			.2978	.3031
.25	-.0904	-.034.	-.0904	.1240	.3353	.3845	.3888	.4318	.3918	.4366	.3894	.4347	.262.	.2474
.30	-.2212		-.2212	-.900			.3453	.3592	.3617	.3893	.3736	.4033	.252.	.211.
.40	-.0591	-.021.8					-.0718	-.0443	-.0820	-.0525	.2928	.2764	.173.	.393
.50					-.1140	-.0339	-.0913	-.0680	-.0789	-.0452	-.117	-.0830	.056.	-.0137
.60	-.0826	-.1059	-.2129	-.1914					-.0748	-.0421	.1740	-.1554	-.3505	-.3321
.70					-.1606	-.1469	-.2383	-.2362	-.2961	-.2727	-.3222	-.2961	-.3357	-.3353
.80	-.2674	-.2793	-.3063	-.3065	-.3559	-.3419	-.3368	-.3156	-.3071	-.3027	-.3261	-.3083		
.90	-.2586	-.2622	-.3109	-.3074	-.3587	-.3495	-.3462	-.3292	-.2960	-.3065	-.2918	-.2918	.299.	-.2644
.95			-.3131	-.3079	-.3337	-.3250	-.3195	-.3208			-.2823	-.2729	-.2713	-.2275

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.4 U.S.	0.4 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.3373	.6754	-.4191	1.0613	-.4342	1.0700	-.4427	.1031	-.4434	.1249	-.4347	1.2407		.995
.10	-.1705	.7357	-.3928	.9889	-.4246	.3179	-.4296		-.4287	1.0526			-.1375	.287
.15	-.1580	.8245	-.3571	.9094	-.3866	.9453	-.3894		-.3974	.3840			-.264	.782
.20	-.1292	.8149	-.3425	.8108	-.3693	.8593	-.3305	.9027	-.3716	.9253	-.3650	.9315	-.1075	.7
.25					-.3537	.7805	-.355	1.265	-.3528	.8	-.3658	.9830	-.2541	.52
.30	-.2255	.7350			-.4324	.6303	-.4268	.5786	-.3384	.79	-.3466	.8038	-.3090	.533
.40	-.895	.6887	-.3182	.6139	-.4046	.6636	-.4238	.6085	-.4304	.4965	-.3362	.9335	-.3031	.170
.50			-.2507	.5815	-.3678	.5796	-.3894	.5866			-.3962	.75.3	-.3157	.205
.60											-.3846	.1709	-.1424	.539
.70	-.374	.4307	-.2478	.5359	-.3413	.5169	-.3164	.3382	-.4123	.0126	-.3625		-.383	.5
.80	-.3083	.1263	-.3638	.0111			-.3902	.0173	-.3984	.0004	-.3601	.0013	-.4410	.152
.90	-.2847	.0552	-.3386	-.0145	-.3472	.0083	-.3499	.0005	-.3802	-.0085	-.3627	-.0409	-.4277	.570
.95	-.2528	.0461	-.2983	-.0236			-.3151	-.0079	-.3631	-.0172	-.3529	-.0499	-.4299	.855

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.1235	.2329	.2452	.4123			.3629	.6305			.5218	.6997	.4503	.5533
.10	-.1352	.2228					.5526	.6517	.6105	.6654	.5073	.5738	.4289	.4984
.15					.4140	.4375	.5410	.5620	.5866	.6209			.39.	.179
.20	.1079	.1710			.1930	.2186	.4561	.4562	.4961	.5502	.4752	.5241	.3419	.3519
.25	-.1061	-.0640	-.0370	.2090			.3760	.3656	.4528	.4831	.4173	.4877	.3692	.2976
.30			-.1669	-.1371			.3066	.2751	.4191	.4248			.2713	.2638
.40	-.0647	-.0091							-.0603	-.0452	.3522	.3470	.2255	.1967
.50					-.2659	-.2530	-.1656	-.1608	-.0952	-.0778	-.0774	-.0546	.1097	.0389
.60	-.0737	-.0877	-.1785	-.1722			-.2013	-.1958	-.1140	-.0958	-.1552	-.1488	-.335	-.3.37
.70					-.3212	-.3095	-.3227	-.3255	-.3252	-.3088	-.3208	-.3013	-.33.	-.3.65
.80	-.3283	-.3420	-.3419	-.3281	-.4217	-.4190	-.3973	-.3866			-.3283	-.3138		
.90	-.3343	-.3512	-.3531	-.3437	-.4078	-.4034	-.4035	-.3945	-.3485	-.3409	-.2632	-.3071	.2457	.2170
.95			-.3448	-.3410	-.4012	-.3953	-.3888	-.3892	-.3386	-.3436	-.2916	-.2925	-.2294	.1899

TAIL 2

TABLE V. - CONCLUDED
(k) α = 18.00°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05				.0968	-.4515	-.0955	-.4644	-1.1281	-.4677	-1.1416				
.10	-.2350		-.4179	-.0368	-.4530	-1.0515			-.4706	-.9962	-.4543			
.15			-.3826	.2533	-.4350	.8894	-.4101	-.9050	-.4655	-1.0050	-.4117		-.4480	
.20	-.1394		-.3587		-.4155		-.4067	.9504	-.4367	-.9701	-.4108		-.4361	
.25					-.4046		-.4099	.8812	-.4037	-.1077	-.4150	.2555		
.30	-.2436	.7627							-.3951	.8401	-.3851		-.3655	
.40	-.2091	.7451		.5838	-.4488	.6795	-.4549	.6497	-.4477	.5819	-.3873	.3954	-.3718	
.50			-.2946	.6140	-.1161	.6621	-.4391	.6650			-.3935	.5955	-.3880	
.60					-.3838	.6313	-.4155	.6220			-.3748	.5343		
.70	-.1555	.4684	-.3105	.5822	-.3798	.5450	-.4133	.3597	-.4101	.0230	-.3575	.5050	-.4484	
.80	-.3192	.1431	-.3943	.0385			-.3816	.0315	-.4085	.0174	-.3620	.5050	-.4535	
.90	-.2904	.0786	-.3670	.0054	-.3737	.0352	-.3501	.0208	-.3846	.0135	-.2533	.5178	-.4377	
.95	-.2532	.0768	-.3363	-.0118			-.3502	.0152	-.3647	.0063	-.3809	-.0187	-.3358	

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.1121	-.2291	-.2291	.3935			-.2830	.4745			.5534	.7512	-.5005	-.5852
.10	-.1260	-.2270				.3588	-.4101	.5505	-.5677	.6427				
.15	-.1042	-.1700			.3095		-.4255	.4817	-.5556	.5978	-.5584	.5298	-.4437	
.20	-.1062	-.2618	-.0598	.1852	-.1335	.1567	-.3055	.7803	-.4669	.5142			.3658	
.25			-.1815	.1455			-.2554	.2805	-.4253	.4359	-.5015	.5351	-.3622	
.30							-.2553	.1855	-.3753	.3675	-.4614	-.337	-.3290	
.40	-.0718	-.0138			-.2947	-.2884	-.2591	.2242	-.0887	-.0983	-.3615	-.3146	-.2825	
.50	-.0808	-.0655	-.0958	-.1613			-.2553	-.2613	-.1636	-.1661	-.3572	-.710	-.3353	
.60					-.3499	-.3432	-.3336	-.363	-.3535	-.3517	-.325	-.3175	-.3265	
.80	-.3223	-.3350	-.3462	-.3328	-.4425	-.4384	-.4022	-.425			-.3515	-.3348		
.90	-.3260	-.3613	-.3628	-.3507	-.4261	-.4269	-.4283	-.4256	-.3784	-.3744	-.3163	-.3254	-.2583	
.95	-.3200		-.3605	-.3583	-.4212	-.4194	-.4207	-.4197	-.3774	-.3798	-.3101		-.2517	

TAIL 2

TABLE VI. - PRESSURE COEFFICIENTS, $\phi = 0°$, $\delta = 0°$, $M = 2.36$

(a) $\alpha = -4.08°$

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0743	.1255	.2157		.1769	.2758	.1875	.3476		.2076				.2299
.10	.1069	.1431	.2501	.2977	.2942	.3072		.3130	.2121	.3067	.2046	.2932		.3159
.15	.0945	.1085	.291	.2715	.2063	.302			.2033	.3095				.2760
.20	.0777	.0353	.900	.2547	.2030	.2625	.1998	.2924	.2046	.3036	.2093	.2653		.2510
.25	-.0255	-.0375			.1906	.2835	.2015	.2914	.2071	.2955	.2097	.3014		.2330
.30	-.0156	-.0225							.2046	.2911	.2090	.3039		.2159
.40	.0007	.0097	-.0329	-.2217	-.0032	-.0225	.0043	.0371	.0114	.0534	.2007	.2653		.1960
.50			-.0411	-.0355	-.0131	-.0163	-.0074	-.023			.0428	.2332		.1509
.70	-.0223	-.0200	-.0200	-.0093	-.0173	-.0077	.061	.0257	-.0087	.0251	-.1561	.0753		.1367
.80	-.1073	-.0985	-.212	-.1063	-.0257	-.0015	-.0365	-.0282	-.245	-.1121	-.1353	-.1250		.1354
.90	-.0962	-.0900	-.1423	-.1272	-.1285	-.1501	-.1302	-.1470	-.1186	-.1360	-.1172	-.1272		.1376
.95	-.0994	-.0920	-.1352	-.1279	-.1341	-.1501	-.1223	-.1349	-.1157	-.1240	-.1391	-.1162		-.1153

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2152	.0490	.4544	.1267			.4141	.1059			.4455	.1200	.3298	.1201
.10	.2158	.0331					.4384	.1574					.3848	.1396
.15					.4537	.1427	.4441	.1461					.3580	.1239
.20	.2050	.0378					.4533	.1385	.4442	.1584			.3465	.1058
.25	.0536	-.0341	.1124	.0632	.4341	.1289	.4516	.1362	.4456	.1442	.4320	.1456	.3393	.0948
.30			.0539	-.0787			.4360	.1230	.4341	.1428	.4404	.1742	.3275	.0920
.40	.0855	-.0384							.4439	.1425	.4248	.1208	.3118	.0862
.50	.1522	.0085	.0438	-.0782	.0773	-.0682	.0910	-.0597	.1245	-.0389	.1166	-.0464	.2635	.0465
.70							.0825	-.0706	.1004	-.0604	.0562	-.0915	-.1097	-.1275
.80	-.0647	-.0921	-.0757	-.1410	.0601	-.0831	-.0217	-.1311	-.0840	-.1427	-.0838	-.1226	-.1125	-.1206
.90	-.0410	-.1208	-.0850	-.1312	-.1004	-.1177	-.1017	-.1191	-.1079	-.1189	-.1137	-.1180	-.1077	-.1419
.95	-.0926	-.1264	-.0926	-.1264	-.1242	-.1187	-.1182	-.1185	-.1150	-.1156	-.1193	-.1184	-.1181	-.1508

61

TABLE VI.- CONTINUED
(b) α = -2.07°

TAIL 1

x/c	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0692	.1160	.2219		.1833	.2793	.1942	.3545		.2141			.2470	.2254
.10	.0876	.1110	.2014	.3005	.2090	.3103		.3193	.2181	.3027	.2105	.2985	.2274	.2065
.15	.0638	.1100	.1863	.2759	.2117	.3062			.2071	.3103			.1832	.2455
.20	.3732	.1021	.1759	.2520	.2090	.2923	.2001	.2954	.2078	.3041	.2114	.2982	.1732	.2515
.25	.0141	-.0226			.2031	.2979	.2057	.2943	.2103	.2952	.2107	.3037	.1553	.2299
.30	-.0023	-.0072							.2072	.2998	.2116	.3006	.1368	.2307
.40	-.0240	.0358	-.0382	-.0217	-.0038	.0242	.2064	.0319	.0129	.0582	.2032	.2914	.279	.1925
.50			-.0452	-.0353	-.0154	.2081	.2050	.0182			.0112	.0424	.279	.1535
.60					-.0198	-.0005	-.0033	.0180	-.0078	.0224	.0201	-.0157	.1134	.1555
.70	-.0143		-.0100	-.0023	-.0298	-.0077	-.0231	-.0323	-.1255	-.1094	-.357	-.1229	.1362	.1353
.80	-.0861	-.0713	-.1198	-.1029			-.1450	-.1351	-.1422	-.1354	-.1300	-.1353	.1411	.1355
.90	-.0836	-.0760	-.1407	-.1272	-.1256	-.1443	-.1283	-.1424	-.1193	-.1355	-.164	-.1259	.1395	.1385
.95	-.0963	-.0816	-.1299	-.1275			-.1222	-.1284	-.1155	-.1236	-.1137	-.1154	-.1122	

TAIL 2

x/c	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.88		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1600	.0943	.3626	.1983			.3263	.1609	.3548		.3574	.1710	.2524	.1669
.10	.1637	.0721					.3479	.2188	.3591	.2166			.3125	.1874
.15					.3581	.2077	.3532	.2066	.3591	.2040			.2883	.1649
.20	.1545	.0733	.1033	.1177	.3548	.1932	.3532	.1994	.3470	.2039			.2724	.1459
.25	.0245	-.0269	.1033	.1177			.3591	.1970	.3510	.2034	.3449	.2020	.2633	.1312
.30			.0325	-.0402			.3562	.1815	.3482	.1978	.3527	.2001	.2563	.1235
.40	.0520	-.0156									.3396	.1729	.2442	.1215
.50							.0536	-.0257	.0859	-.0061	.0683	-.0190	.1997	.0712
.60	.1118	.0212	.0028	-.0598	.0421	-.0367	.0462	-.0364	.0595	-.0270	.0140	-.0687	.1202	.1275
.70	-.0725	-.0852	-.0989	-.1361	.0235	-.0543	-.0472	-.1124	-.0508	-.0328	-.1079	-.1335	-.1202	-.1342
.80					-.1199	-.1283	-.1214	-.1348	-.1064	-.1453	-.1231	-.1162	-.1219	
.90	-.0616	-.1152	-.1086	-.1269	-.1370	-.1232	-.1330	-.1235	-.1254	-.1178	-.1308	-.1135	-.1239	-.1106
.95			-.1138	-.1257	-.1336	-.1218	-.1322	-.1233	-.1278	-.1189	-.1258	-.1132	-.195	-.1236

TABLE VI.- CONTINUED
(c) α = -0.08°

TAIL 1

x/c	0.02		0.22		0.44		0.55		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0678	.1284	.2232	.2785	.1871	.2815	.1960	.2534		.2200			.2489	.2231
.10			.2671	.3031										
.15			.1906	.2829	.2139									
.20	.0814	.1204	.1817		.2112	.2945	.2040		.2119	.3105	.2152	.3005		
.25		.0251			.2068			.2944	.2135	.3015	.2122	.3057		
.30	.0087	.0093							.2107	.2959	.2114	.2935		
.40	.0123	.0253	.0328	.0136	.0030	.0255	.0052	.0333	.0141	.0534	.2043	.2914		
.50			.0414	.0281	.0149	.0165	.0052	.0131				.2419		
.60					.0190	.0029		.0185	.0073			.1228		
.70	.0076	.0303	.0184	.0063	.0281	.0065	.0333	.0303	.0250	.0063	.0368		.1342	.1360
.80	.0862	.0656	.1193	.1065			.1438	.1325	.1413	.1330	.1290	.1361	.1310	.1367
.90	.0817	.0750	.1358	.1244	.1244	.1413	.1254	.1387	.1183	.1314	.1152	.1227		.1427
.95	.0845	.0797	.1270	.1225			.1199	.1251	.1142	.1195	.1129	.1137		.1060

TAIL 2

x/c	0.02		0.22		0.44		0.56		0.67		0.88		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1237	.1317	.2754	.2785			.2533	.2199	.2790	.2802	.2843	.2379	.1903	.2261
.10	.1185	.1097					.2758	.2844	.2829	.2676			.2486	.2465
.15					.2788	.2769	.2757	.2715	.2726	.2686			.2242	.2182
.20	.1075	.1114					.2785	.2660	.2769	.2679			.2135	.1973
.25	-.0039	.0008	.0644	.1825	.2729	.2616	.2773	.2632	.2736	.2621	.2712	.2577	.2022	.1773
.30	-.0042	-.0036					.2742	.2472			.2774	.2674	.1960	.1719
.40	.0213	.0129									.2649	.2389	.1890	.1597
.60	.0730	.0450	-.0305	-.0398	.0062	-.0024	.0155	.0113	.0170	.0102	.0294	.0192	.1505	.1024
.70					-.0112	-.0195	.0086	-.0003	.0095	.0038	-.0224	-.0381	-.1269	-.1283
.80	-.0778	-.0731	-.1161	-.1258	-.1373	-.1406	-.1387	-.1411	-.1273	-.1287	-.1291	-.1332	-.1381	-.1425
.90	-.0791	-.1024	-.1269	-.1308	-.1366	-.1296	-.1312	-.1316	-.1183	-.1161	-.1375	-.1293	-.1094	-.0904
.95			-.1296	-.1245	-.1241	-.1212	-.1203	-.1207	-.1145	-.1126	-.1118	-.1090	-.1018	-.1010

63

TABLE VI.- CONTINUED
(d) α = 1.92°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0751	.1503	.2258		.1915	.2845	.1978	.3539		.2240			.2492	.2274
.10	.1146	.1544	.2114	.3095	.2148	.3169		.3311	.2277	.3063	.2182		.2245	.2918
.15	.1072	.1535	.1966	.2932	.2155	.3154			.2142	.3104			.249	.2687
.20	.0905	.1396	.1870	.2681	.2140	.3025	.2112	.2971	.2149	.3138	.2200	.3104	.671	.2493
.25	-.029	-.0275			.2099	.2981	.2151	.2999	.2173	.3052	.2154	.3114	.1539	.2186
.30	-.0123	-.0107							.2147	.3000	.2152	.3014	.1368	.2065
.40	-.0018	-.0113	-.0298	-.0087	-.0001	.0285	.0068	.0354	.0147	.0517	.2077	.2941	.1368	.1914
.50			-.0401	-.0241	-.0116	.0127	-.0043	-.0213			.0155	.0445	.1225	.1563
.60					-.0153	.0057	-.0038	.0194	-.0081	.0233	-.0165	.0154	.1301	.1266
.70	-.0076	-.0348	-.0292	-.0136	-.0252	-.0009	-.0315	-.0283	-.1255	-.1074	-.1379	-.1243	.1480	.1395
.80	-.0923	-.0656	-.1290	-.1179			-.1426	-.1312	-.1408	-.1324	-.1316	-.1384	.1150	.1404
.90	-.0825	-.0769	-.1304	-.1290	.1239	.1402	-.1254	-.1366	-.1180	-.1293	-.1166	-.1225		
.95	-.0858	-.0800	-.1221	-.1227			-.1187	-.1234	-.1135	-.1177	-.1140	-.1138		-.1078

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0886	.1687	.1973	.3678			.1864	.2843			.2193	.3065	.1378	.2825
.10	.0839	.1495					.2124	.3586	.2124	.3516			.1911	.3056
.15					.2073	.3571	.2030	.3442	.2148	.3401			.1697	.2810
.20	.0628	.1549	.0215	.2422	.2014	.3368	.2054	.3403	.2073	.3405	.2068	.3359	.1619	.2555
.25	-.0320	.0304	-.0404	.0330			.2065	.3406	.2100	.3408	.2111	.3366	.1525	.2332
.30	-.0008	.0458					.2045	.3179	.2067	.3360	.1998	.3052	.147C	.2299
.40					-.0297	.0334	-.0232	.0487	-.0022	.0719	-.0075	.0596	.1432	.2099
.50	.0393	.0738	-.0517	-.0088			-.0304	.0359	-.0213	.0513	-.0543	-.0069	.1099	.1408
.60					-.0469	.0154	-.1006	-.0645	-.0274	.0447	-.1480	-.1106	.1339	.1203
.70					-.1494	-.1240	-.1447	-.1231	-.1467	-.1088	-.1299	-.1220	.1464	.1255
.80	-.0823	-.0596	-.1330	-.1062	-.1306	-.1358	-.1281	-.1305	-.1206	-.1220	-.1227	-.1265	.1171	.1113
.90	-.0906	-.0869	-.1411	-.1183	-.1278	-.1306	-.1261	-.1286	-.1228	-.1250	-.1218	-.1238	.1243	.1026
.95			-.1341	-.1199										

64

FIGURE VII.- CONTINUED
AI = 3.72°

Cp at η/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.88	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.081?	.1533	.2334		.1963	.2902		.3555				
.10	.1255		.3003	.3207								
.15	.1140	.1726	.2036	.3042								
.20		.1561	.1245	.2756				.3028				
.25		-.0255					.3027	.3034				
.30	-.0155	-.0058										
.40	-.0075	.0053	-.0275	-.0050	.0022	.0280	.042		.0071	.3005		
.50			-.0379	-.0224	-.0091							
.60			-.0306	-.0147	-.0135							
.70	-.0155	.0270	-.0348	-.1223	-.0224	-.0035	-.0255	-.0203	-.0073	.0940		
.80	-.0353	-.0661	-.1348	-.1341	-.1252	-.1375	-.1409	-.1311	-.1303	-.1389	-.1217	
.90	-.0845	-.0756	-.1292	-.1341			-.1174	-.1274	-.3035	-.1217		
.95	-.0855	-.0763	-.1221	-.1235			-.1129	-.1150	-.1144	-.1242		

TAIL 1

Cp at η/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0477	.2192	.1294	.4595			.260	.3685		.4405	.1607	.3854	.0943	.3469
.10	.0491	-.1953						.4604	.532	.4405			.1438	.3748
.15					.1437	.4422		.4313	.1513	.4222				.3515
.20	.0273	.2098	-.0155	.3003	.1387	.4110	.431	.4235	.1422	.4253	.549	.4154	.1208	.3137
.25	-.0554	-.0505	-.0746	.0716			.435	.4012	.507	.4283	.560	.4204	.1155	.3021
.30	-.0225	.0778							-.1479	-.3207	.1473	.3805		.2886
.40					-.0628	.0679	-.0652	.0855	-.0362	-.1160	-.0393	.1065	.1093	.2662
.50	.0178	.1042	-.0663	.0312	-.0768	.0512	-.0544	.0720	-.0555	.0928	-.0813	.0314	-.0789	
.60							-.1246	-.0377	-.0617	.0834	-.1437	-.0863	-.1403	-.1123
.70							-.1315	-.036	-.552	-.0834			-.1435	
.80	-.0852	-.0443	-.1463	-.0862	-.1305	-.1032	-.1286	-.1122	-.1252	-.1035	-.1326	-.3826	-.1337	-.1052
.90	-.0360	-.0711	-.1494	-.0978	-.1302	-.1179	-.1292	-.1161	-.1287	-.1103	-.1314	-.1055	-.1482	-.1128
.95			-.1380	-.1004	-.1298	-.1215					-.1308	-.1148		

TAIL 2

65

TABLE VI - CONTINUED
(1) α = 5.92°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0862	.1718	.2430	.5467			.158?	.3597		.2288	.2245	.3109	.2436	.2250
.10	.1393	.1898	.2303	.3351	.2022	.3078		.3485	.2355	.3174	.2212		.2212	.2773
.15	.1257	.1892	.2136	.3193	.2255	.3211			.2269	.3037			.1713	.2543
.20	.1042	.1701	.2030	.2886	.2240	.3255	.2194	.3105	.2202	.3189	.2274	.3200	.1652	.2393
.25	-.0264	-.0206	-.0522		.2225	.3180	.222?		.2234	.3168	.2212	.3167	.1554	.2247
.30	-.0118	-.0049	-.1061		.2200	.2113	.022?	.3219	.2210	.3109	.2189	.3075	.1515	.2116
.40	-.0068	-.0095			.0040	.0411	.0106		.0186	.0560	.2142	.3013	.1498	.2043
.50			-.0250	-.0000	-.0054	-.0231	-.0015	.0316			.0169	.0480	.1339	.1755
.60			-.0058	-.0173	-.0088	-.0187	-.0082	.0270	-.0051	.0255	-.0151	.0153	.1229	.119?
.70	-.0195	.0190	-.0302	-.0124	-.0165	-.0066	-.0277	-.0209	-.1244	-.1072	-.1387	-.1262	-.1157	-.1379
.80	-.0961	-.0673	-.1345	-.1233			-.139?	-.1275	-.1404	-.1304	-.127?	-.1411	-.1198	-.1005
.90	-.0791	-.0729	-.1217	-.1350	-.1210	-.137?	-.1266	-.1347	-.1159	-.1253	-.1162	-.1222		
.95	-.0786	-.0716	-.1204	-.1233		-.1222	-.1136	-.1222	-.1116	-.1144	-.146?	-.1150		-.1462

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0050	.2662	.0690	.5467			.0705	.4718	.0990	.5495	.1129	.4833	.0482	.4127
.10	.0118	.2349				.5308	.0885	.5540	.0991	.5311			.0933	.4673
.15					.0865	.532?		.5325	.0922	.5305			.0838	.4391
.20	-.0034	.2614	-.0522	.3533	.0802	.4772	.047?	.5182	.0950	.5200	.0990	.5279	.0809	.4100
.25	-.0838	.0902	-.1061	.1056			.032?	.300?	.0935	.5021	.0987	.5291	.0774	.3860
.30						.465?			-.0689	.1557	.0907	.4658	.0770	.3737
.40	-.0450	.1171			.1030		-.0855	.1213	-.0855	.1304	-.0686	.1475	.0767	.3458
.50					-.0924		.095?	.0093	-.0911	.1210	-.1081	.0680	.0509	.2440
.60	-.0625	.1423	-.0886	.0748	-.1026	.0693	-.1414	-.0120	-.1433	-.0603	-.1354	-.0652	-.1411	-.0991
.70	-.0911	-.0234	-.1574	-.0620	-.1356	-.0315	-.1313	-.0823			-.1342	-.0812	-.1389	-.1063
.80	-.1039	-.0506	-.1506	-.0733	-.1374	-.0964	-.1313	-.0904	-.1282	-.0833	-.1340	-.0899	-.1481	-.0892
.90					-.1378	-.106?	-.131?	-.0953	-.1314	-.0898	-.1343	-.0952	-.1603	-.0964
.95	-.1469	-.0761												

TAIL 2

66

TABLE VI. - CONTINUED
(αj i = 7.3°)

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.93 U.S.	0.93 L.S.
.05	.0947	.1634	.2549	.3531	.2065	.3052	.187?	.3505		.2210	.0668		.2402	.2273
.10	.1495	.2099	.2422	.3344	.2285	.3240		.3475					.2117	.2784
.15	.1354	.2063	.2254	.3044	.2294	.3316			.234?	.3195	.220?			
.20	.1142	.1845	.2153	.3044	.2280	.1263			.2243	.3005			.1753	.2515
.25	-.0188	.0157			.2265	.3034	.2273	.3133	.224?	.3131	.243?	.3240	.1662	.2382
.30	-.0057	-.0022	-.0204	-.0053			.2277	.3250	.22?	.3204	.230?	.3208	.1583	.225?
.40	-.0031	.0179	-.0315	-.0107	.0081	.0455	.0124	.0472	.22?	.2181	.21?	.3208		.21?
.50					-.0002	.0305	.0000	.0322	.0199	.0602	.215?	.3050	.1561	.2073
.60	-.0223	.0200	-.0282	-.0092	-.0034	.0246	.00?	.0289	-.0043	-.0279	.0155	.0482	.1402	.925
.70	-.0964	-.0686	-.1323	-.1222	-.0113	.0147	-.0301	-.0181	-.1239	-.104C	-.1400	-.1288	-.1181	-.1295
.80	-.0755	-.0691	-.1154	-.1334			-.1341	-.1217	-.1353	-.129C	-.1231	-.1400	-.1087	-.1295
.90	-.0725	-.0659	-.1150	-.1221	-.1103	-.1326	-.1126	-.1289	-.1124	-.1259	-.1155	-.1212	-.165	-.1055
.95					-.1175		-.1080	-.1175	-.1093	-.1146	-.1145	-.1158		-.560

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.57 U.S.	0.57 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0332	.3228	.0163	.6241			.0218	.5811	.0505	.6934	.0668	.6758	.0115	.5758
.10	-.0210	.2651					.0480	.6661	.0497	.642C			.0550	.645?
.15					.0341	.6032	-.0425	.6208	.0424	.6224			.0530	.5852
.20	-.0289	.3088	-.0846	.4008	.0268	.5402	-.0368	.5337	-.0433	.6008	.0539	.6295	.0557	.5367
.25	-.1008	.1199	-.1330	.1408			-.0373	.5715	-.0423	.5771	.0515	.6185	.0553	.4855
.30							-.0329	.5254	-.0959	.1825	.0432	.5272	.0568	.4545
.40	-.0622	.1630			-.1187	.1409	-.1128	.1582	-.1124	.1654	-.0956	.1797	.0321	.4035
.50							-.1229	.1508	-.1179	.1606				.275?
.60	-.0266	.1905	-.1151	.1242	-.1265	-.1321	-.1501	-.0164	-.1383	-.0363	-.1309	-.0996	-.1403	-.0926
.70											-.1360	-.0458	-.1370	-.1422
.80	-.0954	.0017	-.1732	-.0300	-.1420	-.0576	-.1375	-.0579	-.1322	-.0589	-.1360	-.0603		
.90	-.1140	-.0266	-.1678	-.0428	-.1450	-.0712	-.1378	-.0654	-.1348	-.0647	-.1365	-.0686	-.1489	-.1060
.95			-.1553	-.0480	-.1452	-.0749	-.1379	-.0699			-.1355	-.0757	-.1569	-.1167

TAIL 2

TABLE VI. - CONTINUED
(h) α = 9.92°

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1030	.2063	.2568	.3665	.2090	.3148	.1870	.3541		.3327			.2602	.2402
.10	.1655	.2784	.2634	.3529	.2239	.3273		.3535	.2430	.3378	.3360	.3372	.2174	.2523
.15	.1482	.2247	.2378	.3230	.2318	.3380			.2328	.3148			.1895	.2532
.20	.1262	.2002	.2236		.2318	.3353	.2233	.3252	.2225	.3260	.24.0	.3358	.1813	.2527
.25	-.0115	.0007		.4655	.2292	.3320	.2325	.3318	.2339	.3350	.203	.3655	.745	.2415
.30	-.0007	.0110	-.1545	.1798					.2292	.3272	.2695	.3247	.72	.232
.40	.31.1	.31.1	-.1025		.065	.0434	.2012	.1339	.2293	.0358			.9	
.50				-.0617	-.0023	-.0403	-.0012	-.0222	.047		.322	.744	.1650	.20.1
.60	-.0482	-.0262	-.0224	-.0022	-.0061	-.0355	-.0033	-.0243	-.0039	-.0254	-.0152	-.265	-.1143	-.1025
.70	-.0117		-.0279	-.0135	-.0062	-.0243	-.0553	-.0165	-.1219	.041	-.355	-.301	-.1040	-.114
.80	-.0853	-.0695	-.1279		-.1064		-.1273	-.1203	-.129	-.1293	-.12.1	-.381	-.1186	-.0395
.90	-.0725	-.0865	-.1.04	-.1302			-.1083	-.1258	-.1093	-.224	-.1.1	-.251		
.95	-.0682	-.0614	-.1.60	-.1191	-.1064	-.1288	-.1049	-.1149	-.1067	-.114	-.1.3	-.155		-.1648

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	-.0632	.3352	-.0302	.6899			-.0229	.7345		.7745	.2203	.8703	-.0225	.9025
.10	-.0447	.2784					-.0005	.7470	-.0051	.7076			-.0245	.7518
.15					-.0118	.6615	-.0038	.6501	-.0041	.6907			.0314	.6793
.20	-.0464	.3393			-.0211	.5912	-.0072	.5535	-.0025	.5692	.0132	.7051	.0358	.6103
.25	-.1113	.1966	-.1114	.4155			-.0098	.5245	-.0022	.5289	.0502	.5819	.0363	.5523
.30			-.1545	.1798			-.0138	.5674	-.0035	.5289	.50.3	.5699	.0364	.51.2
.40	-.081.2	.2026			-.1402	.1796	-.1353	.1854	-.1216	.2056	.27	.2028	.0350	.4383
.50							-.1463	.1935	-.1355	.2021	.19.	.259	.0147	.2988
.60	-.0482	.2392	-.1278	.1727	-.1437	.1762	-.1547	.0461	-.1401	.202	.153	.252	-.1513	-.0857
.70					-.1520	-.0318	-.1494	-.0317	-.1441	.0137	.153	.259	-.1452	-.107H
.80	-.1056	.0281	-.1866	.0012	-.1545	-.0429	-.1428	-.0383	-.1407	.0366	.14.7	-.0366		
.90	-.1255	-.0031	-.1672	-.0147	-.1540	-.0446	-.1493	-.0430	-.1436	.0423	.145	-.014	-.1651	-.1048
.95			-.1457	-.0185							.148	-.0544	-.1809	-.1161

TAIL 2

TABLE VI. - CONTINUED
(i) α = 11.72°

Cp at η/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.89 U.S.	0.89 L.S.	0.98 U.S.	0.98 L.S.
.05	.1154	.2250	.2840		.2367	.3509	.2129	.3836		.2597			.2846	.2577
.10	.1789	.2469	.2787	.4021	.2530	.3619		.3835				.3540	.2285	.3115
.15	.1595	.2425	.2591	.3817	.2600	.3726			.2685	.3677	.2525		.2083	.2833
.20	.1376	.2169	.2489	.3487	.2590	.3676	.2533	.3502	.2581	.3445		.3652	.2025	.2732
.25	-.0045	.0108			.2559	.3639	.2591	.3625	.2573	.3571	.2617	.3612	.1974	.2646
.30	-.0086	-.0208							.2585	.3610	.2586	.3514	.1964	.2569
.40	-.0134	-.0447	-.0060	.0231	.0222	.0617	.0260	.0643	.2534	.3517	.2556	.3410	.1955	.2531
.50			-.0162	.0057	.0137	.0536	.0125	.0473	.0363	.082	.2465	.0611	.1901	.2301
.60	-.0124				.0102	-.0438	.0062	.0376	.300	.0415	.2334	.0495		.0970
.70	-.0124	-.0333	-.0197	.0025	.0036	.0327	-.0207	-.0063	-.124	-.0958	-.078	-.1246	-.1059	-.0970
.80	-.096	-.0682	-.1249	-.1181			-.1256	-.1135	-.1273	-.1224	-.335	-.1313	-.0956	-.0837
.90	-.0631	-.0640	-.069	-.1256	-.1040	-.1250	-.1043	-.1201	-.031	-.1151	-.1159	-.1131	-.1278	
.95	-.0631	-.0573	-.1063	-.1141			-.0983	-.1083	-.0999	-.1033	-.1081	-.1088		-.1670

TAIL 1

Cp at η/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.89 U.S.	0.89 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0807	.3195	-.0699	.7392			-.0627	.8513			-.0397	.9768	-.0679	.9183
.10	-.0592	.2686					-.0410	.8206	-.0332	.8400			-.0176	.8241
.15					-.0510	.7178	-.0432	.7562	-.0344	.7781			-.0019	.7433
.20	-.0637	.3509					-.0467	.7169	-.0398	.7560			-.0063	.6670
.25	-.1150	.1662	-.1319	.4807	-.0623	.6408	-.0492	.6774	-.0411	.7252	-.0239	.7637	-.0068	.6008
.30			-.1710	.1996			-.0536	.6055	-.0432	.6705	-.0309	.7365	-.0080	.5526
.40	-.1015	.2406							-.1429	.2284	-.0404	.5921	-.0074	.4667
.50					-.1569	.2223	-.1536	.2345	-.1558	.2373	-.1446	-.2242	-.0091	.3003
.60	-.0617	-.2875	-.1563	.2258			-.1654	.2385	-.1587	.2424	-.1593	-.1512	-.1508	-.0795
.70					-.1508	-.2240	-.1589	.0785	-.1506	.0115	-.1514	-.0013	-.1493	-.0574
.80	-.1122	-.0551	-.1850	-.0320	-.1591	-.0023	-.1584	-.0029	-.1483	-.0076	-.1508	-.0144		
.90	-.1362	.0199	-.1675	-.0209	-.1602	-.0084	-.1592	-.0097	-.1514	-.0122	-.1509	-.0227	-.1479	-.0918
.95			-.1570	-.0072	-.1497	-.0082	-.1585	-.0145			-.1513	-.0300	-.1624	-.1028

TAIL 2

69

TABLE VI.- CONTINUED
(j) α = 15.92°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1579	.2819	.3719		.3059	.4326	.2902	.4636		.3202			.356?	.3?1?
.10	.2405	.3311	.3590	.5158	.3340	.4545		.4743	.3379	.4431	.3196	.4226	.2790	.3075
.15	.2294	.3283	.3396	.4756	.3363	.4628			.3285	.4228			.263?	.3416
.20	.2046	.2956	.3319	.4415	.3365	.4628	.3166	.4283	.3281	.4?40	.3301	.4432	.2590	.3033
.25	.0365	.0539			.3322	.1575	.3329	.4481	.3290	.4455	.3243	.4385	.2550	.3033
.30	.0536	.0539							.3230	.4359	.3?86	.444?	.2550	.3239
.40	.0666	.1563	.0329	.0642	.3652	.109?	.0651	.1100	.0751	.1277	.3?61	.4?4?	.2550	.3?28
.50			.020?	.0448	.0560	.0?0?	.0525	.0953			.3?61	.085?	.256?	.3?4?
.60	.0250	.0775	.0158	.041?	.0520	.0533	.0320	.0567	.0486	.0874	.0660	.0550	.057?	.37??
.70	.0889	.0542	.1092	.0939	.0452	.0803	.0162	.0345	.0881	.0637	.0218	.1068	.0813	.051?
.80	.0666	.0515	.0906	.1053			.1082	.0866	.1101	.0998	.095?	.091?	.09?	.1??
.90	.0474	.0427	.0877	.0948	.098?	.1548	.0859	.0962	.0815	.0629	.0684			
.95							.0722	.0873	.0773	.0?65	.0873	.0573		.15??

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.55 U.S.	0.55 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0766	.1720	-.1318	.8059			-.136?	.9913		.9222	-.1315	1.0802	-.1540	1.0429
.10	-.0794	.1439			-.1131	.8003	-.116?	.9203	-.1116	.9669			-.1152	.9095
.15							-.1124	.8399	-.1080	.8669			-.0948	.830?
.20	-.0957	.2340	-.1589	.5119	-.1278	.5966	-.134	.7897	-.1096	.8300	-.0902	.8290	-.0830	.7422
.25	-.1296	.1405	-.1862	.2561			-.1156	.7345	-.1099	.7799	-.0935	.7840	-.0769	.6772
.30	-.123?	.318?					-.1198	.6422	-.111?	.70?2	-.048?	.7840	-.07??	.62??
.40					-.1716	.3186	-.178?	.3142	-.1791	.26?4	-.048	.6224	-.0659	.51?4
.50	.0859	.3972	-.1611	.3645			-.180?	.3419	-.187?	.3689	-.1761	.2752	-.0772	.3249
.70					-.1663	.330?	-.1763	.1469	-.1732	.3372	-.1586	.2213	-.1718	-.0585
.80			-.1950	.1154	-.1790	.086?	-.1793	.0635	-.1673	.0726	-.1672	.0555	-.1672	-.06?9
.90	-.1351	.0877	-.1860	.0662	-.1730	.0752	-.178?	.0652	-.1668	.0555	-.1673	.0460	-.1570	-.0466
.95	-.1503	.0951	-.1812	.0432	-.1632	.0732	-.1720	.0668	-.1595	.0522	-.168?	.0367	-.17??	-.055?

TAIL 2

TABLE VII.- CONCLUDED
(k) α = 19.22°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2287	.3865	.1842		.3962	.5478	.2639	.3689						
				.6482										
				.5860										
	.2882			.5533										
	.338	.807		.1126										
				.0896										
					.1045			.0950						
	.0759			.0321				.0550						
				.0683				.0883						
				.0803	.0822			.0553		.0555				
.65	.0051			.0876	.0817			.5535	.0502	.0601	.0545			

TAIL 1

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.1276	.2231	-.1740	.8901			-.1783	.3855			-.1634	1.1577	-.1838	1.1386
	-.1280	.1806					-.1613	.0164	-.1567	.0257			-.546	.0208
					-.1532	.8980	-.1558	.9367	-.1514	.9718			-.1330	.9358
	-.1275	.2875					-.1556	.9776	-.1508	.8234			-.1200	.8491
	-.1553	.1917	-.1783	.5690	-.1698	.7678	-.1568	.8173	-.1497	.8625	-.1234	.9017	-.1197	.7704
			-.1968	.3679			-.1535	.7089	-.1499	.7823	-.346	.8783	-.1048	.7089
	-.1427	.4419							-.1970	.3246	-.1391	.6933	-.1561	.5959
					-.1796	.4529	-.1823	.4586	-.1910	.4298	-.1883	.3539	-.1166	.5787
	-.1032	.5245	-.1835	.4854			-.1911	.4811	-.1836	.4854	-.1782	.3255	-.1802	.0263
					-.1761	.4841	-.1904	.2417	-.1796	.0529	-.776	.3328	-.772	.3338
	-.1523	.1281	-.2657	.1621	-.1893	.1652	-.1921	.1572	-.1767	.1420	-.1785	.1261	-.1667	.0119
	-.1723	.1819	-.1931	.1128	-.1885	.1491	-.1915	.1549	-.1815	.1401	-.1784	.1161	-.1814	.0041
.65			-.1954	.0922	-.1846	.1451	-.1895	.1483			-.1793	.1065		

TAIL 2

TABLE VII.- PRESSURE COEFFICIENTS, φ = 22.5°, δ = 0°, M = 2.36

(a) α = -4.07°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0566	.2328	.2955		.2404	.2149	.2354	.2865		.1696			.2901	.1914
.10	.0675	.1258	.2623	.2249	.2747	.2417		.2581	.2705	.2484	.2518	.2512	.2819	
.15	.0743	.1199	.2347	.2074	.2798	.2411			.2632	.2512			.2417	.2315
.20	.0665	.1080	.2169	.1933	.2722	.2256	.2708	.2664	.2675	.2478	.2665	.2454	.2255	.2112
.25	-.0115	-.0196			.2631	.2247	.2706	.2320	.2708	.2402	.2652	.2484	.2045	.1862
.30	-.0062	-.0033							.2677	.2338	.2637	.2443	.1815	.1665
.40	.0507	.0107	-.0218	-.0476	.0273	-.0086	.0422	-.0019	.2478	.0234	.2586	.2347	.1678	
.50			-.0318	-.0492	-.0128	-.0226	-.0269	-.0142			.2175	.0089	.484	
.60					-.0053	-.0287	.0372	-.0343			.0195	-.0180	.320	.444
.70	-.0065	-.0136	.2226	-.0122	-.0032	-.0365	-.0098	-.0578	-.261	-.0127	-.155	-.1402	-.1272	-.1423
.80	-.0828	-.0893	-.1072	-.1201			-.1324	-.1489	-.1023	-.1283	-.1283	-.1356	-.342	-.1285
.90	-.0786	-.0995	-.1334	-.1424	-.1375		-.1392	-.1335	-.1319	-.1474	-.1305	-.1201		
.95	-.0847	-.1034	-.1339	-.1294		-.1345	-.1290	-.1276	-.1336	-.1254	-.1215	-.1176	-.1177	

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2389	.0691	.4465	.1381			.3971	.1097			.4297	.1360	.3294	.1167
.10	.2348	.0319				.1536	.4225	.1661	.4291	.1623			.3651	.1443
.15					.4390		.4298	.1548	.4319	.1523			.3389	.1306
.20	.2235	.0370					.4349	.1496	.4193	.1517			.3246	.1134
.25	.0530	-.0603	.1400	.0752	.4312	.1403	.4382	.1474	.4277	.1524	.4436	.1552	.3166	.1024
.30			.0697	-.0724			.4306	.1341	.1277	.1493	.4232	.1548	.3074	.1005
.40	-.0788	-.0379							.278	-.0356	.4026	.1322	.2930	.0948
.50					.0771	-.0634	.0903	-.0555	-.0979	-.0576	-.1055	-.0413	.2463	.0534
.60	.1439	-.0103	.0405	-.0858			.0816	-.0659	.0883	-.0620	.0462	-.0921	-.1105	-.1359
.70					.0574	-.0773	-.0215	-.1301	-.0876	-.1441	-.0889	-.1280	-.1146	-.1334
.80	-.0653	-.0092	-.0830	-.1251	-.1014	-.1170	-.1029	-.1200	-.1099	-.163	-.1067	-.1241		
.90	-.0411	-.1305	-.0877	-.1238	-.1198	-.1176	-.1155	-.1184	-.1168	-.1184	-.1177	-.1245	-.1131	-.1557
.95	-.0922	-.1248			-.1249	-.1175	-.1200	-.1182			-.1230	-.1253	-.1202	-.1689

TAIL 2

TABLE VII. - CONTINUED
(b) α = -2.07°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0494	.1518	.2529		.2090	.2513	.2136	.3256		.2022			.2632	.2079
.10	.0929	.1059	.2290	.2705	.2365	.2842		.2912	.2465	.2784	.2372	.2949	.2553	.2855
.15	.0918	.1032	.2136	.2466	.2417	.2805			.2351	.2850			.2?01	.2?80
.20	.0817	.0946	.199?	.2280	.2393	.2679	.2410	.2649	.2377	.2843	.2413	.2796	.19??	.2315
.25	-.0121	-.0244			.2335	.2650	.2356	.2632	.2413	.2766	.240?	.281?	.1790	.2100
.30	-.0025	-.0090							.2376	.2697	.2396	.2756	.1606	.1886
.40	.0375	.0248	-.0243	-.0327	.0128	.0097	.0245	.0186	.0301	.0400	.2221	.2652	.1465	.1724
.50			-.0340	-.0455	-.0005	-.0044	.0118	.0039			.0274	.0278	.1322	.1416
.60					-.0051	-.0132	-.0217	-.0119	.0100	.0061	-.0006	-.000?	.1345	.1387
.70	-.0053	.0023	.0032	-.0096	-.0152	-.0211	-.0180	-.0451	-.1158	-.1170	-.1269	-.1316	-.1341	-.1417
.80	-.0823	-.0741	-.1133	-.1114			-.1376	-.1419	-.1380	-.1435	-.1376	-.1385	-.1363	-.1332
.90	-.0794	-.0835	-.1347	-.1351	-.1279	-.1361	-.1366	-.1339	-.1257	-.1247	-.1204	-.1177		
.95	-.0848	-.0885	-.1302	-.1308			-.1237	-.1241	-.1161	-.1169	-.1131	-.1129		-.1110

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1710	.1151	.3577	.2036			.3211	.1572			.3505	.1843	.2632	.1660
.10	.1741	.0742					.3437	.2224	.3494	.2130			.3043	.1915
.15					.3527	.2100	.3490	.2081	.3536	.2053			.2788	.1698
.20	.1954	.0757					.3498	.2022	.3417	.2054			.2654	.1511
.25	.0277	-.0288	.1020	.1239	.3521	.1961	.3529	.2020	.3454	.2066	.3352	.2065	.2546	.1368
.30			.0339	-.0378			.3494	.1899	.3427	.2024	.3430	.2063	.2442	.1314
.40	.0293	-.0269							.0816	-.0048	.3296	.1804	.2379	.1254
.50					.0415	-.0339	.0525	-.0248	.0569	-.0269	.0631	-.0140	.1937	.0758
.60	.1093	.0162	-.0093	-.0618			.0452	-.0347	.0489	-.0321	.0068	-.0685	-.1203	-.1317
.70					.0267	-.0530	-.0476	-.1088	-.1078	-.1450	-.1117	-.1411	-.1233	-.1436
.80	-.0743	-.0867	-.1054	-.1385	-.1138	-.1401	-.1218	-.1428	-.125?	-.1162	-.1269	-.1207		
.90	-.063?	-.117?	-.1105	-.1293	-.1327	-.1279	-.1325	-.1253	-.1256	-.1162	-.1327	-.1177	-.1236	-.1187
.95			-.1139	-.1285	-.1347	-.1256	-.1310	-.1244	-.1273	-.1181	-.1237	-.1174	-.1106	-.1350

73

TABLE VII.- CONTINUED
(c) a = -0.07°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.57 U.S.	0.57 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0602	.1321	.2235		.1859	.2935	.1950	.3576	.2253	.2268			.2481	.2325
.10	.0971	.1322	.2047	.3077	.2100	.3163		.3267		.3113	.2181	.3178	.2298	.3067
.15	.0845	.1317	.1904	.2845	.2132	.3136			.2140	.3182			.1799	.2805
.20	.0813	.1204	.1738	.2544	.2124	.3027	.2158	.2965	.2146	.3171	.2193	.3119	.1741	.2520
.25	-.0214	-.3255			.2085	.2987	.2139	.3008	.2183	.3081	.2157	.3128	.1560	.2298
.30	-.0066	-.0078			-.0000	.0283	.0097	.0373	.2153	.3022	.2171	.3063	.1418	.2103
.40	-.0150	-.0278	-.0322	-.0119	-.0116	.0130	-.0019	.0217	.0159	.3022	.208	.2966	.1348	.1920
.50			-.0398	-.0267	-.0152	.0042	.0075	.0146	.0159	.0564	.0155	.0433	.1185	.1604
.60	-.0071	-.0287	-.0167	-.0075	-.0257	-.0038	-.0302	-.0306	-.0051	.0233	-.0167	.0142	.1331	.1307
.70	-.0844	-.0670	-.1205	-.084			-.1124	-.1337	-.1247	-.1077	-.1354	-.1236	-.1479	-.1375
.80	-.0806	-.0766	-.345	-.1265	-.1195	-.1411	-.1236	-.1384	-.1411	-.1345	-.1293	-.1371	-.1300	-.1435
.90	-.0839	-.0812	-.1243	-.1244			-.1175	-.1257	-.1181	-.1308	-.1142	-.1215		
.95									-.1132	-.1185	-.1119	-.1137	-.1072	

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.33 U.S.	0.33 L.S.	0.98 U.S.	0.98 L.S.
.05	.1245	.1472	.2766	.2778			.2528	.2039	.2785	.2702	.2810	.2421	.2027	.2140
.10	.1219	.1083					.2753	.2846	.2816	.2643			.2461	.2428
.15					.2773	.2724	.2744	.2685	.2721	.2657			.2181	.217
.20	.1344	.1089					.2768	.2641	.2750	.2664	.2680	.2649	.2089	.1962
.25	-.0021	-.0001	.0649	.1821	.2718	.2591	.2767	.2621	.2717	.2613	.2720	.2641	.2003	.1783
.30	-.0090	.0113	-.0025	-.0034			.2729	.2467	.0386	.0300	.2501	.2347	.1938	.1717
.40													.1865	.1594
.50	.0726	.0459	-.0373	-.0397	.0062	-.0034	.0153	.0095	.0160	.0069	.0256	.0185	.1489	.025
.60							.0085	-.0012	.0087	.0015	.0249	.0410	.1288	.1278
.70	-.0782	-.0735	-.1183	-.1276	-.0095	-.0196	-.0720	-.0876	-.1280	-.1278	-.1309	-.1341	-.1389	-.1444
.80					-.1351	-.1421	-.1393	-.1415			-.1334	-.1288		
.90	-.0792	-.028	-.1275	-.1302	-.1388	-.1305	-.1311	-.1308	-.1194	-.1176	-.1185	-.1121	-.1117	-.0909
.95			-.1291	-.1249	-.1247	-.1218	-.1204	-.1206	-.1151	-.1134	-.1136	-.1094	-.1032	-.1039

TABLE VII.- CONTINUED
(d) α = ?.?°

TAIL 1

	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0592	.1526	.0997		.1974	.3150	.1758	.3918						
.10	.0884	.1604	.0921		.1800	.3501		.3629				.3458		
.15	.0866	.1730			.1800	.3504								
.20	.0740	.1566			.1887	.3301	.1955	.3240						
.25	-.0351	-.0182			.1853	.3345		.3360						
.30	-.0224	.0000												
.40	-.0115	.0309	-.0435	.0061	-.0118	.0453								
.50			-.0505	-.0098	-.0233	.0300								
.60					-.0275	.0218		.0253		.0306				
.70	-.0169	.0478	-.0377	-.0002	-.0368	.0138	-.0947	-.0159		-.0979				
.80	-.0537	-.0617	-.0312	-.1088			-.1294	-.1243						
.90	-.0853	-.0712	-.1238	-.1224	-.1185		-.1207	-.1340		-.1300				
.95	-.0873	-.0742	-.1203	-.1189		-.1376	-.1194	-.1294		-.1250				

TAIL 2

	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.93		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0934	.1607	.2016	.3660			.1885	.2699			.2203	.3057	.1514	.2629
.10	.0869	.1297					.2430	.3524	.2150	.3377			.1851	.2992
.15					.2105	.3489	.2051	.3421	.2163	.3329			.1715	.2759
.20	.0844	.1351					.2053	.3375	.2084	.3322			.1643	.2512
.25	.0274	.0237	.0208	.2332	.2043	.3284	.2063	.3334	.2112	.3355	.2070	.3292	.1531	.2262
.30			.0375	.0278			.2055	.3130	.2084	.3319	.2097	.3307	.1486	.2218
.40	.0024	.0481							.0009	.0704	.1985	.2979	.1433	.2030
.50	.0350	.0746	-.0490	-.0135	-.0273	.0291	-.0257	.0441	-.0202	.0474	.0058	.0548	.1093	.1372
.60					-.0435	.0096	-.0273	.0316	-.0252	.0405	-.0524	-.0079	-.0354	-.1232
.80	.0803	-.0606	-.1313	-.1072	-.1487	-.1269	-.0981	-.0688	-.1445	-.1070	-.0468	-.1129	-.1420	-.1282
.90	.0804	-.0877	-.1420	-.1193	-.1295	-.1385	-.1480	-.1256	-.1206	-.1239	-.1292	-.1242	-.1160	-.1203
.95			-.1330	-.1215	-.1266	-.1297	-.1281	-.1333	-.1221	-.1267	-.1221	-.1293	-.1227	-.1203
							-.1251	-.1303			-.1210	-.1273		-.1082

75

TABLE VII. - CONTINUED
(e) α = 3.93°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0511	.1925	.1759				.1567	.4205		.2949				
.10	.0747	.2049	.1643	.3872				.3696	.1874	.3790	.1627	.3835		
.15	.171	.2162		.3618					.1762	.3899				
.25		.1992		.3556			.1805	.3569	.1751	.3845	.1335			
.30	.0482	.1052					.1744	.3755	.1776	.3765	.1786			
.35	.0366								.1758	.3720	.1760	.3661		
.40	.0502	.1423	.0555	.0239		.0557	.0168	.0771	.0078	.0912	.1704	.3553		
.50			.0627	.0063			.0297	.0605			.0072	.0782		
.60	.0365	.0586	.0532	.0152		.0228	.0186	.0425	.0322	.0587	.0393	.0486		
.70	.1025	.0535	.1390	.1031			.0541	.0010	.1392	.0987	.1478	.1097		
.80	.0945	.0618	.1252	.1188	.1201	.1293	.1345	.1129	.1313	.171	.1260	.1263		
.90	.0678	.0618	.1250	.1162			.1214	.1239	.1205	.1218	.1213	.1331	.1207	
.95							.1210	.1280	.1192	.1234	.1206	.1281		.3997

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0647	.664	.1347	.4415			.298	.3413	.1575	.4221	.642	.3738	.032	.2.89
.10	.0578	.1450					.545	.4362	.565	.4163			.404	
.15					.1465	.1222	.478	.4275	.1499	.4186			.1270	.3465
.25	.0365	.569	.0145	.2822	.1409	.3315	.1472	.4151	.1521	.498	.1537	.4061	.1124	.3172
.30	.0476	.0423	.0698	.0594			.1436	.3836	.1492	.438	.1548	.411	.1122	.2850
.40	.0036	.0768					.0534	.0758	.0361	.084	.1446	.374	.058	.2849
.50	.0096	.012	.0632	.0207	.0586	.0585	.0617	.0630	.0538	.0831	.0385	.0972	.0761	.2504
.70	.0853	.0470			.0731	.0426	.1139	.0433	.0580	.0745	.0603	.0280	.1412	.1814
.80	.0817	.0717	.1410	.0909	.1316	.1089	.1330	.1084	.1565	.0879	.1432	.0894	.422	.1138
.90			.1536	.1011	.1303	.1233	.129	.117	.1257	.1095	.318	.1026		.32
.95			.1344	.1044	.1302	.1263	.1284	.1208	.1287	.1152	.1297	.1161	.1247	.1058

TABLE VII.- CONTINUED
(f) α = 5.93°

TAIL 1

	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0398	.2482	.1526		.1357	.3887	.1343	.4490		.3125			.1803	.3068
.10	.0576	.2415	.1465	.4354	.1524	.4272		.4382	.703	.4114	.628	.410	.645	.3630
.15	.0521	.2623	.1306	.4092	.1516	.4228			.584	.4110				.336
.20	.0381	.2415		.377	.1494	.4192	.1631	.3940	.580	.4135	.561	.4022	1.15	.3122
.25	-.0574	.0156			.1479	.4175	.156	-.1145	.600	.4122	.613	.405	1.11	.2662
.30	-.0480	-.0338							.574	.4059	.578	.3900	.136	.2728
.40	-.0470	.0655	-.0662	.0428	-.0367	.0841	-.0289	.0954	-.3205	.1073	.506	.3887	.129	.2579
.50			-.0748	.0243	-.0460	.0670	-.0422	.0797			-.0204	.0958	.054	.25.
.60					-.0491	.0597	-.0313	.0612	-.0428	.0788	-.0508	.0615	.302	.077
.70	-.0541	.0702	-.0668	.0323	-.0569	.0510	-.0679	.0190	-.1447	-.0778	-.1344	-.1027	-.167	.225
.80	-.1114	-.0405	-.1262	-.0932			-.1191	-.1033	-.1221	-.1062	-.1228	-.1203	-.1317	-.1193
.90	-.0954	-.0471	-.1231	-.1114	-.1150	-.1196	-.1164	-.1147	-.1175	-.1111	-.1219	-.1275		
.95	-.0792	-.0429	-.1239	-.1101			-.1162	-.1198	-.1170	-.1146	-.1217	-.1282		-.0988

Cp at y/b of

TAIL 2

	0.02		0.22		0.44		0.56		0.67		0.88		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0438	.1637	.0747	.5061			.0736	.4360		.5357	.1121	.4669	.2595	.3919
.10	.0391	.1448					.0980	.5350	.1036	.5357			.1012	.4723
.15					.0873	.5007	.0915	.5130	.1005	.5209			.0873	.4455
.20	.0193	.1660	-.0435	.3214	.0808	.4454	.0901	.4891	.0942	.5100	.1026	.5133	.0805	.4164
.25	-.0517	.0522	-.0963	.0887			.0900	.4696	.0960	.4976	.1025	.5080	.0760	.3896
.30							.0857	.4337	.0936	.4781	.0932	.4405	.0744	.3717
.40	-.0254	.1039							-.0673	.1396		.1330	.0735	.3358
.50					-.0877	.0880	-.0831	.1060	-.0838	.1132	-.0683	.1330	.0474	.2320
.60	-.0074	.1333	.0813	.0578			-.0917	.0945	-.0879	.1046	-.1065	.0533	-.1432	.1053
.70					-.0999	.0751	-.1416	-.0220	-.1464	-.0697	-.1368	-.0715	-.1400	-.1136
.80	-.0863	-.0326	-.1545	-.0709	-.1370	-.0907	-.1339	-.0905	-.1291	-.0905	-.1344	-.0856	-.1392	-.0955
.90	-.001	-.0545	-.1481	-.0813	-.1388	-.1050	-.1330	-.0990	-.1291	-.0905	-.1345	-.0933	-.1525	-.1040
.95			-.1300	-.0850	-.1390	-.1093	-.1326	-.1032	-.1322	-.0970	-.1347	-.0993		

Cp at y/b of

77

TABLE VII.- CONTINUED
(g) α = 7.93°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0297	.2948	.1370		.1227	.4287	.1082	.487		.3415			.1629	.3263
.10	.0452	.2780	.1346	.4843	.1374	.4698		.4758	.1537	.4439	.1399	.4559	.1347	.6258
.15	.0595	.3080	.1177	.4554	.362				.141	.4422	.753		.053	.3509
.20	.0637	.2805	.1094	.4228	.1342	.468	.1474	.4345	.1907	.4485	.763	.386	.621	.5200
.25	.0633	.0400		.3568	.1322	.464	.1419	.4636	.1424	.4486	.321	.356	.1019	.471
.30	.0605	.0574	.1153	.164					.396	.456	.391	.297	.038	.2959
.40	.0558	.0544	.0755	.0629	.0459	.0765	.0384	.05	.030	.1295	.311	.424	.075	.2640
.50			.0827	.0442	.0559	.0848	.0530	.1225	.0300		.324	.150	.0967	.5973
.60	.0655	.0863	.0767	.0527	.0586	.0845	.0439	.080	.0536	.1006	.069	.0751	.040	.110
.70	.014	.0228	.1221	.0803	.0657	.0753	.0808	.0552	.1410	.0653	.223	.0951	.209	.0923
.80	.0982	.0284	.1222	.1007			.1147	.0861	.175	.0955	.97	.31	.558	
.90			.1230	.0991	.1126	.1079	.1137	.078	.142	.0999	.1201	.204		
.95	.0777	.0220					.136	.099		.1041	.203	.222		.025

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0340	.144	.0221	.5541			.0209	.5650					.0180	.5989
.10	.0269	.272				.5455	.0435	.6.46	.0515	.6466	.0597	.6708	.0534	.6258
.20	.0240	.1555	.0727	.3568	.0230		.0369	.5726	.0483	.6019			.0540	.572
.25	.0534	.0534	.1153	.164	.0247	.4860	.034	.5382	.0412	.572	.0533	.5869	.0537	.5205
.30	.0466	.1322					.0298	.5183	.0410	.5497	.0519	.5740	.0514	.471
.40					.1130	.1170	.0298	.4738	.0960	.5267	.0448	.4797	.0509	.4343
.50	.0154	.1647	.0952	.0997			.1098	.360	.1110	.1628	.0952	.548	.0485	.3804
.60					.1206	.117	.1193	.1257	.1154	.1400	.284	.025	.0253	.2525
.70	.0953	.0230	.1520	.0531	.1411	.073	.1521	.0036	.1392	.1352	.353	.0672	.1366	.015
.80	.1100	.0377	.1476	.0625	.1436	.0847	.1361	.0659		.0505	.360	.0672	.368	.1193
.90	.329		.329	.1593	.1437	.0873	.1377	.078	.1312	.0711	.361	.0746	.1298	.1146
.95							.1395	.0827	.1348	.0769	.360	.092	.134	.1259

TAIL 2

TABLE VII.- CONTINUED
(h) 2 = 9.93°

TAIL 1

	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.63		0.98	
z/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0341	.1263	-.0224	.5606			-.031	.279		.7060	.0101	.8130		
	.0204	.1074			-.0182	.5850	-.0094	.5706	-.0014	.6468				.7704
	.0215	.134	-.0815	.3797	-.0275	.5193	-.0148	.5229	-.0029	.6152				
	-.0575	.0461	-.1279	.459			-.0184	.5778	-.0097	.5923	.0055	.633	.0025	.6452
	-.0606	.1488					-.0193	.5527	-.0091	.5685	.0008	.6107	.0025	.5288
	-.0268	.1800	-.1043	.421	-.1363	.1502	-.0231	.4365	-.0107	.797	-.0062	.5027	.0025	.4858
							-.1359	.644	.258	.1672	-.1229	.1751	-.0037	.4430
	-.0971	-.0201	-.1555	-.0385	-.137	.1434	-.1459	.1608	-.387	.1685	-.1481	.104	.1325	.2663
	-.162	-.0267	-.152	-.0516	-.1502	-.0523	-.1556	.0263	-.1420	-.0308	-.1410	-.0337	-.1084	.0949
	-.0845	-.0006	-.1375	-.0578	-.1509	-.0610	-.1497	-.0466	.136	-.0493	-.1407	-.0458	-.1099	.147
					-.1406	-.0611	-.1503	-.0574	-.1413		-.1400	-.0535	-.1422	.1110
							-.1499	-.0631	-.1432	-.0544	-.1399	-.0605		-.1228

TABLE VII. - CONTINUED
(l) α = 11.93°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0156	.4069	.1140		.1095	.5312	.0929	.5724		.4177			.1680	.4024
.10	.0143	.3491	.1129	.6001	.1198	.5755	.0929	.5780	.1432	.5399	.1331	.5568	.1236	.4581
.15	.0044	.4044	.0967	.5607	.1176	.5913		.5384	.1294	.5384			.1109	.4275
.20	-.0044	.3719	.0842	.5242	.1144	.5839	.1267	.5392	.1272	.5485	.1409	.5337	.1135	.4038
.25	-.0800	.0960			.1105	.5723	.1241	.5696	.1277	.5532	.1360	.5323	.1142	.3859
.30	-.0746	.1132							.1238	.5447	.1324	.5224	.1167	.3727
.40	-.0792	.1631	-.0928	.1078	-.0618	.1562	-.0508	.1707	-.0454	.1838	.1224	.5057	.1128	.3580
.50			-.1016	.0911	-.0730	.1461	-.0678	.1557			-.0434	.1635	.1082	.3168
.60	-.0860	.1380			-.0764	.1364	-.0624	.1288	-.0670	-.1538	-.0751	-.1115	-.1319	.0729
.70			-.0959	.105	-.0826	.1250	-.0947	.0830	-.1279	-.0345	-.1211	-.0760	-.1465	.0955
.80	-.1376	.0163	-.1222	-.0498			-.1131	-.0613	-.1165	-.0669	-.1206	-.0941	-.1881	.0478
.90	-.0919	.0125	-.1235	-.0720	-.1131	-.0825	-.1129	-.0734	-.1137	-.0725	-.1214	-.1004		
.95	-.0848	.0233	-.1239	-.0700			-.1129	-.0799	-.1134	-.0780	-.1216	-.1030		-.0861

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0362	.1168	-.0647	.6018			-.0758	.7537		.7559	-.0544	.8685	-.0750	.8658
.10	.0171	.0956				.6171	-.0556	.7146	-.0494	.6897			-.0271	.7729
.15					-.0604		-.0585	.6617	-.0485	.6540			-.0173	.6991
.20	.0110	.1105	-.1034	.4089	-.0717	.5457	-.0625	.6126	-.0535	.6255	-.0354	.6714	-.0118	.6336
.25	-.0644	.0339	-.1404	.1632			-.0640	.5821	-.0545	.5948	-.0432	.6446	-.0097	.5739
.30							-.0682	.5136	-.0565	.5948	-.0520	.5162	-.0098	.5236
.40	-.0737	-.1395					-.1564	.1926	-.1510	.1944	-.1473	.1907	-.0127	.4422
.50					-.1509	.1831	-.1662	.1988	-.1614	.1925	-.1608	.1295	-.0327	.2829
.60	-.0375	.1823	-.1231	.1857			-.1639	.0534	-.1631	.2016	-.1516	-.0142	-.1500	-.0867
.70					-.1514	.1749	-.1624	-.0260	-.1536	-.0130	-.1513	-.0248	-.1484	-.0997
.80	-.0990	-.0206	-.1699	-.0325	-.1634	-.0278	-.1631	-.0370	-.1531	-.0286	-.1509	-.0306	-.1401	-.0927
.90	-.1190	-.0214	-.1615	-.0468	-.1649	-.0319	-.1631	-.0370	-.1557	-.0327	-.1514	-.0372	-.1524	-.1048
.95	-.1489		-.1489	-.0494	-.1580	-.0312	-.1629	-.0419						

TABLE VII.- CONTINUED
(j) α = 15.9?°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.57 U.S.	0.57 L.S.	0.89 U.S.	0.89 L.S.	0.98 U.S.	0.98 L.S.
.05	.0274	.5299	.1506		.1403	.7034	.1227	.7272		.5257			.1879	.5059
.10	.0456	.4452	.1496	.7655	.1523	.7764		.7412	.1385	.5333	.1552	.7024		.5704
.15	.0318	.5261	.1299	.7052	.1506	.7850			.1570	.7036	.1529			.5355
.20	.0229	.4922	.1161	.6552	.1467	.7490	.1484	.7033	.1541	.7321			.1469	.5152
.25	.0609	.1690			.1420	.7214	.1544	.7418						.4962
.30	.0538	.1923												.4837
.40	.0623	.2604	.0784	.1762	.0557	.2275	.0365	.2456	.0318	.2554	.1453	.3635		
.50			.0881	.1582	.0582	.2446	.0595	.2297			.0296	.6576		.1274
.60	.0752	.2188	.0866	.1852	.0621	.2035	.0600	.1832	.0576	.2307	.0653	.1814		.0305
.70	.1460	.0741	.1082	.0047	.0686	.1937	.0830	.1415	.1160	.0067	.1131	.0363		.0455
.80	.0969	.0757	.1102	.0287	.1023	.0450	.1026	.0235	.1069	.0301	.1130	.0575	.1889	.0063
.90	.0931	.0933	.1108	.0248			.1024	.0374	.1057	.0394	.1146	.0661		
.95							.1025	.0441	.1034	.0469	.1154	.0696		.0398

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.88 U.S.	0.88 L.S.	0.98 U.S.	0.98 L.S.
.05	.0491	.0544	.1192	.6147			.1460	.8246	.1297	.8106	.1383	.8952	.1528	.9429
.10	.0263	.0782					.1293	.7638	.1257	.7561			.1250	.8452
.15					.1217	.6618	.1274	.7172	.1274	.6978			.1088	.7725
.20	.0041	.0836	.1240	.4470			.1300	.6585	.1282	.6541	.1080	.7103	.1003	.7030
.25	.0891	.0052	.1489	.2083	.1341	.5776	.1319	.6152	.1299	.6094	.1190	.6736	.0931	.5575
.30							.1352	.5377	.1863	.2209	.1271	.5235	.0929	.5843
.40	.0965	.0854					.1801	.2587	.1934	.2371	.1840	.2271	.1076	.4816
.50	.0488	.1445	.1481	.2725	.1702	.2528	.1860	.2744	.1834	.2667	.1781	.1802	.1734	.2987
.60					.1632	.2600	.1836	.0952	.1751	.0326	.1756	.0261	.1733	.0661
.70	.1123	.0337	.1829	.0085	.1858	.0255	.1851	.0210			.1759	.0228	.1615	.0544
.80	.1320	.0511	.1755	.0259	.1866	.0095	.1850	.0195	.1777	.0109	.1748	.0207	.1757	.0652
.90			.1626	.0387	.1742	.0031	.1829	.0133	.1797	.0091	.1756	.0144		

TAIL 2

TABLE VII.- CONCLUDED
(k) α = 19.92°

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0606	.7158	.1983		.1827	1.0023	.1652	1.0203		.6971			.2202	.6574
.10	.0899	.5752	.1982	.9409	.1975	1.0146		.9880	.2081	.9717	.1939	.9245	.1590	.7321
.15	.0708	.6753	.1747	.8801	.1966	.9831			.1986	.9703			.1853	.6903
.20	.0616	.6388	.1583	.8291	.1929	.9258	.1891	.9011	.1963	.9608	.2027	.9279	.1943	.6734
.25	-.0344	.2553			.1870	.8791	.1987	.9126	.1955	.9361	.1979	.9280	.1958	.6620
.30	-.0244	.2876							.1909	.9062	.1951	.8974	.1972	.6514
.40	-.0335	.3768	-.0591	.2552	-.0212	-.2952	-.0128	-.3242	-.0062	.3482	.1867	.8165	.1905	.6378
.50			-.0688	.2387	-.0329	-.2887	-.0301	-.3091			-.0064	.3122	.1894	.5721
.60					-.0377	-.2839	-.0452	-.2554	-.0316	.3106	-.0446	.2456	-.1262	.0128
.70	-.0488	.3326	-.0668	.2937	-.0443	.2725	-.0616	-.2123	-.1045	-.0520	-.0987	-.0021	-.1866	-.0058
.80	-.1347	.1617	-.0866	.0478			-.0865	-.0217	-.0908	-.0093	-.0985	-.0234	-.1833	-.0676
.90	-.0813	.1738	-.0902	.0268	-.0850	-.0035	-.0865	-.0040	-.0873	-.0026	-.1006	-.0311		
.95	-.0731	.1875	-.0915	.0376			-.0866	-.0045	-.0874	-.0112	-.1021	-.0344		-.0125

TAIL 2

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0153	.0381	-.1584	.6500			-.1935	.8192		.8083	-.1834	.8769	-.2006	.9051
.10	-.0104	-.0575					-.1836	.7825	-.1831				-.1885	.8407
.15					-.1641	.6954	-.1781	.7356	-.1808	.7624			-.1798	.7753
.20	-.0414	.0643	-.1539	.4831	-.1762	.5846	-.1782	.6628	-.1801	.6988	-.1571	.7029	-.1729	.7079
.25	-.1189	-.0157	-.1761	.2660			-.1779	.6030	-.1788	.6417	-.1708	.6606	-.1688	.6427
.30							-.1790	.5154	-.1784	.5842	-.1746	.5027	-.1656	.5890
.40	-.1200	.0728	-.1677	.3268	-.1813	.3227	-.1860	.3439	-.2062	.2389	-.1970	.2707	-.1609	.4881
.50							-.1969	.3583	-.1986	.3337	-.1912	.2696	-.1674	.3037
.60	-.0755	.1532			-.1794	.3227	-.1973	.1604	-.1951	.3592	-.1904	.0951	-.1898	-.0367
.70							-.1977	.0687	-.1897	.0845	-.1908	.0840	-.1846	-.0091
.80	-.1294	-.0355	-.1946	.0408	-.1977	-.0640	-.1938	-.0579	-.1912	.0644				
.90	-.1519	-.0544	-.1853	.0014	-.1946	-.0499	-.1910	-.0517	-.1939	.0594	-.1893	-.0797	-.1742	-.0073
.95			-.1776	-.0160	-.1925	-.0425					-.1903	-.0737	-.1902	-.0049

TABLE VIII.- PRESSURE COEFFICIENTS, Λ = 45°, δ = 0°, M = 2.36

(a) α = -4.05°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.57 U.S.	0.57 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.57 U.S.	0.57 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.

TAIL 2

83

TABLE VIII.- CONTINUED
(b) α = -2.05°

Cp at η/b of

x/c	0.02		0.11		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0668													
	-.1077													
.50	-.007													
	-.0779			-.162										
.90	-.0794		-.299	-.392	-.1316				-.307	-.1215				
.95	-.0797		-.1276	-.1296				-.1244	-.1216	-.1177				

TAIL 1

Cp at η/b of

x/c	0.02		0.22		0.4		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1698			.2175			.3025	.1723		.2261	.2375	.2003	.2516	.1713
	.1623						.3320	.2570	.2342	.2135			.2923	.2016
.15					.3574	.2040	.3335	.2225	.3402	.2224			.2355	.1824
.20	.1539						.3372	.2171	.3234	.2225			.2557	.1918
.25	.0270			.1369	.3398	.2054	.3329	.2156	.3320	.2205	.3262	.2023	.2422	.1472
.30							.3335	.2030	.3251	.2234	.3375	.2225	.2209	
.40	.0240								.2722	.2029	.2725			
.50					.2355	.2036	.3462	.2186	.2884	.1489	.2835	.0045	.1884	
.60	.0967		-.0906	-.0582			.3387	.2258	.2412	-.0247	.0013	-.0635	.1665	.1035
.70	-.0777	-.0953	-.1129	-.1366	-.0172	-.0180	-.1517	-.1013	-.1114	-.1119	-.155	-.1179	-.1267	-.481
.90	-.0682	-.1158	-.1176	-.1279	-.1356	-.1264	-.1249	-.1476	-.1277	-.1180	-.1310	-.1225	-.179	-.138
.95			-.1174	-.1268	-.1325	-.1248	-.1290	-.1277	-.1256	-.188	-.1189	-.175	-.1012	-.1370

TAIL 2

TABLE VIII. - CONTINUED
(c) α = -0.04°

TAIL 1

	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0629	.1225	.2284		.1923	.2820	.2010	.3576	.2335					
.10	.0993	.1277	.2100	.3061	.2172	.3147		.3201	.2212	.3120	.2246	.3172		
.15	.0967	.1281	.1955	.2915	.2203	.3116			.2212	.3181				
.20	.0837	.1179	.1838	.2621	.2195	.3007	.2259	.2825	.2224	.3177	.2257	.3120		
.25	.0195	.0258			.2145	.2967	.2202	.3010	.2259	.3101	.2231	.3141		
.30	.0046	.0084							.2232	.3035	.2231	.3078		
.40	.0179	.0271							.0201	.0565	.2148	.2981		
.50			.0308	.0132	.0026	.0263	.0133	.0367			.0197	.0440		
.60			.0383	.0275	.0089	.0117	.0013	.0213	.0012	.0240	.0135	.0148		
.70	.0057	.0275	.0147	.0071	.0139	.0033	.0111	.0156	.0231	.1070	.1335	.1236		
.80	.0832	.0673	.1198	.1080	.0233	.0042	.0274	.0304	.1405	.1361	.1298	.1364		
.90	.0601	.0773	.1346	.1264		.1389	.1416	.1331	.1173	.1288	.1130	.1192		
.95	.0842	.0819	.1248	.1233	.1202		.1239	.1372	.1123	.1167	.1105	.1121		.1056

TAIL 1

TAIL 2

	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1257	.1417	.2780	.2744			.2556	.2103			.2861	.2447	.2096	.2132
.10	.1221	.1081					.2782	.2832	.2813	.2696			.2523	.2412
.15					.2808	.2719	.2775	.2672	.2840	.2649			.2256	.2162
.20	.1320	.1082					.2799	.2622	.2745	.2674			.2144	.1954
.25	.0028	.0011	.0659	.1793	.2761	.2592	.2796	.2607	.2776	.2715	.2737	.2643	.2016	.1776
.30			.0019	.0046			.2756	.2455	.2750	.2682	.2804	.2647	.1989	.1706
.40	.0098	.0080					.0164	.0094	.0406	.0302	.2670	.2363	.1912	.1584
.50			.0367	.0405			.0093	.0006	.0177	.0065	.0289	.0188	.1525	.1013
.60	.0732	.0454					.0716	.0873	.0105	.0012	.0228	.0443	.1286	.1284
.70					.0100	.0208			.1271	.1276	.1301	.1361	.1376	.1453
.80	.0793	.0735	.1190	.1283	.1354	.1424	.1390	.1420	.1210	.1166	.1398	.1283		
.90	.0797	.1030	.1277	.1306	.1380	.1302	.1314	.1299	.1210	.1166	.1190	.1132	.1125	.0925
.95			.1288	.1253	.1245	.1219	.1204	.1203	.1167	.1134	.1137	.1107	.1025	.1022

TAIL 2

85

TABLE VIII.- CONTINUED
(d) α = 1.95°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0476	.1343	.804		.1528	.2433	.1632	.4154		.2740			.2166	.2799
.10	.0708	.1398	.640	.2587	.1700	.3768		.3803	.1917	.3728	.884	.3722	.850	.3486
.15	.0722	.1810	.504	.3050	.1720	.3740			.1810	.3784			.1461	.3235
.20	.0586	.1625	.416	.3188	.1725	.3631	.1794	.3356	.1309	.3708	.963	.3638	.1403	.2919
.25	.0378	.0121			.1704	.3580	.1783	.3618	.1844	.3654	.931	.3691	.1300	.2581
.30	.0264	.0085									.920	.3691	.1214	.2500
.40	.0138	.0467	.0533	.0159	.0215	.0549	.0136	.0682	.1322	.3531	.942	.3509	.1172	.2308
.50			.0594	.0002	.0332	.0394	.0255	.0512	.0050	.2890	.0440	.2747	.1042	.1967
.60					.0376	.0314	.0152	.0296	.0284	.0551	.351	.2756	.340	.1222
.70	.0215	.0603	.0415	.0127	.0466	.0239	.0509	.0058	.1356	.2900	.260	.2756	.1519	.1242
.80	.0938	.0566	.1324	.0975			.1324	.1183	.1289	.1214	.251	.1242	.1074	.1338
.90	.0868	.0653	.1239	.1138	.1172	.1335	.1201	.1291	.1190	.1251	.192	.1309		
.95	.0891	.0685	.1218	.1112			.1192	.1303	.1174	.1254	.1133	.1274		.1060

Cp at y/b of

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1003	.1343	.2181	.3446			.2046	.2538			.2351	.2848	.1685	.2440
.10	.0969	.1398					.2272	.3320	.2311	.3194			.2118	.2793
.15					.2267	.3298	.2211	.3235	.2319	.3160			.1863	.2578
.20	.0922	.1128					.2232	.3178	.2237	.3165			.1755	.2335
.25	.0175	.0143	.0308	.2148	.2206	.3094	.2250	.3145	.2257	.3215	.2240	.3094	.1677	.2139
.30			.0298	.0155			.2209	.2946	.2228	.3196	.2274	.3109	.1619	.2059
.40	.0085	.0473							.0099	.0617	.2069	.2863	.1555	.1885
.50	.0380	.0674	.0464	.0233	.0201	.0191	.0120	.0347	.0106	.0359	.0010	.0425	.1194	.1253
.60							.0189	.0229	.0176	.0294	.0451	.0183	.1352	.1261
.70					.0361	.0001	.0921	.0750	.1400	.1120	.1424	.1181	.1393	.1311
.80	.0818	.0648	.1270	.1116	.1476	.1325	.1497	.1304	.1200	.1286	.1300	.1295	.1117	.1193
.90	.0892	.0915	.1410	.1240	.1304	.1419	.1281	.1384	.1200	.1303	.1195	.1303	.1183	.1058
.95			.1347	.1262	.1261	.1277	.1248	.1299	.1203	.1262	.1180	.1205		

TABLE VIII.- CONTINUED
(e) α = 3.95°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0283	.2123	.1328		.176	.4115	.1270	.4753		.3273				
.10	.0369	.2163	.125	.371	.313	.4110		.445	.559	.359	.539	.355		
.15	.0377	.2441	.1051	.4105	.1401	.4429			.1441	.385				
.20	.0270	.2280	.1013	.3736	.322	.4325	.1505	.3982	.1432	.4311	.1521	.1308		
.25	.0502	.0113			.305	.4234	.1406	.4338	.161	.1295	.1475	.1308		
.30	.0507	.0332							.144	.1275	.1446	.1238		
.40	.0475	.0724	.0770	.0492	.0447	.0860	.0364	.015	.0289	.1230	.1382	.1109		
.50			.0823	.0285	.055	.0761	.0497	.0835			.0262	.060		
.60					.0592	.0626	.0348	.0550	.0511	.0867	.0572	.075		
.70	.0429	.0909	.0663	.0436	.0672	.0544	.0739	.0217	.1485	.0734	.1398	.0923		
.80	.1075	.0405	.1356	.0820			.1242	.1021	.1270	.1047	.1268	.1089		
.90	.0980	.0477	.1278	.0994	.1291		.1221	.1135	.1225	.1095	.1254	.118		
.95	.0888	.0461	.1280	.0964	.1280	.1197	.1221	.1185	.1221	.1132	.1246	.1214		.0867

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0828	.1086	.1573	.4036			.1532	.3115	.1805	.3874	.1865	.3330	.1287	.2833
.10	.0851	.0912					.1752	.4013	.799	.3852			.716	.335
.15					.210	.3971	.1700	.394	.725	.3986			.48	.344
.20	.0658	.0258			.368	.3553	.1706	.3822	.1725	.3919	.1752	.374	.374	.2896
.25	.0085	.0287	.0036	.2417			.1712	.3765	.1742	.3897	.1785	.3750	.315	.2658
.30			.0666	.0329			.1664	.3462	.1712		.1686	.3437	.255	.255
.40	.0028	.0635			.0461	.0368	.0384	.0549	.0201	.0962	.2258	.0647	.215	.2333
.50	.0089	.0800	.0514	.0055	.0633	.0204	.0470	.0423	.0392	.0625	.0680	.0443	.2850	.1602
.60							.1115	.0564	.0443	.0528	.1483	.1008	.34	.9
.70	.0891	.0527	.1365	.0990	.1321	.1218	.1348	.1193	.1515	.0999	.1290	.138		.175
.80	.0991	.0763	.1418	.124	.297	.1357	.1277	.1291	.1246	.1203	.1254	.210	.186	.144
.95	.1254		.1254	.1186	.1280	.1366	.1268	.1312	.1263	.1251	.1250	.247	.129	.125

TAIL 2

TABLE VIII.- CONTINUED
(f) α = 5.95°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0054	.2947	.0889	.5056	.0865	.4893	.0887	.5387	.1225	.3842	.1184	.4807	.1347	.387
.10	.000	.2605	.0870	.4770	.0988	.5244		.5182	.1098	.5131			.242	.457
.15	.0003	.3111	.0713	.4396	.0981	.5286			.1092	.5041	.1190	.4973	.0852	.43
.20	.0072	.2909	.0636		.0952	.5095	.1222	.4737	.1110	.5031	.1151	.4954	.0938	.3826
.25	.0734	.0423			.0938	.4901	.1064	.5093	.1086	.5047	.107	.4915	.0844	.3553
.30	.0734	.0656					.0572		.0503		.1041	.4960	.0859	.370
.40	.0777	.1086	.0975	.0749	.0562	.1176	.0574	.1339		.1610	.0484	.4421	.064	.319
.50			.1034	.0589	.0768	.1073	.0744	.1164	.0712	.1199	.0767	.1401	.0785	.2943
.60	.0644	.1244	.0895	.0797	.0798	.0947	.0525	.0862	.1409	.0541	.1272	.0752	.1356	.105
.70	.1180	.0163	.1303	.0625	.0867	.0858	.0953	.0490	.1245	.0867	.1259	.0949	.1226	.105
.80	.1085	.0223	.1310	.0817			.1218	.0850	.1218	.0918	.1264	.1013	.162	
.90	.0991	.0170	.1321	.0778	.1207	.1036	.1215	.0967	.1215	.0963	.1264	.087		.0863
.95							.1217	.1024						

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0963	.0991	.0636	.4444			.0993	.3910		.4806	.1405	.3943	.0909	.3425
.10	.1072	.0842			.1106	.4465	.1193	.4871	.1302	.4709			.1320	.409
.15							.1136	.4638	.1275	.4614			.1116	.3826
.20	.1193	.0940	.0395	.2707	.1047	.3885	.1152	.4365	.1206	.4452	.1301	.4589	.1023	.3680
.25	.0144	.0306	.0807	.0456			.1137	.4153	.1215	.4307	.1316	.4520	.0975	.3475
.30							.1063	.3815	.1188	.418	.1202	.3938	.0935	.329
.40	.0219	.0689			.0724	.0581			.0503	.1183	.0519	.1024	.061	.224
.50							.0681	.0752	.0681	.0931	.1024	.1017	.1443	.137
.60	.0020	.0742	.0525	.0545			.0755	.0633	.0723	.0699	.0910	.0278	.407	.1179
.70					.0861	.0402	.1325	.0408	.1529	.0901	.386	.0860		
.80	.0897	.0497	.1292	.0878	.1372	.1123	.1338	.1060	.1275	.1031	.1329	.1016	.1259	.1028
.90	.057	.0663	.1399	.1065	.350	.124	.1323	.1165	.1298	.1149	.1316	.1092	.1353	.1120
.95			.1252	.1141	.1348	.1251	.1313	.1214			.1315	.1147		

TAIL 2

TABLE VIII - CONTINUED

Cp at η/b of

TAIL 1

Cp at η/b of

TAIL 2

TABLE VIII. - CONTINUED
(h) α = 9.95°

TAIL 1

Cp at -.5 cf

x/c	0.02		0.22		0.44		0.56		0.57		0.33		0.38	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

Cp at y/b cf

x/c	0.02		0.22		0.44		0.56		0.67		0.33		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0753	.1179	.0529	.3242			-.0275	.5752	.0102	.6037	.0384	.6994	.0031	.6415
.10	.0845	.0778					-.0105	.5713	.0105	.5637			.0472	.6121
.15					-.0197	.4775	-.0161	.5332	.0076	.5183			.0427	.5597
.20	.1032	.0860					-.0175	.4799	.0008				.0382	.5034
.25	-.0096	.0039	-.0789	.2308	-.0120	.4218	-.0153	.4535	.0011	.4957	.0266	.5457	.0345	.4625
.30			-.1127	.0434			-.0191	.4067	-.0015	.4780	.0248	.4973	.0320	.4269
.40	-.0120	.0484									-.0139	.4240	.0273	.3635
.50	.0161	.0509	-.1140	.0904	-.1166	.0943	-.1199	.1122	-.1205	.1524	-.120	.1315	-.0029	.2344
.55	-.0161				-.1083	.0812	-.1262	.1062	-.1311	.1236	-.1407	.0661	-.0273	
.70	-.1129	-.0726	-.1714	-.0695	-.1638	-.0847	-.1615	-.0102	-.1318	-.1130	-.1494	-.0596	-.1538	-.1078
.80	-.1272	-.0811	-.1683	-.0931	-.1535	-.0880	-.1533	-.0799	-.1517	-.0665	-.1496	-.0708	-.1494	-.1229
.90							-.1534	-.0894	-.1460	-.0821	-.495	-.0774	-.1261	-.1167
.95			-.1589	-.1052	-.1458	-.0885	-.1536	-.0943	-.1487	-.0875	-.1500	-.0832	-.1324	-.1265

TABLE VIII. - CONTINUED
(b) α = 11.9°

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	-.0913	.5927	-.0062		.0075	.8615	-.0025	.8855		.8855			.0612	.0315
.10	-.0997	.4045	-.0131	.7321	.0094	.3092			.0403	.9302	.0362	.9143	.0150	
.15	-.1025	.5145	-.0238	.6749	.0081	.7709			.0237	.7842			.0350	.5511
.20	-.1012	.4880	-.0323	.6317	.0073	.7226	.0351	.7191	.0194	.7566	.0345	.7872	.0756	
.25	-.1391	.1569			-.0063	.6924	.0155	.7192	.0195	.7405	.0343	.7694	.0535	
.30	-.1392	.1993							.0153	.7103	.0245	.7356	.0535	
.40	-.1413	.2540	-.1523	.1768	-.1163	.3070	-.1085	.2240	-.1080	.2566	.0215	.6678	.0492	
.50			-.1575	.1680	-.1308	.2045	-.1244	.2172			-.1015	.2304	.0456	.4155
.60					-.1342	.1987	-.1066	.1945	-.1261	.2216	-.1252	.1870	.0684	.0755
.70	-.1120	.2785	-.1397	.2193	-.1383	.1916	-.1394	.1378	-.1396	.0048	-.1416	-.0339	-.1829	-.0683
.80	-.1444	.1221	-.1444	.0159			-.1357	-.0229	-.1384	-.0231	-.1416	-.0634	-.1725	
.90	-.1204	.0941	-.1465	.0047	-.1364		-.1358	-.0349	-.1370	-.0346	-.1427	-.0640		
.95	-.1170	.0965	-.1466	.0185		-.0417	-.1356	-.0409	-.1368	-.0407	-.1432	-.0688		-.0647

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0508	.1078	.0734	.2918			-.0993	.5911			-.0336	.7281	-.0501	.7236
.10	.0633	.0651					-.0737	.5580	-.0556	.6158			-.0053	.6604
.15					-.0536	.4531	-.0753	.5220	-.0552	.5729			-.0027	.6011
.20	.0796	.0511					-.0599	.4807	-.0610	.5346			-.0043	.5463
.25	-.0263	-.0176	-.0479	.2220	-.0499	.4064	-.0649	.4520	-.0514	.5024	-.0271	.5402	-.0067	.4969
.30			-.0928	.0360			-.0663	.4056	-.0528	.4772	-.0345	.5282	-.0085	.4567
.40	-.0198	-.0306					-.1391	.1287	-.1509	.1555	-.0432	.4208	-.0123	.3914
.50			-.1130	.0896			-.1465	.1296	-.1557	.1503	-.1435	.1338	-.0333	.2454
.60	.0078	-.0342			-.1388	.1060	-.1738	.0023	-.1531	.1406	-.1653	.0791	-.1643	-.2997
.70					-.1467	.0961	-.1706	-.0705	-.1643	-.0503	-.1627	-.0467	-.1629	-.155
.80	-.057	-.0558			-.1741	-.0733					-.1625	-.0561		
.90	-.1145	-.1013	-.1827	-.1020	-.1726	-.0734	-.1683	-.0764	-.160	-.0710	-.1620	-.0604	-.511	-.073
.95			-.1665	-.1102	-.1691	-.0745	-.1661	-.0813	-.1642	-.0762	-.1622	-.0658	-.622	-.197

TAIL 2

91

TABLE VIII.- CONTINUED
(j) α = 15.95°

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.33		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05		.7238	-.2122	.9880	.0092	1.0953	-.0015	1.1120		.1000			.0506	.094?
.10		.5226				.6521		.9987	.0450					.255?
.15					-.0052	.4738			-.0028					
.20						.7852	.0654	.9822	.2341		.0934			.756?
.25			-.0726	.7852	-.0254	.8852	.0343	.9727	.2215		.0877		.0715	
.30										.0570	.0905			.0519
.40	-.0250			.2619	-.1230	.2860	-.1098	.2920	-.0865		.0818		.0502	.0934
.50			-.865	.5525	-.36?	.2626	-.285	.3007		.3071	.1218	.7505		.1985
.60	-.0024	.0029		.0583	-.1413	.2654	-.185	.2655	-.257		.1211		-.172?	.053?
.70			-.415	.3517	-.419	.2653	-.1437	.2220	-.1431	.0542	.1452		-.1865	.0455
.80	-.1150	-.1053	-.470	.1098	-.372	.0195	-.1382	-.0328	-.1410	.0012	.1458	.0137	-.752	.0374
.90	-.127?	-.1853	-.117?	.1047			-.1390	-.0194	-.1335	-.0736	.174	-.0227		
.95	-.132	-.357	-.407	.1145			-.1381	-.0125	-.1393	-.0060	.1485	-.0245		-.0387

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.33		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0311	.0380	.0653	.1535			-.1750	.5219		.7434	.1533	.5737	-.1659	.7336
.10	.0482	.509?				.4903	-.1514	.4905	-.1507	.5217			-.1367	.6607
.15	.0677	.205?			-.1324		-.1553	.4597	-.1652	.4976			-.1256	.6210
.20	-.0383	.205?					-.1537	.4357	-.1550				.217	.5626
.25	-.0323	-.0659	-.0726	.1570	-.1326	.3735	-.1521	.1099	-.1633	.4695	-.180	.5147	-.1205	.5127
.30			-.155	.0039			-.1532	.3575	-.1637	.4270	-.1513	.1336	-.1207	.1692
.40	-.0250	-.0219							-.1653	.1294	-.1556	.3751	-.1205	.3903
.50					-.724	.198	-.1805	.442	-.1945	.1595	-.1954	.138	-.1289	.2290
.60	-.0024	.0029	-.133?	.0583			-.1326	.149	-.1915	.1738	-.1910	-.1057	-.1875	.0666
.70					-.1814	.1289	-.2003	.0135	-.1870	-.0264	.998	-.0245	-.1821	.0851
.80	-.1150	-.1053	-.165?	.1037	-.1973	-.0505	-.1973	-.0558	-.1855	-.0570	.1883	.038		
.90	-.127?	-.125?	-.1938	-.1235	-.986	-.0673	-.1977	-.0620	.862	-.0565	-.1887	-.0377	-.1744	-.0755
.95			-.1804	-.1291	-.1975	-.0747	-.1969	-.0645			-.1930	-.0432	-.1898	-.0862

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.1122	.8465	-.0037		.015?	.3348	-.007?	.3636		.4197			.008?	.346?
.10	-.0929	.6719	-.0053	.387?	.027?	.3?8?		.2395	.0579	.2783	.0431	.3?58	.2292	.5344
.15	-.1?..	.8480	-.017?	.0243	.0256	.1544	.0388		.0434	.2057			.0957	.385?
.20	-.006?	.8110	-.030?	.9656	.0218	.0745	.0389	.0743	.0410	.1440	.0541	.15??	.1038	.31??
.25	-.0409	.3480			.0162	.0075	.0355	.0475	.0410	.0848	.0489	.1122	.0?	.935?
.30	-.1450	.409?			-.1?61				.0339	.0145	.0432	.0300	.0??	.??
.40	-.1433		-.1563	.3622	-.1310	.3737	-.102?	.3690	-.0993	.3704	.0323	.0?30	.091?	.70??
.50		.5162	-.1621	.3803	-.1310	.39?0	-.12?5	.4010			.0?70	.32??	.073?	.705?
.60					.353	.4029	-.12?2	.3714	-.1197	.4042	-.1?74	.3074	-.0?55	.5696
.70	-.1363	.5829	-.1358	.5975	-.1386	.4009	-.1374	.3189	-.1344	.1119	-.1389	.05?2	-.1718	-.0266
.80	-.153?	.3467	-.1402	.2356			-.130?	.0945	-.1338	.0776	-.1404	.0365	-.1876	-.0266
.90	-.1622	.2860	-.1413	.1910	-.1305	.1226	-.1303	.0786	-.1321	.0689	-.1414	-.0293	-.1717	-.008?
.95	-.1608	.2918	-.1412	.1991			-.1308	.0706	-.1318	.0606	-.1428	.0245		.00?8

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0028	-.0095	-.0224	.1419			-.1956	.4973			-.1928	.5789	-.2075	.6291
.10	.0172	-.0362					-.1856	.4807	-.1922	.5035			-.198?	.5344
.15					-.1625	.4087	-.1817	.4616	-.1903	.4872			-.1924	.5587
.20	.0421	-.0325	-.1109	.1584			-.1818	.4376	-.1898	.4657	-.1743	.4603	-.1893	.5149
.25	-.0575	-.0865	-.1475	.0088	-.1720	.3849	-.1853	.4066	-.1903	.4368	-.1898	.4358	-.1880	.4689
.30							-.1893	.3445	-.1911	.3935	-.1940	.3313	-.1888	.4303
.40	-.0496	-.0406											-.1872	.3580
.50			-.1593	.0574	-.1850	.1638	-.1928	.1708	-.2099	.1288	-.2070	.1519	-.1911	.21?0
.60	-.0309	-.0220					-.2054	.1827	-.2087	.1728	-.2044	.1234	-.2030	-.0643
.70					-.1912	.1691	-.2125	.0389	-.2062	.1901	-.2041	-.0112	-.1953	-.0539
.80	-.1412	-.1171	-.1985	-.1012	-.2095	-.0389	-.2109	-.0393	-.1994	-.0089	-.2043	-.0179		
.90	-.1566	-.1394	-.2023	-.1238	-.2099	-.0629	-.2097	-.0524	-.1995	-.0352	-.2027	-.0204	-.1850	-.0449
.95			-.1938	-.1316	-.2095	-.0720	-.2090	-.0591	-.2034	-.0396	-.2036	-.0251	-.2001	-.0555

TAIL 2

TABLE IX.- PRESSURE COEFFICIENTS, Λ = 67.5°, δ = 0°, M = 2.36

(a) α = -4.10°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0353	.3486	.3732		.3367	.1453	.3253	.2114		.1134			.3865	.119?
.10	.1915	.0652	.3545	.1534	.3733	.1720		.2271	.3652	.1817	.3418	.190?	.3728	.1965
.15	.157?	.0520	.3257	.1353	.3722	.1769			.3589	.1751			.3266	.172?
.20	.1461	.0433	.3066	.1201	.3605	.1614	.2809	.3134	.3621	.1796	.3619	.1823	.3072	.53?
.25	-.0045	-.0453			.3462	.1555	.3605	.1688	.3654	.1775	.3618	.1658	.2807	.129?
.30	-.0241	-.0323							.3645	.1708	.3615	.1759	.255?	.124?
.40	-.0999	-.0082	-.0365	-.0778	-.0738	-.0440	-.0903	-.0355	-.0937	-.0195	.3578	.157?	.2429	.105?
.50			-.2217	-.0782	-.0582	-.0595	-.0747	-.0512			-.0746	-.0253	-.2235	.0855
.60					-.0503	-.0615	-.0226	-.1252	-.0775	-.0481	-.0746	-.0633	-.123?	.145?
.70	-.0399	-.0249	-.0637	-.0397	-.0452	-.0517	-.0334	-.0869	-.0757	-.0469	-.0867	-.0517	-.1079	.151?
.80	-.0703	-.0829	-.0787	-.1296			-.1075	-.1482	-.1077	-.1362	-.1022	-.1325	-.1110	-.1317
.90	-.0551	-.0911	-.1065	-.1487	-.1211	-.1306	-.1171	-.1382	-.1105	-.1312	-.1092	-.1292		
.95	-.0669	-.0930	-.1119	-.1211			-.1210	-.1351	-.1149	-.1302	-.149?	-.1297		-.134?

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.57 U.S.	0.57 L.S.	0.83 U.S.	0.83 L.S.	0.93 U.S.	0.93 L.S.
.05	.1922	.1245	.3564	.2178			.3168	.1731	.3416	.2256	.3448	.1984	.2525	.1614
.10	.1937	.0928					.3435	.2257	.3433	.2194			.2900	.1960
.15					.3460	.2250	.3425	.2232	.3433	.2194			.2723	.1805
.20	.1943	.0934					.3442	.2200	.3379	.2217			.2615	.1599
.25	.0426	-.0300	.1039	.1445	.3507	.2121	.3461	.2182	.3416	.2256	.3362	.2197	.2509	.1472
.30			.0330	-.0294			.3416	.2022	.3395	.2235	.3418	.2217	.2391	.1439
.40	-.0188	-.0358			.0438	-.0260	.0525	-.0134	.0789	.0013	.3279	.1973	.2350	.1350
.50							.0457	-.0276	.0520	-.0215	.0638	-.0072	.1930	.0907
.60	.0748	-.0114	.0057	-.0614	-.0223	-.0437	-.0449	-.1081	.0460	-.0258	.0049	-.0656	-.1148	-.125?
.70									-.1096	-.1406	-.166?	-.1423	-.1336	-.1361
.80	-.0792	-.0916	-.1208	-.1303	-.1212	-.1377	-.1316	-.1361	-.1260	-.1142	-.1324	-.1212	-.0937	-.1449
.90	-.0661	-.1198	-.1263	-.1243	-.1365	-.1240	-.1316	-.1200	-.1263	-.1154	-.1342	-.1180	-.1001	-.1618
.95			-.1233	-.1247	-.1325	-.1215	-.1285	-.1185			-.1227	-.1182		

TAIL 2

TABLE IX. - CONTINUED
(b) α = -2.10°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0877	.1247	.3072		.2595	.2075	.2596	.2805		.1676			.3225	.1727
.10	.1320	.0898	.2845	.2206	.2904	.2379		.2524	.2965	.2404	.2844	.2485	.303	.2460
.15	.1280	.0860	.2657	.2008	.2949	.2382			.2852	.2378			.2555	.2461
.20	.1176	.0767	.2488	.1857	.2903	.2255	.2950	.2296	.2880	.2440	.2927	.2475	.2440	.2020
.25	-.0048	-.0357			.2831	.2272	.2875	.2289	.2908	.2398	.2911	.2479	.2212	.1771
.30	-.0136	-.0218							.2883	.2340	.2894	.2400	.2009	.1636
.40	-.0601	-.0060	-.0030	-.0471	.0386	-.0107	.0519	-.0030	.0533	.0155	.2836	.2329	.1854	.1463
.50			-.0082	-.0578	.0256	-.0248	.0393	-.0176			.0591	.0096	.1722	.219
.60					.0184	-.0320	.0185	-.0243	-.0392	-.0146	-.0292	-.0188	-.1239	-.1368
.70	-.0167	-.0085	.0213	-.0252	.0083	-.0389	.0066	-.0621	-.0993	-.1282	-.1105	-.1413	-.1212	-.1493
.80	-.0763	-.0749	-.0995	-.1208			-.1246	-.1492	-.1236	-.1434	-.1240	-.1271	-.1330	-.1298
.90	-.0705	-.0885	-.1226	-.1410	-.1314	-.322	-.1331	-.1300	-.1267	-.1216	-.1285	-.1172		
.95	-.0753	-.0932	-.1243	-.1285	-.1266		-.1291	-.1266	-.1240	-.1189	-.1224	-.1158		-.1176

Cp at y/b of

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1595	.1364	.3152	.2432			.2843	.1912		.2455	.3172	.2183	.2329	.1893
.10	.1555	.1040					.3099	.2582	.3090	.2403			.2733	.2173
.15					.3120	.2460	.3068	.2434	.3159	.2428			.2490	.1955
.20	.1610	.1045	.0816	.1604			.3113	.2400	.3066	.2457	.3058	.2425	.2408	.1757
.25	.0227	-.0153	.0145	-.0172	.3115	.2334	.3127	.2386	.3097	.2441	.3118	.2145	.2259	.1599
.30							.3096	.2251	.3064	.2184	.2986		.2181	.1540
.40	.0108	-.0225			.0244	-.0148	.0342	-.0045	.0573	.0184	.0468	-.0069	.2118	.1452
.50	.0782	.0164	-.0152	-.0502			.0273	-.0138	.0360	-.0075	-.0090	-.0558	.1723	.0951
.60					-.0055	-.0343	-.0590	-.0922	.0292	-.0130	-.1226	-.1421	-.1206	-.1264
.70									-.1173	-.1354			-.1327	-.1464
.80	-.0812	-.0815	-.1237	-.1400	-.1289	-.1456	-.1297	-.1457	-.1277	-.1120	-.1369	-.1195		
.90	-.0748	-.1112	-.1274	-.1276	-.1406	-.1271	-.1367	-.1224	-.1191	-.1126	-.1223	-.1135	-.1060	-.1123
.95			-.1233	-.1258	-.1260	-.1229	-.1234	-.1185			-.1145	-.1130	-.0992	-.1313

TABLE IX. - CONTINUED
(c) a = -0.10°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0746	.1098	.2324		.1965	.2772	.2054	.3531		.2255			.2623	.2322
.10	.1033	.249	.2139	.3008	.2210	.3094		.3166	.2360	.3080	.2299	.3160	.2432	.3073
.15	.0999	.251	.2001	.2763	.2243	.3078			.2236	.3142			.1930	.2820
.20	.0869	.149	.1885	.2579	.2226	.2972	.2419	.2778	.2250	.3128	.2318	.3208	.1870	.2522
.25	-.0178	-.0258			.2184	.2942	.2235	.2972	.2280	.3058	.2293	.3128	.1687	.2298
.30	-.0026	-.0094			.0049	.0255			.2250	.2995	.2295	.3065	.1539	.2123
.40	.0203	.0259	-.0285	-.0141	-.0058	-.0103	.0139	.0349	.0212	.0545	.2218	.2976	.1463	.1959
.50			-.0368	-.0283	-.0125	.0019	-.0018	.0199			.0236	.0440	.1288	.1625
.60	-.0040	.3266	-.0137	-.0076	-.0222	-.0054	-.0128	-.0144	-.0010	-.0230	-.0097	.0148	-.1299	-.1299
.70	-.0831	-.0673	-.1189	-.1083			-.0266	-.0316	-.1219	-.1074	-.1313	-.1236	-.1452	-.1377
.80	-.0808	-.0775	-.1342	-.1268	-.1220	-.1385	-.1410	-.1336	-.1381	-.1356	-.1310	-.1361	-.1294	-.1422
.90	-.0832	-.0823	-.1251	-.1236			-.1245	-.1365	-.1175	-.1271	-.1124	-.1170		
.95							-.1170	-.1232	-.1121	-.1151	-.1095	-.1104		-.1023

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1246	.1385	.2800	.2719			.2542	.2104			.2877	.2395	.2125	.2138
.10	.1200	.1089					.2768	.2818	.2810	.2676			.2547	.2405
.15					.2797	.2696	.2761	.2663	.2849	.2636			.2272	.2144
.20	.1251	.1086	.0646	.1789	.2751	.2578	.2795	.2617	.2761	.2658	.2728	.2640	.2167	.1931
.25	.0016	-.0013	-.0037	-.0055			.2799	.2602	.2795	.2679	.2806	.2640	.2056	.1757
.30							.2766	.2449	.2761	.2666	.2663	.2388	.1993	.1668
.40	.0087	.0028			.0064	-.0046	.0172	.0090	.0410	.0345			.1923	.1571
.50	.0717	.0426	-.0353	-.0414			.0098	-.0008	.0186	.0061	.0288	.0156	.1538	.1017
.60					-.0111	-.0209	-.0712	-.0873	.0114	.0009	-.0232	-.0456	.1278	.1277
.70	-.0797	-.0732	-.1206	-.1281	-.1370	-.1424	-.1388	-.1415	-.1268	-.1280	-.1313	-.1372	-.1379	-.1447
.80	-.0798	-.1027	-.1284	-.1315	-.1365	-.1306	-.1315	-.1284	-.1204	-.1150	-.1412	-.1239	-.1117	-.0928
.90			-.1288	-.1257	-.1238	-.1222	-.1204	-.1193	-.1153	-.1124	-.1198	-.1116	-.1013	-.1036
.95											-.1148	-.1094		

TAIL 2

TABLE IX.- CONTINUED
(d) α = 1.91°

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0513	.1515	.1677	.3125	.1428	.3557	.1545	.4295		.2874		.3815	.2059	.2981
.10	.0624	.1655	.1525	.3707	.1614	.3825		.3935	.1810	.3863	.1804		.1925	.3630
.15	.0645	.1810	.1393	.3551	.1625	.3872			.1702	.3930			.1490	.3410
.20	.0514	.1687	.1303	.3254	.1516	.3770	.1855	.3486	.1701	.3836	.1765	.3640	.1379	.3.02
.25	-.0372	-.0089			.1588	.3701	.1670	.3759	.1734	.3779	.1755	.3860	.1276	.3965
.30	-.0253	.0130	-.0590	.021?	-.0278	.0619	-.0209	.0742	.1712	.3751	.1751	.3796	.1135	.2645
.40	-.0106	.0571	-.0538	.0054	-.0403	.0459	-.0330	.0578	-.3122	.3990	.1672	.3654	.1258	.2450
.50					-.0454	.0368	-.0104	.0335	-.0344	.0626	-.0085	.3927	.1028	.2082
.60											-.0387	.3535	.1241	.2095
.70	-.0226	.0677	-.0411	.0206	-.0543	.0295	-.0575	-.0006	-.1386	-.0861	-.1470	-.1030	.1532	.1205
.80	-.0923	-.0540	-.0337	-.0910			-.1269	-.1154	-.1297	-.1174	-.1259	-.1186	.1095	.1299
.90	-.0882	-.0611	-.1279	-.1094	-.1183	-.1310	-.1205	-.1267	-.1201	-.1216	-.1208	-.1261		
.95	-.0884	-.0646	-.1235	-.1031			-.1200	-.1293	-.1188	-.1234	-.1199	-.1265		-.1054

TAIL 2

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1090	.1262	.2439	.3125			.2249	.2329	.2520	.2938	.2589	.2594	.1916	.2268
.10	.1041	.1015					.2462	.3072	.2536	.2918			.2347	.2569
.15					.2474	.2931	.2431	.2963					.2072	.2377
.20	.1028	.1026	.0454	.1951	.2415	.2945	.2458	.2853	.2449	.2908	.2458	.2892	.1938	.2140
.25	-.0062	-.0044	-.0210	.0026			.2473	.2892	.2475	.2930	.2514	.2893	.1853	.1942
.30							.2429	.2592	.2451	.2917	.2407	.2648	.1784	.1875
.40	.0115	-.0283							.0233	.0514	.0128	.0221	.1701	.1741
.50	.0507	.0557			-.0096	.0085	.0000	.0217	.0017	.0217	-.0340	-.0331	.1329	.1224
.60			-.0446	-.0344	-.0250	-.0096	-.0072	.0100	-.0051	.0160			.1345	.1290
.70							-.0828	-.0833	.1356	-.1205	-.1372	-.1276	.1393	.1361
.80	-.0843	-.0723	-.1226	-.1175	-.1444	-.1385	-.1466	-.1355	-.1194	-.1295	-.1345	-.1347	.1124	.1093
.90	-.0893	-.0991	-.1373	-.1298	-.1340	-.1388	-.1293	-.1402	-.1180	-.1208	-.1181	-.1190	.1155	.1006
.95			-.1363	-.1288	-.1261	-.1252	-.1233	-.1263			-.1156	-.1125		

97

TABLE IX. - CONTINUED
(a) α = 3.90°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0219	.2332	.1054		.0949	.4491	.1088	.5116		.3609			.1555	.3735
.10	.0191	.2113	.0922	.4595	.098	.4831		.4827	.1315	.4800	.1555	.4581	.1492	.4421
.15	.0225	.2467	.0841	.4343	.1098	.4788			.1207	.4777			.1014	
.20	.011	.2326	.0774	.3987	.078	.4528	.1374	.4553	.1199	.4694	.1315	.4675	.0973	
.25	.0614	.3158			.055	.4470	.1162	.4380	.1225	.4664	.1280	.4633	.0931	
.30	.0533	.3415					.0506	.1119	.1210	.4635	.125	.4657		.3215
.40	.0472	.3915	.0887	.0564	.0575	.0590	.0637	.0962	.0404	.1432	.1236	.4461	.0906	.3068
.50			.0890	.0415	.0689	.0809	.0372	.0655			.0387	.1277	.0804	.2625
.60	.0339	.1109	.0682	.0630	.0738	.0735	.0861	.0313	.0637	.1014	.0674	.0968	.1386	.109
.70	.1022	.0365	.1456	.0683	.0816	.0659	.1244	.0957	.1506	.0644	.1355	.0805	.1270	.104
.80	.0990	.0403	.1340	.0878	.1223	.128	.1244	.1076	.1282	.0972	.1282	.0988	.1251	
.90	.0894	.0392	.1305	.0867			.1247	.1121	.1246	.1024	.1275	.1011		
.95									.1244	.1065	.1270	.1126		.1027

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1510	.0931	.1831	.3583			.1942	.2607	.2225	.3284	.2252	.2778	.1667	.2422
.10	.1446	.0749					.2123	.3423	.2226	.3273			.2095	.2846
.15					.2087	.3456	.2088	.3381	.2130	.3259			.1825	.2653
.20	.1261	.0915					.2090	.3326	.2142	.3300	.2151	.3197	.1721	.2450
.25	.0102	.0062	.0286	.2050	.2017	.3120	.2097	.3222	.2102	.3300	.2.95	.3201	.1646	.2217
.30			.0379	.0066			.204	.2992		.3279			.1575	.2164
.40	.0012	.0355			.0248	.0179	.0190	.0352	.0022	.0745	.2054	.2975	.1483	.1936
.50							.0249	.0218	.0179	.0403	.0034	.0361	.1145	.1264
.60	.0323	.0571	.0411	.0225	.0432	.0006	.0971	.0756	.0243	.0295	.2502	.0143	.1389	.1281
.70							.1511	.1295	.1448	.1115	.1454	.1149	.1410	.1269
.80	.1064	.0760	.1272	.1129	.1498	.1346	.1399	.1386	.1224	.1305	.1291	.1258	.1139	.1227
.90	.1122	.0955	.1436	.1221	.1325	.451	.1276	.1360	.1224	.1286	.1205	.1304	.1230	.1264
.95			.1289	.1278	.1292	.1307					.1195	.1247		

98

TABLE IX. - CONTINUED
(f) α = 5.90°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0162	.3300	.0496		.0523	.5693	.0645	.6154		.4380			.1087	.4661
.10	-.0260	.2527	.0487	.5469	.0636	.5987		.5935	.0884	.5960	.0913	.5464	.1073	.5317
.15	-.0217	.3160	.0354	.5092	.0631	.5743			.0755	.5809			.0655	.4823
.20	-.0264	.3022	.0280	.4679	.0598	.5458	.0938	.5276	.0745	.5724	.0893	.5778	.0656	.4611
.25	-.0886	.0490			.0577	.5225	.0717	.5465	.0764	.5618	.0854	.5812	.0683	.4270
.30	-.0834	.0783							.0751	.5485	.0810	.5661	.0706	.4027
.40	-.0861	.1343	-.1149	.0925	-.3859	.1320	-.0772	.1488	-.0693	.1859	.0758	.5255	.0702	.3839
.50			-.1148	.0796	-.0977	.1164	-.0913	.1329			-.0654	.1700	.0631	.3221
.60					-.1003	.1116	-.0642	.1020	-.0896	.1392	-.0919	.1358	-.1403	-.0996
.70	-.0578	.1598	-.0964	.1148	-.1070	.1042	-.1118	.0654	-.1343	-.0447	-.1285	-.0606	-.1292	-.0993
.80	-.1101	-.0084	-.1415	-.0419			-.1251	-.0740	-.1273	-.0769	-.1285	-.0806	-.1513	-.0980
.90	-.1097	-.0109	-.1392	-.0621	-.1260		-.1251	-.0864	-.1250	-.0818	-.1293	-.0913		
.95	-.1130	-.0071	-.1388	-.0606		-.0917	-.1250	-.0916	-.1247	-.0864	-.1292	-.0964		-.0930

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2222	.0341	.1234	.3334			.1563	.3086			.1933	.2923	.1432	.2651
.10	.2194	.0206					.1723	.3971	.1866	.3783			.1862	.3194
.15					.1597	.3799	.1676	.3897	.1856	.3813			.1603	.3018
.20	.1704	-.0611					.1661	.3695	.1754	.3752			.1498	.2792
.25	.0138	-.0193	.0005	.1766	.1592	.3319	.1666	.3510	.1753	.3725	.1825	.3630	.1404	.2636
.30			-.0348	-.0119			.1634	.3184	.1709	.3615	.1842	.3663	.1345	.2561
.40	-.0075	-.0329					-.0361	-.0409	-.0214	-.0869	.1689	.3239	.1260	.2345
.50			-.0397	-.0007			-.0424	-.0294	-.0395	-.0532	-.0233	-.0587	.0934	.1568
.60	.0108	.0598			-.0618	.0023	-.1038	-.0636	-.0447	-.0378	-.0675	.0003	-.1447	-.1239
.70							-.1470	-.1245	-.1524	-.1088	-.1507	-.1048	-.1433	-.1219
.80	-.1248	-.0791	-.1282	-.1094	-.1468	-.1351	-.1322	-.1349	-.1259	-.1268	-.1302	-.1180		
.90	-.1308	-.0962	-.1390	-.1205	-.1351	-.1459	-.1305	-.1373	-.1272	-.1293	-.1262	-.1253	-.1203	-.1203
.95			-.1305	-.1243	-.1330	-.1354					-.1257	-.1289	-.1278	-.1321

99

TABLE IX.- CONTINUED
(g) α = 7.90°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0543	.4256	.0041		.0160	.7240	.0225	.7733		.5936			.0617	.5922
.10	-.0699	.2995	.0003	.6263	.2232	.6990		.7132	.0495	.7295	.0514	.7035	.0551	
.15	-.0647	.3893	-.0093	.5763	.3214	.5585			-.0351	.6873			-.0371	
.20	-.0652	.3736	-.0164	.5316	.0176	.6202	.0575	.6111	.0341	.6528	.0507	.6941	-.0463	.5727
.25	-.1130	.0866			-.0151	.5987	.0297	.6191	.0355	.6444	.0473	.6815	-.0543	.5225
.30	-.1101	-.1197							-.0343	.6220	.0426	.6530	-.0580	.4902
.40			-.1396	-.1202										
.50											-.0887		-.0491	.3525
.60	-.0949	.2186	-.1237	.1718	-.1258	.1447	-.1334	.0994	-.1121	-.1750	-.138	-.1667	-.1538	-.0902
.70	-.1335	.0312	-.1448	-.0089	-.1306		-.1339	-.0516	-.1389	-.0254	-.1368	-.0437	-.1508	-.1010
.80	-.1193	.0260	-.1459	-.0318	-.1337	-.0668	-.1335	-.0643	-.1348	-.0533	-.1363	-.0637	-.1687	-.0993
.90	-.1351	.0291	-.1467	-.0251			-.1336	-.0695	-.1336	-.0583	-.1371	-.0746		
.95										-.0628	-.1371	-.0795		-.0951

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2459	.0086	.1257	.1768			.1045	.3833			.1577	.3454	.1151	.3032
.10	.2598	-.0119					.1224	.4665	.1420	.4585			.1564	.3740
.15					.0925	.4111	.1142	.4373	.1399	.4452			.1363	.3663
.20	.2234	-.0038					.1112	.3943	.1308	.4181			.1228	.3484
.25	.0366	-.0742	-.0041	.1165	.1149	.3464	.1110	.3683	.1293	.3970	.1459	.4154	.1131	.3304
.30			-.0176	-.0406			.1065	.3360	.1248	.3767	.1466	.3975	.1081	.3110
.40	.0058	.0125							-.0487	-.0965	.1342	.3336	.1006	.2739
.50			-.0450	-.0025	-.0624	.0286	-.0536	.0556	-.0662	.0656	-.0440	.0774	-.0707	.1789
.60	.0037	.0495					-.0605	.0408	-.0672	.0480	-.0847	.0126	-.1502	-.1217
.70					-.0570	.0093	-.1213	-.0615	-.1577	-.1036	-.1436	-.0993	-.1414	-.1241
.80	-.1323	-.0750	-.1416	-.1068	-.1501	-.1282	-.1368	-.1232	-.1338		-.1338	-.1113		
.90	-.1411	-.0980	-.1473	-.1202	-.1368	-.1366	-.1341	-.1324	-.1298	-.1236	-.1322	-.1188	-.1239	-.1118
.95			-.1321	-.1259	-.1313	-.1346	-.1340	-.1355	-.1316	-.1285	-.1321	-.1233	-.1304	-.1206

TABLE IX. - CONTINUED
(h) α = 9.90°

TAIL 1

	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	-.1040	.4999	-.0378		-.0190	.855!	-.0153	.8972		.85!5			.0255	.9987
.10	-.1122	.3479	-.044!	.6875	-.0142	.7790	-.0142	.9073	.0174	.9279	.02!3	.04!3	.0255	.9635
.15	-.1061	.4539	-.0525	.6355	-.0171	.734!	.0174	.7748	.0010	.7748			.0229	.7086
.20	-.1015	.4411	-.0592	.5946	-.2216	.6352	.0177	.6899	-.0017	.7459	.0185	.7870	.0055	.9160
.25	-.1354	.1214			-.0246	.65!!	-.0077	.6892	-.0006	.7213	.0147	.76!6	.0!!!	.3862
.30	-.1333	.161!	-.0150	.0193	-.1314	.1980	-.!200		-.0019	.6863	.0086	.724!	.04!3	.6452
.40	-.366	.2316	-.0165	-.0774	-.!453	.195!	-.!37!	.2080	-.1174	.231!	.0012	.6433	.036!	.!856
.50			-.1593	.1683	-.!484	.194-5	-.!!!!	.2081			-.!!06	.2228	.0!!!	.3875
.60			-.1572	.1660	-.1507	.1883	-.1494	.1836	-.1329	.2164	-.1320	.1921	-.!!7!	.0856
.70	-.1175	.2935	-.1400	.2297			-.1398	.1398	-.1478	.0022	-.1483	.0264	-.!!72	.1028
.80	-.1581	.0791	-.1533	.0291			-.1448	-.0244	-.1458	-.0272	-.1485	-.0443	-.18!!	.1025
.90	-.1412	.0664	-.1554	.0100	-.1444	-.0379	-.1444	-.0371	-.1449	-.0319	-.1492	-.0535		
.95	-.1347	.0640	-.1559	.0143			-.1444	-.0422	-.1447	-.0371	-.1496	-.0587	-.13!4	.1039

TAIL 2

	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1945	.0393	.1791	-.0450			.0198	.4831		.5177	.1114	.4878	.0789	.4157
.10	.2149	.0151					.0332	.5062	.0790	.4800			.1!95	.4797
.15					.0715	.3802	.0294	.4584	.0739	.4392			.1063	.4424
.20	.2203	-.0083	.0150	.0193			-.0453	.4083	.0641	.4121	.0389	.4239	.0925	.4023
.25	.0379	-.0877	-.0165	-.0774	.0777	.3379	.0653	.3839	.0644	.3904	.0978	.4009	.0835	.3684
.30							-.0749	.3511	-.0636		-.0868	.3453	-.0733	.3417
.40	.0284	-.0576							-.0779	.1089	-.0711	.0834	.073!	.2939
.50			-.0332	-.0521	-.0538	.0395	-.0773	.0673	-.0831	.0785	-.1072	.0220	.04!7	.1885
.60	.0134	.0079					-.0754	.0556	-.0828	.0584	-.1072	.0220	-.1532	.1180
.70					-.0549	.0299	-.1225	-.0531	-.1611	-.0969	-.1401	-.0332	-.14!!	.1272
.80	-.1305	-.0918	-.1427	-.1294	-.1497	-.102!	-.1521	-.1131	-.1379	-.1166	-.1380	-.1040		
.90	-.1438	-.1137	-.1518	-.1365	-.1457	-.1146	-.1422	-.1186	-.1379	-.1166	-.1373	-.1113	-.13!!	.1074
.95			-.1387	-.1399	-.1369	-.1135	-.1372	-.1211	-.1397	-.1227	-.1372	-.1164	-.1354	.164

101

TABLE IX. - CONTINUED
(I) a = 11.89°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.1528	.5592	-.0763		-.0647	.9429	-.0533	.9861		.9873				
	-.1465	.3939	-.0819	.7476	-.0509	.9550		.8825	-.0142	.9247	-.0085	.9717		
		.504	-.0890	.6975	-.0635	.8140			.3313	.9594				
			-.0957	.6579	-.0576	.7540	-.0247	.7693	.0359	.9268	-.0107	.8586		
		.5033			-.0604	.7500	-.0493	.7530	.0352	.7905	-.0148	.8201		
		.0548							.0360	.710	-.0200	.7818		
	-.1529	.505	-.1732	.2132	-.1498	.2916	-.1387	.2342	.387	.2435	-.0307	.6075		
			-.1697	.2158	-.1644	.2407	-.1570	.2492	-.1531		-.1308	.2362		
					-.1604	.2420	-.1385	.2319	-.1537	.2587	-.1504	.2142		
	.1200	.3650	-.1480	.3105	-.1604	.2388	-.1565	.1802	-.1536	.0295	-.1554	-.0085	-.1815	
	-.1535	.1300	-.1590	.0773			-.1517	.0047	-.1536	.0005	-.1563	-.0235	-.2000	
	-.1708	.1086	-.1620	.0511	-.1524	-.0006	-.1517	-.0080	-.0525	-.0045	-.1582	-.0322		
	-.1553	.1003	-.1620	.0473			-.1517	-.0131	-.1524	-.0102	-.1587	-.0373		-.1835

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1463	.0526	.2896	-.0998			-.0755	.4837			-.0495	.6075	.0336	.5509
	.1650	.0229					-.0372	.4696	-.0054	.5113			.0766	.5335
					.0310	.2131	.0030	.4162	-.0109	.4953			.0673	.435
	.1815	.2181	-.0343	-.0441	.0061	.2010	-.0202	.3828	-.0017	.4534	.0408	.4391	.0573	.4451
	.0135	-.0794	-.0157	-.1128			-.0273	.3648	.0145	.4257	.0367	.4251	.049	.3952
							-.0165	.3304	-.0233	.4034	-.0257	.3597	.049	.366
	-.0245	-.0769							-.0099	.28			.0398	.3130
	.0287	-.0695	-.0322	-.0418	-.0820	.0150	-.0751	.0597	-.1020	-.0867	-.1037	-.0905	-.0127	.2024
							-.0797	.0517	-.0942	-.0726	-.1310	-.0319	-.1481	-.1135
					-.0955	.0268	-.1316	-.0311	-.1645	-.0929	-.1461	-.0844	-.1455	-.1270
	-.1295	-.1406	-.1453	-.1221	-.1689	-.1147	-.1650	-.0871	-.1477	-.0006	-.1458	-.0962		
	-.1440	-.1564	-.1546	-.1341	-.1616	-.1273	-.1583	-.1007	-.449	.1030	-.1455	-.1018	-.1358	-.076
			-.1446	-.1387	-.1525	-.1312	-.1483	-.1081			-.1450	-.1069		-.179

TAIL 2

TABLE IX.- CONTINUED
(β = 15.90°)

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.1724	.6144	-.1267	-.1093	-.120?	.10?8	-.1115	-.1551		1.2249				
.10	-.1873	.4733	-.1294	.8807	-.094?	.0186	-.094?	.0453	-.0565	.0933	-.0630	.1374		
.15	-.1801	.5082	-.1370	.8340	-.099?	.9515		.0200	-.0582	.0200				
.20	-.1720	.6129	-.1436	.7888	-.0985	.8938	-.0527	.9018	-.0727	.9711	-.0535	.9857		
.25	-.187?	.2200			-.094?	.9305	-.082?	.8734	-.0735	.9174	-.0556	.8938		
.30	-.1624	.2872	-.1823	.3153	-.1?5	.3100	-.1595	.297?	-.0762	.8499	-.0608	.9338		
.40	-.16?	.119?	-.1805	.3285	-.1957	.3392	-.1798	.3404	-.1618	.2910	-.0?00	.285?		
.50					-.1?6	.3525	-.1553	.3213	-.1752	.3564	-.1537	.2852		
.60	-.1432	.4993	-.1610	.5000	-.1?2?	.357?	-.166?	.2784	-.1592	.0866	-.1?05	.0?4?		
.70	-.1740	.2365	-.1778	.1693	-.1??		-.1671	.0701	-.1678	.0633	-.1725	.0294		
.80	-.1871	.1888	-.1766	.1134	-.1668	.1314	-.1672	.0633	-.1678	.0575	-.1738	.0209		
.90	-.1745	.1770	-.1735	.1117			-.1672	.0657	-.1577	.0508	-.1745	.0152		-.07?0

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1683	-.0237	.1649	-.1093			-.1107	.1226	-.1138	.3230	-.0995	.6294	-.0781	-.6540
.10	.1866	-.0421					-.0861	.1250	-.0954	.3095			-.0384	-.5800
.15							-.0683	.1149					-.0374	-.5308
.20	.1949	-.0428			-.0500	.0176	-.0668	.1088	-.0802	.2962			-.0431	-.4804
.25	.0194	-.1227	-.0135	-.0820	-.0669	.0140	-.0755	.1096	-.0745	.2895	-.0789	.4524	-.0484	-.4364
.30			-.0503	-.1461			-.0906	.0973	-.0782	.2817	-.0775	.4351	-.0498	-.4050
.40	.0107	-.1121									-.0612	.3542	-.0520	-.3463
.50					-.1095	-.0855	-.1266	-.0147	-.1509	.0561	-.1401	.0927	-.0695	-.2116
.60	-.0009	-.1023	-.0594	-.1260			-.1362	-.0069	-.1454	.0609	-.1606	.0328	-.1619	-.1071
.70					-.1110	-.0680	-.1635	-.0811	-.1416	-.0660	-.1709	-.0740	-.1612	-.1195
.80	-.1412	-.1647	-.1565	-.1733	-.1778	-.1486	-.1903	-.1248	-.1829	-.0830	-.1698	-.0789		
.90	-.1579	-.1850	-.1688	-.1828	-.1843	-.1547	-.1842	-.1297	-.1718	-.1037	-.1689	-.0814	-.1517	-.1163
.95	-.1705		-.1705	-.1777	-.1763	-.1580	-.1777	-.1326	-.1699	-.1077	-.1666	-.0855	-.1657	-.1294

TABLE IX.- CONCLUDED
(h) α = 19.90°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.1821	.7102	-.1392		-.1198	1.2923	-.1394	1.3361		1.3972			-.1394	1.3754
.10	-.1918	.5939	-.1353	1.0567	-.1009	1.2036		1.2228	-.0793	1.2524	-.0920	1.3003	-.1103	1.1835
.15	-.1872	.7527	-.1406	1.0063	-.0985	1.1347			-.0808	1.1829			-.0622	1.0448
.20	-.1825	.7639	-.1466	.9483	-.1016	1.0491	-.0623	1.0491	-.0803	1.1216	-.0685	1.1490	-.0363	.9577
.25		3.131			-.1050	.9680	-.0853	1.0055	-.0741	.0527	-.0564	1.1027	-.0223	.87CC
.30	-.1915	.3931							-.0813	.3733	-.0675	1.0209	-.0130	.8C37
.40	-.1900	.6375	-.1910	.4367	-.1732	.4054	-.1615	.3783	-.1542	.3577	-.0743	.8525	-.0356	.5394
.50			-.1916	.5420	-.1906	.4525	-.1824	.4548			-.1563	.3501	-.0625	.5390
.60	-.1663	.6124	-.1694	.6725	-.1850	.5026	-.1635	.4489	-.1776	.4827	-.1729	.3729	-.2037	.0295
.70	-.1868	.3466	-.1826	.2413	-.1749	.6285	-.1711	.4078	-.1705	.1691	-.1734	.1084	-.1990	-.0360
.80	-.1947	.2766	-.1837	.1875			-.1692	.2069	-.1698	.1407	-.1742	.0969	-.1900	-.0232
.90	-.1783	.2684	-.1830	.1933	-.1635	.2424	-.1693	.2281	-.1696	.1435	-.1760	.0892		
.95							-.1695	.2293	-.1697	.1576	-.1768	.0836		-.0240

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1661	-.0800	.0680	-.0920			-.1430	.0442			-.1682	.2394	-.1592	.4896
.10	.1749	-.0963					-.1249	.0519	-.1647	.1397			-.1376	.4327
.15					-.0532	.0014	-.1063	.0500	-.1502	.1419			-.1351	.3927
.20	-.1733	-.0864					-.0951	.0493	-.1363	.1377			-.1372	.3501
.25	-.0000	-.1459	-.0587	-.0855	-.0669	-.0120	-.0949	.0520	-.1287	.320	-.1487	.1734	-.1373	.3128
.30			-.0869	-.1535			-.1040	.0421	-.1275	.201	-.1562	.1615	-.1357	.2795
.40	-.0215	-.1307							-.1697	.0251	-.509	.1101	-.1310	.2224
.50					-.1225	-.0994	-.1404	-.0538	-.1677	.0200	-.1762	.0055	-.1361	.1090
.60	-.0420	-.1164	-.0956	-.1398			-.1468	-.0532	-.1646	-.0153	-.1864	-.0241	-.2031	-.1116
.70					-.1225	-.0757	-.1748	-.1120	-.1939	-.1212	-.1978	-.1071	-.1918	-.1137
.80	-.1549	-.1717	-.1724	-.1848	-.1835	-.1621	-.1956	-.1517	-.1900	-.1399	-.1951	-.1140		
.90	-.1749	-.1943	-.1836	-.1955	-.1905	-.1741	-.1958	-.1603	-.1696		-.1912	-.1180	-.1704	-.1069
.95			-.1854	-.1921	-.1859	-.1779	-.1892	-.1648	-.1892	-.1459	-.1901	-.1226	-.1779	-.1196

TAIL 2

TABLE X. - PRESSURE COEFFICIENTS, ϕ = 90°, δ = 0°, M = 2.36

(a) α = -4.05°

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.57		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

105

TABLE X. - CONTINUED
(b) α = -2.05°

Cp at y/b of

TAIL 1

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 1

Cp at y/b of

TAIL 2

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

TABLE X.- CONTINUED
(c) α = -0.04°

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05			.2374	.3094			.2063	.3557		.2222				
				.3094				.3241		.3087	.2307	.3228		
			.2217	.2918						.3177				
										.3096				
										.3045				
			-.027?	-.0133	.0055	.0245	.0155	.0345		.3045	.2228	.3019		
			-.0356	-.0272	-.0062	-.0097	.0069	.0180		.0563	.0240	.0456		
			-.013?		-.0118	-.0055	-.0004	-.0040			-.0693	-.0077		
			-.007?	-.0070	-.0218	-.0050	-.0267	-.0325	-.122?	-.081	-.131?	-.1223		
.80	-.0835	-.0676	-.1134	-.1090			-.1405	-.1342	-.1411	-.1351	-.131?	-.1352	-.1289	
.90	-.0838	-.0760	-.1344	-.1267	-.1205	-.1391	-.1246	-.1350	-.1175	-.1259	-.1124	-.1174		
.95	-.0843	-.0817	-.1244	-.1263			-.1163	-.1216	-.117	-.1139	-.1094	-.1091		

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.12??	.1355	.2796	.2723			.2539	.2?11			.28?3	.2334	.2098	
.0?	.16??	.1?2					.276?	.2822	.2798	.2645			.2?07	
.15					.2755	.2526	.275?	.2644	.2834	.2608			.222?	
.20	.13??	.11??					.278?	.2588	.2746	.2628			.2?3?	
.25	.?08?	.30?4	.0637	.1791	.272?	.2556	.27??	.2586	.2774	.2651	.2701	.2603	.202?	
.30		.?123	-.0048	-.0061			.27??	.2429	.2737	.2537	.2777	.261?	.96?	
.40	.?158	.?123							.0401	.0348	.2677	.2351	.190?	
.50					.007?	-.?053	.0175	.0086	.0182	-.0051	.0295	.0?42	.5?9?	
.60	.?747	.?437	-.0300	-.0425			.0109	-.0016	.0115	-.0302	-.0211	-.0465	.281?	
.70					-.0091	-.0217	-.0693	-.0879	-.1278	-.1276	-.1297	-.1373	.1?8?	
.80	-.0775	-.0738	-.115?	-.1287	-.1369	-.1428	-.1377	-.1416	-.1193	-.1146	-.1387	-.237	-.1094	-.0933
.90	-.077?	-.1033	-.1256	-.1312	-.1360	-.1299	-.1313	-.1272	-.1171	-.1114	-.1171	-.1096	-.1013	
.95			-.1276	-.1249	-.1236	-.12?8	-.118?	-.1185	-.1142	-.1120	-.1121			

TAIL 2

107

TABLE X - CONTINUED
(d) α = 1.95°

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TABLE X. - CONTINUED
(e) α = 3.95°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0254	.2069	.0978				.0994	.5336		.3580			.457	
.10	.0208	.1885	.0656	.1690				.5003		.5007	.1252	.4724		
.15		.2013	.0771	.1307					.214	.4900			.0855	
.20		.2115	.0635	.3985			.308	.4388	.108	.4855	.205	.4932	.282	
.25	.0505	.0117					.055	.4612	.13	.1743	.170	.497	.0855	
.30	.0420	.0399							.112	.1655	.162	.1848	.0870	
.40	.0299	.1020	.0881	.0565	.0623	.0652	.0558	.1107	.0476	.164	.1095	.4552	.396	.3255
.50			.0805	.0444	.0746	.0604	.0665	.0958			.0437	.320	.0656	.2758
.60					.0761	.0757	.0400	.061	.0692	.1014	.0730	.0912		
.70	.0260	.142	.0619	.0741	.0867	.0581	.0907	.0317	.1487	.0699	.1348	.0781	.1387	.1086
.80	.0907	.0391	.1474	.0638			.1246	.0944	.1284	.0981	.1293	.0948	.1297	.1054
.90	.0928	.0396	.1438	.0868	.1249	.1125	.1249	.1071	.1254	.1022	.1284	.1036		
.95	.0876	.0404	.1278	.0904			.1253	.1114	.1251	.1062	.1280	.1087		.1073

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1158	.1541	.2780	.2641			.2516	.2029			.2768	.2243	.2159	.1973
.10	.1095	.1235			.2759	.2500	.2687	.2711	.2778	.2595			.2538	.2297
.15							.2689	.2599	.2788	.2595			.2265	.2135
.20	.0986	.1165	.0615	.1854	.2684	.2462	.2722	.2527	.2683	.2557	.2570	.2567	.2162	.1919
.25	.0221	.0076	.0044	.0023			.2726	.2496	.2701	.2555	.2721	.2553	.2062	.1734
.30							.2677	.2318	.2674	.2533	.2607	.2365	.2009	.1672
.40	.0045	.0007			.0089	.0049	.0163	.0040	.0370	.0346	.2607	.2365	.1907	.1517
.50	.057	.0220	.0402	.0440			.0095	.0059	.0172	.0051	.0294	.0020	.1515	.0936
.60					.0074	.0165	.0675	.0883	.0112	.0027	.0197	.0457	.1330	.0359
.70	.1063	.0874	.1222	.1375	.1375	.142	.1373	.1408	.1265	.1295	.1281	.1347	.1347	.1360
.90	.0995	.1178	.1281	.1362	.1377	.1357	.1339	.1306	.1185	.1159	.1178	.1145	.1058	.1029
.95			.1281	.1289	.1256	.1259	.1214	.1207	.1153	.1130	.123	.1118	.166	.1133

TABLE X. - CONTINUED
(I) α = 5.95°

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	-.0097	.2938	.0388		.0355	.6185	.0519	.6633		.174			.0923	.5077
	-.0156	.2257	-.0351	.5950	-.0422	.5989		-.6196	.278	-.5298	.0788	.5907	.0961	.5899
	-.0032	.2559	-.0354	.4960	-.0477	.5675	-.3654	-.5987	.0606	-.5967			-.0537	.5442
	-.0111	.2898	-.0157	.16.13	-.0450	.5398	.078.	.5398	-.0538	-.5783	.0729	.6580	-.0523	.5150
	-.0729	.0327	-.0351		-.0427	.5392	-.0593	.5365	-.6517	.5597	.0688	.5951	-.0551	.4745
	-.0629	.6678			-.0632	.273	-.0856	.172.	-.0602	.210	.0660	.5737	.0585	.4433
	-.0549	.487	-.0054	.0954	-.1049	.1181	-.0994	.306	-.2757	.563	-.0507	.5237	.0581	.4014
.55			-.0991	.0817	-.1082	.113	-.0893	.098			-.0742	.1689	-.0503	.3225
	-.0322	.1654	-.0887	.1280	-.1145	.053	-.1174	.066.	.079	.379	-.006	.260	-.403	.1005
.80	-.0939	-.0197	-.1608	-.0358	-.1356	-.084	-.1292	-.0727	-.330	-.0475	-.1302	-.0582	-.1317	-.1086
	-.019	-.0155	-.1531	-.0628	-.1356		-.1300	-.0857	-.293	-.0756	-.1297	-.0750	-.383	-.1087
.95	-.1109	-.0134	-.1327	-.0553			-.1303	-.0899	-.278	-.0757	-.1301	-.0844		
									-.276	-.0837	-.1300	-.0953		-.1008

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1213	.1559	.2772	.2605			.2575	.2928	.2933	.2506	.2797	.2191	.2218	.1930
	.1235	.1312				.2575	.2744	.2964	.2793	.2589			.2652	.2288
					.2773		.2654	.2511	.2793	.2586			.2380	.2134
	.0555	.1295	.2653	.925	.2757	.2641	.2712	.2595	.253.	.2526	.2716	.2553	.222.	.1973
	.0327	.0191	-.0655	.0631			-.279	-.245.	.2649	.2518	.2749	.255.	.2040	.1773
	-.0155	-.2543					.270.	-.222.	-.2575	-.231.	.2559	.2311	.1953	.1700
					.3191	.0603	.3228	.3055	.2357	.339.	-.0307	-.0002	-.1548	.1487
	.359	-.0397	-.0515	-.559	-.0027	-.0035	-.0183	-.0328	.1157.	-.0653	.0214	-.0477	-.1546	.0895
							.0652	.1855	-.215	-.0633	.1286	-.342	-.361	.394
	-.0655	-.0625	-.1415	-.1536	-.1358	-.1356	-.1353	-.363	-.216	-.1293	-.1373	-.1288	-.327	.329
	-.1043	-.1201	-.1305	-.1357	-.1405	-.1461	-.136.	-.133.	-.177	-.144	-.1158	-.1145	-.1090	-.1037
.95			-.1291	-.351	-.1291	-.36.	-.1225	-.1619	-.134	-.19	-.1107	-.1125	-.1155	-.1159

TAIL 2

TABLE X. - CONTINUED
(g) α = 7.95°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0393	.3209	-.0124	.2499	-.0065	.7406	.0077	.3063		.72·3	.0351	.7472	.0359	.7657
					-.0023	.6825		.7135	.0294	.7365			.0551	.7343
			-.0142	.6102	-.0008	.6409			.0150	.6856				
.15			-.0243	.5546	-.0031	.6006	.0378	.5899	.0142	.6538	.0292	.6997		.607.
.20			-.0303	.5201	-.0055	.5680	.0057	.6026	-.0155	.6331	.0219	.6803		.5466
											.0203	.6472		
													.0412	
		.0857	-.1237	.323	-.86	.1578	-.1·0	.1688	-.048		-·0·8	.575·	.0395	.317.
			-.1200	.250	-.1316	.155·	-.1·5·	.1665			-.0008	.651	.0336	.35··
.50					-.332	.1513	-.0655	.1405	-.1282	.175·	.1239	.510		.0·3·
.60				.859	-.371	.147·	-.1397	.052	-.346	-.0238	-.1341	.0381	-.1362	-1.3·
.70	.0440	.3.67	-.1741	-.0053			-.1385	-.0504	-.343	.052·	.342	.0551	.157·	.1·7·
.80	.1015	.3.·7·	-.1758				-.333	-.0615	.343	-.0546	-.346	.0636		
.90		.0·55	-.1565	-.0331	-.442	-.0652	-.1400	-.0660	.34·	-.0553	-.346	-.0694		.2··
.95	-.288	.0·63	-.349	-.0349										

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.11·6	.635	.2613	.2499			.2627	.1996			.2823	.2146	.2285	.1938
	.1·45	.1325					.2752	.2675	.2864	.2583	.2716	.2328		
						.257·	.273·	.2578	.2847	.2598	.2481			
.15					.2830		.275·	.2487	.2716	.2320	.2282			
.20	.0855	.223·	.0688	.1949	.2770	.2463	.2755	.2455	.2725	.2517	.2705	.2549	.2·78	.843
.25	.0494	.0206	.0077	-.0004			.2683	.2257	.2687	.2480	.2737	.2537	.2670	.172·
											.2520	.2260	.1963	.51·
	-.0635	-.04·2			.0410	.0085	.0227	.0060	.3343	.0295	.0279	-.0003	.1555	.0·5·
.50	-.0214	-.037·	-.0777	-.0624	.0069	.0075	-.0357	-.0014	.0156	.0049	-.0221	-.0475	-.1379	.1··
.60							-.0555	-.0822	.0104	-.0014	-.0299	-.0335	-.1326	-.12··
.70	-.1·5	-.175	-.1534	-.1593	-.1355	-.1340	-.1272	-.1266	-.1197	-.1287	-.1356	-.1283		
.80	-.1··	-.139·	-.1·05	-.1434	-.1534	-.1510	-.1153	-.1367	-.247	-.·46	-.146	-.1143	-.1374	-.16·2
.90			-.1401	-.130	-.1398	-.1447	-.1252	-.1234	-.164	-.·08	-.·03	-.1123	-.147	-.·3

TABLE X. - CONTINUED
(h) α = 9.95°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05		.3432	-.0571				-.0362	.801?		.8505				
		.2559								.8219				
		.028?								.7616				
		.030?	-.0722							.7293				
		.0707					-.0030	.654?		.6386				
		.124?					-.032?	.601?		.5635				
		.2319								.2?6?				
							-.3?0	.201?						
		.277?	-.14?0				-.149?	.182?		2.57				
		.0365	.957?				-.156?	.155?		.C019				
		.0401	-.1601				-.487?	-.024?		-.0252				
		.0477	-.1462				-.150?	-.349?		-.0287				
						-.0337	-.507?	-.0582		-.0332				

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0956	.1420	.2119	.2?30			.2694	.2009			.2864	.2443	.2304	.1913
.10	.1029	.136					.2827	.2526	.2944	.2595			.2?51	.2330
.15					.2944	.2529	.2801	.2541	.2908	.2591			.2520	.2207
.20	.076?	.1059					.2801	.2477	.276?	.2515			.2?13	.201?
.25	.052?	.277?	.0323	.582?	.280?	.2485	.2788	.247?	.2755	.2498	.271?	.2544	.2?89	.1847
.30			.0421	.2212			.2779	.2297	.2717	.2441	.2740	.2517	.2094	.1766
.40	.065?	.0362							.2383	.0294	.2496	.2225	.1933	.1535
.50			-.0051	.0792	-.0403	.0645	-.0285	.0083	.0?97	.0052	.0262	-.0006	.1580	.0908
.60	-.0444	-.0944			.0030	-.0150	-.0479	-.0052	-.0161	-.0032	-.0236	-.0-87	-.1378	-.1389
.70			-.1685	-.238?	-.1388	-.1359	-.0370	-.0657	-.1145	-.1284	-.1300	-.0-336	-.130C	-.1171
.80	-.1446	-.1348	-.1622	-.621?	-.154?	-.1533	-.1231	-.1184	-.1226	-.1114	-.1313	-.1225	-.1067	-.0996
.90	-.1570	-.1643	-.1624	-.626?	-.149?	-.1497	-.1397	-.1302	-.1225	-.1114	-.1113	-.1121	-.1117	-.1102
.95							-.127?	-.1285	-.1147	-.1080	-.076?	-.1095		

TABLE X. - CONTINUED
(i) α = 11.94°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.57 U.S.	0.57 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0885	.3329	.2940		.0847	.888	.0809	.3541		.0009	.3234	.3355	.0090	.0533
.10	.0732	.2423	.0967	.5977	.0768	.817		.8529		.3352			.0248	
.15	.0633	.325	.1026	.6570	.0780	.7615	.0313							
.20		.337	.06	.6392	.0825	.7162	.0318	.762		.7539		.3558		
.25		.0792			.0852	.6722		.749				.7923		
.30	.0885	.459								.7080		.7383		
.40		.2976	.1550	.2154	.1578	.2226	.1525	.2173		.2295		.2339		
.45			.1582	.2093	.1679	.2358	.1634	.2409				.2237		
.50					.1618	.2449	.1553	.2300		.2281	.1518	.2047		
.60	.0740	.3344	.1375	.3011	.1600	.2472	.1563	.1843	.1632	.0291		.0047		.0666
.70	.1280	.0649	.1828	.0573			.1570	.0076	.1488	.0016	.1508	.0090	.1654	.0355
.80	.1322	.0616	.1671	.0254	.1515	.0110	.1585	.0043	.1503	.0018	.0508	.0166		
.90	.1562	.0798	.1608	.0185			.1588	.0081	.1501	.0063	.1507	.0225	.1020	

TAIL 1

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2872	.295	.1459	.1743			.2638	.1946			.2936	.2165	.2349	.1907
.10	.2935	.0013					.2892	.2583	.2986	.2560			.2826	.2352
.15					.2343	.2152	.2850	.2460	.2932	.2556			.2599	.2229
.20	.0663	.0369	.0102	.1088	.2253	.2073	.2870	.2432	.2889	.2523	.2784	.2533	.2375	.2039
.25	.2596	.0352	.0747	.0511			.2759	.2453	.2834	.2519	.2815	.2511	.2255	.1860
.30	.0708	.0503					.2721	.2313	.2852	.2514	.2517	.2512	.2140	.1775
.40									.0492	.2310	.2512	.2512	.2047	.1517
.50	.0560	.0508	.0021	.0966	.0118	.0331	.0161	.0003	.0271	.3064	.0327	.0003	.1512	
.60							.0373	.0094	.0225	.019	.0171		.3730	.0936
.70	.1453	.0363	.0813		.0183	.0034	.0319	.0822	.1133	.1333	.1257	.1337	.1276	
.80	.1582	.1663	.191	.1775	.1634	.1373	.1228	.1158			.1325	.1187		
.90			.739	.1798	.1739	.1596	.1437	.1258	.1185	.1276	.1102	.1099	.1919	.1665
.95			.786	.1760	.1687	.653	.1394	.1315	.1109	.1043	.1054	.1680	.1993	

TAIL 2

TABLE X. - CONTINUED
(j) α = 15.95°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0975	.2357	-.1544	.0889	-.150:	.977:	-.1627	.0448		.0556				
.10	-.000:	.128:	-.1535	.7730	-.1413	.901:		.9384	-.238	.9764	-.1326	.0156		
.15	-.0968	.194:	-.1536	.7225	-.1391	.8457		.9102	-.1289	.9102				
.20	-.0575	.2044	-.1508	.6880	-.1414	.7886	-.0768	.7957	-.276	.8605	-.121:	.8626		
.25	-.1243	.0032			-.1435	.7305	-.1294	.768:	-.1265	.8098	-.195	.8626		
.30	-.1208	.1404							-.277	.7468	-.75	.633		
.40	-.1622	.4033	-.1732	.2985	-.1772	.2807	-.1762	.2661	-.1849	.2539	-.1542	.264		
.50			-.1718	.3175	-.1820	.3395	-.1846	.3295			-.1771	.2551		
.60	-.1022	.3070	-.1535	.4392	-.1801	.3567	-.1507	.3170	-.1723	.3575	-.1649	.2662		
.70					-.1808	.3858	-.1783	.2803	-.1714	.0997	-.1636	.0670	-.174:	
.80	-.1556	.1328	-.1961	.1153			-.1788	.0811	-.1704	.0717	-.1651	.0577	-.174:	
.90	-.1535	.1399	-.1858	.0575			-.1755	.0903	-.1725	.0683	-.1664	.0515		
.95	-.171:	.1455	-.182:	.0625	-.1697	.107:	-.1694	.0904	-.1712	.0665	-.1664	.0457		-.0580

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0527	.0992	.0815	.0889			.1226	.0961			.3203	.2332	.2577	.2015
.10	.0542	.0732					.1363	.1279	.2414	.2030			.302	.2417
.15					-.0385	.0429	.1251	.1209	.2404	.2024			.2739	.2267
.20	.0229	.0630	-.0441	.0561	.0216	.0264	.1154	.1146	.2235	.2023	.3024	.2623	.251	.2060
.25	-.0871	-.0552	-.1013	-.0770			.1073	.1088	.2197	.2030	.3077	.2617	.2393	.189
.30							.0989	.0945	.2153	.2013	.2948	.2404	.2270	.176
.40	-.0974	-.0704			-.1275	-.1290	-.0953	-.0915	-.0140	-.0209	.0446	.0218	.2162	.578
.50							-.1075	-.1079	-.0416	-.0454	-.0044	-.0391	-.1766	.0981
.60	-.0765	-.0750	-.1376	-.1250	-.1298	-.1380	-.1506	-.1585	-.0527	-.0542	-.1204	-.1333	-.1319	-.1404
.70									-.1535	-.1557			-.1279	-.1336
.80	-.1569	-.1467	-.1940	-.1883	-.1842	-.1855	-.1826	-.1885	-.1603	-.1626	-.1356	-.1389		
.90	-.1747	-.1754	-.1930	-.1929	-.1871	-.1817	-.1768	-.1802	-.1545	-.1575	-.1354	-.1178	-.1123	.021
.95			-.1904	-.1896	-.1835	-.1800	-.1727	-.1737			-.1230	-.1133	-.1185	-.1159

TAIL 2

TABLE X.- CONCLUDED

(h) α = 19.95°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-1.2121	.2171	-.1980		-.1877	1.0684	-.1977	1.1264		1.1348			-.1967	1.2150
.10	-.1461	.1660	-.1922	.8731	-.1828	1.0049		-.0373	-.1635	1.0723	-.1649	1.1120	-.870	-.0912
.15	-.1339	.2359	-.1887	.8372	-.1795	.8452			-.1689	1.0055			-.653	.3801
.20	-.1268	.2665	-.1844	.7916	-.1803	.8763	-.164	.8926	-.1657	.9549	-.1570	.9968	-.501	.9101
.25	-.1504	.0846			-.1818	.8092	-.673	.8479	-.1637	.9974	-.1539	.9556	-.380	.8253
.30	-.1453	.2085							-.1638	.8238	-.1515	.8853	-.325	.7582
.40	-.1826	.5733	-.1877	.4235	-.1787	.4081	-.1822	.3612	-.1995	.3127	-.1539	.7368	-.1326	.6476
.50			-.1987	.5213	-.1919	.4874	-.1919	.4810			-.1862	.3488	-.1438	.482
.60					-.1916	.5415	-.1635	.5085	-.1842	.5197	-.1770	.4555	-.802	.3225
.70	-.305	.3673	-.1733	.5428	-.1906	.5531	-.1894	.4187	-.1846	.1904	-.1766	.1591	-.887	.0734
.80	-.744	.1873	-.2064	.1513			-.1915	.1861	-.1827	.1702	-.1778	.1447	-.1883	.0.3
.90	-.841	.2514	-.1976	.1239	-.1828	.668	-.1908	.1743	-.1837	.709	-.1784	.135		
.95	-.1802	.2285	-.1949	.1257			-.1885	.1687	-.1825	.1639	-.1784	.1307	.0049	

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0172	.0766	.0057	.0267			.0017	-.0051	.0275	.0232	.1072	.0723	.1967	.1256
.10	-.0107	.0468					.0091	.0143	-.0284	-.0292			-.2197	.719
.15					-.0142	.0026	-.0035	.0131	-.0200	-.0293			-.2018	.1633
.20	-.0207	-.0284	-.0852	.0071	-.0311	-.0113	-.0030	.0119	.0163	-.0253	.0786	.0802	.1876	.1489
.25	-.1176	-.0843	-.1360	-.1088			-.0082	.0099	.0107	-.0189	-.0632	.072	.1736	.1331
.30							-.0158	-.0041	-.186	-.1093	-.0508	.0475	.1589	.1257
.50	-.1331	-.0959	-.1624	-.1466	-.1503	-.1432	-.1422	-.1339	-.376	-.311	-.1050	-.1037	.1453	.1128
.60	-.1052	-.0958					-.1539	-.1488	-.1429	-.1380	-.1441	-.1455	-.1019	.0755
.70					-.1487	-.1464	-.1821	-.1821	-.1951	-.1872	-.1954	-.1910	-.1512	.1431
.80	-.1576	-.1562	-.2036	-.1989	-.1990	-.1954	-.2025	-.2015			-.2015	-.1953	-.1667	.1443
.90	-.868	-.1851	-.2002	-.1994	-.1982	-.1937	-.1968	-.1944	-.1907	-.1864	-.1965	-.1903	-.1754	.1733
.95			-.1938	-.1972	-.1953	-.1916	-.1938	-.1916	-.920	-.1832	-.1943	-.1869	-.1618	.1972

TABLE XI.- PRESSURE COEFFICIENTS, δ = 3°, δ = 3°, M = 3.70

(a) α = -4.15°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0590	.0777	.1367	.1302	.1383	.1373	.1355	.1317						
.10	.0551	.0691	.1353	.1313	.1394	.1918								
.15				.1838	.1388	.1959								
.20	.0357	.0603			.1367	.1925	.1771	.1870						
.25	.0427	.0593	.0455		.1540	.1918	.1355	.1870	.1349	.1919		.1655		
.30	.0007	.0658							.1357	.1919				
.40	.0056	.0666	.0063	.0269	.0156	.0376	.0133	.0372	.1338	.1884	.1402	.1655		
.50			.0023	.0174	.0071	.0244	.0012	.0257	.0233	.0583	.375	.1918		
.60	.0012	.0200			.0001	.0196	.0158	.1450			.320			
.70	.0362	.0148	.0082	.0019	.0045	.0139	.0175	.0611	.0008	.0274	.305	.0438		
.80	.0365	.0287	.0451	.0381	.0329		.0552	.0387	.0384	.0273	.0487	.0388		
.90	.0374	.0283	.0397	.0375		.0187	.0491	.0399	.0386	.0357	.0414	.0421		
.95			.0392	.0366			.0484	.0374	.0377	.0333	.0402	.0363		

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1080	.0216	.2944	.0842			.2746	.0851			.2624	.1487	.2500	.0825
.10	.1250	.0156					.2911	.0972	.2929	.1277			.2345	.0943
.15					.2898	.0849	.2895	.0931	.2940	.0951			.2550	.0815
.20	.1337	.0167	.1470	.0484			.2904	.0895	.2877	.0897	.2788	.0880	.2315	.0726
.25	.0367	-.0135	.0835	-.0057	.2898	.0794	.2915	.0857	.2903	.0877	.2833	.0389	.2287	.0617
.30							.2842	.0785	.2863	.0849			.2282	.0603
.40	.0159	.0469							.1091	-.0013	.2725	.0769		.0536
.50	.0424	.0191	.0470	-.0112	.0589	.0036	.0739	-.0121	.0765	-.0132	.2923	-.0015	.1957	.0316
.60							.0594	-.0203	.0684	-.0167	.0442	-.0212	.0272	-.0419
.70	.0424	.0191			.0547	-.0176	.0707	-.0368	.0345	-.0180	.0317	-.0368	.0404	-.0289
.80	-.0184	-.0294	.0355	-.0372	.0280	-.0317	.0346	-.0397	.0467	-.0356	.0420	-.0356		
.90	-.0347	-.0406	.0479	-.0338	.0417	-.0354	.0421	-.0363	.0467	-.0302	.0459	-.0328	.0391	-.0366
.95			.0501	-.0405	.0450	-.0338	.0447	-.0387	.0488	-.0307	.0477	-.0361	.0459	-.0442

TABLE XI.- CONTINUED
(b) α = -2.15°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05								.2225						
								.2234	.2040	.2040				
									.357					
						.1487	.2415	.392	.1841					.1837
						.1364	.1985	.1325	.1923					
								.360	.896					
.50	-.0067		-.0011	.0177	.0140	.0359	.0145	.0359	.0254	.0576			.1042	
			-.0072	.0068	.0098	.0219	.0023	.0219					.0905	
	.0020	.0130	-.0075	.0032	.0058	.0165	.0043	.0867	-.0004	.2236			-.0455	
	-.0318	-.0188	-.0453	.0403	.0058	.0112	-.0173	-.0018	-.0508	-.0326			-.0513	
.80	-.0343	-.0310	-.0405	-.0418	-.0357	-.0311	-.0557	-.0456	-.0448	-.0414			-.0522	
	-.0370	-.0320	-.0430	-.0403			-.0488	-.0463	-.0430	-.0465				
.95							-.0484	-.0431	-.0417	-.0428				.0422

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.3805	.0450	.2361	.1259			.2251	.1179			.2423	.1225	.2055	.1219
	.3560	.0365					.2374	.1373					.2242	.1254
.15					.2319	.125.	.2345	.1320	.2387	.1393			.2091	.1162
.20	.0975	.0346					.2342	.1283	.2383	.1347			.1951	.1066
.25	.0362	-.0065	.1121	.0851	.2316	.1212	.2343	.1258	.2319	.1281	.2282	.1265	.1869	.0964
.30			.0560	.0016			.2294	.1157	.2333	.1248	.2319	.1230	.1801	.0902
.40	.0366	.0192			.0470	-.0046	.0453	-.0044	.0764	.0195	.2222	.1141	.1822	.0807
.50			.0243	-.0196			.0395	-.0112	.0493	-.0004	.0670	.0086	.1505	.0542
.60	.0413	.0013			.0296	-.0176	-.0016	-.0367	.0412	-.0051	.0234	-.0208	-.0320	-.0446
.70					.0343	-.0395	-.0417	-.0446	-.0290	-.0395	-.0353	-.0480	-.0385	-.0413
.80	-.0240	-.0332	-.0398	-.0422	-.046.	-.0397	-.0480	-.0415	-.0462	-.0397	-.0451	-.0428		
.90	-.0363	-.0465	-.0498	-.0422	-.0447	-.0388	-.0468	-.0411	-.0457	-.0402	-.0475	-.0460	-.0423	-.0371
.95			-.0473	-.0427							-.0459	-.0413	-.0465	-.0422

TABLE XI. - CONTINUED
(c) α = -0.15°

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0551		.1453	.1397	.1401	.2028	.1433	.2238		.1596				
.10	.0553	.0735	.1429	.1872	.1427	.1831			.1473		.738			
.15	.0553	.0753	.1?5	.1855		.1669			.1425	.985				
.20	.0485	.0708	.1901		.1336	.1670	.1418	.2.29	.1406	.949	.1830			
.25						.1838	.1391	.6012		.934				
.30	.0042	.0122	.0027	.0232	.0124	.0366	.0140	.0355	.1392	.1903				
.40	.204?	.0113	.0059	.0295	.0028	.0222	.0004	.0228	.0245	.0601				
.50					.0037	.0160	.0116	.0656	.0019	.0225	.0623	.0153		
.60	.001?	.0167	.0075	.0034	.0082	.0096	.0200	.0037	.0524	.0339	.0?5.	.0113		
.70	.0330	.0209	.0467	.0428			.0583	.0458	.0458	.0440	.0480	.0523		
.80	.0363	.0345	.0403	.0433	.0394		.0513	.0478	.0435	.0491	.0437	.0462		
.90	.0393	.0357	.0398	.0412		.0350	.0503	.0444	.0422	.0451	.0?2?	.0432		

TAIL 2

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0598	.0665	.18?3	.769			.1787	.1558	.1888	.798	.6060	.533	.6?5	.1578
.10	.0693	.0549					.868	.1828	.1879	.1800			.178?	.657
.15					.179?	.1739	.1831	.1782	.1879	.1800			.166?	.1554
.20	.0678	.0602					.1821	.1742	.1811	.1752	.1830	.171?	.533	.453
.25	.0153	.0081	.0731	.1311	.1779	.1699	.1826	.1715	.1825	.1732	.242	.75?	.466	.35?
.30			.0285	.0245			.1779	.1595	.185	.1699	.?50	.1582	.130?	.25.
.40	.0211	.0157							.0476	.0440	.450	.0297	.3?5	.00?
.50	.0252	.0088	.0019	.0385	.0229	.0115	.0205	.0147	.0256	.0205	.0415	.0085	.033?	.0?2?
.60							.0141	.0084	.0183	.0135	.0341	.0475	.0?2?	.0?18
.70	.0294	.0304	.0478	.0370	.0068	.0012	.0196	.0265	.0361	.0393	.0539	.0454	.0??	
.80	.0406	.0455	.0458	.0425	.0434	.0440	.0509	.0495	.0361		.0509	.0454	.041	.0?0?
.90			.0443	.0?2?	.0435	.0406	.0459	.0421	.0440	.0400	.0451	.0401	.04??	.0?0?
.95					.0410	.0383	.0434	.0404	.0432	.0402	.0437	.0407	.0435	.0?23

TABLE XI.- CONTINUED
(d) α = 1.86°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.1477	.1405	.1441	.2105	.1465	.2259		.1612			.1595	.1713
.10	.0670	.0937	.1494	.1997	.1449	.1963		.2189	.1497	.2129	.1437	.984	.728	.2051
.15	.0674	.0963	.1400	.1927	.1437	.1936			.1454	.2011			.1451	.1841
.20	.0592	.3891	.348	.1958	.1415	.1990	.1416	.2058	.1431	.1960	.1488	.2216	.1309	.1825
.25	.0025	.3099			.1392	.1976	.1403	.2029	.1440	.1937	.1462	.2022	.1136	.1682
.30	.0016	.0104							.1418	.1912	.1443	.1999	.1035	.1542
.40	.0000	.0057	.0048	.0232	.0135	.0353	.0174	.0359	.0256	.0570	.1380	.1881	.1002	.1413
.50			.0036	.0112	.0047	.0228	.0031	.0222			.0330	.0505	.0910	.1197
.60	.0046	.0110	.0073	.0051	.0009	.0162	.0116	.0508	.0015	.0235	.0027	.0179	.0438	.0413
.70	.0046	.0110	.0073	.0051	.0054	.0090	.0173	.0049	.0476	.0325	.0515	.0442	.0515	.0490
.80	.0394	.0258	.0468	.0415			.0555	.0465	.0466	.0450	.0499	.0532	.0542	.0551
.90	.0415	.0401	.0400	.0449	.0369	.0480	.0488	.0480	.0439	.0504	.0441	.0495		
.95	.0427	.0407	.0394	.0418		.0361	.0473	.0446	.0428	.0469	.0430	.0462		.0443

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0392	.0867	.1308	.2325			.1370	.1972			.1642	.2084	.1271	.1977
.10	.0455	.0820					.1411	.2331	.1432	.2283			.1355	.2094
.15					.1307	.2278	.1368	.2294	.1414	.2298			.1260	.2001
.20	.0390	.0875					.1357	.2247	.1348	.2245			.1146	.1876
.25	.0017	.0275	.0400	.1809	.1289	.2228	.1351	.2219	.1358	.2234	.1363	.2210	.1087	.1723
.30			.0028	.0557			.1311	.2087	.1344	.2193	.1383	.2257	.1030	.1644
.40	.0049	.2221							.0220	.0708	.1311	.2058	.1001	.1512
.50					.0370		.0000	.0388	.0047	.0441	.0186	.0541	.084	.136
.60	.0125	.0238	.0152	.0111		.0227	.0064	.0326	.0012	.0359	.0131	.0078	.0432	.038
.70					.0227	.0389	.0329	.0118	.0424	.0338	.0503	.0425	.0440	.0390
.80	.0304	.0246	.0472	.0434	.0420	.0464	.0471	.0443	.0427		.0468	.0473		
.90	.0419	.0413	.0449	.0469	.0407	.0464	.0434	.0476	.0427	.0449	.0432	.0417	.0384	.0435
.95	.0427	.0412	.0447	.0442	.0396	.0422	.0427	.0449	.0428	.0433	.0421	.0431	.0427	.0464

TABLE XI.- CONTINUED
(e) α = 3.35°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0774	.1127	.1531	.1484	.1500	.2213	.1553	.2325		.1652				
.10	.0771	.1107	.1518	.2086	.1502	.20??		.2238	.571	.2198	.497	.2086		
.15	.0657	.1162	.1452	.1995	.1488	.20?3			.1520	.2063				
.20	.0022	.1074	.1404	.1965	.146?	.20??	.1431	.207?	.1497	.2015	.1562	.2100		
.25	.0012	.0137			.1435	.20?8	.1462	.2080	.1499	.1985	.1536	.2105		
.30	-.0012	.0122							.1474	.1961	.1512	.2075		
.40	-.0008	.0071	.0074	.0258	.0147	.0359	.0184	.0382	.0310	.0573	.1448	.1959		
.50			-.0022	.0149	.0055	.024?	.0043	.0236			.0364	.0563		
.60					.0016	.01?5	.0123	.0424			.0046	.0203		
.70	-.0077	.0079	-.0063	.0059	.0048	.0099	.0154	.0055	.0007	.0231	.0511	.0433		
.80	-.0434	.0287	-.0469	.0397			.0567	.0465	.0491	.0339	.0519	.0531		
.90	-.0419	.0425	-.0401	.0455	.0389	.0372	.0489	.0485	.0477	.0455	.0451	.0513		
.95	-.0419	.0425	-.0399	.0422			.0476	.0448	.0433	.0474	.0437	.0472		

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0179	.1142	.0872	.2919			.0992	.2433			.1247	.2517	.093?	.2406
.10	.0230	.1107					.1002	.2882	.1035	.2804			.3983	.2563
.15					.0881	.2863	.0952	.2856	.0998	.2835			.083?	.2479
.20	.0155	.1186					.0930	.2813	.0937	.2791			.0797	.231?
.25	.0180	.0438	.0152	.2272	.0851	.2799	.0927	.2782	.0940	.2785	.0954	.2750	.0713	.2168
.30			-.0177	.3854			.0894	.2622	.0931	.2729	.0964	.2796	.0703	.2068
.40	-.0107	.0329							.0021	.1007	.0899	.2565	.0670	.1930
.50					-.0139	.0648	-.0167	.0665	-.0130	.0709	-.0018	.0809	.0539	.1504
.60	.0014	.0414	-.0272	.0410	-.0273	.0485	-.0238	.0608	-.0176	.0627	-.0282	.0259	-.0473	-.3319
.70					-.0397	.0287	-.0448	.0068	-.0457	-.0252	-.0482	-.0340	-.0430	-.0355
.80	-.0299	-.0151	-.0467	-.0339	-.0410	-.0402	-.0448	-.0338	-.0433	-.0404	-.0451	-.0409	-.0404	-.0386
.90	-.0396	-.0346	-.0462	-.0468	-.0402	-.0416	-.0433	-.0399	-.0490	-.0420	-.0429	-.0427	-.0417	-.0436
.95			-.0462	-.0477			-.0433	-.0422			-.0437	-.0441		

120

TABLE XI.- CONTINUED
(f) α = 5.85°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.57 U.S.	0.57 L.S.	0.33 U.S.	0.33 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0925	.1331	.1673	.1643	.1642	.235	.1667	.2464	.1690	.1747	.1635	.2272	.1845	.1955
.10	-.0906	.1331	.1661	.2256	.1642	.2185		.2355		.2353				
.15	-.0906	.1377	.1535	.2105	.1624	.2133	.1512			.2116			.1553	
.20	-.0780	.1259	.1541	.2116	.1591	.2181		.2158	.1622	.2132	.1707	.2250		
.25	-.0801	.1184			.1566	.2260	.1666	.2222	.1624	.2132	.1683			
.30	-.0056								.1602	.2036	.1532	.2137		
.40	-.0026	.1115	.0122	.0332	.0171	.0351	.0256	.0438	.0395	.0644	.0445	.0552		
.50		.0176	.0025	.0186	.0076	.0275	.0103	.0285			.0335	.0265		
.60	-.0056	.0062	-.0031	.0081	-.0030	.0212	-.0138	.0389	.0055	.0296	-.0133		-.0252	.0256
.70	-.0442	-.0298	-.0460	-.0308	-.0019	.0114	-.0130	.0001	-.0458	-.0314	-.0433	-.0314	-.0419	.0450
.80	-.0397	-.0435	-.0396	-.0474	-.0356		-.0552	-.0460	-.0480	-.0455	-.0525	-.0523	-.0413	.0447
.85	-.0393	-.0436	-.0393	-.0438		.0378	-.0457	-.0484	-.0438	-.0508	-.0443	-.0515		-.0527
								-.0443	-.0423	-.0469	-.0429	-.0467		

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0034	.1331	.0486	.3543		.3483	.0619	.2937	.0688	.3385	.0907	.3012	.0594	.2872
.10	-.0035	.1253					.0634	.3489	.0631	.3423			.0610	.3035
.15					.0499		.0582	.3460	.0567	.3396			.0530	.2853
.20	-.0027	.1340	-.0097	.2725	.0452	.3386	.0552	.3423	.0552	.3364	.0593	.3327	.0462	.2771
.25	-.0266	.0530	-.0341	.1152			.0515	.3386	.0555	.3285	.0531	.3331	.0436	.2609
.30							.0515	.3160	.0555	.3295	.0531	.3165	.0398	.2559
.40	-.0254	.0550			-.0272	.0958	.0307	.0939	.0105	.1335	.0533		.0390	.2381
.50	-.0055	.0671	-.0349	.0684			-.0384	.0931	-.0297	.1024	-.0184	.1101	-.0265	.1855
.60					-.0391	.0779	-.0402	.0942	-.0318	.0942	-.0339	.0494	-.0490	.0644
.70	-.0362	-.0069	-.0512	-.0213	-.0424	-.0162	-.0387	-.0198	-.0415	-.0119	-.0477	-.0224	-.0435	-.0344
.80	-.0430	-.0215	-.0359	-.0360	-.0442	-.0300	-.0355	-.0277	-.0432	-.0310	-.0449	-.0337	-.0418	-.0316
.85			-.0504	-.0417	-.0437	-.0335	-.0455	-.0312	-.0455	-.0335	-.0458	-.0370	-.0450	-.0456

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.57 U.S.	0.57 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.115?	.?96	.193?	.130?	.1975	.2687	.194?	.375?		.1955		.?5?		
.10	-.113?	.?13	.?66	.250?	.1877	.2455	.19??	.25??	.1925	.2633	.?4?			
.15	-.09?3	.?08	.250?	.2470	.1657	.2431			.1851	.2469				
.20	-.0913	.?88	.?94	.2385	.1953	.2128	.165?	.2?2?	.1832	.2411	.?9??	.?6??		
.25	-.0155	.0355			.?95	.2?15	.?55?	.2?1?	.1?12	.2383	.?683	.3883		
.30	-.0155	.294?	.0335	.0455	.027?	.0503	.0353?	.0567	.0?0	.2345	.?5?	.30?		
.40	-.0123	.233?	.0?13	.0303	.0?67	.0381	.0?25	.035?	.0490	.0760	.?5?	.3?		
.50	.001?	.?34	.0053	.0?38	.0?25	.035?	.0?88	.045?	-.5176	.0370	.?97	.0?5?		
.60	-.0413	.0251	.0?35	.0347	.0058	.0244	.0038	.0058	-.0403	-.0295	-.0??	.3??		
.80	-.0366	.396	.0366	.0432	.0360	.0368	-.04??	-.0437	-.0464	-.0433	-.?95	-.04??		
.90	-.036?	.?3?1	.0360	.0328			-.04??	-.0462	-.0405	-.0470	-.0?8?	-.0??		
.95							-.0?4?	-.0?13	-.0387	-.0424	-.039?	-.0124		

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0221	.291	.0156	.4125			.0337	.3449			.0555	.3538	.0368	.3396
.10	-.0153	.10?					.0?2?	.?066	.0334	.3970	.?37?	.?5??	.03??	.35??
.15					.0?7?	.4?99	.0?1?	.?091	.0278	.4038	.?292	.?5??	.0292	.3554
.20	-0.169	.263	-.0301	.31?	-.0108	.3982	.0?1?	.4039	.0228	.3997	.0?3?	.0?7?	.02??	.3325
.25	-.0378	.528	-.0369	.383			.0?2?	.3972	.0220	.3962	.0232	.3843	.0?1?	.31??
.30							.019?	.374?	.02?5	.391?	.0228	.30??	.02?5	.29??
.40	-.0270	.693			-.0388	.276	-.0428	.1352	-.0321	.1708	.0150	.3703	.0?3?	.28??
.50	-.0252	.0620	-.042?	.0948	-.0?43	.276	-.0508	.1300	-.0416	.1410	-.0357	.1339	.0073	.2273
.60					-.0?43	.1042	-.0465	.0505	-.0428	.1318	-.0185	.0753	-.05C.	.0?1?
.80	-.0412	.0151	-.0538	-.0088	-.0453	-.0039	-.0456	-.0043	-.0443	.0054	-.0489	-.0648	-.04?8	-.0303
.90	-.0487	.0131	-.0550	-.0273	-.0480	-.0182	-.0488	-.0136	-.0475	-.0166	-.0486	-.0140	-.0133	-.0337
.95			-.0544	-.0315	-.0478	-.0224	-.0455	-.0160	-.0482	-.0196	-.0483	-.0229	-.0481	-.0405

TAIL 2

TABLE XI - CONTINUED
(h) α = 9.85°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.2254	.2240	.2161	.3052	.2123	.3111		.2256			.2359	.2473
.10	.1453	.1937	.2253	.2853	.2173	.2798		.2910	.2220	.2960	.2034	.2868	.2384	.2906
.15	.1408	.1391	.2177	.2857	.2151	.2767			.2145	.2792			.1962	.2500
.20	.1221	.1808	.2118	.2770	.2151	.2761	.1890	.2630	.2118	.2727	.2130	.2822	.1845	.2375
.25	.0300	.2155			.2099	.2743	.2109	.2427	.2123	.2586	.2165	.2837	.1739	.2213
.30	.0295	.0443							.2335	.2548	.2144	.2955	.1587	.2124
.40	.0258	.0383	.0376	.0619	.0393	.0659	.0453	.0736	.0611	.0927	.2262	.2558	.1631	.2140
.50			.0248	.0434	.0292	.0529	.0324	.0541			.0692	.0927	.1581	.1975
.60	.0119	.0336	.0179	.0306	.0246	.0467	.0223	.0468	.0256	.0513	.0310	.0483	.0213	.0146
.70	-.0377	-.0194	-.0391	-.0305	.0179	.0394	.0041	.0379	.0397	.0243	.0414	.0329	.0220	.0334
.80	-.0335	-.0358	-.0323	-.0411			.0041	.0379	.0437	.0402	.0455	.0404	.0540	.0465
.90	-.0316	-.0367	-.0308	-.0360	-.0336	-.0326	.0405	.0406	.0356	.0422	.0353	.0411		
.95							.0382	.0350	.0335	.0372	.0339	.0365		-.0475

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0299	.1217	-.0051	.4628			.0098	.4002			.0414	.4169	.0251	.3998
.10	-.0222	.1108					-.0044	.4719	.0149	.4659			.0252	.4306
.15					-.0095	.4756	-.0008	.4773	.0065	.4753			.0189	.4160
.20	-.0255	.1209	-.0398	.3444	-.0172	.4525	-.0051	.4708	.0000	.4707	.0107	.4525	.0158	.3941
.25	-.0417	.0541	-.0527	.1642			-.0063	.4640	-.0023	.4678	-.0067	.4555	.0142	.3728
.30							-.0094	.4386	-.0034	.4607	.0012	.4356	-.0133	.3675
.40	-.0313	.0850							-.0437	.2136	.0420	.1534	.0129	.3462
.50					-.0442	.1596	-.0510	.1723	-.0508	.1855	-.0538	.1124	-.0014	.2777
.60	-.0335	.1142	-.0455	.1214			-.0561	.1656	-.0501	.1744	-.0526	.0152	-.0541	.0060
.70					-.0462	.1339	-.0528	.0750	-.0460	.0280	-.0524	.006	-.0472	-.0207
.80	-.0453	.0283	-.0565	.0043	-.0489	.0099	-.0531	.0116			-.0509	-.0010	-.0459	-.0288
.90	-.0525	-.0024	-.0579	-.0129	-.0520	-.0041	-.0531	.0010	-.0503	-.0010	-.0524	-.0040	-.0516	-.0357
.95			-.0569	-.0181	-.0516	-.0088	-.0530	-.0036	-.0514	-.0044				

TAIL 2

123

TABLE XL - CONTINUED
(i) q = 11.38°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1814	.2312	.2645	.2621	.2507		.2281	.3525						
.10	.1151	.3378	.2652		.2545				.2552	.3376	.2408	.3243		
.15	.1528	.2169	.2694	.3319	.2491				.2467	.3176	.2505			
.20	.0485	.1640	.2499	.3232	.2451		.2435	.2941	.2435	.3065	.2478			
.25	.0484	.0521			.2422		.2415	.3150	.2412		.2453			
.30	.0443	.0572	.0560	.0815	.0584	.0565	.0680	.0933	.0802	.3012	.2371			
.40			.0424	.0609	.0484	.0700	.0461	.0712		.1172	.0859			
.50	.0274	.0517	.0334	.0468	.0534	.0640	.0383	.0550	.0471	.0673	.0455	.0617		
.60	.0311	.0164	.0327	.0225	.0367	.0560	.0205	.0312	.0283	.0145	.0352	.0281		
.70	.0278	.0285	.0249	.0349			.0413	.0322	.0299	.0362	.0400	.0413	.0343	.026
.90	.0243	.0294	.0232	.0289	.0259	.0257	.0334	.0354	.0278	.0376	.0295	.0354		
.95							.0265	.0287	.0254	.0315	.0263	.0316		.0533

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0418	.1616	-.0195	.5165			.0030	.7717	.0081	.5471	.0334	.4954	.0189	.4745
.10	-.0311	.1263					-.0022	.5512	-.0007	.5573			-.0179	.5109
.15					-.0165	.5463	-.0062	.5575	-.0072	.5514			-.0220	.4922
.20	-.0348	.1322	-.0478	.3611	-.0243	.5139	-.0124	.5363	-.0209	.5191	.0334	.5393	-.0150	.4706
.25	-.0483	.0655	-.0568	.1927			-.0119	.5021	-.0211	.5438	-.0033	.5480	-.0096	.4511
.30	-.0353	.1179							-.0176	.2627	-.0067	.5272	-.0084	.4417
.40			-.0490	.1504	-.0467	.1932	-.0542	.2061	-.0542	.2231	-.0451	.2163	-.0082	.4212
.50	-.0389						-.0551	.2009	-.0534	.2163	-.0575	.2543	-.0035	.3373
.60			-.0480		-.0491	.1637	-.0553	.1013	-.0482	.2513	-.0573	.0956	-.0255	.0277
.70	-.0408		-.0515	.0238	-.0529	.0265	-.0582	.0298			-.0571	.0345	-.0635	.0052
.80	-.0565		-.0611	.0146	-.0553	.0116	-.0579	.0146	-.0538	.0168	-.0555	.0265	-.0530	.0153
.95			-.0508	-.0005	-.0547	.0047	-.0576	.0125	-.0552	.0148	-.0570	.0227	-.0533	.0245

TABLE XI.- CONTINUED
(j) α = 15.94°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2651	.3244	.3624	.3527	.3245	.4538	.3043	.4526		.3343	.3113	.4125	.2146	.2965
.10	.2549	.3392	.3518	.3490	.3385	.4451		.4210	.3356	.4308	.3252		.1708	.2359
.15	.2577	.3056	.3534	.4465	.3357	.4176	.2959	.3693	.3280	.4034	.3223	.4045	.1627	.2293
.20	.0837		.3456	.398	.3318	.4184	.3255	.4177	.3251	.4012	.3605	.4019	.1776	.2468
.25	.0948				.3284	.4155			.3245	.3963		.4019	.1816	.2590
.30	.0911	.088	.1020	.3145	.1013	.1317	.1123	.1427	.3244	.3920	.3104	.3857	.2042	.2865
.40			.0854	.0455	.0903	.1179	.0923	.1173	.1295	.1674	.252	.456	.2190	.2753
.50	.0687	.1010	.0732	.0887	.0871	.1122	.0574	.0775	.0857	.1082	.0753	.0968	.0007	.0056
.60	-.0135	.0125	-.0160	-.0041	.0786	.1038	.0577	.0655	-.0077	.0049	-.0229	-.0175	-.0130	-.0135
.80	-.0103	-.0112	-.0073	-.0198	-.0139	-.0169	-.0242	-.0142	-.0290	-.0257	-.0221	-.0200	-.0335	-.0210
.90	-.0053	-.2099	-.0042	-.0111			-.0110	-.0190	-.0135	-.0228	-.0113	-.0177		
.95							-.0077	-.0105	-.0101	-.0152	-.0093	-.0141		-.0333

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0578	.2227	-.0238	.5573			.0006	.6566			.0279	.7042	.0128	.6452
.10	-.0449	.6?5					-.0047	.7522	.0054	.7548			.0156	.7094
.15		.772			-.0184	.7120	-.0111	.7471	-.0041	.7707			.0117	.6901
.20	-.0482	.615	-.0526	.4922	-.0299	.6554	-.0150	.7200	-.0109	.7593	-.0008	.7863	.0105	.6750
.25	-.0522		-.0602	.2640			-.0184	.6987	-.0139	.7368	-.0053	.7545	.0104	.6506
.30		.7?7					-.0211	.6589	-.0151	.7169	-.0119	.6803	.0103	.6393
.40	-.0415	.717							-.0500	.3637			.0107	.6048
.50			-.0513	.2264	-.0494	.2720	-.0555	.2956	-.0555	.3267	-.0484	.3531	-.0047	.4861
.60	-.0450	.2008					-.0633	.2881	-.0552	.3065	-.0594	.2683	-.0594	.0740
.70					-.0525	.2452	-.0598	.1572	-.0518	.1001	-.0604	.1048	-.0549	.0298
.80	-.0527	.0705	-.0631	.0710	-.0564	.0681	-.0619	.0718			-.0603	.0849		
.90	-.0502	.0381	-.0557	.0482	-.0591	.0515	-.0610	.0598	-.0563	.0644	-.0587	.0750	-.0556	.0149
.95			-.0658	.0445	-.0579	.0460	-.0601	.0540	-.0591	.0594	-.0598	.0688	-.0625	.0090

TAIL 2

125

TABLE XI.- CONCLUDED
(N) g = 10.35°

Cp at y/b of

x/c	0.02		0.22		0.44		0.55		0.57		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	-.0646	.2849	-.0229	.834:		.905:	.0055	.9283			.0308	.007:		
.10	-.0538	.2.93					.0059	.9882						
.15					-.0148	.905:		.9512	.9113	1.0235				
.20	-.0553	.2380	-.0537	.6300	-.0276	.8354	-.013:	.9400	-.0078	1.0087				
.25	-.0616	.1518	-.0613	.3553			-.0158	.8794		.9766	.0025	.9679		
.30							-.0194	.8245	-.0127	.93.:	-.0034	.9502		
.40	-.0653	.2532			-.0503	.37.2		.40.:	-.0503	.69.1	-.000	.9533		
.50	-.0499	.2858	-.0533	.3254	-.0537	.3505	-.0612	.3502	-.0558	.459:	-.092	.519:		
.60					-.0570	.1262	-.0606	.2326	-.0554	4.187	-.059	.3557	-.0607	.214
.70	-.0554	.121:	-.0647	.132:	-.0601	.1047	-.0625	.1302	-.0524	.1579	-.0611	.175:	-.0523	.077:
.80	-.064:	-.084:	-.0672	.1115	-.0589	.056:	-.0617	.1170	-.0553	.1209	-.0507	.152:		
.90			-.0574	.1082			-.05:7	1.07	-.0588	.1182	-.0592	.4.:	-.0525	.2636
.95											-.0606	.12:	-.0601	.0585

TAIL 2

TABLE XII.- PRESSURE COEFFICIENTS. Φ = 22.5° δ = 0°, M = 3.70

(a) α = -4.20°

TAIL 1

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0241	.0793	.1963	.0722	.1720	.1565	.1672	.1745		.229			.192	.365
.10	.0280	.0728	.1856	.148	.1824	.445		.1942	.1813	.607	.715	.159	.2004	.358
.15	.0269	.0568	.1753	.1195	.1835	.1468			.785	.1525	.1903	.161	.1834	.156
.20	-.0015	.0115	.1613	.207	.1923	.1455	.1359	.2309	.1780	.1514	.177	.166	.1735	.445
.25	-.0004	.0111			.1791	.1430	.1756	.1539	.1790	.1496	.1756	.165	.1613	.402
.30	.0037	.0100	.0094	.0023	.0309	.0103	.0388	.0147		.1473	.1700	.1429	.1195	.288
.40				.0033	.0202	.0013	.0245	.0019	.0521	.0345	.1700	.1429	.1396	.166
.50					.0157	.0056	.0086	.1614			.0501	.0265	.1251	.0461
.60	.0024	.0025	.0006	.0053	.0083	.0096	.0022	.0120	.0226	.0055	.0157	.0041	.0387	.0497
.70	.0303	.0260	.0409	.0408			.0432	.0439	.0325	.0384	.0413	.0453	.0475	.0497
.80	.0329	.0361	.0431	.0462	.0329		.0416	.0396	.0408	.0362	.0484	.0431	.0487	.0451
.90	.0353	.0355	.0416	.0389	.0329	.0237	.0433	.0390	.0443	.0392	.0470	.0409		
.95									.0420	.0386	.0432	.0405	.0379	

TAIL 2

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1341	.0241	.2811	.0927			.2686	.0923	.2883	.1311	.2852	.1475	.2457	.0990
.10	.1516	.0055					.2856	.1047	.2892	.1044			.2700	.0987
.15					.2844	.0927	.2546	.1009	.2892	.1044			.2490	.0891
.20	.1576	.0131	.1482	.0557	.2850	.0870	.2856	.0960	.2819	.0981	.2766	.0954	.2359	.0783
.25	.0475	-.0210	.0844	-.0043			.2868	.0933	.2853	.0959	.2816	.0962	.2291	.0712
.30							.2793	.0849	.2825	.0928	.2599	.0847	.2211	.0679
.40	.0365	-.0009							.1027	.0041			.2231	.0605
.50					.0693	.0019	.0687	-.0109	.0733	-.0119	.0920	.0003	.1933	.0397
.60	.0524	-.0154	.0489	-.0132			.0635	-.0198	.0650	-.0157	.0425	-.0207	.0288	.0409
.70					.0523	-.0174	.0145	-.0384	.0297	-.0257	.0310	-.0403	.0397	.0340
.80	-.0198	-.0932	-.0324	-.0384	-.0271	-.0357	-.0347	-.0429	-.0462	-.0363	-.0429	-.0390	-.0423	.0413
.90	-.0352	-.0490	-.0476	-.0424	-.0414	-.0393	-.0430	-.0415	-.0489	-.0372	-.0480	-.0370	-.0490	-.0483
.95			-.0499	-.0436	-.0448	-.0387	-.0458	-.0419			-.0497	-.0400		

127

TABLE VII.- CONTINUED

(b) α = -2.20°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.1677	.1177	.1563	.179?	.1553	.18??		.1405	.1?2?			
.10	.0486	.0611	.1643	.1580	.1618	.1705		.1522	.16??	.1850		.1?2?		
.15	.0504	.0582	.1567	.1581	.1613	.1733			.16??	.1755	.165?	.192?		
.20	.046?	.0531	.1504	.1519	.1535	.1722	.159?	.1?9?	.16??	.1735	.162?	.1?5?		
.25	.006?	.0049			.1535	.1599	.158?	.1?6?	.161?	.171?	.600	.1?6?		
.30	.0075	.0054							.19?	.1685	.54?	.16??		
.40	.0120	.0054	.0104	.0051	.0248	.0227	.030?	.0255	.0423	.0458	.0427	.030?		
.50			.0002	-.0052	.0153	.0091	.0???	.0119			.0110	.0065		
.60					.026?	.0033	.0113	.0843	.0155	.0130	.0462	.0482	.0???	
.70	.009C	.0094	-.0016	-.0047	.0062	-.0015	.0039	.0120	.0381	.0369	.0523	.0502	.0???	
.80	-.0302	-.0227	-.0449	-.0441			.0485	.0493	.0407	.0454	.0464	.04??		
.90	-.0329	-.0338	-.0422	-.0426	-.0353	-.0323	.0455	.0445	.0458	.0454	.0437	.0428		
.95	-.0360	-.0353	-.0411	-.0415			.0425	.0425	.0434	.0434			.0?1?	

Cp at y/b of

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.09C5	.0504	.2340	.1314			.2232	.1223			.2425	.1356	.2054	.1277
.10	.104:	.0364					.2355	.1425	.2363	.1449			.2239	.1313
.15					.2296	.1310	.232?	.1372	.2365	.1403			.2233	.1201
.20	.1062	.0381	.1098	.0901			.2325	.1334	.2258	.1349	.2232	.1313	.1915	.110:
.25	.03C4	-.0095			.2293	.1260	.2336	.1306	.232:	.1331	.2334	.1305	.1672	.C0?
.30			.0553	.0041			.227?	.1213	.2314	.1296	.2231	.1187	.18?	.C8?
.40	.0344	-.0011							.0738	.0220			.1803	.0848
.50			.0237	-.0195	.0438	-.CC35	.0425	-.0033	.0482	.0018	.0554	.0110	.1553	.0577
.60	.0375	-.0089			.0274:	-.0164	.037C	-.0101	.0398	-.0036	.0221	-.0190	.0344	-.0425
.70							-.0047	-.0371	.0308	-.0409	.0377	-.0466	.0?7?	-.C?23
.80	-.0267	-.0385	-.0403	-.0423	-.0362	-.04C5	-.0439	-.0451	.0494	-.0407	.0477	-.0431	.0456	-.0368
.90	-.0396	-.0485	-.0508	-.0426	-.0477	-.C?C5	-.049?	-.0421	.0474	-.0411	.0499	-.C???	.0435	-.0434
.95			-.0473	-.0431	-.0462	-.0394	-.047?	-.0419	.0411?		.0481	-.0413		

TABLE VII - CONTINUED
(c) α = 3.20°

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.85		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.025	.0607	.0637	.1818	.1775			.1820	.1570		.1826	.2014	.123	.1633	.595
	.553	.5588			.808	.155	.182	.1818	.1901	.1815				
							.833	.1796	.1882	.1765				
.005	.0683	.0618	.0730	.313	.730	.735	.835	.756	.1823	.1715	.1823	.153		.458
.025	.0443	.0088	.0285	.0253			.531	.725	.1838	.1711	.1865	.153		.332
.030							.241	.661	.690		.1772			.252
.010	.013	.0043			.2218	.0123	.2053	.0152	.0464	.0113	.0417	.557		.145
.050	.0233	.0054	.0012	-.0087	.0065	-.0009	.2415	.0094	.025	.0205	.0037	.709	.038	.857
							.258	.0656	.0130	.0134	-.0453	-.109	.033	.733
.20	-.0352	-.0315	.0486	.0471	.0450	.0417	.0514	.0500	-.0380	.0401	-.0453	-.0585		.137
.025	-.0313	-.0455	.0461	.0428	.0438	.0418	.0452	.0124	-.0448	.0453	-.0462	-.0503	.0.0	.243
.035	-.0305		.0143	-.0423	-.0472	-.0385	.0533	.0406	-.0429	-.0465	-.0446	-.0212		.432

TAIL 2

TABLE XII. - CONTINUED
(a) α = 1.80°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0534	.1044	.325	.1529	.1316	.225		.2455	.378	.1753	.1328	.2149	.479	.855
.10	.0550	.1090	.300	.2164	.1302	.2145		.236	.378	.2307			.154	
.15	.0483	.1011	.1235	.2118	.1284	.2182			.318	.2195	.349	.2162	.1322	
.20	-.0019	.0143	.1189	.2047	.259	.219		.2145	.289	.2145	.1332	.2252		.935
.25	-.003	.0165			.1236	.2161	.296	.2217	.302	.2118	.1308		.1078	
.30	-.0052	.0113							.294	.2056	.1245	.2052	.0932	
.40			-.0015	.0314	.0072	.0456		-.0438	.241	.0672		.0589	.0897	.556
.50			-.0102	.017?	-.0012	.0315		-.0298	-.0011		.0250	.0583	.0809	.330
.60					-.0042	-.0248		.0461	-.0057	.0298	-.0026	.0242	.0455	-.0401
.70	-.0008	.0167	-.0136	.011?	-.0098	.017?	-.0172	-.0008	-.0457	-.0312	-.0523	-.0418	-.0532	-.0468
.80	-.033?	-.0243	-.0465	-.0401			-.0485	-.0452	-.0453	-.0445	-.0483	-.0515	-.0516	-.0540
.90	-.0420	-.0399	-.0404	-.0466	-.0343	-.0363	-.0426	-.0493	-.0443	-.0511	-.0443	-.0510	-.0399	
.95	-.042?	-.0403	-.0401	-.0429			-.0425	-.0465	-.0435	-.0483	-.0435	-.0470	-.0442	-.0454

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0407	.0759	.1319	.2291			.393	.1950	.1467	.2246	.1625	.2047	.1315	.1942
.10	.0438	.0582						.2308	.1452	.2268			.1416	.208C
.15					.1339	.2247		.2267	.1452	.2268			.1315	.1954
.20	.0389	.0748						.2219	.1383	.2217			.1290	.1858
.25	-.0003	.0228	.0391	.1752	.1321	.2132	.387	.2191	.1395	.2204	.1409	.2191	.1136	.1717
.30			.0025	.0511			.341	.2051	.1333	.2164	.1433	.2235	.1057	.1624
.40	.0039	.0129							.0247	.0688	.1358	.2056	.1062	.1491
.50					.0013	.0335	.0009	.0355	.0055	.0424	.0204	.0515	.0890	.1131
.60	.0147	.0208	-.0155	.0068	-.0124	.0201	-.0054	.0263	.0004	.0343	.0122	.0050	-.0445	-.0387
.70					-.0425	-.0405	-.0327	-.0131	-.0448	-.0350	-.0515	-.0439	-.0464	-.0407
.80	-.0286	-.0249	-.0475	-.0454	-.0406	-.0462	-.0474	-.0458	-.0430	-.0449	-.0470	-.0481		
.90	-.0397	-.0410	-.0445	-.0465	-.0398	-.0414	-.0462	-.0480	-.0433	-.0449	-.0433	-.0418	-.0399	-.0431
.95			-.0444	-.0441			-.0425	-.0450	-.0433	-.0427	-.0433	-.0431	-.0442	-.0461

TABLE XII.- CONTINUED
(e) α = 3.90°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.1182	.1735	.1218	.2517	.1288	.2712		.1952				.2067
.10	.0440	.1419	.143	.2507	.18	.2467		.26.6	.126	.2563	.235	.2416	.5	.2473
.15	.0447	.1485	.1079	.2424	.157	.2449			.1204	.2429		.97	.2249
.20	.0390	.1387	.1034	.2369	.122	.2437	.1255	.2393	.175	.2384	.248	.2462	.34	.2.34
.25	.0094	.0273			.093	.2439	.113	.246.	.14	.2350	.23.	.2463	.053	.2054
.30	.0118	.0274							.155	.2378	.209	.2433	.096	.902
.40	.0147	.0249	.0080	.0470	.0007	.0565	.0068	.256.	.0157	.0776	.146	.2304	.3860	.1749
.50			.159	.302	.0085	.0426	.006.	.0416			.205	.0737	.04	.513
.60					.0127	.0354	.0035	.046.	.0075	.0399	.0082	.0363	.0414	.0243
.70	.0182	.0251	.0202	.0233	.0.79	.024.	.0218	.0072	.0480	.0275	.0545	.0372	.0523	.0226
.80	.0452	.0217	.0440	.0342			.0468	.042.	.0447	.0419	.0486	.0483	.0452	.0527
.90	.0421	.0384	.0404	.0445	.0348	.0364	.0434	.0460	.0446	.0497	.0455	.0515		
.95	.0421	.0392	.0405	.0440			.032	.0477	.0444	.0433	.0448	.0498		.0456

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0251	.0739	.0875	.2832			.1024	.2360	.1076	.2713	.1263	.2417	.3986	.2306
.10	.0255	.0754					.1037	.2795	.1045	.2751			.1061	.25.4
.15					.0909	.2780	.095.	.2764	.0984	.2710			.0370	.2421
.20	.0190	.0809	.0120	.2135	.0883	.270.	.0955	.2727	.0984	.2704	.1019	.2564	.087	.2272
.25	.0108	.0318	.0188	.0753			.096.	.2689	.0974	.2643	.030	.2703	.080	.2137
.30							.0925	.2527	.0038	.2643	.030	.2703	.755	.202.
.40	.0040	.0234			.0146	.0582	.0158	.0627	.0111	.0956	.863	.2499	.744	.923
.50	.0058	.0367	.0245	.0303			.0220	.0563	.0154	.0682	.007	.07.8	.053	.13
.60					.0275	.0430	.0431	.0059	.0456	.0598	.0262	.0220	.0478	.0324
.70										.0260	.0477	.0350	.036	.0373
.80	.027.9	.0139	.0478	.0384	.0394	.0319	.0436	.0358	.012.	.042.	.0445	.0415		
.90	.0368	.0333	.046.	.0482	.0405	.0428	.042.	.042.	.0429	.0426	.0424	.0426	.0397	.036.
.95			.055	.047.	.0402	.0430	.0420	.0435			.0431	.0498	.044	.043.

TAIL 2

TABLE XII. - CONTINUED
(1) δ = 5.10°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05				.2001		.2903		.3060						
.10	.0371	.807	.1075	.2913	.1194			.3926		.2736				
.15	.0344	.803	.1001	.2762	.1157				.1056	.2750				
.20	.0225	.781	.0350	.2761	.1055			.2605	.1620	.2664				
.25	-.0146	.0427			.1051	.2975		.2776	.1156	.2688				
.30	-.0173	-.0143												
.40	-.0215		-.0213	-.0450	-.0134	.0576		.0558						
.50					-.0166	.0552		.0588	-.0109	.0539				
.60					-.0220	.0416		.0508	-.0507	.0211				
.70	-.0246	-.0385	-.0243	.0353				.0170	-.0506	.0388				
.80	-.0460	-.0166	-.0424	-.0279	-.0290			.0368	-.0436	.0465				
.90	-.0405	-.0349	-.0422	-.0412	-.0344			.0425	-.0443	.0477				
.95	-.0408	-.0353	-.0402	-.0433		-.0222		.0452	-.0410					

TAIL 1

Cp at y/b of

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0143	.0585	.0487	.3354			.0661	.2803	.0708	.3230	.0953	.2893	.0540	.2730
.10	.0159	.0585						.3327	.0665	.3292				.3014
.15					.0514	.2319		.3325	.0602	.3255				.2902
.20	.0112	.0745	-.0100	.2463	.0469	.2219		.3276	.0595	.3224	.0855	.3145	.0512	.2731
.25	.0136	.0309	-.0340	.0951				.3227	.0584	.3152	.0655	.3203		.2516
.30								.3034	-.0364	.3152	.0525	.3024	.0456	.2476
.40	-.0083	.0344			-.0256	.0869	-.0299	.0935	-.0155	.1258	.0161			.2332
.50			-.0319	.0536			-.0372	.0876	-.0268	.0992	-.0377	.0928	.0500	
.60	-.0065	.0512			-.0384	.0560	-.0464	.0234	-.0299	.0911	-.0478	-.0229	-.0500	.0236
.70					-.0421	-.0223	-.0417	-.0237	-.0447	-.0142	-.0452	-.0315	-.0433	.1357
.80	-.0343	-.0067	-.0517	-.0266	-.0439	-.0350	-.0322	-.0322	-.0443	-.0344	-.0447	-.0352	-.0412	-.0379
.90	-.0435	-.0278	-.0501	-.0409	-.0436	-.0378	-.0313	-.0354	-.0447	-.0352	-.0455	-.0376		
.95			-.0495	-.0443										

TAIL 2

TABLE XII.- CONTINUED
(g) α = 7.90°

TAIL 1

	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.83		0.93	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0415	.2219	.1216	.2361	.2988	.3295	.1322	.3524		.2537			.1556	
.10	.0367	.2359	.1456	.3398		.3376		.3318	.1357	.3342	.1294	.3622	.1560	
.15			.1076	.3290	.1956	.3224			.1287	.3184				
.20				.2237			.1234	.2978		.3128	.1304			
.25	-.0134	.0627			.1725	.3225	.1236	.3207	.1216	.3115	.1285			
.30	-.0161	-.0611							.1163	.3089	.1250	.3227		
.40		-.0647	-.0110	.0862	-.0021	.0908	.0084	.0933	.0090	.1205				
.50			-.0207	.0655		.0775	-.0062	.0761						
.60						.0705	.0061	.0611	-.0167	.0746	-.0074	.0706	-.0363	
.70	-.0250	.0577	-.0243	.0546	-.0214	.0517	-.0254	.0343	-.0531	.0114	-.0538	-.0231	-.0407	
.80	-.0425	-.0077	-.0402	.0184			-.0442	-.0282	-.0419	-.0338	-.0465	-.0381	-.0613	
.85	-.0380	-.0280	-.0384	-.0344	-.0340		-.0421	-.0364	-.0426	-.0409	-.0440	-.0436		
.95	-.0382	-.0293	-.0387	-.0377		-.0281	-.0427	-.0391	-.0424	-.0430	-.0436	-.0455		

TAIL 2

	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0122	.0399	.0171	.3738		.3941	.0327	.3253		.3766	.0571	.3338	.0432	
.10	.0135	.0411					.0299	.3831	.0371	.3831			.0427	
.15					.0174		.0252	.3877	.0314	.3843			.0361	
.20	.0097	.0562	-.0258	.2717	.0011	.3693	.0220	.3810	.0253	.3814	.0333	.3631	.0298	
.25	.0226	.0215	-.0433	.1145			.0211	.3749	.0242	.3772	.0314	.3728	.0262	
.30							.0180	.3520	.0230	.3631	.0254	.3627	.0233	
.40	-.0141	.0425							-.0320	.1635	-.0309	.1242	.0222	
.50					-.0356	.1094	-.0419	.1220	-.0405	.1334	-.0470	.0802	-.0105	
.60	-.0132	.0528	-.0382	.0715			-.0491	.1145	-.0418	.1240	-.0498	-.0061	-.0508	
.70					-.0434	.0863	-.0499	.0409	-.0445	.0026	-.0487	-.0146	-.0450	
.80	-.0400	-.0081	-.0548	-.0125	-.0450	-.0130	-.0495	-.0135	-.0472	-.0238	-.0476	-.0195	-.0429	.0335
.85	-.0498	-.0286	-.0532	-.0313	-.0471	-.0265	-.0487	-.0228	-.0476	-.0263	-.0485	-.0221	-.0481	-.0433
.95			-.0532	-.0368	-.0467	-.0298	-.0486	-.0271						

133

TABLE XII.- CONTINUED
(h) α = 9.90°

Cp at y/b of

TAIL 1

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0538	.2568	.1384	.2748	.1412	.3802	.1391	.4073	.349	.3976	.409	.3712		.3179
.10	.0164	.2850	.1314	.3974	.1396	.3705		.3965	.300	.3869				.3502
.15	.0474	.2850	.1229	.3685	.1238	.3757			.361	.3655	.42	.3774		.3532
.20	.0400	.2670	.1600	.3810	.1282	.3780	.1252	.3645		.3630	.333	.3784		.3703
.25	-.0067	.0860				.3762	.1310	.3726		.3627	.38	.3740		.3602
.30	-.0095	.0860								.3528	.3310	.3563		.3518
.40	-.0168	.0937	-.0055	.1136	.0023	.1171	.0085	.1189	.052	.1494	.0294	.1433		.3336
.50			-.0152	.0860	-.0092	.1038	-.0070	.1020			.0022	.0937		.2656
.60					-.0120	.0964	-.0003	.0852	.024	.0967	-.0022	.0937	-.0388	.0075
.70	-.0224	.0845	-.0194	.0776	-.0168	.0881	-.0295	.0552	-.0566	-.0001	-.0482	-.0127	-.0395	-.0228
.80	-.0367	-.0048	-.0343	-.0063	-.0347		-.0458	-.0166	-.0371	-.0240	-.0404	-.0232	-.0553	-.0287
.90	-.0324	-.0179	-.0328	-.0258	-.0347	-.0193	-.0448	-.0262	-.0373	-.0309	-.0386	-.0353		
.95	-.0331	-.0182	-.0327	-.0298			-.0450	-.0299	-.0373	-.0335	-.0382	-.0386		-.0343

TAIL 2

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0154	.0247	.0116	.2915			.0010	.3760	.0552	.4324	.2299	.3817	.0115	.3582
.10	.0164	.0282				.4269	-.0025	.4382	.2012	.4115			.0271	.4020
.15					-.0104		-.0067	.4417	.2065	.4383			.0075	.3874
.20	.0082	.0426	-.0377	.2852	-.0139	.4003	-.0072	.4330	.0066	.4376	.0022	.4237	.0053	.3705
.25	-.0284	.0137	-.0473	.1304			-.0054	.4232	-.0053	.4261	-.0013	.4455	.0030	.3602
.30							-.0067	.3965		.1979	-.0064	.3907	-.0033	.3518
.40	-.0229	.0456							.0434		-.0064		-.0007	.3336
.50					-.0452	.1281	-.0505	.1452	.0455	.1663	-.0553	.1740	-.0057	.2656
.60	-.0223	.0452	-.0437	.0897			-.0576	.1368	.0195	.1563	-.0556	.1233	-.0557	.0082
.70					-.0485	.1050	-.0545	.0535	.0178	.0190	-.0543	.0188	-.0432	-.0136
.80	-.0470	-.0092	-.0594	-.0000	-.0518	-.0030	-.0558	-.0018	-.0530	-.0051	-.0541	-.0051		
.90	-.0565	-.0289	-.0587	-.0240	-.0538	-.0163	-.0551	-.0116	-.0530	-.0118	-.0529	-.0022	-.0497	-.0288
.95			-.0588	-.0304	-.0538	-.0199	-.0550	-.0155	-.0536	-.0140	-.0533	-.0057	-.0551	-.0355

TABLE XII. - CONTINUED
(i) α = 11.80°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.1596	.3382	.1636	.4424	.1520	.4733					.1879	.3686
.10	.0679	.3154	.1524	.4662	.1579	.4335		.4494		.3494		.4298	.1764	.4167
.15	.0610	.3435	.1430	.4586	.1522	.4403			.1619	.4497	.1551		.1409	.3854
.20	.0527	.3206	.1352	.4507	.1468	.4441	.1354	.4059	.1535	.4302			.1335	.3687
.25	.0007	.1158			.1440	.4408	.1430	.4352	.1487	.4234	.1571	.4372	.1281	.3500
.30	-.0020	.1140	.0005	.1460					.1478	.4223	.1548	.4386	.1277	.3392
.40	-.0107	.1253	-.0097	.1211	.0085	.1487	.0179	.1503	.1446	.4193	.1527	.4348	.1270	.3332
.50					-.0036	.1344	.0012	.1323	.0233	.1810	.1458	.4159	.1221	.2991
.60			-.0144	.1059	-.0081	.1271	-.0037	.1021	-.0048	.1278	.0350	.1742	-.0285	.0058
.70	-.0185	.1142	-.0291	-.0071	-.0142	.1191	-.0214	.0792	-.0509	-.0139	.0025	.1200	-.0362	-.0122
.80	-.0324	.0187	-.0275	-.0142			-.0362	-.0053	-.0328	-.0161	-.0416	-.0018	-.0578	-.0182
.90	-.0276	-.0065	-.0274	-.0195	-.0299	-.0103	-.0370	-.0163	-.0324	-.0221	-.0351	-.0201		
.95	-.0287	-.0058					-.0375	-.0200	-.0325	-.0250	-.0334	-.0312		-.0293

Cp at y/b of

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0046	.0177	-.0224	.4102			-.0168	.4231			.0104	.4392	-.0100	.4033
.10	.0076	.0180					-.0202	.4876	-.0133	.4809			-.0102	.4555
.15					-.0258	.4546	-.0239	.4837	-.0211	.4911			-.0138	.4415
.20	-.0010	-.0325					-.0268	.4669	-.0261	.4872			-.0157	.4328
.25	-.0344	-.0065	-.0439	.3003	-.0353	.4182	-.0282	.4495	-.0282	.4806	-.0185	.4774	-.0163	.4202
.30			-.0515	.1477			-.0294	.4179	-.0283	.4622	-.0225	.4748	-.0163	.4147
.40	-.0266	-.0437							-.0547	.2152	-.0264	.4396	-.0163	.3967
.50					-.0467	.1433	-.0552	.1627	-.0575	.1881	-.0530	.2158	-.0238	.3176
.60	-.0273	.0411	-.0479	.1097			-.0592	.1546	-.0525	.1791	-.0592	.1529	-.0604	.0268
.70					-.0507	.1213	-.0573	.0654	-.0494	.0283	-.0577	.0388	-.0526	-.0071
.80	-.0496	-.0088	-.0618	.0052	-.0542	-.0056	-.0599	.0076	-.0559	-.0005	-.0577	.0207		
.90	-.0536	-.0285	-.0624	-.0182	-.0572	-.0071	-.0592	-.0015	-.0566	-.0036	-.0562	.0128	-.0523	-.0155
.95			-.0622	-.0236	-.0565	-.0116	-.0592	-.0057			-.0575	.0087	-.0583	-.0207

TABLE XII. - CONTINUED

(j) α = 15.80°

Cp at y/b of

z/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1071	.4348	.2160	.4959	.2131	.5381	.1894	.6308		.4753	.1919		.2229	.4772
.10	.1000	.4854	.2078	.6484	.2075	.5886		.6006	.2101	.5985		.5702	.1937	.5110
.15	.1000	.4854	.1966	.6227	.2209	.6010			.1999	.5723			.1586	.1632
.20	.0890	.4528	.1965	.6192	.1650		.1608	.5227	.1952	.5677	.1948	.5826	.1600	.1548
.25	.0232	.1991			.1512	.5014			.1935	.5723	.1920	.5875	.1614	.1437
.30	.0212	.1862					.1920	.5895	.1994	.5710	.1898	.5795	.1650	.1425
.40	.0103	.2086	.0199	.2261	.3287	.2298	.0405	.2312	.0484	.2538	.1823	.5645	.1650	.4194
.50			.0074	.1218	.0145	.2146	.0220	.2055			.0527	.2497	.1602	.3797
.60	-.0047	.1913	.0022	.1754	.0117	.2071	.0142	.1448	.0166	.2010	.0171	.1814	-.0176	.0313
.70	-.0224	.0572	.0131	.0433	.0054	.2003	-.0025	.1449	-.0333	.0521	-.0238	-.0257	-.0347	.0048
.80	-.0144	.0243	-.0119	.0149	.0189		-.0170	.0310	-.0215	.0076	-.0199	.0021	-.0539	.0171
.90	-.0158	.0297	-.0119	.0094		.0146	-.0166	.0158	-.0193	.0049	-.0193	-.0084	-.0555	
.95							-.0166	.0104	-.0192	.0009	-.0195	-.0128	-.0624	-.0027

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0261	.0056	-.0360	.4433			-.0352	.5561			-.0040	.6266	-.0214	.5794
.10	-.0191	.0024					-.0392	.5838	-.0292	.6040			-.0198	.6379
.15					-.0417	.5091	-.0422	.5590	-.0389	.6009			-.0224	.6176
.20	-.0256	.0186					-.0459	.5331	-.0439	.5791			-.0239	.5918
.25	-.0465	.0054	-.0524	.3418	-.0538	.4696	-.0475	.5141	-.0465	.5607	-.0305	.5846	-.0254	.5649
.30			-.0576	.1825			-.0485	.4733	-.0466	.5343	-.0366	.5850	-.0262	.5410
.40	-.0334	.0453			-.0490	.1946	-.0575	.2121	-.0631	.2604	-.0410	.5070	-.0286	.5029
.50	-.0375	.0591	-.0520	.1680			-.0635	.2060	-.0617	.2400	-.0595	.2594	-.0353	.4021
.60					-.0551	.1696	-.0628	.1008	-.0569	.2303	-.0636	.1903	-.0657	.0446
.70	-.0534	-.0035	-.0660	.0319	-.0536	.0359	-.0656	.0379	-.0532	.0583	-.0628	.0651	-.0572	.0147
.80	-.0634	-.0179	-.0669	.0067	-.0629	.0227	-.0650	.0272	-.0603	.0277	-.0628	.0516		
.90			-.0670	.0002	-.0620	.0180	-.0649	.0223	-.0616	.0241	-.0613	.0443	-.0555	.0136
.95											-.0627	.0396	-.0624	.0112

TAIL 2

TABLE XII.- CONCLUDED
(k) α = 10.90°

TAIL 1

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1605	.5827	.2834	.7104	.2734	.7855	.2384	.8237		.6402			.1095	.3601
.10	.1512	.6612	.2756	.7670	.2382	.7303		.8042	.2556	.7975	.0872	.4391	.0642	.4060
.15	.1354	.6116	.2632	.9435	.2603	.6052			.2408	.7637			.0542	.3874
.20					.2541	.8112	.2077	.7051	.2422	.7576	.0756	.4979	.0526	.3598
.25	.0550	.2792			.2502	.8061	.2470	.7328	.2391	.7514	.0803	.5062	.0514	.3865
.30	.0546	.277							.2365	.7425	.0876	.5275	.0502	.382
.40	.0436	.3123	.0481	.3233	.0631	.3362	.0659	.3343	.2695	.3424	.0915	.5273	.0479	.3820
.50			.0934	.2845	.0386	.3178	.0458	.3087			.0160	.2293	.0375	.365
.60	.0180	.2874	.0650	.2617	.0525	.3131	.0222	.2288	.0294	.2604	-.0085	.525	.0537	.0033
.70	-.0216	.1113	-.0024	.0946	.0328	.3090	.0140	.2289	-.0372	.0880	-.0416	.0301	-.0535	-.0109
.80	-.0055	.0730	-.0012	.0608	-.0073		-.0177	.0743	-.0176	.0463	-.0397	.0114	-.0607	-.0047
.90	-.0044	.0847	-.0015	.0560		.0598	-.0146	.0532	-.0176	.0439	-.0238	.0034		
.95							-.0143	.0465	-.0173	.0393	-.0268	-.0016		-.0378

TAIL 2

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	-.0498	.0019	-.0439	.5362			-.0386	.7214			-.0103	.3029	-.0263	.8351
.10	-.0377	.0036					-.0417	.7039	-.0317	.7258			-.0202	.7948
.15					-.0437	.6079	-.0453	.6691	-.0408	.7131			-.0217	.7618
.20	-.0399	.0411	-.0567	.4181			-.0490	.6389	-.0457	.6898			-.0254	.7214
.25	-.0546	.0243	-.0605	.2433	-.0571	.5683	-.0506	.6139	-.0481	.6640	-.0321	.6984	-.0286	.6839
.30							-.0520	.5647	-.0486	.6381	-.0382	.6831	-.0318	.6510
.40	-.0388	.0575			-.0509	.2613	-.0597	.2799	-.0644	.3110	-.0443	.5895	-.0336	.6145
.50	-.0444	.0925	-.0636	.2424			-.0659	.2722	-.0643	.3079	-.0616	.3120	-.0400	.4717
.60			-.0638	.2424	-.0578	.2348	-.0653	.158	-.0594	.3037	-.0653	.2475	-.0666	.0753
.70	-.0553	.0138		.0666	-.0529	.0737	-.0684	.0748	-.0550	.1014	-.0650	.1033	-.0530	.0637
.80	-.0652	.0015	-.0635	.0501	-.0654	.0595	-.0572	.0641	-.0614	.0671	-.0647	.0909		
.90			-.0700	.0425	-.0648	.0537	-.0670	.0592	-.0638	.0642	-.0525	.0830	-.0568	.0517
.95											-.0644	.0770	-.0645	.0463

TABLE XIII.- PRESSURE COEFFICIENTS, Λ = 45°, δ = 0°, M = 3.70

(a) α = -4.30°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.33 U.S.	0.33 L.S.	0.98 U.S.	0.98 L.S.
.05			.2315	.2668		.1345	.1978	.1455		.0003	.2122			
.10								.2027				.1380		
.15						.1150		.3294			.2105			
.20							.1531	.3294			.2224			
.25							.2108	.1226			.2111			
.30			.0356			.2041	.0508	.0051			.2050			
.40			.0245			.0003	.0473	.0069		.1189	.0028			
.50	.0150	.0007	.0175	.0416	.0636	.0159	.0135	.0056	.0497	.0054	.0372	.0095		
.60	.0659	.0252	.0354	.0428			.0201	.0174	.0235	.0074	.0353	.0452		
.70	.0263	.0320	.0466	.0413			.0387	.0387	.0424	.0316	.0462	.0413		
.80	.0312	.0331	.0464	.0399		.0225	.0453	.0387	.0484	.0382	.0494	.0407		
.90							.0465	.0384	.0482	.0375	.0488	.0400		.0238

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1361	.0449	.2697	..3.			.2501	.1103	.2530	.342	.2626	.1313	.2281	.1186
.10	.1486	.0298					.2656	.1256	.2681	.255			.2493	.1195
.15	.1547	.0291			.2636	.1142	.2640	.1207	.2520	.1202			.2290	.1091
.20	.0396	.0178	.1313	.0732			.2630	.1169	.2640	.184			.2168	.0948
.25			.0745	.0845	.2644	.1087	.2603	.1145	.2519	.151	.2565	.1162	.2186	.0889
.30	.0733	.0098					.2608	.1050	.2517	.180	.2617	.1180	.2066	.0859
.40									.0891	.0136	.2507	.1052	.2007	.0778
.50	.0359	.0221	.0361	.0284	.0535	.0086	.0567	.0092	.0612	.0056	.0803	.0037	.1775	.0529
.60	.0277						.0512	.0171	.0530	.0103	.0323	.0237	.0239	.0423
.70					.0366	.0219	.0027	.0408	.0394	.0429	.0382	.0497	.0431	.0412
.80	.0419	.0476	.0387	.0447	.0350	.0423	.0417	.0456	.0497	.0454	.0495	.0454		
.90		.0464	.0507	.0448	.0449	.0416	.0479	.0435	.0497	.0431	.0503	.0436	.0163	.0537
.95	.0412		.0502	.0451	.0467	.0416	.0487	.0432	.0509	.0440	.0510	.0442	.0492	.0527

TAIL 2

138

TABLE XIII. - CONTINUED
(b) α = -2.30°

Cp at y/b of

TAIL 1

z/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.

Cp at y/b of

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.55 U.S.	0.55 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.

TABLE XIII.- CONTINUED
(c) α = -0.30°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0590	.0699	.3515	.3071	.1469	.2011	.1489	.2215		.580		.952		
.10	.0535	.0610	.1492	.1933	.1478	.1413		.2648	.532	.204	.515			
.15	.0595	.0712	.1718	.1951	.1468	.952	.511	.902	.674	.935	.542			
.20	.0610	.0652	.1365	.772	.945	.1001		.965		.903	.560			
.25	.0070	.0360			.621	.922	.1252		.600	.867		.203		
.30	.0090	.0673								.807	.1409	.865		
.40	.0098	.0653	.0065	.0915	.0175	.0017	.0023	.0334	.341	.537	.1413	.862		
.50			.0025	.0915	.0033	.0171	.0105	.0150			.0357	.0452		
.60	.0042	.0216	.0052	.0002	.0056	.0099	.0263	.0623	.0585	.200	.0055	.0163		.0536
.70	.0038	.0241	.0460	.0464	.0000	.0041	.0091	.0452	.0470	.0350	.0488	.0162	.0532	
.80	.0036	.0376	.0469	.0454	.0357		.0435	.0478	.0455	.0464	.0502	.0522		
.90	.0429	.0391	.0415	.0451	.0415	.0359	.0435	.0477	.0437	.0487	.0448	.0466		
.95	.0363	.0391	.0410	.0433			.0422	.0444		.0456	.0434	.0442		

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0608	.0742	.3221	.1782			.3111	.1585		.850	.2026	.2707	.1673	.610
.10	.0710	.0610					.1892	.1651	.905	.834			.1817	.593
.15					.1809	.1773	.1852	.1817	.895	.834			.634	.566
.20	.0694	.0638					.844	.776	.927	.787			.582	.485
.25	.0150	.0112	.0736	.1330	.1799	.725	.1842	.745	.943	.767	.1838	.1751	.1485	.350
.30			.0282	.0275			.1797	.525	.831	.1735	.1875	.1790	.140	.129
.40	.0165	.0019							.485	.0456	.1785	.1617	.115	.54
.50					.0231	.0134	.0209	.0163	.259	.0219	.0427	.0312	.229	.041
.60	.0230	.0045	.0016	.0035	.0072	.000	.0145	.0035	.187	.0144	.0042	.0071	.0405	.0425
.70					.0021	.0534	.0201	.0554	.386	.0410	.0455	.0494	.0414	.0415
.80	.0310	.0328	.0488	.0482	.0448	.0453	.0520	.0425	.451	.0414	.0532	.0472	.0477	.0417
.90	.0429	.0458	.0463	.0428	.0440	.0406	.0468	.0425	.449	.0410	.0468	.0417	.0443	.0438
.95			.0444	.0421	.0413	.0385	.0436	.0405			.0445	.0417		

140

TABLE VIII. - CONTINUED

(d) α = 1.71°

	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.57		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05			[illegible]	[illegible]	[illegible]	.2383	[illegible]	[illegible]		.1994			[illegible]	[illegible]
.10	[illegible]	[illegible]	[illegible]	[illegible]	.1186	[illegible]		[illegible]	[illegible]	.2487	[illegible]	.2230	[illegible]	[illegible]
.15	[illegible]	[illegible]	[illegible]	.2288	[illegible]	[illegible]			[illegible]	.2355			[illegible]	[illegible]
.20	[illegible]	[illegible]	[illegible]	.2227	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	.1243	[illegible]	[illegible]	[illegible]
.25	[illegible]	[illegible]			[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	.2236	.1223	[illegible]	[illegible]	[illegible]
.30	[illegible]	[illegible]							[illegible]	[illegible]	.1201	[illegible]	[illegible]	[illegible]
.40	-.0088	[illegible]	[illegible]	.0362	.0025	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	.1137	[illegible]	[illegible]	[illegible]
.50			[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]			.0209	[illegible]	[illegible]	[illegible]
.60					[illegible]	.0306	[illegible]	[illegible]	[illegible]	.0392	-.0068	[illegible]	-.0462	[illegible]
.70	-.0032	[illegible]	[illegible]	.0157	-.0137	.0238	-.0202	[illegible]	[illegible]	-.0271	-.0526	[illegible]	[illegible]	[illegible]
.80	-.0383	-.0229	[illegible]	-.0404			-.0457	-.0423	-.0450	-.0443	-.0475	[illegible]	[illegible]	[illegible]
.90	[illegible]	[illegible]	[illegible]	-.0483	-.0348	-.0357	-.0425	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]		
.95	-.0430	-.0399	-.0407	-.0462			[illegible]	[illegible]	[illegible]	-.0489	[illegible]	-.0488		-.0473

TAIL 1

	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.57		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0456	.0691	.1400	.2164			.1479	.1865			.1711	.1977	.1395	.1854
.10	.0515	.0581					.1530	.2208	.1551	.2157			.1513	.2007
.15					.1430	.2150	.1481	.2167	.1537	.2169			.1414	.1916
.20	.0464	.0621					.1463	.2124	.1471	.2124			.1303	.1786
.25	.0358	[illegible]	.1451	.1649	.1413	.2094	.1465	.2095	.1481	.2107	.1492	.2106	.1223	.1644
.30			.0372	.0450			.1422	.1958	.1471	.2071	.1520	.2145	.1154	.1560
.40	.0082	.0099							.0293	.0641	.1436	.1366	.1162	.1434
.50					.0066	.0304	.0048	.0327	.0099	.0387	.0260	.0455	.0970	.1068
.60	.0179	.0209	-.0121	.0014			-.0012	.0266	.0038	.0308	-.0094	.0023	-.0441	-.0335
.70					-.0080	.0165	-.0305	-.0152	-.0447	-.0364	-.0510	-.0452	-.0467	-.0418
.80	-.0298	-.0251	-.0488	-.0477	-.0442	-.0423	-.0491	-.0470			-.0481	-.0491		
.90	-.0415	-.0406	-.0454	-.0443	-.0412	-.0447	-.0439	-.0476	-.0434	-.0448	-.0438	-.0445	-.0420	-.0429
.95			-.0446	-.0432	-.0402	-.0404	-.0429	-.0432	-.0436	-.0425	-.0434	-.0425	-.0437	-.0460

TAIL 2

TABLE XIII.- CONTINUED
(e) α = 3.70°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.0904	.2077	.0968	.2175	.0990	.3060		.2320	.089	.2513		
		.1551	.0851	.2163	.0921	.2717		.2895	.065	.2894	.052			
		.1660	.0895	.2095	.0889	.2093		.2650	.0865	.2555				
	.0358	.156	.0751	.2018	.0851	.2407	.1155	.2565	.0862	.2905	.0945			
	.065	.0319			.031	.2210	.089	.2765	.0613	.2695	.0942			
	.0207	.0381	.0151	.0501	.03	.0112	.0050	.0727	.0895	.2685	.0954			
	.029	.0400	.055	.038	.18	.0306	.05	.0586	.090	.0304	.0842			
											.065			
	.065	.0445	.028	.036	.030	.0500	.0095	.0548	.072	.0605	.079			
	.0410	.0155	.0407	.036	.0226	.0453	.030	.0202	.0598	.0333	.52	.0339		
	.0434	.0357	.0443	.0403	.0319		.0448	.036	.0452	.0394	.0476	.0463		
	.0434	.0361	.0447	.0451		.0349	.043	.0437	.0452	.0463	.0461	.0463		
							.0434	.0453	.0434	.0315	.0453	.0468		

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0367	.0489	.0912	.2686			.1147	.2177			.1417	.2248	.130	.2119
	.013	.0432					.117	.2579	.210	.2500	.250		.250	.2334
					.1090	.0530	.1120	.2550	.188	.2535	.05		.05	.2245
	.0358	.0401	.0177	.0910	.009	.2497	.101	.2517	.120	.2493	.169	.2457	.055	2.35
	.055	.020	.0154	.0588			.093	.2181	.122	.2486	.187	.2493	.055	.959
	.0061						.1056	.2328	.110	.2440	.05	.237	.0905	.1867
		.0178			.0086	.0392	.097	.2553	.010	.0840	.085	.0502	.003	.178
	.0095	.0319	.0189	.0124	.0166	.0478	.0166	.0478	.0057	.059	.0205	.016	.022	.327
					.0219	.0365	.0404	.0024	.0104	.0511	.0503	.0381	.0489	.0354
	.0308	.0190	.0507	.0122	.0402	.0511	.0411	.0399	.0483	.0291	.0455	.0417	.035	.0338
	.0459	.0344	.0472	.0185	.035	.0561	.0428	.045	.030	.045	.033	.050	.039	.045
			.0458	.0437	.0403	.0428	.0427	.0451	.033	.0435	.037	.0450	.047	.0452

TABLE XIII.- CONTINUED
(I) α = 5.70°

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.57		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0036	.0382	.0639	.2506	.081	.3217	.081.2	.3566		.3629	.0893	.3465		.2752
.10	.05.2	.2271	.0565	.3045	.072.2	.2055		.338.	.3675	.3366				.326.
.15			.0499	.3501	.0678	.3314			.287.	.312.			.0807	.301.
.20	.0548	.0380	.466	.2650	.0629	.3048	.0929	.3045	.359	.3145	.0851	.3298	.0654	.290.
.25	.0055	.0153			.3066	.3060	.2687	.3289	.343	.3194	.0927	.3301	.0654	.2751
.30			.0063	.3305					.722	.3.87	.0806	.3254	.0625	.2565
.40	.0043	.0238	.0254	.3715	.3217		.0134	.0876	.068	.12.8	.0746	.3087	.230	.2405
.50					.3301	.0839	.0256	.0840			.0005	.1139	.0531	.213.
.60	.0015	.0315	.0366	.0655	.0335	.0773	.0020.	.0660	.3244	.3802	.0250	.3753	.0467	.0267
.70	.0315	.0672	.0373	.0667	.0375	.0707	.0374	.0400	.35.8	.3091	.0522	.0222	.0515	.0328
.80	.0457	.0060	.0421	.0638			.0456	.0266	.3136	.3330	.0489	.3369	.055.4	.0419
.90	.0432	.0284	.0421	.0349	.0360	.0292	.0443	.0360	.3164	.3394	.0477	.0419		
.95	.0433	.0286	.0428	.0385	.0411		.0411	.0389	.0452	.3417	.0476	.0439		.0429

TAIL 2

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0336		.0355	.2855			.0788	.2539	.863	.2899	.105	.2550	.0850	.2405
.10	.05.2						.0760	.2896	.3625	.2946	.0927		.0927	.2699
.15					.061.5	.3040	.0737	.3006	.3761	.2946			.0845	.2538
.20	.0548	.0380					.0713	.2964	.2750	.2927	.0832	.2816	.0755	.2453
.25	.0055	.0153	.0063		.0556	.1629	.070.	.2920	.3743	.2907	.0836	.2837	.0621	.2307
.30			.0254	.0715			.0667	.2739	.3073	.2842	.0763	.2694	.0657	.2285
.40	.0043	.0238							.3073	.1092	.0078		.0643	.2123
.50					.3230	.0676	.0248	.3775	.2208	.3856	.0315	.0753	.464	.163.
.60	.0015	.0315	.0231	.0251			.0322	.0700	.3243	.077.	.0315	.355.	.35.0	.05.
.70					.0339	.047.	.0482	.0.3.	.3.8.	.3191	.0467	.0282	.0452	.0379
.80	.0403	.0138	.0524	.0308	.0419	.031.	.0456	.0328			.0463	.0359		
.90	.0166	.0326	.0488	.0466	.0432	.0426	.0451	.0420	.3452	.0392	.0348	.0393	.035.1	.0373
.95			.0477	.0780	.0.33	.0438	.0446	.0420	.0453	.0415	.0452	.0412	.0455	.0421

143

TABLE XIII.- CONTINUED
(g) α = 7.70°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05		.0439	.0583	.3139	.0775	.3773	.0762	.4202		3.29	.0846			
		.2437	.0494	.3936	.0685	.3675		.3955	.0831	.3955				
		.2703	.0410	.3817	.0630	.3937			.0753	.389				
		.0500	.0373	.3804	.0577	.3919	.0799	.3562	.0707	.3780	.0795	.3864		
		.0789			.0550	.3879	.0637	.3847	.0688	.3810	.0770	.3828		
		.0990							.0660	.3779	.0747	.3638		
		.0999	-.0330	.0563	-.0663	.2893	-.0473	.2283	-.3110	.5990	.0687	.3633		
			-.0413	.0665	-.0350	.1136	-.0294	.1151			-.0042	.1459		
		.0954			-.0385	.1077	-.0032	.0850	-.0294	.1103	-.0291	.0956		
		.0068	-.0399	.0876	-.0423	.0657	-.0415	.0657	-.0534	.0048	-.0525	-.0103		
		.0188	-.0430	-.0057		.0107	-.0463	-.0140	-.0438	-.0234	-.0497	-.0227		
		.0183	-.0432	-.0242	-.0372	-.0263	-.0453	-.0243	-.0471	-.0291	-.0488	-.0334		
			-.0438	-.0285			-.0462	-.0281	-.0470	-.0321	-.0488	-.0356		-.0368

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0195	.0439	.0190	.2168			.0394	.2948			.0804	.2933		.2725
	.0353	.0257					.0377	.3472	.0492	.3357				.3058
					.0159	.3329	.0328	.3476	.0440	.3420				.2982
	.0449	.0237	-.0241	.1874	.0095	.3065	.0285	.3384	.0377	.3401	.0505	.3213		.2829
	.0017	-.0006	-.0375	.0649			.0261	.3307	.0364	.3375	.0435	.3293		.2763
	.0033	.0241					.0238	.3083	.0350	.3284	.0431	.2958		.2664
			-.0375	.0293	-.0348	.0788	-.0395	.0927	-.0256	.1400	-.0231	.1117		.2549
	.0019	.0261			-.0432	.0564	-.0468	.0835	-.0365	.0999	-.0421	.0701		.2002
			-.0581	-.0291	-.0473	-.0258	-.0529	.020	-.0388	.0099	-.0528	-.0123		.0156
	.0435	.0246	-.0557	-.0434	-.0494	-.0382	-.0515	-.0265	-.0187	-.0090	-.0513	-.0222		-.0339
	.0557	.0372	-.0549	-.0470	-.0488	-.0410	-.0513	-.0349	-.0494	-.0335	-.0497	-.0260	-.0457	-.0387
							-.0512	-.0382	-.0503	-.0361	-.0503	-.0336		-.0454

TABLE II. - CONTINUED
(b) M = 0.70°

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.93	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

TABLE XIII.- CONTINUED
(i) α = 11.55°

Cp at y/b of

	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
					.0835	.5217	.0835	.5835		.4437				
					.0730	.5429		.5619	.0925	.5191	.0855			
					.0720	.5545			.0833	.5282				
					.0660	.5517	.0714	.5099	.0782	.5309	.0833			
					.0626	.5470	.0700	.5351	.0759	.5339	.0809			
					-.0251	.2059	-.0142	.2085	-.0527	.3307	.0779			
					-.0314	.1938	-.0271	.1919		.2160	-.0723			
					-.0373	.1882	-.0065	.1583	-.0553	.863	-.0308			
					-.0415	.813	-.0406	.1352	-.2719	.2470	-.0461			
					-.0351		-.0421	.0237	-.2514	.2247	-.0462			-.0655	
							-.0421	.0102	-.2444	.0086	-.0461			-.0062	
							-.0423	.0053	-.2445	.0039	-.0460				

TAIL 1

Cp at y/b of

	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
		.2235	-.0014	.0326			-.0231	.3381						.3400
		.0082					-.0272	.3771	-.0190	.3872	.0127	.3614	-.0085	.3843
					-.0322	.3142	-.0317	.3611	-.2222	.3897			-.0055	.3920
		.3030	-.0318	.1452	-.0413	.2926	-.0355	.3403	-.2314	.3813			-.0090	.3720
		.0253	-.0313	.0178			-.0368	.3333	-.3536	.3708	-.0148	.3796	-.0115	.3636
		.0094					-.0365	.3027	-.3547	.3552	-.0200	.3865	-.0129	.3556
					-.0495	.0858	-.0592	.1055	-.0582	.1513	-.0257	.3497	-.3531	.3370
		.2241	-.0498	.0258			-.0654	.0972	-.2615	.1282	-.0534	.1620	-.0714	.2729
		.3321	-.0702	.0298	-.0531	.0735	-.0630	.0252	-.3556	.1162	-.0662	.0568	-.0650	.0125
		.0453	-.0530	.0465	-.0622	.0165	-.0657	.0183	-.3528	.0010	-.0657	.0063	-.0663	-.0196
					-.0614	.0308	-.0662		-.2529	-.0240	-.0630	.0137	-.057	-.0248
			-.0582	.0457	-.0640	.0349	-.0662	.0305	-.636	-.0267	-.0643	.0178	-.063	-.0320

TAIL 2

TABLE XIII - CONTINUED
(i) α = 15.75°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0000	-1.789	.0950	.7051		.7218	.1039	.7992		.621		.7056	.1340	.6262
.10	-.0070	-.0390	.0823	.7752		.764		.730	.26	.7574	.062			.709
.15	-.0070	-.5615		.760						.636		.766		.660
.20	-.0035	-.5380	.002			.678	.0830	.6850		.744	.000	.7530		
.25	-.0000	-.220				.53	.0906	.460		.700	.063	.7530		
.30	-.0394	-.2260	-.0006	.6313	-.0178	.3110	-.0059	.320		.500	.0340	.7372	.058	.735
.40	-.0394	-.2720	-.0378	.255	-.0253	.3019	-.0217	.3065	.076	.3576	.0872	.7172	.0955	.605
.50					-.021	.2921	-.0065	.2965	.222	.2980	.0030	.3426	.035	.509
.60					-.0365	.2868	-.0367	.2341	.262	.1079	-.0230	.271	.0400	.347
.70	-.0316	-.2616	-.0353	.2449			-.0377	.0770	-.0372	.0658	-.0417	.0517	-.0515	.0347
.80	-.0367	-.3044	-.036	.0918			-.0377	.0658	-.0361	.5639	-.0405	.0401	-.0610	.0317
.90	-.0383	-.0549	-.0358	.0523	-.0326	.0529	-.0383	.0537	-.0395	.0542	-.0401	.0339		
.95	-.0421	-.0732	-.0356	.0472							-.0402	.0187		

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.55 U.S.	0.55 L.S.	0.67 U.S.	0.67 L.S.	0.33 U.S.	0.33 L.S.	0.93 U.S.	0.93 L.S.
.05	-.0162	.0016	-.0300	.2381			-.0112	.0669	-.0302	.3679	-.0149	.4593	-.0301	.3420
.10	-.0050	-.0098					-.0446	.3813	-.0149	.3634	-.0211		-.0241	.3023
.15					.0329	.3125	-.0457	.3593	-.0199	.3578	-.0303		-.0363	.3331
.20		-.0097					-.0496	.3393		.3578	-.0355		-.0305	
.25	-.0021	-.0255	-.0240	.2052	-.0540	.2906	-.0510	.3244	-.0510	.356	-.043	.3737	-.0730	.3008
.30	-.0179	-.0951	-.054	.023			-.0519	.3003	-.0500	.3038	-.046	.3734	-.0498	.3714
.40					-.0525	.0973	-.0522		-.0650	.1184	-.0466	.3691	-.0949	.3441
.50	-.125	.013	-.052	.0770			-.0682		-.0537	.356	-.0623	.1523		
.60					-.0555	.561	-.0575		-.0535	.325	-.0565	.565		
.70	-.505				-.0555	.0060	-.0766	.400	-.0490	.5339	-.060			
.80	-.563				-.0535	.0004	-.0668	.3944	-.057		-.0683	.3455		
.90					-.0515	.037	-.0669	.3040	-.057	.39	-.0603	.3071		

TAIL 2

TABLE XIII.- CONCLUDED
(K) β = 10.00°

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	-.0195	.0525	.0260	.0531	.0661	.0921	.1270	.0799	.0712	.9476	.0217	.0361	.0214	.5841
.10	-.0257	.0565	.0471	.0472	.0567	.0522		.0498	-.0125	.0208	.0017		.0650	
.15	-.0270	.7203	.0327	.0543	.0255	.0637			-.0215	.0017	.0215	.0592	.0037	.0565
.20	-.0183	.7356	.0313	.081	.1124	.0432	.1044	.0484	.0194	.0164	.1036	.0652	.0018	.6576
.25	-.0232	.5279				.0239	.1173	.0337	.0815	.0542	.1037	.0932	.0078	.2361
.30	-.0267	.0317	-.0268	.0613	-.006	.4484	.0062	-.055	-.0093	.5096	.0027	.0232	.0018	.5891
.40		.0617	-.0305	.3862	-.067	.4327	-.0104	.4481			.0012	.4360	.0118	
.50					-.067	.3956	-.0029	.3538	-.0334	.1411	-.0085	.3236	-.015	
.60		.3850	-.0286	.3616	-.0257	.4221	-.0284	.3611	-.0334	.1872	-.0312	.1036	-.0118	.0720
.70	-.0285	.649	-.0378	.485			-.0288	.1439	-.0294	.398	-.0308	.0832	-.0363	.0843
.80	-.0344	.1226	-.0270	.143	-.0263	.1135	-.0296	.1246	-.0299	.3303	-.0312	.0747		
.90	-.0363	.1549	-.0269	.0883			-.0291	.1170	-.0304	.1216	-.0307	.0657		.0802
.95														

TAIL 2

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	-.0281	-.0063	-.0413	.0022			-.0555	.4030	-.0496	.4080	-.0299	.4876	-.0504	.5050
.10	-.0225	-.0202			-.0501	.3265	-.0578	.3871	-.0583	.3962			-.0473	.4724
.15							-.0583	.3691	-.0610	.3853			-.0490	.4491
.20	-.0201	-.0069	-.0531	.3017	-.0629	.3027	-.0601	.3458	-.0628	.3675	-.0484	.3924	-.0510	.429
.25	-.0418	-.0033	-.0594	.347			-.0608	.3335	-.0615	.3500	-.0559	.3629	-.0540	.1137
.30							-.0610	.307?	-.0615	.1671	-.0581	.3237	-.0570	.3952
.40	-.0290	.0029							-.0595		-.0670		-.0585	.3538
.50	-.0356	-.0034	-.0554	.482	-.0543	.1221	-.0629	.384	-.0656	.1581	-.0678	.1677	-.0601	.2867
.60					-.0618	.1227	-.0698	.1334	-.0630	.500	-.0692	.1175	-.0654	.0208
.70	-.0551	.0112	-.0742	.0155	-.0675	.0114	-.0692	.0569	-.0602	.0225	-.0552	.0294	-.0634	.0129
.80					-.0702	-.0029	-.0729	.0086	-.0673	.0002	-.0677	.0168	-.0598	.0051
.90	-.0594	-.0535	-.0735	-.0229	-.0694	-.0074	-.0719	.0009	-.0692	-.0031	-.0901	.0108	-.0678	-.0011
.95							-.0718	-.0024				.0058		

TABLE XIV.- PRESSURE COEFFICIENTS, β = 67.5°, δ = 0°, M = 3.70

(a) α = -4.25°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05		.0380	.2520	.0602	.2235		.2218	.1285		.2865				.0945
.10			.2504	.0805	.2389			.2353	.2408		.2323	.29		
.20		.0306	.2413	.081.9	.2410	.0006								
.25		.2052	.2332	.0905	.2405						.2295			.0490
.30		.0076			.2270	.0890			.2408		.2366			
.40		.0035					.0716	-.0020			.2352			
.50		.0074	.0515	-.0108	.0656		.0535		.2261		.2275	.1024		.0711
.60			.0376	-.0125	.0573		.0050				.0184	.0048		
.70	.0283	.0025	.0316	-.0184	.0526	-.0132	.0313	-.0172	.0545	-.0082	.0454			
.80	.0288	-.0194	-.0315	-.0408	.0445		-.0313	-.0172	-.0421	-.0186	-.0347	-.0380	.0442	-.0408
.90	-.0305	-.0277	-.0440	-.0378	-.0351	-.0134	-.0358	-.0359	-.0482	-.0303	-.0446	-.0372	.0464	
.95	-.0311	-.0288	-.0458	-.0381			-.0427	-.0359	-.0492	-.0305	-.0475	-.0372		
							-.0449	-.0359			-.0487	-.0368		-.0398

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1202	.0799	.2360	.1496			.2217	.1357			.2330	.1502	.2061	.1462
.10	.1275	.0532					.2343	.1562	.2374	.1589			.2232	.1495
.20					.2300	.1464	.2319	.1513	.2375	.1566			.2073	.1395
.25	.1323	.0557	.1109	.1053	.2301	.1411	.2325	.1477	.2311	.1521	.2289	.1484	.1850	.1250
.30	.0265	-.0074	.0552	.0112			.2335	.1458	.2327	.1506	.2342	.1508	.1868	.1156
.40							.2289	.1353	.2316	.1470	.2243	.1367	.1828	.1122
.50	-.0048	-.0060			.0332	-.0012	.0391	.0016	.0745	.0300	.0631	.0171	.1795	.1025
.60	.0112	-.0193	.0185	-.0220			.0335	-.0053	.0453	.0070	.0185	-.0164	.1565	.0756
.70					.0218	-.0127	-.009	-.0352	.0375	.0015	-.0419	-.0525	-.0336	-.0393
.80	.0361	-.0467	-.0459	-.0469	-.0414	-.0456	-.0479	-.0486	-.0407	-.0448	-.0509	-.0481	-.0422	-.0433
.90	.0456	-.0466	-.0529	-.0445	-.0508	-.0424	-.0525	-.0437	-.0530	-.0457	-.0512	-.0450	-.0431	-.0529
.95			-.0483	-.0446	-.0490	-.0422	-.0486	-.0427	-.0510	-.0457	-.0483	-.0443	-.045	-.059

TAIL 2

149

TABLE XIV.- CONTINUED
(b) τ = -2.25°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
			.203	.969	.99	.60	.94	.727	.85	.93	.90			
	.55	.56	.56	.76	.65	.41		.65	.56	.63	.95			
.74	.481	.68	.97	.55	.58			.31	.516	.49			
.793	.45	.85		.66	.59	.86	.2006	.928	.477	.49	.56		
.196	.054			.18		.198	.510	.902	.458	.828	.55		
.229	.059	.998	.58			.463	.116	.802	.434	.833	.58		
.277	.057	.94	.16			.935	.006	.585	.0332	.587	.29		
.0183	.006	.621	.013	.015	.005	.107	.968	.298	.013	.250	.20		
.0301	.057	.0398	.082	.05	.043	.0429	.089	.363	.024	.0395	.050	.43	.5
.0318	.053	.0462	.028	.0361	.428	.0474	.0466	.9430	.0420	.0489	.045	.49	.33
.034	.067	.0434	.025	.0367	.425	.0453	.046	.9463	.0427	.0460	.043	.9450

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0871	.0832	.2070	.631			.2004	.464	.2129	.1729	.2230	.1625	.195	.1545
.10	.0946	.0632			.2035	.1599	.2113	.1701	.2123	.1692			.2008	.1572
.15							.2251	.650	.2064	.1638			.1869	.1460
.20	.0963	.0639	.0887		.203		.2079	.1614			.2052	.1583	.129	.343
.25	.0196	.0043	.0416	.19		.155	.2084	.1590	.2075	.1624	.2102	.165	.1552	.1250
.30				.0254			.2035	.1489	.2066	.1589	.2004		.1554	.1175
.40	.0139	.0004							.0603	.0374	.204	.1171	.1561	.1073
.50			.0103	.0135	.030C	.0073	.0361	.0086	.0357	.0143	.0540	.0239	.372	.0767
.60	.0216	.0067					.0239	.0015	.0279	.0075	.0123	.012	.0735	.0400
.70			.0463	.0052	.0174	.0056	.0242	.0304	.0365	.0428	.0425	.0508	.042	.0944
.80	.0338	.0402	.0478	.014	.0425	.0454	.0453	.0417	.0485	.0414	.0517	.0519	.0413	.0315
.95	.0468	.0453	.0445	.0417	.0226	.0385	.0454	.0406	.0457	.0416	.0451	.0425	.043	.0455

TAIL 2

TABLE XIV.- CONTINUED
(c) α = -0.25°

Cp at y/b of

	0.02		0.22		0.44		0.55		0.67		0.83		0.96	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 1

Cp at y/b of

	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

TABLE XIV - CONTINUED
(d) α = 1.76°

TAIL 1

	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0365	.0858	.1111	.1977	.1133	.2455				.1855				
.10	.0368	.1075		.2385	.1501					.2578		.2351		
.15					.1074					.2431				
.20	.0666	.0168		.0365	.0521					.2452		.2455		
.25									.1083	.2381		.2322		
.30	.0151	.0224		.0242		.0574		.0585	.0179	.0878	.0250	.0638		
.40					.0139	.0351								
.50	.0077	.0276	.0197	.0193	.0182	.0287		.0243	.0091	.0436	.0531	.0330		
.60	.0358	.0201	.0436	.0388					.0479	.0243	.0534	.0387	.0535	
.70	.0405	.0368	.0307	.0471	.0359	.0359			.0437	.0428	.0424	.0486	.0474	
.80	.0424	.0378	.0304	.0340					.0445	.0431	.0415	.0496		
.90									.0438	.0484	.0345	.0436	.0453	

TAIL 2

	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0520	.0732	.1556	.1992			.1617	.1722	.1707	.2022	.1832	.1863	.1541	.1750
.10	.0583	.0553					.1680	.2038	.1700	.2013			.1687	.825
.15					.1583	.1963	.1655	.1937					.1578	.805
.20	.0538	.0563					.1622	.1957	.1633	.1969			.1468	.67
.25	.0685	.0125	.0585	.1493	.1570	.1918	.1622	.1928	.1644	.1855	.1652	.1958	.1372	.543
.30			.0165	.0365			.1584	.1799	.1630	.1916	.1680	.1999	.1315	.453
.40	.0082	.0127					.2122	.0259	.0387	.0558	.1529	.1827	.1319	.1326
.50					.0133	.0245	.0681	.0194	.2174	.0313	.0310	.0415	.1110	.0093
.60	.0205	.0224	.0084	.0021	.0022	.0108	.3258	.0194	.009	.0241	.0223	.0017	.0407	.0410
.70	.0307	.0253	.0497	.0491	.0467	.0494	.0545	.0493	.0424	.0375	.0473	.0472	.0438	.0429
.80	.0422	.0415	.0450	.0463	.0456	.0437		.0457	.0436	.0436	.0467	.0439	.0388	.0423
.90	.0424	.0378	.0446	.0427	.0490	.0358	.0424	.0420	.042	.045	.0417	.0413	.0420	.0416

TABLE XIV - CONTINUED

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.57		0.63	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1313		.0594	.1995			.1142	.2110			.392	.2.64		

TAIL 2

TABLE XIV - CONTINUED

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

TABLE XIV - CONTINUED
(i) α = 11.75°

Cp at y/b of

TAIL 1

x/c	0.02		0.22		0.44		0.56		0.57		0.33		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05														
							.0345	.58_						
							.013_	.587_						
						-.0353	.255_							
						-.0482	.335_							
						-.0149	.088_							
						-.0540	.170_				.1533			
	-.0620		-.0530	.042_	-.0543	.0178			-.0574	.0267			
	-.0235		-.0530	.0163	-.0542	.0265			.0251		-.0360		-.0360	
.95	-.0356		-.0532	.0131	-.0543	.0223					-.0573		-.0549	

TAIL 2

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.11_	-.20_3	.2138	-.0279			-.0251	.2481			.3525	.2975	.0485	
	.30_2	-.0490					-.0265	.2484	.0055	.3378			.0512	
.5	.10_				-.0298	.0755	-.0244	.2236	.005_	.33_9			.0477	
.25	.01_	-.0200	-.0124	-.0231	-.0268	.0828	-.0209	.2072	-.0055	.313_	.0275	.312_	.042_	
.3		-.047_	-.0252	-.0399			-.0180	.1991	-.0077	.294_	-.0360	.3_14	.0357	
	-.0012	-.011_					-.0189	.1847	-.0077	.276_	-.0235	.299_	.0261	
.16		-.0272	-.0293		-.0367	.0185	-.0413	.0520	-.0453	.291_	-.0331	.112_	.0327	
				-.0350	-.0450	.010_	-.0459	.0444	-.0452	.251_	-.0488	.0611	.0260	
.70	-.0428	-.0518	-.0622	-.0601	-.061_	-.0408	-.0568	-.0028	-.0453	.263_	-.0558	.0149	.0596	
.90	.633	-.0605	-.068	-.063_	-.066_	-.0492	-.0623	-.0357	-.0545	.170	-.0559	-.0297	.0539	
							-.0592	-.0415	-.0549	-.0377	-.0551	-.0360	-.0497	-.0355
.95			-.0640	-.0615	-.0535	-.0508	-.0585	-.0439	-.0555	-.0404	-.0562	-.0400	-.0549	-.0425

157

TABLE XIV. - CONTINUED
(i) τ = 15.75°

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 1

Cp at y/b cf

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

TABLE XIV.- CONCLUDED
(k) α = 13.75°

Cp at y/b of

TAIL 1

x/c	0.02		0.22		0.44		0.55		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

Cp at y/b of

TAIL 2

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

159

TABLE XV. - PRESSURE COEFFICIENTS, $\Phi = 40°$, $\delta = 0°$, M = 3.70

(a) $\alpha = 4.20°$

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.38	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

160

TABLE XV.- CONTINUED
(b) α = -2.20°

Cp at y/b of

TAIL 1

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0852	.0446	.2083	.0955	.1903	.1584	.1904	.1712		.159	.135.		.252	.39.
.10	.0855	.0739	.2075	.1347	.1554	.170.		.355	.0655	.0641		.0.7		.323
.15	.0856	.0435	.200.	.165.	.156.	.156.			.650	.15.	.0.5.		.55.	.5.
.20	.0866	.0425	.0939	.1058	.158.	.143.	.2146	.145	.655	.142	.065	.534		.99.
.25	.0254	.208.			.1933	.141.		.135	.057.		.052	.150		.6.
.30	.0650	.010.							.357.	.336	.343	.465		.5.
.40	.0307	.0151	.0348	.0671	.2136	.0066	.0451	.3091	.620	.295	.182	.135		.5.
.50			.2243	.0155	.0553	.0053	.0363	.0051			.3.3	.0.0		.5.
.60					.0312	.0112	.0604	.0311	.3.8	.0051	.0278	.0010		.0.8
.70	.0229	.3042	.0155	.0276	.0656	.0172	.0145	.025.	.06.	.0.50	.0.74	.0312	.071.	.055.
.80	.0281	.0294	.0356	.0488			.0380	.0489	.0375	.0437	.0450	.0455		.055.
.90	.0308	.0364	.0434	.0435	.0287	.0332	.0433	.0418	.0451	.0452	.0435	.0453		.5.
.95	.0315	.0416	.0404	.0425			.0418	.0438	.0.50	.0415	.0.38	.0449		.41.

Cp at y/b of

TAIL 2

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0757	.1058	.1854	.1942			.1833	.1625	.1835	.1813	.2090	.806	.739	.171.
.10	.082.	.0739					.1920	.195.	.1827	.1380	.182.		.185.	.17.
.15					.1836	.1858	.1979	.648	.852	.826				.1634
.20	.081.	.0792					.272	.827	.325	.812	.972	.1795	.524	.151.
.25	.011.	.015.	.0777	.1338	.1827	.157.	.1380	.785	.854	.774	.1817	.1822	.550	.1.1.
.30			.0295	.0337			.836	.1675		.1.55	.1834	.1664	.17.	.1332
.40	.0273	.021.					.3011	.0178	.051.	.1.55	.1664	.0.04	.1.3.	.29.
.50	.011.	.0062	.3011	.0082	.0225	.0177	.113.	.0006	.2267	.2210	.0108	.0357	.0.10	.3.
.60					.3053	.0093	.0138	.0235	.0.93	.0163	.0053	.0.7	.0.50	.3.
.70	.055.	.0347	.0476	.0456	.0443	.0445	.0507	.0489	.0366	.0342	.0436	.0436	.0.58	.335.
.80	.045.	.0447	.0428	.038.	.0428	.0399	.0443	.0406	.0423	.0399	.0506	.0451		
.90									.0490		.0490	.0379	.0311	.035.
.95	.0456	.0.7.	.0420	.0389	.0394	.0368	.0415	.0382	.410	.0375	.0415	.0378	.0457	.0.66

TABLE XV. - CONTINUED
(c) a = -0.20°

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0605	.0889	.1822	.1735			.1799	.1584	.1904	.1881	.0227	.284	.1686	.1629
.10	.0682	.0643					.188	.1866	.1898	.1852			.1855	.1733
.15					.1830	.1777	.187	.1820	.1829	.1805			.1727	.1623
.20	.0573	.0654	.0730	.1345	.1790	.733	.193	.1780	.1945	.1795	.385	.79	.153	.527
.25	.0127	.0158	.0286	.0305			.19	.1631	.1833	.755	.35	.825	.525	.385
.30							.1				.8	.8	.1451	.1318
.40	.008-	.0200	.0006	.0024	.0001	.0.62	.203	.0179	.0489	.0467	.433	.373	.14	.1202
.50	.0191	.0136			.0058	.062	.215	.0125	.0265	.0231	.5	.373	.1234	.284
.60	.0136		.0490	.0455	.0451	.0341	.0212	.0235	.0290	.0162	.415	.0354	.0270	.0394
.70	.0309	.0209	.0433	.0409	.0319	.0329	.0538	.0489	.0374	.0355	.0611	.0354	.0405	.0393
.80	.0424	.0437	.0431	.0365	.0391	.0363	.041	.0422	.0417	.0398	.528	.0392	.0422	.0322
.90	.0424						.0415	.0379	.0408	.0380	.1	.0389	.0417	.0405

TAIL 2

TABLE XV. - CONTINUED
(d) α = 1.81°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.1072	.1962	.1099	.2468	.1108	.2766		.1975			.1275	.2094
.10	.0375	.0851	.1030	.2329	.1065	.2455		.2535	.153	.2501		.2445	.135	.2500
.15	.0389	.0589	.0961	.2390	.1013	.2536	.150		.030	.2485			.103	.2374
.20	.0327	.0981	.0915	.2385	.0920	.2510	.377	.2222	.1051	.2468		.2503	.1055	.2254
.25	-.0032	.0173			.0887	.2470	.054	.2508	.060	.2440		.2508		.222
.30	-.0053	.0236			-.0002	.0606	.3045	.0622	.010	.2421		.2461		.220
.40	-.0059	.0238	-.0376	.0419	-.0075	.0449	-.0662	.0466	.010-6	.0877		.2350		.1822
.50			-.0150	.0246	-.0109	.0378	-.0298	.0362				.0715		.1538
.60	-.0010	.0294	-.0167	.0194	-.0155	.0313	-.3200	.0104	-.0061	.0460		.0343	-.0754	.0374
.70	-.0293	-.0181	-.0409	-.0379			-.0410	-.0391	-.0439	-.3222		.0371	-.0500	.0442
.80	-.0347	-.0347	-.0381	-.0466	-.0282	-.0346	-.0389	-.0448	-.0415	-.0476		-.0469	-.0459	.0477
.90	-.0369	-.0354	-.0378	-.0454			-.3389	-.0447	-.0409	-.0475		-.0483		
.95												-.0463		-.0447

Cp at y/b of

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0502	.0851	.1794	.1737			.1781	.1559			.1977	.1745	.1633	.1507
.10	.0584	.0589					.1857	.1841	.1873	.1842			.1869	.1732
.15		.0563			.1781	.1753	.1818	.1798	.1876	.820			.1754	.1538
.20	.0562	.0122	.0719	.1311			.1855	.175	.1809	.776	.193		.1627	.1524
.25	.0112		.0244	.0275	.1767	.1711	.1807	.1727	.1823	.1760	.1809	.1763	.1529	.1391
.30							.1763	.1602	.1809	.1722	.1777	.1635	.1483	.1306
.40	.0134	.0198							.0492	.0455			.1492	.1183
.50	.0241	.0167	.0229	-.0043	.0199	.0174	.0208	.0176	.0261	.0231	.0418	.0329	.1245	.0872
.60							.0149	.0106	.0188	.0166	.0545	.0056	.0385	.0405
.70	-.0292	-.0273	-.0484	-.0464	.0057	.0028	-.0198	-.0248	-.0382	-.0355	-.0413	-.0465	.0409	.0409
.80	-.0328	-.0400	-.0438	-.0410	-.0452	-.0452	-.0512	-.0496	-.0414	-.0389	-.0507	-.0444	.0399	.0391
.90			-.0430	-.0408	-.0421	-.0394	-.0441	-.0415	-.0409	-.0382	-.0423	-.0393	-.0399	-.0391
.95					-.0395	-.0373	-.0417	-.0389			-.0414	-.0383	-.0426	-.0407

163

TABLE XV.- CONTINUED
(a) α = 3.80°

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05			.0669	.2510	.0753	.2984	.0758	.3372		.2948				.2537
.10	.0142	.1205	.0606	.2948	.0688	.3067		.3161	.0801	.3154	.0810	.2987		.3020
.15	.0149	.1340	.0543	.3054	.0654	.3159	.1013		.0725	.3070				.2930
.20	.0115	.1257	.0516	.2974	.0625	.3113	.0675	.2712	.0694	.3056	.0757	.3056		.2816
.25	.0154	.0271			.0504	.3078		.3091	.0689	.3050	.0734	.3060		.2612
.30	.0181	.0396							.0670	.3022	.0715	.3023		.2452
.40	.0205	.0490	.0212	.0709	.0163	.0881	.0123	.0910	.0662	.1166	.0601	.2887		.2336
.50			.0274	.0529	.0246	.0716	.0221	.0768			.0026	.1617		.2624
.60	.0040	.0529	.0264	.0465	.0276	.0661	.0157	.0503	.0194	.0761	.0240	.0612	.0435	.2283
.70					.0313	.0601	.0323	.0359	.0451	.0097	.0457	.0268	.0425	.0395
.80	.0278	.0091	.0418	.0252			.0404	.0282	.0384	.0348	.0436	.0381	.0435	.0420
.90	.0333	.0285	.0404	.0396	.0296	.0305	.0397	.0373	.0422	.0411	.0429	.0417		
.95	.0359	.0293	.0405	.0420			.0398	.0397	.0422	.0426	.0430	.0433		.0413

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.57		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0574	.0944	.1764	.1692			.1758	.1538		.1810	.1931	.1740	.1660	.1560
.10	.0587	.0669					.1834	.1818	.1846	.1792			.1643	.1712
.15					.1770	.1736	.1733	.1778	.1853	.1792				.1639
.20	.0534	.0630			.1760		.1787	.1741	.1788	.1755	.1792	.1747	.1561	.1514
.25	.0637	.0601	.0727	.1314		.1638	.1787	.1709	.1793	.1736	.1833	.1782	.1580	.1371
.30			.0271	.0278			.1744	.1586	.1781	.1700	.1744	.1638	.1510	.1321
.40	.0053	.0170			.0203	.0167			.0505	.0441			.1450	.1229
.50	.0125	.0077	.0027	.0044			.0203	.0172	.0251	.0234	.0212	.0290	.1450	.0872
.60							.0154	.0103	.0165	.0167	.0055	.0069	.0525	.0414
.70	.0329	.0334	.0491	.0483	.0073	.0030	.0189	.0242	.0378	.0357	.0449	.0471	.0414	.0407
.80	.0437	.0452	.0446	.0424	.0453	.0453	.0513	.0503			.0509	.0447		
.90			.0435	.0419	.0435	.0408	.0451	.0420	.0417	.0398	.0428	.0389	.0333	.0380
.95					.0404	.0384	.0422	.0399	.0407	.0387	.0416	.0383	.0433	.0412

TAIL 2

TABLE XV. - CONTINUED

(f) α = 5.30°

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TABLE XV. - CONTINUED

(g) α = 7.90°

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.33		0.99	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

TABLE XV. - CONTINUED
(1) α = 11.80°

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			-.0355	.5303	-.0116	.7919		.9513						
.10	-.0503	.0868	-.0415	.6835	-.0231	.7647								
.15	-.0516	.2131	-.0453	.6374	-.0335									
.20	-.0516	.1859	-.0377	.5439	-.0324	.7743		.6857		.9888				
.25	-.0531	.0551			-.0380	.5683		.743		.7833				
.30	-.0556	.1103					-.0502			.6230				
.40	-.0585	.2142	-.0478	.2595	-.0555	.3012	-.0606	.3154		.6535				
.50			-.0539	.2486	-.0611	.2974		.3126						
.60					-.0624	.2845		.2455		.3252				
.70	-.0529	.2550	-.0580	.2429	-.0594	.2757		.2438	-.0591	.1205				
.80	-.0545	.0691	-.0580	.0947			-.0583	.3812	-.0524	.0787				
.90	-.0578	.0374	-.0592	.0690	-.0436	.0525	-.0584	.0613	-.0605	.0722				
.95	-.0559	.0545	-.0593	.0647			-.0587	.0530	-.0606	.0662				.0139

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0103	.0566	.0141	.0208			.0338	.0313			.777	.1418	.1615	.1472
.10	.0152	.0263					.0315	.0362	.0517	.0733			.1822	.1559
.15	.0028	.0153			.0155	.0231	.0298	.0345	.0480	.0526			.1730	.1553
.20	-.0375	-.0269	-.0256	-.0009	.0043	.0118	.0233	.0304	.0412	.0481	.487	.335	.1671	.1422
.25			-.0425	-.0338			.0205	.0274	.0316	.0403	.454	.373	.1512	.1326
.30	-.0344	-.0075					.0163	.0203	-.0276	-.0229	.291	.66	.1557	.1355
.50	-.0427	-.0353	-.0466	-.0416	-.0365	-.0334	-.0383	-.0358	-.0388	-.0360	.080	.0641	-.1342	-.0885
.70					-.0433	-.0472	-.0479	-.0463	-.0407	-.0383	-.0214	-.0245	-.0374	-.0432
.80	-.0581	-.0570	-.0694	-.0674	-.0659	-.0647	-.0574	-.0570	-.0493	-.0471	-.0554	-.0556	-.0424	-.0438
.90	-.0638	-.0633	-.0702	-.0684	-.0683	-.0662	-.0707	-.0690	-.0606	-.0588	-.0611	-.0592	-.0638	-.0452
.95			-.0693	-.0684	-.0664	-.0644	-.0683	-.0664	-.0615	-.0597	-.0535	-.0584	-.0505	-.0523

169

TABLE XV.- CONCLUDED

(k) α = 19.80°

TAIL 1

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TABLE XVI.- PRESSURE COEFFICIENTS, δ = 0°, δ₂,ᵢ = -15°, M = 1.50

(a) α = -3.36°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1724	.2048	.3061	.4613	.3835	.5475	.4372	.5804	.5656	.5833		.5629		
.10	.1783	.2310	.3758	.4036	.4206	.4826				.5632			.5572	
.15	.1543	.1854	.2780	.3525	.3725	.3952				.4804	.3550		.3249	.4086
.20	.1035	.1648	.2630	.3157	.3348	.3931	.3453	.4175	.3552	.4543	.3685	.4886	.2508	
.25					.3033	.3465	.3657	.3873	.3326	.4246	.3539			.2603
.30	.0120	-.0295									.3647	.4338		.2283
.40	.0272	.0446	-.0200	-.1242	-.0943	-.0924	-.0884	-.0846	-.3003	.3845	.2980	.3384	.0635	.0930
.50			-.0799	-.0925	-.0694	-.0924	-.0995	-.0691	-.0997	-.0861	-.0445	-.3601		
.60					-.0819	-.0825	-.0816	-.0765			-.1360	-.1360	-.3128	.3128
.70	-.0227	-.0757	-.0556	-.0431	-.0733	-.0927	-.0955	-.1499	-.2928	-.3035	-.3083	-.3255	-.2852	.3085
.80	-.2411	-.2427	-.2862	-.2790			-.2882	-.3041	-.2993	-.3076	-.3204	-.2958	-.2514	.2692
.90	-.2558	-.2837	-.3207	-.3163	-.2832	-.2790	-.3046	-.2752	-.2935	-.2945	-.3234	-.2787	-.2516	.2692
.95	-.2743	-.2816	-.3219	-.3261			-.2987	-.2661	-.2972	-.2759	-.3106	-.2753	-.2518	.2560

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.5327	.0057	.1222	-.3729			1.1423	-.4271					.9597	-.4154
.10	.5552	-.0822					1.0659	-.3959	1.0705	-.4048			.8715	-.4185
.15					.9420	-.3235	.9952	-.3477	1.0213	-.3593	.9739	-.3002	.7881	-.4073
.20	.6476	-.0798					.9185	-.3151	.9536	-.3297			.7274	-.3653
.30	.3780	-.1079	.2964	-.2829	.7845	-.2981	.8429	-.3000	.8798	-.3134	.8927	-.3414	.6703	-.2973
.40			.3524	-.3721			.7482	-.2994	.8162	-.3061	.8338	-.3286	.6578	-.2858
.50	.7164	-.2494							.4954	-.4116	.6554	-.3195	.5146	-.2873
.60			.5853	-.2929	.6525	-.4116	.6498	-.4192	.6475	-.4269	.4293	-.4261	.3293	-.3320
.70	.4713	-.2063					.6052	-.4193	.5796	-.4220	.3459	-.4051	-.1542	-.4829
.80					.4936	-.3988	.1827	-.4008	.0418	-.3947	.0078	-.3868	-.1223	-.4744
.90	-.0905	-.3033	.0295	-.3901	.0371	-.4034	-.0217	-.3861	-.3053	-.3534	-.0132	-.3756		
.95	.0567	-.3564	-.0077	-.3367	.0064	-.3710	-.0027	-.3723			-.0315	-.3743	-.1340	-.4554
			-.0013	-.2544	.0009	-.3390	-.0045	-.3591	-.3207	-.3607	-.0451	-.3773	-.1500	-.4420

171

TABLE XVI.- CONTINUED
(b) α = -1.35°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
				.4485	.3368	.3567	.1333	.6015		.6028				
				.3921	.4167	.4928					.3842			
				.3503	.382C								
				.3651	.3555	.4130	.3668	.4593		.4867	.3820	.5045		
							.3458	.4524		.4360	.2715	.1850		
												.3537		
				-.1617	-.0853	-.087	-.0375	-.078C		.371	.2853	.3396		
		.571		-.0701	-.0914	-.0809	-.0203	-.085C			.0462	.0357		
					-.0678	-.0895	-.0858	-.0762			.1455	.1440		
				-.0236	-.0715	-.0855	-.111	-.1650	-.3047		.3729	.3322	-.29	
				-.2722			-.2955	-.3017	-.3151		.3092	.2993	-.26	
				-.3106	-.2773		-.2994	-.2678	-.2874		.3343	.2871	-.26	
				-.3173	-.2749		-.2835	-.2665	-.2757		.3167	.0849	-.25	

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
	.4837	.0133		-.3116			.0995	.3895		.3445			.9310	.3734
	.4920	-.0536					1.014	-.1355			.3561	-.2950	.8285	.3738
					.8893	-.0622	.9371	-.2033	.3584	-.2945			.7400	-.3503
	.5260	-.0535	.2556	-.2272	.7255	-.2364	.8510	-.2517	.8050	-.2725	.8319	-.2935	.6775	-.2924
	.5284	-.0940	.2474	-.3360			.7622	-.2373	.7257	-.2615	.7685	-.2764	.6185	-.2324
							.6615	-.2406	.6154	-.2506	.5838	-.2666	.5550	-.2215
	.5665	-.0224			.6053	-.3812	.6325	-.3977	.5345	-.3577	.2800	-.3915	.1637	-.2031
	.4019	-.852	.5551	-.2589			.5950	-.3355	.5172	-.3532	.3213	-.3843	.2877	-.2345
					.4728	-.3675	.1622	-.3935	.2297	-.3755	.0114	-.3840	-.245	-.4606
	-.023	-.2490	.0033	-.3793	.0170	-.3937	.0011	-.378	-.3550	-.3397	.3055	-.3735	-.55	-.4527
	-.022	-.3543	-.0255	-.3236	-.0156	-.3674	-.0317	-.36C	-.0550	-.3472	.0573	-.3611	-.1549	-.4503
	-.225		-.0273	-.2387	-.0235	-.3260	-.030	-.3477			.0028	-.3643	-.703	-.4371

TABLE XVI.- CONTINUED
(c) α = 0.58°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.711	.1847	.0776	.4601	.2997	.5652	.4253	.6215	.4580	.6223			.0802	
.10	.9226	.2379	.3672	.4098	.4167	.5076			.779	.5643			.2662	
.15	.1823	.2180	.2793	.3714	.3810	.4606			.1251	.5157	.4214	.502	.324	
.20	.1522	.2037	.2545	.3416	.3609	.4271	.3739	.4553	.4139	.4830	.3982	.5242	.3034	
.25					.3372	.3939	.3588	.4230	.1033	.4518	.3972	.5050	.3151	
.30	.0576	.0300	.0820	.0837	.0774	.0785	.0623	.0601	.3504	.4150	.3713	.4600	.0515	
.40	.0853	.0868	.0558	.0518	.0820	.0833	.0830	.0786	.0689	.0608	.2851	.3550	.0916	
.50					.0760	.0756	.0837	.0719			.0473	.0896	.1128	
.60			.0678	.0104	.0663	.0787	.1113	.1508	.3013	.3036	.146	.1413	.3051	.3135
.70	.0346	.0409	.2677	.2571			.3000	.3011	.3120	.3132	.3107	.3311	.2638	.2627
.80	.2325	.2133	.2914	.2951	.2747	.2628	.2999	.2657	.3116	.2796	.3265	.2982	.2955	.2850
.90	.2056	.2615	.2951	.3038			.2925	.2590	.2971	.2713	.3270	.2868	.2952	.2760
.95	.2630	.2714									.3079	.2842		

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.4926	.0306	.9747	-.2412			-.0567	-.3368	.9689	-.2772			.9094	-.3421
.10	.4681	-.0175					.9697	-.2600	.9159	-.2299			.7980	-.3295
.15					.8924	-.1948	.8933	-.2107	.8462	-.2093	.9193	-.2700	.7065	-.2874
.20	.4635	-.0253	.2214	-.1525			.8120	-.1872	.7655	-.1935			.6477	-.2204
.25	.1893	-.0918	.599	-.2896	.6890	-.1749	.7319	-.1760	.6634	-.1844	.796	-.2309	.5807	-.1737
.30							.6329	-.1819			.7313	-.2152	.5172	-.54
.40	.4265	-.1796			.3816	-.3443	.3053	-.3510	.1002	-.3452	.5462	-.1976	.4227	-.331
.50			.4706	-.2190			.4964	-.3582	.2400	-.3628	.0858	-.3584	.2502	-.1584
.60	.2995	-.1655			.4299	-.3287	.1476	-.4055	.4666	-.3651	.0666	-.3854	.3085	-.4145
.70					-.0069	-.3842	-.0140	-.3770	-.0081	-.3585	-.0764	-.3710	-.2943	-.4064
.80	-.3300	-.2707	-.0197	-.3587	-.0503	-.3564	-.0439	-.3534	-.0463	-.3295	-.0651	-.3715	-.2143	-.4175
.90	-.0793	-.3460	-.0589	-.3156					-.0634	-.3379	-.0841	-.3620	-.1814	-.4042
.95	-.0675	-.2268			-.0595	-.3065	-.0559	-.3381			-.0985	-.356		

TAIL 2

173

TABLE XVI.- CONTINUED
(d) α = 2.65°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1632	.1890	.2778	.4609	.3007	.5797	.4325	.6355	.3550	.6357			.2552	
.10	.2062	.2619	.3564	.4171	.4222	.5155			.4332	.5600	.5502	.6192	.2865	
.15	.185?	.2349	.2790	.3754	.3885	.4741			.4360	.5326			.3030	
.20	.1625	.2243	.2701	.3432	.3676	.4370	.3885	.4696	.4261	.4977	.455?	.5394	.3225	
.25					.3417	.3924	.3666	.4361	.4162	.4928	.4160	.5194	.3226	
.30	.3253	.3064							.3650	.4364	.3965	.4705	.2147	
.40	.3903	.3974	-.0760	-.0754	-.0740	-.0740	-.0630	-.0613	-.0602	-.0555	.2915	.3603	.3603	
.50			-.0415	-.0450	-.0831	-.0804	-.0824	-.0759			.3465	.0853	.2605	
.60					-.0774	-.0731	-.0843	-.0691			.3338	.3389	.2976	
.70	-.3055	-.0150	-.0084	.0175	-.0653	-.0756	-.1123	-.1475	-.3022	-.3046	.3087	.3304	.2440	
.80	-.2717	-.1934	-.2531	-.2445			-.3019	-.3002	-.3138	-.3116	.3253	.2979	.2802	
.90	-.1953	-.2461	-.2720	-.2785	-.2717	-.2570	-.2993	-.2641	-.3146	-.2758	.3223	.2862	.3122	
.95	-.2556	-.2570	-.2777	-.2989			-.2899	-.2530	-.2934	-.2633	.3053	.2843	.3172	

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.89 U.S.	0.89 L.S.	0.98 U.S.	0.98 L.S.
.05	.5325	.0444	.9028	-.1657			1.0120	-.2710	.9256	-.2375			.8805	-.295?
.10	.4752	.0299					.9229	-.1821		-.2575			.7657	-.263?
.15					.7936	-.1263	.8495	-.1421	.8738	-.553	.8867	-.2359	.6748	-.22??
.20	.4479	.0017	.868	-.0654	.6532	-.1074	.7718	-.1215	.8072	-.1457	.7606	-.1628	.6094	-.535?
.25	.1139	-.0897					.6956	-.1124	.7302	-.1296			.5491	-.121?
.30			.0970	-.2513			.6011	-.1194	.6622	-.1211	.6993	-.1419	.4874	-.65?
.40	.311.8	-.1045							.0527	-.3092	-.5203	-.1295	.3979	-.08??
.50	.2410	-.1473	.3441	-.1784	.2603	-.3018	.2318	-.3153	.726	-.3238	-.0359	-.3260	-.2336	-.205?
.60							.2984	-.3229	.2584	-.3255	-.5077	-.3657	-.3203	-.38?
.70					.3452	-.2832	.0867	-.3916	-.0809	-.3522	-.0706	-.3618	-.3209	-.3852
.80	-.1622	-.2714	-.0951	-.3394	-.0399	-.3839	-.0533	-.3735	-.0867	-.3255	-.1630	-.3715	-.27?0	-.454?
.90	-.1266	-.3188	-.0953	-.3130	-.0825	-.3424	-.0760	-.3465			-.1610	-.3560	-.27?5	-.452?
.95			-.1088	-.2437	-.0917	-.2890	-.0776	-.3253	-.061	-.3305	-.744	-.3385		

TAIL 2

TABLE XVI.- CONTINUED

(e) α = 4.56°

TAIL 1

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1561	.1952	.2898	.1714	.3076	.6034	.4425	.6577	.2700	.5560	.4492	.5315		.5325
.10	.2247	.2850	.3578	.1269	.3553	.5578			.5118	.5985				.4575
.15	.1902	.2409	.2967	.3672	.1848	.4835			.3511	.5560	.1562	.0934		.3552
.20	.1599	.2322	.2783	.3540	.3837	.4504	.3937	.4845	.1420	.5147	.1227	.3338		.3552
.25					.3525	.4027	.3793	.4455	.1209	.3810	.1430	.3051	.1397	.3125
.30	-.0317	-.0156							.3771	.4459	.3009	.3051		.2835
.40	-.0637	.0615	-.0856	-.0820	-.0710	-.0722	-.0550	-.0530	-.0532	.0445	.2511	.1806		.2341
.50			-.2545	.0522	.0839	.0801	.0815	.0702			.1355	.0850	.1243	.2521
.60					.3858	.0762	.0833	.0674						
.70	.0215	.0055	.0104	.0344	.0870	.0839	.1112	.1453	.0933	.3058	.3032	.3298	.2843	.2528
.80	-.1968	.1763	.2410	.2289			.3044	.3048	.3141	.3100	.3218	.3067	.2810	.2369
.90	-.1762	.2299	.2554	.2645	.2749	.2604	.3095	.2717	.3161	.2749	.3133	.2863	.3305	.3007
.95	-.2403	.2400	.2510	.2733			.2910	.2639	.2936	.2705	.2951	.2649	.3345	.3076

TAIL 2

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.5559	.2667	.8307	-.0720			.9583	-.1874					.8521	-.2480
.10	.4752	.0818			.7452	-.0475	.8706	-.0972	.8778	-.1309	.8464	-.157	.8293	-.2098
.15							.7931	-.0623	.8260	-.0891			.8113	-.1437
.20	.4380	-.0496	.1518	.0025	.5146	-.0261	.7265	-.0377	.7647	-.0677	.7239	-.0750	.5758	-.0778
.25	.0926	-.0845	.0492	.2203			.6549	-.0303	.6908	-.0504	.6634	-.0598	.5165	-.0924
.30							.5675	-.0437	.6273	-.0416	.4922	-.0528	.3562	-.0272
.40	.2300	-.0981							.2232	-.2641	.0061	-.0621	.3714	-.0676
.50					.1754	-.2488	.1617	-.2697	.1115	-.2831	-.0363	-.2821	.2155	-.0653
.60	.1827	-.1255	.2598	-.1288			.1959	-.2729	.1694	-.2870	-.2150	-.3339	.3264	-.3755
.70					.2435	-.2410	-.0114	-.3584	-.1359	-.3600	-.2133	-.3556	.3223	-.3682
.80	-.2062	-.2964	.1313	-.3206	.2549	-.3610	-.1181	-.3614			-.2150	-.3626		
.90	-.1674	-.2985	.1576	-.3295	.1768	-.3419	-.1279	-.3375	-.1577	-.3312	-.2150	-.3594	-.2940	-.4214
.95			.1551	-.2942	-.1141	-.2962	-.1341	-.3123	-.1727	-.3324	-.2251	-.3330	-.2965	-.4135

175

TABLE XVI. - CONTINUED
(f) α = 6.66°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1571	.2034	.3077	.4955	.9455	.6311	.4569	.6791	.2307	.6633	.4558	.6515		.1809
	.2435	.3080	.3665	.4470	.4583	.5555			.5342	.6414				
	.2057	.2633	.3003	.4074	.4295	.5049	.4109	.4964	.4655	.5676	.4608	.4725		
	.1625	.2464	.2933	.3707	.3924	.4602	.3914	.4655	.4530	.5328	.4453			
									.4259	.5017	.4240	.4949		
.30	-.0196	-.0180							.3784	.4667				
	.0523	.0804	-.0929	-.2893	-.0613	-.2648	-.0505	-.2434		.3340			.1969	-.0035
.50			-.0848	-.0379	-.2612	-.0723	-.0781	-.0531				-.2932		-.0035
.60					-.0832	-.0737	-.0730	-.0615				-.2917		-.3435
	.0486	.0294	-.0298	-.0254	-.0892	-.0863	-.1022	-.1408	-.2948	-.3045	-.2958	-.2953		-.3350
.80	-.1817	-.1625	-.2309	-.2158			-.2999	-.3043	-.3115	-.3067	-.3157	-.2843	-.2894	-.3808
.90	-.1539	-.2118	-.2397	-.2476	-.2924	-.2607	-.3086	-.2723	-.3118	-.2594	-.3049	-.2825	-.2981	-.3582
.95	-.2241	-.2224	-.2452	-.2582			-.2907	-.2631	-.2957	-.2656	-.2857			

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.4155	.0828	.7203	.0412			.8927	-.0830	.8103	-.0412			.8132	-.1809
	.4151	.124					.6468	-.0635	.7724	-.0017	.2653	.0316	.6218	-.195
.15					.5838	.0607	.7420	.0410		.0262			.6058	-.1524
.20	.3868	.1062	.1367	.0564	.5710	.0762	.6760	.0653	.7141	.0576	.6336	.0165	.5708	-.0505
.25	.0741	-.0587	.0102	-.1862			.6220	.0693	.6475	.0576	.6300	.0307	.4823	.034
							.5316	.0553	.5888	.0651	.4656	.0151	.4427	-.0385
.30	-.1806	-.1266							-.0063	.2098			.3447	-.0453
.50	.1233	-.076	.1777	-.0796	.1042	-.2114	.0955	-.2143	-.0571	-.2304	-.0159	-.2332	.1969	-.0035
.60						-.1787	-.1187	-.2255	-.0965	-.2370	-.0715	-.2917	-.3335	-.3435
					.1298		-.0745	-.3342	-.1788	-.3736	-.2494	-.3462	-.3135	-.3350
.80	-.2284	-.2853	-.1543	-.3112	-.1425	-.3217	-.1733	-.3413			-.2530	-.3394		
.90	-.1891	-.2678	-.1904	-.3284	-.1628	-.3228	-.1829	-.3228	-.2047	-.3195	-.2571	-.3333	-.2894	-.3808
.95			-.1914	-.2885	-.1614	-.2934	-.1832	-.3049	-.2230	-.3153	-.2657	-.3184	-.2981	-.3582

TAIL 2

TABLE XVI. - CONTINUED
(g) α = 3.66°

Cp at y/b of

TAIL 1

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1553	.2198	.3283	.5263	.3774	.6506	.4654	.6957	.5046	.6761	.4671	.6725	.3481	.5721
.10	.2587	.3345	.3956	.4713	.4708	.5685			.5951	.6386			.3372	.5251
.15	.2178	.2844	.3233	.4214	.4015	.5168	.4130	.5172	.4734	.5937	.4557	.5933	.2842	.4613
.20	.1821	.2629	.3121	.3800	.3974	.4767	.3975	.4892	.4603	.5578	.4622	.5556	.3551	.3801
.25					.3577	.4332			.3500	.5240	.4125	.5028	.3512	.3457
.30	-.0131	-.0158	-.0971	-.0587	-.0537	-.0550	-.0415	-.0323	-.0391	-.5243	.3345	.3950	.2994	.3308
.40	-.0461	.0761	-.0944	-.0691	-.0726	-.0677	-.0641	-.0558		-.5253	-.0416	-.0603	.1312	.1346
.50					-.0731	-.0707	-.0565	-.0551			-.1137		-.2583	-.2714
.70	.0776	.0520	-.0393	-.0050	-.0803	-.0834	-.0931	-.1364	-.2887	-.3024	-.2926	-.3231	-.1701	-.2102
.80	-.1618	-.1442	-.2167	-.1934			-.2851	-.3009	-.3097	-.3001	-.3096	-.2852	-.2405	-.2242
.90	-.1357	-.1899	-.2242	-.2276	-.3021		-.3070	-.2646	-.3132	-.2646	-.2914	-.2818	-.3491	-.3184
.95	-.2042	-.2022	-.2312	-.2380		-.2564	-.2847	-.2575	-.2963	-.2618	-.2791	-.2808	-.3531	-.3258

Cp at y/b of

TAIL 2

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.2119	.0938	.6019	.1491			.3051	.0051					.7752	-.0984
.10	.3314	.1490					.7279	.1438	.7441	.0780			.6496	-.0372
.15					.6086	.1714	.6712	.1822	.7064	.1297	.7533	.0042	.5614	-.0760
.20	.3210	-.1657	.1095	.1059	.5194	.1580	.6156	.1969	.6535	.1748			.4955	.1280
.25	.0478	-.0080	-.0258	-.1552			.5622	.1758	.5965	.1912	.6434	.1356	.4415	-.1153
.30							.4894	.1459	.5429	.1679	.5923	.1520	.3885	-.1262
.40	.1433	-.0285	.1100	-.0382	-.0428	-.1737	-.0373	-.758	-.0144	-.1644	.1437	.1403	.3135	-.1217
.50	.0599	-.0728					-.0436	-.1909	.0110	-.1864	-.0384	-.755	-.764	-.0524
.70			.1100	-.0382	.0402	-.0974	-.1221	-.3061	.0352	.1922	-.2776	-.2510	-.3272	-.3113
.80	-.2495	-.2752	.1453	.2855	-.1970	-.2815	-.2253	-.3317	-.2167	-.3357	-.2853	-.3525	-.3119	-.2892
.90	-.1908	-.2509	-.2108	-.3142	-.1974	-.3043	-.2310	-.3085	-.2441	-.3055	-.2871	-.3224	-.2759	-.3613
.95			-.2110	-.2779	-.1941	-.2880	-.2291	-.2815	-.2656	-.2998	-.2865	-.3026	-.2502	-.334

TABLE XVI. - CONTINUED
(h) α = 10.65°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1829	.2471	.3509	.5484	.3794	.6712	.4504	.7169	.1686	.6995				
.10	.2808	.3555	.3963	.4873	.4788	.5905			.5512	.6592	.5004	.6908	.2785	.5905
.15	.2318	.2977	.3248	.4399	.4412	.5404			.5027	.6094			.3893	.5435
.20	.1853	.2734	.3119	.3963	.4115	.4972	.4370	.5393	.4889	.5715	.5044	.6069	.4017	.4787
.25					.3855	.4513	.4269	.5022	.4620	.5375	.4827	.5727	.3851	.4138
.30	-.0212	-.0059	-.0888	-.0880	-.0424	-.0481	-.0289	-.0239	.4259	.4995	.4578	.5146	.3715	.3774
.40	.0510	.0866	-.0902	-.0773	-.0594	-.0534	-.0500	-.0462	-.0175	-.0162	.3465	.4064	.3165	.3600
.50											-.0464	-.0623	.1325	.1330
.60			.0460	-.0195	-.0678	-.0621	-.0468	-.0472			-.1146	-.1210	-.1694	-.2565
.70	.1065	.0788	-.1976	-.1841	-.0754	-.0766	-.0889	-.1345	-.2836	-.2988	-.2878	-.3178	-.2301	-.1872
.80	-.1399	-.1209	-.2120	-.2076			-.2915	-.2973	-.3025	-.2952	-.3024	-.2978	-.3585	-.2109
.90	-.1136	-.1663	-.2174	-.2172	-.2984	-.2513	-.3012	-.2595	-.3081	-.2610	-.2839	-.2782	-.3549	-.3304
.95	-.1820	-.1793					-.2762	-.2534	-.2963	-.2585	-.2727	-.2755		-.3345

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1352	.1025	.4744	.2580			.6948	.1561					.7070	.0137
.10	.2595	.1891					.6267	.3257	.6428	.2483			.5928	.1026
.15					.5141	.2673	.5798	.3017	.6178	.3284	.7076	.1449	.5063	.2342
.20	.2349	.2169	.0700	.1542	.4573	.2296	.5356	.2729	.5768	.2907	.5894	.3122	.4427	.2602
.25	-.0149	.0370	-.0671	-.1203			.4948	.2524	.5363	.2684	.5447	.2979	.3329	.2520
.30	.0542						.4370	.2066	.4952	.2436	.4110	-.2133	.3458	.2344
.40	.0151	-.0285	.0282	.0036	-.0146	-.1218	-.0123	-.1397	-.0341	-.1215	-.0586	-.1420	.2821	.1856
.50		-.0481			-.0312	-.0142	-.0080	-.1413	-.0259	-.1140	-.1340	-.2243	-.1610	-.0687
.60							-.1677	-.2529	-.0133	-.1487	-.3014	-.3475	-.3159	-.3079
.70					-.2490	-.2610	-.2643	-.2883	-.2508	-.3303	-.3094	-.3084	-.3179	-.2513
.80	-.2648	-.2608	-.2027	-.2655	-.2405	-.2809	-.2608	-.2717	-.2778	-.2864	-.2888	-.3061	-.2550	-.3506
.90	-.1808	-.2309	-.2231	-.3012	-.2228	-.2712	-.2360	-.2661	-.2863	-.2863	-.2760	-.2972	-.2537	-.3427
.95			-.2256	-.2686										

TABLE XVI. - CONTINUED
(I) α = 12.65°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1891	.2661	.3507	.5760	.4029	.7018	.4839	.7404	.2087	.7242			.3204	.6082
.10	.2866	.3838	.4016	.5088	.5056	.6173			.5691	.6882	.5213	.7144	.4131	.5706
.15	.2394	.3243	.3439	.4578	.4781	.5622			.5343	.6382			.4153	.5077
.20	.1925	.2957	.3374	.4123	.4421	.5227	.4638	.5529	.5038	.6014	.5274	.6241		
.25					.4083	.4746	.4413	.5302	.4772	.5661	.5012	.5881	.3977	.4445
.30	-.0293	-.0007							.4439	.5257	.4734	.5294	.3965	.4409
.40	.0564	.0821	-.0776	-.0806	-.0374	-.0371	-.0225	-.0134	.0020	-.0062	.3622	.4243	.3338	.3916
.50			-.0843	-.0730	-.0538	-.0485					-.0487	-.0535		
.60					-.0616	-.0505					-.1140	-.1137		
.70	.1400	.1165	-.0325	-.3206	-.0673	-.0680	-.0824		-.2830	-.2954	-.2899	-.3126	-.2586	
.80	-.1193	-.0953	-.1822	-.1850			-.2895	-.2932	-.2999	-.2977	-.3022	-.2985	-.1729	-.1741
.90	-.0936	-.1438	-.1945	-.1912	-.2817	-.2467	-.2892	-.2560	-.3078	-.2600	-.2911	-.2751	-.2529	-.1958
.95	-.1532	-.1565	-.1960	-.1956			-.2684	-.2485	-.2855	-.2563	-.2638	-.2720	-.3533	-.3572

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0598	.1120	.3435	.3606			.5452	.4302					.5897	.2542
.10	.788	.2204					.4788	.4173	.5299	.4385			.5162	.3957
.15					.3941	.3549	.4572	.3781	.5103	.4208	.6377	.3213	.4384	.3484
.20	.1263	.2824	.0149	.2150	.3596	.3011	.4262	.3515	.4832	.3847			.3816	.2941
.25	.1144	.1030	-.1118	-.0686			.4057	.3320	.4575	.3545	.5109	.3811	.3431	.2495
.30							.3706	.2809	.4281	.3286	.4822	.3622	.3097	.2325
.40	-.0218	-.0044							-.0575	-.0887	.3729	.2563	.2652	.2325
.50	-.0185	-.0155			-.0655	-.0607	-.0575	-.0861	-.0656	-.1057	-.0786	-.1156	.1562	.0664
.60			-.0378	.0199			-.0628	-.0834	-.0607	-.1013	-.1585	-.2080	-.3160	-.3061
.70					-.0897	.0362	-.2108	-.1921	-.2818	-.3024	-.3235	-.3351	-.3357	-.2509
.80	-.2871	-.2398	-.2278	-.2468	-.2897	-.2369	-.2972	-.2363	-.2696	-.2730	-.2983	-.2994	-.2618	-.3274
.90	-.1556	-.2107	-.2421	-.2853	-.2612	-.2639	-.2540	-.2456	-.2696	-.2730	-.2809	-.2917	-.2618	-.3274
.95			-.2488	-.2566	-.2506	-.2594	-.2577	-.2548	-.2707	-.2748	-.2795	-.2872	-.2625	-.3068

179

TABLE XVII.- CONTINUED
(β = 15.00°)

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.89 U.S.	0.89 L.S.	0.98 U.S.	0.98 L.S.
.05	-.2351	.3224	-.1766	.6360	.4593	.7502	.5214	.8066	.8002	.7787	.5294	.7463	.3555	.5514
.10	.3399	.4900	.4495	.5600	.5550	.6729			.5791	.7335				
.15	-.2923	-.3660	-.3978	.5088	.5283	.6168			.5785	.6878	.5345	.6458		.6428
.20	-.2373	.3347	.3829	.4612	.4891	.5721	.5049	.6051	.5338	.6053	.6000	.6047		
.25	.0647	.0326			.4537	.5206	.4862	.5353	.4853	.5611	.4308	.5453	.4000	.4538
.30	-.0364	.1353	-.0554	-.0619	-.0153	-.0177	-.0035	.0079	.0087	.0069	.3758	.4436		
.40			-.0632	-.0346	-.0371	-.0255	-.0218	-.022			-.0335	-.0406		
.50					-.0468	-.0364	-.0292	-.0290			-.1164	-.0972	-.2000	
.60	.2011	.869	.0213	.0029	-.0626	-.0548	-.0797	-.123	-.2772	-.2889	-.2830	-.3014	-.1639	-.1505
.70	-.0788	-.0482	-.1764	-.1633			-.2863	-.2813	-.2931	-.2915	-.2863	-.2858	-.3215	-.1705
.80	-.0520	-.1008	-.1692	-.1668	-.2840	-.2340	-.2900	-.2435	-.2975	-.2527	-.2649	-.2638	-.3728	-.3500
.90	-.0941	-.1081	-.1729	-.1652			-.2620	-.2390	-.2914	-.2498	-.2548	-.2532	-.3532	-.3466

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.89 U.S.	0.89 L.S.	0.98 U.S.	0.98 L.S.
.05	-.2727	.1158	.1106	.4838			.1871	.6463					.1430	.6075
.10	-.0263	.2851					.2615	.5985	.2703	.6105			.2628	.5102
.15	-.0756	.4197			.1909	.5207	.2511	.5518	.2831	.5755	.4815	.4831	.2895	.4320
.20	-.2851	.2011	-.0911	.3116	.1764	.4312	.2341	.504	.2674	.5185			.2817	.3618
.25			-.1924	.0448			.2159	.4552	.2504	.4803	.3037	.5247	.2520	.2957
.30	-.1155	-.0227					.1950	.3672	.2397	.4283	.2878	.4873	.2207	.2561
.40			-.1444	.0981	-.1592	.1059	-.1527	-.0028	-.1369	-.0442	.2457	.3325	.1900	.1928
.50	-.0715	.0341					-.1601	-.1035	-.1574	-.0385	-.1337	-.0726	.1015	.0454
.60					-.1922	-.1038	-.2819	-.0837	-.1570	-.0134	-.2120	-.1631	-.3263	-.3632
.70					-.3137	-.1947	-.3235	-.1904	-.3405	-.2019	-.3544	-.3056	-.3130	-.3325
.80	-.3065	-.2065	-.2624	-.2063	-.3154	-.2147	-.3190	-.2035	-.3047	-.1910	-.3158	-.3132		
.90	-.172	-.1963	-.2857	-.2577	-.3089	-.2183	-.3106	-.2106	-.3097	-.2155	-.3090	-.2988	-.3489	-.2701
.95			-.2867	-.2439							-.3043	-.2922	-.3321	-.2632

TABLE XVI. - CONCLUDED
(k) α = 18.66°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2643	.3529	.3401	.6670	.4897	.79¦1	.5705	.9334	.2305	.8097				
.10	.3680	.4606	.4789	.5913	.5920	.7027			.5888	.7656	.5494	.7654	.3816	.5770
.15	.3160	.3977	.4316	.5353	.5582	.6461			.5946	.7116			.4426	.6277
.20	.2510	.3627	.4091	.4860	.5133	.5936	.5263	.6388	.5538	.6691	.5551	.6623	.4550	.5786
.25					.4752	.5494	.4996	.6006	.5345	.6288	.5119	.6223	.4353	.5269
.30	.0851	.0522	.C410	.C464	.C081	.C073	.C07¦	.0182	.5089	.5819	.5C¦6	.5531	.4C69	.4927
.40	.1187	.1585	.0570	.0377	.0297	.0207	.011¦	.0148	.0¦33	.0148	.4C36	.4¦52	.4¦25	.4¦78
.50					.0375	.0291	.0202	.0228			.0101	.0316	.1333	.1291
.60	.2182	.2116	.0197	.0116	.0531	.0503	.0692	.1205	.2653	.2878	.1032	.0897	.2041	.2092
.70	.0674	.0316	.1805	.1671			.2818	.2713	.2881	.2894	.2819	.2966	.1646	.1475
.80	.0805	.0835	.1607	.1523	.2829	.2285	.2892	.2381	.2965	.2510	.2606	.2820	.3623	.1860
.90	.0710	.0820	.1542	.1457			.2532	.2350	.2920	.2479	.2483	.2556	.3760	.3515
.95													.3573	.3493

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1361	.1149	.C016	.5237			.0299	.7126	.1091	.6766			.0820	.7011
.10	.C407	.3328					.1166	.6567	.1461	.6350			.0807	.5830
.15					.C9¦9	.5707	.1339	.6042	.1535	.5735	.3243	.6634	.1244	.4756
.20	.1860	.48C2	.1330	.3464			.133¦	.5516	.1522	.5247	.1792	.5635	.1520	.3945
.25	.3250	.2178	.2205	.0960	.0825	.4633	.1208	.4972	.1433	.4624	.1766	.5¦18	.1532	.3244
.30							.1031	.3977	.1764	.0246	.1489	.3¦¦5	.1465	.2766
.40	.1742	.0388											.1389	.2023
.50					.2025	.2126	.2051	.0710	.2077	.0082	.1747	.0527	.0741	.C409
.60	.0953	.0701	.1773	.1363			.2089	.2121	.2140	.0676	.2482	.379	.3291	.320¦
.70					.2307	.1420	.3123	.0629	.3744	.1199	.3654	.2833	.2851	.3210
.80	.3¦39	.1910	.2889	.1812	.3291	.1637	.3395	.1680			.3391	.2683		
.90	.1897	.2012	.3118	.2390	.3329	.1916	.3319	.1823	.3279	.1734	.3337	.2545	.3393	.2442
.95			.3042	.2401	.3270	.1988	.3179	.1878	.3319	.1935	.3274	.2448	.3553	.238¦

TAIL 2

TABLE XVII. - PRESSURE COEFFICIENTS. b = 0°, δ... = -15°, M = 2.36

(a) j = -4.03°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05					.909	.2724	.1756	.2033						
.10					.2053	.3005								
.15					.2076	.2835								
.20					.2044	.2904								
.25					.1996	.2849								
.30														
.40								.2345						
.50		-.0354	-.0668	-.0495	-.0005	.0219	.0062	.0215						
.60				-.0316	-.0102	.0117	-.0051	.0260						
.70	-.0438	-.0105	-.0282	-.0220	-.0132	.0057	-.0056	.0260						
.80	-.1328	-.1109	-.1339	-.1262	-.0204	-.0050	-.1468	-.0314						
.90	-.1259	-.1198	-.1150	-.1042	-.1340		-.1358	-.1439						
.95	-.1285	-.1183	-.1407	-.1460	-.1482		-.1271	-.1330						

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.4537	-.0298	1.0466	-.1047			1.1322	-.1388			1.1895	-.1393	1.2338	-.1494
.10	.3729	-.0529					.0406	-.1015	.0371	-.10-5			1.0124	-.107C
.15					.9419	-.0943	.9746	-.0981	.9942	-.0989			.8975	-.0808
.20	.4741	-.0462					.9150	-.0988	.9422	-.09?3			.8422	-.0677
.25	.2294	-.0543	.3872	-.1149	.8189	-.1055	.8501	-.1002	.8804	-.0975	.9421	-.0872	.7957	-.0656
.30			.3260	-.1815			.7707	-.1077	.8238	-.1000	.9044	-.094?	.732?	-.0614
.40	.4418	-.0869							.2975		.7560	-.037	.6350	-.0648
.50			.3914	-.1766	.3962	-.1777	.387?	-.1784	.3706	-.18?5	.2952	-.1762	.6360	-.0865
.60	.3756	-.1061					.4436	-.1755	.4048	-.17?6	.2588	-.1718	.6649	-.1844
.70					.3764	-.1624	.2138	-.1695	.1093	-.165?	.0764	-.1679	.6581	-.1785
.80	.0556	-.1489	.0918	-.1920	.0948	-.1738	.0935	-.1703	.0811	-.1625	.0689	-.1681	.033?	-.1610
.90	.0385	-.1729	.0828	-.1778	.0763	-.1762	.0753	-.1710	.0708	-.15?2	.0563	-.1680	.0447	-.1744
.95	.0850		.0855	-.1795	.0674	-.1735	.0656	-.1?05			.0488	-.1685		

TABLE XVII.- CONTINUED
(b) α = -2.08°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.2252	.3043			.1823	.3111					.2458	
.10	.0895	.1118	.2306	.2980	.1852	.2762			.2204	.3044	.2127	.3129	.2258	.3010
.15	.0876	.1114		.2746	.2099	.3045			.2255	.3059			.2256	.2156
.20	.0763	.1049		.2530	.2126	.2988			.2278	.3003			.1813	.2232
.25	-.0094	-.0196			.2094	.2940	.2009	.2910	.2.05	.2658	.2227	.2983	.1726	.2277
.30	-.0051	-.0010			.2043	.2994	.2056	.2922	.2.19	.2595	.2219	.2955	.1545	.2272
.40	.0215	.0343	-.0556	-.0294	-.0013	.0212	.0070	.0357	.2263	.2595	.2122	.2961	.2355	.2272
.50			-.0319	-.0315	-.0131	.0086	-.0048	.0220	.129	.2571	.2037	.2644	.2293	.1855
.60	-.0437	-.0124	-.091	-.0314	-.0180	-.0022	-.0035	-.0208	-.0067	-.0262	-.1019	-.237	-.294	-.1538
.70	-.1202	-.0104	-.294	-.179	-.0273	-.0066	-.0329	-.0333	-.253	-.14	-.0352	-.259	-.353	-.325
.80	-.1176	-.1108	-.486	-.1406			-.1463	-.1370	-.424	-.1355	-.1354	-.241	-.1407	-.347
.90	-.1211	-.135	-.413	-.1462	-.1295	-.1469	-.1319	-.1438	-.206	-.1350	-.1355	-.352	-.1285	-.1370
.95							-.1247	-.1316	-.162	-.233	-.137	-.1263		-.1031

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.4172	.0032	.3752	-.0714			1.0584	-.1056					1.2042	-.1120
.10	.3450	-.0274				-.0664	.9752	-.0667	.3787	-.3725	1.1155	-.1149	.9628	-.0633
.15					.8791		.9159	-.0688	.3387	.0685			.8448	-.0431
.20	.4085	-.0333	.3577	.0914			.8636	-.0729	.8908	.0697			.7906	-.0328
.25	.1785	-.0542	.2059	-.1711	.7777	-.0785	.8123	-.0750	.3407	-.0713	.9000	-.0607	.7542	-.0317
.30							.7426	-.0830	.7917	.0746	.8699	-.0671	.6944	-.0317
.40	.3790	-.0856					.3251	-.674	.2651	-.1506	.7236	-.0798	.6045	.0383
.50	.2943	-.1053	.3380	-.1672	.3286	-.1699	.3510	-.1757	.353	-.1732	.2695	-.1659	.4487	-.0530
.60							.1700	-.1624	.3410	-.1707	.2152	-.1704	-.0557	-.1851
.70	.0152	-.1457	.3213	-.1855	.3051	-.1645	.0538	-.1621	.634	-.1607	.3374	-.1636	-.0655	-.372
.80	.0053	-.1743	.2237	-.1718	.0310	-.1668	.0344	-.1627	.0393	-.1584	.0255	-.1635		
.90			.2337	-.1631	.0266	-.1656	.0251	-.1623	.632	-.1619	.0166	-.637	-.0553	-.1501
.95											.0098	-.639	-.0725	-.722

TABLE XVII - CONTINUED
(c) α = -0.08°

Cp at η/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.2251	.2999	.1834	.2802	.1909	.2191					.2515	
	.0932	.1320	.2051	.2888		.3012			.2222	.3048	.218-			
.15	.0955	.1308	.1954	.2913	.1943	.2855			.2133	.3077				
.20	.1819	.1222	.1828	.2532	.2127	.2947	.2053	.2912	.2135	.3041	.2157			
	.0185	.0248			.2075	.2916	.2112	.2937	.2104	.2995	.2119			
.30	.0044	.0054							.2124	.2936	.2115			
.40	.0143	.0293	.0325	.0148	.0008	.0230	.0094	.1355	.1152	.0437	.2016			
								.3216						
.60	.0336	.0003	.0214	.0122	.0157	.0034	.0021	.0194	.0057	.0229	.1356			
	.1141	.0995	.1282	.1175	.0251	.0058	.0308	.0331	.1258	.1103	.1296			
.80	.1163	.1101	.1402	.1365			.1125	.1336	.1408	.1338	.1153			
	.1202	.1116	.1320	.1398	.1221	.1468	.1246	.1395	.1138	.1339	.1127			
							.1183	.1275	.1140	.1222			.022	

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.3929	.0263	.8774	.0355			.3621	.0705			1.0062	.0780	.12--	.057-
	.3258	.0025					.8945	.0332	.8585	.0381			.80--	.02--
.15					.8030	.0351	.8443	.0383	.8594	.0394			.7756	.009-
.20	.3566	.0152	.3275	.0627	.7188	.0480	.7984	.0442	.8223	.0417	.8558	.0338	.72--	.0014
.25	.1394	.0486	.244	.552			.7594	.047	.7855	.0433	.8075	.0403	.0---	.0005
.30							.7000	.0560	.7168	.0467	.6852	.0548	.5---	.0067
.40	.3086	.0362			.2727	.1573	.2732	.1529	.2510	.1448	.2450	.1525	.42--	.02--
.50							.2873	.1639	.2731	.1589	.1838	.1677	.0665	.16--
.65	.2232	.0978	.2223	.1510	.2537	.1497	.1368	.1552	.2866	.1611	.1-12	.1554	.0---	.15--
.72							.1338	.1557	.0337	.154-				
.80	.0171	.1420	.0100	.1729	.0064	.1512	.0178	.1527			.0015	.1554		
.90	.0408	.1677	.0005	.1654	.0125	.1559	.0131	.1532	.0387	.1503	.0119	.1559	.0825	.1536
.95			.0001	.1596	.0183	.1563	.0069	.1530	.0015	.1535	.0188	.1559	.0946	.1661

184

TABLE XVII. - CONTINUED
(d) α = 1.72°

TAIL 1

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	-.1122	.1549	.2226	.3052	.1948	.2971	.1931	.2265			.2289	.3792	.2485	.3099
.10	-.1084	.1509	.2138	.3033	.2134	.3092			.2308	.3059			.2610	.2817
.15	-.0897	.1405	.2015	.2900	.2172	.3003			.2166	.3045	.2103	.3001	.2734	.2453
.20	-.0265	-.0273	.1910	.2718	.2162	.2998	.2119	.2393	.2155	.3085	.2758	.3006	.1660	.2173
.25	-.0129	-.0503			.2131	.2957	.2158	.2391	.2188	.304	.2554	.2905	.2551	.2125
.30	-.0015	.0143	-.0293	-.0104	-.2022	.0254	.0088	.0355	.151	.2552	.2079	.2915	.1955	.2055
.40			-.0396	-.0236	-.0094	.0151	-.0034	.0215	.015	.0480	.0153	.2438	.117	.84
.50	-.0236	.0089	-.0290	-.0164	-.0145	.0082	-.0034	.0008	.0072	.0226	-.1511	.0657	.2255	.0255
.60	-.1174	-.0946	-.1297	-.1236	-.0252	-.0005	-.0305	-.0311	-.1241	-.1086	-.1373	-.1251	.1121	-.1384
.70	-.1118	-.1075	-.1306	-.1360			-.1447	-.1323	-.1396	-.1324	-.1297	-.1383	-.1121	-.1351
.80	-.1160	-.1070	-.1241	-.1342	-.1268	-.1442	-.1271	-.1357	-.1171	-.1301	-.1155	-.1234		
.90							-.1205	-.1252	-.1128	-.1187	-.1131	-.1148	-.1057	

TAIL 2

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.3642	.0339	.7439	.0016			.8500	-.0350			.8945	-.0255	.0763	-.0180
.10	.3133	.0234					.8012	.0003	.8088	-.0021			.8191	-.2051
.15					.7242	-.0021	.7616	-.0062	.7879	-.0079			.7015	-.2202
.20	.3067	.0088	.2846	-.0310	.6577	-.0132	.7245	-.0119	.7468	-.0116	.7735	-.0032	.5637	-.2235
.25	.0955	-.0323	.1750	-.1352			.5987	-.3148	.7205	-.0123	.7548	-.0088	.6385	-.2189
.30							.6565	-.247	.6950	-.0144	.6555	-.0241	.5357	-.0153
.40	.2386	-.0926			.2206	-.1398	.2267	-.355	.2289	-.1264	.2299	-.1347	.4507	-.0127
.50	.1588	-.0896	.1466	-.1306			.2349	-.1471	.2344	-.1424	.1586	-.1590	-.0701	-.1004
.60					.2029	-.1422	.0876	-.1504	.2379	-.1460	-.0095	-.1497	-.0933	-.592
.70									.3012	-.1480				
.80	-.0345	-.1379	-.0221	-.1503	-.0210	-.1453	-.0130	-.1460	-.0213	-.1435	-.0255	-.1492	-.0373	-.1753
.90	-.0711	-.1633	-.0410	-.1581	-.0423	-.1453	-.0286	-.1453	-.0276	-.1463	-.0376	-.1495	-.1122	-.1822
.95			-.0407	-.1556	-.0502	-.1471	-.0356	-.1460			-.0451	-.1497		

185

TABLE XVIII.- CONTINUED
(e) α = 3.22°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.55 U.S.	0.55 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2??		.2382	.3130	.1999	.2946	.1966	.33??	.2???	.3?7?	.2?35	.3?5?	.2?55	.3?.??
.10	.2?0	.1744	.2192	.310?	.2204	.3152			.2207	.3102		.3?5?	.2?05	
.15	.1?94	.1681	.2082	.3001	.2207	.2934			.2?89	.3195	.2?4?	.3?4?		
.20	.0975	.1566	.1976	.2929	.2195	.305?	.21??	.3?9?	.2?94	.3079	.2184	.3?4?	.3?3?	
.25	.0277	.0250			.2?68	.3036	.2205	.3?7?	.2139	.300?	.2?73	.2?99	.3?.?	
.30	.01??	.0087	.2?7?	.30??	.0052	.0294	.01??	.03??	.2?08	.300?	.2?.?	.2?9?	.3??	
.40	.02??	.0077	.0355	.3?7?	.0064	.0189	.00??	.02??		.05??	.2?.?	.2?9?		
.50					.0110	.0124	.0019	.02??	.0050	.0234	.0152	.06??	.3?5?	
.60	.0234	.0091	.0306	.0157	.0205	.0049	.0275	.0230	.0231	.1106	.0152	.?66?	.3?3?	
.70	.1?53	.0918	.1352	.126?			.1365	.123?	.390	.131?	.1279	.1?9?	.0?3?	
.80	.1?63	.1038	.274	.388	.1297	.14?3	.1228	.13??	.105	.276	.153	.?2?		
.90	.1?99	.1012	.1?65	.32?			.1167	.12??	.121	.166	.1133	.1?5?	.2?5?	

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2867	.0321	.6108	.0421			.7026	.0000	.7049	.0337	7.72	.012?	.2917	.0158
.10	.2946	.0398			.6226	.0359	.6941	.0376	.6939	.0257			.7254	.0308
.15							.6623	.0296	.6654	.0226			.6033	.0383
.20	.2825	.0398	.2414	.0002	.5849	.0247	.6350	.0242	.6413	.0230	.6856	.0279	.5945	.0394
.30	.0721	.0128	.1352	-.1151			.6195	.0222	.6229	.0215	.6750	.0234	.5656	.0348
.40	.1755	-.0962					.5321	.0119	.2082	-.1056	.6074	.0075	.5334	.0341
.50							.1831	-.1161	-.948	-.1238	.2079	-.1148	.4893	.0300
.60	.0958	-.0773	.1074	-.1123	.1708	-.1200	.1820	-.1276	-.1897	-.1280	.1309	-.1478	.3843	.0000
.70					.1567	-.1272	.0523	-.1496	-.0238	-.1428	-.0310	-.1434	-.1036	-.1558
.80	-.0524	-.1318	-.0529	-.1515	-.0467	-.1375	-.0426	-.1394	-.0513	-.1372	-.0499	-.1432	-.1079	-.1634
.90	-.0943	-.1565	-.0727	-.1487	-.0665	-.1385	-.0569	-.1392	-.0575	-.1396	-.0624	-.1443	-.1220	-.1814
.95			-.0755	-.1499	-.0737	-.1386	-.0631	-.1391			-.0698	-.1446		

TABLE XVII.- CONTINUED
(l) α = 5.92°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.2446	.3252	.2054	.3024	.1971	.3395						
.10	.1364	.1935	.2291	.3271	.2256	.3209			.2391	.3104	.2246	.3115	.2533	
.15	.1272	.1840	.2182	.3127	.2256	.3030			.2256	.3103				.296?
.20	.1052	.1638	.2076	.2958	.2236	.3121	.2230	.3067	.2237	.3156	.2275	.3155	.1722	.2342
.25	-.0245	-.0187	-.0245		.2212	.3088	.2257	.3065	.2262	.3149	.2215	.3090	.158?	.2285
.30	-.0115	-.0041	-.0341						.2235	.3062	.2136	.3046	.157?	.1116
.40	-.0074	.0084		-.0012	-.0085	.0355	.0144	.0424	.0225	.0572	.2138	.2953	.1375	.2062
.50			-.0341	-.0160	-.0004	.0247	.0022	.0287					.152?	.2002
.60	-.0200	-.0066	-.0290	-.0134	-.0038	.0194	.0014	.0263	-.0043	.0251	.0177	.0481	.1376	.1743
.70	-.1143	-.0926	-.1354	-.1265	-.0124	.011?	-.0274	-.0251	-.1259	-.1120	-.0141	-.0065	.1193	.1199
.80			-.1204	-.1386			-.1393	-.1270	-.1373	-.1302	-.1391	-.1272	-.1193	-.1310
.90	-.1038	-.1008	-.1186	-.1288	-.1293	-.1375	-.1205	-.1362			-.1258	-.1208	-.1253	-.0905
.95	-.1052	-.0971					-.1165	-.1254	-.1106	-.1159	-.1139	-.1150		-.1479

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2324	.0441	.4889	.0865			.5405	.0358	.5840	.0724	.5157	.0480	.6510	.0481
.10	.2264	.0502					.5805	.0781	.5900	.0654			.590E	.0593
.15					.5267	.0794	.5638	.0704	.5762	.0636			5.155	.0587
.20	.2371	.0671	.1922	-.0333										
.25	.0582	.0147	.0925	-.0917	.4929	.0678	.5425	.0658	.5546	.0648	.5889	.0655	.5089	.0547
.30	.1116	-.0910					.5284	.0647	.5426	.0632	.5857	.0623	.4925	.0428
.40							.5080	.0941	.1735	-.0802	.5440	-.0459	.4611	.0502
.50	.0397	-.0639	.0648	-.0893	.1210	-.0975	.1356	-.0940	.1523	-.1014	.1745	-.0914	.3552	-.0476
.60							.1322	-.1045	.1430	-.1054	.1025	-.1317	.0142	
.70					.1032	-.1087	.0166	-.1494	-.0525	-.1386	-.0526	-.1353	-.0875	-.1426
.80	-.0611	-.1221	-.0845	-.1528	-.0746	-.1298	-.0730	-.1325	-.0784	-.1306	-.0729	-.1354	-.082	-.1428
.90	-.0978	-.1485	-.1008	-.1414	-.0926	-.1311	-.0855	-.1315	-.0849	-.1331	-.0859	-.1367	-.0975	-.1481
.95			-.1004	-.1426	-.0989	-.1315	-.0909	-.1315			-.0931	-.1367		-.1455

187

TABLE XVIII.- CONTINUED

(q) α = 7.92°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1494	.0649	.2557	.3370	.2099	.3072	.1888	.3425						.2915
.10	.1375	.0654		.3357	.2310	.3654			.2378	.3089				.2427
.15	.137-			.3053	.2312	.3081		.3072	.2975	.3078	.2214	.312		
.20	.1144	.1827		.3093	.2301	.3203	.2287	.3062	.2216	.3165	.2254	.3162	.1525	.2315
.25	-.0194	-.0109			.2288	.3135	.2336	.3174	.2302	.3178	.2620	.3149	.1509	.2156
.30	-.0067	-.0013		.0017					.2265	.3119	.2193	.3069	.1530	.2113
.40	-.0034	-.0142		-.0071	-.0132	.0142	-.0167	.0461	.2238	.3555	.2.6	.2985	.1530	.2034
.50					-.0050	.0324	-.0047	.0312			.0184	.0033	.1455	.183-
.60	-.0257	-.0105	-.0025	-.0095	.0012	.0275	-.0031	.0282	-.0017	.0259	-.0184	-.0004	-.1143	-.1143
.70	-.1156	-.0940	-.0315	-.1259	-.0070	.0162	-.0260	-.0235	-.1240	-.1099	-.0397	-.1297	-.0932	-.1238
.80	-.1022	-.1001	-.1155	-.1369	-.1227	-.1372	-.1362	-.1276	-.1350	-.1296	-.1236	-.1358	-.1187	-.1129
.90	-.1017	-.0943	-.1149	-.1251			-.1171	-.1329	-.1125	-.1261	-.1156	-.1182		
.95							-.1121	-.1206	-.1091	-.1149	-.1145	-.1145		-.1595

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.55 U.S.	0.55 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1514	.0649	.3739	.3950			.4167	.0765						.0908
.10	.1541	.0654					.4655	.1254	.4650	.1167	.3928	.0888	.5161	.0982
.15					.4240	.1272	.4557	.1174	.4755	.1115			.4791	.0897
.20	.1833	.0922	.3317	.0014			.4430	.1155	.4676	.1113	.4799	.1103	.4072	.0763
.25	.0319	.0384	.3416	-.071-	.4045	.1150	.4351	.1134	.4586	.126	.4825	.1090	.3935	.0670
.30							.4219	.1002	.4457	.1108	.4543	.0898	.3751	.0669
.40	-.0579	-.0752							.1297	-.0522	.1316	.0898	.3535	.0633
.50	-.0055	-.0133		.0071	.0687	-.0735	-.0977	-.0572	-.1077	-.0745	-.0662	-.0646	-.2948	-.0262
.60							-.0739	-.0771	-.0971	-.0737	-.0759	-.1122	-.104-	-.141-
.70	-.0752	-.111-	-.68	.0519	.0551	-.0885	-.1053	-.1345	-.0771	-.1450	-.0709	-.0325	-.112-	-.1332
.80			-.244	-.1371	-.1043	-.1272	-.1021	-.1287	-.1050	-.1262	-.0955	-.1321		
.90	-.0985	-.1-	-.2-	-.135-	-.1196	-.1280	-.1119	-.1272	-.1121	-.1284	-.1377	-.1329	-.0986	-.1495
.95					-.1240	-.1285	-.1126	-.127-			-.114-	-.1332	-.1125	-.1618

188

TABLE XVIII. - CONTINUED
(h) α = 3, 12°

Cp at γ/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1645	.2322	.2566	.3469	.2113	.3092	.1877	.3510					.266	.3013
.10	.1502	.2164	.2439	.3466	.2320	.3306			.2444	.3274	.2330	.3160	.2104	.2505
.15	.1267	.1969	.2408	.3523	.2338	.3146			.2349	.3222			.1888	.2475
.20	-.0127	-.0023	.2332	.3285	.2330	.3270	.2319	.3157	.2238	.3310	.242	.3338	.81	.2328
.25	.0005	.0095			.2306	.3265	.235	.3259	.2353	.3309	.2253	.3320	.748	.2298
.30	.0045	.0247	-.0108	.0153	.0113	.0484	.0130	.0509	.2302	.3238	.2313	.3290	.733	.2298
.40			-.0213	-.0010	.0039	.0356	.0002	.0333	.0241	.0635	.2235	.3096	.173	.2007
.50	-.0203	.0184	-.0215	-.0027	.0016	.0329	.0000	.0325	.023	.0259	.0175	.046	.545	.2007
.60	-.1146	.0922	-.1303	-.1241	-.0058	.0227	-.0325	-.0190	-.1222	.1056	-.1387	-.1302	-.198	-.1063
.70	-.1004	.0982	-.1113	-.1334	-.1210	-.1286	-.1338	-.1207	-.1316	-.1305	-.1231	-.1357	-.105	-.1098
.80	-.0986	.0921	-.1103	-.1207			-.1139	-.1251	-.1103	-.1236	-.1151	-.1175	-.152	-.1012
.90							-.1092	-.1142	-.074	-.129	-.1143	-.1142		-.167

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0720	.0904	.2694	.1838			.3156	.1215	.3605	.1656	.2923	.1349	.4029	.1382
.10	.0783	.0812					.3580	.1791	.3712	.1639			.3844	.1416
.15					.3295	.1777	.3522	.1692	.3655	.1646			.3138	.1245
.20	-.1257	.1130	.0744	.1037	.3102	.1660	.3458	.1640	.3595	.1644	.3750	.1619	.3070	.1065
.25	-.0076	.0525	-.0096	-.0499			.3403	.1650	.3550	.1648	.3754	.1598	.3022	.0965
.30							.3280	.1509			.3536	.1384	.2857	.0915
.40	-.0049	-.0571			.0219	-.0490	.0424	-.0378	.0807	-.0209			.2716	.0886
.50							.0337	-.0485	.0586	-.0440	.0813	-.0374	.2311	.0447
.60	-.0355	-.0342	-.0230	-.0416	.0051	-.0635	-.0613	-.1208	.0481	-.0490	-.0175	-.0907	-.1207	-.1395
.70							-.1270	-.1367	-.029	-.1504	-.1038	-.1390	-.1246	-.1462
.80	-.0870	-.1017	-.1395	-.1377	-.1280	-.1375	-.1373	-.1285	-.1285	-.1244	-.1197	-.1293	-.1184	-.1385
.90	-.0991	-.1331	-.1364	-.1501	-.1433	-.1302	-.1347	-.1279	-.1331	-.1259	-.1299	-.1282	-.1293	-.1502
.95			-.1283	-.1368	-.1363	-.1289					-.1333	-.1279		

TABLE XVIII - CONTINUED
(l) α = 11.12°

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.33		0.38	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1794		.2947	.3804	.2391	.2941	.2141	.3875					.2992	
.10	.1636	.2533	.2757	.3821	.2810	.3662			.2699	.3554	.2543	.3413		
.15	.1390	.2371	.2625	.3724	.2623	.3507			.2607	.3483				
.20	.1351	.2167	.2518	.3560	.2610	.3534	.2435	.3355	.2501	.3572	.2554	.3622		
.25	.0035	.0082			.2654	.3570	.2624	.3533	.2610	.3575	.2635	.3584		
.30	.0035	.0209							.2549	.3504	.2665			
.40	.0138	.0576	-.0044	.0245	.0251	.0612	.0276	.0549	.3397	.0773	.2471	.3368		
.50			-.0145	.0065	.0163	.0492	.0143	.0404			.0047	.0555		
.60					.0132	.0449	.0072	.0404	.0125	.0398	-.0059	.0548	.1065	
.70	-.0147	.0276	-.0178	.0025	.0056	.0392	-.0168	.0052	-.08	-.1006	-.1330	.1249	-.0944	-.1002
.80	-.1123	-.0882	-.1276	-.1195			-.1253	-.1137	-.280	-.1232	-.1167	.1307	-.1235	-.0729
.90	-.0858	-.0948	-.1079	-.1292	-.1159		-.1078	-.1199	-.1036	-.1148	-.1084	.1405		
.95	-.0945	-.0881	-.066	-.1158	-.1159	-.1257	-.1044	-.1083	-.1000	-.1037	-.1073	.1042		-.1692

TAIL 2

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0095	.1143	.1910	.2372			.2396	.1715			.2115	.1882	.3041	.1882
.10	.0251	.1013					.2740	.2373	.2782	.2223			.2957	.1893
.15					.2489	.2355	.2673	.2279	.2875	.2251			.2339	.1653
.20	-.0627	.1357					.2637	.2229	.2815	.2255			.2313	.1493
.25	-.0619	.0742	.0257	.1408	.2325	.2216	.2590	.2247	.2754	.2281	.2901	.2195	.2250	.1338
.30			-.0491	-.0289			.2488	.2078	.2708	.2265	.2902	.2177	.2155	.1268
.40	-.0376	-.0412							.0337	.0157	.2708	.1955	.2023	.1205
.50					-.0209	-.0235	-.0001	-.0088	.0118	-.0099	.0341	-.0055	.1705	.0663
.60	-.0438	-.0131	-.0602	-.0160			-.0101	-.0212	-.0028	-.0158	-.0210	-.0544	-.1335	.1358
.70					-.0365	-.0366	-.0900	-.1031	-.271	-.1367	-.1283	-.1450	-.1348	.1508
.80	-.1076	-.0901	-.1529	-.1218	-.1507	-.1476	-.1486	-.1498			-.1416	-.1289		
.90	-.0871	-.1244	-.1400	-.1391	-.1357	-.1379	-.1349	-.1356	-.1313	-.1260	-.1296	-.1203	-.1216	-.1076
.95			-.1314	-.1387	-.1304	-.1299	-.1285	-.1282	-.1253	-.1231	-.1210	-.1190	-.1211	-.1162

TABLE XVII. - CONTINUED

(1) α = 15.92°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.025	.2479	.3375	.3744	.4857	.3080	.4265	.2999	.3709					.3655	.3760
.10	.2356	.3194	.3591	.4888	.3358	.4550			.3376	.4386	.3189	.4272	.2561	.3552
.15	.2047	.2936	.3436	.4721	.3375	.4445			.3298	.4270			.2571	.3350
.20	.2362	.2808	.3357	.4569	.3380	.4552	.3034	.3863	.3294	.4409	.3317	.4397	.2571	.3250
.25	.2362	.2576			.3324	.4520	.3335	.4113	.3289	.4032	.3250	.4225	.2551	.3240
.30	.2660	.2579	.0352	.0664	.0681	.1079	.0660	.1410	.3222	.4355	.3211	.4125	.2575	.3133
.40			.0224	.0447	.0536	.0980	.0553	.0958	.0784	.1243	.3116	.3125	.2573	.3060
.50					.0545	.0930	.0378	.0709	.0511	.0863	.0697	.0953	.2567	.2560
.60	.0240	.0725	.0175	.0420	.0489	.0804	.0135	.0362	.2849	.0725	.0231	.0417	.0825	.0765
.70	.0858	.0592	.1103	.0969	.0998	.1027	.1028	.0856	.1097	.1004	.1168	.1055	.0763	.0687
.80	.0583	.0504	.0947	.1073			.0846	.0950	.0818	.0931	.0967	.1120	.1345	.0635
.90	.0568	.0550	.0836	.0952			.0754	.0863	.0772	.0808	.0882	.0906		
.95											.0871	.0858	.1555	.1555

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.025	-.0754	.1596	.0260	.3273			.0882	.2971			.0623	.2978	.1368	.2965
.10	-.0805	.1370					.1146	.3792	.1184	.3649			.1281	.3037
.15							.1175	.3694	.1340	.3695			.0872	.2856
.20	-.0843	.1718			.1038	.3540	.1117	.3537	.1333	.3683			.0798	.2614
.25	-.1381	.1229	-.0506	.1968	.0936	.3221	.1118	.3474	.1264	.3687	.1367	.3575	.0778	.2447
.30			-.1026	.2169			.1057	.3170	.1211	.3632	.1397	.3598	.0737	.2404
.40	-.0698	.0174							.0525	.2902	.1267	.3335	.0813	.2188
.50	-.0592	.0254	-.0873	.0299	-.0913	.0259	-.0771	.0448	-.0723	.0529	-.0471	.0523	.0649	.1469
.60					-.1077	.0197	-.0913	.0317	-.0802	.0417	-.0935	.0005	-.1435	.1234
.70	-.0916	.0671	-.1551	.0862	-.1370	.1063	-.1412	.0649	-.1491	.1044	-.1465	.1051	-.1527	.1220
.80	-.0834	.1103	-.1494	.1114	-.1381	.1125	-.1354	.1217	-.1330	.1241	-.1405	.1175	-.1316	.1181
.95			-.1370	.1188	-.1381	.1153	-.1347	.1300	-.1353	.1295	-.1393	.1294	-.1389	.1305

TABLE XVII.- CONCLUDED
(b) α = 19.92°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.3272	.4373	.4825	.6158	.3965	.5427	.3657	.5863			.3970	.5450		
.10			.4534	.6196	.4320	.5708			.4201	.5332				
.15			.446	.5346	.4356	.5644			.4163	.5290	.4106			
.20	.2954	.3863	.4309	.5663	.4354	.5751	.3792	.4809	.4152	.5445	.4252	.5279		
.25					.4238	.5722	.4059			.5445		.514		
.30	.2221	.1272							.4085	.5315	.4006			
.40	.340	.1769	.0825	.115	.1225	.1603	.1094	.655	.273	.705	.3901	.4960		
.50			.0687	.0895	.1118	.1494	.1053	.561			.1907	.1322		
.60	.0736	.274	.0623	.0840	.1060	.1388	.0755	.1190	.0973	.1308	.5599	.0739		
.70	-.0505	-.0251	.082	-.0716	.0995	.1242	.0677	-.0751	-.0536	-.0486	-.0953	-.0865		
.80	-.0302	-.0224	-.0724	-.0785			-.0781	-.0664	-.0885	-.0775	-.0764	-.0886		
.90	-.0293	-.0196	-.0643	-.0674	-.0831	-.0813	-.0639	-.0707	-.0560	-.0629	-.0653	-.0655		
.95							-.0500	-.0581	-.0508	-.0514	-.0635	-.0631		

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0733	.2312	.0179	.4325			.0601	.4368	.0737	.5401	.0332	.4804	.1053	.4479
.10	-.0863	.2129					.0635	.5261	.0728	.5265			.0283	.4974
.15					.0404	.4702	.0529	.5021	.0650	.5033			.0635	.4743
.20	-.1427	.2556	-.1175	.2795	.0123	.4172	.0415	.4609	.0531	.4881	.0759	.5166	.0575	.4441
.25	-.1796	.2196	-.1686	.0619			.0332	.4508	.0441	.4718	.0693	.5015	.0541	.4086
.30							.0256	.4158			.0519	.4123	.0504	.3822
.40	-.1022	-.0286			-.1399	.0798	-.1251	.017	-.1014	.1492	-.0957	.1277	.0200	.3453
.50			-.1564	.0992			-.1420	-.0905	-.1194	.1081	-.1323	.0550	-.1533	.2328
.60	-.0456	-.0877					-.1698	-.0212	-.1275	.0968	-.1620	-.0673	-.1533	-.1062
.70			-.1761			-.1148	-.1595	-.0845	-.1601	-.0717	-.1602	-.0823	-.1700	-.1190
.80	-.1040	-.0322	-.1620	-.0503	-.1531	-.0581	-.1594	-.0794	-.1520	-.0925	-.1595	-.0922	-.1654	-.1024
.90	-.1038	-.0958	-.1429	-.0804	-.1605	-.0730	-.1590	-.0781	-.1563	-.0978	-.1599	-.0981	-.1677	-.1135
.95				-.0909	-.1627	-.0734								

TAIL 2

TABLE XVIII.- PRESSURE COEFFICIENTS, β = 0°, δ... = -15°, M = 1.70

(a) α = -4.15°

TAIL 1

x/c	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	....	....	.375	....	....	....	....	....	....	....	....	....	....	....
.10	....	.0645	.304	....	....	....	....	....	.376	....	....	....	....	....
.15	....	....	....	....	....	....	....	....	.360	....	....	....	....	....
.20	....	....	.226	....	....	....	....	....	.32.	....	....	....	....	....
.25	....	....	....	....	....	....	....	....	.306	....	....	....	....	....
.30	....	....	....	....	....	....	....	....	.299	....	....	....	....	....
.40	.0026	.0006	.0073	.0009	.024	.0622	.0092	....	.0197	.0530	....	....	....	....
.50	....	....	.002.	.0058	.0622	....	.0008	....	....	....	....	....	....	....
.60	....	....	....	....	.0188	.0138	.0561	.0197	.0042	.0234	....	....	....	....
.70	-.0032	-.0113	-.0042	-.0001	-.0071	-.0075	-.0199	-.0534	-.0355	-.0345	....	.0428	....	.0472
.80	-.0345	-.0247	-.0425	-.0413	....	....	-.0615	-.0534	-.0355	-.0396	....	.0429	....	.0455
.90	-.0383	-.0377	-.0373	-.0386	-.0345	-.0335	-.0551	-.0529	-.0391	-.0435	....	.0122	....	....
.95	-.0372	-.0382	-.0371	-.0377	....	....	-.0580	-.0465	-.0383	-.0408	....	.038.	....	-.0377

TAIL 2

x/c	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.2927	.0139	.3481	-.0198			.8927	-.0232			.8498	-.0015	.2648	-.0161
.10	.2299	.0134					.9859	-.0247	.8817	.0605			.929.	-.0145
.15	.2533	-.0184			.8267	-.0262	.8585	-.0289	.8825	-.0229			8.050	-.0173
.20	.1576	-.0262	.2265	-.0383	.7611	-.0384	.3295	-.0350	.8553	-.0342	.6543	.0675	.7729	-.0197
.25			.3315	-.0500			.8072	-.0350	.9293	-.0358	.8457	.0375	.7577	-.0223
.30	.276.	-.0103					.7734	-.0377	.8063	-.0354	.7906	-.0219	.724.	-.0229
.40	.2632	-.0309	.2976	-.0392	.3471	-.0423	.3169	-.0494	.3906	-.0558	.3853	-.0518	.6842	-.018.
.50							.358.	-.0531	.3706	-.0512	.3041	-.0493	.5723	-.0542
.60	.1932	-.0378	.2988	-.0549	.3135	-.0473	.2151	-.0513	.3645	-.0469	.343.	-.0152	.583.	-.0340
.70	.0362	-.0571	.2715	-.0556	.1133	-.0552	.1167	-.0535	.1420	-.0351	.1.8	-.0135		
.80					.0691	-.0535	.0911	-.0528			.102.	-.0480	.0389	-.0450
.90			.2548	-.0564	.080.	-.0522	.0875	-.0528	.0965	-.0482	.0344	-.0352	.0238	-.0513
.95									.0927	-.0464				

TABLE XVIII. - CONTINUED
(b) α = -2.14°

Cp at γ/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0435	.0501	.1422	.1885	.1331	.1984	.1358	.2152	.392	.855	.1435	.0604		.2005
.10	.0472	.0612	.1395	.1805		.2035			.351	.1625				
.15	.0425	.0583	.1516	.1833		.1248	.1565	.255	.1323	.1999	.1324	.1945		
.20	.0045	.0099	.1256	.1832	.1935	.1551	.1304	.1952	.1343	.1575		.1863		
.25	.0050	.0117							.310	.1925	.1513	.1803		
.30	.0084	.0128	.0034	.0150	.0095	.0282	.0055	.0361	.3185	.0555	.358			
.40			.0024	.033	.0015	.0211	.0050	.0217			.329	.0455		
.50						.0158	.0376	.0446	.0089	.0203	.0033	.0135		
.55	.0007	.0156	.0053	.0014	.0113	.0085	.0224	.0043	.0562	.0345	.0472	.0432	.0485	
.70	.0331	.0241	.0426	.0395			.0655	.0444	.0385	.0402	.0467	.0501		
.80	.0378	.0365	.0378	.0388	.0400	.0230	.0585	.0431	.0415	.0444	.0415	.0435		
.90	.0382	.0378	.0371	.0369			.0570	.0395	.0404	.0414	.0395	.0404		.0388

TAIL 1

Cp at γ/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.2680	.0214	.7394	.0134			.7209	.0168		.0002	.6437	.0011	.7655	.0295
.10	.2299	.0087					.7549	.0182	.7429				.7597	.0254
.15					.7467	.0218	.7594	.0239	.7595	.0217			.6848	.0115
.20	.2506	.0129					.7510	.0270	.7533	.0270	.7410	.0209	.6533	.0136
.25	.1440	.0234	.3854	.0347	.7727	.0325	.7248	.0284	.7501	.0280	.7501	.0231	.6533	.0147
.30			.2966	.0512			.7123	.0325	.7349	.0289	.750	.0234	.6392	.0153
.40	.2590	.0009							.3602	.0547	.7149	.0319	.620	.0114
.50					.2993	.0432	.3122	.0512	.3287	.0547	.3516	.0512	.534	.0199
.60	.1859	.0339	.2335	.0415			.3109	.0535	.391	.0484	.2712	.0498	.0805	.0536
.70					.2637	.0479	.1818	.0515	.1123	.0351	.079	.0487	.0478	.0414
.80	.0579	.0494	.2571	.0546	.0817	.0515	.0602	.0528	.0676	.0487	.0858	.0495	.0208	.0401
.90	.0112	.0578	.2424	.0565	.0595	.0527	.0526	.0528	.0642	.0433	.0738	.0476	.0114	.0461
.95			.0350	.0570	.0526	.0527	.0576	.0535			.0661	.0482		.0515

TAIL 2

TABLE XVIII.- CONTINUED
(c) α = -0.15°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.1453	.1948	.1411	.1903	.1362	.2213			.1453		.1642	.2264
.10	.0558	.0712	.1437	.1962	.1433	.2054			.1425	.2025			.1637	.2089
.15	.0557	.0734	.137C	.1906	.1422	.1973			.1376	.2007			.1447	.1859
.20	.0497	.0711	.1311	.1975	.1400	.1955	.1497	.2022	.1357	.2005	.1489	.2017	.1346	.1859
.25	.0056	.0117			.1378	.1922	.1352	.1964	.1366	.1988	.1459	.1987	.1224	.1539
.30	.0055	.0133							.1340	.1945	.1432	.1954	.1094	.1556
.40	.0057	.0115	.0053	.0191	.0041	.0285	.0053	.0313	.0162	.0517	.1370	.844	.1003	.1460
.50			.0014	.0063	-.0054	.0192	-.0088	.3170	-.0101	.0177	.3330	.0525	.0894	.1211
.70	-.0008	.0176	-.0053	.0043	-.0096	.0152	-.0215	.0364	-.0101	.0390	.0036	-.0166	-.0421	-.0382
.80	-.0345	.0244	-.0437	-.0395	-.0160	.0082	-.0272	-.0104	-.0602	-.0401	-.0481	-.0429	-.0492	-.0450
.90	-.0390	.0386	-.0378	-.0401	-.0474		-.0696	-.0507	-.0398	-.0443	-.0473	-.0502	-.0509	-.0494
.95	-.0391	-.0393	-.0375	-.0382		-.0314	-.0608	-.0447	-.0411	-.0413	-.0406	-.0412		-.0401

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2500	.0300	.6208	-.0012			.6046	-.0047			.5409	.0051	.6500	.0023
.10	.2125	-.0000					.6486	-.0054	.6298	.0063			.6603	.0008
.15					.6371	-.0115	.6456	-.0113	.6507	-.0094			.5755	-.0015
.20	.2193	-.0038	.3468	-.0249	.6243	-.0212	.6450	-.0147	.6510	-.0138			.5596	-.0038
.25	.1098	-.0182	.2413	-.0495			.6401	-.0166	.6447	-.0157	.6296	-.0107	.5523	-.0052
.30							.6197	-.0244	.6356	-.0172	.6395	-.0153	.5380	-.0054
.40	.2135	-.0027							.3133	-.0502	.6116	-.0216	.5178	-.0068
.50					.2529	-.0444	.2639	-.0524	.2762	-.0546	.2953	-.0483	.4735	-.0130
.60	.1416	-.0350	.780	-.0423			.2625	-.0535	.2689	-.0494	.2159	-.0491	.0567	-.0509
.70					.2164	-.0457	.1507	-.0502	.0852	-.0369	.0763	-.0472	.0238	-.0413
.80	.0268	-.0507	.0339	-.053	.0565	-.0490	.0557	-.0529			.0584	-.0471	.0025	-.0427
.90	-.0047	-.0575	.0119	-.0551	.0348	-.0513	.0404	-.0524	.0428	-.0478	.0477	-.0454	.0025	-.0427
.95			.0108	-.0554	.0279	-.0504	.0343	-.0526	.0390	-.0482	.0404	-.0472	.0057	-.0479

TAIL 2

195

TABLE XVIII. - CONTINUED
(a) α = 1.36°

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0668			.1992	.1444	.1931	.1465							
.10	.0670			.2011										
.15	.0586				.1436	.1986								
.20														
.25														
.30														
.40														
.50	-.0411			.0048	-.2165									
.70	-.0388									-.0393				
.80	-.0411				-.2373	-.0212				-.0415				
.90	-.0404			-.0399						-.0428				

TAIL 2

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.2130	.0275	.5106	.0147			.5027	.0095		.0161	.4547		.5529	.0137
.10	.1945									.0063				.0114
.15					.5367	.0032							.4563	.0079
.20	.1868										.5348		.1783	
.25	.0723				.5291	-.0055							.4779	
.30														
.40	.1712								.2217		.2428		-.1.80	
.50					.1931	-.0435					.534			
.60	.0858							-.0554		-.0497				
.70					.1763	-.0449	.1321	-.0501	.0570	-.0380				.0431
.80	.0073				-.0337	-.0471								
.90						-.0494		-.0510	-.0184	-.0481	-.0210		-.0113	-.0438
.95					-.0079	-.0488		-.0512		-.0491			-.0224	-.0488

196

TABLE XVIII - CONTINUED
(e) α = 3.35°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0775	.1142	.536	.2056	.1508	.1987	.1512	.2322			.1513		.1750	
.10	.0775	.1100	.522	.2082	.1510	.2129			.520	.2133			.1807	
.15	.0607	.1041	.455	.2033	.1494	.2023			.475	.2078	.1573		.1455	
.20	.0033	.0122	.1414	.1998	.1465	.2033	.144	.205	.450	.214	.1548		.1365	
.25	.0027	.0123	.1357		.1441	.2000	.1437	.211	.453	.2064	.1523		.1250	
.40	-.0000	.0063			.0075	.0267	.01..	.02..	.227	.0507	.0368		.0098	
.50					-.0091	.0156	-.0035	.0150			-.0054		.0357	
.60	.006.	.0107	-.0050	.0064	-.0086	.0106	-.0145	.0296	-.0068	.0127	-.0488		-.0389	
.70	-.0412	-.0290	-.0447	-.0403	-.0155	.0036	-.0232	-.0158	-.0567	-.0453	-.0502		-.0420	
.80	-.0408	-.0430	-.0396	-.0423	-.0459	-.0403	-.0661	-.0574	-.0431	-.0419	-.0435			
.90	-.0394	-.0417	-.0389	-.0398			-.0595	-.0565	-.0428	-.0463	-.0420			
.95							-.0580	-.0525	-.0417	-.0433				

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1792	.0425	.4111	.0352			.4220	.0266			.3742	.0256	.4642	.0294
.10	.1626	.0147					.4552	.0301	.4475	.0301			.4715	.0255
.15					.4407	.0221	.4531	.0237	.4617	.0254			.4258	.0199
.20	.1533	.0199					.4508	.0212	.4594	.0210	.4474	.0164	.3966	.0158
.25	.0583	.0014	.2156	.0062	.4369	.0149	.4491	.0191	.4562	.0196	.4564	.0131	.3978	.0133
.30			.1357	-.0374			.4409	.0126	.4518	.0174	.4375	-.0350	.3835	.0131
.40	.1331	-.0036			.1478	-.0400			.2005	-.0355	.1936	-.0415	.3736	.0118
.50			.0973	-.0398			.1601	-.0451	.1681	-.0447	.1249	-.0521	.3342	-.0022
.60	.0466	-.0337			.1251	-.0455	.1587	-.0516	.1602	-.0454	.0197	-.0490	.0122	-.0526
.70					.0096	-.0461	.0728	-.0500	.0332	-.0384	.0054	-.0486	-.0103	-.0453
.80	-.0115	-.0493	-.0090	-.0488	-.0074	-.0479	.0070	-.0501	-.0017	-.0476	-.0001	-.0472	-.0234	-.0442
.90	-.0363	-.0529	-.0284	-.0504	-.0116	-.0477	-.0044	-.0493	-.0047	-.0485	-.0060	-.0488	-.0309	-.0453
.95			-.0329	-.0513			-.0091	-.0492						

197

TABLE XVIII.- CONTINUED
(f) α = 5.85°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0920		.1680	.2236	.1654	.2134	.1641	.2463	.1701	.2256				.2556
.10	.0910	.1374	.1671	.2247	.1655	.2280			.1658	.2195	.1647			
.15		.1302	.1611	.2135	.1537	.2182	.1495	.2201	.1636	.2203	.1720	.2237		
.20	.0776	.1223	.1555	.2163	.1601	.2182	.1584	.2252	.1641	.2204	.1638			
.25	.0670	.0184			.1575	.2148			.1515	.217	.1574	.2219		
.30	.0052	.0178									.1503			
.40	.0034	.0112	.0143	.0299	.0190	.0360	.0301	.0381	.0425	.0605	.0448			
.50			.0051	.0151	.0103	.0225	.1152	.0227			.0113			
.60	.0046	.0118	.0014	.0109	.0073	.0185	.0256	.0315	.0127	.0223	.0471	.0412	.0433	.0313
.70	.0412	.0234	.0437	.0332	.0014		.0045	.0115	.0352	.0381	.0507	.0506	.0422	.0364
.80	.0387	.0426	.0381	.0422	.0282	.0359	.0461	.0549	.0415	.0414	.0431	.0456		
.90	.0369	.0410	.0374	.0392			.0393	.0528	.0420	.0456	.0412	.0427		.0508
.95							.0375	.0493	.0406	.0420				

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1321	.0485	.3156	.0585			.3417	.0458			.2955	.0419	.3729	.0492
.10	.1155	.0204					.3682	.0527	.3645	.0483			.3752	.0432
.15					.3407	.0457	.3664	.0465	.3758	.0485			.3399	.0353
.20	.0699	.0304					.3613	.0441	.3753	.0440	.3645	.0379	.3155	.0285
.25	.0400	.0118	.1568	.0253	.3405	.0399	.3616	.0421	.3710	.0421	.3728	.0353	.3173	.0240
.30			.0857	.0298			.3539	.035C	.3676	.0357	.3580	.0258	.3095	.0195
.40	.0866	.0029							.1521	.0245	.1463	.0034	.2997	.0040
.50			.0542	.0365	.1003	.0342	.1106	.0377	.1200	.0361	.0881	.0437	.2632	.0562
.60	.0079	.0324			.0905	.0427	.0370	.0446	.1109	.0385	.0017	.0496	.0221	.0450
.70	.0313	.0482	.0258	.0483	.0122	.0446	.0136	.0510	.0074	.0390	.0151	.0480		
.80	.0446	.0515	.0419	.0491	.0276	.0457	.0232	.0492	.0214		.0201	.0468	.0281	.0432
.85			.0361	.0499	.0307	.0464	.0274	.0480	.0248	.0476	.0253	.0482	.0362	.0483

TAIL 2

TABLE XVIII.- CONTINUED

(g) α = 7.35°

TAIL 1

	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1150		.1935	.2526	.1893	.2377	.1882	.2739					.2150	.2550
.10		.1654	.1932	.2534	.0830	.2539			.0930	.2594	.1855		.2128	.2446
.15		.1566	.1888	.2484	.0865	.2401	.1613		.0877	.2510	.1933	.2557	.1757	
.20		.1460	.1808	.2404	.0830	.2441	.1815	.2437	.0848	.2496	.1812	.2529	.1633	
.25					.0905	.2403			.0855	.2495	.1888	.2478		
.30		.2280	.0242	.0414	.0263	.0444	.0325	.0562	.0603	.2435	.1912	.2356		
.40		.2212	.0132	.0258	.0153	.0350	.0167	.0325	.0436	.2735	.0562	.0744		
.50					.0115	.0255	.0063	.0353	.0093	.0303	.0200	.0329		
.70	-.0017	.0198	.0059	.0203	.0049	.0186	-.0079	.0019	-.0479	-.0370	-.0440	-.0379	-.0513	
.80	-.0390	-.0254	-.0411	-.0356			-.0562	-.0502	-.0404	-.0397	-.0487	-.0481		
.90	-.0355	-.0397	-.0350	-.0399	-.0349	-.0380	-.0485	-.0480	-.0391	-.0426	-.0402	-.0430		
.95	-.0336	-.0382	-.0342	-.0363			-.0459	-.0439	-.0373	-.0389	-.0382	-.0390	-.0461	

TAIL 2

	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.3656	.0562	.2196	.0812			.2493	.0659			.2372	.0658	.3143	.0733
.01	.0680	.0292					.2727	.0776	.2762	.0705			.3130	.0668
.5					.2609	.0728	.2762	.0725	.2776	.0735			.2819	.0571
.20	.0630	.0392					.2766	.0698	.2788	.0695	.2753		.2563	.0485
.25	.0224	.0254	.1069	.0472	.2531	.0671	.2770	.0681	.2820	.0675	.2753	.0605	.2517	.0413
.30			.0450	-.0190			.2702	.0599	.2820	.0648	.2812	.0610	.2448	.0384
.40	.0705	-.0011							.1056	-.0116	.2677	.0515	.2333	.0326
.50							.0666	-.0277	.0787	-.0257	.0940	-.0229	.2028	.0135
.60	-.0075	-.0309	.0203	-.0314			.0613	-.0396	.0699	-.0289	.0490	-.0433	.0185	-.0506
.70					.0418	-.0357	.0140	-.0435	.0043	-.0412	.0181	-.0491	.0295	-.0454
.80	-.0352	-.0463	-.0380	-.0477	.0259	-.0440	.0303	-.0483			.0284	-.0478	.0342	-.0458
.90	-.0451	-.0507	-.0500	-.0479	.0393	-.0454	.0376	-.0468	.0327	-.0469	.0319	-.0467	.0342	-.0458
.95			-.0486	-.0487	.0410	-.0449	.0406	-.0467	.0359	-.0480	.0368	-.0478	.0414	-.0508

TABLE XVIII.- CONTINUED
(h) α = 9.35°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.025			.2278	.2905	.2191	.2693	.2091	.2941						.3145
.05	.1456	.2003	.2278	.2908	.2191	.2873			.2186	.2883	.2127			
.10	.1425	.1899	.2209	.2857	.2167	.2741	.1921	.2437	.2175	.2774	.2207			
.15	.1234	.1776	.2147	.2788	.2127	.2770	.2095	.2754	.2136	.2757	.2182			
.20	.0317	.0440			.2099	.2728			.2150	.2742	.2162	.2720		
.25	.0322	.0425	.0396	.0569	.0407	.0538	.0453	.0640	.2115	.2533	.2077	.0652		
.30	.0274	.0353	.0273	.0399	.0313	.0457	.0253	.0468	.0622	.0894	.0701	.0899		
.50			.0192	.0330	.0269	.0409	.0245	.0409	.0234	.0439	.0326	.0101		
.60	.0134	.0327			.0180	.0332	.0008	.0087	.0416	.0295	.0384	.0335		
.70	.0343	.0180	.0365	.0304			.0549	.0444	.0376	.0368	.0433	.0115		
.80	.0313	.0353	.0300	.0363	.0317	.0334	.0456	.0427	.0325	.0388	.0346	.0379		
.90	.0285	.0340	.0289	.0320			.0934	.0381	.0304	.0343	.0323	.0335		.0480

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.025	.0446	.0698	.1739	.1063			.2149	.0910			.2074	.1037	.2821	.1022
.05	.0420	.0471					.2256	.1077	.2390	.1076			.2731	.0966
.10					.1920	.1015	.2138	.1030	.2366	.1040			.2530	.0868
.15	.0374	.0551	.0570	.0583	.1846	.0965	.2112	.0996	.2309	.0997	.2386	.0956	.2252	.0773
.20	.0023	.0464	.0125	.0066			.2071	.0974	.2255	.0977	.2425	.0970	.2196	.0686
.25							.2005	.0879	.2208	.0950	.2295	.0836	.2125	.0635
.30	.0534	.0018							.0550	.0044	.0692	.0050	.2013	.0556
.50	.0171	.0246	.0011	.0226	.0292	.0133	.0287	.0142	.0412	.0121	.0252	.0323	.1729	.0331
.60							.0213	.0215	.0325	.0169	.0298	.0506	.0254	.0477
.70			.0475	.0507	.0144	.0242	.0113	.0438	.0170	.0426	.0391	.0468	.0315	.0466
.80	.0370	.0420	.0486	.0492	.0378	.0456	.0427	.0493	.0423	.0451	.0409	.0418	.0385	.0387
.90	.0425	.0508	.0477	.0484	.0459	.0453	.0467	.0461	.0428	.0458	.0442	.0451	.0456	.0465
.95					.0433	.0445	.0452	.0460						

TAIL 2

TABLE XVIII.- CONTINUED
(i) α = 11.95°

Cp at y/b of

TAIL 1

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.797	.2421	.2656	.3374	.2527	.3084	.237?	.3532			.2424		.2593	.3466
.10	.1753	.2298	.2663	.3358	.2536	.3294			.2557	.3303			.2552	.2899
.15	.1537	.2147	.2589	.3315	.2508	.3148			.2502	.3188			.2389	.2806
.20	.0484	.0629	.2525	.3247	.2463	.3174	.2165	.2852	.2462	.3150	.2517	.3233	.2289	.2562
.25	.0495	.0512			.2442	.3138	.2461	.3207	.2464	.3153	.2489	.3206	.1933	.2562
.30	.0438	.0550	.0576	.0761	.0550	.0805	.0523	.0844	.2430	.3089	.2471	.3157	.1953	.2463
.40			.0421	.0581	.0455	.0654	.0427	.0648	.0754	.1054	.2379	.3017	.1840	.2463
.50					.0410	.0597	.0320	.0552			.0865	.1049	.1970	.2242
.60	.0272	.0500	.0343	.0492	.0333	.0519	.0134	.0220	.0268	.0586	.0462	.0570	.0110	.0131
.70	.0278	.0107	.0305	.0238			.0505	.0397	.0367	.0264	.0339	.0296	.0255	.0262
.80	.0264	.0292	.0232	.0313	.0306	.0303	.0393	.0386	.0332	.0327	.0381	.0315	.0289	.0361
.90	.0215	.0280	.0215	.0253			.0365	.0329	.0261	.0333	.0281	.0315		
.95									.0240	.0293	.0255	.0270		.0525

Cp at y/b of

TAIL 2

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0388	.0890	.1667	.1346			.2037	.1191			.1907	.1303	.2550	.1330
.10	.0295	.0637					.2112	.1408	.2215	.1376			.3596	.1296
.15					.1787	.1336	.2042	.1364	.2194	.1375			.2374	.1195
.20	.0209	.0746					.1957	.1322	.2135	.1335	.2195		.2084	.1054
.25	.0188	.0606	.0388	.0933	.1691	.1289	.1903	.1298	.2070	.1317	.2222	.1313	.2016	.0933
.30			.0048	.0048			.1827	.1191	.2017	.1284	.2089	.1328	.1935	.0921
.40	.0386	.0051					.0190	.0005	.0559	.0223	.2089	.1183	.1830	.0841
.50	.0253	.0162	.0188	.0133	.0131	.0009	.0099	.0074	.0318	.0031	.0577	.0106	.1557	.0552
.60	.0400	.0370	.0484	.0509	.0069	.0123	.0217	.0354	.0232	.0022	.0164	.0216	.0297	.0435
.70					.0459	.0500	.0500	.0552	.0245	.0399	.0357	.0511	.0338	.0457
.80	.0496	.0496	.0485	.0509	.0453	.0484	.0481	.0503	.0459	.0465	.0443	.0483	.0411	.0386
.90	.0436		.0486	.0500	.0437	.0464	.0460	.0484	.0446	.0463	.0451	.0443		.0423
.95											.0455	.0448		

TABLE XVIII.- CONTINUED
(j) α = 15.34°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05							.3034	.4485					.21??	
.10	.2634	.3401	.3629	.4524	.3356	.4031					.3?2?			
.15	.2555	.3234	.3650	.4502	.339?	.4284								
.20	.2289	.3024	.355?	.44??	.3567	.4130								
.25	.0915	.107?	.3473	.4359	.3327	.4177	.2599	.3416	.3297		.3251			
.30	.0953	.086?			.3237	.4?4?	.3227	.4??8			.3??2			
.40	.0885	.1027	.1030	.1257	.0992	.1288	.106?	.1358	.3229	.398?	.3104		.2180	
.50			.0837	.1046	.0881	.1134	.0827	.111?	.1252	.1517	.1231		.2205	
.60	.0658	.0991	.0735	.0913	.0824	.1068	.0490	.072?	.2818		.0769	.0875	.3020	
.70	-.0105	.0111	-.0150	-.0064	.0743	.0981	-.0468	.0576	-.0101	-.0058	-.0224	-.0162	-.0128	-.0148
.80	-.0106	-.0122	-.0068	-.0156			-.0335	-.0228	-.0242	-.0221	-.0211	-.029?	-.0320	-.025?
.90	-.0038	-.0079	-.0038	-.0083	-.0184	-.0210	-.0206	-.0267	-.0133	-.0198	-.0115	-.0159		
.95							-.0163	-.0189	-.0104	-.0126	-.0093	-.0117	-.0366	

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0445	.1415	.1745	.2087			.2047	.1888			.1825	.2033	.2564	.2087
.10	.0297	.1132					.2096	.2233	.2159	.2162			.2480	.2114
.15					.1782	.2151	.2001	.2183	.2134	.2210			.2309	.2004
.20	.0213	.1269	.0361	.1521	.1651	.2077	.1909	.2148	.2068	.2170	.2083	.2159	.2015	.1882
.25	-.0250	.1064	-.0094	.0359			.1833	.2110	.1981	.2155	.2101	.2196	.1913	.1718
.30							.1737	.1975	.1922	.2116	.1950	.2063	.1802	.1665
.40	.0288	.0140							.0514	.0670			.1698	.1551
.50					.0078	.0312	.0146	.0361	.0265	.0436	.0493	.0473	.1449	.1148
.60	-.0347	-.0037	-.0279	.0124			.0045	.0295	.0174	.0360	.0096	.0042	-.0318	-.0360
.70					-.0129	.0180	-.0264	-.0134	-.0287	-.0307	-.0398	-.0426	-.0349	-.039?
.80	-.0415	-.0210	-.0498	-.0405	-.0503	-.0416	-.0530	-.0452			-.0459	-.0472	-.0368	-.0388
.90	-.0453	-.0458	-.0518	-.0514	-.0492	-.0499	-.0481	-.0493	-.0419	-.0463	-.0397	-.0431	-.0412	-.0431
.95			-.0523	-.0537	-.0475	-.0507	-.0463	-.0504	-.0419	-.0468	-.0393	-.0413		

TABLE XVIII.- CONCLUDED
(k) α = 19.95°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.3721				.4395	.5247	.3968	.5744					.2251	.2153
.10	.3555	.4668	.4855	.5985	.4480	.5572			.4083	.5146	.1963			.2219
.15	.3234	.4431	.4882	.5935	.4444	.5386			.3940	.4820				.2236
.20	.3234	.4155	.4749	.5872	.4405	.5454	.3432	.4283	.3906	.4766	.1850	.2533		.2215
.25	.1505	.1715	.4650	.5768	.4368	.5410	.4300	.5305	.3900	.4672	.1847	.2518		
.30	.1523	.1719	.1537				.1670	.1947	.3754	.4568	.1913			.2213
.40	.1513	.1686	.1416		.1602	.1902	.1383	.1645	.1511	.1870	.1840	.2415		.2134
.50					.1512	.1748	.0800	.1031			.0548	.0725		.0292
.60					.1475	.1657	.0893	.0993	.1086	.1355	.0213	.0345		.0405
.70	.1220	.1627	.1238	.1453	.1352	.1565	-.0166	.0011	-.0104	.0064	-.0377	-.0288		.0572
.80	.0156	.0432	.0074	.0170			-.0086	-.0069	-.0184	-.0133	-.0341	-.0327		
.90	.0194	.0125	.0184	.0055	-.0014	-.0024	.0000	-.0054	-.0113	-.0157	-.0314	-.0289		
.95	.0248	.0254	.0232	.0169					-.0039	-.0075	-.0304	-.0275		-.0518

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0608	.2115	.1972	.3087			.2224	.2842			.1891	.3010	.2671	.3117
.10	.0394	.1820					.2250	.3333	.2279	.3243			.2552	.3223
.15					.1940	.3230	.2135	.3282	.2261	.3325			.2381	.3099
.20	.0259	.2042					.2029	.3244	.2180	.3287			.2115	.2898
.25	.0233	.1660	.0408	.2354	.1775	.3120	.1931	.3189	.2076	.3261	.2155	.3311	.1982	.2762
.30			-.0084	.0846			.1825	.3018	.2010	.3198	.2169	.3372	.1839	.2641
.40	.0235	.0289							.0530	.1281	.2008	.3157	.1731	.2516
.50					.0087	.0797	.0170	.0892	.0274	.1007	.0504	.1008	.1474	.2007
.60	-.0381	-.0360	-.0303	.0643			.0061	.0827	.0186	.0914	.0101	.0518	-.0306	-.0180
.70					-.0132	.0624	-.0258	-.0204	-.0302	-.0137	-.0405	-.0228	-.0339	-.0258
.80	-.0443	-.0041	-.0529	-.0224	-.0512	-.0260	-.0512	-.0266	-.0364	-.0323	-.0391	-.0293	-.0296	-.0236
.90	-.0517	-.0337	-.0552	-.0384	-.0494	-.0374	-.0447	-.0342	-.0383	-.0359	-.0339	-.0315	-.0339	-.0302
.95	-.0552		-.0552	-.0425	-.0475	-.0401	-.0435	-.0376			-.0338	-.0335		

TABLE VIX.- PRESSURE COEFFICIENTS, φ = 45°, δ = -15°, M = 1.50
(a) α = -1.25°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2366	.0205	.3742	-.3035	.3500	-.3655	1.0352	-.3933	-.3243	-.3907	.3535	-.2861	.6931	-.3765
.10	.2629	-.0148	.3844	-.3506	.3759	-.3199		-.3954	.3954	-.3668			.6630	-.3425
.15	.3123	-.0425	.9383	-.2140	.9001	-.2751		-.3221	.3113	-.3221				
.20	.3389	-.0739	.7762	-.1827	.8137	-.2477	.8345	-.2845	.8420	-.2838	.8655	-.3055		
.25	.4009	-.1857					.7552	-.2453	.7823	-.2838				
.30	.4529	-.2334	.3561	-.3135	.4172	-.3808	.3495	-.3786	.3986	-.3665	.3407	-.2810		
.40			.4617	-.2851	.5316	-.3720	.5719	-.3861	.3637	-.3757	.3618	-.3634		
.50					.5004	-.3655	.5250	-.3738			.3679	-.2887		
.60	.3749	-.2793	.3908	-.2987	.3591	-.3512	.3831	-.4115	.3968	-.4086	.3968	-.3086	.3007	-.4633
.70	.1993	-.3658	.3412	-.4037			-.0070	-.4167	.3005	-.4028	-.3197	-.4113	.631	-.4733
.80	-.1757	-.3922	-.0810	-.3829	-.0281	-.3922	-.0274	-.4058	-.0282	-.4038	-.0478	-.4110	.3652	-.4642
.90	-.1350	-.3783	-.0019	-.3485			-.0377	-.3922	-.0410	-.4020	-.0609	-.4104	-.3573	-.4573
.95									-.0410	-.3985	-.3740	-.4074	-.1793	-.4473

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.5106	-.2746	1.2560	-.3811			1.2150	-.4088					.9762	-.3863
.10	.5337	-.0819					1.1424	-.3957	1.1390	-.3998			.9375	-.3925
.15					1.0301	-.3280	1.0762	-.3532	1.0869	-.3604	1.0248	-.2804		
.20	.8197	-.0169					-.0012	-.3171	.0246	-.3208			.7610	-.2971
.25	.5169	-.1025	.4019	-.2802	.8895	-.2812	.9309	-.2963	.9532	-.2963	.9505	-.3356	.7154	-.3011
.30			.5745	-.3327			.8455	-.2907	.8880	-.2850	.3936	-.3.97	.6543	-.3016
.40	.8313	-.1404							.6177	-.3797	.7161	-.2984	.5622	-.3323
.50					.7582	-.3570	.7421	-.3591	.7077	-.3577	.5119	-.3127	.3737	-.3725
.60	.6558	.0103	.7337	-.0488			.6871	-.3462	.6445	-.3512	.3745	-.2773	-.233	-.3942
.70					.5882	-.2593	.2133	-.3351	.3658	-.3194	.2231	-.2587	-.1036	-.3967
.80	-.063C	-.1629	.1013	-.2709	.0877	-.3735	-.0677	-.3282	.0421	-.2973	.0121	-.2620		
.90	.2323	-.2369	.0756	-.2413	.0758	-.3322	.0685	-.2873	.0350	-.2892	.0015	-.2632	.1020	-.3829
.95			.0568	.C97	.0740	-.2488	.0668	-.2434			-.0087	-.2636	-.1114	-.3761

TAIL 2

TABLE XIX. - CONTINUED
(b) α = -1.25°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.3882	.0344	.9833	-.2547	.9318	-.3389	1.0150	-.3517	.9115	-.3567				
.10	.3868	-.0152	.8806	-.1966	.3397	-.2815			.3754	-.3122	.9350	-.2823		
.15	.4255	-.0317	.8118	-.1566	.8605	-.2355	.9955	-.2208	.9955	-.2690			.6846	-.3416
.20	.4221	-.0556	.7271	-.1594	.7753	-.2079	.8123	-.2209	.7664	-.2405	.8481	-.2558	.6422	-.2744
.25	.4221		.7271		.6832	-.1891	.7216	-.2023	.6941	-.2249	.7953	-.2399	.5527	-.1885
.30	.7001	.1858	.3307	-.2074	.3118	-.3552	.2752	-.3513	.2225	-.3133	.7153	-.2073	.4864	-.1619
.40	.1215	-.1763	.1419	-.2657	.1616	-.3566	.4953	-.3668			.5678	-.2073	.4071	-.1707
.50							.4031	-.3641			.2158	-.3633		
.60	.3321	-.2496	.3513	-.2725	.4538	-.3455	.3600	-.3924	-.0314	-.3886	.3162	-.3881	-.2917	-.4422
.70	-.2214	-.3513	-.0599	-.3945	.4361	-.3302	-.0242	-.3990	-.0354	-.3892	-.0131	-.3992	-.2238	-.4481
.80									-.0477	-.3868	-.0567	-.4057	-.1646	-.4566
.90	-.1903	-.3845	-.0912	-.3787	-.0461	-.3858	-.0484	-.3916			-.0728	-.4077	-.1633	-.4476
.95	-.561	-.3827	-.1140	-.3437			-.0599	-.3804	-.3610	-.3838	-.0873	-.3988	-.1752	-.4381

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.5474	-.1110	1.1701	-.3287			1.1493	-.3770					.9034	-.3700
.10	.5533	-.0406					1.0709	-.3496	1.0766	-.3521			.9046	-.3782
.15					.9522	-.2806	1.0023	-.2955	1.0246	-.3016	1.0036	-.2910		
.20	.6671	.0343	.3047	-.2250			.9261	-.2633	.9620	-.2694			.7196	-.2654
.25	.3857	-.0431			.7978	-.2309	.8554	-.2455	.8913	-.2513	.8999	-.2883	.6724	-.2412
.30			.3584	-.3023			.7689	-.2432	.8258	-.2466	.8416	-.2691	.6112	-.2314
.40	.7266	-.1283							.5342	-.3822	.6645	-.2541	.5188	-.2183
.50					.6979	-.3379	.6910	-.3785	.6779	-.3654	.4413	-.3027	.3351	-.2480
.60	.5717	.0015	.6670	-.0470			.6487	-.3455	.6121	-.3447	.3537	-.2801	-.1571	-.3868
.70					.5567	-.2436	.1994	-.3302	.0526	-.3087	.0122	-.2712	-.1228	-.3783
.80	-.0790	-.1623	.0848	-.2763	.0741	-.3633	.0480	-.3152			-.0074	-.2722		
.90	.2010	-.2384	-.0547	-.2463	.0539	-.3045	.0433	-.2939	.0172	-.2951	-.0230	-.2747	-.1283	-.3723
.95			-.0346	-.1133	.0501	-.1781	.0410	-.2439	.0065	-.2935	-.0343	-.2725	-.1398	-.3625

205

TABLE XIX.. CONTINUED
(c) α = 0.75°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.4934	.0464	.9433	-.2130	.9094	-.2924	1.0030	-.3020	.9983	-.3193	.9271			
.10	.4577	.0054	.8459	-.1508	.9179	-.2289			.3657	-.2536				
.15	.4915	-.0086	.7736	-.1176	.8384	-.1846			.8827	-.2095	.8387			
.20	.4847	-.0210	.6921	-.0975	.7555	-.1589	.7972	-.1754	.8140	-.1762	.7870			
.25					.6668	-.1471	.7176	-.1548	.7550	-.1635	.7058			
.30	.3378	-.1758	.2853	-.2831	.2458	-.3333	.2061	-.3317	.6755	-.1553				
.40	.3918	-.1276	.3673	-.2617	.3562	-.3337	.3166	-.3447	.1192	-.2293	.5607			
.50					.4275	-.3183	.4453	-.3445			.0795			
.60	.3078	-.2181	.2970	-.2473	.3892	-.3028	.3441	-.3744	-.0177	-.3743	.1325			
.70	-.2327	-.3339	-.0807	-.3840			-.0387	-.3865	.0484	-.3747	-.0705			
.80	-.2027	-.3731	-.1044	-.3714	-.0685	-.3744	-.0636	-.3825	-.0621	-.3727	-.0762			
.90	-.1601	-.3792	-.1224	-.3394			-.0760	-.3712	-.0743	-.3697	-.0890			
.95											-.1030			

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.88 U.S.	0.88 L.S.	0.98 U.S.	0.98 L.S.
.05	.4590	.0069	1.0753	-.2721			1.0819	-.3449	.9925	-.3033			.9275	-.3424
.10	.4600	-.0103					.9929	-.2962	.9345	-.2543			.8400	-.3398
.15					.8842	-.2226	.9178	-.2368			.9452	-.2743		
.20	.5157	.0519	.2628	-.1600			.8328	-.2096	.8671	-.2259			.6655	-.2342
.25	.3082	-.0175			.7177	-.1800	.7492	-.1981	.7876	-.2108	.8273	-.2431	.6154	-.1845
.30			.2241	-.2622			.6456	-.2038	.7182	-.2057	.7689	-.2172	.5529	-.1713
.40	.5710	-.1109							.3854	-.3532	.5967	-.2085	.4630	-.1544
.50					.6633	-.3187	.6836	-.3566	.6189	-.3662	.3254	-.3104	.2874	-.1782
.60	.4520	-.0071	.6029	-.0398			.6152	-.3510	.5755	-.3406	.3431	-.2861	.2256	-.3538
.70					.5327	-.2387	.1760	-.3631	.0395	-.3165	-.0070	-.2829	.1517	-.3491
.80	-.1050	-.1613	.0406	-.2809	.0463	-.3224	.0322	-.3193	-.0043	-.3002	-.0327	-.2800	-.1518	-.3491
.90	-.1464	-.2301	.0178	-.2469	.0143	-.2256	.0186	-.2838	-.0158	-.2972	-.0506	-.2775	-.1625	-.3425
.95			.0015	-.1267	.0113	-.0997	.0127	-.2314			-.0623	-.2737		

TAIL 2

TABLE XIX. - CONTINUED
(d) a = 2.75°

Cp at η/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.89 U.S.	0.89 L.S.	0.98 U.S.	0.98 L.S.
.05	.5367	.0444	.9151	-.1570	.8893	-.2373	.9852	-.2446	.9841	-.2720	.9287	-.2350		
.10	.36-	.3281	.8155	-.0991	.8966	-.1704			.3527	-.1833				
.15	.5558	.0146	.7448	-.0636	.8178	-.1246			.8678	-.1388			.5939	-.2472
.20	.538-	.0146	.6639	-.0508	.7385	-.1008	.7799	-.1176	.8025	-.1144	.8255	-.1387	.6163	-.1372
.25					.6525	-.0936	.7057	-.008	.7454	-.1031	.7741	-.1220	.5245	-.0239
.30	.2390	-.1612	.2471	-.2551	.1976	-.3077	.1500	-.3027	.6662	-.0962	.6933	-.1030	.4613	-.0358
.40	.3563	-.0862	.2127	-.2390	.2753	-.3104	.2545	-.3174	.0889	-.3048	.5489	-.1012	.3837	-.0444
.50					.2447	-.2852	.3167	-.3179			.0455	-.3075		
.60	.2563	-.1855	.2512	-.2127	.3642	-.2855	.2956	-.3531	-.0770	-.3621	.0798	-.3400	.3114	-.3897
.70	.2-3-	-.3126	.1066	-.3754			-.0483	-.3712	-.0749	-.3602	-.1470	-.3775	.3060	-.4145
.80	.5-3	-.3569	-.1293	-.3753	-.0850	-.3616	-.0739	-.3751	-.0770	-.3596	-.1434	-.3831	.2734	-.4693
.90		-.3664	-.1404	-.3402			-.0864	-.3537	-.0876	-.3573	-.1403	-.3866	.2339	-.4771
.95											-.1472	-.3761	.2336	-.4719

Cp at η/b of

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.89 U.S.	0.89 L.S.	0.98 U.S.	0.98 L.S.
.05	.3657	.0380	.9504	-.2166			1.0261	-.3048					.7653	-.3114
.10	.3554	.0097					.9398	-.2370	.9345	-.2568	.8920	-.2466	.7732	-.2974
.15					.8359	-.1551	.8677	-.1785	.8776	-.2076				
.20	.3897	.0598	.2270	-.0787	.6845	-.1240	.7877	-.1551	.8116	-.1797	.7678	-.1918	.6133	-.2026
.25	.2335	-.0058	.1211	-.2286			.7090	-.1450	.7337	-.1635	.7067	-.1741	.5579	-.1500
.30							.6094	-.1494	.6627	-.1604	.5253	-.1659	.4930	-.1276
.40	.4445	-.0921							.1160	-.3209	.0911	-.3366	.3983	-.1045
.50					.3698	-.2861	.3194	-.3276	.2399	-.3394	.0585	-.2938	.2285	-.1343
.60	.3463	-.0193	.4392	-.0380			.5097	-.3230	.4869	-.3410	-.0548	-.2934	.3185	-.2934
.70					.4727	-.1954	.1616	-.3630	.0220	-.3358	-.0477	-.2827	.2923	-.3017
.80	.4--	-.1700	.0009	-.2825	.0300	-.2933	.0150	-.3202			-.0656	-.2769		
.90	.0923	-.2179	.2283	-.2410	-.0083	-.2467	-.0072	-.2907	-.0180	-.2975	-.0807	-.2727	.1825	-.3197
.35			-.0529	-.301	-.0177	-.1120	-.0165	-.2166	-.0366	-.2872			.1595	-.3218

207

TABLE XIX.- CONTINUED
(e) α = 4.75°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.6222	.0475	.8700	-.0853	.6645	-.1744	.9603	-.1792	.3634	-.2082				
.10	.5461	.0607	.7743	-.0349	.8720	-.0997			.3597	-.1078	.3213	-.1813		
.15	.5726	.0415	.7102	-.0156	.7946	-.0537			.3513	-.0578			.5424	
.20	.5413	.0402	.6532	.0015	.7198	-.0331	.7645	-.0663	.3872	-.0490	.8119			
.25					.6378	-.0632	.6355	-.0375	.7315	-.0400	.7585			
.30	.2155	-.1374	.2062	-.2250	.1540	-.2944	.1173	-.2657	.3554	-.0353	.6785	-.0472	.1482	
.40	.3053	-.0462	.2557	-.2140	.2224	-.2791	.2055	-.2854	.0753	-.2722	.5336	-.0422	.3752	
.50					.2224	-.2781	.2055	-.2731			.0303	-.2787		
.60					.2662	-.2678		-.2911			.0436	-.3107	.3129	-.3762
.70	.2160	-.1510	.2254	-.1598	.3031	-.2649	.1825	-.3274	-.1149	-.3588	-.1867	-.3578	-.2875	-.4063
.80	-.2628	-.2936	-.1210	-.3632			-.0813	-.3575	-.1239	-.3517	-.1898	-.3682	-.2553	-.16.5
.90	-.2296	-.3230	-.1501	-.3393	-.1001	-.3505	-.0948	-.3611	-.1201	-.3507	-.1855	-.3635	-.2446	-.4599
.95	-.1839	-.3444	-.1576	-.3251			-.105	-.3507	-.1254	-.3478	-.1913	-.3594	-.2440	-.4511

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2532	.0406	.8055	-.1600			.9661	-.2354					.7001	-.2773
.10	.2390	.0232					.8792	-.1522	.8807	-.1908			.7003	-.2550
.15					.7589	-.0874	.8105	-.1081	.8273	-.1427	.8467	-.2052		
.20	.2651	.0676					.7355	-.0922	.7670	-.1120			.5764	-.1602
.25	.1201	.0104	.1604	-.0171	.6283	-.0797	.6653	-.0865	.6961	-.0929	.7253	-.1341	.5229	-.1167
.30			.0277	-.2172			.5752	-.0962	.6297	-.0932	.6680	-.1141	.4586	-.0844
.40	.3375	-.0708							.0439	-.2912	.4942	-.1099	.3667	-.0712
.50					.2188	-.2487	.2087	-.2989	.1635	-.3076	-.0299	-.3053	-.2037	-.1053
.60	.2944	-.0330	.3594	-.0371			.2733	-.2877	.2276	-.3099	.0079	-.3031	-.3309	-.2782
.70					.3726	-.0926	.1140	-.3411	-.0708	-.3345	-.1685	-.2936	-.3241	-.2827
.80	-.1382	-.1727			-.0338	-.2818	-.0391	-.3148	-.0670	-.3098	-.1649	-.2883		
.90	-.1842	-.2131	-.0902	-.2159	-.0591	-.2435	-.0583	-.2878	-.0872	-.2913	-.1574	-.2775	-.2772	-.2944
.95	-.0870	-.1115			-.0566	-.1163	-.0565	-.1773			-.1595	-.2732	-.2721	-.2956

TABLE XIV - CONTINUED
(1) = 5.74°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.583.	.0686	.8072	.0111	.3263	-.0910	.9243	-.0973	.9333	-.1294				
.10	.5097	.0924	.7132	.0302	.835.	-.0112			.5129	-.0227	.8942	-.0919		-.1002
.15	.5252	.0750	.6553	.0386	.7613	-.0254	.7403	.0211	.9235	.0256			.5132	-.0906
.20	.4853	.0712	.53..	.52.	.6314	.0327	.7403	.0211	.7668	.0256	.7905	.0116	.5735	.0887
.25					.6166	.0367	.6718	.0353	.7147	-.0334	.7387	.0215	.389.	.0570
.30	.1510	-.1064	.1394	.1359	.111.	-.2414	.0925	-.2337	.6422	.0350	.6627	.0256	.4347	
.40	.2331	.00.0	.1910	.1907	.3587	-.2.54	.1456	-.25.5	.0641	-.2334	.5282	.0256	.3661	
.50					.941.	-.2457	.1824	-.252.			.0176	-.24.		
.60					.2053	-.2421	.1242	-.3008			.0134	-.27.6	.311.6	-.3624
.70	.1894	-.1085	.1937	-.1294			.1343	-.3466	.1547	-.3690	-.2180	-.3673	-.2787	-.3886
.80	.2635	-.2735	.1387	-.3440			.1336	-.3453	.1681	-.3463	-.2257	-.3563	-.2607	-.4480
.90	.2427	-.3070	.1667	-.3397	.1148	-.3406	.1367	-.3353	.1719	-.3434	-.2260	-.3567	-.2387	-.4341
.95	.2046	-.3192	.1708	-.3099					.1786	-.3390	-.2329	-.3455	-.2394	-.4236

Cp at y/b of

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2288	.0562	.7012	-.0946			.8800	-.1637					.6127	-.2419
.10	.1987	.0413					.7946	-.0824					.5760	-.2027
.15					.6735	-.0227	.734.	-.0442	.8100	-.1304	.7796	-.1473		
.20	.2246	.0848	.1058	.0174	.5663	-.0107	.668.	-.0282	.7606	-.0802			.5399	-.1077
.25	.1108	.0196	-.0016	-.2002			.6050	-.0223	.7034	-.0390	.6799	-.072.	.4865	-.0871
.30							.5248	-.0268	.6378	-.0251	.6269	-.0525	.4224	-.0634
.40	.3150	-.0634							.5798	-.0327	.4650	-.0529	.3369	-.0354
.50					.1792	-.1922	.1577	-.2480	.0130	-.2575	-.0006	-.2721	-.1611	-.0818
.60	.3148	-.0410	.3477	-.0287			.2482	-.2579	-.1083	-.2706	-.0336	-.2984	-.34C3	-.2740
.70					.3407	-.0558	.0958	-.2572	-.1687	-.2702	-.2061	-.2812	-.3323	-.2781
.80	.0755	-.1900	-.0659	-.2820	-.0433	-.2762	-.0558	-.2983	-.0727	-.3232	-.1991	-.2792		
.90	.16.9	-.2410	-.0956	-.2.53	-.0839	-.2663	-.0704	-.2710	-.0749	-.2832	-.1791	-.2642	-.2935	-.2708
.95			-.C147	-.120	-.0897	-.1520	-.0757	-.1616	-.0955	-.2576	-.1760	-.2598	-.2753	-.2722

TABLE XIX.- CONTINUED
(g) α = 8.75°

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.93		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.5215	.0819	.7511	.0632	.7876	-.0095	.8829	-.0121	.8967	-.0438	.8890	.0005	.4944	.0175
.10	.4722	.1258	.6572	.0955	.7933	.0793			.8856	.0500	.3855	.0000	.5522	.1533
.15	.4626	.1080	.6653	.0949	.7233	.1061	.7112	.0765	.8013	.0900	.7663	.0877	.4658	.1380
.20	.4255	.1045	.5993	.1056	.6574	.1140	.6480	.1122	.7441	.1050	.7150	.0960	.4150	.1130
.25					.5917	.1043			.6951	.1079	.6413	.0653		
.30	-.1022	-.0724	-.0702	-.1634	-.0776	-.2078	-.0722	-.1947	.6258	.1050	.5127	.0975	.3992	.1132
.40	.1412	.0528	.144	-.1633	.1022	-.2136	.1015	-.2152	.0532	-.1918	.0036	-.2159	.3051	.1080
.50					.1227	-.2108	.1245	-.2232			.2147	-.2454	-.3051	-.3397
.60	-.1519	-.0600	.1691	-.0933	.1235	-.2141	.0737	-.2712	-.1904	-.3786	-.2557	-.3715	-.2761	-.3622
.70			-.1684	-.3185			-.1818	-.3367	-.2067	-.3385	-.2561	-.3473	-.2551	-.4404
.80	-.2768	-.2425	-.1814	-.3246	-.1487	-.3233	-.1901	-.3311	-.2144	-.3354	-.2580	-.3431	-.2039	-.4160
.90	-.2555	-.2829	-.1860	-.3033			-.1928	-.3194	-.2239	-.3286	-.2639	-.3348	-.2139	-.3966
.95	-.2242	-.2929												

TAIL 2

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.57		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1987	.0794	.6000	-.0264			.7814	-.0868					.5523	-.2115
.10	.1765	.0693					.7018	-.0061	.7295	-.0624			.4980	-.1507
.15					.5814	-.0537	.6512	-.0328	.6852	-.0223	.7361	-.0849	.4957	-.0654
.20	.2357	-.0968	.0673	.0425	.4921	.0741	.5936	-.0543	.6361	-.0453	.6220	.0072	.4432	-.0463
.25	.1786	-.0240	.0012	-.1789			.5375	-.0697	.5778	-.0547	.5747	.0178	.3820	-.0141
.30							.4655	.0555	.5250	-.0515	.4276	.0058	.2986	-.0113
.40	.2994	-.0613			.1884	-.1416	.1092	-.2034	-.0182	-.2075	-.0309	-.2387	-.1500	-.0382
.50							.2347	-.1458	.0543	-.2251	-.0751	-.2891	-.3484	-.2679
.60	.3010	-.0532	.3070	-.0274	.2812	-.0399	.0457	-.2237	.1116	-.2258	-.2418	-.2747	-.3185	-.2752
.70					-.0680	-.2733	-.0911	-.2842	-.0983	-.3127	-.2320	-.2752		
.80	-.0144	-.2064	-.1037	-.2825	-.1117	-.2702	-.0945	-.2862	-.0970	-.2623	-.2141	-.2554	-.2690	-.2489
.90	-.1187	-.2434	-.0640	-.2238	-.1232	-.1827	-.1002	-.2193	-.1186	-.2367	-.2058	-.2470	-.2602	-.2405
.95			-.0167	-.1199										

TABLE XIX.- CONTINUED
(h) α = 10.75°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.4299	.1199	.7097	.1578	.7390	.0782	.8365	.0790	.8476	.0513	.8409	.0937		
.10	.4317	.1552	.6077	.1751	.7447	.1805			.8477	.1582				
.15	.4112	.1429	.5540	.1649	.6804	.1911			.7656	.1807			.4715	.1266
.20	.3782	.1431	.5020	.686	.6293	.1947	.681	.1849	.7114	.1907	.7227	.1644	.5.56	.2116
.25					.5657	.1748	.6243	.1953	.6663	.1897	.6812	.1736	.4331	.1961
.30	.0670	-.0307	.0217	-.231					.6025	.1853	.6103	.1748	.3931	.1765
.40	.0734	.1098	-.2424	-.350	.0538	-.1699	.0563	-.1551	.0431	-.1487	.4898	.1618	.3.67	.1681
.50					.6625	-.1805	.0684	-.1774			-.0114	-.1826		
.60					.613	-.1812	.0802	-.1797			-.0382	-.2093		
.70	-.1077	-.0192	-.1113	-.0580	.0563	-.1869	-.0265	-.2427	-.2213	-.3644	-.2644	-.3601	-.2827	-.3109
.80	-.2879	-.2177	-.1937	-.2915			-.2221	-.3188	-.2398	-.3208	-.2735	-.3296	-.2614	-.3262
.90	-.2705	-.2593	-.2076	-.3018	-.2064	-.3040	-.2357	-.3128	-.2474	-.3164	-.2691	-.3229	-.1789	-.4264
.95	-.2420	-.2672	-.2040	-.2956			-.2423	-.3026	-.2562	-.3116	-.2709	-.3155	-.2175	-.3866

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1886	.1007	.5258	.3387			.6724	-.0055	.6328	.0285	.6347	-.0029	.5023	-.1313
.10	.1976	.0884					.5926	.0763	.5926	.1190			.4517	-.0679
.15					.4786	.1342	.5491	.1281	.5325	.1412				
.20	.2367	.1035	.0173	.0632	.4004	.1261	.4998	.1628	.5497	.1339	.5575	.1214	.4547	-.0040
.25	.1954	.0183	-.0066	-.1658			.4543	.1463	.4996	.1134	.5188	.1402	.4054	.0406
.30							.3935	.1086	.4523	.1134			.3473	.0877
.40	.2834	-.0609			.1728	-.0857			-.0537	-.1872	.3897	.1022	.2661	-.0864
.50							.0498	-.1469	-.0015	-.1993	-.0560	-.1950	.1258	-.0057
.60	.2666	-.0649	.2612	-.0325	.2217	-.0379	.2046	-.1067	-.0527	-.1581	-.1100	-.2648	.2952	-.3209
.70					-.1290	-.2787	.0013	-.2065	-.1216	-.3142	-.2723	-.3217	-.2974	-.3062
.80	.0065	-.2237	-.1328	-.2657	-.595	-.2716	-.1347	-.2811			-.2524	-.3055		
.90	.1.04	-.2540	-.0395	-.2458			-.1471	-.2800	-.1463	-.2705	-.2312	-.2770	-.2640	-.2725
.95			-.0163	-.329	-.1657	-.2081	-.1528	-.2294	-.1647	-.2355	-.2194	-.2461	-.2395	-.2454

TAIL 2

211

TABLE XIX.- CONTINUED
(I) α = 12.75°

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.57		0.33		0.58	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.3956	.1538	.6590	.2498	.6332	.1747	.7829	.1632		.308				
.10	.4046	.1873		.2446	.6008	.2977							.4720	.2366
.15	.3802	.1820		.2203	.6375	.2866								
.20	.3333	.1851		.2.63	.5949	.2688	.6412	.2655						.2493
.25						.2429	.5392	.2065		.2977				.2470
.30	.0355											.2347		
.40	.0051	.0917	.0483	.0877	.0288	.1402	.0362	.1256	.0233	.1113				
.50			.0129	.1066	.0327	.1658	.0336	.1543					.2784	
.60					.0239	.1557	.0379	.1579						.2847
.70	.0607	.0306	.0334	.0233	.0063	.1533	.0133	.2234	.2377	.2443			.1989	.3863
.80	.3009	.1885	.2251	.2502			.2446	.3097	.2552	.3097			.2240	.3935
.90	.2855	.2384	.2494	.2758	.2511	.2897	.2561	.3002	.2627	.3017			.2273	.3797
.95	.2610	.2427	.2443	.2777			.2632	.2888	.2714	.2363				

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1913	.1112	.4555	.1012			.5563	.0804					.4639	.0173
.10	.2169	.1664					.4766	.1749	.5112	.2066	.5326	.1755	.4351	.0340
.15					.3701	.1797	.4296	.2085	.1775	.2175				
.20	.2230	.1001	.0311	.3093	.2991	.1514	.3882	.1835	.1425	.2.22	.1622	.2203	.3975	.1982
.25	.1803	.0082	.0255	.1152			.3475	.1608	.1023	.1935	.1453	.2061	.3524	.1761
.30							.2971	.1138	.3702	.1650	.3713	.305	.2933	.1440
.40	.2623	.0756			.1024	.0538	.0093	.1126	.0834	.1855	.0828	.1478	.2254	.0902
.50							.1462	.0470	.0521	.1322	.057	.2211	.0963	.0174
.60	.2653	.0823	.2267	.0343	.1824	.0327	.0458	.1800	.0025	.190	.2994	.3301	.2840	.3181
.70					.507	.2718	.1498	.2696	.507	.2501	.2660	.2920	.285	.3098
.80	.0778	.2350	.1031	.2381	.2030	.2808	.1785	.2811	.1573	.2680	.2633	.2747	.2683	.2518
.95	.0675	.2844	.0960	.1641	.1875	.2318	.1895	.2320	.1755	.2493	.2418	.2497	.2416	.2389

TAIL 2

TABLE XIX.- CONTINUED
(j) α = 16.77°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.3553	.2328	.5667	.4176	.5926	.4358	.6273	.4351	.6190	.4554	.7126	.5282		
.10	.3640	.2661	.4647	.3842	.5996	.4921			.6854	.5021			.4808	.4652
.15	.3166	.2517	.4152	.3476	.5271	.4309	.5383	.4143	.5196	.4827	.6285	.4897	.4511	.4282
.20	.2508	.2701	.3658	.3295	.4784	.4013	.5036	.4048	.5895	.4620	.5884	.4890	.4066	.3934
.25					.4278	.3727			.5664	.4426	.5265	.4359	.4113	.3702
.30	-.0315	.1121	-.0826	-.0205	-.0176	-.0833	-.0094	-.0559	.5239	.4211	.4423	.3533	.3695	.3503
.40	-.1380	.2376	-.1008	-.0175	-.0276	-.0929	-.0026	-.0803	.0156	-.0424	-.0235	-.0778		
.50					-.0311	-.0764	-.0067	-.0866			-.0699	-.1312	-.2395	-.2565
.60					-.0482	-.0709	-.0599	-.1583			-.2889	-.3254	-.1332	-.2020
.70	-.0638	.1464	-.0781	.0750			-.2789	-.2973	-.2696	-.3186	-.2977	-.2983	-.2083	-.2697
.80	-.3358	-.1244	-.2982	-.1808			-.2899	-.2697	-.2833	-.2873	-.2792	-.2839	-.2856	-.3859
.90	-.3061	-.2356	-.3032	-.2131	-.2610	-.2445	-.2676	-.2655	-.2926	-.2726	-.2728	-.2822	-.2912	-.3696
.95	-.2636	-.2262	-.2799	-.2242					-.2783	-.2690				

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2309	.0809	.3163	.1462			.3118	.2648					.3781	.3994
.10	.2943	.0681					.2574	.2634	.2629	.2887			.3342	.3452
.15					.1916	.1939	.2175	.2482	.2452	.2839	.3319	.3098	.2218	.2357
.20	.2957	-.0674	-.0194	.0793	.1234	.2093	.1818	.2548	.2145	.2958	.2531	.3163	.1919	.1857
.25	.1158	-.0160	-.0659	-.1215			.1494	.2555	.1800	.2797	.2293	.2933	.1523	.1465
.30							.1083	.1895	.1534	.2350	.1656	.1806	.1029	.0777
.40	.2510	-.1528			.0713	-.0142	-.0203	-.0636	.1889	-.1314	.1746	-.1380	-.0141	-.0637
.50	.2478	-.1417	.2339	-.0599			.0374	.0104	-.1320	-.1117	-.2369	-.2067	-.2831	-.2825
.60					.0105	-.0429	-.1494	-.1873	-.0956	-.0645	-.3036	-.3167	-.3043	-.3001
.70			-.0788	-.3166	-.1755	-.2844			-.2284	-.2369				
.80	-.1348	-.2574	-.1126	-.3107	-.2120	-.3137	-.2238	-.2786	-.2279	-.2739	-.3031	-.2923	-.2871	-.2892
.90	-.0714	-.3233	-.1046	-.2605	-.2160	-.2784	-.2127	-.2892	-.2241	-.2519	-.2842	-.2757	-.2577	-.2559
.95							-.2134	-.2599			-.2567	-.2535		

TAIL 2

213

TABLE XIX.- CONCLUDED
(h) α = 18.76°

TAIL 1

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.3394	.2663	.5186	.5074	.5332	.5368	.5286	.5773	.5429	.6344	.6494	.6495	.4652	.5437
.10	.3507	.3038	.4278	.4490	.5391	.5510			.6337	.6228		.6629		.4677
.15	.3007	.3050	.3722	.4085	.4868	.4986	.5076	.5127	.5740	.5822	.5660	.5763	.3930	.4415
.20	.2245	.3187	.3257	.3866	.4454	.4751	.4719	.4907	.5150	.5251	.5675	.5476	.4165	.4122
.25	-.0584	.1875			.4055	.4379			.4800	.4942	.4858	.4856	.3697	.3847
.30	-.1873	.4207			-.0344	-.0465	-.008	-.0245	.4175					
.40					-.0542	-.0432	-.0284	-.0495	.0001	-.0146				
.50					-.0611	-.0138	-.0331	-.0506			-.0263	.0576	-.2264	.2457
.60	-.1155	-.2053	-.1144	-.1639	-.0746	-.0143	-.0882	-.1312	-.2829	-.3022	-.0770	-.1151	-.1436	-.1845
.70	-.3548	-.0862	-.3222	-.1316			-.2953	-.2613	-.3014	-.2619	-.2953	-.3150	-.2033	-.2353
.80	-.3029	-.2161	-.3341	-.1811	-.2989	-.2063	-.2706	-.2410	-.2641	-.2519	-.3003	-.2804	-.3335	-.3673
.90	-.2544	-.2166	-.3000	-.1975			-.2568	-.2378	-.2555	-.2503	-.2745	-.2697	-.3420	-.3665
.95											-.2673	-.2685		

TAIL 2

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.2420	.0586	.2571	.1369			.2084	.2865	.1568	.3126			.1509	.4526
.10	.3091	.0472					.1692	.2642	.1420	.3210			.2114	.3542
.15					.1310	.2023	.1342	.2682	.1157	.3020	.2518	.3583		
.20	.2737	-.0440	.0219	.0815	.0660	.2011	.1000	.2646	.0847	.2672	.1440	.3021	.1343	.2305
.25	-.0719	-.0455	.0735	-.1036			.0694	.2410	.0591	.2172	.1237	.2666	.1064	.1811
.30							.0280	.1662	-.2132	-.1404	-.0676	-.1489	.0756	.1374
.40	.2250	-.1899			.0247	-.0285	-.0565	-.0488	-.1725	-.1058	-.2256	-.1500	.0312	.0664
.50							-.0079	-.0016	-.0833	-.0354	-.2783	-.2069	-.0467	-.0786
.60	.2311	-.1563	.2411	-.0799	-.0492	-.0581	-.2170	-.1993	-.2655	-.2408	-.3278	-.3114	-.3212	-.3293
.70							-.2486	-.2850			-.3190	-.2910	-.3404	-.3247
.80	-.1240	-.2871	-.0892	-.3288	-.2171	-.2862	-.2640	-.2982	-.2586	-.2826	-.2961	-.2743	-.2915	-.3007
.90	-.0553	-.3393	-.1178	-.3350	-.2485	-.3270	-.2706	-.2918	-.2533	-.2721	-.2748	-.2481	-.2703	-.2727
.95			-.1142	-.2981	-.2551	-.2982								

214

TABLE XX. - PRESSURE COEFFICIENTS, Λ = 45°, δ = -15°, M = 2.36
(a) α = -4.05°

TAIL 1

	Cp at y/b of														
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

	Cp at y/b of														
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

215

TABLE XX - CONTINUED
(b) α = -2.05°

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05			.3577											
.10														
.15														
.20														
.25														
.30														
.40														
.50			.278		.2855				.3150					
.60			.374	.386					.064					
.70			.006	.87					.03					
.90			.002	.757	.0111				.035	.698	.231	.673		
.95				.724					.000	.637	.130	.670		

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.53		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.5134	-.0395	.9899	-.0556				-.0670	.9945	-.0558	.595	-.134	.087	
.10	.450	-.0247												
.15					.8948	-.055								
.20											.725			
.25	.2353	-.245	.3682	-.0558	.7864	-.0622			.852	-.0637	.029	-.012	.714	
.30			.2772	-.1572				-.0745	.800	-.0516	.598	-.055	.081	
.40									.27.8	.572	.730	-.0675	.078	
.50			.3039	-.1575	.3203	-.1585	.325	-.632	.179	-.694	.529	-.599	.414	
.60	.3772	.357					.328	-.174	.333	-.673	.606	-.155	.559	
.70			.1074	-.1674	.2951	-.1557	.162	-.164	.604	-.576	.354	-.1493	.0706	
.80			.1278	-.1350	.0450	-.1665	.0403	-.161	.0367	-.1572	.235	-.107	.6653	.675
.90	.0633	-.177	.1280	-.0988	.0293	-.1645	.0367	-.161	.0295	-.1572	.125	-.1509	.0777	.760
.95					.0270	-.1510	.025	-.1568			.019	-.1514		

TAIL 2

TABLE XX.- CONTINUED
(c) α = -0.35°

TAIL 1

	Cp at y/b of										
	0.02		0.22		0.44		0.56		0.57		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.

TAIL 2

	Cp at y/b of										
	0.02		0.22		0.44		0.56		0.57		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.365?	-.0027	.9999	-.2299		-.0355	.9881	-.0113		-.2346	.2769	-.1311		-.0522
	.237	-.008			.0995		.9035	-.034	.980.0	-.0535			9.27	-.022
							.855?	-.025	.8092	-.0300			9.27	-.065
.20	.375?	-.023?	.3319	-.3658	.7293	-.0431	.8064	-.243	.5138	-.0300	.5523	-.023	.750	-.0525
	1.4?0	-.3932	.2364	-.537			.7662	-.0453	.7295	-.0425	.8224	-.0372	.749	-.022
							.7101	-.0522	.7554	-.0472	.8939	-.052.	.659	-.00.
									.2554	-.1717			5.90	-.0?.
	.3462	.0018	.2514	-.3?9	.2768	-.15.3	.2796	-.1?4	.2776	-.1800	.467	-.3.	.5699	-.0343
							.2943	-.1652	.2811	-.1619	.581	-.354	-.063	-.1763
.70	.345?	-.0795	.2843	-.173?	.2561	-.1469	.1257	-.163	.0231	-.1537	.214	-.195	-.081	-.1761
	-.041.3	-.1!63	.3952	-.3665	-.0029	-.1655	.0215	-.163	-.1013	-.1547	.2032	-.155	-.064	-.123?
.95			.3979	-.0687	-.0C.5	-.1522	-.0059	-.1625	.2043	-.1562	-.173	-.5.3	-.0472	-.55?
					-.0C0	-.1??	-.0012	-.1225	.3041				-.043?	-.055?

217

TABLE YX. - CONTINUED
(b) α = 45°

Cp at y/b of

x/c	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.55 U.S.	0.55 L.S.	0.67 U.S.	0.67 L.S.	0.33 U.S.	0.33 L.S.	0.98 U.S.	0.98 L.S.
.05	.7060	.0336	.7707		.7761	.0146						
.10		-.1387										
.15												
.20												
.25												
.30												
.40												
.50					.2449	-.1257						
.60					-.2578	-.1419						
.70			.2261	-.1302	.1936	-.1567						
.80	-.0132	-.1684			-.0018	-.1492						
.90	-.0336	-.1592			-.0129	-.1488						
.95	-.0392	-.1576			-.0205	-.1469						

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2704	.0189	.7931	.0003			.9025	-.0208			.6689	-.1159	.9722	-.0232
.10	.2542	.0134					.8258	-.0157	.8138	-.0177			.8509	-.0015
.15					.7553	-.0131	.7796	-.0185	.8123	-.0152			.7616	-.0107
.20	.2742	-.0076	.2867	-.0396			.7336	-.0225	.7798	-.0207			.7142	-.0087
.25	.0893	-.0937	.1877	-.1390	.6627	-.0291	.7071	-.0261	.7371	-.0205	.7595	-.0202	.6374	-.0063
.30							.6532	-.0359	.7025	-.0280	.6584	-.0332	.6159	-.0025
.40									.2296	-.0357			.5436	-.0287
.50					.2330	-.1429	.2401	-.1423	.2425	-.1455	.2275	-.1402	.4043	-.0287
.60	.3108	-.0085	.2478	-.1199			.2493	-.1525	.2486	-.1522	.2613	-.1550	.0627	-.1416
.70					.2114	-.1430	.0980	-.1572	.0107	-.1470	.0094	-.1935	.0911	-.1410
.80	.0009	-.0940	.0688	-.1659	.0120	-.1554	-.0038	-.1534	-.0035		-.0149	-.1446	-.0928	-.1414
.90	.0251	-.152	.0452	-.1401	-.0183	-.1571	-.0192	-.1552	-.0127	-.1479	-.0259	-.1468		
.95			.0312	-.1198	-.0139	-.1426	-.0260	-.1551	-.0195	-.1498	-.0358	-.1472	-.1065	-.1515

TAIL 2

TABLE XX - CONTINUED
(e) α = 3.05°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05				.0630		.0412								
.10						.0380								
.15						.0350								
.20						.0305								
.25											.7012	.0400		
.30							.6808				.6625	.0375		
.35											.6719	.0300		
.50											.2559			
.60											.2042	.1380		
.70	.0695	.0904	.288	-.1572	.057	.1367	.0641				-.0150	.1481	-.0623	-.576
.80	-.0727	-.1448	-.0409	-.1572	-.0437		-.0223	.1449			-.0343	-.1431	-.0843	-.1578
.90	-.1108	-.1537	-.0586	-.1523			-.0337	-.1445			-.0439	-.1484	-.0774	-.1570
.95	-.1654	-.1684	-.0616	-.1521			-.0404	-.1443			-.0529	-.1485		

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1962	.0283	.6974	.0337			.8276	.0046		.0052	.8454	-.1017	.897?	.0053
.10	.1716	.0179					.7403	.0100	.7403	.0052			.78.9	.023?
.15					.6614	.0150	.7011	.0070	.7323	.0071			.7071	.0303
.20	.1780	.0015			.5887	.0036	.6638	.0034	.7077	.0017	.7119	.0060	.6543	.027?
.25	.2333	-.0734	.2141	-.0157			.6359	.0008	.5714	-.0002	.6954	-.0021	.6.79	.217?
.30			.1121	-.1232			.5983	-.0099	.5461	-.0047	.6033	-.0113	.5695	.0084
.50									.2560		.6033		.5051	.001?
.60	.2461	-.0180	.2771	-.1088	.1795	-.1291	.1965	-.1277	.2053	-.1359	.2036	-.1288	.3817	-.0236
.70			.0235	-.1648	.1518	-.1332	.2000	-.1382	.2085	-.1394	.1397	-.1520	-.0761	-.1365
.80	-.0434	-.0934	-.0132	-.1385	-.0497	-.1507	.0600	-.1550	-.0122	-.1417	-.0190	-.1391	-.1006	-.1356
.90	.0359	-.269	-.0245	-.1132	-.0494	-.1532	-.0368	-.1470	-.0411	-.1409	-.0335	-.1396	-.1044	-.1434
.95					-.0464	-.1463	-.0530	-.1487	-.0479	-.1428	-.0543	-.1415	-.1188	-.1556

TABLE XX - CONTINUED
(f) α = 3.30°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.57 U.S.	0.57 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.5676	.0307	.5368	.0719	.5297	.0766						
.10			.5325	.0555	.6078	.0721							.5481	
.15				.0570	.5957	.0608							.5201	
.20			.5075	.0533			.5995	.0503					.4939	
.25						.0533	.5800	.0620	.5045	.0603	.6220	.0673	.4659	.0555
.30			.4175	.1095	.1733	.0621	.6004	.0621						
.40			.1073	.1067	.1646	.1093	.1901	.1093	.2219	.0979			.4155	
.50					.1609	.1123	.1905	.1217					.3763	
.60			.0607	.0853	.1553		.1331	.1374	.0103	.1221	.0827	.1215	.0695	
.70			.0595	.1492			.0429	.1355	.0429	.1333	.0305	.0300	.0715	.1539
.80			.0955	.1430			.0536	.1351	.0450	.1362	.0519	.1399	.0717	
.90			.0893	.1435	.0637	.1313	.0533	.1353	.0511	.1351	.0613	.1409	.0618	.1490

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1383	.0343	.5735	.0616			.6911	.0337			.7231	-.0838	.8113	.0343
.10	.1341	.0197				.0481	.6541	.0405	.6544	.0313			.7075	.0457
.15					.5673		.6145	.0371	.6101	.0238			.6384	.0484
.20	.1511	.0052	.1333	.0061	.4999	.0241	.5783	.0347	.6220	.0293	.6346	.0280	.5917	.0385
.25	.0495	.0576	.0350	.0694			.5547	.0328	.5655	.0278	.6222	.0237	.5619	.0229
.30							.5248	.0210	.5697	.0235	.5353	.0117	.5209	.0118
.40					.1135	.1144	.1483	.1105	.1743	.0954	.1625	.1134	.4648	.0061
.50	.1945	.0271	.4115	.0557			.1476	.1212	.1610	.1185	.1555	.1431	.3655	.0212
.60			.0008	.1588	.0892	.1262	.0191	.1495	.0532	.1324	.0395	.1315	.0814	.0292
.80	.0417	.1039	.0291	.1362	.0822	.1455	.0685	.1376	.0376		.0542	.1312	.1057	.1231
.90	.0806	.1355	.0316	.1117	.0768	.1464	.0630	.1385	.0666	.1356	.0635	.1321	.1121	.1258
.95					.0736	.1452	.0894	.1397	.0755		.0720	.1319	.1257	.1409

TAIL 2

TABLE XX. - CONTINUED
(g) α = 7.75°

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.3C91	.363?	.5071	.C?3?	.5?15	.1061	.3558	.1??3	.55?9	.1073				
	.3052	.3996	.4857	.C?4?	.5?09	.?5??			.5?38	.1006			.1??5	.C?5?
	.286?	.C?0?	.4467	.?65?	.5246	.1C?7	.5261	.08C0	.5?35	.0970	.5228	.1C??	.??.?	.075?
	.0766	-.C632	.?1??	.?656	.?1C?	.C?91	.5189	.0??3	.3?0?	.09??	.5253	.1C0?	.????	.0755
	.0530	.C55?			.1933	.095?			.2?0?	.0?12	.5225	.0?24	.35??	.C?0?
	.3714	-.C410	.0852	-.C?78	.1518	-.0785	.1745	-.0753	.19??	-.C?13	.5017	.0800	.33??	.C5??
			.0739	.?645	.1338	.?216	.162?	-.C?2?			.1925	-.0784	.3?7?	.C53?
					.1299	.C953	.1606	.C?56	.64?	.C?78	.1489	.1091	.37??	.463?
	.0112	-.0566	.0598	-.08C4	.1210	.10?4	.1054	-.127?	-.0278	.387	-.0502	-.1372	-.0772	-.15C0
	-.1256	-.1175	-.0895	-.1483			-.0624	-.132?	-.0589	-.1330	-.0?34	-.1370	-.C765	-.177?
	-.1254	-.1429	-.1092	-.14C0	-.0809	-.13C8	-.0723	-.1318	-.0623	-.1327	-.0785	-.1379		
	-.255?	-.129?	-.1128	-.1327			-.0776	-.1318	-.0687	-.1327	-.C864	-.1383	-.C53?	-.155?

TAIL 2

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1404	.0405	.4648	.0758			.5443	.0673			.5759	-.0628	.6699	.0642
	.1779	.0225			.4668	.0786	.5523	.0742	.5573	.0611			.6159	.07C
	.18C1	.CC4C					.5173	.0708	.5505	.0666			.5613	.0639
	.C94?	-.0683	.0826	.0195	.4039	.0647	.4867	.0694	.5311	.0638	.5505	.0556	.5274	.0436
			-.0092	-.0985			.4655	.0669	.5088	.0626	.5422	.0523	.4648	.0243
							.4406	.0527	.4897	.0577	.4886	.0414	.4154	.0166
	.1511	-.0354	.0879	-.0899	.0535	-.1013	.0955	-.0942	.1379	-.0834	.1449	-.0945	.3252	.0165
					.0328	-.1091	.0886	-.1059	.1208	-.0979	.0797	-.1308	-.0629	-.0118
							-.0234	-.1484	.1143	-.1023	-.0626	-.1304	-.1182	-.1295
	-.0144	-.1069	-.0485	-.1546	-.0875	-.1397	-.1048	-.1337	-.0687	-.1302	-.0772	-.1298		-.1277
	-.0566	-.1338	-.0360	-.1356	-.0848	-.1395	-.1157	-.1338	-.1001	-.1266	-.0865	-.1303	-.1174	-.1090
			-.0310	-.1139	-.0833	-.1384	-.1163	-.1341	-.1075	-.1274	-.0954	-.1306	-.123?	-.1355

221

TABLE XX. - CONTINUED
(h) α = 2.95°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
			.4587	.1504										
		.0861	.4725	.1342										
		.1300	.1062	.1317										
		.0916	.3677	.132										
		-.0361	.0558	-.0798										
	-.0233		-.0439	-.0769										
		-.0343	.0279	-.0614					.0773		.1146			
	-.0991		-.1114	-.1464					-.1308	-.0706	-.1334			
	-.1419		-.1286	-.1337					-.1282	-.0874	-.1325	-.0812		
	-.1350		-.1306	-.1328					-.1275	-.0948	-.1335			
									-.0850		-.1015	-.1338	-.0552	-.1611

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.025	.1582	.0322	.3904	.0783			.4088	.1029	.4415	.0958	.4035	-.0354	.4877	.0289
.05	.2037	.0135			.3545	.0989	.4352	.1090	.4452	.1069			.4848	.013
.10							.4078	.1063	.4452	.1046			.46C4	.082
.15	.2050	-.0035	.0563	.0213	.2966	.0818	.3761	.1033	.4400	.02	.4579	.0909	.4253	.0362
.20	.0879	-.0754	-.0073	-.0979			.3522	.098	.3933	.0958	.4503	.0901	.3928	.0322
.30							.3273	.0813	.0875	-.0601	.4061	.0767	.3607	.0312
.40					-.0190	-.0915	.0273	-.0806	.0630	-.0779	.1042	-.0698	.2848	-.0031
.50	.1641	-.0422	-.0648	-.0873	.0137	-.1017	.0120	-.0929	.0526	-.0847	.0399	-.1114	.1051	-.1166
.60					.0980	-.1394	-.0749	-.1489	.1019	-.1433	.0909	-.1360	.1272	-.1390
.80	-.0646	-.1107	-.0708	-.1533	-.0980	-.1394	-.1295	-.1365	-.1338	-.1309	-.1061	-.1339		
.90	.0233	-.1391	-.0895	-.1398	-.1012	-.1383	-.1228	-.1358	-.1356		-.146	-.1332	-.1082	-.1409
.95			-.0957	-.1251	-.0986	-.1395	-.1190	-.1354	-.1317		-.1226	-.1339	-.1176	-.1472

222

TABLE XX.- CONTINUED
(l) α = 11.95°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.3957	.1955	.3256	.1856	.3479	.1937						.1414
.10	.2462	.1038	.3884	.1818	.3887	.1912			.4098	.1862			.3872	.1419
.15	.2477	.1216	.3544	.1811	.3948	.1850			.3975	.1797			.3498	.1367
.20	.2128	.1207	.3172	.1749	.3870	.1829	.3996	.1643	.3969	.1776	.4111	.1795	.3313	.1320
.25	.0297	.0314			.3801	.1806	.3833	.1787	.3975	.1748	.4102	.1763	.3080	.1288
.30	.0064	.0167							.3891	.1705	.4028	.1665	.2918	.1141
.40	-.0022	.0057	.0275	-.0587	.0946	-.0348	.1012	-.0322	.1123	-.0263	.3887	.1624	.2851	.1113
.50			.0152	-.0562	.0799	-.0483	.0957	-.0496			.1165	-.0370	.2625	.1356
.60					.0682	-.0519	.1028	-.0641	.0873	-.0560	.0738	-.0732	.0897	.1292
.70	-.0563	-.0090	-.0029	-.0397	.0549	-.0584	.0557	-.0908	.0693	-.1471	.0958	-.1327	.1038	.1647
.80	-.1618	-.0781	-.1292	-.1387			.0938	-.1243	.0919	-.1246	.1121	-.1287	.0602	
.90	-.1488	-.1330	-.1438	-.1289	-.1137	-.1226	.1042	-.1224	.0953	-.1229	.1187	-.1289	.0944	
.95	-.1433	-.1378	-.1311	-.1264			.1088	-.1224	.1002	-.1229	.1228	-.1292		.1667

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1735	.0110	.3158	.0834			.2931	.1283			.2729	-.0039	.3562	.1377
.10	.2118	-.0062			.2636	.1058	.3180	.1320	.3232	.1326			.3605	.1359
.15							.2962	.1279	.3275	.1426			.3445	.1088
.20	.2155	-.0181	.0377	.0244	.1991	.0831	.2675	.1211	.3162	.1370	.3462	.1352	.3305	.0846
.25	.0739	-.0838	.0291	-.0972			.2415	.1129	.2993	.1317	.3421	.1334	.3273	.0743
.30							.2171	.0928	.2797	.1230	.3098	.1130	.3187	.0724
.40					-.0366	-.0872	-.0367	-.0731	-.0243	-.0448	.0512	-.0477	.2922	.0645
.50							-.0457	-.0837	-.0031	-.0650	-.0072	-.0958	.2332	.0214
.60	.1426	-.0539	.0761	-.0779	-.0228	-.0985	-.0988	-.1424	-.0171	-.0724	-.1185	-.1606	-.1166	-.1625
.70							-.1405	-.1457	-.1392	-.1633	-.1324	-.1426	-.1283	-.1622
.80	-.0523	-.1185	-.0567	-.1539	-.1331	-.1442	-.1404	-.1436	-.1442	-.1387	-.1378	-.1383	-.1129	-.1314
.90	-.0031	-.1602	-.0817	-.1522	-.1415	-.1442	-.1393	-.1438	-.1381	-.1393	-.1426	-.1387	-.1252	-.1388
.95			-.0900	-.1414	-.1418	-.1439								

TAIL 2

TABLE XX. - CONTINUED
(j) α = 15.95°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2960	.1910	.4293	.2855	.3351	.2856	.3514	.2987	.4117	.2908			.3855	.2353
.10	.2831	.2013	.4214	.2880	.3988	.2981			.3337	.2836			.3475	.2319
.15	.2428	.2006	.3787	.2849	.4036	.2899			.3995	.2820	.4114	.2817	.3290	.2229
.20	.0427	.0185	.3307	.2706	.3947	.2908	.3880	.2464	.4003	.2795	.4091	.2825	.3085	.2147
.25	.0143	-.0403			.3850	.2920	.3878	.2832	.3925	.2744	.4017	.2753	.2968	.2104
.30	-.0037	.0690	.0217	-.0069	.0844	.0198	.0991	.0252	.1119	.0327	.3870	.2647	.2899	.1916
.40			.0032	-.0036	.0694	.0089	.0842	.0098	.0830	.0010	.1675	.0197	.2655	.1833
.50	-.0795	.0563			.0553	.0054	.0817	-.0182	.0757	-.1245	.0647	-.0250	.0795	-.1118
.60	-.1684	-.0297	-.0237	.0181	.0389	-.0032	.0435	-.0409	-.1005	-.1091	-.0957	-.1244	-.0832	-.1357
.70	-.1532	-.0996	-.1444	-.025			-.1022	-.1195	-.1052	-.1008	-.1160	-.1106	-.0851	-.1246
.80	-.1402	-.1124	-.1405	-.1187	-.1223	-.1087	-.1117	-.1029	-.1072	-.1003	-.1177	-.1083		
.90			-.1301	-.1165			-.1135	-.1015			-.1093	-.1081	-.1255	-.1594

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2244	-.0588	.2031	.0640			.1005	.1592			.0377	.0202	.1062	.2022
.10	-.2290	-.0489					.1132	.1518	.1045	.1676			.1073	.2090
.15					.0963	.1011	.0913	.1361	.0941	.1680			.0986	.2026
.20	.1692	-.0657	.0470	.0210	.0350	.0763	.0646	.1210	.0792	.1547	.0937	.1839	.0937	.1883
.25	.0184	-.1221	.0331	-.0998			.0411	.1078	.0601	.1425	.0892	.1748	.0930	.1714
.30							.0168	.0897	.0427	.1280	.0672	.1367	.0910	.1633
.40									-.1042	-.0413	-.0812	-.0334	.0925	.1357
.50	.1102	-.0811	.0532	-.0604	-.0929	-.0864	-.1159	-.0666	-.1298	-.0594	-.1213	-.0838	.0634	.0701
.60					-.1135	-.0918	-.1230	-.0785	-.1380	-.0644	-.1762	-.1588	-.1649	-.1526
.70			-.0866	-.1508	-.1800	-.1628	-.1590	-.1393	-.1678	-.1627	-.1696	-.1665	-.1648	-.1506
.80	-.0567	-.1349	-.1075	-.1725	-.1797	-.1607	-.1837	-.1781	-.1654	-.1722	-.1634	-.1669	-.1550	-.1388
.90	-.0274	-.1705	-.1151	-.1572	-.1734	-.1589	-.1729	-.1738	-.1666	-.1677	-.1663	-.1685	-.1637	-.1583
.95							-.1679	-.1673						

TAIL 2

TABLE XX.- CONCLUDED
(k) α = 19.95°

TAIL 1

	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05			.4878	.4102	.3681	.4206	.3858	.4367						
.10	.3655	.2861	.4725	.4214	.4417	.4421			.4419	.4269			.3500	.3473
.15	.3472	.3003	.4208	.4037	.4469	.4343			.4309	.4207			.3538	.3370
.20	.2856	.2976	.3663	.3766	.4363	.4377	.4183	.3849	.4306	.4221	.4251	.4161	.3367	.3269
.25	.0625	.0785			.4252	.4330	.4248	.4262	.4316	.4191	.4207	.4231	.3233	.3162
.30	.0284	.1120	.0389	.0553	.1030	.0914	.1172	.1064	.4214	.4135	.4137	.4096	.3164	.3076
.40	.0104	.1543	.0173	.0604	.0857	.0808	.1011	.0899	.1256	.1137	.3984	.3963	.2946	.2793
.50					.0711	.0726	.0903	.0578	.0932	.0805	.1078	.0908		.2744
.60	-.0693	.1414	-.0144	.0944	.0529	.0605	.0535	.023	-.0722	-.0802	-.0676	-.0395	-.0623	-.0778
.70	-.1652	.0271	-.1406	-.0531			-.0983	-.0974	-.0970	-.0955	-.0967	-.1063	-.0412	-.0629
.80	-.1454	-.0548	-.1343	-.0682	-.0979	-.1001	-.0993	-.0858	-.0799	-.0737	-.0990	-.0831	-.0410	-.0638
.90	-.1262	-.0726	-.1245	-.0658			-.0804	-.0764	-.0679	-.0672	-.0771	-.0772	-.1443	-.1511
.95											-.0735	-.0761		

TAIL 2

	Cp at y/b of													
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1724	-.0667	.0852	.0835			-.0079	.1969	-.0018	.1854	-.0507	.2756	-.0298	.2733
.10	.1714	-.0710					.0160	.1761	-.0061	.1793			-.0257	.2571
.15					.0244	.1221	-.0103	.1545	-.0092	.1619			-.0312	.2332
.20	.1081	-.0791	-.0184	.0264	-.0273	.0951	-.0051	.1375	-.0207	.1485	-.0274	.1830	-.0364	.2063
.25	-.0242	-.1278	-.0277	-.0882			-.0227	.1245	-.0318	.1329	-.0346	.1720	-.0455	.1883
.30							-.0410	.1047	-.0318	-.0413	-.0499	.1278	-.0474	.1704
.50	.0579	-.0932	-.0149	-.0456	-.1231	-.0674	-.1418	-.0553	-.1397	-.0515	-.1438	-.0308	-.0518	.1487
.60					-.1420	-.0234	-.1509	-.0651	-.1598	-.0575	-.1726	-.0812	-.0720	.0785
.70	-.0872	-.1487	-.1314	-.1522	-.1950	-.1346	-.1752	-.1260	-.1645	-.1528	-.1868	-.1557	-.1853	-.1535
.80	-.0803	-.1743	-.1494	-.1774	-.1907	-.1498	-.1954	-.1508	-.1884	-.1627	-.1863	-.1631	-.1861	-.1573
.90	-.1555		-.1555	-.1699	-.1851	-.1546	-.1863	-.1399	-.1831	-.1629	-.1827	-.1659	-.1652	-.1493
.95							-.1831	-.1408	-.1823		-.1863	-.1683	-.1776	-.1703

TABLE XXI.- PRESSURE COEFFICIENTS, φ = 45°, δ = -15°, M = 3.70
(a) α = -4.30°

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
C_p at y/b of														
.05	.1082	.0018	.6879	-.0126	.6663	-.0122	.6684	-.0140						
.10	.1224	-.0031	.6303	-.0275	.7424	-.0242			.7204	-.0210			.6937	-.0210
.15	.1323	-.0029	.5918	-.0357	.7200	-.0294			.7151	-.0263			.6930	-.0174
.20	.0873	-.0276	.5661	-.0306	.6790	-.0318	.6718	.0087	.7180	-.0239	.7111	-.0243	.6756	-.0132
.25	.0852	-.0297			.6528	-.0348	.6909	-.0308	.7129	-.0321	.7187	-.0295	.6577	-.0182
.30	.1219	-.0401	.2622	-.0487	.2917	-.0562	.3215	-.0541	.6956	-.0343	.7133	-.0351	.6652	-.0192
.40			.2468	-.0543	.2985	-.0588	.3025	-.0587	.3618	-.0575	.6836	-.0375	.5536	-.0231
.50			.2574	-.0490	.2812	-.0571	.2839	-.0243	.3160	-.0519	.3682	-.0629	.6858	-.0308
.60	.1231	-.0426			.2723	-.0571	.2654	-.0543	.1160	-.0567	.3164	-.0612	.6712	-.0647
.70	.0093	-.0552	.0965	-.0551			.0786	-.0561	.0789	-.0492	.1084	-.0612	.6376	-.0646
.80	-.0191	-.0615	.0550	-.0551	.0586	-.0431	.0671	-.0565	.0731	-.0588	.0916	-.0505	.0376	
.90	-.0245	-.0593	.0452	-.0557			.0618	-.0567	.0663	-.0592	.0836	-.0597	.0256	-.0597
.95											.0756	-.0637		

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
C_R at y/b of														
.05	.5799	-.0235	.8192	-.0118			.7902	-.0133			.7081	-.0184	.7722	-.0042
.10	.4789	-.0192					.8383	-.0221	.3034	.0224			.7609	-.0119
.15					.8269	-.0228	.8312	-.0265	.8404	-.0212			.7337	-.0157
.20	.4323	-.0288	.4302	-.0358	.7888	-.0334	.8290	-.0305	.8431	-.0294	.8076	-.0200	.7127	-.0174
.25	.2590	-.0518	.3277	-.0497			.8174	-.0332	.8357	-.0322	.8178	-.0265	.6990	-.0198
.30							.7915	-.0357	.8127	-.0337	.7789	-.0326	.6788	-.0183
.40									.4033	-.0564			.6500	-.0225
.50	.2760	.0046	.2796	-.0382	.3395	-.0427	.3478	-.0480	.3654	-.0465	.3906	-.0488	.5756	-.0378
.60							.3495	-.0523	.3550	-.0455	.2964	-.0497	.0878	-.0457
.70					.3016	-.0463	.2106	-.0512	.1298	-.0364	.1237	-.0441	.0463	-.0378
.80	-.0863	-.0318	.0852	-.0536	.1039	-.0512	.1024	-.0527			.0995	-.0446		
.90	.0328	-.0432	.0595	-.0539	.0809	-.0528	.0861	-.0522	.0871	-.0471	.0858	-.0373	.0245	-.0405
.95			.0533	-.0539	.0722	-.0524	.0796	-.0522	.0825	-.0472	.0761	-.0452	.0157	-.0458

TABLE XXI.- CONTINUED
(b) α = -2.30°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1519	-.0050	.6135	.0033	.5708	-.0037	.5808	-.0017						
.10	.1675	-.0025	.6093	-.0140	.6172	-.0144			.6401	-.0099			.6056	-.0039
.15	.1846	-.0054	.5788	-.0246	.6440	-.0196			.6260	-.0154			.6025	-.0099
.20	.1070	-.0328	.5506	-.0256	.6310	-.0226	.6343	-.0057	.6272	-.0190	.6285	-.0156	.5873	-.0115
.25	.1039	-.0335			.6213	-.0256	.6288	-.0217	.6306	-.0214	.5355	-.0203	.5632	-.0099
.30	.1243	-.0399	.2281	-.0519	.2539	-.0568	.3033	-.0533	.6230	-.0239	.6351	-.0242	.5399	-.0097
.40			.2129	-.0562	.2651	-.0605	.2845	-.0608	.3275	-.0543	.6074	-.0292	.5167	-.0099
.50					.2564	-.0570	.2839	-.0355			.3250	-.0584	.4774	-.0132
.60	.1424	-.0434	.797	-.0493	.2494	-.0559	.2368	-.0539	.2938	-.0526	.2768	-.0642	.0649	-.0680
.70	.0158	-.0562	.0505	-.0552			.0675	-.0549	.1042	-.0552	.0877	-.0613	.027	-.0663
.80	-.0201	-.0635	.0316	-.0556	.0478	-.0447	.0520	-.0553	.0646	-.0590	.0711	-.0610	.0139	-.0650
.90	-.0263	-.0596	.0284	-.0560			.0459	-.0555	.0581	-.0590	.0644	-.0608		
.95							.0524	-.0532	.0574	-.0608	.0064	-.0586		

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.3929	-.0152	.7181	-.0065			.6989	-.0057	.7114	-.0184	.6249	-.0171	.6967	.0007
.10	.3239	-.0132					.7394	-.0147					.6911	-.0070
.15					.7372	-.0187	.7378	-.0205	.7400	-.0161			.6637	-.0109
.20	.3281	-.0189					.7380	-.0236	.7422	-.0229	.7158	-.0155	.6428	-.0128
.25	.1772	-.0466	.3886	-.0322	.7148	-.0285	.7339	-.0257	.7414	-.0251	.7227	-.0219	.6285	-.0141
.30			.2839	-.0516			.772	-.0303	.7315	-.0269	.6955	-.0292	.6118	-.0151
.40									.3630	-.0541	.3471	-.0518	.5827	-.0138
.50	.2219	.0025	.2310	-.0456	.2954	-.0419	.3061	-.0479	.3252	-.0493	.2598	-.0451	.5204	-.0247
.60							.3060	-.0511	.3154	-.0442	.1013	-.0456	.0630	-.0466
.70					.2609	-.0451	.1816	-.0500	.1059	-.0373	.0795	-.0462	.0298	-.0393
.80	.0692	-.0322	.0550	-.0553	.0780	-.0496	.0775	-.0518	.0627	-.0475	.0667	-.0399		
.90	.0142	-.0430	.0338	-.0549	.0564	-.0520	.0615	-.0513	.0580	-.0475	.0578	-.0469	.0109	-.0414
.95			.0285	-.0547	.0486	-.0513	.0555	-.0515					.0025	-.0465

227

TABLE XXI.- CONTINUED
(c) α = -0.30°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1879	-.0037	.5378	.0190	.5004	.0074	.5166	.0107	.5745	.0030			.5444	.0075
.10	.1970	-.0015	.5465	-.0014	.5480	-.0015			.5625	-.0023			.532?	.0025
.15	.2123	-.0008	.5314	-.0124	.5649	-.0068			.5604	-.0063	.5616	.0019	.5209	.001?
.20	.1093	-.0327	.5137	-.0141	.5639	-.0190	.5738	-.0015	.5632	-.0031	.5737	-.0032	.4760	-.0014
.25	.1056	-.0345			.5564	-.0127	.5605	-.0102	.5561	-.0118	.5667	-.0135	.5363	-.003?
.30	.1165	-.0384	.2054	-.0501	.2332	-.0539	.2611	-.0456	.2737	-.0498	.2843	-.0485	.4204	-.0060
.50			.1894	-.0557	.2363	-.0600	.2537	-.0590	.2544	-.0527	.2319	-.0535	.0459	-.0656
.60	.1312	-.0422	.1521	-.0479	.2329	-.0573	.2604	-.0361	.0814	-.0537	.0631	-.0623	.0070	-.0619
.80	.0132	-.0547	.0285	-.0530	.2258	-.0545	.1996	-.0525	.0501	-.0490	.0465	-.0590	-.0029	-.0607
.90	-.0251	-.0616	.0061	-.0537	.0357		.0530	-.0530	.0424	-.0570	.0403	-.0587		
.95	-.0306	-.0578	.0028	-.0545		-.0435	.0383	-.0532	.0374	-.0572	.0343	-.0585	-.0103	-.0553
							.0315	-.0534						

Cp at y/b of

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2545	-.0064	.6186	.0036			.6192	.0031	.6408	.0184	.5562	-.0134	.6285	.0091
.10	.2182	-.0032					.6548	-.0058	.6582	-.0084			.6317	.0010
.15					.6502	-.0105	.6525	-.0122	.6588	-.0141			.6032	-.0025
.20	.2352	-.0053	.3454	-.0238	.6379	-.0196	.6524	-.0147	.6547	-.0168	.6402	-.0075	.5843	-.004?
.25	.1181	-.0397	.2426	-.0503			.6493	-.0159	.6494	-.0194	.6487	-.0137	.5707	-.0049
.30							.6392	-.0223	.3187	-.0512	.6218	-.0220	.5562	-.0054
.40													.5306	-.0078
.50	.1723	-.0004	.1818	-.0412	.2560	-.0422	.2670	-.049?	.2823	-.0505	.3022	-.0514	.4740	-.0141
.60							.2666	-.0504	.2742	-.0434	.2226	-.0458	.0555	-.0449
.70					.2239	-.0483	.1537	-.0485	.0847	-.0366	.0774	-.0445	.0196	-.0386
.80	.0502	-.0333	.0305	-.0557	.0574	-.0507	.0569	-.0503	.0445	-.0459	.0592	-.0450	.0005	-.0400
.90	.0049	-.0438	.0135	-.0548	.0358	-.0507	.0416	-.0504	.0398	-.0459	.0515	-.0399	-.0079	-.0446
.95			.0109	-.0535	.0291	-.0507	.0353	-.0506			.0408	-.0454		

TABLE XXI .- CONTINUED

(d) α = 1.71°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.4761	.0357	.4409	.0217	.4565	.0238						
.10	.2116	-.0034	.4879	.0121	.4810	.0121			.5095	.0154			.4883	.0186
.15	.2189	-.0078	.4758	-.0008	.4862	.0069			.5023	-.0095	.5037	.0068	.4779	.0103
.20	.2323	-.0085	.4575	-.0018	.4972	.0032	.5103	.0049	.5001	-.0058	.5094	-.0032	.4608	.0072
.25	.1074	-.0321			.4941	.0004	.4931	-.0021	.5007	-.0028	.5052	-.0003	.4394	-.0072
.30	.1006	-.0348							.4957	-.0001	.4857	-.006	.4154	-.0067
.40	.1023	-.0372	.1762	-.0493	.2032	-.0521	.2221	-.0477	.2345	-.0452	.2458	-.0493	.3959	-.0029
.50			.1637	-.0557	.1954	-.0602	.2139	-.0582	.2080	-.0540	.1953	-.0616	.3687	-.0022
.60	.1092	-.0430			.1968	-.0605	.2302	-.0393	.0628	-.0545	.0422	-.0589	.0259	-.0655
.70	.0057	-.0556	.1344	-.0482	.1930	-.0568	.1676	-.0543	.0328	-.0499	.0255	-.0586	-.0067	-.0611
.80	-.0320	-.0588	.0187	-.0522			.0336	-.0538	.0251	-.0574	.0192	-.0586	-.0152	-.0596
.90	-.0365	-.0570	-.0072	-.0531	.0226	-.0452	.0216	-.0540	.0206	-.0576	.0139	-.0583	-.0202	-.0546
.95			-.0121	-.0539			.0159	-.0541						

Cp at y/b of

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1596	.0005	.5201	.0167			.5439	.0138			.4922	-.0093	.5612	.0180
.10	.1484	.0061					.5746	.0046	.5673	.0222			.5696	.0095
.15					.5656	.0009	.5743	-.0014	.5835	-.0016			.5446	.0067
.20	.1611	-.0041	.2904	-.0133			.5696	-.0034	.5803	-.0031	.5699	.0012	.5271	.0053
.25	.0753	-.0302	.1851	-.0470	.5581	-.0081	.5683	-.0056	.5770	-.0054	.5776	-.0048	.5165	.0049
.30							.5562	-.0115	.5723	-.0075	.5526	-.0138	.5019	.0046
.40													.4808	.0024
.50	.1239	-.0036	.1285	-.0405	.2150	-.0439	.2266	-.0503	.2760	-.0466	.2612	-.0494	.4284	-.0112
.60							.2261	-.0497	.2388	-.0514	.1860	-.0469	.0408	-.0458
.70					.1840	-.0420	.1260	-.0463	.2320	-.0430	.0531	-.0447	.0059	-.0390
.80	.0353	-.0350	-.0059	-.0528	.0343	-.0457	.0345	-.0480	.0598	-.0358	.0362	-.0449	.0122	-.0408
.90	-.0035	-.0461	-.0050	-.0524	.0135	-.0477	.0203	-.0478	.0235	-.0445	.0297	-.0391	.0204	-.0457
.95			-.0055	-.0526	.0073	-.0479	.0149	-.0479	.0190	-.0445	.0196	-.0452		

TABLE XXI.- CONTINUED
(e) α = 3.70°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2430		.4184	.0554	.3879	.0383	.4002	.0395					.4449	.0335
.10	.2262	.0016	.4307	.0291	.4241	.0292			.4496	.0310			.4299	.0238
.15	.2401	.0178	.4227	.0179	.4284	.0238			.4453	.0251		.0224	.4153	.0201
.20		-.0224	.4079	.0143	.4295	.0200	.4498	.0151	.4443	.0214	.4527		.382.	.013.
.25	.1051	-.0281			.4287	.0173	.4338	.0178	.4459	.0181	.4564	.0185	.3704	.0085
.30	.0947	-.0302	.1421	-.0458			.181.	-.0430	.4406	.0152	.4515	.0160	.3519	.0118
.40	.0858	-.0383	.1301	-.0525	.1707	-.0477	.1731	-.0547	.2092	-.0386	.4351	-.0085	.3246	.0079
.50					.1587	-.0567			.2075	-.0427				
.60					.1589	-.0584	.1932	-.0395	.1668	-.0521	.1601	-.0582	-.0128	-.0633
.70	.0731	-.0408	.1079	-.0473	.1573	-.0574	.1353	-.0554	.0399	-.0549	.0229	-.0582	-.0149	-.0612
.80	-.0093	-.0551	-.0067	-.0510			.0177	-.0537	.0140	-.0489	.0072	-.0577	-.0168	-.0595
.90	-.0392	-.0554	-.0167	-.0517	.0101	-.0452	.0064	-.0537	.0062	-.0558	.0014	-.0575	-.0211	-.0426
.95	-.0419	-.0548	-.0218	-.0524			.0018	-.0539	.0024	-.0561	-.0033	-.0574	-.0219	-.0537

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1044	.0060	.4261	.0314			.4658	.0263			.4290	-.0040	.4986	.0290
.10	.0993	.0115					.4924	.0181	.4938	.0283			.5096	.0199
.15					.4811	.0152	.4934	.0125	.5056	.0137			.4903	.0168
.20	.0975	-.0075					.4893	.0106	.5043	.0097			.4727	.0153
.25	.0349	-.0242	.2169	-.0013	.4786	.0064	.4857	.0081	.5000	.0076	.4988	.0124	.4637	.0140
.30			.1157	-.0417			.4729	-.0015	.4951	.0053	.5060	.0071	.4497	.0134
.40									.2320	-.0412	.4854	-.0027	.4319	-.0099
.50			.0611	-.0389	.1780	-.0425	.1868	-.0482	.1973	-.0488	.2208	-.0444	.3815	-.0071
.60	.1131	-.0072					.1850	-.0498	.1905	-.0427	.1511	-.0467	.2278	-.0441
.70					.1413	-.0398	.0998	-.0438	.0419	-.0343	.0316	-.0432	-.0043	-.0381
.80	.0130	-.0370	-.0040	-.0491	.0121	-.0422	.0159	-.0450			.0163	-.0433		
.90	.0057	-.0498	-.0113	-.0500	-.0082	-.0444	-.0018	-.0450	.0079	-.0424	.0120	-.0380	-.0211	-.0426
.95			-.0125	-.0507	-.0132	-.0444	-.0033	-.0450	.0035	-.0424	.0021	-.0435	-.0291	-.0475

TABLE XXI.- CONTINUED
(l) α = 5.71°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.3768	.0794	.3532	.0589	.3665	.0597						
.10	.2458	.0112	.3857	.0503	.3866	.0503			.4150	.0521			.4221	.0531
.15	.2172	.0325	.3765	.0397	.3882	.0450			.4104	.0462			.4035	.0424
.20	.2278	.0371	.3632	.0360	.3877	.0414	.4050	.0294	.4093	.0422	.4244	.0427	.3803	.0378
.25	.0970	-.0213			.3856	.0386	.3951	.0383	.4104	.0391	.4292	.0409	.3597	.0351
.30	.0825	-.0227							.4052	.0359	.4213	.0373	.3451	.0352
.40	.0600	-.0346	.1093	-.0392	.1413	-.0401	.1512	-.0349	.1864	-.0283	.4057	.0302	.3264	.0321
.50			.0956	-.0460	.1308	-.0497	.1404	-.0476			.1805	-.0330	.3020	.0235
.60					.1244	-.0523	.1571	-.0367	.1383	-.0463	.1356	-.0516	.0071	-.0586
.70	.0368	-.0351	.0762	-.0421	.1198	-.0535	.1067	-.0541	.0258	-.0532	.0101	-.0552	-.0139	-.0608
.80	-.0285	-.0524	-.0074	-.0484			.0027	-.0511	-.0001	-.0467	-.0051	-.0554	-.0140	-.0604
.90	-.0456	-.0522	-.0269	-.0485	-.0017	-.0432	-.0081	-.0509	-.0087	-.0533	-.0109	-.0551		
.95	-.0466	-.0510	-.0313	-.0492			-.0123	-.0512	-.0124	-.0536	-.0154	-.0552	-.0182	-.0536

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0647	.0027	.3328	.0439			.3813	.0407			.3624	.0020	.4301	.0413
.10	.0823	.0093					.4029	.0341	.4158	.0379			.4415	.0324
.15					.3832	.0310	.4032	.0295	.4218	.0291			.4274	.0287
.20	.0937	.0041					.4024	.0272	.4216	.0252			.4109	.0250
.25	.0448	-.0245	.1156	-.0085	.3835	.0224	.3990	.0247	.4165	.0234	.4237	.0257	.4032	.0211
.30			.0403	-.0381			.3874	.0173	.4122	.0208	.4303	.0211	.3911	.0180
.40									.1840	-.0332	.4133	.0115	.3764	.0111
.50	.0840	-.0125			.1278	-.0386	.1902	-.0424	.1522	-.0428	.1780	-.0385	.3319	-.0062
.60	.0840		.0478	-.0384			.1389	-.0486	.1449	-.0427	.1161	-.0473	.0150	-.0418
.70					.0905	-.0413	.0664	-.0435	.0232	-.0341	.0120	-.0426	-.0137	-.0368
.80	-.0031	-.0400	-.0048	-.0478	-.0092	-.0414	-.0026	-.0436	-.0086	-.0416	-.0018	-.0422	-.0289	-.0385
.90	.0092	-.0536	-.0152	-.0494	-.0269	-.0429	-.0154	-.0435	-.0125	-.0414	-.0038	-.0374	-.0365	-.0439
.95			-.0175	-.0501	-.0303	-.0426	-.0204	-.0435			-.0135	-.0426		

TAIL 2

231

TABLE XXI.- CONTINUED
(g) a = 7.70°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.3796	.1076	.3491	.0842	.3609	.0845						
.10	.2589	.0263	.3866	.0741	.3826	.0749			.4062	.0773			.4153	.0759
.15	.2288	.0495	.3754	.0642	.3828	.0697			.4009	.0713			.3931	.0644
.20	.2340	.0559	.3609	.0619	.3832	.0661	.3966	.0496	.4017	.0673	.4151	.0672	.3808	.0590
.25	.0999	.3133			.3796	.0633	.3890	.0635	.4021	.0640	.4139	.0664	.3606	.0559
.30	.0836	.3135							.3968	.0657	.4124	.0626	.3376	.0548
.40	.0566	.2256	.1021	-.0322	.1344	-.0306	.1450	-.0247	.1789	-.0160	.3972	-.0549	.3181	.0515
.50			.0862	-.0388	.1241	-.0411	.1320	-.0385	.1303	-.0388	.1740	-.0221	.2929	.0419
.60			.0631	-.0359	.1159	-.0439	.1410	-.0323	.0203	-.0523	.1259	-.0441	.0048	.0530
.70	.0186	-.0280	-.0155	-.0484	.1088	-.0470	.0980	-.0510	-.0048	-.0457	.0044	-.0552	.0098	.0600
.80	-.0378	-.0484	-.0330	-.0473	-.0053	-.0412	-.0013	-.0483	-.0137	-.0518	-.0102	-.0540	-.0137	.0653
.90	-.0482	-.0515	-.0374	-.0478			-.0120	-.0481	-.0174	-.0522	-.0160	-.0536		
.95	-.0473	-.0501					-.0162	-.0483			-.0202	-.0538	-.0232	.0529

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0785	-.0089	.2515	.0489			.2904	.0547			.2937	.0085	.3598	.0561
.10	.1037	-.0002			.2768	.0440	.3034	.0506	.3282	.0476			.3695	.0493
.15							.3021	.0465	.3288	.0457			.3585	.0452
.20	.1367	-.0050	.0771	.0109	.2731	.0357	.2999	.0436	.3274	.0424	.3440	.0407	.3471	.0391
.25	.0618	-.0306	.0190	-.0366			.2976	.0409	.3233	.0406	.3488	.0371	.3389	.0319
.30							.2869	.0332	.3194	.0380	.3345	.0263	.3280	.0260
.40					.0675	-.0340	.0842	-.0359	.1301	-.0253	.1322	-.0323	.3167	.0161
.50	.0720	-.0143	.0366	-.0385			.0824	-.0432	.1005	-.0355	.0779	-.0475	.2784	-.0029
.60					.0312	-.0419	.0282	-.0430	.0942	-.0375	.0086	-.0460	.0001	-.0486
.70					.0354	-.0439	.0264	-.0464	.0010	-.0382	-.0209	-.0459	-.0242	-.0414
.80	-.0038	-.0426	-.0258	-.0509	-.0426	-.0457	-.0370	-.0465	-.0279	-.0456	-.0211	-.0403	-.0371	-.0416
.90	-.0131	-.0562	-.0373	-.0513	-.0426	-.0451	-.0414	-.0468	-.0307	-.0458	-.0302	-.0464	-.0446	-.0468
.95			-.0408	-.0514										

TAIL 2

232

TABLE XXI.- CONTINUED
(h) α = 9.71°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2797	.0440	.3993	.1410	.3592	.1137	.3696	.1139	.4118	.1070			.4182	.1031
.10	.2519	.0682	.4054	.1017	.3938	.1047			.4062	.1009	.4202	.0965	.3931	.0912
.15	.2528	.0804	.3934	.0927	.3934	.0995	.3942	.0729	.4069	.0963	.4239	.0966	.3801	.0848
.20	.1104	-.0038	.3770	.0907	.3951	.0958	.3582	.0928	.4084	.0935	.4163	.0927	.3606	.0800
.25	.0921	-.0021			.3913	.0929			.4028	.0001	.4008	.0840	.3386	.0783
.30	.0626	-.0119	.1062	-.0230	.1373	-.0203	.1469	-.0134	.1803	-.0021	.1750	-.0089	.3183	.0745
.40			.0889	-.0301	.1265	-.0315	.1327	-.0286	.1302	-.0298	.1249	-.0345	.2936	.0643
.50	.0150	-.0192			.1175	-.0346	.1342	-.0281	.0194	-.0506	.0020	-.0517	.2361	.0462
.60	-.0403	-.0431	.0625	-.0271	.1102	-.0387	.0975	-.0461	-.0066	-.0427	-.0123	-.0498	-.0061	.0543
.70	-.0466	-.0515	-.0166	-.0468			-.0026	-.0448	-.0155	-.0479	-.0182	-.0495	-.0170	.0650
.80			-.0342	-.0443	-.0076	-.0392	-.0138	-.0445	-.0193	-.0483	-.0225	-.0497	-.0191	.0538
.90	-.0446	-.0489	-.0387	-.0444			-.0179	-.0447						
.95														

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0993	-.0209	.1998	.0506			.1982	.0646			.2180	.0174	.2818	.0719
.10	.1109	-.0111					.2042	.0631	.2395	.0604			.2882	.0693
.15					.1849	.0522	.2004	.0590	.2267	.0611			.2786	.0644
.20	.1390	-.0161	.0459	.0115	.1767	.0443	.1953	.0559	.2232	.0585	.2532	.0564	.2699	.0561
.25	.0574	-.0379	.0367	-.0352			.1913	.0534	.2186	.0568	.2560	.0540	.2652	.0455
.30					.0140	-.0303	.1833	.0451	.2150	.0532	.2454	.0411	.2557	.0377
.40			.0245	-.0383			.0351	-.0301	.0707	-.0160	.0823	-.0237	.2460	.0272
.50	.0617	-.0182			-.0094	-.0406	-.0275	-.0374	-.0480	-.0279	.0369	-.0429	.2161	.0068
.60			-.0367	-.0576	-.0436	-.0499	.0149	-.0519	-.0438	-.0305	-.0285	-.0543	-.0170	-.0543
.70			-.0488	-.0564	-.0501	-.0515	-.0498	-.0543	-.0175	-.0448	-.0379	-.0515	-.0352	-.0476
.80	-.0012	-.0468	-.0519	-.0553	-.0498	-.0511	-.0536	-.0524	-.0442	-.0502	-.0358	-.0447	-.0419	-.0455
.90	-.0283	-.0591					-.0523	-.0522	-.0469	-.0508	-.0451	-.0508	-.0475	-.0508
.95														

233

TABLE XXI.- CONTINUED
(i) α = 11.70°

TAIL 1

x/c	\multicolumn Cp at y/b of													
	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.3052	.0641	.4295	.1808	.3785	.1492	.3853	.1494						.349
.10	.2809	.0937	.4349	.1344	.4138	.1402			.4269	.1425			.4278	.1232
.15	.2779	.1088	.4213	.1265	.4145	.1352			.4209	.1365			.3956	.1155
.20	.1249	.0096	.4032	.1248	.4158	.1314	.4077	.1035	.4215	.1323	.4328	.1309	.3884	.1121
.25	.1742	.0132			.4130	.1283	.4157	.1294	.4231	.1289	.4364	.1321	.3663	.1092
.30	.0734	.0076							.4173	.1251	.4287	.1280	.3460	.1068
.40			.1155	-.0122	.1460	-.0064	.1552	.0029	.1871	.0155	.4126	.1185	.3271	.117
.50	.0166	-.0068	.0965	-.0177	.1341	-.0181	.1395	-.0137			.1804	.0074	.3013	
.60					.1268	-.0217	.1369	-.0200	.1359	-.0164	.1294	-.0217	.0064	.0352
.70	-.0396	-.0347	.0666	-.0144	.1174	-.0263	.1032	-.0361	.0221	-.0461	.0025	-.0465	-.0027	-.0464
.80	-.0433	-.0496	-.0150	-.0428			-.0001	-.0375	-.0055	-.0375	-.0123	-.0438	-.0120	-.0615
.90	-.0404	-.0467	-.0333	-.0385	-.0055	-.0340	-.0159	-.0378	-.0143	-.0419	-.0185	-.0433	-.0071	-.0548
.95			-.0376	-.0382					-.0183	-.0424	-.0229	-.0434		

TAIL 2

x/c	\multicolumn Cp at y/b of													
	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0936	-.0240	.1351	.0491			.1533	.0708			.1490	.0247	.2002	.0876
.10	.1057	-.0164					.1539	.0701	.1767	.0697			.2017	.0891
.15					.1391	.0566	.1463	.0658	.1541	.0699			.1910	.0820
.20	.1237	-.0205	.0275	.0116	.1268	.0487	.1364	.0625	.1459	.0667	.1601	.0669	.1829	.0689
.25	.0444	-.0411	.0236	-.0337			.1297	.0602	.1373	.0650	.1590	.0656	.1779	.0566
.30							.1199	.0514	.1305	.0614	.1447	.0535	.1720	.0494
.40					-.0070	-.0283	.0006	-.0259	.0229	-.0104	.0291	-.0172	.1644	.0428
.50	.0499	-.0213	.0122	-.0369			-.0120	-.0333	.0041	-.0234	-.0041	-.0391	.1408	.0216
.60					-.0240	-.0389	-.0389	-.0510	-.0019	-.0264	-.0456	-.0579		
.70	.0101	-.0489	-.0436	-.0591	-.0504	-.0562	-.0600	-.0617	-.0339	-.0464	-.0522	-.0577	-.0343	-.0544
.80	-.0376	-.0601	-.0547	-.0626	-.0564	-.0553	-.0568	-.0578	-.0542	-.0546	-.0474	-.0485	-.0450	-.0516
.90			-.0575	-.0602	-.0553	-.0546	-.0567	-.0573	-.0549	-.0550	-.0545	-.0542	-.0471	-.0492
.95													-.0535	-.0540

TABLE XXI. - CONTINUED
(i) α = 15.70°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.88 U.S.	0.88 L.S.	0.98 U.S.	0.98 L.S.
.05			.5152	.2815	.4376	.2376	.4381	.2382						
.10	.3776	.1179	.5185	.2180	.4754	.2296			.4767	.2331			.4612	.2150
.15	.3615	.1775	.5014	.2136	.4801	.2255			.4701	.2262			.4279	.2029
.20	.3497	.1818	.4775	.2129	.4823	.2210	.4452	.1537	.4709	.2215	.4753	.2196	.4135	.1934
.25	.1653	.0483			.4786	.2177	.4722	.2171	.4731	.2179	.4791	.2237	.3927	.1847
.30	.1387	.0566	.1443	.0234	.1781	.0292	.1834	.0416	.4669	.2135	.4706	.2186	.3731	.1805
.40	.1039	.0593	.1225	.0152	.1644	.0172	.1660	.0222	.2121	.0602	.4530	.2066	.3588	.1709
.50					.1553	.0133	.1515	-.0048	.1587	.0194	.2227	.0506	.3337	.1590
.60					.1425	.0076	.1254	-.0110	.0321	-.0347	.1505	.0127	.0182	.0228
.70	.0261	.0274	.0870	.0203			.0091	-.0215	.0006	-.0252	-.0092	-.0350	.0016	-.0250
.80	-.0350	-.0105	-.0073	-.0307	.0005	-.0227	-.0034	-.0205	-.0074	-.0268	-.0070	-.0287	-.0062	-.0464
.90	-.0351	-.0388	-.0286	-.0235			-.0080	-.0208	-.0114	-.0272	-.0138	-.0274		
.95	-.0317	-.0382	-.0302	-.0223							-.0181	-.0274	-.0135	-.0470

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.88 U.S.	0.88 L.S.	0.98 U.S.	0.98 L.S.
.05	.0249	-.0093	.0474	.0626			.0561	.0836			.0634	.0308	.0740	.1098
.10	.0533	-.0096					.0582	.0837	.1033	.0790			.0714	.1087
.15					.0534	.0719	.0600	.0803	.0670	.0860			.0659	.0946
.20	.0504	-.0142	-.0083	.0254	.0495	.0636	.0579	.0784	.0633	.0840	.0687	.0823	.0633	.0808
.25	.0044	-.0404	-.0157	-.0265			.0569	.0759	.0607	.0822	.0672	.0826	.0634	.0722
.30							.0527	.0656	.0585	.0773	.0579	.0708	.0620	.0690
.40									-.0102	-.0007	-.0124	-.0061	.0608	.0628
.50	.0254	-.0221	-.0141	-.0304	-.0213	-.0218	-.0231	-.0165	-.0234	-.0134	-.0320	-.0308	.0431	.0398
.60					-.0362	-.0330	-.0332	-.0250	-.0270	-.0170	-.0566	-.0554	-.0511	-.0477
.70					-.0557	-.0571	-.0507	-.0459	-.0433	-.0447	-.0593	-.0589	-.0537	-.0496
.80	-.0283	-.0513	-.0527	-.0568	-.0588	-.0588	-.0612	-.0621	-.0571	-.0574	-.0517	-.0520	-.0521	-.0479
.90	-.0472	-.0628	-.0608	-.0624	-.0573	-.0573	-.0589	-.0609	-.0581	-.0578	-.0576	-.0577	-.0582	-.0545
.95			-.0629	-.0631			-.0591	-.0597						

TAIL 2

235

TABLE XXI. - CONCLUDED
(h) α = 19.70°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.4728		.6216	.4101	.5119	.3540	.5029	.3568						
.10	.4621	.1875	.6222	.3254	.5530	.3471			.5392	.3546			.1844	.2011
.15	.4391	.2624	.6015	.3254	.5614	.3436			.5310	.3465			.1991	.1995
.20	.4351	.2780	.5703	.3250	.5648	.3381	.5072	.2640	.5317	.3418	.5249	.3386	.2135	.2225
.25	.2156	.1003			.5584	.3350	.5433	.3365	.5340	.3381	.5235	.3426	.2288	.2064
.30	.1825	.1147							.5274	.3327	.5117	.3354	.2345	.2105
.40	.1414	.1271	.1825	.0761	.2179	.0860	.2195	.0993	.2463	.1220	.4895	.3241	.2309	.2095
.50			.1569	.0657	.2031	.0756	.2016	.0786			.2231	.1778	.2396	.1922
.60	.0408	.0852			.1920	.0722	.1784	.0266	.1832	.0751	.1656	.0617	.0332	.0235
.70	-.0266	.2286	.1177	.0728	.1765	.0665	.1567	.0342	.0453	.0162	.0134	.0228	.0200	.0175
.80	-.0?34	-.0165	.0035	-.0077			.0216	.0025	.0095	.0070	.0042	.0079	.0224	.0165
.90	-.0213	-.0186	-.0209	-.0036	.1100	-.0036	.0078	.0015	.0121	.0037	.0098	.0038		
.95			-.1145	-.0004			.0030	.0016	-.0117	-.0039	.0097	.0132	.0112	.1143

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0287	.0456	.0103	.0858			-.0002	.1089	.1463	.0932	.0140	.0368	.0229	.1323
.10	.0017	.0308					-.0049	.1101	.0017	.1122			.0176	.1269
.15					-.0038	.0978	-.0036	.1075	-.0071	.1106			.0097	.1134
.20	-.0034	.0257					-.0052	.1054					.0041	.1034
.25	-.0250	.0313	-.0347	.0440	-.0120	.0883	-.0053	.1013	-.0085	.1078	.0028	.1080	.0000	.0953
.30			-.0407	.0160			-.0070	.0909	-.0082	.1022	.1132	.1090	-.0037	.0947
.40									.2404	.0153	.0103	.0944	-.0081	.0946
.50					-.0351	-.0123	.0427	-.0047	.0454	.0008	.0418	.0088	.0187	.0635
.60	-.0035	-.0240	-.0362	-.0196			.0507	.0132	.0455	.0037	.0520	.0201	.0633	.0426
.70					-.0467	-.0218	.0595	.0401	.0498	.0423	.0618	.0522	.0581	.0491
.80	-.0428	-.0540	-.0615	-.0523	-.0600	-.0551	.0648	.0603			.0618	.0573		
.90	-.0535	-.0652	-.0667	-.0596	-.0618	-.0595	.0630	.0624	.0594	.0528	.0555	.0528	.0550	.0483
.95			-.0677	-.0622	-.0609	-.0592	.0629	.0629	.0616	.0601	.0612	.0594	.0621	.0563

TAIL 2

TABLE XXII.- PRESSURE COEFFICIENTS, θ = 90°, δ_{1,3} = -15°, M = 1.60

(a) α = -3.29°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.5215	-.1191	1.0727	-.3154	1.0961	-.3726	1.1175	-.3835	-.0396	-.3714				
.10	.5430	-.1034	.8653	-.2975	1.0043				-.0454	-.3463	.6435			
.15	.6308	-.0935	.8906	-.2321	.9180	-.3146	.8812		-.0532	-.3206				
.20	.6549	-.0713	.7641	-.2643	.8035	-.2663	.8050		.2545	-.3030	.8412			
.25					.7400	-.2491			.8517	-.2761	.8413			
.30	.5851	-.1531	.6433	-.3352	.5826	-.3905	.5201	-.3955	.7754	-.2513	.7003			
.40	.6227	-.2055	.6436	-.2960	.6413	-.3935	.6302	-.3935	.4822	-.3950	.6571			
.50											.3319			
.60					.6032	-.3852	.5935	-.3943			.4328			
.70	.5116	-.1887	.5562	-.2366	.5374	-.3788	.4233	-.3945	.0224	-.3643	.0056	-.3855		
.80	-.1508	-.3040	.0331	-.3709			.0273	-.3737	.0128	-.3589	-.0191	-.3620		
.90	-.0179	-.3433	.0080	-.3344	.0319	-.3679	.0264	-.3533	-.0085	-.3601	-.0185			
.95	-.0599	-.3156	-.0111	-.2490			.0121	-.3419	-.0017	-.3519	-.0333			

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2319	.2900	.2433	.5177			.4777	.6554	.5076	.6019	.4540	.7201	.2978	.5506
.10	.2418	.2836					.5154	.5791	.4699	.5774			.4607	.5184
.15					.4244	.4899	.4757	.5349	.4478	.5376	.5086	.5554	.4321	.4471
.20	.2639	.3102	.0403	.3220	.3814	.4319	.4456	.5012	.4339	.5024	.4443	.5351	.4073	.3940
.25	.1291	.1029	-.0531	-.0231			.4200	.4638	.4226	.4562	.4358	.4656	.3762	.3475
.30							.3723	.4025	-.0502	-.0273	.3647	.3506	.3464	.3227
.40	.3294	.3948			-.0256	.0582	-.0555	-.0040	-.0744	-.0428	-.0834	-.0724	.3054	.2262
.50			.3373	.3737			-.0554	.0248	-.0750	-.0363	-.1443	-.1418	.1965	.1355
.60	.3390	.4306			.2364	.1553	-.1575	-.1278	-.2195	-.1756	-.1405	-.1263	-.1176	-.1006
.70			-.0731	-.0311	-.0838	.0146	-.1373	-.1030			-.1519	-.1415	-.1256	-.1123
.80	.1032	.0818	-.0512	-.0575	-.1093	-.0304	-.1013	-.0120	-.1297	-.1550	-.1392	-.1647		
.90	.0877	.1001	.0309	.0053	-.0401	-.0290	-.0489	-.0145	-.1087	-.1268	-.1302	-.1681	-.0907	-.1091
.95													-.0832	-.1082

TAIL 2

237

TABLE XXII. - CONTINUED
(b) α = -1.30°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.4619	-.0244	.9983	-.2385	-.0528	-.345	1.0738	-.3384	.9838	-.3254				
.10	.4813	-.0635	.8941	-.1841	.9572	-.2714			.9356	-.2873	.9916	-.3267		
.15	.5297	-.0613	.8258	-.1699	.873	-.2133			.9140	-.2533				
.20	.5311	-.0456	.7384	-.1533	.7886	-.1997	.8292	-.2144	.8454	-.2381	.847	-.2355		
.25					.6962	-.1945	.7501	-.1833			.6133	-.2025		
.30	.4534	-.1363	.3649	-.2898	.2823	-.3542	.2457	-.3542	.7012	-.1823	.7131	-.2020		
.40	.4952	-.1935	.5235	-.2745	.5753	-.3572	.5801	-.3554	.2390	-.3134	-.1872	-.1957		
.50					.5527	-.355	.5718	-.3534			-.1957	-.3375		
.60											-.4035	-.2711		
.70	.4292	-.1650	.5108	-.2051	.5082	-.2480	.4073	-.3735	.0142	-.3943	-.0124	-.3589		
.80	-.1646	-.2810	.0136	-.3605	.0097	-.3580	-.0145	-.3671	-.0051	-.3553	-.0331	-.3638		
.90	-.0525	-.3420	-.0170	-.3281			-.0027	-.3616	-.0130	-.3425	-.0382	-.3666		
.95	-.0793	-.3178	-.0311	-.2355			-.0076	-.3474	-.0229	-.3944	-.0545	-.3663		

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2236	.2723	.2508	.5043			.4743	.6375	.5075	.5853	.4477	.7008		
.10	.2465	.2563					.5072	.5547	.5525	.5674				
.15	.2573	.2304	.3455	.3114	.4243	.4843	.4689	.5260	.4411	.5304	.4934	.5902		
.20	.1260	.1934	-.0642	-.0399	.3672	.4257	.4377	.4985	.4230	.4886	.4352	.5133		
.25							.4225	.4623			.4230	.4839		
.30	.2756	.3352					.2748	.3996	.4135	.4412	.3535	.3372		
.40					-.0461	.0331	-.0640	-.0264	-.0545	-.0375	-.0924	-.0792		
.50	.3213	.3555					-.0494	-.0013	-.0752	-.0512	-.1535	-.1672		
.60			.2260	.3216	.1903	.1089	-.1768	-.1581	-.0815	-.0445	-.2262	-.1746		
.70	.0422	.0632	-.1613	-.0354	-.0897	-.0417	-.1836	-.1532	-.2912	-.2424	-.2374	-.1914		
.80	.0513	.0655	-.1111	-.1037	-.1334	-.0852	-.1371	-.0676	-.2085	-.1797	-.2007	-.2096		
.95			-.0238	-.0428	-.1151	-.0864	-.1151	-.0714	-.1905	-.1780	-.1793	-.2043		

TAIL 2

TABLE XXII. - CONTINUED
(c) a = 0.70°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.33 U.S.	0.33 L.S.	0.98 U.S.	0.98 L.S.
.05	.4494	.0383	.9155	-.1538	.9975	-.2252	1.0309	-.2712	.9338	-.2692			.6412	.3692
.10	.4462	.0200	.8142	-.1112	.8947	-.1896			.9471	-.2158	.5535			.3125
.15		.0681		-.1618		-.1325		-.1575	.8572	-.1974				
.20	.4553	.0441		-.0863	.7368	-.1097	.7920		.8012	-.1597	.8107		.6001	
.25					.6513	-.1046	.7131	-.1152	.7459	-.1250	.8850		.6233	
.30	.3823	-.1180			.2290	-.3128	.1614	-.3135	.6310		.7001		.4880	
.40	.3748	-.1610	.2538	-.2526	.3125	-.3205	.2850	-.3255	.6857	-.3040	.5525	.3295	.3803	
.50			.3212	-.2464				-.3335				.3465	.270	
.60			.4004	-.1553	.4438	-.3150	.4093	-.3575	-.0188	-.3228	.1650	.3465	.2039	
.70	.3203	-.1442	-.0198	-.3385	.4550	-.3070	.3570	-.3622	-.0271	-.3351	.1220	-.3215	.2630	.4554
.80	.1876	-.2736	-.0479	-.3205			-.0087	-.3463	-.0326	-.3337	.1085	-.3675	.2159	.4571
.90	-.110?	-.3319	-.0592	-.2334	-.0152	-.3527	-.0241	-.3321	-.0425	-.3320	.0895	-.3565	.2125	
.95	-.1112	-.3202					-.0341				.0343			

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2202	.2517	.2996	.5013			.4837	.6277	.5027		.4530	.6853	.3177	.5392
.10	.2345	.2578					.4994	.5604	.5027	.5674	.4986	.5838	.4381	.4839
.15					.4238	.4743	.4553	.5215	.4334	.5489			.4138	.4131
.20	.2245	.2540	.0379	.2913	.3729	.4107	.4213	.4833	.4296	.5087	.4305	.5043	.3794	.3541
.25	.1294	.1209	-.0781	-.0534			.4052	.4468	.4098	.4659	.4158	.4653	.3372	.3063
.30							.3622	.3683	.3938	.4153	.3362	.3300	.3065	.2785
.40	.2381	.2796			-.0592	.0163	-.0745	-.0388	-.0644	-.0501	-.1039	-.0805	.2687	.2276
.50							-.0643	-.0200	-.0935	-.0600	-.1564	-.1735	-.1733	.0946
.50	.2531	.2866	.2089	.2550	.1352	.0981	-.1914	-.1744	-.0833	-.0526	-.2579	-.2093	-.2278	-.2013
.70							-.2109	-.1741	-.3014	-.2557	-.2583	-.2197	-.2409	-.2153
.80	-.0065	-.0105	-.1338	-.1081	-.1259	-.0702	-.1604	-.0971	.2413	.2059	-.2237	-.2257	-.2314	-.2170
.90	.0200	.0344	-.1439	-.1480	-.1544	-.1100	-.1480	-.1000	.2254	.1938	-.1990	-.2153	-.2342	-.2068
.95			-.0679	-.0871	-.1435	-.1136								

TAIL 2

TABLE XXII.- CONTINUED
(d) α = 2.71°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.4548	.1095	.6364	-.0609	.9418	-.1867	.9751	-.1877	.8874	-.2042			.6126	-.2155
.10	.4234	.0320	.7338	-.0385	.8445	-.0964			.9992	-.1384	.9035	-.1512		
.15	.4457	.0123	.6836	-.0136	.768	-.0332			.8264	-.1028			.4558	-.1553
.20	.4308	.0205	.6164	.0056	.6517	-.0251	.7421	-.0465	.7533	-.0564	.7570	-.0812		-.0271
.25					.5202	-.0270	.6695	-.0336	.7079	-.0463	.7443	-.0575	.3060	-.0150
.30	.1657	-.1011							.6312	-.0439	.6626	-.0613	.4253	-.0250
.40	.2811	-.1293	.1751	-.2192	.1450	-.2739	.1051	-.2680	.0653	-.2634	.5234	-.0652	.3535	-.0343
.50			.2568	-.2154	.2198	-.2736	.1981	-.2820			.0237	-.2837	.2515	-.0250
.60					.2713	-.2564	.2656	-.2824			.0502	-.3131	.2284	-.3783
.70	.2214	-.1200	.3045	-.1154	.3224	-.2625	.2270	-.3224	-.1107	-.3453	-.1812	-.3480	-.2294	-.3728
.80	-.2110	-.2737	-.0710	-.3204			-.0785	-.3599	-.1091	-.3429	-.1806	-.3604	-.2801	-.44
.90	-.1424	-.2314	-.0982	-.3310	-.0588	-.3344	-.0758	-.3344	-.1075	-.3424	-.1753	-.3653	-.2424	-.44
.95	-.1491	-.3289	-.0981	-.2793			-.0783	-.3109	-.1135	-.3335	-.1814	-.3468	-.2452	-.4411

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2073	.2293	.3186	.4993			.4929	.6117			.4424	.6525	.3354	.5342
.10	.2151	.2315					.4756	.5460					.4130	.4706
.15	.1920				.4016	.4654	.4333	.5015	.4154	.5231	.4833	.5583	.3606	.4030
.20	.1945	.2160	.0257	.2741			.3873	.4655	.4174	.4833			.3446	.3429
.25	-.1045	.1013	-.1007	-.0436	.3491	.3930	.3832	.4208	.3872	.4424	.4129	.4789	.3061	.2963
.30							.3508	.3412	.3788	.3957	.3975	.4522	.2823	.2557
.40	.1966	.2303							-.0793	-.0533	.3174	.3204	.2544	.2057
.50	.2023	.2304	.1651	.2052	-.0688	-.0000	-.0863	-.0498	-.0947	-.0553	-.1104	-.0861	.1501	.0613
.60							-.0785	-.0312	-.0970	-.0564	-.1745	-.1786	-.2225	-.228
.70	-.0543	-.0523	.1651	.1412	.1057	.0584	-.2048	-.1838	-.3061	-.2687	-.2855	-.2346	-.2035	-.2267
.90	-.0133	-.0027	-.1243	-.1751	-.1755	-.1345	-.1850	-.1255	-.2551	-.2130	-.2527	-.2432	-.2472	-.2411
.95			-.1056	-.1135	-.1723	-.1387	-.1684	-.1233	-.2350	-.2143	-.2269	-.2377	-.2366	-.2272

TAIL 2

TABLE XXII. - CONTINUED
(α) α = 4.73°

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.4307	.1409	.7585	.0380	.8846	-.0945	.9115	-.0980	.8275	-.1294			.3731	-.2231
.10	.4043	.0934	.6442	.0651	.7820	.0284			.8431	-.0112	.8565	-.0933	.3208	-.1900
.15	.4160	.0671	.6059	.0651	.7137	.0631			.7703	.0122			.3334	.0413
.20	.4053	.0654	.5598	.0613	.6470	.0660	.6833	.0375	.7164	-.0275	.7203	.0032	.3334	-.0217
.25					.5744	.0530	.6265	.0514	.7223	.0370	.7043	.0132	.4111	-.0413
.30	-.1019	-.0693	.1045	-.1291	.0915	-.2202	.0625	-.2213	.6243	.0442	.6243	-.0217	.3631	-.0338
.40	.2010	-.0732	.1666	-.1753	-.1382	-.2334	-.1327	-.2355	.0413	-.2103	.4941	.0143	.2211	-.0650
.50					-.1744	-.2255	-.1724	-.2412			-.0007	-.2356	.2211	-.0550
.60											.0103	-.2708	.3250	-.3495
.70	-.1457	-.0938	.2386	-.0818	.2074	-.2163	-.1177	-.2842	-.1562	-.3731	-.2188	-.3480	.3225	-.3389
.80	-.2363	-.2602	-.1248	-.3019			-.1383	-.3474	-.1632	-.3455	-.2224	-.3495	-.2741	-.4113
.90	-.1738	-.2552	-.1456	-.3254	-.1129	-.3223	-.1395	-.3271	-.1699	-.3473	-.2203	-.3499	-.2578	-.4152
.95	-.1683	-.3086	-.1452	-.2956			-.1427	-.3015	-.1763	-.3383	-.2267	-.3338	-.2609	-.4004

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.2685	.2995	.3850	.5277			.4743	.5976		.5205	.4373	.6237	.3371	.5302
.10	.2516	.2740					.4645	.5262	.4866		.4694	.5357	.4021	.4672
.15					.3907	.4524	.4261	.4773	.4172	.5015			.3707	.3956
.20	.1827	.2126	.0209	.2577	.5447	.3702	.3942	.4367	.4106	.4657	.3971	.4550	.3193	.3295
.25	-.0184	-.0156	-.1063	-.0853			.2717	.3963	.3719	.4309	.3797	.4362	.2965	.2769
.30							.3355	.3259	.3524	.3853	.2934	.3052	.2778	.2427
.40	.0992	.1663	.1512	.1780			-.0954	-.0534	-.0936	-.0629	-.1096	.0927	.2383	.1817
.50					-.0837	-.0239	-.0936	-.0442	-.1037	-.0673	-.1791	-.1807	-.1259	-.0385
.60	.1680	.2090					-.2239	-.2027	-.1032	-.0627	-.2302	-.3102	-.3148	-.2707
.70					.0611	.0038	-.2623	-.2244	-.3094	-.2751			-.3283	-.2706
.80	-.0846	-.1360	-.1627	-.1440	-.1653	-.1243	-.2139	-.1653			-.2979	-.2715		
.90	-.1015	-.0947	-.2040	-.1839	-.1852	-.1402	-.1739	-.1391	-.2700	-.2353	-.2862	-.2707	-.2557	-.2601
.95			-.1939	-.1802	-.1840	-.1484			-.2472	-.2313	-.2734	-.2552	-.2508	-.2401

TAIL 2

TABLE XXII.- CONTINUED
(f) α = 6.70°

Cp at y/b of

TAIL 1

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.3358	.1624	.6403	.1267	.7936	.0365	.8278	.0394	.7642	-.0110			.5169	-.2301
.10	.3278	.1374	.5736	.1543	.6931	.1604			.7705	.1042	.7989	.0452	.6763	-.0653
.15	.3454	.1189	.5454	.1697	.6418	.1715			.7066	.1266			.5830	-.0523
.20	.3415	.1226	.5029	.1580	.5903	.1651	.6325	.1539	.6602	.1443	.6708	.1121	.5122	-.1020
.25					.5254	.1615	.5753	.1533	.6136	.1585	.6532	.1622	.1353	-.1242
.30	.0585	-.0265	.0426	-.1380	-.0452	-.861	.0354	-.1744	.5534	.1612	.5857	.1311	.3555	-.1133
.40	.1534	-.0317	.0200	-.1012	-.0737	-.953	.0730	-.945	.0161	-.1658	.4653	.1252	.2226	-.1265
.50					.1011	-.1833	.1018	-.2027			-.0183	-.1762	-.2078	-.0969
.60											-.0231	-.2230	-.2209	-.3190
.70	.1133	-.0628	.1772	-.0538	.1202	-.1466	.0535	-.2577	-.1969	-.3727	-.2505	-.3533	-.2528	-.2923
.80	-.2565	-.2432	-.1551	-.2825			-.2102	-.3324	-.2102	-.3336	-.2575	-.3314	-.2628	-.3251
.90	-.1726	-.2392	-.1757	-.3100	-.1583	-.3014	-.1873	-.3205	-.2131	-.3258	-.2565	-.3271	-.2555	-.3759
.95	-.1763	-.2821	-.1770	-.2787			-.1862	-.2995	-.2202	-.3105	-.2627	-.3163	-.2353	-.3563

Cp at y/b of

TAIL 2

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.2937	.3419	.4248	.5622			.4845	.5735	.4705	.5116	.4161	.6067	.3295	.5220
.10	.3661	.3898					.4551	.5091	.4007	.4940			.3853	.4595
.15					.2872	.4376	.4112	.4668	.3840	.4597	.4498	.5152	.3482	.3816
.20	.1755	.2048	.6108	.2341	.3265	.3681	.3733	.4343	.3554	.4200	.3829	.4430	.2959	.3149
.25	-.0712	-.0681	-.1191	-.1001			.3485	.3971	.3317	.3725	.3644	.4123	.2317	.2622
.30							.3158	.3241	-.1012	-.0721	.2732	.2873	.2641	.2265
.40	-.0098	.0035			-.0920	-.0531	-.0990	-.0584	-.1092	-.0740	-.1126	-.0373	.2148	.1527
.50	.1526	.1810	.1653	.1915			-.1003	-.0531	-.1070	-.0671	-.1842	-.1813	-.1006	.0163
.60					-.0031	-.0362	-.2342	-.2119	-.3113	-.2798	-.3387	-.3225	-.3294	.0316
.70							-.2840	-.2492			-.3145	-.3030	-.3325	-.2540
.80	-.1183	-.1699	-.1613	-.1382	-.1760	-.1515	-.2494	-.2079	-.2768	-.2406	-.2990	-.2840	-.2793	-.2678
.90	-.1372	-.1303	-.2012	-.1946	-.1879	-.1365	-.1981	-.1661	-.2660	-.2383	-.2893	-.2802	-.2644	-.2463
.95			-.2226	-.2125	-.1892	-.1394								

TABLE XXII.- CONTINUED
(g) α = 8.70°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2432	.1830	.5055	.2258	.6602	.2181	.7287	.2112	.6862	.1557			.4887	-.1607
.10	.2473	.1753	.4427	.2542	.5723	.285?			.6602	.2817	.7275			
.15	.2649	.1709	.4273	.2364	.5300	.2224	.5730	.2563	.6077	.2735	.6146			
.20	.2602	.1863	.4091	.2148	.4933	.254?	.5179	.2527	.5725	.2924				
.25					.4792	.2289			.5333	.2632				
.30	.0209	-.0214	-.0127	-.0923	.0120	-.1538	.0028	-.1394	.4846	.2456	.4411			
.40	.0383	.0347	.0217	.0489	.0237	-.1497	.0193	-.1609	-.0155	-.1332	-.0349			-.1522
.50					.0391	-.1147	.0473	-.1656			-.0545			-.3105
.70	-.1025	-.0310	-.1299	-.0207	.0526	-.0564	-.0022	-.2180	-.2266	-.3525	-.2766	-.2508	-.3073	-.2515
.80	-.2764	-.2229	-.1713	-.2587			-.2320	-.3225	-.2420	-.3228	-.2874	-.3184	-.2660	-.2624
.90	-.1626	-.2256	-.1384	-.2899	-.1876	-.2760	-.2327	-.2951	-.2462	-.3077	-.2874	-.3153	-.2433	-.2563
.95	-.1777	-.2581	-.2043	-.2715			-.2273	-.2716	-.2528	-.2933	-.2869	-.3062	-.2432	-.2613

Cp at y/b of

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2200	.2910	.3657	.5810			.4633	.6089			.3964	.6158	.3132	.5106
.10	.2304	.2705					.4653	.5402	.4672	.5031			.3732	.4533
.15					.4056	.4513	.4225	.4901	.4052	.4828	.4358	.5288	.3253	.3727
.20	.2308	.3207					.3835	.4470	.3820	.4458			.2865	.3035
.25	-.0471	-.0222	.0035	.2325	.3420	.3680	.3556	.4040	.3563	.4052	.3753	.4473	.2878	.2463
.30	-.0343	-.0536	-.1357	-.1123			.3190	.3263	.3276	.3545	.3533	.4154	.2552	.2089
.40									-.1036	-.0808	.2610	.2851	.2015	.1378
.50	.1085	.1187	.0461	.0108	-.0854	-.0671	-.0898	-.0512	-.1097	-.0800	-.1098	-.0353	-.0854	-.0082
.60							-.0929	-.0578	-.1033	-.0799	-.1849	-.1783	-.3410	-.3171
.70			-.1767	-.1220	-.1037	-.0883	-.2315	-.2236	-.3056	-.2291	-.3372	-.3153	-.3413	-.3099
.80	-.1226	-.1611	-.2026	-.1903	-.2412	-.2251	-.3102	-.2840	-.2827	-.2503	-.3225	-.3444	-.2896	-.2805
.90	-.1561	-.1476	-.2176	-.2169	-.1957	-.1677	-.2730	-.2481	-.2743	-.2400	-.2970	-.2842	-.2654	-.2535
.95					-.1934	-.1404	-.2313	-.2365			-.2310	-.2791		

243

TABLE XXII. - CONTINUED
(h) α = 10.59°

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1532	.2218	.3732	.3403	.5243	.4229	.5916	.4434	.6095	.4389			.3632	.3737
.10	.1724	.2249	.3348	.3223	.4577	.3895			.5522	.4120	.6197	.4491	.5439	.3505
.15	.1703	.2241	.3130	.2973	.4293	.3514			.4912	.3864			.4611	.3456
.20	.1523	.2437	.3653	.2728	.4008	.3260	.4640	.3485	.4882	.3659	.5254	.3895	.4004	.3232
.25					.3757	.2947	.4291	.3271	.4705	.3421	.5903	.3803	.3370	.2905
.30	-.0630	.0728							.4356	.3221	.4881	.3575	.2973	.2421
.40	-.0034	.0508	-.0670	-.0336	-.0773	-.1158	-.0379	-.1103	-.0298	-.0822	.4022	.3005	.2532	.2174
.50	-.0158	.0376	-.0337	-.0855	-.0400	-.0802	-.0297	-.1236			.0515	.1156	.1975	.1456
.60	.0254	-.0033		-.1113	-.0335	-.0483	-.0135	-.1002			.0852	.1724	-.2633	-.3090
.70	-.0752	-.0011	-.1110	-.0143	-.0172	.0012	-.0531	-.1473	-.2642	-.3218	-.2995	-.2163	-.2777	-.2671
.80	-.2500	-.373	-.1950	-.2400			-.2687	-.2724	-.2774	-.3195	-.3107	-.2933	-.2612	-.2841
.90	-.1540	-.2103	-.2200	-.2742	-.2215	-.2549	-.2624	-.2527	-.2793	-.2891	-.3018	-.3053	-.2675	-.3425
.95	-.1625	-.2327	-.2235	-.2641			-.2399	-.2487	-.2620	-.2786	-.2879	-.2942	-.2562	-.3350

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.2118	.2646	.3662	.5494			.4664	.5104			.3742	.5880	.3076	.4934
.10	.212	.522					.4845	.5424	.4693	.5100			.3633	.4475
.15					.4220	.4830	.4376	.4928	.4094	.4912	.4207	.5006	.3105	.3650
.20	.1623	.2453	.0367	.1907	.3517	.3904	.3938	.4493	.3825	.4532	.3675	.4247	.2930	.3603
.25	.0525	.0102	.1750	-.1418			.3648	.4106	.3564	.4193	.3500	.3920	.2932	.2744
.30							.3305	.3367	.3270	.3771	.2552	.2552	.2453	.2070
.40	-.0158	-.0376			-.0860	.0701	-.0779	-.0408	-.1014	-.0696	.2552	.2552	.1500	.1333
.50	.0254	-.0033		-.1113			-.0887	-.0551	-.1011	-.0611	-.1120	-.1023	.0700	-.0731
.60					-.1212	-.0954	-.2318	-.2219	-.0302	-.0516	-.1842	-.1784	-.3438	-.3268
.70	-.1410	-.1560	-.1975	-.1753	-.3076	-.2796	-.3158	-.2958	-.2987	-.2730	-.3331	-.3124	-.3404	-.3209
.80			-.2219	-.1883	-.2646	-.2435	-.2868	-.2564	-.2674	-.2663	-.3262	-.3134		
.90	-.1697	-.1545	-.2356	-.1850	-.2300	-.2132	-.2671	-.2519	-.2831	-.2566	-.2957	-.2936	-.2998	-.2752
.95											-.2898	-.2715	-.2701	-.2453

TAIL 2

TABLE XXII.- CONTINUED
(I) a = 12.70°

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0818	.2499	.2414	.4550	.3235	.5506	.4151	.5632	.4638	.5677			.0743	.4154
.10	.0961	.2669	.2270	.3939	.3539	.4762			.4499	.5330	.4935	.5549	.5022	.4583
.15	.0726	.2785	.2170	.3588	.3191	.4282			.3687	.4914		.4833	.4357	.4043
.20	.0287	.3180	.1991	.3422	.2955	.3938	.3479	.4208	.3816	.4625	.4178	.4637	.3981	.4453
.25					.2737	.3632	.3272	.4048	.3737	.4345	.4172	.4342	.2963	.2885
.30	-.1486	.1433	-.1190	.0771	-.0921	-.0691	-.0800	-.0677	.3500	.4039	.3972	.3472	.2507	.2620
.40	-.0351	.1283	-.0912	.1226	-.0941	-.0137	-.0786	-.0672	-.0648	-.0655	.3451	.3177	.2218	.2231
.50					-.0892	.0223	-.0701	-.0590			-.0767	-.0937	-.1798	.1801
.60			.0577	.0507	-.0731	.1063					-.1155	-.1438	-.2261	.1522
.70	-.0349	.0312	-.2038	-.2221			-.1114	-.0810	-.2962	-.2973	-.3208	-.3117	-.2746	-.3101
.80	-.2203	-.1777	-.2485	-.2532	-.2521	-.2364	-.3034	-.2215	-.3081	-.2915	-.3002	-.2845	-.2553	-.2573
.90	-.1480	-.2100					-.2721	-.2243	-.2777	-.2582	-.2801	-.2856	-.2635	-.2873
.95	-.1628	-.2145	-.2554	-.2506			-.2617	-.2310	-.2644	-.2587	-.2913	-.2896	-.2846	-.2773

TAIL 2

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1939	.2719	.3200	.5145			.4913	.6627	.5005	.5359	.3864	.5871	.2216	.4962
.10	.1831	.2615					.5455	.5904	.4365	.5153			.2756	.4513
.15					.4672	.5067	.4840	.5303	.4166	.4774	.4233	.5015	.3043	.3675
.20	.1398	.2022	-.0805	.1200	.3603	.3851	.4231	.4786	.3796	.4363	.3853	.4344	.3109	.3054
.25	-.0807	-.0363	-.2165	-.1988			.3962	.4322	.3532	.3659	.3577	.4033	.2948	.2471
.30							.3600	.3552			.2676	.2754	.2503	.2104
.40	-.0379	-.0327					-.0734	-.0449	-.0842	-.0558	-.1027	-.0860	.1829	.1351
.50					-.1085	-.0952	-.0880	-.0651	-.0773	-.0455	-.1697	-.1585	.0644	.0163
.60	-.0305	-.0837	-.1831	-.1771	-.1510	-.1338	-.2315	-.2301	-.0730	-.0412	-.3168	-.2931	-.3562	-.3941
.70					-.3371	-.3234	-.3243	-.3054	-.2958	-.2697	-.3250	-.3042	-.3367	-.3327
.80	-.1734	-.1993	-.2111	-.2297	-.3061	-.2822	-.3079	-.2930	-.2913	-.2302	-.2857	-.2834	-.2955	-.2715
.90	-.1689	-.1633	-.2351	-.2258	-.2835	-.2735	-.2894	-.2662	-.2847	-.2799	-.2812	-.2663	-.2633	-.2333
.95			-.2555	-.2343										

245

TABLE XXII.- CONTINUED
(j) α = 16.71°

TAIL 1

| x/c | Cp at y/b of | | | | | | | | | | | | |
| | 0.02 | | 0.22 | | 0.44 | | 0.56 | | 0.67 | | 0.83 | | 0.98 | |
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	-.0580	.3097	.0098	.5836	.0001	.7328	-.0039	.7664	-.0031	.8005			-.2318	.7563
.10	-.0463	.3653	.0164	.5273	-.1136	.6562			.1092	.7016	.1137	.7152	-.0131	.6590
.15	-.1026	.4187	-.0331	.5227	-.1136	.6052			.1204	.6412			-.0905	.5183
.20	-.1911	.4643	-.0423	.5021	-.1018	.5517	.1602	.5705	.1407	.5939	.1618	.6251	-.1384	.4415
.25					-.0910	.4733	-.1330	.5154	-.1584	.5472	.1763	.5932	-.1517	.3680
.30	-.2660	.2563			-.1837	.3306	-.1755		-.1517	.4931	.1738	.5318	-.1518	.3133
.40	-.0594	.2090	-.2116	.2662	-.1878	.0918	-.1856	.0383	-.1541	-.0369	-.1625	-.4042	-.1326	-.2363
.50			-.1822	.1830	-.1876	.2062	-.1620	-.1225			-.1483	-.0661	-.1044	-.1239
.60											-.1891	-.1008	-.3230	-.3314
.70	.0102	.0912	-.0273	.1277	-.1829	.1596	-.2101	-.0799	-.3559	-.1938	-.3538	-.2990	-.2675	-.3298
.80	-.2162	-.1436	-.2568	.1623			-.3566	-.1584	-.3520	-.1673	-.3230	-.3006	-.2724	-.2838
.90	-.1752	-.2144	-.2878	-.2192	-.3075	-.1959	-.3235	-.1873	-.3228	-.1759	-.3195	-.2820	-.3234	-.2596
.95	-.1862	-.2091	-.2744	-.2304			-.2886	-.1944	-.3112	-.1845	-.3118	-.2768	-.3498	-.2715

TAIL 2

| x/c | Cp at y/b of | | | | | | | | | | | | |
| | 0.02 | | 0.22 | | 0.44 | | 0.56 | | 0.67 | | 0.83 | | 0.98 | |
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1558	.2238	.2749	.4089			.4464	.6468			.4989	.7019	.3726	.5463
.10	.1435	.2082					.5445	.6378	.5703	.6594			.4146	.4942
.15					.4054	.4453	.5233	.5546	.5643	.6118	.5062	.5610	.3539	.4107
.20	.1092	.1605					.4915	.4467	.5136	.5353			.3436	.3451
.25	-.1072	-.0742	-.0404	.2019	.2406	.2145	.3611	.3548	.4590	.4723	.4556	.5121	.3326	.2892
.30			-.1719	-.1408			.2914	.2678	.4195	.4146	.4266	.4768	.2956	.2569
.40	-.0668	-.0364							-.0629	-.0521	.3380	.3402	.2407	.1886
.50			-.2032	-.1934	-.2692	-.2652	-.1635	-.1657	-.0994	-.0838	-.0887	-.0613	.1178	.0344
.60	-.0460	-.0950					-.2023	-.1977	-.1184	-.0996	-.1520	-.1528	-.3364	-.3182
.70					-.3224	-.3117	-.3223	-.3256	-.3272	-.3109	-.3188	-.3018	-.3388	-.3206
.80	-.2772	-.3167	-.3081	-.3061	-.3979	-.3955	-.3942	-.3850	-.3523	-.3413	-.3306	-.3165		
.90	-.2798	-.2970	-.2982	-.3045	-.3866	-.3825	-.3881	-.3856			-.2963	-.3051	-.2530	-.2196
.95	-.2832	-.2788			-.3719	-.3725	-.3742	-.3775	-.3408	-.3403	-.2917	-.2904	-.2285	-.2018

TABLE XXII.- CONCLUDED
(h) α = 18.70°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.1860	.3574	-.1795	.6417	-.2122	.7905	-.2342	.8202	-.2245	.8562	-.1653	.7670	-.3069	.8055
.10	-.1990	.4393	-.1593	.6204	-.1487	.7059			-.1507	.7588			-.2576	.6912
.15	-.3205	.4936	-.1429	.6060	-.1059	.6430			-.1129	.6325			-.1402	.5535
.20	-.3308	.5243	-.1157	.5567	-.0986	.5809	-.0528	.6228	-.0945	.6391	-.0805	.6541	-.0552	.4749
.25					-.0938	.5099	-.0769	.5529	-.0710	.5837	-.0682	.6263	-.0156	.39??
.30	-.3345	.3002	-.2734	.3071	-.2933	.0844	-.2788	.0237	-.0639	.5197	-.0674	.5580	-.0122	.34??
.40	-.0891	.2350	-.2256	.2050	-.2906	.2684	-.2941	.0920	-.2709	-.0237	-.0653	.4202	-.0044	.2533
.50					-.2743	.2358	-.2685	.2809			-.2621	.0501	-.0158	.1358
.60	-.0430	.1180	-.0854	.1699	-.2553	.1937	-.3149	.1222			-.2880	.0706	-.0649	.3364
.70	-.2450	-.1241	-.2944	-.1721			-.3662	.1433	-.3837	.1143	-.3676	.2668	-.3431	.3142
.80	-.1897	-.2078	-.3176	-.1937	-.3446	-.1663	-.3554	.1776	-.3606	.1422	-.3668	.2478	-.3770	.3017
.90	-.1969	-.2026	-.2878	-.2142			-.3378	.1834	-.3518	.1571	-.3592	.2270	-.3740	.2736
.95									-.3435	.1681	-.3455	.2103	-.3594	.27??

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1392	.2054	.2763	.3438			.3402	.2899	.4772	.5032	.5233	.7085	.3485	.6216
.10	.1374	.1965					.3756	.4146	.5225	.5300			.4534	.5935
.15					.2757	.3510	.3812	.4454	.4839	.4954	.5548	.6366	.4356	.5202
.20	-.0915	.1904	-.0654	.1042	.1608	.2074	.3497	.4069	.4325	.4277	.4859	.5471	.4021	.4532
.25	-.1115	-.0976	-.1929	-.1956			.2877	.3220	.3813	.3607	.4580	.4891	.3595	.4057
.30							.2296	.2179	-.0879	-.1148	.3634	.3298	.3354	.3723
.40	-.0764	-.0713			-.2976	-.2808	-.2228	-.2260	-.1364	-.1786	-.0787	-.0958	.2882	.3046
.50							.2571	-.2758	-.1648	-.2188	-.1612	-.2075	.1732	.1487
.60	-.0825	.1366	-.2120	-.2117	-.3556	-.3572	-.3510	-.3868	-.3538	-.3844	-.3289	-.3520	-.2071	-.2593
.70							-.4222	-.4372			-.3427	-.3683	-.3212	-.2200
.80	-.2898	-.3227	-.3132	-.3352	-.4332	-.4457	-.4253	-.4411	-.3735	-.4081	-.3212	-.362?	-.2602	-.2807
.90	-.2911	-.3071	-.3195	-.3478	-.4192	-.4304	-.4167	-.4327	-.3780	-.4082	-.3115	-.3555	-.2558	-.2962
.95			-.3204	-.3425	-.4094	-.4277								

TABLE XXIII.- PRESSURE COEFFICIENTS. $\theta = 90°$, $\delta_{1,3} = -15°$, $M = 2.36$

(a) $\alpha = -4.05°$

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.3628	-.048C	-.0C63	-.091?	.0?5?	-.095?	-.099?	-.0976	.0373	-.?7??				
.10	.4063	-.C578	.896?	-.09?4	.3678	-.0?13			.964?	-.0925				
.15	.470?	-.C5?4	.834?	-.C957	.324?	-.0?4?	.065?	-.0506	.814?	-.0?2?				
.20	.235?	-.130?	79?.?	-.C394	.855?	-.?9??	.83??	-.0872	.8738	-.84?				
.25	.2340	-.136?			.803?	-.?9??			.8122	-.?80?				
.30	.381?	-.1?6	.3400	-.1685	.3?6?	-.?7??	.3243	-.1664	.3103	-.?572				
.40	.334C	-.1025	.3235	-.170?	.37?C	-.18??	.3823	-.1843						
.50	-.0318	-.1448	.3720	-.1661	.385?	-.17??	.3057	-.566	.3993	-.?73?				
.60	.0218	-.177?	.1008	-.1902	.37??	-.172?	.3407	-.1677	.1205	-.16??	.0372	-.1?5?		
.80	.0422	-.1671	.071?	-.179?	.0726	-.17?6	.0863	-.1681	.1959	-.16??	.0758	-.1056		
.90			.0625	-.1733			.37??	-.1691	.0922	-.165?	.0674	-.1003		
.95							.0653	-.1587	.0822	-.1649	.0561	-.?8?		-.1703

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1457	.1869	.2383	.3162			.2592	.2986	.2473	.2723	.2512	.1819	.2853	.2639
.10	.1383	.1673					.2676	.3104	.2660	.3025			.2425	.2665
.15					.2647	.3047	.2593	.3025	.2617	.2994			.2042	.2455
.20	.1267	.1486	.0741	.2214	.2584	.2896	.2539	.2996	.2583	.2982	.2530	.2861	.1761	.2209
.25	-.0196	-.0034	-.0090	.0145			.2536	.2941	.2545	.2912	.2562	.2885	.1802	.1988
.30							.2505	.2714	.2299	.0482	.2365	.2657	.1777	.1844
.40					-.0010	.0148	.0046	.0216	.0050	.0195	.0154	.0361	.1830	.1748
.50	.2032	.1370	-.0204	-.0145	-.0210	-.1831	-.0011	-.0138	-.0015	-.0133	-.1344	-.0291	.1564	.1223
.60					-.1203	-.1287	-.0807	-.0776	-.1314	-.1184	-.1373	-.1257	.1242	.175
.70							-.1144	-.1281					.1292	.1363
.80	.0791	.0703	-.0632	-.0752	-.1095	-.1070	-.1030	-.1048	-.1058	-.1174	-.1136	-.1243	.1085	.1068
.90	.0765	.1722	-.0741	-.0717	-.1091	-.1042	-.0990	-.1006	-.1740	-.1029	-.1079	-.1117	.1224	.1343
.95			-.0727	.1672							-.1072	-.1088		

TABLE XXIII.- CONTINUED
(b) α = -2.05°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.3166	-.0562	.9938	-.2621	1.0043	-.0552						
.10	.3322	-.0251	.3134	-.0583	.9025	-.05..							.9832	-.09.1
.15	.3675	-.0362	.3504	-.0637	.5473	-.05.7			.9619	-.0.31	.39..		.842.	-.0.0.
.20	.3938	-.0416	.3999	-.0675	.7961	-.0585	.9152	-.0574	.8931	-.0520			.77.9	
.25	.1761	-.1151			.7561	-.0605	.7843	-.0606	.9536	-.05.4	.9615		.7.0	
.30	.1821	-.1018							.8204	-.0574	.8.15			
.40	.2634	-.1044	.2706	-.1568	.2993	-.1535	.2922	-.1542	.7711	-.0609	.7.24		.9.3	
.50			.2523	-.1581	.3157	-.1740	.3257	-.1715	.2953	-.1532	.2905		.3560	-.0.55
.60	.2555	-.0976	.3014	-.1539	.3160	-.1733	.3459	-.163.	.338.	-.1696	.2767	-.15.0	.4.94	-.01.7
.70	-.0042	-.1374	.0613	-.1875	.3085	-.1644	.2905	-.1569	.0819	-.1569	.0518	-.1569	.0.94	-.1.35
.80	-.0296	-.1802	.0345	-.1706			.0507	-.1575	.0518	-.1573	.0391	-.1588	-.0674	-.1709
.90	-.0121	-.1728	-.0246	-.1645	-.0254	-.1620	.0390	-.1583	.0513	-.1571	.0310	-.15.4	-.0623	-.1810
.95							.0310	-.1581	.0439	-.1572	.0208	-.15.7	-.0613	-.1720

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1302	.1651	.2297	.3081			.2534	.2961	.2451	.2807	.2465	.170.	.2897	.2832
.10	.1257	.143.					.2637	.3052		.2997			.2327	.271.
.15					.2596	.2997	.2552	.2973	.2611	.2961			.200.	.2455
.20	.1165	.336.	.063.	.2125			.2555	.2954	.2577	.296.			.177	.2186
.25	-.0182	-.0034	-.0130	-.0084	.2523	.2835	.2545	.2900	.2547	.2939	.2483	.2551	.1809	.19.2
.30							.2449	.2572	.2512	.2861	.2520	.2578	.794	.8..
.40									.0247	.0451	.2348	.2612	.776	.71.
.50	.1828	.1343	-.0175	-.0124	-.0043	.0102	.0026	.0196	.0036	-.0207	.0147	.0370	.515	.5..
.60							-.0029	.0111	-.0028	.0131	-.0358	.0258	.3.5	.64
.70					-.0243	-.0104	-.0854	-.0808	-.1317	-.1186	-.1374	-.1243	.30.	-.1339
.80	.2531	.0437	-.0654	-.0710	-.1252	-.1303	-.1155	-.1285	-.1068	-.1056	-.1134	-.1290	-.098.	-.0929
.90	.0542	.0510	-.2817	-.0825	-.113.	-.1081	-.1055	-.1050	-.1073	.105	-.1057	.105.	-.1062	-.10..
.95			-.08..	-.0747	-.1126	-.1043	-.1040	-.1016	-.1056	-.1019	-.1057				

TAIL 2

249

TABLE XXIII.- CONTINUED
(c) α = -0.05°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05														
.10	.3086	.0011	.8095	-.0196	.8950	-.0218	.8921	-.0148						
.15	.3255	-.0101	.7223	-.0244	.8127	-.0183								
.20	.3387	-.0211	.6604	-.0264	.7609	-.0230	.7508	-.0307						
.25	.1332	.0312	.5146	-.0304	.7181	-.0270	.7189	-.0287						
.30	.1383	-.0819			.6886	-.0310								
.40	.2050	-.0947	.2104	-.1433	.2566	-.1439	.2611	-.1389						
.50			.1910	-.1424		-.1573	.2765	-.1556						
.60					.2620	-.1590	.2932	-.1584	.2853	-.1558				
.70	.1942	-.0900	.2280	-.1329	.2528	-.1574	.2263	-.1533	-.0465	-.1499				
.80	-.0336	-.1336	-.0245	-.1773			.0176	-.1490	-.0177	-.1502				
.90	-.0610	-.1727	-.0027	-.1624	-.0114	-.1529	-.0048	-.1495	.0171	-.1498				
.95	-.0461	-.1747	-.0064	-.1483			-.0026	-.1494	.0110	-.1497				

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1092	.1407	.2244	.3037			.2484	.2935	.2423	.2805	.2414	.1800	.2848	.2831
.10	.1088	.1296					.2592	.2999	.2581	.2973			.2292	.2755
.15					.2562	.2966	.2517	.2925	.2549	.2927			.975	.2481
.20	.1025	.1161	.0694	.2043	.2481	.2779	.2510	.2913					.1799	.2176
.25	-.0120	-.0000	-.0173	.0027			.2508	.2856	.2517	.2890	.2436	.2819	.1854	.1905
.30							.2429	.2637	.2494	.2802	.2475	.2847	.1801	.1795
.40					-.0056	.0082	.0028	.0180	.0210	.0454	.2324	.2634	.1765	.1686
.50	.1560	.1248	-.0061	-.0041			-.0037	-.0085	.0047	.0227	.0136	.0356	.1457	.1137
.60					-.0267	-.0118	-.0852	-.0831	-.0013	.0136	-.0372	-.0268	-.1306	-.1254
.70			-.0691	-.0715	-.1274	-.1329	-.1157	-.1287	-.1327	-.1200	-.1362	-.1243	-.1296	-.1368
.80	.0257	.0194	-.0862	-.0857	-.1155	-.1098	-.1064	-.1061	-.1047	-.1034	-.1125	-.1325		
.90	-.0315	.0326	-.0847	-.0792	-.1153	-.1050	-.1054	-.1033	-.1041	-.1004	-.1067	-.1095	-.1010	-.0069
.95											-.1062	-.1048	-.1095	-.1015

TABLE XXIII.- CONTINUED
(d) α = 1.95°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05					.7367	.0144	.7409	.0228						
.10	.2844	-.0290	.6677	.0197	.7208	.0165			.7647	.0255			.7777	-.0290
.15	.2865	-.0220	.6324	.0171	.6781	.0126			.7161	.0138			.6927	-.0375
.20	.2897	-.0083	.5805	.0130	.6396	.0091	.6696	.0004	.6938	.0100	.7322	.0159	.6357	-.0224
.25	.0910	-.0875	.5370	.0092	.6150	.0053	.6459	.0066	.6787	.0077	.7194	.0122	.5879	-.0394
.30	.0929	-.0801							.6521	.0046	.6904	.0081	.5373	-.0324
.40	.1319	-.0821	.1618	-.1274	.2128	-.1258	.2273	-.1206	.2421	-.1170	.6331	-.0015	.4833	-.0323
.50			.1461	-.1252	.2110	-.1387	.2285	-.1379	.2363	-.1396	.2462	-.1208	.4152	-.0278
.60	.1459	-.0804	.1542	-.1149	.2087	-.1408	.2394	-.1474	.0124	-.1426	.2100	-.1444	-.0621	-.1472
.70	-.0538	-.1331	-.0129	-.1617	.2031	-.1437	.1774	-.1483	-.0154	-.1425	-.0024	-.1440	-.0896	-.1472
.80	-.0839	-.1502	-.0285	-.1548			-.0138	-.1408	-.0157	-.1417	-.0192	-.1441	-.0932	-.1644
.90					-.0401	-.1422	-.0255	-.1407			-.0286	-.1450		
.95	-.0729	-.1733	-.0348	-.1509			-.0327	-.1408	-.0211	-.1419	-.0376	-.1450	-.0896	-.1647

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0918	.1315	.2282	.3009			.2441	.2903			.2381	.1802	.2785	.2800
.10	.0923	.1179					.2555	.2948	.2399	.2793			.2263	.2771
.15													.1950	.2483
.20	.0880	.1048			.2535	.2908	.2506	.2889	.2552	.2951			.1845	
.25	-.0081	.0033	.0598	.1961	.2465	.2734	.2500	.2876	.2514	.2886	.2411	.2801	.1832	.1901
.30			-.0229	-.0023			.2497	.2823	.2502	.2849	.2457	.2824	.1780	.1800
.40					-.0069	.0057	.2414	.2595	.2488	.2779	.2316	.2591	.1728	.1679
.50	.1258						.0039	.0175	.0230	.0424	.0148	.0332	.1412	.1095
.60		.0987	-.0052	.0022	-.0256	-.0143	-.0043	-.0070	.0042	.0218	-.0367	-.0263	-.1316	-.1313
.70					-.0286		-.0856	-.0850	-.0010	.0138	-.1354	-.1241	-.1221	-.1364
.80	.0025	-.0042	-.0754	-.0765	-.1286	-.1362	-.1156	-.1302	-.1337	-.1216	-.1132	-.1340	-.1013	-.0991
.90	.0087	.0093	-.0938	-.0949	-.1168	-.1135	-.1071	-.1072	-.1047	-.1043	-.1065	-.1117	-.1084	-.1089
.95			-.0926	-.0891	-.1173	-.1089	-.1065	-.1047	-.1043	-.1019	-.1058	-.1059		

251

TABLE XXIII.- CONTINUED
(e) α = 3.95°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.99 U.S.	0.99 L.S.
.05	.2575	.0551	.5363	.0632	.5704	.0538	.5601	.0617		.0640			.6105	
.10	.2474	.0533	.5047	.0607	.6021	.0561			.6334	.0527	.6234	.0522	.5815	
.15	.2461	.0533	.4727	.0567	.5751	.0533	.5770	.0366	.6125	.0495	.6253	.0501	.5525	
.20	-.0577	.0424	.4474	.0514	.5470	.0498	.5556	.0455	.5981	.0474	.5664	.0462	.5094	
.25	-.0614	-.0697			.5280	.0462		-.0898	.5904	.0439	.5660	-.0360	.4663	
.30	-.0749	-.0633	.1164	-.1079	.1639	-.1044	.1847	-.1161	.5711	-.0950		-.0936	.4298	
.40		-.0717	.1072	-.1051	.1591	-.1161	.1776	-.1303	.2094		.2209	-.1268	.3776	
.50	.1062	-.0669	.0976	-.0965	.1553	-.1186	.1847	-.1400	.1867	-.1188	.1772	-.1362	.0718	
.60	-.0702	-.1272	.0527	-.1534	.1529	-.1237	.1261	-.1330	-.0143	-.1365	-.0278	-.1365	-.0808	
.70	-.0962	-.1372	.0643	-.1449	-.0551	-.1334	-.0455	-.1333	-.0468	-.1355	-.0453	-.1374	-.0976	
.80	-.0943	-.1592	.0639	-.1437			-.0659	-.1334	-.0478	-.1343	-.0548	-.1374	-.0984	
									-.0526	-.1343	-.0638			

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0965	.1736	.2291	.2906			.2421	.2664			.2374	.1797	.2725	.2768
.10	.0902	.1473					.2546	.2901	.2379	.2756			.2240	.2772
.15					.2532	.2849	.2521	.2850	.2543	.2913			.1953	.2458
.20	.0840	.1225					.2506	.2826	.2506	.2847			.1927	.2155
.25	-.0241	-.0051	.0709	.2050	.2477	.2679	.2438	.2751	.2499	.2816	.2415	.2807	.1957	.1929
.30			-.0170	.0357			.2410	.2530	.2478	.2729	.2462	.2822	.1835	.1829
.40											.2316	.2570	.1710	.1690
.50	.0833	.0928	-.0212	-.1410	-.0028	.0072	-.0047	.0145	.0250	.0416	.0148	.0317	.1407	.1090
.60							-.0036	-.0093	.0013	.0203	-.0362	-.0276	-.1346	-.1354
.70					-.0208	-.0092	-.0849	-.0844	-.0004	.0125	-.1356	-.1252	-.1259	-.1366
.80	-.0385	-.0583	-.0938	-.0976	-.1354	-.1343	-.1206	-.1329	-.1331	-.1239	-.1178	-.1345		
.90	-.0332	-.0308	-.0946	-.1045	-.1167	-.1135	-.1088	-.1115	-.1077	-.1066	-.1085	-.1129	-.1015	-.1073
.95			-.0970	-.1065	-.1171	-.1084	-.1078	-.1070	-.1076	-.1047	-.1080	-.1066	-.1096	-.1125

TABLE XXIII.--CONTINUED
(1) α = 5.96°

TAIL 1

	Cp at η/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.2024	.0743	.4205	.1110	.4305	.0973	.4314	.1048	.5088	.1079		.0958	.4857	.0767
.10	.1938	.0800	.3969	.1102	.4871	.1021	.4749	.0790	.4907	.0970	.5125	.0944	.4655	.0952
.15	.1901	.0737	.3768	.1048	.4692	.0994	.4678	.0924	.4919	.0944	.5125	.0898	.4133	.0681
.20	.0272	-.0521	.3533	.0957	.4508	.0963			.4929	.0922	.5054		.4134	.0657
.25	.0319	-.0445			.4366	.0929			.4822	.0883	.4799	.0782	.3806	.0609
.30	.0304	-.0469	.0662	-.0870	.1154	-.0785	.1404	-.0757	.1651	-.0698	.1753	-.0749	.3563	.0606
.40			.0582	-.0830	.1072	-.0904	.1304	-.0908	-.1382	-.0933	-.0529	-.1053	.3174	.0463
.50					.1047	-.0935	.1282	-.1081	-.0427	-.1298	-.0704	-.1275	-.0864	-.1278
.60	.0716	-.0485	.0498	-.0743	.1002	-.1006	.0755	-.1240	-.0759	-.1271	-.0794	-.1279	-.0909	-.1272
.70	-.0785	-.1151	-.0841	-.1503			-.0748	-.1247	-.0777	-.1254		-.1284	-.0927	-.1281
.80	-.0955	-.1253	-.0959	-.1368	.0929	-.1244	-.0850	-.1247	-.0824	-.1253	-.0873	-.1285		
.90	-.0910	-.1467	-.0929	-.1347			-.0909	-.1248					-.0854	-.1476
.95														

TAIL 2

	Cp at η/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.1079	.2031	.2352	.2898			.2448	.2841	.2374	.2766	.2386	.1752	.2652	.2774
.10	.0969	.1745					.2571	.2866	.2549	.2884			.2235	.2776
.15					.2567	.2803	.2547	.2822	.2515	.2817			.1985	.2474
.20	.0743	.1397					.2512	.2793					.2040	.2187
.25	-.0478	-.0124	.0704	.2136	.2516	.2654	.2502	.2720	.2506	.2763	.2440	.2806	.2029	.1981
.30			-.0136	.0125			.2406	.2488	.2487	.2675	.2478	.2812	.1901	.1882
.40											.2333	.2529	.1741	.1717
.50					.0034	.0123	.0089	.0169	.0266	.0381	.0169	.0290	.1401	.1077
.60	.0521	.0044	-.0490	-.0400			.0022	.0083	.0048	.0177	-.0343	-.0295	-.1375	-.1388
.70					-.0169	-.0016	-.0807	-.0791	.0004	.0113	-.1350	-.1269	-.1283	-.1346
.80	-.0600	-.0781	-.1153	-.1329	-.1415	-.1330	-.1351	-.1294	-.1312	-.1249	-.1190	-.1346	-.1051	-.1070
.90	-.0592	-.0618	-.010	-.1185	-.1188	-.1153	-.1145	-.1160	-.1110	-.1094	-.1087	-.1118	-.1139	-.1123
.95			-.1027	-.1146	-.1171	-.1096	-.1119	-.1081	-.1100	-.1059	-.1077	-.1063		

253

TABLE XXIII.- CONTINUED
(g) α = 7.95°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.3186	.1595	.3178	.1447	.3386	.1535	.4083	.1591				.1640
.10	.1348	.0944	.3075	.1616	.3779	.1529			.3925	.1483			.3929	.1369
.15	.1400	.1021	.2828	.1518	.3702	.1501			.3893	.1462	.4129	.1435	.3727	.1047
.20	.1317	.0938	.2657	.1385	.3551	.1476	.3999	.1276	.3917	.1432	.4142	.1427	.3548	.0953
.25	-.0081	-.0349			.3453	.1445	.3754	.1438	.3869	.1389	.4079	.1388	.3294	.0815
.30	-.0126	-.0272	.0194	-.0657	.0705	-.0513	.0931	-.0465	.1127	-.0395	.3896	.1277	.3008	.0793
.40	-.0109	-.0168	.0112	-.0602	.0562	-.0629	.0806	-.0607			.1271	-.0467	.2797	.0663
.50					.0514	-.0680	.0910	-.0800	.0898	-.0650	.0877	-.0796	.2480	
.60	.0556	-.0299	.0090	-.0488	.0476	-.0765	.0329	-.1012	-.0734	-.1372	-.0795	-.1226	-.1046	-.1242
.70	-.0976	-.1005	-.1141	-.1441			-.1030	-.1196	-.1002	-.1228	-.0957	-.1223	-.1054	-.1239
.80	-.0880	-.1134	-.1204	-.1355	-.1160	-.1185	-.1124	-.1192	-.1039	-.1207	-.1042	-.1226		-.1218
.90	-.0806	-.1347	-.1142	-.1294			-.1169	-.1192	-.1082	-.1205	-.1108	-.1225	-.1055	-.1519

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1029	.1978	.2229	.2821			.2508	.2834			.2427	.1760	.2604	.2766
.10	.0903	.1715					.2624	.2852	.2402	.2725			.2243	.2779
.15					.2621	.2803	.2597	.2804	.2586	.2871			.2066	.2483
.20	.0681	.1347					.2551	.2779	.2555	.2799			.2130	.2237
.25	-.0585	-.0188	.0729	.2139	.2536	.2666	.2525	.2714	.2539	.2740	.2456	.2797	.2094	.2030
.30			-.0183	-.0109			.2422	.2487	.2506	.2638	.2476	.2789	.1915	.1927
.40					.0248	.0220	.0101	.0177	.0254	.0361	.2324	.2486	.1721	.1718
.50							-.0144	.0135	.0033	.0150	.0171	.0276	.1387	.1083
.60	-.0169	-.0336	-.0851	-.0541	-.0064	.0152	-.0680	-.0717	-.0013	.0090	-.0345	-.0314	-.1405	-.1407
.70					-.1419	-.1281	-.1335	-.1206	-.1301	-.1242	-.1359	-.1280	-.1295	-.1345
.80	-.0648	-.0947	-.1330	-.1252	-.1241	-.1160	-.1187	-.1234	-.1129	-.1112	-.1195	-.1330		
.90	-.0722	-.0879	-.1298	-.1233	-.1198	-.1096	-.1123	-.1124	-.1100	-.1064	-.1095	-.1094	-.1046	-.1061
.95			-.1295	-.1232							-.1090	-.1045	-.1145	-.1115

TABLE XXIII.- CONTINUED
(h) α = 9.95°

TAIL 1

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05				.2525		.1981	.2551	.2089				.1782		
.10	.0677	.1153	.2234	.2128	.2245	.2090			.3150	.2162			.3110	.2326
.15	.0773	.1230	.2180	.2144	.2762	.2073			.3035	.2067			.2866	.1758
.20	.0664	.1224	.1995	.1967	.2758	.2053	.3114	.1858	.2980	.2045	.3202	.1989	.2731	.1532
.25	-.0613	-.0166	.1838	.1794	.2641	.2010	.2832	.2022	.2989	.2015	.3211	.1992	.2515	.1386
.30	-.0644	-.0091			.2572				.2926	.1970	.3166	.1963	.2093	.1236
.40	-.0566	.0145	-.0245	-.0431	-.0241	-.0223	-.0434	-.0138	.0624	-.0059	.3018	.1831	.1861	.1134
.50			-.0290	-.0359	-.0087	-.0358	-.0299	-.0278			.0732	-.0142		.0931
.60			-.0326		.0026	-.0422	-.0458	-.0466	.0378	-.0313	-.0351	-.0501	-.1210	-.1329
.70	.0522	-.0137	-.1350	-.0182	-.0025	-.0517	-.0095	-.0769	-.1041	-.1409	-.1086	-.1323	-.1197	-.1275
.80	.1118	-.0883	-.1255	-.1262			-.1289	-.1228	-.1249	-.1254	-.1220	-.1207	-.1274	-.1223
.90	.0682	-.1040	-.1201	-.1420	-.1364	-.1165	-.1371	-.1185	-.1290	-.1194	-.1284	-.1194		
.95	.0767	-.1209		-.1298			-.1333	-.1179	-.1299	-.1188	-.1303	-.1190	-.1039	-.1219

TAIL 2

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	.0901	.1766	.1780	.2525			.2602	.2828			.2444	.1782	.2560	.2752
.10	.0796	.1499					.2702	.2852	.2476	.2711			.2239	.2762
.15					.2678	.2783	.2654	.2769	.2650	.2863			.2136	.2484
.20	.0646	.1177					.2614	.2757	.2593	.2785	.2476	.2783	.2174	.2242
.25	-.0605	-.0276	.0319	.1817	.2608	.2679	.2601	.2723	.2574	.2718	.2481	.2753	.2126	.2044
.30			-.0536	-.0137			.2512	.2515	.2545	.2639	.2314	.2435	.1951	.1940
.40							.0155	.0197	.0286	.0363	.0168	.0245	.1754	.1727
.50	-.0520	-.0481	-.1084	-.0680	.0218	.0202	-.0243	-.0188	.0074	.0164	-.0336	-.0337	.1382	.1092
.60							-.0548	-.0597	-.0043	.0114	-.1356	-.1295	-.1423	-.1424
.70					-.0077	-.0236	-.1279	-.1124	-.1260	-.1237			-.1252	-.1324
.80	-.1220	-.1352	-.1494	-.1377	-.1438	-.1297	-.1326	-.1258	-.1126	-.1123	-.1188	-.1315	-.1040	-.1004
.90	-.1224	-.1418	-.1507	-.1385	-.1502	-.1471	-.1174	-.1275	-.1055	-.1065	-.1085	-.1087		
.95			-.1525	-.1402	-.1369	-.1455					-.1074	-.1043	-.1134	-.1106

TABLE XXIII.- CONTINUED
(i) a = 11.95°

Cp at y/b of

TAIL 1

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.1455	.2724	.1507	.2574	.1840	.2699						
.10	.0136	.1385	.1443	.2656	.1848	.2732			.2359	.2813			.2315	.2755
.15	.0212	.1470	.1299	.2399	.1973	.2728			.2267	.2723			.2098	.2243
.20	.0050	.1483	.1136	.2190	.1854	.2683	.2329	.2483	.2241	.2705	.2437	.2654	.2000	.2364
.25	-.1014	.0023			.1798	.2615	.2043	.2680	.2230	.2681	.2335	.2618	.1816	.1890
.30	-.0997	.0104	-.0632	-.0192	-.0169	.0046	-.0005	.0226	.2155	.2629	.2317	.2587	.1615	.1713
.40	-.0767	.0483	-.0673	-.0103	-.0337	-.0092	-.0149	-.0055	.0146	.0333	.2227	.2422	.1515	.1543
.50					-.0401	-.0159	-.0029	-.0157			.0255	.0218	.1329	.1288
.60			-.0546	.0123	-.0467	-.0259	-.0492	-.0491	-.0090	.0057	-.0094	-.0168	-.1334	-.1373
.70	.0414	.0041							-.1271	-.1238	-.1334	-.1363	-.1404	-.1474
.80	-.0836	-.0773	-.1369	-.1072	-.1276	-.1186	-.1471	-.1441	-.1454	-.1423	-.1416	-.1357	-.1338	-.1410
.90	-.0588	-.0985	-.1280	-.1336			-.1298	-.1254	-.1258	-.1262	-.1211	-.1168		
.95	-.0746	-.1084	-.1249	-.1320			-.1260	-.1206	-.1209	-.1197	-.1160	-.1135	-.0952	-.1024

Cp at y/b of

TAIL 2

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0821	.1591	.1178	.2104			.2659	.2673	.2569	.2697	.2519	.1776	.2576	.2758
.10	.0710	.1352					.2772	.2773	.2798	.2863			.2281	.2787
.15					.2253	.2367	.2659	.2710	.2747	.2803			.2231	.2500
.20	.0550	.1087					.2614	.2664	.2712	.2756	.2559	.2779	.2247	.2260
.25	-.0675	-.0335	-.0115	.1297	.2105	.2263	.2613	.2638	.2682	.2680	.2572	.2760	.2191	.2064
.30			-.0840	-.0422			.2556	.2461	.0362	.0382	.2411	.2483	.2015	.1962
.40					-.0243	-.0212	.0059	.0103	.0161	.0192	.0212	.0270	.1814	.1739
.50	-.0647	-.0539	-.1092	-.0863			.0174	.0032	.0105	.0138	-.0284	-.0315	.1424	.1101
.60					-.0264	.0131	-.0475	-.0693	-.1245	-.1201	-.1321	-.1281	-.1413	-.1424
.70							-.1272	-.1059			-.1173	-.1304	-.1224	-.1292
.80	-.1323	-.1431	-.1734	-.1698	-.1564	-.1333	-.1444	-.1201	-.1138	-.1081	-.1050	-.1075	-.1014	-.0996
.90	-.1384	-.1542	-.1726	-.1718	-.1729	-.1557	-.1286	-.1280	-.1021	-.1032	-.1037	-.1030	-.1104	-.1090
.95			-.1710	-.1700	-.1605	-.1618								

TABLE XXIII.- CONTINUED
(j) α = 15.95°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0934	.1825	-.0136	.3799	.0101	.4137	.0441	.4312					.0935	.3727
.10	-.0986	.1919	-.0207	.3383	.0461	.4254							.0717	.3633
.15	-.1068	.1961	-.0013	.3050	.0608	.4053	.1352	.3829	.0817	.4436	.0900	.4165	.0624	.3433
.20	-.1496	-.0399	.0052	.2822	.0608	.3809	.0722	.3958	.0885	.4342	.0908	.4199	.0543	.3271
.25	-.1363	-.0536			.0553	.3607			.0924	.4271	.0958	.4138	.0435	.3071
.30	-.0962	-.1006							.0858	.4159	.0893	.3826	.0497	.2834
.40			-.1175	.0290	-.0851	.0525	-.0725	.0749	.0959	.3954	-.0550	-.1007	.0458	.2434
.50			-.1141	.0505	-.1029	.0424	-.0905	.0572	-.0655	.1201	-.0840	.0558	-.1463	-.1211
.60					-.1100	.0384	-.0513	.0363	-.0905	.0635	-.1386	-.0972	-.1502	-.1233
.70	.0101	.0378	-.0738	.0788	-.1180	.0335	-.1184	-.0053	-.1437	-.0933	-.1359	-.1113	-.1228	-.1201
.80	-.0820	-.0583	-.1407	-.0846			-.1330	-.1166	-.1358	-.1179	-.1353	-.1185		
.90	-.0687	-.1012	-.1498	-.1047	-.1355	-.1057	-.1335	-.1244	-.1317	-.1211				
.95	-.0832	-.1016	-.1329	-.1086			-.1338	-.1261	-.1311	-.1239	-.1351	-.1227	-.1429	-.1181

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0429	.1283	.0635	.1157			.1325	.1417			.2853	.1777	.2779	.2847
.10	.0301	.1120					.1239	.1433	.2243	.2378			.2456	.2875
.15					.0242	.0524	.1127	.1380	.2251	.2268			.2411	.2569
.20	.0080	.0780	-.0473	.0786	.0103	.0372	.1059	.1325	.2178	.2205	.2780	.2823	.2391	.2278
.25	-.0979	-.0542	-.1112	-.0662			.0991	.1224	.2103	.2198	.2811	.2830	.2326	.2050
.30							.0310	.1056	.2040	.2143	.2687	.2654	.2162	.1939
.40					-.1350	-.1208			-.0187	-.0048	.0365	.0368	.1944	.1773
.50			-.1442	-.1145			-.0984	-.0852	-.0467	-.0344	-.0160	-.0232	.1593	.1135
.60	-.0919	-.0717			-.1361	-.1302	-.1099	-.1014	-.0581	-.0443	-.1267	-.1227	-.1355	-.1379
.70			-.1942	-.1813	-.1868	-.1806	-.1546	-.1520	-.1615	-.1477	-.1399	-.1346	-.1315	-.1318
.80	-.1556	-.1603	-.1905	-.1895	-.1847	-.1783	-.1847	-.1780			-.1241	-.1295		
.90	-.1657	-.1770	-.1879	-.1869	-.1814	-.1766	-.1741	-.1780	-.1589	-.1621	-.1159	-.1219	-.1071	-.1068
.95							-.1629	-.1715	-.1533	-.1562			-.1147	-.1128

TAIL 2

TABLE XXIII.- CONCLUDED
(h) a = 19.95°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	-.0996	.2644	-.0229	.4953	-.0225	.6013	.0158	.6425						
.10	-.319	.2773	-.0389	.4355	-.0014	.5587			.0459	.6170			.0708	.6135
.15	-.1702	.2853	-.0573	.3974	-.0005	.5195			.0363	.5779			.0532	.582?
.20	-.1825	.1029	-.0762	.3770	-.0357	.4859	.0478	.4568	.0285	.5349	.0500		.0468	.5449
.25	-.1782	.1214			-.0176	.4535	-.0047	.4973	-.0242	.5322	.0417	.5657	.0403	.4953
.30	-.1561	.1774	-.1636	-.1003	-.1322	-.1064	-.1130	.1255	.0164	.5058	.0328	.5453	.0372	.4543
.40			-.1623	-.1363	-.1546	-.0962	-.1398	.1160	-.1112	.1482	-.0207	.4637	.0348	.4006
.50					-.1623	.0992	-.1056	.0973			-.0994	.1515	-.0228	.3250
.60			-.1438	-.1506	-.1627	.1115	-.1580	-.0463	-.1385	.1227	-.1243	.1103	-.158?	.1014
.70	-.0224	.0963	-.1769	-.0522			-.1551	-.0802	-.1535	-.0590	-.1533	-.0637	-.1465	-.118b
.80	-.0366	-.0215	-.1687	-.0702	-.1556	-.0452	-.1564	-.0799	-.1486	-.0836	-.1530	-.0766	-.1334	-.1251
.90	-.0825	-.0916	-.1474	-.0757			-.1565	-.0794	-.1499	-.0867	-.1529	-.0839	-.1389	-.1235
.95	-.0951	-.1031							-.1494	-.0905	-.1529	-.0892		

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0047	.1024	-.0037	.0452			.0071	.0256			.0845	.1030	.2675	.2215
.10	-.0145	.0858					-.0012	.0290	.0895	.1330			.2375	.1987
.15					-.0256	.0117	-.0072	.0274	.0157	.0459			.2074	.1802
.20	-.0366	.0425	-.0884	.0268			-.0132	.0242	.0083	.0909	.0704	.0846	.1713	.1621
.25	-.1255	-.0795	-.1420	-.0983	-.0405	-.0020	-.0180	.0185	.0036	.0398	-.0588	-.0757	.1614	.1473
.30							-.0240	.0345	-.0004	.0336	-.0430	-.0553	.1512	.1436
.40									-.1217	-.1048	-.1060	-.1000	.1375	.1327
.50							-.1442	-.1276	-.1403	-.1256	-.1434	-.1443	.0993	.0876
.60	-.1118	-.0923	-.1651	-.1392	-.1519	-.1375	-.1560	-.1434	-.1458	-.1322	-.1924	-.1883	-.1513	-.1409
.70							-.1835	-.1778	-.1895	-.1794	-.1984	-.1932	-.1640	-.1429
.80	-.1676	-.1691	-.2020	-.1938	-.1524	-.1418	-.2005	-.1986						
.90	-.1817	-.1875	-.1985	-.1979	-.1984	-.1919	-.1937	-.1933	-.1865	-.1869	-.1861	-.1813	-.1766	-.1694
.95			-.1971	-.1958	-.1954	-.1925	-.1915	-.1907	-.1884	-.1871	-.1913	-.1887	-.1939	-.1881

TAIL 2

TABLE XXIV - PRESSURE COEFFICIENTS, $\phi = 90°$, $\delta_{1,3} = -15°$, M = 3.70

(a) $\alpha = -4.20°$

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.7656	-.0294	.7337	-.0151	.7307	-.0171						
.10	.2238	-.0217	.7437	-.0343	.8130	-.0274			.7907	-.0242			.7335	-.0172
.15	.2268	-.0223	.7038	-.0378	.7856	-.0335			.7815	-.0309		.3301	.7222	-.0151
.20	.2804	-.0260			.7553	-.0358	.7601	-.0129	.78	-.0351	.7711	-.0351	.7085	-.0157
.25	.1732	-.0454			.7519	-.0399	.7532	-.0367	.7653	-.0372	.7802	-.0361	.6803	-.0176
.30	.173	-.0462							.7632	-.0395	.7742	-.0390	.6535	-.0176
.40	.2283	-.0473	.3122	-.0465	.3233	-.0565	.3657	-.0557	.70.7	-.0429	.7410	-.0429	.6223	-.0346
.50			.2974	-.0527	.3351	-.0582	.3488	-.0569			.7415	-.0542	.5749	-.0346
.60					.3272	-.0576	.3516	-.0292	.3576	-.0486	.3471	-.0583	.0957	-.0629
.70	.2645	-.0353	.2501	-.0477	.3184	-.0578	.3022	-.0542	.1434	-.0538	.1299	-.0585	.0548	-.06.9
.80	.0780	-.0519	.0919	-.0549			.1066	-.0557	.1037	-.0484	.1121	-.0589	.0453	-.06.9
.90	.0173	-.0598	.0692	-.0548	.0869	-.0422	.0941	-.0559	.0989	-.0568	.1039	-.0589		
.95	.0007	-.0504	.0652	-.0549			.0885	-.0555	.0928	-.0568	.0956	-.0590	.0305	-.0557

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0839	.1094	.1735	.2165			.1856	.2136	.1871	.2732	.1853	.1985	.2106	.2256
.10	.0893	.1118					.1837	.2143	.1790	.2163			.2016	.2064
.15					.1759	.2054	.1787	.2126	.1772	.2106			.1814	.1855
.20	.0825	.1014	.0634	.0653	.743	.1999	.1755	.2263	.175.	.2236	.1746	.1983	.1588	.1759
.25	.0073	.0254	.0280	.0473			.1700	.1917	.1743	.2035	.1760	.2017	.1513	.163.
.30											.1587	.1841	.1440	.1573
.40					.0144	.0282	.0142	.0278	.0458	.0617	.0355	.0519	.1401	.119.
.50	.013.	.0222	.0113	.0124			.0083	.0209	.0219	.0344	.0314	.0101	.1193	.113.
.60					.0009	.0129	-.0238	-.0156	-.0143	-.0270	-.0419	-.0347	-.0356	-.022.
.70					-.0348	-.0382	-.0348	-.0390	-.0367	-.0235	-.0334	-.0384	-.0385	-.022.
.80	.0048	-.0355	-.0416	-.0388	-.0311	-.0310	-.0315	-.0297	-.0314	-.0294	-.0270	-.0231	-.0312	-.0263
.90	.0177	-.0129	-.0363	-.0344	-.0304	-.0283	-.0308	-.0282	-.0307	-.0279	-.0306	-.0292	-.0360	-.0403
.95			-.0356	-.0335										

259

TABLE XXIV.- CONTINUED
(b) α = -2.20°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.2125	-.0116	.6588	-.0163	.6016	-.0056	.6152	-.0042						
.10	.2251	-.0126	.6563	-.0224	.6572	-.0160								
.15	.2554	-.0159	.6290	-.0264	.6874	-.0220			.6753	-.0107				
.20	.1475	-.0413	.6014	-.0242	.6695	-.0248	.6866	-.0089	.6610	-.0182	.6558	-.0195		
.25	.1545	-.0412			.6606	-.0279	.6687	-.0253	.6622	-.0221	.6647	-.0248		
.40	.1674	-.0452	.2614	-.0475	.2844	-.0564	.3256	-.0533	.3452	-.0548	.6366	-.0326		
.50			.2450	-.0525	.2808	-.0577	.3065	-.0568			.3433	-.0519		
.60					.2830	-.0557	.3183	-.0294	.3148	-.0486	.2935	-.0601		
.70	.1869	-.0356	.2048	-.0465	.2758	-.0553	.2518	-.0516	.1161	-.0525	.0983	-.0585	.0285	-.0625
.80	-.0439	-.0505	.0595	-.0527			.0809	-.0529	.0778	-.0486	.0817	-.0586		
.90	-.0023	-.0615	.0385	-.0533	.0642	-.0415	.0651	-.0532	.0705	-.0566	.0742	-.0583	-.0307	-.0274
.95	-.0100	-.0609	.0349	-.0534			.0586	-.0529	.0652	-.0567	.0659	-.0581	.0109	-.0558

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0680	.0867	.1665	.2078			.1793	.2075	.1815	.2479	.1776	.1853	.2056	.2158
.10	.0776	.0946					.1779	.2091	.1732	.2098			.1968	.2001
.15					.1699	.1993	.1735	.2069	.1714	.2048			.1770	.1849
.20	.0722	.0860	.0733	.1574			.1707	.2046	.1706	.2027	.1691	.1923	.1511	.1706
.25	.0063	.0188	.0240	.0432	.1681	.1940	.1695	.2003	.1690	.1974	.1722	.1958	.1439	.1582
.30							.1638	.1863			.1624	.1815	.1363	.1523
.40									.0437	.0604			.1318	.1429
.50					.0142	.0277	.0129	.0273	.0198	.0331	.0331	.0521	.1130	.1070
.60	.0204	.0243	-.0034	.0103			-.0067	.0194	.0123	.0257	-.0031	.0093	-.0384	-.0307
.70					-.0004	.0124	-.0253	-.0169	-.0378	-.0252	-.0434	-.0357	-.0400	-.0313
.80	.0126	.0095	-.0424	-.0398	-.0343	-.0378	-.0357	-.0398			-.0350	-.0403		
.90	.0174	.0107	-.0377	-.0356	-.0318	-.0310	-.0319	-.0307	-.0326	-.0311	-.0290	-.0249	-.0307	-.0274
.95			-.0369	-.0345	-.0308	-.0284	-.0314	-.0290	-.0320	-.0295	-.0326	-.0305	-.0348	-.0323

TABLE XXIV.- CONTINUED
(c) α = -0.20°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.5453	-.0013	.5033	-.0060	.5205	.0099						
.10	.1890	-.0002	.5540	-.0055	.5490	-.0016			.5782	.0035			.5432	.0025
.15	.1950	-.0019	.5388	-.0108	.5668	-.0074	.5784	-.0035	.5661	-.0045	.5639	-.0064	.5377	.0059
.20	.2146	-.0051	.5200	-.0123	.5676	-.0105			.5627	-.0084	.5709	-.0115	.5200	.0006
.25	.1133	-.0346			.5605	-.0133	.5647	-.0125	.5655	-.0113	.5672	-.0150	.4997	.0009
.30	.1106	-.0361							.5580	-.0138	.5473	-.0139	.4756	-.0011
.40	.1234	-.0428	.2063	-.0472	.2337	-.0547	.2673	-.0507	.2746	-.0502	.2856	-.0475	.4580	-.0021
.50			.1912	-.0533	.2388	-.0596	.2564	-.0588	.2553	-.0504	.2329	-.0532	.4207	-.0040
.60					.2348	-.0557	.2677	-.0313			.0643	-.0554	.0168	-.0603
.70	.1311	-.0362	.1534	-.0456	.2268	-.0537	.2019	-.0512	.0830	-.0522	.0478	-.0563	.0087	-.0579
.80	.0175	-.0502	.0300	-.0510			.0547	-.0522	.0508	-.0478	.0417	-.0560	-.0006	-.0570
.90	-.0183	-.0615	.0080	-.0516	.0397	-.0409	.0394	-.0528	.0434	-.0551	.0356	-.0559		
.95	-.0220	-.0613	.0053	-.0519			.0328	-.0528	.0384	-.0553			-.0079	-.0519

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0551	.0644	.1626	.2032			.1749	.2043	.1776	.2323	.1747	.1769	.2052	.2120
.10	.0665	.0753					.1740	.2064	.1707	.2071			.1957	.1994
.15					.1665	.1960	.1703	.2043	.1686	.2011			.1735	.1852
.20	.0626	.0721	.0713	.1515	.1646	.1900	.1674	.2016	.1674	.1993	.1671	.1909	.1475	.1718
.25	.0080	.0186	.0213	.0391			.1661	.1972	.1658	.1943	.1706	.1942	.1409	.1595
.30							.1604	.1831			.1604	.1782	.1337	.1526
.40					.0135	.0267	.0123	.0267	.0423	.0576	.0327	.0516	.1283	.1411
.50	.0309	.0335	-.0040	.0082			.0069	.0193	.0192	.0323	-.0034	.0106	.1086	.1039
.60					-.0008	.0115	-.0252	.0174	.0120	.0256	-.0046	-.0363	-.0419	-.0341
.70					-.0354	.0389	-.0363	-.0413	-.0386	-.0267	-.0361	-.0419	-.0413	-.0331
.80	.0170	.0139	-.0421	-.0393	-.0327	-.0318	-.0327	-.0322	-.0337	-.0322	-.0302	-.0265	-.0319	-.0290
.90	.0146	.0128	-.0385	-.0362	-.0317	-.0293	-.0322	-.0302	-.0331	-.0304	-.0339	-.0308	-.0356	-.0323
.95			-.0375	-.0350										

TAIL 2

TABLE XXIV.- CONTINUED
(d) α = 1.81°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.4419	.0180	.4177	.0217	.4333	.0289						.0161
.10	.1602	.0122	.4524	.0137	.4534	.0169			.4871	.0220			.4632	.0161
.15	.1591	.0116	.4406	.0090	.4632	.0115			.4794	.0139			.4583	.0207
.20	.1780	.0089	.4255	-.0047	.4731	.0080	.4957	.0068	.4766	.0098	.4796	.0107	.4428	.0140
.25	.0794	-.0255			.4684	.0052	.4688	.0059	.4777	.0061	.4852	.0065	.4230	.0111
.30	-.0718	-.0294							.4718	.0036	.4829	.0030	.4629	.0077
.40	-.0751	-.0398	.1587	-.0441	.1871	-.0505	.2086	-.0454	.2189	-.0432	.4643	-.0025	.3853	.0052
.50			.1446	-.0509	.1805	-.0578	.1988	-.0556			.2325	-.0407	.3563	.0010
.60					.1810	-.0572	.2230	-.0323	.1970	-.0506	.1825	-.0573	.0261	-.0571
.70	-.0884	-.0359	.1123	-.0452	.1775	-.0533	.1553	-.0510	.0527	-.0518	.3372	-.0545	.0076	-.0555
.80	-.0018	-.0504	.0095	-.0438			.0287	-.0512	.0289	-.0464	.0209	-.0541	.0159	-.0546
.90	-.0278	-.0569	.0124	-.0499	.0219	-.0399	.0167	-.0516	.0199	-.0531	.0156	-.0539	.0211	-.0499
.95	-.0299	-.0591	-.0161	-.0502			.0112	-.0517	.0158	-.0534	.0104	-.0539		

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0463	.0604	.1595	.1959			.1711	.2019			.1707	.1696	.2071	.2092
.10	.0566	.0691					.1704	.2048	.1746	.2242			.1943	.1996
.15					.1644	.1938	.1670	.2020	.1681	.2040			.1715	.1875
.20	.0522	.0636	.0697	.1470	.1620	.1870	.1642	.1992	.1659	.1985	.1639	.1881	.1457	.1751
.25	.0074	.0163	.0183	.0356			.1630	.1948	.1649	.1967	.1673	.1903	.1416	.1630
.30							.1573	.1812	.1635	.1919	.1570	.1759	.1343	.1548
.40									.0409	-.0539			.1251	.1417
.50	.0352	.0362	-.0056	-.0056	.0133	.0258	.0126	.0266	.0186	-.0326	.0319	.0485	.1084	.1027
.60							.0067	.0196	.0119	-.0260	-.0037	.0102	-.0411	-.0365
.70					-.0011	.0102	-.0244	-.0175	-.0388	-.0272	-.0468	-.0376	-.0411	-.0346
.80	.0059	.0018	-.0428	-.0405	-.0362	-.0399	-.0377	-.0429			-.0383	-.0428		
.90	.0026	.0001	-.0396	-.0376	-.0334	-.0328	-.0336	-.0334	-.0343	-.0328	-.0319	-.0283	-.0324	-.0302
.95			-.0388	-.0364	-.0326	-.0299	-.0332	-.0315	-.0341	-.0312	-.0355	-.0324	-.0358	-.0337

TABLE XXIV.- CONTINUED
(c) α = 3.80°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.1346	-.0239	.3478	.0440	.3399	.0451	.3559	.0522						
.10	.1347	-.0261	.3586	.0402	.3688	.0414			.4015	.0463			.3874	.0337
.15	.1429	-.0259	.3510	.0359	.3725	.0362			.3964	.0387			.3822	.0408
.20	.0554	-.0161	.3387	.0311	.3773	.0325	.4195	.0227	.3957	.0345	.4001	.0330	.3697	.0322
.25	-.0467	-.0219			.3803	.0297	.3859	.0299	.3960	.0310	.4055	.0306	.3515	.0252
.30	-.0427	-.0345	-.1096	-.0385	-.1440	-.0424	-.1568	-.0367	.3920	.0279	.4022	.0274	.3331	.0200
.40			-.0976	-.0449	-.1316	-.0508	-.1468	-.0481	.1733	-.0314	.3854	-.0209	.3152	.0165
.50					-.1316	-.0525	-.1785	-.0306	-.1424	-.0449	.1821	-.0315	.2935	.0083
.60	-.0496	-.0345	-.0779	-.0416	-.1278	-.0523	-.1102	-.0502	-.0275	-.0495	-.1369	-.0527	-.0077	-.0551
.70	-.0147	-.0495	-.0053	-.0472	.0056		-.0047	-.0482	-.0087	-.0451	.0144	-.0529	-.0203	-.0537
.80	-.0360	-.0523	-.0257	-.0473		-.0385	-.0057	-.0483	-.0010	-.0511	-.0001	-.0524	-.0249	-.0532
.90	-.0367	-.0534	-.0299	-.0478			-.0104	-.0482	-.0047	-.0515	-.0051	-.0522	-.0261	-.0484
.95											-.0092	-.0522		

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0475	.0757	.1583	.1907			.1678	.1989			.1664	.1637	.2065	.2045
.10	-.0539	.0800					.1677	.2022	.1728	.2186			.1899	.1977
.15					.1638	.1911	.1639	.1990	.1661	.2003			.1667	.1877
.20	.0464	.0702	.0722	.1488	.1614	.1843	.1623	.1960	.1640	.1957	.1602	.1836	.1447	.1763
.25	-.0015	.0132	.0205	.0364			.1615	.1920	.1626	.1940	.1639	.1870	.1399	.1640
.30							.1561	.1778	.1611	.1893	.1534	.1697	.1310	.1551
.40									.0400	-.0543			.1316	.1414
.50	.0166	-.0242	-.0071	.0053	.0135	.0256	.0133	.0263	.0181	-.0323	.0312	-.0450	.1100	.1021
.60					-.0005	.0104	.0077	.0190	.0115	-.0259	-.0042	-.0073	-.0401	-.0381
.70	-.0175	-.0183	-.0459	-.0439	-.0385	-.0403	-.0243	-.0179	-.0389	-.0283	-.0479	-.0388	-.0423	-.0364
.80	-.0232	-.0251	-.0407	-.0388	-.0350	-.0339	-.0403	-.0446	-.0361	-.0344	-.0404	-.0445	-.0341	-.0329
.90			-.0404	-.0378	-.0340	-.0309	-.0358	-.0355	-.0360	-.0332	-.0330	-.0302	-.0379	-.0358
.95							-.0350	-.0333			-.0366	-.0344		

TAIL 2

263

TABLE XXIV.- CONTINUED
(1) $\alpha = 3.80°$

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05		.0996		.0700		.0713		.0770						.0542
.10	.0937	.0367	.2595	.0700	.2650	.0713	.2802	.0770					.3070	.0622
.15	.0913	.0367	.2669	.0678	.2912	.0680			.3189	.0724			.3008	.0522
.20	.0982	.0398	.2623	.0640	.2927	.0633			.3159	.0650	.3210	.0574	.2918	.0518
.25	.0327	.0084	.2540	.0604	.2973	.0602	.3411	.0398	.3165	.0609	.3266	.0560	.2761	.0342
.30	-.0248	-.0154			.2924	.0571	.3051	.0563	.3175	.0575	.3229	.0531	.2500	.0269
.40	-.0148	-.0273	.0652	-.0310	.0972	-.0334	-.1078	-.0267	.3133	.0542	.3104	.0453	.2479	.0182
.50			.0544	-.0370	.0853	-.0424	.0975	-.0397	.1328	-.0190	.1349	-.0210	.2258	
.60					.0821	-.0447	-.1328	-.0277	.0967	-.0379	.0951	-.0456	-.0103	.0532
.70	.0152	-.0309	.0428	-.0355	.0797	-.0469	.0690	-.0493	.0069	-.0489	-.0060	-.0516	-.0278	.0518
.80	-.0301	-.0468	-.0201	-.0460			-.0119	-.0468	-.0092	-.0438	-.0184	-.0507	-.0287	.0520
.90	-.0380	-.0498	-.0354	-.0453	-.0073	-.0375	-.0207	-.0465	-.0206	-.0493	-.0227	-.0506		
.95	-.0380	-.0529	-.0388	-.0458			-.0244	-.0462	-.0235	-.0496	-.0261	-.0505	-.0291	-.0467

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0581	.0996	.1588	.1868			.1676	.1978	.1709	.2136	.1627	.1588	.2029	.1987
.10	.0598	.0994					.1678	.2010	.1647	.1979			.1827	.1948
.15					.1650	.1903	.1645	.1982	.1625	.1933			.1597	.1861
.20	.0471	.0828	.0708	.1507			.1628	.1945	.1615	.1918	.1578	.1809	.1411	.1763
.25	-.0082	.0147	.0209	.0381	.1623	.1839	.1616	.1901	.1597	.1859	.1610	.1852	.1362	.1633
.30							.1563	.1760	.0398	-.0527	.1510	.1672	.1305	.1549
.40							.0137	.0250	.0182	.0306	.0298	.0435	.1318	.1413
.50					.0129	.0249	.0075	.0177	.0120	.0245	-.0044	.0055	.1078	.1023
.60	-.0037	.0075	-.0106	.0035	.0001	.0093	-.0243	-.0192	-.0396	-.0288	-.0489	-.0395	-.0405	-.0385
.70							-.0457	-.0471			-.0438	-.0456	-.0436	-.0377
.80	-.0358	-.0331	-.0443	-.0446	-.0432	-.0419	-.0395	-.0398	-.0391	-.0370	-.0356	-.0331	-.0364	-.0342
.90	-.0378	-.0359	-.0417	-.0350	-.0384	-.0390	-.0388	-.0371	-.0391	-.0357	-.0394	-.0369	-.0400	-.0367
.95			-.0421	-.0390	-.0372	-.0349								

TAIL 2

TABLE XXIV.- CONTINUED
(g) α = 7.80°

TAIL 1

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05			-.1737	-.0956	-.1907	-.0984	-.1983	-.1033						
.10	-.0409	-.0503	-.1798	-.0950	-.2122	-.0961			-.2281	-.1004			-.2520	-.0824
.15	-.0444	-.0523	-.1781	-.0918	-.2173	-.0924			-.2252	-.0933		-.0864	-.2433	-.0890
.20	-.0477	-.0521	-.1734	-.0887	-.2212	-.0898	-.2699	-.0630	-.2283	-.0838	-.2419	-.0837	-.2346	-.0774
.25	-.0013	-.0052			-.2192	-.0864	-.2297	-.0855	-.2331	-.0863	-.2442	-.0827	-.2199	-.0642
.30	-.0063	-.0052							-.2329	-.0829	-.2332	-.0745	-.2039	-.0539
.40	-.0097	-.0163	-.0279	-.0215	-.0582	-.0212	-.0668	-.0144	-.0920	-.0046	-.2268	-.0079	-.1891	-.0452
.50			-.0181	-.0274	-.0461	-.0306	-.0541	-.0283			-.0826	-.0359	-.1681	-.0358
.60	-.0004	-.0264	-.0108	-.0275	-.0408	-.0332	-.0930	-.0228	-.0564	-.0279	-.0502	-.0511	-.0249	-.0540
.70	-.0338	-.0423	-.0345	-.0480	-.0352	-.0371	-.0314	-.0441	-.0131	-.0519	-.0243	-.0497	-.0360	-.0534
.80	-.0370	-.0475	-.0426	-.0454			-.0288	-.0467	-.0225	-.0435	-.0334	-.0497	-.0361	-.0494
.90	-.0361	-.0526	-.0406	-.0454	-.0186	-.0363	-.0360	-.0461	-.0353	-.0488	-.0366	-.0497		
.95							-.0384	-.0458	-.0374	-.0491	-.0388	-.0497	-.0387	-.0493

TAIL 2

Cp at y/b of

x/c	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	-.0467	-.0785	-.1340	-.1692			-.1705	-.1979	-.1710	-.2112	-.1619	-.1558	-.2012	-.1947
.10	-.0527	-.0871					-.1706	-.2011	-.1662	-.1977			-.1770	-.1928
.15					-.1633	-.1873	-.1667	-.1976	-.1638	-.1936			-.1556	-.185.
.20	-.0419	-.0744	-.0517	-.1319	-.1628	-.1790	-.1639	-.1942	-.1625	-.1921	-.1574	-.1725	-.1385	-.1755
.25	-.0133	-.0096	-.0046	-.0281			-.1621	-.1898	-.1612	-.1860	-.1604	-.1840	-.1369	-.1627
.30							-.1565	-.1759			-.1509	-.1652	-.1360	-.1545
.40									-.0396	-.0537	-.0301	-.0428	-.1295	-.1415
.50					-.0154	-.0245	-.0148	-.0251	-.0129	-.0303	-.0046	-.0042	-.1074	-.1038
.60	-.0181	-.0023	-.0221	-.0067	-.0017	-.0115	-.0032	-.0189	-.0336	-.0236	-.0493	-.0405	-.0405	-.0386
.70					-.0469	-.0412	-.0509	-.0465			-.0452	-.0470	-.0440	-.0388
.80	-.0462	-.0448	-.0546	-.0526	-.0446	-.0459	-.0431	-.0428	-.0403	-.0385	-.0366	-.0347	-.0370	-.0359
.90	-.0490	-.0477	-.0518	-.0503	-.0421	-.0411	-.0419	-.0397	-.0405	-.0373	-.0399	-.0383	-.0407	-.0386
.95			-.0518	-.0497										

TABLE XXIV.- CONTINUED
(h) α = 9.80°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.1288	.1232	.1500	.1275	.1680	.1343						
.10	.0173	.0682	.1230	.1234	.1587	.1270			.1953	.1345			.2210	.1200
.15	.0196	.0714	.1128	.1200	.1578	.1239			.1902	.1273			.2119	.1214
.20	.0166	.0703	.1040	.1163	.1542	.1213	.2055	.093	.1878	.1234	.2090	.1203	.2038	.1072
.25	-.0205	.0009			.1491	.1179	.1674	.1181	.1870	.1199	.2099	.1202	.1905	.0925
.30	-.0275	-.0001							.1821	.1160	.2038	.1171	.1758	.0612
.40	-.0251	-.0029	-.0025	-.0108	.0222	-.0079	.0318	.0002	.0579	.0123	.1920	.1077	.1610	.0734
.50			-.0062	-.0165	.0118	-.0173	.0182	-.0142			.0616	.0381	.1409	.0615
.60					.0089	-.0203	.0564	-.0152	.0241	-.0153	.0291	-.0226	-.0319	-.0524
.70	-.0066	-.0200	-.0097	-.0177	.0044	-.0248	.0009	-.0349	-.0286	-.0509	-.0359	-.0564	-.0401	-.0579
.80	-.0357	-.0367	-.0436	-.0492			-.0404	-.0480	-.0341	-.0445	-.0442	-.0518	-.0440	-.0538
.90	-.0361	-.0446	-.0409	-.0460	-.0235	-.0363	-.0425	-.0457	-.0457	-.0486	-.0468	-.0500		
.95	-.0358	-.0479	-.0405	-.0455			-.0403	-.0454	-.0441	-.0485	-.0464	-.0495	-.0431	-.0467

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0355	.0734	.0705	.1044			.1694	.1984			.1628	.1563	.2010	.1937
.10	.0385	.0813					.1710	.1989	.1708	.2106			.1745	.1931
.15					.1573	.1729	.1677	.1928	.1659	.1987			.1546	.1859
.20	.0256	.0626					.1662	.1920	.1651	.1921			.1386	.1766
.25	-.0240	-.0011	.0026	.0673	.1572	.1700	.1656	.1890	.1645	.1895	.1571	.1799	.1395	.1642
.30			-.0250	-.0011			.1613	.1767	.1633	.1853	.1593	.1845	.1383	.1558
.40					.0077	.0183	.0162	.0250	.0420	.0521	.1496	.1655	.1305	.1941
.50							.0102	.0182	.0207	.0303	.0307	.0417	.1097	.1060
.60	-.0280	-.0131	-.0355	-.0220	-.0079	.0009	-.0229	-.0179	.0152	.0251	-.0036	.0038	-.0403	-.0382
.70					-.0514	-.0463	-.0534	-.0482	-.0391	-.0296	-.0489	-.0404	-.0445	-.0398
.80	-.0513	-.0504	-.0608	-.0577	-.0551	-.0536	-.0487	-.0494	-.0421	-.0424	-.0469	-.0471	-.0375	-.0365
.90	-.0571	-.0549	-.0596	-.0568	-.0510	-.0505	-.0462	-.0452	-.0423	-.0402	-.0373	-.0356	-.0413	-.0395
.95			-.0597	-.0567							-.0402	-.0389		

266

TABLE XXIV.- CONTINUED
(i) α = 11.80°

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05			.1215	.1550	.1392	.1602	.1570	.1687						
.10	.0095	.0908	.1130	.1558	.1473	.1620			.1797	.1718			.2028	.651
.15	.0083	.0956	.1007	.1519	.1457	.1552			.1741	.1650			.1930	.1582
.20	-.0002	.0937	.0881	.1472	.1418	.1564	.1726	.1275	.1712	.1612	.1909	.1588	.1856	.1417
.25	-.0320	.0106			.1353	.1526	.1512	.1540	.1696	.1574	.1907	.1595	.1733	.1271
.30	-.0387	.0118							.1644	.1532	.1842	.1560	.1594	.1155
.40	-.0357	.0145	-.0127	.0014	.0113	.0076	.0218	.0172	.0459	.0319	.1722	.1453	.1452	.1081
.50			-.0253	-.0041	-.0014	-.0015	.0079	.0020			.0507	.0269	.1250	.0929
.60					-.0083	-.0047	-.0343	-.0061	.0131	.0006	.0191	-.0067	.0361	.0453
.70	-.0132	-.0114	-.0258	-.0062	-.0152	-.0100	-.0107	-.0232	-.0354	-.0449	-.0415	-.0547	-.0431	-.0558
.80	-.0359	-.0303	-.0437	-.0461			-.0476	-.0524	-.0400	-.0488	-.0493	-.0564	-.0478	-.0572
.90	-.0396	-.0441	-.0421	-.0492	-.0264	-.0377	-.0447	-.0495	-.0481	-.0511	-.0493	-.0509		
.95	-.0390	-.0453	-.0424	-.0476			-.0433	-.0476	-.0460	-.0497	-.0462	-.0495	-.0441	-.0434

TAIL 2

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0278	.0651	.0171	.0408			.1588	.1773	.1710	.2087	.1638	.1576	.2040	.1967
.10	.0312	.0718					.1586	.1775	.1695	.1961			.1746	.1953
.15					.0900	.1135	.1549	.1756	.1683	.1916			.1541	.1887
.20	-.0170	.0521	-.0148	.0269	.0811	.1054	.1522	.1749	.1680	.1906	.1582	.1811	.1369	.1783
.25	-.0299	-.0080	-.0339	-.0138			.1513	.1731	.1677	.1876	.1614	.1842	.1387	.1647
.30							.1482	.1629			.1520	.1663	.1384	.1543
.40					-.0185	-.0110	.0010	.0113	.0441	.0512	.0017	.0044	.1316	.1413
.50	-.0347	-.0217	-.0413	-.0301	-.0348	-.0287	-.0078	.0007	.0220	-.0306	-.0320	-.0422	.1120	.1050
.60							-.0353	-.0302	.0153	-.0253	-.0485	-.0406	-.0401	-.0391
.70							-.0606	-.0557	-.0385	-.0303	-.0491	-.0477	-.0452	-.0407
.80	-.0552	-.0542	-.0648	-.0612	-.0600	-.0564	-.0602	-.0583	-.0484	-.0488	-.0383	-.0379	-.0382	-.0373
.90	-.0634	-.0615	-.0652	-.0635	-.0627	-.0614	-.0577	-.0576	-.0473	-.0470	-.0406	-.0406	-.0421	-.0403
.95			-.0652	-.0630	-.0597	-.0588								

TABLE XXIV.- CONTINUED
(1) α = 15.80°

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0142	.1498	.1266	.2363	.1391	.2429	.1556	.2565	.1738	.2657				
.10	.0089	.1578	.1155	.2382	.1175	.2491			.1676	.2580				
.15	-.0051	.1547	.1006	.2324	.1449	.2467	.1593	.1954	.1637	.2537	.1802	.2528		
.20	-.0368	.0393	.0852	.2260	.1269	.2431	.1441	.2435	.1615	.2499	.1789	.2548		
.25	-.0441	.0446			.1309	.2383			.1555	.2444	.1714	.2503		
.30	-.0437	.0659	-.0170	.0334	.0076	.0476	.0178	.0602	.0388	.0806	.1585	.2357		
.40			-.0309	.0295	-.0067	.0392	.0029	.0448	.0079	.0443	.0426	.0739		
.50					-.0113	.0355	.0242	.0148	-.0380	.0273	.0120	.0340		
.60	-.0243	.0144	-.0353	.0278	-.0216	.0293	-.0162	.0084	-.0416	.0449	-.0452	.0416		
.70	-.0392	-.0110	-.0438	-.0300	-.0291	-.0373	-.0494	-.0412	-.0458	-.0509	-.0483	-.0495		
.80	-.0379	-.0409	-.0441	-.0455			-.0452	-.0470	-.0443	-.0506	-.0421	-.0504		
.90	-.0376	-.0455	-.0445	-.0492			-.0442	-.0486			-.0404	-.0479		
.95														

TAIL 1

Cp at y/b of

x/c	0.02 U.S.	0.02 L.S.	0.22 U.S.	0.22 L.S.	0.44 U.S.	0.44 L.S.	0.56 U.S.	0.56 L.S.	0.67 U.S.	0.67 L.S.	0.83 U.S.	0.83 L.S.	0.98 U.S.	0.98 L.S.
.05	.0026	.0402	.0094	.0306			.0335	.0470			.1506	.1377	.2000	.1927
.10	.0080	.0440					.0281	.0456	.1358	.1738			.1735	.1893
.15					.0109	.0299	.0259	.0442	.0489	.0697			.1526	.1799
.20	-.0054	.0257	-.0280	.0075	.0000	.0180	.0197	.0394	.0368	.0571	.1376	.1439	.1368	.1702
.25	-.0415	-.0223	-.0435	-.0277			.0170	.0355	.0312	.0530	.1363	.1457	.1351	.1577
.30							.0136	.0277	.0278	.0474	.1241	.1310	.1337	.1496
.40							-.0392	-.0331	-.0286	-.0187	.0070	.0137	.1303	.1374
.50	-.0396	-.0274	-.0463	-.0364	-.0366	-.0300	-.0484	-.0436	-.0391	-.0321	-.0230	-.0188	.1123	.1017
.60					-.0491	-.0451	-.0578	-.0544	-.0414	-.0346	-.0575	-.0513	-.0355	-.0399
.70			-.0682	-.0648	-.0644	-.0614	-.0692	-.0662	-.0494	-.0423			-.0442	-.0406
.80	-.0571	-.0555	-.0685	-.0666	-.0657	-.0629	-.0668	-.0646	-.0603	-.0589	-.0609	-.0569		
.90	-.0672	-.0651	-.0686	-.0665	-.0639	-.0612	-.0659	-.0637	-.0612	-.0592	-.0540	-.0495	-.0452	-.0418
.95											-.0593	-.0565	-.0516	-.0478

TAIL 2

TABLE XXIV.- CONCLUDED

(h) α = 19.80°

TAIL 1

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	-.0259	.2274	.1445	.3432	.1522	.3520	.1692	.3708	.1864	.3874			.1977	.3800
.10	.0169	.2374	.1310	.3458	.1620	.3632			.1785	.3785	.1858	.3741	.1863	.3621
.15	-.0038	.2345	.1135	.3362	.1591	.3601	.1604	.2970	.1755	.3742	.1834	.377.	.1793	.3500
.20	-.0378	.0823	.0941	.3220	.1513	.3557	.1531	.3534	.1701	.3692	.1753	.3708	.1659	.3359
.25	-.0452	-.0928			.1421	.3505	.0214	.1200	.1633	.3616	.1613	.3520	.1524	.3231
.30	-.0458	.1350	-.0179	.0804	.0099	.1042	.0053	.1044	.0404	.1453	.0435	.1372	.1380	.3077
.40			-.0327	.0798	-.0058	.0959	.0209	.0529	.0085	.1049	.0125	.0914	.1189	.2742
.50					-.0138	.0892	-.0157	.0586	-.0384	-.0001	-.0455	-.0178	-.0369	-.0153
.60	-.0314	.0597	-.0374	.0758	-.0216	.0780	-.0466	-.0203	-.0382	-.0314	-.0412	-.0306	-.0441	-.0266
.70	-.0442	.0200	-.0463	-.0039									-.0432	-.0277
.80	-.0434	-.0266	-.0466	-.0301	-.0301	-.0290	-.0428	-.0310	-.0412	-.0373	-.0365	-.0347		
.90							-.0426	-.0341	-.0406	-.0393	-.0356	-.0366	-.0296	-.0281
.95	-.0454	-.0365	-.0469	-.0362										

TAIL 2

	Cp at y/b of												
	0.02		0.22		0.44		0.56		0.67		0.83		0.98	
x/c	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.	U.S.	L.S.
.05	-.0213	.0003	-.0076	.0092			-.0024	.0181	.0975	.1391	.0455	.0540	.0577	.0653
.10	-.0125	-.0096					-.0006	.0171	.0106	.0335			.0456	.0551
.15					-.0091	.0057	-.0025	.0162	.0013	.0227			.0333	.0480
.20	-.0224	-.0047	-.0352				-.0055	.0125	-.0011	.0199	.0216	.0408	.0212	.0401
.25	-.0495	-.0371	-.0482	-.0095	-.0183	-.0047	-.0067	.0099	-.0022	.0176	.0172	.0376	.0155	.0332
.30				-.0362			-.0087	.0090	-.0400	-.0293	.0099	.0281	.0098	.0289
.40							-.0453	-.0387	-.0457	-.0374	-.0322	-.0225	-.0051	.0225
.50			-.0487	-.0397	-.0408	-.0344	-.0534	-.0477	-.0460	-.0388	-.0459	-.0395	-.0051	-.0064
.60	-.0419	-.0310			-.0511	-.0462	-.0612	-.0568	-.0539	-.0463	-.0643	-.0581	-.0586	-.0524
.70			-.0695	-.0660	-.0646	-.0614	-.0706	-.0670			-.0661	-.0615	-.0557	-.0487
.80	-.0571	-.0556	-.0697	-.0672	-.0661	-.0638	-.0678	-.0658	-.0635	-.0605	-.0595	-.0543		
.90	-.0680	-.0656			-.0644	-.0618	-.0672	-.0648	-.0651	-.0616	-.0643	-.0603	-.0568	-.0518
.95			-.0698	-.0671			-.0672						-.0645	-.0594

269

Figure 1.- Details of model. All linear dimensions are in centimeters.

Tail planform A

Tail planform B

Tail planform C

+ pressure orifices

x/c	y/b						
0.05	0.02	0.22	0.44	0.56	0.67	0.83	0.98
.10	.02	.22	.44	.56	.67	.83	.98
.15	.02	.22	.44	.56	.67	.83	.98
.20	.02	.22	.44	.56	.67	.83	.98
.25	.02	.22	.44	.56	.67	.83	.98
.30	.02	.22	.44	.56	.67	.83	.98
.40	.02	.22	.44	.56	.67	.83	.98
.50	.02	.22	.44	.56	.67	.83	.98
.60	.02	.22	.44	.56	.67	.83	.98
.70	.02	.22	.44	.56	.67	.83	.98
.80	.02	.22	.44	.56	.67	.83	.98
.90	.02	.22	.44	.56	.67	.83	.98
.95	.02	.22	.44	.56	.67	.83	.98

Figure 2.- Details of pressure orifice locations.

(a) $\alpha = 0.66^{\circ}$.

Figure 3.- Pressure coefficients for tail planform B at $M = 1.60$, $\phi = 0^{\circ}$, and $\delta = 0^{\circ}$.

(b) $\alpha = 10.68^\circ$.

Figure 3.- Continued.

(c) α = 18.67°.

Figure 3.- Concluded.

(a) $\alpha = -0.08°$.

Figure 4.- Pressure coefficients for tail planform B at $M = 2.36$, $\phi = 0°$, and $\delta = 0°$.

(b) α = 9.92°.

Figure 4.- Continued.

(c) $\alpha = 19.92°$.

Figure 4.— Concluded.

(a) $\alpha = -0.15°$.

Figure 5.- Pressure coefficients for tail planform B at $M = 3.70$, $\phi = 0°$, and $\delta = 0°$.

278

(b) α = 9.85°.

Figure 5.- Continued.

(c) α = 19.95°.

Figure 5.- Concluded.

(a) $\alpha = 0.78°$.

Figure 6.— Pressure coefficients for tail planform B at $M = 1.60$, $\phi = 22.5°$, and $\delta = 0°$.

(b) α = 10.76°.

Figure 6.- Continued.

(c) α = 18.76°.

Figure 6.- Concluded.

(a) $\alpha = -0.07^{\circ}$.

Figure 7.- Pressure coefficients for tail planform B at $M = 2.36$, $\phi = 22.5^{\circ}$, and $\delta = 0^{\circ}$.

(b) $\alpha = 9.93°$.

Figure 7.- Continued.

(c) α = 19.92°.

Figure 7.- Concluded.

Figure 8.- Pressure coefficients for tail planform B at $M = 3.70$, $\phi = 22.5^\circ$, and $\delta = 0^\circ$.

(a) $\alpha = -0.20^\circ$.

(b) α = 9.80°.

Figure 8.- Continued.

288

(c) $\alpha = 19.80°$.

Figure 8.- Concluded.

(a) $\alpha = 0.74^\circ$.

Figure 9.- Pressure coefficients for tail platform B at $M = 1.60$, $\phi = 45^\circ$, and $\delta = 0^\circ$.

290

C-4

(b) α = 10.76°.

Figure 9.– Continued.

(c) α = 18.75°.

Figure 9.- Concluded.

(a) α = -0.04°.

Figure 10.- Pressure coefficients for tail planform B at M = 2.36, φ = 45°, and δ = 0°.

293

(b) α = 9.95°.

Figure 10.- Continued.

(c) α = 19.95°.

Figure 10.- Concluded.

(a) $\alpha = -0.30^{\circ}$.

Figure 11.- Pressure coefficients for tail planform B at $M = 3.70$, $\phi = 45^{\circ}$, and $\delta = 0^{\circ}$.

(b) $\alpha = 9.70^\circ$.

Figure 11.- Continued.

(c) $\alpha = 19.70°$.

Figure 11.- Concluded.

(a) $\alpha = 0.80^\circ$.

Figure 12.— Pressure coefficients for tail planform B at $M = 1.60$, $\phi = 67.5^\circ$, and $\delta = 0^\circ$.

299

(b) $\alpha = 10.75^{\circ}$.

Figure 12.- Continued.

(c) α = 18.76°.

Figure 12.- Concluded.

(a) α = -0.10°.

Figure 13.- Pressure coefficients for tail planform B at M = 2.36, ϕ = 67.5°, and δ = 0°.

(b) α = 9.90°.

Figure 13.– Continued.

303

(c) α = 19.90°.

Figure 13.- Concluded.

(a) $\alpha = -0.25^{\circ}$.

Figure 14.- Pressure coefficients for tail planform B at M = 3.70, $\Lambda = 67.5^{\circ}$, and $\delta = 0^{\circ}$.

(b) α = 9.75°.

Figure 14.- Continued.

(c) α = 19.75°.

Figure 14.- Concluded.

(a) $\alpha = 0.72^{\circ}$.

Figure 15.- Pressure coefficients for tail planform B at $M = 1.60$, $\phi = 90^{\circ}$, and $\delta = 0^{\circ}$.

(b) α = 10.71°.

Figure 15.- Continued.

(c) α = 18.00°.

Figure 15.– Concluded.

(a) $\alpha = -0.04^{o}$.

Figure 16.- Pressure coefficients for tail planform B at $M = 2.36$, $\phi = 90^{o}$, and $\delta = 0^{o}$.

311

(b) α = 9.95°.

Figure 16.- Continued.

(e) α = 19.90°.

Figure 16.- Concluded.

(a) $\alpha = -0.20^{\circ}$.

Figure 17.- Pressure coefficients for tail planform B at $M = 3.70$, $\phi = 90^{\circ}$, and $\delta = 0^{\circ}$.

(b) α = 9.80°.

Figure 17.- Continued.

315

(c) $\alpha = 19.80°$.

Figure 17.- Concluded.

316

(a) $\alpha = 0.68°$.

Figure 18.- Pressure coefficients for tail planform B at $M = 1.60$, $\phi = 0°$, and $\delta_{2,4} = -15°$.

317

(b) $\alpha = 10.75°$.

Figure 18.- Continued.

318

(c) α = 18.66°.

Figure 18.- Concluded.

(a) $\alpha = -0.08^\circ$.

Figure 19.- Pressure coefficients for tail planform B at $M = 2.36$, $\phi = 0^\circ$, and $\delta_{2,4} = -15^\circ$.

(b) α = 9.93°.

Figure 19.- Continued.

(c) α = 19.92°.

Figure 19.- Concluded.

322

(a) α = -0.15°.

Figure 20.- Pressure coefficients for tail planform B at M = 3.70, φ = 0°, and δ$_{2,4}$ = -15°.

(b) $\alpha = 9.85°$.

Figure 20.- Continued.

(c) $\alpha = 19.85°$.

Figure 20.- Concluded.

Figure 21.- Pressure coefficients for tail planform B at M = 1.60, φ = 45°, and δ = -15°.

(a) α = 0.75°.

(b) α = 10.75°.

Figure 21.- Continued.

(c) α = 18.76°.

Figure 21.- Concluded.

(a) $\alpha = -0.15°$.

Figure 22.- Pressure coefficients for tail planform B at $M = 2.36$, $\phi = 45°$, and $\delta = -15°$.

(b) α = 9.95°.

Figure 22.- Continued.

(c) α = 19.95°.

Figure 22.- Concluded.

331

Figure 23.- Pressure coefficients for tail planform B at M = 3.70, φ = 45°, and δ = -15°.

(a) α = -0.30°.

AFT
END
VIEW

(b) α = 9.71°.

Figure 23.- Continued.

(c) $\alpha = 19.70°$.

Figure 23.- Concluded.

334

(a) $\alpha = 0.10°$.

Figure 24.- Pressure coefficients for tail planform B at $M = 1.60$, $\phi = 90°$, and $\delta_{1,3} = -15°$.

(b) α = 10.69°.

Figure 24.– Continued.

(c) $\alpha = 18.70^\circ$.

Figure 24.- Concluded.

Figure 25.- Pressure coefficients for tail planform B at $M = 2.36$, $\phi = 90^\circ$, and $\delta_{1,3} = -15^\circ$.

(a) $\alpha = -0.05^\circ$.

(b) α = 9.95°.

Figure 25.- Continued.

339

(c) α = 19.95°.

Figure 25.- Concluded.

(a). $\alpha = -0.20^\circ$.

Figure 26.- Pressure coefficients for tail planform B at $M = 3.70$, $\phi = 90^\circ$, and $\delta_{1,3} = -15^\circ$.

(b) $\alpha = 9.80°$.

Figure 26.- Continued.

(c) α = 19.80°.

Figure 26.- Concluded.