

CHAPTER XX

DataComm in Flight Deck Surface Trajectory-Based Operations

*Deborah L. Bakowski¹, David C. Foyle², Becky L. Hooey¹, Glenn R. Meyer³,
Cynthia A. Wolter¹*

¹San Jose State University at NASA Ames Research Center

²NASA Ames Research Center

³Dell Services, Federal Government

Moffett Field, CA

debi.bakowski@nasa.gov

ABSTRACT

The purpose of this pilot-in-the-loop aircraft taxi simulation was to evaluate a NextGen concept for surface trajectory-based operations (STBO) in which air traffic control (ATC) issued taxi clearances with a required time of arrival (RTA) by Data Communications (DataComm). Flight deck avionics, driven by an error-nulling algorithm, displayed the speed needed to meet the RTA. To ensure robustness of the algorithm, the ability of 10 two-pilot crews to meet the RTA was tested in nine experimental trials representing a range of realistic conditions including a taxi route change, an RTA change, a departure clearance change, and a crossing traffic hold scenario. In some trials, these DataComm taxi clearances or clearance modifications were accompanied by ‘preview’ information, in which the airport map display showed a preview of the proposed route changes, including the necessary speed to meet the RTA. Overall, the results of this study show that with the aid of the RTA speed algorithm, pilots were able to meet their RTAs with very little time error in all of the robustness-testing scenarios. Results indicated that when taxi clearance changes were issued by DataComm only, pilots required longer notification distances than with voice communication. However, when the DataComm was accompanied by graphical preview, the notification distance required by pilots was equivalent to that for voice.

Keywords: NextGen, STBO, surface operations, taxi, displays, DataComm

1 SURFACE TRAJECTORY-BASED OPERATIONS

Surface operations are one aspect of the design of the next generation (NextGen; JPDO, 2009) of the National Airspace System. Research efforts in this phase of flight have focused on the development of surface traffic management (STM) systems for air traffic control (ATC) to provide taxi clearances enabling efficient airport operations and improved throughput. One such example of an STM system is the Spot and Runway Departure Advisor (SARDA), which estimates spot-to-runway taxi times based on the current average (Jung, 2010). Future STM systems will have associated aircraft arrival times (i.e., required time of arrival, RTA) at active runway thresholds so that aircraft can cross with minimal or no delay, and at the departure runway, enabling aircraft departure queue sequencing. Such future “full capability” STM systems will require aircraft to reach specified locations on the airport surface with relatively precise timing. For the flight deck, in order to achieve an RTA, pilots should be provided the aircraft speed required to reach the specified location at the specified time, since speed (actually, thrust) is what the pilots control with the throttles. These NextGen taxi operations with “taxi clearances and RTAs” are termed surface trajectory-based operations (STBO).

The use of Data Communications (DataComm) in surface operations has several potential benefits (e.g., reduced radio congestion, elimination of misunderstandings, see Wargo and D’Arcy, 2011). However, one concern is that DataComm may not be appropriate for use in time-critical situations. Specifically, it has been suggested that taxi route changes during taxi and time-critical events may require that ATC revert to voice communication (Jakobi, 2007; Wargo and D’Arcy, 2011).

1.1 Previous STBO Research

Several experiments have assessed speed-based taxi clearances and their effect on pilots’ ability to meet an RTA from an initial ramp spot to the departing runway (Foyle, Hooey, Bakowski, Williams, and Kunkle, 2011). Foyle et al. (2011, Expt. 2) explored pilots’ ability to meet an RTA using a commanded speed, with no additional flight deck equipment. Pilots were instructed to comply with the commanded speed on straight segments and accelerate/decelerate “aggressively”. The primary measure of pilot performance on the taxi task was RTA error, calculated by subtracting the RTA from the observed arrival time. Results revealed that requiring pilots to comply with a commanded speed, without additional flight deck equipment, produced unacceptably large RTA errors.

Foyle et al. (2011, Expt. 3) explored whether requiring pilots to follow specific acceleration/deceleration speed profiles and follow the speed command more precisely would decrease RTA error. By requiring pilots to taxi within +/- 1.5 kts of a commanded speed and with a specific speed profile, RTA error was quite accurate. However, these requirements required excessive visual attention to the head-down speed display. Fourteen out of eighteen pilots reported that the demand of maintaining the required speed conformance range in actual operations would compromise safety.

The results of these two studies demonstrated that: 1) Simply incorporating a commanded speed requirement into the taxi clearance alone was not sufficient for good RTA performance; and, 2) When pilots were given clearances that required them to control their aircraft according to precise acceleration/deceleration speed profiles in addition to a commanded speed, RTA conformance was quite good -- but, that added precision caused pilots to spend an unacceptable amount of time viewing/tracking the speed display. This suggests the need for a flight deck technology solution to aid pilots in safely meeting the speed/time requirements.

The technology solution investigated by Foyle et al. (2011, Expt. 4) was a speed indicator on the primary flight display (PFD) driven by an “error-nulling” algorithm. The speed algorithm dynamically compensated for speed-maintenance deviations by adjusting the current advised speed according to the remaining time and current distance to the RTA location. In addition to improved RTA error, pilots reported that the use of the algorithm/display did not compromise their out-the-window attention.

1.2 Present Study

The goals of the present study were three-fold:

1) Test an improved version of the error-nulling algorithm/display that more precisely calculated and presented the speed required to reach the departure runway at an RTA. Specifically, advised speed was computed based on remaining time, distance, number of turns, turn speed, and specific rate of acceleration/deceleration.

2) Evaluate that algorithm/display for robustness under multiple realistic conditions. The impact of the improved error-nulling algorithm on pilots’ ability to meet an RTA to the departing runway was tested under robust traffic and surface operation conditions, including taxi route changes, departure clearance changes, RTA changes, and a 2-min hold scenario.

3) Assess the use and integration of flight deck DataComm in STBO. The present study also explored DataComm integration with flight deck displays. This integration allowed DataComm information to be displayed graphically, which may improve situation awareness and extend the use of DataComm communication in time-critical situations.

2 METHOD

Twenty commercial pilots, with a mean age of 52 years (range of 36 – 63 years), participated in the study. Nine of the pilots were currently Captains and 11 were First Officers. The mean flight hours logged was 9,885 hours (range of 600 – 17,000 hours). Pilots were paired by company affiliation to form 10 two-person crews.

2.1 Flight Simulation

The study was conducted in the Airport and Terminal Area Simulator (ATAS), in the Human-Centered Systems Laboratory at the NASA Ames Research Center. The airport environment was the Dallas-Fort Worth International Airport (DFW) with high visibility and distant fog/haze conditions. The forward, out-the-window scene was depicted on four LCD displays, with a total viewing angle of 140 deg. The modified-B737NG cockpit included a Primary Flight Display (PFD), Navigation Display (ND), and Flight Management System (FMS) Control Display Unit (CDU) on both crew members' sides, and a shared Taxi Navigation Display (TND) and DataComm display with a touchscreen interface. Aircraft controls included a tiller on the Captain's side, toe brakes, throttles, and emergency brake. The physical and handling characteristics of the aircraft were modeled after a B757.

2.2 RTA Speed Algorithm

Each departure taxi clearance included a required time of arrival (RTA) at the queue area of the departure runway. To aid the pilots in arriving on time, the flight deck was equipped with an algorithm that computed the straightaway speed required to precisely meet the RTA. The RTA algorithm dynamically computed the advised speed by accounting for remaining distance, remaining time to RTA, number of turns, an assumed acceleration/deceleration rate of 1 kt/sec, and a turn speed of 10 kts (per standard operating procedures, SOPs). Taxi clearance RTAs were calculated such that the initial advised straightaway speed was 15 kts. The algorithm was dynamic and compensated for the pilot slowing down or speeding up by appropriately increasing or decreasing the advised straightaway speed.

2.3 STBO Experiment Displays

The PFD was modified for taxi operations by expanding (doubling) the speed scale from 0-60 kts. Advised straightaway speed, as calculated by the RTA algorithm, was displayed as a magenta analog pointer ("speed bug") on the speed tape and digitally in magenta directly above the speed tape (see Figure 1, panel 1). As shown in Figure 1 (panel 2), upon entering a turn, the magenta advised speed bug dropped to 10 kts (per taxi SOPs), while the white inner speed bug continued to dynamically indicate the straightaway speed required to meet the RTA. The PFD also included the current speed, shown as a sliding indicator with digital value inside (18 kts in Figure 1, panel 1), RTA time (Zulu) in magenta, and time remaining to the RTA (min:sec) in the white box.

A Taxi Navigation Display (TND) depicted the airport layout to aid the pilots in airport navigation. The ownship aircraft's position, shown as a white chevron, and other aircraft traffic within the ownship's 1,250 ft declutter circle, shown as yellow aircraft icons, were updated in real time (see Figure 1, panel 3). When the initial taxi clearance, sent via the DataComm, was accompanied by preview information, the TND populated with details of route: a graphical route on an overview map,

clearance text, RTA, time remaining to RTA (T Rem), route distance, and advised straightaway speed in cyan (see Figure 1, panel 3). Once accepted by the flight deck, clearance information was loaded into the PFD and the TND updated with the taxi clearance displayed as a magenta route, in perspective, track-up, and with text of the accepted clearance. When a mid-route taxi route change or RTA change was accompanied by preview information, the RTA, time remaining, distance remaining, and advised speed of the pending route were displayed in cyan. Turn graphics and route text were also displayed for taxi route changes. RTA location in the departure runway queue area was displayed as a white, dashed line across the ownship route on the TND, visible on the TND as the pilot neared it.



Figure 1 PFD: on straightaway (panel 1), and in turn (panel 2). TND: pending taxi route change with preview information in cyan (panel 3). DataComm: pending taxi route change (panel 4).

The DataComm touchscreen interface was located aft of the throttles between the two pilots. At the start of the trial, the flight deck received a DataComm with an expected taxi and departure clearance, followed by an initial taxi clearance. Taxi route changes (Figure 1, panel 4), RTA changes, and departure clearance changes were delivered via the DataComm during taxi. The DataComm followed a format similar to the European Airport Movement Management by Advanced Surface Movement Guidance and Control System, Part 2 project (EMMA2; Airbus, Thales, DSNA, 2009). When a clearance was delivered via DataComm, three touchscreen response buttons were available to the pilot to respond to ATC: Unable, Standby, and Wilco. The DataComm display included the message sent time in the upper left corner, an indicator of message status in the upper right hand corner (i.e., “OPEN” while ATC was awaiting a response from the flight deck, or “WILCO”, “STBY”, or “UNABLE” after a response was selected and sent to ATC), and status of the connection (i.e., “COMM OK” or “RECEIVED BY ATC” when ATC received the crew’s response). After the crew responded “WILCO” to a clearance, the DataComm text turned magenta, as an indication of acceptance.

2.4 Experimental Design

Each crew experienced nine experimental trials (see Table 1 in Results, Section 3). Taxi routes were constructed with 11,883 ft average distance and 8 min 2 sec average duration. The presentation of trials was randomly ordered and counterbalanced for each of the 10 crews. Each trial started at a 'ramp spot', had a unique route, and ended at the departure queue area.

Four taxi route change trials were included with pilots receiving notification either 500 ft or 2,000 ft before the required turn, and with either Preview or No Preview information on the TND. Route distance was held approximately constant (within 950 ft), and the RTA and runway remained the same in these four trials.

Two RTA change trials consisted of a revised RTA that was changed to approximately one minute earlier. These were given with either No Preview (57 sec earlier) or with Preview information (50 sec earlier) shown on the TND. In order to meet the amended RTA, an 18-kt straightaway speed was required in both trials.

Two departure clearance change trials required the First Officer to reprogram the FMS by selecting a different departure and transition. The change occurred either early (at 25% into the route), or late (at 75% into the route). These clearance changes were sent and responded to via the DataComm.

In the crossing traffic hold scenario, ATC gave instructions via voice to stop for two 777 aircraft -- the RTA and route remained in effect. The crew was delayed for 127 sec before being cleared by voice to continue taxi. Required straightaway speed increased to 21 kts during the 127 sec that passed while being held.

2.5 Procedure

Pilots were told that their primary goal in each trial was to minimize RTA error to the greatest extent possible so as to arrive at the departing queue area at the designated time. They were explicitly instructed to taxi as they would in a B757 aircraft, and never to taxi faster than would be safe in the real world. Pilots were informed that the advised straightaway speed was provided as an aid to help them reach the RTA point on time, but that it was not a requirement to constantly follow it. They were also told that the algorithm was dynamic, and that it assumed a 10-kt turn speed and 1 kt/sec acceleration/deceleration rate. Pilots were instructed to not "track" the advised speed indicator, but rather to use it as a strategic indicator.

Four initial taxi trials were presented to allow each crew to become familiar with the simulator, FMS, and experimental procedures. These trials also provided an opportunity for the pilots to experience the types of scenarios to be tested: a taxi route change, an RTA change, and a departure clearance change. Pilots were not provided with information about the crossing traffic hold scenario prior to its occurrence (or during familiarization trials).

Each trial began with an expected taxi clearance sent to the flight deck via DataComm. The clearance included the expected taxi route, departure runway, RTA, and departure clearance. Conceptually, pilots were told that an expected taxi clearance would be received at the gate, 30 min prior to pushback. In addition to

paper airport charts, the TND showed an overview map of DFW airport with the current ownship location. The expect-clearance DataComm allowed pilots to orient themselves to their initial location, taxi route, and departure runway. Crews were instructed to use this time to thoroughly review and discuss the taxi clearance and carefully plan their taxi route. The First Officer was responsible for managing the DataComm and programming the Flight Management System (FMS) for the initial departure clearance and departure clearance change while taxiing.

After completing taxi route planning and FMS entry at the gate, the simulation advanced to a ramp departure spot. Upon receiving the crew's 'ready to taxi' call, the experimenter initiated an ATC-sent DataComm with the initial taxi clearance to the flight deck. In three No-Preview trials (see Table 1), the initial taxi clearance was not accompanied by preview information on the TND. The six remaining trials included preview information on the TND. In particular, the preview of advised speed allowed pilots to quickly understand whether, given the route distance and number of turns, meeting the RTA would be reasonable. The graphical depiction of the taxi route on the overview map facilitated understanding of the clearance. In all trials, pilots were to review and accept or reject the initial taxi clearance with RTA as soon as possible after receiving it, because the time to the RTA was counting down. Time remaining ("T Rem" in cyan on the TND in Figure 1, panel 3), prior to acceptance of the clearance, was only visible to the crew in trials with Preview.

If the crew accepted the clearance, the First Officer responded by selecting "WILCO" on the DataComm, and the Captain released the emergency brake and began taxi. When the clearance was accepted, the RTA, time remaining, and advised speed were loaded into the aircraft avionics and displayed on the PFD (see Figure 1, panel 1), while the magenta route was displayed on the TND (panel 3).

During each of the nine experimental trials, the crew received a taxi route change, an RTA change, a departure clearance change, or a verbal instruction from ATC to stop for crossing traffic. When a taxi route change was accompanied by preview information (see Figure 1, panel 3), pilots were able to use the cyan graphical route depicted on the TND to note their position and locate the required turn. When an RTA change was accompanied by Preview, pilots were able to use the advised speed to determine whether it was reasonable/acceptable to meet the revised RTA.

In the event that the crew decided they could not comply with the initial taxi clearance or any of the three change clearances, pilots were to notify ATC by responding "UNABLE" via DataComm. If pilots decided they were unable to meet the RTA at any time during taxi, they were instructed to contact ATC via voice. When pilots reported they were unable to meet the RTA, by either DataComm or voice, ATC instructed them to "continue taxiing and minimize RTA delay."

Conceptually, pilots were told that they would receive their takeoff clearance after crossing the RTA location in the queue area. For this reason, they were responsible for completing any FMS programming changes prior to reaching the RTA location. Pilots were instructed to continue taxiing after crossing the RTA location; with the trial ending shortly after that point.

Following completion of the trials, pilots estimated the minimum required

notification distance using voice, DataComm text only, and DataComm with Preview for: a taxi route change, an RTA change, a runway change, and a departure clearance change. Pilots estimated these minimum notification distances on a post-study airport chart showing a taxi route with a distance scale.

3 RESULTS

The primary measure of pilot performance on the taxi task was RTA error, calculated by subtracting the RTA from the observed arrival time. (Negative RTA errors indicate early arrival; positive RTA errors indicate late arrival.) As shown in Table 1, RTA error is very good (near zero) across all conditions.

Table 1 Mean RTA Error in Seconds (S.E.)

Taxi Route Change (Same RTA)	Speed and Turn Graphics Preview	No Preview
500 ft turn notification	-0.43 (1.11) ¹	4.14 (1.81) ⁵
2,000 ft turn notification	-0.99 (1.19)	1.39 (1.02)*
RTA Change (15 kts to 18 kts)	Speed Preview	No Preview
57 sec earlier	--	3.71 (1.01) ¹
50 sec earlier	0.08 (0.29)	--
Departure Clearance Change (Early)	-2.30 (1.09)	
Departure Clearance Change (Late)	-1.57 (1.21)	
127-sec Crossing Traffic Hold (via voice)	4.96 (3.76) ²	

Notes: Superscript indicates number of crews (of 10) that responded "UNABLE"

* One crew stopped because they misunderstood the clearance, arriving 161.34 sec late. Only this one outlier was removed from the RTA error analysis.

DataComm responses other than "WILCO" are noted as superscripts in Table 1. Note that even though pilots responded "UNABLE" in some cases, they were still able to meet the RTAs with relatively small RTA error (with one exception noted).

Statistical tests did show some differences among means: With a Taxi Route Change (Table 1 top two rows), RTA error was greater with No Preview than with Preview, $F(1,9)=4.89$, $p=.05$; and, for RTA Change, RTA error was greater with No Preview than with Preview, $t(9)=3.44$, $p<.01$. There was no significant effect of location of departure clearance change (early or late in route) on RTA error.

It should be noted, however, that despite these significant findings, the important point is that these are all very small RTA errors, especially when put in the context that the taxi routes were, on average, more than 8 minutes in duration. (All RTA errors were also equivalent to zero, except for the No Preview 500-ft taxi route change, $t(9)=2.29$, $p<.05$, and the No Preview RTA Change, $t(9)=3.67$, $p<.01$.) The most notable "robustness finding" is that despite being held for crossing traffic for more than 2 minutes (specifically, 127-sec), RTA error was under 5 seconds, and was statistically equal to (i.e., not different from) zero, $t(9)=1.32$, $p>.05$.

As in Foyle et al. (2011), to assess visual attention to the error-nulling speed

display, pilots (only the last $n=12$ pilots tested) were asked, using a 5-point scale, where 1=Rarely, 2=Seldom, 3=Sometimes, 4=Frequently, and 5=Most of the Time, “During this trial, how often did you find yourself focusing on the speed and/or time displays when you should have been paying attention to the external taxiway environment?” Results ($M=2.13$, $SD=0.62$) indicated that pilots responded that the error-nulling algorithm/display did not negatively impact their visual attention to the out-the-window airport view, as was found in Foyle et al. (2011, Expt. 3).

3.1 DataComm Notification Distance

On a post-study questionnaire, pilots estimated the minimum distance that they were willing to accept a taxi route change, an RTA that was 1 min earlier, a change to a parallel runway, and a departure clearance change. Pilots provided distances for three communication types: DataComm with Preview information, DataComm text only (No Preview), and voice only. Participants indicated their responses on a taxiway map overlaid with a distance scale. Mean (and S.E.) minimum notification distances (ft) are shown in Table 2.

Table 2 Mean Minimum Notification Distance in Feet (S.E.)

Minimum Notification Distance (ft) Required before Taxi Route Change			
Type of Change	DataComm with Preview	DataComm No Preview	Voice Only
Taxi Route Change	895 (178)	1,378 (119)	928 (149)
Minimum Notification Distance (ft) Required before Runway Takeoff Clearance			
Type of Change	DataComm with Preview	DataComm No Preview	Voice Only
RTA Change (1 min earlier)	4,856 (489)	5,825 (488)	5,675 (536)
Change to Parallel Runway	2,763 (395)	3,025 (386)	2,785 (417)
Type of Change	DataComm (No Preview)	Current Day Voice Environment	
Departure Clearance Change	2,600 (307)	2,986 (387)	

For a 1-min RTA change, pilots required a shorter notification distance for DataComm with Preview, $F(2,38)=8.14$, $p<.01$. For a taxi route change, pilots required a longer notification distance for DataComm No Preview, $F(2,38)=11.22$, $p<.01$. That is, pilots indicated that DataComm with Preview (i.e., preview of advised speed or route change graphic) could be used in place of voice in these scenarios. There was no significant effect of communication type on minimum distance notification to a parallel runway change or a departure clearance change.

4 DISCUSSION

The present study tested a version of an error-nulling algorithm that more precisely calculated advised speed by accounting for remaining time, distance,

number of turns, turn speed, and acceleration/deceleration rate. The improved RTA algorithm was tested under robust traffic and surface operation conditions, including taxi route changes, departure clearance changes, RTA changes, and a 2-min traffic hold scenario. RTA error in the present study was near zero across all trials, indicating that pilots were able to meet the RTA with very little time error, and that meeting this RTA did not interfere with visual attention out-the-window.

Typically, it has been noted (e.g., Jakobi, 2007; Wargo and D'Arcy, 2011) that DataComm may not be appropriate for time-critical situations. In this study, pilots reported that for taxi route modifications with a graphical preview of the required turn and for RTA changes with a preview of the advised speed, DataComm requires the same, or less, notification distance as voice communication. This potentially important finding suggested by these results is that DataComm *with graphical preview information* may be usable in more situations than previously considered (presumably, of course, when non-compliance would not result in an unsafe condition). Clearly, more research is needed, but these results suggest that with DataComm information integrated and displayed on a flight deck display, reverting to voice communication may not be required for some time-critical communications as was previously considered.

ACKNOWLEDGMENTS

NASA Airspace Systems/NextGen Concepts and Technology Development/Safe and Efficient Surface Operations funded this work. The authors thank Rob Koteskey and Christina Kunkle of San Jose State University for their help with this study.

REFERENCES

- Airbus, Thales Air Systems, DSN. 2009. "EMMA2 CPDLC Trials in Toulouse." Accessed February 21, 2012, http://www.dlr.de/emma2/meetdoc/DemoDayMalpensa/9_Demo_Day-CPDLC_Toulouse-Public.pdf
- Foyle, D. C., B. L. Hooley, D. L. Bakowski, J. L. Williams, and C. L. Kunkle. 2011. "Flight deck surface trajectory-based operations (STBO): Simulation results and ConOps implications." Ninth USA/Europe Air Traffic Management Research and Development Seminar (Paper 132), EUROCONTROL/FAA. Berlin, Germany.
- Jakobi, J. "Operational Concept for TAXI-CPDLC." Third AP21 Workshop, NASA Ames, October 31, 2007. Accessed February 21, 2012, http://www.dlr.de/a-smgcs/AP21/2007/10_Jakobi/TAXI-CPDLC_Jakobi_006.ppt
- Joint Planning and Development Office. 2009. Concept of Operations for the Next Generation Air Transport System, v3.0. Accessed February 21, 2012, www.jpdo.gov/library/NextGen_ConOps_v3%200.pdf
- Jung, Y. C., T. Hoang, J. Montoya, G. Gupta, W. Malik, and L. Tobias. 2010. "A concept and implementation of optimized operations of airport surface traffic," 10th AIAA Aviation Technology, Integration, and Operations (ATIO) Conference, Ft. Worth, TX.
- Wargo, C. A. and J. F. D'Arcy. 2011. "Performance of Data Link Communications in Surface Management Operations." Aerospace Conference 2011 IEEE, pp 1- 10.