Hypervelocity Impact (HVI)

Volume 4: WLE Small-Scale Fiberglass Panel Flat Target C-2

Michael R. Gorman and Steven M. Ziola
Digital Wave Corporation, Englewood, Colorado

September 2007

Since its founding, NASA has been dedicated to the advancement of aeronautics and space science. The NASA Scientific and Technical Information (STI) Program Office plays a key part in helping NASA maintain this important role.

The NASA STI Program Office is operated by Langley Research Center, the lead center for NASA's scientific and technical information. The NASA STI Program Office provides access to the NASA STI Database, the largest collection of aeronautical and space science STI in the world. The Program Office is also NASA's institutional mechanism for disseminating the results of its research and development activities. These results are published by NASA in the NASA STI Report Series, which includes the following report types:

- TECHNICAL PUBLICATION. Reports of completed research or a major significant phase of research that present the results of NASA programs and include extensive data or theoretical analysis. Includes compilations of significant scientific and technical data and information deemed to be of continuing reference value. NASA counterpart of peer-reviewed formal professional papers, but having less stringent limitations on manuscript length and extent of graphic presentations.

- TECHNICAL MEMORANDUM. Scientific and technical findings that are preliminary or of specialized interest, e.g., quick release reports, working papers, and bibliographies that contain minimal annotation. Does not contain extensive analysis.

- CONTRACTOR REPORT. Scientific and technical findings by NASA-sponsored contractors and grantees.

- CONFERENCE PUBLICATION. Collected papers from scientific and technical conferences, symposia, seminars, or other meetings sponsored or co-sponsored by NASA.

- SPECIAL PUBLICATION. Scientific, technical, or historical information from NASA programs, projects, and missions, often concerned with subjects having substantial public interest.

- TECHNICAL TRANSLATION. English-language translations of foreign scientific and technical material pertinent to NASA's mission.

Specialized services that complement the STI Program Office's diverse offerings include creating custom thesauri, building customized databases, organizing and publishing research results ... even providing videos.

For more information about the NASA STI Program Office, see the following:

- Access the NASA STI Program Home Page at *http://www.sti.nasa.gov*

- E-mail your question via the Internet to help@sti.nasa.gov

- Fax your question to the NASA STI Help Desk at (301) 621-0134

- Phone the NASA STI Help Desk at (301) 621-0390

- Write to:
  NASA STI Help Desk
  NASA Center for AeroSpace Information
  7115 Standard Drive
  Hanover, MD 21076-1320

NASA/CR-2007-214885/VOL4

Hypervelocity Impact (HVI)

Volume 4: WLE Small-Scale Fiberglass Panel Flat Target C-2

Michael R. Gorman and Steven M. Ziola
Digital Wave Corporation, Englewood, Colorado

September 2007

Hypervelocity Impact (HVI)

Volume 4: WLE Small-Scale Fiberglass Panel Flat Target C-2

During 2003 and 2004, the Johnson Space Center's White Sands Testing Facility in Las Cruces, New Mexico conducted hypervelocity impact tests on the space shuttle wing leading edge.

Hypervelocity impact tests were conducted to determine if Micro-Meteoroid/Orbital Debris impacts could be reliably detected and located using simple passive ultrasonic methods.

The objective of Target C-2 was to study impacts through the reinforced carbon-carbon (RCC) panels of the Wing Leading Edge. Fiberglass was used in place of RCC in the initial tests.

Impact damage was detected using lightweight, low power instrumentation capable of being used in flight.

Table of Contents

List of Figures

List of Tables

Hypervelocity Impact (HVI)
Volume 4: WLE Small-Scale Fiberglass Panel Flat Target C-2

Introduction

In the wake of the Columbia accident, NASA personnel decided to test the idea that impacts during space flight could be detected by acoustical sensors at ultrasonic frequencies. The substance of this idea rested on the knowledge that in laboratory experiments lower velocity impacts had created signals with frequencies in the 20 – 200 kHz range. If Shuttle engine and aerodynamic noise were down in the sonic range then locating impacts would be easier in the 20-200 kHz range. The questions were what frequencies would be created during hypervelocity impacts by tiny objects, what would their energies be, and what would be the best way to detect them, keeping in mind the potential need for lightweight, simple installation procedures and low electrical energy consumption.

A further basis for selecting this method was that recent fundamental research had elucidated the basic physics of the ultrasonic signals created by the impacts in a variety of aerospace materials and geometries. This made it more likely that signal and noise could be separated and that subsequent analysis of the signals would yield the desired information about impact severity and location. All of the above reasoning proved to be correct. Hypervelocity impact by tiny aluminum spheres created signals in the 20-200 kHz frequency range easily detectable with small piezoelectric sensors similar to equipment being flown.

Target C-2 was one of several targets (see below) used for hypervelocity impact testing. There is a section in this Report for each of the other targets. The structure of this report includes a General Introduction that contains the overall goals, the personnel involved, the test methods, instrumentation, calibration, and overall results and conclusions. Only abbreviated descriptions of the test methods, instrumentation, and calibration are given in each of the target sections such as this one.

This section describes Target C-2, the test equipment, features tables of kinetic energy and damage results, and discusses the linear relationship found between kinetic energy, ultrasonic wave signal energy and damage. Also discussed are wave propagation effects, the wave modes and their velocities, and location of impacts by analysis of wave arrival times.

The Appendix has a test condition data sheet and the impact waveform for each shot. No damage photos were available for Target C-2. Also included are tables of impact kinetic energy, gain settings and energies for individual channels, and damage size results.

The number of targets tested in the overall HVI study was extensive as shown in the list below:
- – A-1 – Fiberglass plate and aluminum plate with standoff rods (with grommets)

- A-2 – Fiberglass plate and aluminum plate with standoff rods (no grommets)
- B-1 –Two fiberglass plates and aluminum plate with standoff rods
- C-1 – Fiberglass flat plate
- C-2 – Fiberglass flat plate
- Fg(RCC)-1 – Fiberglass in the shape of Wing Leading Edge
- Fg(RCC)-2 – Fiberglass in the shape of Wing Leading Edge
- RCC16R – Carbon-Carbon Actual WLE
- A-1 Tile – Tile structure of forward part of wing with no gap filler
- Ag-1 Tile – Tile structure of forward part of wing with gap filler
- B-1 Tile – Tile structure of aft part of wing with no gap filler
- Bg-1 Tile – Tile structure of aft part of wing with gap filler

It is everyday experience that when a solid material is struck, sound is created. This new passive ultrasonic technique has been designated modal acoustic emission (MAE) due to its (physical) similarity to an older, but less robust technique known as acoustic emission. In structures built of plate-like sections (aircraft wings, fuselages, etc.) the sound waves of interest are the extensional mode (in-plane stretching and compressing of the plate) and the flexural mode (bending of the plate). These are called plate waves and they propagate in bounded media where the wavelength of the wave is larger than the thickness of the plate. The frequency spectrum typically ranges from the low kilohertz to about one megahertz. Plate waves can be detected with simple piezoelectric transducers that convert mechanical motion into electrical voltage.

By analyzing mode shapes, and taking into account the material and loading, sources can be identified and located. The direct connection to fundamental physics is a key characteristic of MAE. For simple geometries the wave shapes and velocities have been calculated from wave equations derived from Newton's laws of motion and they compare well with measurements. (See General Introduction to this report for a fuller discussion of modal AE.) By using arrival times at transducers with known positions, the location of the source can be triangulated by various mathematical methods (similar to methods used in SONAR).

Experimental Description

Target C-2 consisted of a 34" x 34" 20-ply fiberglass panel (Figure 1). L-shaped angles added to the back of the fiberglass panel were used to attach the target to a target support stand. Physically, Target C-2 was identical to Target C-1.

Figure 1: Fiberglass Panel Target C-2. Front View.

There were a total of 23 shots fired. The impact angle of the shots was 90 degrees from the surface of the target for shots #8-17e and 45 degrees for shots #1-7 and #18-20 (Figure 2 and Figure 3).

Figure 2: Fiberglass Panel Target C-2 with 90 deg Impact Angle. Back Side View.

Figure 3: Fiberglass Panel Target C-2 with 45 deg Impact Angle. Back side View.

The tests were conducted on the 0.50 caliber hypervelocity launcher range at the White Sands Test Facility (WSTF). The flight range for the hypervelocity projectile and target chamber were evacuated to near vacuum pressure (6-8 Torr) prior to each shot. The AE recording equipment was connected by feed-throughs to the sensors on the target inside the vacuum chamber. The connectors were BNC type.

The projectiles were small spheres made of 2017 T-4 aluminum. They ranged in diameter from 0.4 mm to 2.4 mm. Impact velocity was measured with WSTF diagnostic equipment on each shot. The projectile kinetic energy for these shots ranged from 1.37 J to 711.19 J.

Six acoustic (ultrasonic) emission sensors were coupled to the back surface of the target with Lord 202 epoxy (Figure 4). A diagram of the sensor layout is shown in Figure 5.

Figure 4: C-1 Detail of Sensor 2
No photo was available for sensors on C-2.

Figure 5: C-2 Diagram of Sensor and Impact Locations. Front View.
Acoustic emission sensors are highlighted in yellow with the following coordinates:
#1 (8, 26), #2 (15, 26), #3 (22, 26), #4 (29, 26), #5 (30, 19), #6 (4, 19).
Dimensions are inches.
Impact locations are highlighted in magenta with the following coordinates:
#1 (8, 10), #2 (10, 10), #3 (14, 10), #4 (17, 10), #5 (21, 10), #6 (26, 10), #7 (8, 14),
#8 (12, 12), #9 (12, 14), #10 (14.5, 14), #11 (20, 14), #12 (12, 17), #13 (17.5, 17.5),
#14 (14.5, 19), #15 (21, 20.5), #16 (18, 22), #17 (16, 2), #18 (14, 22), #19 (12, 22),
#20 (8,22)

The piezoelectric sensors converted the sound wave energy to electrical voltages. The energy computed from the voltage data collected by each sensor channel is referred to as the wave signal energy. (A complete description of the type of sensor used and calibration is given in the General Introduction to this report.)

The wave signal energy for each channel was analyzed and compared to the impact energy. A full description of the wave recording instrumentation is given in the General Introduction to this Report. (Each individual sensor was connected to a separate

9

amplification and filtering channel and the voltage produced by the sensor recorded and stored on a computer.)

The wave signal energy was computed by integrating the squared voltage with respect to time and dividing this number by the impedance at the preamp input. The voltage versus time values of the wave, which were displayed in the waveform window on the computer screen for each channel, were not corrected for any applied gain (or attenuation).

Attenuation was the norm because hypervelocity impact produced very energetic signals that in most cases would have saturated the A/D converter on the recording card in the computer had the amplitude not been reduced.

Some recorder channels were found to have a slight DC offset (Figure 6). This added significantly to the wave energy when the integral of squared voltage versus time signal was computed. To eliminate the offset, the average wave signal voltage for the impact event was subtracted from each data point. This resulted in a zeroed raw wave signal (no DC offset. Correcting the offset was more important for small signals than large signals.

Figure 6: Example of DC Offset

The top signal is centered at -0.002 V whereas the bottom signal is centered at -0.001V.

A typical impact signal is shown in Figure 7. The impact signal had a distinct waveform and varied in both in arrival time and amplitude on each channel. The distinct modal characteristics can be seen in a time expanded view in Figure 8. The E mode arrived first with its lowest frequency in front followed by progressively higher frequencies. This was followed by the flexural (F) wave. The F wave characteristics were harder to discern because of the filtering of the attenuators. In some cases, the F wave characteristics are much more visible (See Figure 18 to compare with a pencil lead break. A pencil lead

break created a much larger F mode than E mode.) The vastly different velocities of the modes were used to confirm the modes.

The sound waves produced by impact are shown complete in the Appendix. It can be seen that the impact waves have the plate mode characteristics, i.e., the extensional wave arrives first, with its low frequency components out front followed by higher frequency components, and the F wave with just the opposite frequency arrangement. This differs, for example, from noise caused by electromagnetic interference (EMI). In contrast, EMI noise typically looks the same on every channel and arrives simultaneously (Figure 9). EMI exhibits no plate wave propagation characteristics.

Figure 7: C-2 Impact Signal for Shot #3

Figure 8: Detail of C-2 Impact Signal for Shot #3, Sensors 1 and 2

Figure 9: C-2 Electromagnetic Interference for Shot #3

The MAE software computed the raw wave signal energy in Joules uncorrected for any analog gain or attenuation that may have been applied to the signal path. In order to compare the wave energies from shot to shot, the raw wave signal energy was converted

by applying Equation 1 where E_{raw} is the energy computed using the recorded wave (with DC offset eliminated) and G is the system gain.

$$W.S.E. = \frac{E_{raw}}{G^2}$$

Equation 1

The gain G was computed by converting the logarithmic gain, M, in decibels with Equation 2 or Equation 3.

$$M\ dB = 20\ Log_{10}\ (G)$$

Equation 2

$$G = 10^{\frac{M}{20}}$$

Equation 3

The gains, raw wave signals, and wave energies for each shot are listed in the data tables in the Appendix to this section.

High velocity impact produced signals on the order of a few volts directly out of the transducer. These were much larger signals than typically found in most acoustic emission measurements of, say, crack growth in metals. For most shots, attenuators were placed in the signal lines between the sensors and the digital recorders. Greater attenuation was applied for the higher energy shots which made the raw energy appear to be much less. The energy was restored to its full value by compensating in the analysis for the greater attenuation, Equation 3 above.

Results

The most important quantities used in the analysis of the wave signals were the wave signal energy and projectile kinetic energy for each shot. These are given in Table 1 along with the test number, impactor diameter, and angle of impact. Wave signal energy is the sum of the energy, in nano-Joules, detected by all of the sensors. Kinetic energy is calculated based on the velocity and mass of projectile (density of aluminum = 2700 kg/m^3) according to the usual formula K.E. = mv^2/2.

For design engineering and threat analysis purposes, shots were performed at various angles to the normal to the target at the point of impact. It was suggested by Summers (NASA TN D-94, 1959) that only the normal kinetic energy be used to compare with crater depth. The kinetic energy for the normal velocity component was computed (sine squared of the angle, ninety degrees is normal). Normal KE is just the kinetic energy associated with the projectile velocity component normal to the target surface at the point of impact. In this study, the normal kinetic energy compared with penetration depth better than the total kinetic energy (Figure 10 and Figure 11). Shots #6a, 7, 13, 6, 20, 11, and 15 created holes rather than craters. It was assumed that the crater depth for holes was the thickness of the target, 4.83 mm.

Figure 10: Penetration Depth vs. Normal Kinetic Energy

Figure 11: Penetration Depth vs. Total Kinetic Energy

As can be seen in Figure 12 and Figure 13, the normal kinetic energy correlated better than total kinetic energy with damage area.

Figure 12: C-2 Total Kinetic Energy vs. Fiber Damage Area

Figure 13: C-2 Normal Kinetic Energy vs. Fiber Damage Area

In Figure 14 and Figure 15, the total kinetic energy correlates with crater volume damage better than the normal kinetic energy.

Figure 14: C-2 Total Kinetic Energy vs. Crater Volume Damage

Figure 15: C-2 Normal Kinetic Energy vs. Crater Volume Damage

Wave signal energy correlates with normal kinetic energy better than with total kinetic energy as can be seen in Figure 16 and Figure 17.

Figure 16: C-2 Wave Signal Energy vs. Total Kinetic Energy

Figure 17: C-2 Wave Signal Energy vs. Normal Kinetic Energy

Test No.	Imp Dia mm	Imp Ang deg	Normal K.E. J (±5%)	Total K.E. J (±5%)	W.S.E. nJ
C2-1	0.6	45	3.37	6.75	6.268E+01
C2-2b	0.6	45	0.95	1.89	1.079E+01
C2-3	1.6	45	69.47	139.05	1.330E+04
C2-4	1.8	45	45.11	90.29	2.120E+04
C2-5	2.0	45	24.92	49.88	2.706E+03
C2-6	2.4	45	233.10	466.58	2.419E+04
C2-6a	1.8	45	95.79	191.74	1.224E+04
C2-7	2.0	45	131.41	263.02	2.100E+04
C2-8	0.6	90	7.19	7.19	1.210E+02
C2-9	0.6	90	1.37	1.37	1.473E+01
C2-9a	0.6	90	1.40	1.40	4.743E+02
C2-10	1.4	90	91.28	91.28	1.439E+04
C2-11	2.4	90	454.50	454.50	1.698E+04
C2-12	1.6	90	133.88	133.88	2.360E+04
C2-12a	1.6	90	135.85	135.85	1.780E+04
C2-13	1.8	90	192.31	192.31	3.189E+04
C2-14	2.0	90	42.76	42.76	2.107E+04
C2-15	2.8	90	709.09	709.09	4.814E+04
C2-16	1.0	90	33.75	33.75	8.712E+03
C2-17e	0.6	90	7.61	7.61	6.765E+02
C2-18	0.6	45	3.65	7.31	4.408E+02
C2-19	1.0	45	16.38	32.78	5.067E+03
C2-20	2.8	45	355.31	711.19	4.996E+04

Table 1: C-2 Kinetic Energy and Wave Signal Energy

The damage for each shot is given in Table 2. The crater volume damage is the product of the recorded length, width, and depth measurements on the front side of the panel for each impact. Damage area is the product of recorded length and width measurements of the fiber damage on the front side of the panel.

Test No.	Normal K.E.	Total K.E.	Damage Area	Crater Volume
	J (±5%)	J (±5%)	mm^2	mm^3
C2-1	3.37	6.75	27.0	1.2
C2-2b	0.95	1.89	12.0	0.6
C2-3	69.47	139.05	192.0	126.8
C2-4	45.11	90.29	143.0	47.2
C2-5	24.92	49.88	143.0	33.8
C2-6	233.10	466.58	342.0	347.5*
C2-6a	95.79	191.74	256.0	57.9*
C2-7	131.41	263.02	252.0	188.2*
C2-8	7.19	7.19		1.3
C2-9	1.37	1.37	4.0	0.1
C2-9a	1.40	1.40	11.0	0.04
C2-10	91.28	91.28	126.0	57.6
C2-11	454.50	454.50	588.0	328.2*
C2-12	133.88	133.88	224.0	
C2-12a	135.85	135.85	210.0	
C2-13	192.31	192.31	323.8	146.0*
C2-14	42.76	42.76	97.5	25.8
C2-15	709.09	709.09	892.5	434.3*
C2-16	33.75	33.75	65.0	25.2
C2-17e	7.61	7.61	20.0	1.3
C2-18	3.65	7.31	20.6	1.4
C2-19	16.38	32.78	73.5	6.3
C2-20	355.31	711.19	506.0	506.7*

Table 2: C-2 Damage Results
* = Hole. No damage area was recorded for shot #8. No crater depth was recorded for shots #12 and 12a.

Discussion

Sound waves containing both sonic and ultrasonic frequencies were created by each impact.   The energy in the waves is some fraction of the energy of the impactor. An analysis method was sought that would allow a straightforward and simple technique for comparing the wave energies to the projectile kinetic energy, and thus the damage figures.   One way would be to look at the energy sensor by sensor. For example, the wave energy for shot #1 could be computed from just the signal at sensor 1, then the energy from shot #2 could be computed from the signal at sensor 1, and so forth, and then the energies could be graphed.

The problem with this method would be that the impact position changed from shot to shot.   The method might work if new identical targets were available each time and the sensor 1 position and shot location were always the same. Given this was not feasible, perhaps correction factors could be developed, but it would be arduous, if not impossible, to compare shot energies by correcting for the all the source to receiver relative positional changes because there are so many effects for which to account. Geometric spreading in 3-D means that the intensity varies as $1/r^2$. In plates the spreading is circular and the

intensity only drops as 1/r. Calculating the 1/r attenuation caused by geometric spreading would account for just one effect. There is also attenuation due to material properties which is a function of both frequency and direction. Waves that cut across the main fiber directions were attenuated more than waves that propagated along the fiber directions. This is known as material anisotropy.

In order to reduce the effect of varying impact positions on the acoustical energy values, the energies of the waves at all the transducers on the target were summed together for each shot.   This was approach was based on the following reasoning: If a given sensor records the signals for two impacts that have the same kinetic energy, the closer impact would appear to have a larger wave signal energy. Since the sensors surrounded the impacts, variations in the propagation paths would be roughly accounted for by adding the wave signal energy collected by all sensors.   This approach also makes use of symmetry: Two symmetric impacts would have symmetric propagation paths and thus the same total wave signal energy if the energies collected by all the sensors were summed. The graphs show that this turned out to be an efficacious approach. Symmetry could not be invoked in every case so there were outliers.

The damage measurements themselves were crude.   Although some damage in the interior plies seemed apparent, the "damage area" value that was plotted against KE was related solely to the area the damaged fibers occupied as measured with a ruler on the outside (the impact side) surface.

Overall, the correlations exhibited the correct trend of greater impact energy resulting in larger wave energy.

Location Analysis

Location of the source of a wave is part and parcel of the MAE technique just as it is in SONAR methods.   It contributes to understanding of the type and magnitude of the source and is a crucial step in tracking down and stopping leaks in manned spacecraft.

In these studies the location of the impact was known by visual observation.   This enabled a study of the accuracy of locating a source purely by analysis of the wave arrival at different transducers. The source position was triangulated when the source to receiver path was reasonably homogeneous. This was shown in detail for Target Fg(RCC)-1 and the reader is referred to that Section of this Report. The analysis was not repeated here.

The velocities of the direct arrivals were measured in advance. Pencil lead breaks were done to create the modes. This is discussed under Wave Propagation below.

Wave Propagation

The wave signal energy collected by any given sensor is composed of direct energy and reflected energy. After an impact occurs, a wave propagates radially outward from the impact site. This direct wave is the first signal recorded by a sensor. When this wave

reaches the edges of the target, it is reflected back to the sensor. These reflected waves are lower in amplitude than the direct waves and have later arrival times. In general, reflected waves did not contribute not a significant fraction of the signal energy.

The direct wave is composed of two types of waves: extensional and flexural. Extensional waves have two displacements components with the larger displacements perpendicular to the normal to the plate. A sensor on the surface detects the out-of-plane component of the E wave. The largest displacement of the flexural wave motion is perpendicular to the plane of the plate. This motion is caused by bending at the impact location. The E and F modes have very distinct characteristics (see General Introduction and also Figure 18) that can be readily identified. For one thing, the front part of the E wave travels much faster than any frequency component of the F wave.

Wave speed was determined by performing a lead break at one sensor and measuring the time it took for a direct wave to arrive at another sensor at a known distance away. Figure 18 shows a lead break signal at sensor 3. The extensional wave arrived at sensor 3 at $t_1 = 197.0$ μs and at sensor 2 at $t_2 = 239.2.4$ μs. The sensors were located 7 inches apart which gave a velocity of 0.16 in/μs in the x-direction. Performing this calculation in the y-direction and the diagonal gave extensional wave velocities of 0.16 in/μs and 0.14 in/μs, respectively. Figure 19 is a diagram of the sensor layout. The flexural speeds in the x-direction, y-direction and diagonal were 0.06 in/μs, 0.07 in/μs, and 0.07 in/μs.

Low frequency (< 50 kHz) noise did not affect signal arrival time. Examples of filtered and unfiltered waveforms are given in the Discussion section of RCC16R and in the General Introduction.

Figure 18: C-2 Lead Break at Sensor 3 for Shot #2 Pretest

Figure 19: C-2 Diagram of Sensor and Impact Locations. Front View. (Repeat of Figure 5)
Acoustic emission sensors are highlighted in yellow with the following coordinates:
#1 (8, 26), #2 (15, 26), #3 (22, 26), #4 (29, 26), #5 (30, 19), #6 (4, 19).
Impact locations are highlighted in magenta with the following coordinates:
#1 (8, 10), #2 (10, 10), #3 (14, 10), #4 (17, 10), #5 (21, 10), #6 (26, 10), #7 (8, 14),
#8 (12, 12), #9 (12, 14), #10 (14.5, 14), #11 (20, 14), #12 (12, 17), #13 (17.5, 17.5),
#14 (14.5, 19), #15 (21, 20.5), #16 (18, 22), #17 (16, 2), #18 (14, 22), #19 (12, 22),
#20 (8,22)

In the fiberglass panel, fibers are aligned in the x and y directions (see Figure 19). In addition to having slower speeds, waves that travel diagonally are attenuated more than waves that travel along the fiber direction. This is generally known as material anisotropy and is referred to here as the diagonal attenuation effect.

The data can be corrected for the effect of diagonal attenuation by scaling the wave signal energy with the angle that the sensor makes with the impact location. The scaling factor could be determined by plotting the wave signal energy for an array of sensors. Figure 20 shows a test setup for determining the amount of diagonal attenuation in a material.

Each sensor is the same distance away from the impact location. If the material were homogenous and isotropic, the wave signal energy would be the same for all sensors. If the material were orthogonally isotropic fiberglass, however, the wave signal energy would be strongest along the direction of the fibers. Thus, the wave signal energy would be largest for sensors 1 and 5 and smallest for sensor 3. The ratio of the attenuated signal to the non-attenuated signal would be the correction factor for that angle.

Figure 20: Sensor Array for Observing Diagonal Attenuation

An exact scaling factor for every sensor on every impact would require more effort in the present case than it would be worth, but the effect on the data of the diagonal attenuation can be approximated. It can be shown that the data points that seemed to be outliers would in fact have been more in line with the other data points in the KE plots by considering how many sensors are aligned with each impact point and fiber directions and observing that, for similar kinetic energies, the impact positions that were aligned with both fibers and sensors had the higher wave signal energies.

The effect of diagonal attenuation can be observed by examining shots that have similar kinetic energies. Shots #12, 7, and 12a, for example, have the same kinetic energy but produce different wave signal energies. Each of these impacts are in line with one sensor, but are at varying angles with the other five sensors (see Figure 5 for sensor and impact locations). Figure 21 shows the wave signal energy picked up by one direct sensor and five diagonal sensors for each impact. The direct W.S.E. is the same for each shot, but the diagonal W.S.E. changes. The diagonal component should be scaled so that all sensors record the same amount of energy.

Figure 21: C-2 Diagonal and Direct W.S.E. for Shots #12, 7, and 12a

Another set of shots that has similar kinetic energy is shots #5, 16, 14, and 4 (Figure 22). These four shots are more difficult to compare than the previous set because each shot is in line with a different number of sensors. Shot #14 is in line with three sensors so its total W.S.E. is primarily composed of direct energy. The direct energy for shot #5 is very small because it is far away from the sensor it is in line with (sensor 3) and should be scaled for distance. Shots #5, 16, and 4 consist primarily of diagonal W.S.E and should be scaled to approximately match the total W.S.E. of shot #14.

Figure 22: C-2 Diagonal and Direct W.S.E. for shots #5, 16, 14, and 4

Conclusions

The results of the hypervelocity impact test on fiberglass Target C-2 are as follows:

- Ultrasonic Sensors were successfully bonded to fiberglass Target C-2 with a Lord 202 Acrylic Adhesive.

- Ultrasonic Sensors operated well in near-vacuum (6-8 Torr) inside the vacuum chamber at Johnson Space Center's White Sands Testing Facility.[1]

- Impacts created detectable ultrasonic signals at high (>50 kHz) frequencies which should be above flight noise.[2]

- Ultrasonic signals were detected with small, lightweight sensors capable of space flight.[34]

- Wave propagation characteristics of the cross-ply fiberglass target were measured and used in the analysis of the wave signal energy.

- Wave signal energy correlated well with kinetic energy and impact damage.

This test successfully demonstrated the ability for a wing leading edge impact detection system (WLEIDS) to model the kinetic energy response and material damage below, at and above complete penetration of the projectile through the target.

Appendix

---

[1] B1025 sensors also functioned well in deep vacuum of ESEM. Michael Horn, NASA LaRC, email 2005.
[2] Based on measurement of noise spectra on F16 bulkhead at full throttle, there will not be significant noise power above 50kHz.
[3] Sensors passed 18,000 g shock test. Henry Whitesel, Naval Surface Warfare Center, verbal communication 1998.
[4] DWC sensors survived intense radiation environment. Dane Spearing, LANL, verbal communication 2003.

The appendices contain the information for each shot and the waveforms. No photos of Target C-2 damage were available. For completeness and for usefulness when judging the energy versus damage plots shown in the discussion section above, tables are given at the end that summarize and group together the data for the key test variables.

Figure 23: Fiberglass Article Target C-2 Drawing

Test Condition Data Sheets

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 2-19-04

Specimen description: Fiberglass
                        Target C-2
                         Shot # 1

Impact conditions:
        Projectile material and diameter: 0.6 mm diameter aluminum
        Planned impact coordinates (in.): 8 , 10
        Actual impact coordinates (in.):
        AE estimated impact coordinates (in.):
        Planned impact velocity (km/s): 6.8
        Actual impact velocity (km/s): 6.65
        Impact angle: 45

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	0	27	-23
2	225	15	26	-50	0	27	-23
3	225	22	26	-50	0	27	-23
4	225	29	26	-50	0	27	-23
5	225	30	19	0	-20	18	-2
6	225	04	19	0	-20	18	-2

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
        5 MHz sampling rate
        32k points
        4096 pretrigger points

Comments: Attenuators not available for channels 5 and 6. Signals saturated on those channels.

Figure 24: C-2 Shot #1 Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 3-1-04

Specimen description: Fiberglass
                        Target C-2
                        Shot # 2b

Impact conditions:
        Projectile material and diameter: 0.6 mm diameter aluminum
        Planned impact coordinates (in.): 10 , 10
        Actual impact coordinates (in.):
        AE estimated impact coordinates (in.):
        Planned impact velocity (km/s): 3.0
        Actual impact velocity (km/s): 3.52
        Impact angle: 45

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	0	33	-17
2	225	15	26	-50	0	33	-17
3	225	22	26	-50	0	33	-17
4	225	29	26	-50	0	33	-17
5	225	30	19	-50	0	33	-17
6	225	04	19	-50	0	33	-17

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
        5 MHz sampling rate
        32k points
        4096 pretrigger points

Comments: Very small signals

Figure 25: C-2 Shot #2b Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 2-20-04

Specimen description: Fiberglass
                      Target C-2
                      Shot # 3

Impact conditions:
          Projectile material and diameter: 1.6 mm diameter aluminum
          Planned impact coordinates (in.): 14 , 10
          Actual impact coordinates (in.):
          AE estimated impact coordinates (in.):
          Planned impact velocity (km/s): 6.8
          Actual impact velocity (km/s): 6.93
          Impact angle: 45

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	0	0	-50
2	225	15	26	-50	0	0	-50
3	225	22	26	-50	0	0	-50
4	225	29	26	-34**	-20	0	-54
5	225	30	19	-34**	-20	0	-54
6	225	04	19	-50	0	0	-50

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.
** Not enough attenuators available. Inserted 50 ohm feedthrough into circuit which
provided peak amplitude attenuation of approximately 34 db.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
          5 MHz sampling rate
          32k points
          4096 pretrigger points

Comments: Attenuators not available for channels 4 and 5. 50 ohm feedthrough
terminators used for those channels which provided as yet uncalibrated attenuation.

Figure 26: C-2 Shot #3 Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 2-20-04

Specimen description: Fiberglass
Target C-2
Shot # 4

Impact conditions:
Projectile material and diameter: 1.8 mm diameter aluminum
Planned impact coordinates (in.): 17 , 10
Actual impact coordinates (in.):
AE estimated impact coordinates (in.):
Planned impact velocity (km/s): 6.8
Actual impact velocity (km/s): 4.68
Impact angle: 45

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	0	0	-50
2	225	15	26	-50	0	0	-50
3	225	22	26	-50	0	0	-50
4	225	29	26	-34**	-20	0	-54
5	225	30	19	-34**	-20	0	-54
6	225	04	19	-50	0	0	-50

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.
** Not enough attenuators available. Inserted 50 ohm feedthrough into circuit which
provided peak amplitude attenuation of approximately 34 db.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
5 MHz sampling rate
32k points
4096 pretrigger points

Comments: Attenuators not available for channels 4 and 5. 50 ohm feedthrough
terminators used for those channels which provided as yet uncalibrated attenuation.

Figure 27: C-2 Shot #4 Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 3-2-04

Specimen description: Fiberglass
                        Target C-2
                        Shot # 5

Impact conditions:
        Projectile material and diameter: 2.0 mm diameter aluminum
        Planned impact coordinates (in.): 21 , 10
        Actual impact coordinates (in.):
        AE estimated impact coordinates (in.):
        Planned impact velocity (km/s): 3.0
        Actual impact velocity (km/s): 2.97
        Impact angle: 45

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	0	9	-41
2	225	15	26	-50	0	9	-41
3	225	22	26	-50	0	9	-41
4	225	29	26	-50	0	9	-41
5	225	30	19	-50	0	9	-41
6	225	04	19	-50	0	9	-41

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
        5 MHz sampling rate
   32k points
        4096 pretrigger points

Comments:

Figure 28: C-2 Shot #5 Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 2-23-04

Specimen description: Fiberglass
Target C-2
Shot # 6

Impact conditions:
Projectile material and diameter: 2.4 mm diameter aluminum
Planned impact coordinates (in.): 26 , 10
Actual impact coordinates (in.):
AE estimated impact coordinates (in.):
Planned impact velocity (km/s): 6.8
Actual impact velocity (km/s): 6.91
Impact angle: 45

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-34**	-20	0	-54
2	225	15	26	-50	-20	15	-55
3	225	22	26	-50	-20	15	-55
4	225	29	26	-50	-20	15	-55
5	225	30	19	-50	-20	15	-55
6	225	04	19	-34**	-20	0	-54

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.
** Not enough attenuators available. Inserted 50 ohm feedthrough into circuit which
provided peak amplitude attenuation of approximately 34 db.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
5 MHz sampling rate
32k points
4096 pretrigger points

Comments: Attenuators not available for channels 1 and 6. 50 ohm feedthrough
terminators used for those channels which provided as yet uncalibrated attenuation.

Figure 29: C-2 Shot #6 Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 3-03-04

Specimen description: Fiberglass
                       Target C-2
                       Shot # 6a

Impact conditions:
        Projectile material and diameter: 1.8 mm diameter aluminum
        Planned impact coordinates (in.): 26 , 14
        Actual impact coordinates (in.):
        AE estimated impact coordinates (in.):
        Planned impact velocity (km/s): 6.8
        Actual impact velocity (km/s): 6.82
        Impact angle: 45

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	0	0	-50
2	225	15	26	-50	0	0	-50
3	225	22	26	-50	0	0	-50
4	225	29	26	-50	0	0	-50
5	225	30	19	-50	0	0	-50
6	225	04	19	-50	0	0	-50

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
        5 MHz sampling rate
        32k points
        4096 pretrigger points

Comments: Repeat of shot #4 to get higher velocity

Figure 30: C-2 Shot #6a Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 3-2-04

Specimen description: Fiberglass
                      Target C-2
                      Shot # 7

Impact conditions:
        Projectile material and diameter: 2.0 mm diameter aluminum
        Planned impact coordinates (in.): 8 , 14
        Actual impact coordinates (in.):
        AE estimated impact coordinates (in.):
        Planned impact velocity (km/s): 6.8
        Actual impact velocity (km/s): 6.82
        Impact angle: 45

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	0	3	-47
2	225	15	26	-50	0	3	-47
3	225	22	26	-50	0	3	-47
4	225	29	26	-50	0	3	-47
5	225	30	19	-50	0	3	-47
6	225	04	19	-50	0	3	-47

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
        5 MHz sampling rate
        32k points
   4096 pretrigger points

Comments:

Figure 31: C-2 Shot #7 Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 3-03-04

Specimen description: Fiberglass
                       Target C-2
                       Shot # 8

Impact conditions:
       Projectile material and diameter: 0.6 mm diameter aluminum
       Planned impact coordinates (in.): 12 , 12
       Actual impact coordinates (in.):
       AE estimated impact coordinates (in.):
       Planned impact velocity (km/s): 6.8
       Actual impact velocity (km/s): 6.86
       Impact angle: 90

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	0	27	-23
2	225	15	26	-50	0	27	-23
3	225	22	26	-50	0	27	-23
4	225	29	26	-50	0	27	-23
5	225	30	19	-50	0	27	-23
6	225	04	19	-50	0	27	-23

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
       5 MHz sampling rate
       32k points
   4096 pretrigger points

Comments:

Figure 32: C-2 Shot #8 Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 3-10-04

Specimen description: Fiberglass
Target C-2
Shot # 9

Impact conditions:
Projectile material and diameter: 0.6 mm diameter aluminum
Planned impact coordinates (in.): 12 , 14
Actual impact coordinates (in.):
AE estimated impact coordinates (in.):
Planned impact velocity (km/s): 3.0
Actual impact velocity (km/s): not measured – laser measurement system did not trigger
Impact angle: 90

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	0	36	-14
2	225	15	26	-50	0	36	-14
3	225	22	26	-50	0	36	-14
4	225	29	26	-50	0	36	-14
5	225	30	19	-50	0	36	-14
6	225	04	19	-50	0	36	-14

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
5 MHz sampling rate
32k points
4096 pretrigger points

Comments:

Figure 33: C-2 Shot #9 Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 3-23-04

Specimen description: Fiberglass
                       Target C-2
                       Shot # 9a

Impact conditions:
      Projectile material and diameter: 0.6 mm diameter aluminum
      Planned impact coordinates (in.): 16 , 22
      Actual impact coordinates (in.):
      AE estimated impact coordinates (in.):
      Planned impact velocity (km/s): 3.0
      Actual impact velocity (km/s): 3.03
      Impact angle: 0

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	0	33	-17
2	225	15	26	-50	0	33	-17
3	225	22	26	-50	0	33	-17
4	225	29	26	-50	0	33	-17
5	225	30	19	-50	0	33	-17
6	225	04	19	-50	0	33	-17

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
      5 MHz sampling rate
      32k points
   4096 pretrigger points

Comments:

Figure 34: C-2 Shot #9a Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 3-10-04

Specimen description: Fiberglass
                       Target C-2
                       Shot # 10

Impact conditions:
        Projectile material and diameter: 1.4 mm diameter aluminum
        Planned impact coordinates (in.): 14.5 , 14
        Actual impact coordinates (in.):
        AE estimated impact coordinates (in.):
        Planned impact velocity (km/s): 6.8
        Actual impact velocity (km/s): 6.86
        Impact angle: 90

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	0	6	-44
2	225	15	26	-50	0	6	-44
3	225	22	26	-50	0	6	-44
4	225	29	26	-50	0	6	-44
5	225	30	19	-50	0	6	-44
6	225	04	19	-50	0	6	-44

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
        5 MHz sampling rate
   32k points
        4096 pretrigger points

Comments:

Figure 35: C-2 Shot #10 Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 3-11-04

Specimen description: Fiberglass
                       Target C-2
                       Shot # 11

Impact conditions:
    Projectile material and diameter: 2.4 mm diameter aluminum
    Planned impact coordinates (in.): 20 , 14
    Actual impact coordinates (in.):
    AE estimated impact coordinates (in.):
    Planned impact velocity (km/s): 6.8
    Actual impact velocity (km/s): 6.82
    Impact angle: 90

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	-20	15	-55
2	225	15	26	-50	-20	15	-55
3	225	22	26	-50	-20	15	-55
4	225	29	26	-50	-20	15	-55
5	225	30	19	-50	-20	15	-55
6	225	04	19	-50	-20	15	-55

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
    5 MHz sampling rate
    32k points
   4096 pretrigger points

Comments:

Figure 36: C-2 Shot #11 Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 3-11-04

Specimen description: Fiberglass
                      Target C-2
                      Shot # 12

Impact conditions:
        Projectile material and diameter: 1.6 mm diameter aluminum
        Planned impact coordinates (in.): 12 , 17
        Actual impact coordinates (in.):
        AE estimated impact coordinates (in.):
        Planned impact velocity (km/s): 6.8
        Actual impact velocity (km/s): 6.80
        Impact angle: 90

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	0	0	-50
2	225	15	26	-50	0	0	-50
3	225	22	26	-50	0	0	-50
4	225	29	26	-50	0	0	-50
5	225	30	19	-50	0	0	-50
6	225	04	19	-50	0	0	-50

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
        5 MHz sampling rate
        32k points
   4096 pretrigger points

Comments:

Figure 37: C-2 Shot #12 Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 3-17-04

Specimen description: Fiberglass
Target C-2
Shot # 12a

Impact conditions:
Projectile material and diameter: 1.6 mm diameter aluminum
Planned impact coordinates (in.): 23 , 15
Actual impact coordinates (in.):
AE estimated impact coordinates (in.):
Planned impact velocity (km/s): 6.8
Actual impact velocity (km/s): 6.85
Impact angle: 0

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	0	0	-50
2	225	15	26	-50	0	0	-50
3	225	22	26	-50	0	0	-50
4	225	29	26	-50	0	0	-50
5	225	30	19	-50	0	0	-50
6	225	04	19	-50	0	0	-50

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
5 MHz sampling rate
32k points
4096 pretrigger points

Comments:

Figure 38: C-2 Shot #12a Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 3-15-04

Specimen description: Fiberglass
                       Target C-2
                       Shot # 13

Impact conditions:
        Projectile material and diameter: 1.8 mm diameter aluminum
        Planned impact coordinates (in.): 17.5 , 17.5
        Actual impact coordinates (in.):
        AE estimated impact coordinates (in.):
        Planned impact velocity (km/s): 6.8
        Actual impact velocity (km/s): 6.83
        Impact angle: 90

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	0	0	-50
2	225	15	26	-50	0	0	-50
3	225	22	26	-50	0	0	-50
4	225	29	26	-50	0	0	-50
5	225	30	19	-50	0	0	-50
6	225	04	19	-50	0	0	-50

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
        5 MHz sampling rate
   32k points
        4096 pretrigger points

Comments:

Figure 39: C-2 Shot #13 Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 3-15-04

Specimen description: Fiberglass
                       Target C-2
                       Shot # 14

Impact conditions:
        Projectile material and diameter: 2.0 mm diameter aluminum
        Planned impact coordinates (in.): 14.5 , 19
        Actual impact coordinates (in.):
        AE estimated impact coordinates (in.):
        Planned impact velocity (km/s): 3.0
        Actual impact velocity (km/s): 2.75
        Impact angle: 90

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	0	9	-41
2	225	15	26	-50	0	9	-41
3	225	22	26	-50	0	9	-41
4	225	29	26	-50	0	9	-41
5	225	30	19	-50	0	9	-41
6	225	04	19	-50	0	9	-41

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
        5 MHz sampling rate
   32k points
        4096 pretrigger points

Comments:

Figure 40: C-2 Shot #14 Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 3-16-04

Specimen description: Fiberglass
Target C-2
Shot # 15

Impact conditions:
Projectile material and diameter: 2.8 mm diameter aluminum
Planned impact coordinates (in.): 21 , 20.5
Actual impact coordinates (in.):
AE estimated impact coordinates (in.):
Planned impact velocity (km/s): 6.8
Actual impact velocity (km/s): 6.76
Impact angle: 0

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	-20	12	-58
2	225	15	26	-50	-20	12	-58
3	225	22	26	-50	-20	12	-58
4	225	29	26	-50	-20	12	-58
5	225	30	19	-50	-20	12	-58
6	225	04	19	-50	-20	12	-58

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
5 MHz sampling rate
32k points
4096 pretrigger points

Comments:

Figure 41: C-2 Shot #15 Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 3-16-04

Specimen description: Fiberglass
                       Target C-2
                       Shot # 16

Impact conditions:
    Projectile material and diameter: 1.0 mm diameter aluminum
    Planned impact coordinates (in.): 18 , 22
    Actual impact coordinates (in.):
    AE estimated impact coordinates (in.):
    Planned impact velocity (km/s): 6.8
    Actual impact velocity (km/s): 6.91
    Impact angle: 0

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	0	9	-41
2	225	15	26	-50	0	9	-41
3	225	22	26	-50	0	9	-41
4	225	29	26	-50	0	9	-41
5	225	30	19	-50	0	9	-41
6	225	04	19	-50	0	9	-41

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
    5 MHz sampling rate
    32k points
   4096 pretrigger points

Comments:

Figure 42: C-2 Shot #16 Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 3-23-04

Specimen description: Fiberglass
                      Target C-2
                      Shot # 17e

Impact conditions:
        Projectile material and diameter: 0.6 mm diameter aluminum
        Planned impact coordinates (in.): 16 , 22
        Actual impact coordinates (in.):
        AE estimated impact coordinates (in.):
        Planned impact velocity (km/s): 6.8
        Actual impact velocity (km/s): 7.06
        Impact angle: 0

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	0	21	-29
2	225	15	26	-50	0	21	-29
3	225	22	26	-50	0	21	-29
4	225	29	26	-50	0	21	-29
5	225	30	19	-50	0	21	-29
6	225	04	19	-50	0	21	-29

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
        5 MHz sampling rate
   32k points
        4096 pretrigger points

Comments:

Figure 43: C-2 Shot #17e Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 3-24-04

Specimen description: Fiberglass
                       Target C-2
                       Shot # 18

Impact conditions:
    Projectile material and diameter: 0.6 mm diameter aluminum
    Planned impact coordinates (in.): 14 , 22
    Actual impact coordinates (in.):
    AE estimated impact coordinates (in.):
    Planned impact velocity (km/s): 6.8
    Actual impact velocity (km/s): 6.92
    Impact angle: 45

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	0	24	-26
2	225	15	26	-50	0	24	-26
3	225	22	26	-50	0	24	-26
4	225	29	26	-50	0	24	-26
5	225	30	19	-50	0	24	-26
6	225	04	19	-50	0	24	-26

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
    5 MHz sampling rate
   32k points
    4096 pretrigger points

Comments:

Figure 44: C-2 Shot #18 Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 3-24-04

Specimen description: Fiberglass
                      Target C-2
                      Shot # 19

Impact conditions:
        Projectile material and diameter: 1.0 mm diameter aluminum
        Planned impact coordinates (in.): 12 , 22
        Actual impact coordinates (in.):
        AE estimated impact coordinates (in.):
        Planned impact velocity (km/s): 6.8
        Actual impact velocity (km/s): 6.81
        Impact angle: 45

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	0	6	-44
2	225	15	26	-50	0	6	-44
3	225	22	26	-50	0	6	-44
4	225	29	26	-50	0	6	-44
5	225	30	19	-50	0	6	-44
6	225	04	19	-50	0	6	-44

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
        5 MHz sampling rate
        32k points
   4096 pretrigger points

Comments:

Figure 45: C-2 Shot #19 Impact Waveform

Test conditions for AE (ultrasonic) data acquisition during hypervelocity impact testing

Test date: 3-25-04

Specimen description: Fiberglass
                       Target C-2
                       Shot # 20

Impact conditions:
        Projectile material and diameter: 2.8 mm diameter aluminum
        Planned impact coordinates (in.): 8 , 22
        Actual impact coordinates (in.):
        AE estimated impact coordinates (in.):
        Planned impact velocity (km/s): 6.8
        Actual impact velocity (km/s): 6.77
        Impact angle: 45

Sensor information:

Ch. #	Sensor Model	x coord. (in.)	y coord. (in.)	Attenuation at sensor * (dB)	Preamp gain/ attenuation (dB)	System gain (dB)	Total gain/ attenuation (dB)
1	225	8	26	-50	-20	9	-61
2	225	15	26	-50	-20	9	-61
3	225	22	26	-50	-20	9	-61
4	225	29	26	-50	-20	9	-61
5	225	30	19	-50	-20	9	-61
6	225	04	19	-50	-20	9	-61

* Preliminary estimate for attenuation at sensor based on field measurements.
Attenuators calibrated for 50 ohm input, but used for high impedance preamp input.
Further laboratory characterization required.

Signal filter settings: 20kHz – 1500 kHz bandpass on all channels
Instrumentation settings:
        5 MHz sampling rate
        32k points
   4096 pretrigger points

Comments:

Figure 46: C-2 Shot #20 Impact Waveform

Data Tables

Test	Imp Dia	Imp Vel	Imp Ang	Normal K.E.	Total K.E.	Location		Channel Gain (dB)					
No.	mm	km/s	deg	J (±5%)	J (±5%)	x	y	1	2	3	4	5	6
C2-1	0.6	6.65	45	3.37	6.75	8	10	-23	-23	-23	-23	-2	-2
C2-2b	0.6	3.52	45	0.95	1.89	10	10	-17	-17	-17	-17	-17	-17
C2-3	1.6	6.93	45	69.47	139.05	14	10	-50	-50	-50	-54	-54	-50
C2-4	1.8	4.68	45	45.11	90.29	17	10	-50	-50	-50	-54	-54	-50
C2-5	2.0	2.97	45	24.92	49.88	21	10	-41	-41	-41	-41	-41	-41
C2-6	2.4	6.91	45	233.10	466.58	26	10	-54	-55	-55	-55	-55	-54
C2-6a	1.8	6.82	45	95.79	191.74	26	14	-50	-50	-50	-50	-50	-50
C2-7	2.0	6.82	45	131.41	263.02	8	14	-47	-47	-47	-47	-47	-47
C2-8	0.6	6.86	90	7.19	7.19	12	12	-23	-23	-23	-23	-23	-23
C2-9	0.6	3.00	90	1.37	1.37	12	14	-14	-14	-14	-14	-14	-14
C2-9a	0.6	3.03	90	1.40	1.40	16	22	-17	-17	-17	-17	-17	-17
C2-10	1.4	6.86	90	91.28	91.28	14.5	14	-44	-44	-44	-44	-44	-44
C2-11	2.4	6.82	90	454.50	454.50	20	14	-55	-55	-55	-55	-55	-55
C2-12	1.6	6.80	90	133.88	133.88	12	17	-50	-50	-50	-50	-50	-50
C2-12a	1.6	6.85	90	135.85	135.85	23	15	-50	-50	-50	-50	-50	-50
C2-13	1.8	6.83	90	192.31	192.31	17.5	17.5	-50	-50	-50	-50	-50	-50
C2-14	2.0	2.75	90	42.76	42.76	14.5	19	-41	-41	-41	-41	-41	-41
C2-15	2.8	6.76	90	709.09	709.09	21	20.5	-58	-58	-58	-58	-58	-58
C2-16	1.0	6.91	90	33.75	33.75	18	22	-41	-41	-41	-41	-41	-41
C2-17e	0.6	7.06	90	7.61	7.61	16	22	-29	-29	-29	-29	-29	-29
C2-18	0.6	6.92	45	3.65	7.31	14	22	-26	-26	-26	-26	-26	-26
C2-19	1.0	6.81	45	16.38	32.78	12	22	-44	-44	-44	-44	-44	-44
C2-20	2.8	6.77	45	355.31	711.19	8	22	-61	-61	-61	-61	-61	-61

Table 3: C-2 Impactor Diameter, Impactor Velocity, Impactor Angle, Normal Kinetic Energy, Total Kinetic Energy, Location, and Channel Gain

Test	Normal K.E.	Total K.E.	Crater Dims				Damage Dims		
No.	J (±5%)	J (±5%)	x mm	y mm	z mm	Volume mm^3	x mm	y mm	Area mm^2
C2-1	3.37	6.75	2.0	2.0	0.29	1.2	3.0	9.0	27.0
C2-2b	0.95	1.89	1.5	1.5	0.26	0.6	2.0	6.0	12.0
C2-3	69.47	139.05	5.0	6.5	3.9	126.8	12.0	16.0	192.0
C2-4	45.11	90.29	5.0	4.0	2.36	47.2	11.0	13.0	143.0
C2-5	24.92	49.88	5.0	4.5	1.5	33.8	11.0	13.0	143.0
C2-6	233.10	466.58	8.0	9.0	4.83	347.5	18.0	19.0	342.0
C2-6a	95.79	191.74	3.0	4.0	4.83	57.9	16.0	16.0	256.0
C2-7	131.41	263.02	6.5	6.0	4.83	188.2	14.0	18.0	252.0
C2-8	7.19	7.19	1.5	1.75	0.5	1.3	No data	No data	
C2-9	1.37	1.37	0.8	1.0	0.14	0.1	1.0	4.0	4.0
C2-9a	1.40	1.40	0.75	1.0	0.05	0.04	2.0	5.5	11.0
C2-10	91.28	91.28	4.0	4.5	3.2	57.6	9.0	14.0	126.0
C2-11	454.50	454.50	8.0	8.5	4.826	328.2	28.0	21.0	588.0
C2-12	133.88	133.88	4.0	4.0	No data		14.0	16.0	224.0
C2-12a	135.85	135.85	3.5	4.0	No data		14.0	15.0	210.0
C2-13	192.31	192.31	5.5	5.5	4.83	146.0	17.5	18.5	323.75
C2-14	42.76	42.76	2.5	4.5	2.29	25.8	7.5	13.0	97.5
C2-15	709.09	709.09	10.0	9.0	4.83	434.3	35.0	25.5	892.5
C2-16	33.75	33.75	4.5	4.0	1.4	25.2	6.5	10.0	65.0
C2-17e	7.61	7.61	1.5	1.75	0.49	1.3	2.5	8.0	20.0
C2-18	3.65	7.31	1.25	2.0	0.55	1.4	2.75	7.5	20.63
C2-19	16.38	32.78	2.0	3.5	0.9	6.3	7.0	10.5	73.5
C2-20	355.31	711.19	10.5	10.0	4.83	506.7	23.0	22.0	506.0

Table 4: C-2 Normal Kinetic Energy, Total Kinetic Energy, Front Side Crater Dimensions, Crater Volume, Front Side Fiber Damage Dimensions, and Fiber Damage Area

Test No.	S1 Raw Energy V^2 - µs	S2 Raw Energy V^2 - µs	S3 Raw Energy V^2 - µs	S4 Raw Energy V^2 - µs	S5 Raw Energy V^2 - µs	S6 Raw Energy V^2 - µs
C2-1	1.861	0.336	0.095	0.142	25.716	63.388
C2-2b	0.618	0.294	0.168	0.215	0.203	0.654
C2-3	0.228	0.352	0.028	0.086	0.123	0.196
C2-4	0.256	0.554	0.071	0.170	0.230	0.236
C2-5	0.333	0.377	0.396	0.245	0.327	0.472
C2-6	0.212	0.024	0.036	0.150	0.136	0.315
C2-6a	0.099	0.058	0.111	0.405	0.372	0.179
C2-7	2.023	0.221	0.057	0.093	0.232	1.564
C2-8	1.604	2.187	0.243	0.276	0.499	1.253
C2-9	1.369	1.484	0.378	0.392	0.565	1.676
C2-9a	21.834	23.213	8.656	4.465	10.011	26.447
C2-10	0.859	2.831	0.164	0.225	0.427	1.225
C2-11	0.085	0.101	0.089	0.054	0.097	0.112
C2-12	0.484	0.368	0.059	0.080	0.281	1.087
C2-12a	0.073	0.079	0.934	0.183	0.290	0.221
C2-13	0.275	0.808	0.133	0.158	0.699	1.116
C2-14	1.863	5.002	0.563	0.967	3.049	5.295
C2-15	0.072	0.090	0.084	0.092	0.273	0.152
C2-16	0.748	2.168	1.250	1.034	0.425	1.295
C2-17e	0.641	5.245	1.022	0.530	0.237	0.841
C2-18	1.538	6.488	0.899	0.483	0.256	1.410
C2-19	0.364	0.572	0.310	0.188	0.108	0.475
C2-20	0.105	0.043	0.041	0.034	0.020	0.153

Table 5: C-2 Raw Wave Signal Energy

Test	S1 En	S2 En	S3 En	S4 En	S5 En	S6 En	TOT WSE
No.	nJ	nJ	nJ	nJ	nJ	nJ	nJ
C2-1	37.1	3.713E+01	6.712E+00	1.888E+00	2.826E+00	4.076E+00	1.005E+01
C2-2b	3.1	3.099E+00	1.474E+00	8.412E-01	1.079E+00	1.017E+00	3.276E+00
C2-3	2283.8	2.284E+03	3.523E+03	2.827E+02	2.166E+03	3.085E+03	1.961E+03
C2-4	2558.7	2.559E+03	5.540E+03	7.107E+02	4.262E+03	5.770E+03	2.364E+03
C2-5	419.5	4.195E+02	4.740E+02	4.980E+02	3.081E+02	4.119E+02	5.942E+02
C2-6	5324.8	5.325E+03	7.693E+02	1.142E+03	4.728E+03	4.303E+03	7.922E+03
C2-6a	990.6	9.906E+02	5.813E+02	1.107E+03	4.050E+03	3.720E+03	1.788E+03
C2-7	10137.0	1.014E+04	1.110E+03	2.861E+02	4.640E+02	1.163E+03	7.840E+03
C2-8	32.0	3.200E+01	4.364E+01	4.841E+00	5.514E+00	9.965E+00	2.499E+01
C2-9	3.4	3.439E+00	3.728E+00	9.492E-01	9.852E-01	1.420E+00	4.209E+00
C2-9a	109.4	1.094E+02	1.163E+02	4.338E+01	2.238E+01	5.018E+01	1.326E+02
C2-10	2156.7	2.157E+03	7.111E+03	4.119E+02	5.643E+02	1.072E+03	3.076E+03
C2-11	2680.2	2.680E+03	3.200E+03	2.805E+03	1.697E+03	3.067E+03	3.533E+03
C2-12	4840.3	4.840E+03	3.680E+03	5.914E+02	7.966E+02	2.815E+03	1.087E+04
C2-12a	731.6	7.316E+02	7.889E+02	9.340E+03	1.834E+03	2.896E+03	2.209E+03
C2-13	2745.4	2.745E+03	8.077E+03	1.334E+03	1.583E+03	6.991E+03	1.116E+04
C2-14	2344.8	2.345E+03	6.297E+03	7.091E+02	1.217E+03	3.838E+03	6.666E+03
C2-15	4525.4	4.525E+03	5.698E+03	5.331E+03	5.773E+03	1.720E+04	9.616E+03
C2-16	942.2	9.422E+02	2.729E+03	1.573E+03	1.302E+03	5.350E+02	1.630E+03
C2-17e	50.9	5.090E+01	4.166E+02	8.121E+01	4.209E+01	1.883E+01	6.682E+01
C2-18	61.2	6.121E+01	2.583E+02	3.579E+01	1.923E+01	1.017E+01	5.612E+01
C2-19	913.9	9.139E+02	1.437E+03	7.784E+02	4.730E+02	2.715E+02	1.193E+03
C2-20	13236.8	1.324E+04	5.361E+03	5.222E+03	4.316E+03	2.532E+03	1.929E+04

Table 6: C-2 Gain Adjusted Wave Signal Energy

REPORT DOCUMENTATION PAGE

1. REPORT DATE *(DD-MM-YYYY)*	2. REPORT TYPE	3. DATES COVERED *(From - To)*
01-09-2007	Contractor Report	

4. TITLE AND SUBTITLE

Hypervelocity Impact (HVI) - Volume 4: WLE Small-Scale Fiberglass Panel Flat Target C-2

5a. CONTRACT NUMBER

NNL05AC19T

5b. GRANT NUMBER

5c. PROGRAM ELEMENT NUMBER

6. AUTHOR(S)

Gorman, Michael R.; and Ziola, Steven M.

5d. PROJECT NUMBER

5e. TASK NUMBER

5f. WORK UNIT NUMBER

377816.06.03.03.06

7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES)

NASA Langley Research Center
Hampton, VA 23681-2199

8. PERFORMING ORGANIZATION REPORT NUMBER

9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)

National Aeronautics and Space Administration
Washington, DC 20546-0001

10. SPONSOR/MONITOR'S ACRONYM(S)

NASA

11. SPONSOR/MONITOR'S REPORT NUMBER(S)

NASA/CR-2007-214885/Vol4

12. DISTRIBUTION/AVAILABILITY STATEMENT

Unclassified - Unlimited
Subject Category 70
Availability: NASA CASI (301) 621-0390

13. SUPPLEMENTARY NOTES

Langley Technical Monitor: Eric I. Madaras
An electronic version can be found at http://ntrs.nasa.gov

14. ABSTRACT

During 2003 and 2004, the Johnson Space Center's White Sands Testing Facility in Las Cruces, New Mexico conducted hypervelocity impact tests on the space shuttle wing leading edge. Hypervelocity impact tests were conducted to determine if Micro-Meteoroid/Orbital Debris impacts could be reliably detected and located using simple passive ultrasonic methods. The objective of Target C-2 was to study impacts through the reinforced carboncarbon (RCC) panels of the Wing Leading Edge. Fiberglass was used in place of RCC in the initial tests. Impact damage was detected using lightweight, low power instrumentation capable of being used in flight.

15. SUBJECT TERMS

Hypervelocity impact tests; Space shuttle; Wing leading edge; Debris; Impact damage

16. SECURITY CLASSIFICATION OF:

a. REPORT	b. ABSTRACT	c. THIS PAGE	17. LIMITATION OF ABSTRACT	18. NUMBER OF PAGES	19a. NAME OF RESPONSIBLE PERSON
U	U	U	UU	83	STI Help Desk (email: help@sti.nasa.gov)

19a. NAME OF RESPONSIBLE PERSON
STI Help Desk (email: help@sti.nasa.gov)

19b. TELEPHONE NUMBER *(Include area code)*
(301) 621-0390