National Aeronautics and Space Administration

Status of Advanced Stitched Composite Aircraft Structures

Dawn Jegley
NASA Structures Lead

Alexander Velicki
Boeing PI

Environmentally Responsible Aviation
Integrated Systems Research Program



AIAA Aero Sciences Meeting
January 4-7, 2011

Challenges of Hybrid Wing Body Center Section

- Pressurized non-circular center section
  - Compound curvature
  - Almost 90-degree angles at joints
  - Fatigue
- Bi-directional in-plane loading
  - Continuous load paths in both direction
  - Integral design without shear clips
- Manufacturable
  - Large integral components
  - Out-of-autoclave process
- Economical
  - Hard metal tooling on OML only
  - Simplified bagging process for IML
  - Fabricate entire cover panel in one cure
- Damage Tolerant
  - Arrest damage resulting from discrete source damage
  - Minimal delamination
- Acceptable acoustic response



Pultruded Rod Stitched Efficient Unitized Structure



Stitched Structure Development

NASA/Boeing ACT Technology

1990-2000

Lightly-Loaded Secondary Structure



LAIRCM Fairing

Unitized Structure

Moderately-Loaded Structures



Gear Doors

Complex Integration

Highly-Loaded Structures



Integral Fuselage

Curved Panel 2008

Fairing First Flight 2003

C-17 Prototype Nose 2005

C-17 Production Main 2006

Large Panel Air Force 2006

Hybrid Wing Body



Initial Objective: Develop concept for HWB center

TRL 3 - Proof of Concept

Trades Studies



Combined Load:
- *Spanwise Axial*
- *Chordwise Axial*
- *Internal Pressure*

- *Test Loads*
- *Panel Geometry*

TRL 4 - Validation by Test

Element-level Specimens
- *Stringer and Frame Directions*
- *Static Axially Loaded*
- *Analytical Predictions*

Subcomponents
- *Stringer and Frame Directions*
- *Static Axially Loaded (Fx and Fy)*
- *Pressure Box (Fn)*
- *Analytical Predictions*





Verify improvements with vehicle-level analysis and refine analysis codes

Bending and out-of-plane loading for minimum gauge panels

Buckling of large unsupported spans

Damage arrestment for minimum gauge panels

HWB Vehicle Sizing



Vehicle FEM

Stiffness
Mass Distribution

Vehicle Level Requirements

Aeroelasticity

Linear Aero
(NASTRAN Sol 144)

NASTRAN
Solution 200

Embedded Sizing Equations

Global Analysis

Local Analysis

Fuselage
Design Region



Property Update

Panel Optimization

Local Panel Sizing Req'mts
- Strength and Stability
- Local Geometry Effects
- Material and Mfg Constraints

Panel Geometry

Constant Set of Running Lo

Updated HyperSizer Code Tailored for PRSEUS in Phase II

Panel Level Requirements



Updated Design Allowables in Phase II based on Phase I Testing

Material Properties

Bottoms-up Wts

Flat PRSEUS Panel Fabrication

Tear Straps Placed

Skins Placed

Automated Preform Stitching

Preform on Mold Tool



Resin Infusion



Cured Panel

Manufacturing, Coupons, Design and Mechanics

- Material characterization
- Thermal effects on properties
- Fatigue studies
- Rod-wrap interface improvements
- Positioning aids to improve dimensional tolerance
- Ideal stitching pattern
- Improved bagging methodology
- Simplified analysis methodologies

Compression Panel





Predicted Critical Locations

Max Strains

Possible Edge Effects

Panel CL



Frame CL **Frame CL**

Measured Full Field Axial Strain



IML Specimen Surface

Damaged Tension Panel Test



Flat PRSEUS Pressure Panel



- Minimum gage skin (.052 in.)
- Met 2P (18.4 psi) requirement with no damage
- 20 ft-lb internal damage to rod-stiffener
- Sustained 3P with damage
- Failure in rod-stiffener but continued to hold pressure to 30 psi





18 psi

Failure Site



PRSEUS Progress

Trades Studies

- Weight Goals
- Test Loads
- Panel Geometry



10% better than sandwich.

NRA Phase I Trades



PRSEUS 10.4% lighter.

improved buckling stability.

NRA Phase I Specimens

Stringer



Frame

test stability failure 75% higher than strength design allowable.

within 5% of static results after 2 fatigue lives.

fatigue failures within 5% of static test results.

withstand 2P (18.4 psi) load case.

28 psi with no damage



Pressure Cube

Multi-bay Box







arrested damage at 1.5 times initiation load.

general panel buckling at -5,000 lbs/in.

Arrested damage at 3 times higher than initiation load level.

Compression panel test 73 kips/frame.



Combined axial & pressure loading test at NASA COLTS Facility

Curved Pressure Panel

- IM7-VRM-34
- 127 inches long
- 75 inches wide (with doublers)
- 90-inch radius
- 24-inch frame spacing
- 7.8-inch rod-stiffener spacing

Panel delivered to NASA Dec. 2010
Testing scheduled for summer 2011

Curved Pressure Panel Test

- Pristine panel
  - apply 18.4 psi
  - apply 9.2 psi and DLL tension
- Panel with barely visible damage
  - apply 9.2 psi and DLL tension
  - apply 13.8 psi and DUL tension
- Panel with Discrete Source Damage
  - apply 9.2 psi with DLL
  - apply axial load to failure with no pressure
- Tests planned for summer 2011



FAA FASTER Facility

(**F**ull scale **A**ircraft **S**tructure **T**est **E**valuation and **R**esearch facility)

Repair Concepts

- Design, Testing and Analysis
  - Requirements: (1) Restore load carrying capability of a pristine structure (2) Minimize need for specialized equipment/methods
  - Bolted metallic repair;
  - DSD tension panel used as a baseline

Tension-Loaded Crack-Arrestment Test Panel Baseline

Stress Finite Element Analysis



Repair Assembly

Acoustics

- Experimentally characterize PRSEUS panel without acoustic treatment
- Validate finite element (low freq.) and statistical energy (high freq.) analyses
- Propose effective acoustic treatment with minimal weight penalty

LaRC SALT facility



Finite Element Model

Panel test in 2011

Fundamental Mode



Damage

- Damage arrestment at stitch lines
  - experimental evidence
  - corresponding analytical predictions
- Structural Health Monitoring
  - damage around stitches
  - Rod-overwrap region
- Fatigue and damage growth
- Stitching/damage suppression and arrestment opens the door to more efficient design

Multi-bay Test Article Development Approach

BWB Baseline



Pressure Cube (~48" wide)



Large-Scale Test Article (80% scale)

Combined Loads Test Facility (NASA-LaRC)



Pressure Cube - Risk Reduction



Large-scale Test Article

Pressure Cube Design (52" x 48" x 56" Tall)



- PRSEUS panels on all sides
- Evaluate joint behavior
- Load in pressure only to 2P (18.4 psi)
- Impact at critical joint location
- Supports multi-bay box design

Pressure Cube Benefits

- A build up of highly integrated structural panel assemblies
- Integrated structures eliminates fit-up issues during assembly
- Stitching increased pull-off capability and enables a fail-safe design approach
- PRSEUS concept reduces panel fabrication tooling costs
- No final assembly tooling required
- Drastic part reduction
- Reduced assembly time



Multi-bay Box Overview

- Multibay Box overall dimensions
  - ~30ft x 7.3ft x 18.3ft
- Approximate Volume = 2350 ft^3



Multi-bay Test in NASA LaRC COLTS Facility

- Test conditions
  - Pressure loading to 2P (18.4 psi)
  - Axial Bending to 2.5G
  - Combined Axial loading and 1P (9.2 psi)
- Analysis including loads as applied by COLTS
- Delivered and tested in 2010





Future Plans

- Pressure cube test: April 2011
- Multi-bay box test: 2012
- Circular fuselage development 2011-2015
- Damage tolerance studies 2011-2015
- PRSEUS wing development
- Flight vehicle

Summary of PRSEUS development

- PRSEUS development supported by NASA, Boeing, FAA and AFRL
- Stitching is used to suppress interlaminar failures, arrest damage and turn cracks
- Damage arrest design principles already demonstrated in flat panels
- PRSEUS allows for non-circular pressurized center section to withstand repeated pressure and flight loads
- Unitized structure simplifies final assembly
- Out-of-autoclave processing allows for cheaper fabrication and quicker and easier changes to designs
- Validation of predictions for built-up structure still needed
- Combined axial and pressure loading will be achieved by a near-full-scale 30-foot multi-bay box representing the center section of a HWB vehicle