Combined Thermomechanical and Environmental Durability of Environmental Barrier Coating Systems on SiC/SiC Ceramic Matrix Composites

Dongming Zhu, Bryan Harder and Ramakrishna Bhatt
Materials and Structures Division
NASA John H. Glenn Research Center
Cleveland, Ohio 44135, USA

9th International Conference on High Temperature Ceramic Matrix Composites (HTCMC-9)
Toronto, Canada
June 26-July 1, 2016

NASA Turbine Environmental Barrier Coatings for CMC-EBC Systems

- Emphasize temperature capability, performance and durability for next generation turbine engine systems
- Increase Technology Readiness Levels for component system demonstrations



Environmental Barrier Coating and SiC/SiC System Development: Testing Challenges

- High Temperatures: 2700 to 3000°F (1500-1650°C) along with higher interface temperatures
- Exposure to water vapor and combustion products
- High Cyclic Stresses: thermal and mechanical, creep-fatigue effect
- Combined Interactions, in-plane and through-thickness gradients
- High Velocity Gases: Mach 1 and 2
- High Pressures: ~ up to 40 to 50 atmospheres
- Long term durability: 20,000 hr design life

Outline

- **Advanced testing approaches for SiC/SiC and ceramic coating development: laser high heat flux based testing approaches**
  - NASA CO_2 laser rig development
  - Thermal conductivity
  - Cyclic durability and monitoring degradations of EBCs and CMCs

- **Laser high heat flux and mechanical tests**
  - Combined high heat flux - mechanical tests
  - High heat flux biaxial creep/fatigue test rigs
  - Sub-element testing

- **Summary and future directions**

High Power CO_2 Laser Based High Heat Flux Testing for SiC/SiC and Environmental Barrier Coatings Development

– Developed in 1990's, the rig achieved turbine level high-heat-fluxes (315 W/cm^2) for turbine thermal barrier coating testing
– Crucial for advanced EBC-CMC developments

Turbine: 450°F across 100 microns
Combustor:1250°F across 400 microns



Cooling – high velocity air or air-water mist
Achieved heat transfer coefficient 0.3 W/cm^2-K



High Power CO_2 Laser Based High Heat Flux Testing for SiC/SiC and Environmental Barrier Coatings Development - Continued

- NASA high power CO_2 laser rig systems
- Various test rigs developed
- 7.9 micron single wavelength and 1 micron two color wavelength pyrometers for temperature measurements
- Thermography system for temperature distribution measurements
- Capable of programmable test mission cycles
- Capable of mechanical load cycles under high heat flux
- Environment test conditions (e.g., steam and vacuum)





Some temperature thermal gradient cycles

High heat flux combustor rig

High Power CO_2 Laser Based High Heat Flux Testing for SiC/SiC and Environmental Barrier Coatings Development – Continued

- Controlled beam profiles, beam size and power density were major emphases, by using rotating ZnSe integrating lens with various focus lengths
- Uniform distribution up to 2-3” diameter beam size for various testing



Example of 1” diameter disc specimen tests and beam profile



2” beam size subelement tests

High Power CO_2 Laser Based High Heat Flux Fatigue Test Rig

- Laser creep and fatigue testing capable of full tension and compression loading
- Uniform distribution up to 2-3” diameter beam size for various testing, depending on the heat flux requirements



Laser heat flux Thermal HCF/LCF Rig – Overall View



Specimen under testing in tensile-compression fatigue rig

High Heat Flux Rig Testing with Water vapor Steam Chamber – Established in Early 2000

- High temperature and high-heat-flux testing capabilities
- "Micro-steam environment" allowing high water vapor pressure, relatively high velocity under very high temperature condition
- Used for 3000°F EBC-CMC developments

Specimen holder and water vapor jets

Specimen under testing



Steam during cooling cycles

High temperature testing with steam flow



- **Steam injected at up to 5m/sec**
- **Testing temperature >1700°C**

High Heat Flux Thermomechanical Testing for EBC Development

- High heat flux and combined thermal-mechanical loading capabilities established to allow SiC/SiC system performance data to be obtained under simulated operating conditions
- A 1000 Hz high heat flux HCF testing rig is being established this year



High heat flux tensile TMF and rupture testing







High heat flux flexural TMF testing: HCF, LCF, interlaminar and biaxial strengths

Thermal Conductivity Measurement by a Laser High-Heat-Flux Approach

$$k_{ceramic}(t) = q_{thru} \cdot l_{ceramic} / \Delta T_{ceramic}(t)$$

Where

$$q_{thru} = q_{delivered} - q_{reflected} - q_{radiated}$$

and

$$\Delta T_{ceramic}(t) = T_{ceramic-surafce} - T_{metal-back} - \int_0^{l_{bond}} \frac{q_{thru} \cdot dl}{k_{bond}(T)} - \int_0^{l_{substrate}} \frac{q_{thru} \cdot dl}{k_{substrate}(T)}$$



Thermal Gradient Cyclic Behavior of a Thermal Environmental Barrier Coating System

– Sintering and delamination of coatings reflected by the apparent thermal conductivity changes



Environmental Barrier Coating and High Heat Flux Induced Delaminations





$$G = \frac{1}{6}\left(\frac{1+\nu_1}{1-\nu_1}\right)E_1 h\left(\alpha_1\left(T_S - T_0\right)\right)^2$$

Evans and Hutchinson model, Surface Coating Technology, 2007



The FEM model



Thermal Gradient Cyclic Behavior of Air Plasma Sprayed Yb_2SiO_5 (with HfO_2 Composite)/$Yb_2Si_2O_7$/HfO_2-Si Coatings on SiC/SiC CMCs

- $T_{surface}$ ~1482-1500°C, $T_{interface}$ 1350°C, $T_{back\ surface}$ 1225°C, heat flux 110 W/cm²
- Localized pore formation





After 50hr Cyclic Testing

Fatigue Testing using a Laser High-Heat-Flux Approach for Environmental Barrier Coated Prepreg SiC/SiC CMCs

- Environmental Barrier Coatings Yb_2SiO_5/$Yb_2Si_2O_7$/Si on MI Prepreg SiC/SiC CMC substrates
- One specimen tested in air, air testing at 1316°C
- One specimen tested in steam, steam testing at T_{EBC} 1316°C, T_{CMC} at ~1200°C
- Lower CMC failure strain observed in steam test environments





Fatigue strains (amplitudes) – Time Plot



Thermal conductivity – Time Plot

Fatigue Testing using a Laser High-Heat-Flux Approach for EBC Coated Prepreg SiC/SiC CMCs - *Continued*

- Crack and recession failure in air and steam tests





In Air; EBC cracking



In steam; EBC cracking and volatility

Fatigue Testing using a Laser High-Heat-Flux Approach for EBC Coated Prepreg SiC/SiC CMCs - *Continued*

- Crack and recession failure in air and steam tests



In Air; EBC cracking



In steam; EBC cracking and volatility

EBC Coated CMC 2650°F (1454°C) Creep Rupture Durability Test

- SiC/SiC CMC 12C-470-022 SiC/SiC CVI-MI CMC specimen
- Coated with 2700°F (1482°C) RESi and Rare Earth EBC
- Test temperatures: $T_{EBC\ surface}$ at 2850-3000°F (1600-1650°C), and $T_{cmc\ back}$ at ~2600°F (1426°C)



Advanced EBC-CMC Fatigue Test with CMAS: Successfully Tested 300 h Durability in High Heat Flux Fatigue Test Conditions

- A thin EB-PVD turbine airfoil EBC system with advanced HfO_2-rare earth silicate and GdYbSi (controlled oxygen activity) bond coat tested at $T_{EBC\text{-}surface}$ 1537°C, $T_{bond\ coat}$ 1480°C, $T_{back\ CMC\ surface}$ 1250°C
- Fatigue Stress amplitude 69 MPa, at mechanical fatigue frequency f=3Hz, stress ratio R=0.05
- Low cycle thermal gradient fatigue 60min hot, 3min cooling



1537°C, 69MPa (10ksi), 300 h fatigue (3 Hz, R=0.05) on 14C579-011001_#8 CVI-MI SiC/SiC (with CMAS)





EBC Fatigue Test Failure with CMAS

- Advanced alternating HfO_2-RE-silicate coatings (EB-PVD processing) – HfO2-layer infiltration and rare earth silicate layer melting
- Advanced composition clustering EBCs being developed



EB-PVD Processed EBCs: alternating HfO_2-rich and ytterbium silicate layer systems for CMAS and impact resistance

Advanced EBC-CMC Fatigue Test with CMAS and in steam Jet: Successfully Tested 150 h Durability in High Heat Flux Fatigue Test Conditions

- Advanced Hf-NdYb silicate-NdYbSi bond coat EBC coatings on 3D architecture CVI-PIP SiC-SiC CMC (EB-PVD processing)







SiC/SiC Turbine Airfoil Trailing Edge Tests

- Subelement wedge testing and high temperature tests, aiming at understanding the CMC and EBC degradation

CVI SiC/SiC CMC



Subelement Load-Displacement curve – CVI CMC trailing edge



Subelement Load-Displacement curve – Prepreg MI CMC trailing edge

Summary and Future Plans

- **Advanced high heat flux creep rupture, fatigue rigs established for simulated turbine engine EBC-CMC testing**
  - High temperature comprehensive environment testing capability including heat flux, steam and CMAS, at very high temperature
  - Real time coating degradation monitoring and fatigue-creep stain monitoring
  - Testing capabilities incorporated into the advanced EBC-CMC developments

- **Long term creep rupture and fatigue behavior evaluated for Hafnium Rare Earth silicate and Rare Earth-Silicon based EBCs-CMCs at 1482°C+ (2700°F+)**
  - Crucial for advanced EBC-CMC development and validations

- **The heat flux thermomechanical testing of subelements for the EBC-CMC subelement**
  - Important for durability and life modeling

Future plans

- HCF high heat flux rig with additional environmental testing capabilities (steam-air mixture environments and controlled steam or vacuum capabilities)
- EBC erosion-impact capabilities also planned in combination of laser high heat flux, creep-fatigue, high velocity steam, and CMAS integrated tests
- Additional full field strain measurement experiments, in particular at high temperatures
- Planned a multi-axial testing rig for CMC and EBC testing

Acknowledgements

- The work was supported by NASA Fundamental Aeronautics Program (FAP) and Transformational Tools and Technologies Projects

NASA colleagues include:

Sue Puleo and Rick Rogers – X-ray

Terry McCue, Serene Farmer, Francisco Solá, SEM and TEM

Valerie Wiesner and Narottam Bansal, Gustavo Costa: Fundamental CMAS behavior